# Title List of Documents Made Publicly Available

September 1-30, 1980

Office of Administration U.S. Nuclear Regulatory Commission



## Title List of Documents Made Publicly Available

September 1-30, 1980

Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, D.C. 20555



## CONTENTS

Preface	V
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket 50 Items by Facility Name	xvii
Docketed Items	1
Low Level Radwaste Disposal Sites – Docket 27	1
Domestic Licensing of Source Material – Docket 40	
Domestic Licensing of Production and Utilization Facilities - Docket 50	
Domestic Licensing of Special Nuclear Material - Docket 70	
Packaging of Radioactive Material for Transport and Transportation of	
Radioactive Material Under Certain Conditions - Docket 71	317
Nondocketed Items	323
10CFR - Commission Meeting Records	
ACRS - Advisory Committee on Reactor Safeguards	324
COMMISSION - NRC Commissioners	
CONTRACT - NRC Contracts and Modifications	
DISCLOSURE — Financial Disclosure Information	
FOIA - Freedom of Information Act Requests and Releases	331
GEN TECH IS — Generic Technical Issues	
I&E — Inspection and Enforcement	
MISC - Public Document Room Miscellaneous	
NUREG - NUREG Reports and Related Correspondence	
ORG — Correspondence with Other Organizations	
PR — Proposed Rule	
PRM – Petition for Rulemaking	
PROJ - Projects - Predocket Licensing	
PT21 — Noncompliance Reports and Related Correspondence	
QA999 — Quality Assurance Inspections	
REGGD - Regulatory Guides	
RES – Research and Technical Assistance Reports	
REVIEW GRP – NRC Research Review Groups	
RM Rulemakings	355
SECY — Position Papers Before the Commission	355
STATE PROG — State Programs	
TOPREP — Vendor Reports and Related Correspondence	
XPORTLIC — Export and Import Licenses	
Personal Author Index	
Corporate Source Index	
Report Number Index	
Cross Reference of Enclosures to Principal Documents	431
Appendix A - Definitions of Docket 50 Categories	447
Appendix B — Definitions of Nondocketed Categories	

#### PREFACE

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

#### DOCKETED ITEMS

The listings within dockets are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence

- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences, LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence
- W. Decommissioning stage documents and correspondence

Appendix A sets forth those categories and described the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report


The principal elements of the entries in the list are:

P Operating license stage documents & correspondence



7904170015 Forwards info on TMLJM Hendrie 790410 testimony, preliminary chronology of NRC actions, description of events & generic consideration of incident.

REHM, T A. Office of the Executive Director for Operations.



- I NRC/PDR Document category (see Appendix A).
- 2. NRC Accession Number
- 3. Description of information contained in the document
- 4. Personal author. An asterisk in this position indicates that there is no personal author
- 5. Corporate, agency or nonindividual source
- 6 Date of document described
- 7 Pages in document
- 8. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5

#### NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories and their symbols are:

10CFR — Commission Meeting Records
ACRS — Advisory Committee on Reactor Safeguards
COMMISSION — NRC Commissioners
CONTRACT — NRC Contracts and Modifications
DISCLOSURE — Financial Disclosure Information
FOIA — Freedom of Information Act Requests and Releases

GEN TECH IS — Generic Technical Issues

I&E — Inspection and Enforcement

MISC — Public Document Room Miscellaneous

NUREG — NUREG Reports and Related Correspondence

ORG — Correspondence with other organizations

PR - Proposed Rule

PRM — Petition for Rulemaking

PROJ - Projects-Predocket Licensing

PT9 — Public Records

PT21 — Noncompliance Reports and Related Correspondence

QA999 — Quality Assurance Inspections

REGGD — Regulatory Guides

RES — Research and Technical Assistance Reports

REVIEW GRP — NRC Research Review Groups

RM - Rulemakings

SECY — Position Papers Before the Commission

STATE PROG — State Programs

TOPREP - Vendor Reports and Related Correspondence

WASTE MGT — Nuclear Waste Management

XPORTLIC — Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the teport.

The principal elements of the nondocketed items are:


1 NUREG - NUREG Reports and Related Correspondence



7901060007 NUREG/CR-0161

(4) "Dynamic Analysis to Establish Normal Shock & Vibration Environs Experienced by Radioactive National Shipping Package." Quarterly Progress Report 780101-780331 Identifies parameters which affect normal shock & vibration environs.

FIELDS, S.R., MECH, S.J. Hanford Engineering Development Laboratory,



- 1. Nondocketed category
- 2. NRC Accession Number
- 3. NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author
- 6. Corporate, agency or other nonindividual source
- 7. Contract or financial (FIN) number (if any). If the document has a secondary report number it will appear following this entry.
- 8. Date of document described
- 9. Pages in document

10. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" or "Available at NTIS." See NOTES on this page for information on ordering publications.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

#### NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the charge-card number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: 8¢ per page for standard size paper; 11¢ per page for oversized paper (drawings); 25¢ per microfiche for 24x diazo duplicates. A minimum charge of \$2.00 plus postage is charged for mail orders.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Potomac Research, Inc.

## ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Do	cket	Name	Page
27-010	Beatty, NV	1		40-8502	Irigaray Mine, Wyoming Mining Corp.	6
27-039	Sheffield, IL, Nuclear Engineering Co.	1		40-8568	Dept. of the Air Force	6
27-047	Barnwell, SC, Chem-Nuclear Systems, Inc.	1	1	40-8584	Union 76 Minerals Exploration Co.	6
27-048	Richland, WA, Nuclear Engineering Co.	1		40-8663	Nuclear Dynamics, Inc.	6
40-0299	Union Carbide Corp.	2		40-8681	Energy Fuels Nuclear, Inc.	6
40-0672	Nuclear Metals, Inc.	2		40-8692	Cotter Corp.	7
40-0791	United Technologies, Inc	2		40-8693	Ogle Petroleum, Inc.	7
40-1162	Western Nuclear, Inc.	2		40-8697	Rocky Mountain Energy Co.	7
40-1341	Edgemont Uranium Mine, TVA, and	2		40-8698	Plateau Resources, Ltd.	7
	Mines Development, Inc.			40-8721	Rocky Mountain Energy Co.	7
40-2061	West Chicago Facility, Kerr-McGee Corp.	3		40-8724	Chemtron Corp.	7
40-2259	Pathfinder Mines Corp.	3		40-8743	Conoco	7
40-2940	NL Industries, Inc.	3		40-8745	Ogle Petroleum	7
40-3392	Allied Chemical Corp.	4		40-8768	Kerr-McGee Nuclear Corp.	8
40-3453	Atlas Minerals	4		50-3	Indian Point Station, Unit 1	8
40-4348	Dept. of Commerce	4		<b>50-</b> 5	Pennsylvania State Univ. Research Reactor	9
40-4492	Federal American Partners (Mining)	4		50-10	Dresden Nuclear Power Station, Unit 1	10
40-4826	Northwestern Univ.	4		50-20	Massachusetts Institute of Technology	11
40-6659	Petrotomics Co., Getty Oil Co.	4			Research Reactor	
40-8027	Kerr-McGee Corp.	5		50-22	Westinghouse Test Reactor	11
40-8084	Lisbon Mine, Rio Algom Corp.	5		50-27	Washington State Univ. Research Reactor	12
40-8092	NASA	5		50-29	Yankee-Rowe Nuclear Power Station	12
40-8102	Exxon Minerals Co. USA, Exxon Corp.	5		50-30	Plum Brook Research Reactor Facility	13
40-8113	Univ. of Utah	5		50-47	Army Materials Research Reactor	13
40-8180	Univ. of Oklahoma	5		5 0-54	Union Carbide Research Reactor	13
40-8348	In Situ Uranium Leaching Project	5		50-57	State Univ. of New York Research Reactor	13
40-8380	Rocky Mountain Energy Co.	5		50-59	Texas A&M Univ. Research Reactor	13
40-8452	Bear Creek Uranium Co.	5		50-70	General Electric Test Reactor	13

Docket	Name	Page	Docket	Name	Page
50-77	Catholic Univ. of America Research Reactor	14	50-213	Haddam Neck Plant	24
50-83	Univ. of Florida Training Reactor	14	50-219	Oyster Creek Nuclear Power Plant	26
50-87	Westinghouse Critical Experiment	14	50-220	Nine Mile Point Nuclear Station, Unit 1	28
50-97	Cornell Univ. Zero Power Reactor	14	50-222	Columbia Research Reactor	30
50-99	Babcock & Wilcox Test Reactor	14	50-223	Univ. of Lowell Research Reactor	30
50-112	Univ. of Oklahoma Research Reactor	14	50-224	Univ. of California Research Reactor	30
50-123	Univ. of Missouri Research Reactor	14	50-225	RPI Critical Experiment	30
50-124	Virginia Polytechnic Institute Training Reactor	14	50-227	TRIGA Thermionic Prototype Reactor	30
50-128	Texas A&M Univ. Research Reactor	1.4	50-237	Dresden Nuclear Power Station, Unit 2	30
50-123	Omaha Veterans Administration Hospital	14	50-243	Oregon State Univ. Research Reactor	33
30-131	Research Reactor	15	50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	33
50-133	Humboldt Bay Power Plant, Unit 3	15	50-245	Millstone Nuclear Power Station, Unit 1	35
50-134	Worcester Polytechnic Institute Research Reactor	15	50-247	Indian Point Station, Unit 2	37
50-139	Univ. of Washington Research Reactor	16	50-249	Dresden Nuclear Power Station, Unit 3	39
50-142	UCLA Training Reactor	16	50-250	Turkey Point Plant, Unit 3	41
50-147	Rockwell International Corp. Critical	16	50-251	Turkey Point Plant, Unit 4	43
	Facility		50-254	Quad-Cities Station, Unit 1	45
50-152	Florida West Coast Nuclear Group, Inc.	16	50-255	Palisades Nuclear Plant	47
50-155	Big Rock Point Nuclear Plant	16	50-259	Browns Ferry Nuclear Power Station, Unit 1	50
50-156	Univ. of Wisconsin Research Reactor	19	50-260	Browns Ferry Nuclear Power Station, Unit 2	53
50-157	Cornell Univ. Research Reactor	19	50-261	H.B. Robinson Plant, Unit 2	55
50-166	Univ. of Maryland Research Reactor	19	50-263	Monticello Nuclear Generating Plant	56
50-170	National Naval Medical Center	19	50-265	Quad-Cities Station, Unit 2	58
50-171	Peach Bottom Atomic Power Station, Unit 1	19	50-266	Point Beach Nuclear Plant, Unit 1	60
50-182	Purdue Univ. Research Reactor	20	50-267	Fort St. Vrain Nuclear Generating Station	62
50-184	National Bureau of Standards Reactor	20	50-268	Midwest Fuel Recovery Plant	64
50-185	Plum Brook Reactor - Mock-up	20	50-269	Oconce Nuclear Station, Unit 1	64
50-186	Univ. of Missouri Research Reactor	20	50-270	Oconce Nuclear Station, Unit 2	66
50-193	Rhode Island & Providence Plantations AEC	20	50-271	Vermont Yankee Nuclear Power Station	68
50-199	Manhattan College Research Reactor	20	50-272	Salem Nuclear Generating Station, Unit 1	70
50-201	West Valley Reprocessing Plant	20	50-273	Beznau Nuclear Station, Unit 1, Switzerland	72
50-206	San Onofre Nuclear Station, Unit 1	22	50-274	U.S. Geological Survey Research Reactor	72
50-208	Columbia Univ. Research Reactor	24	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	72

Docket	Name	Page	Docket	Name	Page
50-277	Peach Bottom Atomic Power Station, Unit 2	74	50-326	Univ. of California at Irvine Research Reactor	153
50-278	Peach Bottom Atomic Power Station, Unit 3	76	50-327	Sequoyah Nuclear Plant, Unit 1	153
50-280	Surry Power Station, Unit 1	79	50-328	Sequoyah Nuclear Plant, Unit 2	157
50-281	Surry Power Station, Unit 2	81	50-329	Midland Plant, Unit 1	160
50-282	Prairie Island Nuclear Station, Unit 1	84	50-330	Midland Plant, Unit 2	162
50-285	Fort Calhoun Station, Unit 1	86	50-331	Duane Arnold Energy Center	164
50-286	Indian Point Station, Unit 3	87	50-332	Barnwell Reprocessing Plant	166
50-287	Oconee Nuclear Station, Unit 3	90	50-333	James A. Fitzpatrick Nuclear Power Plant	166
50-289	Three Mile Island Nuclear Station, Unit 1	91	50-334	Beaver Valley Power Station, Unit 1	169
50-293	Pilgrim Nuclear Power Station, Unit 1	99	50-335	St. Lucie Plant, Unit 1	171
50-295	Zion Nuclear Power Station, Unit 1	103	50-336	Millstone Nuclear Power Station, Unit 2	173
50-296	Browns Ferry Nuclear Power Station, Unit 3	106	50-338	North Anna Power Station, Unit 1	174
50-297	North Carolina State Univ. PULSTAR Reactor	108	50-339	North Anna Power Station, Unit 2	177
50-298	Cooper Nuclear Station	108	50-340	Seabrook Nuclear Station, Unit 1	179
50-301	Point Beach Nuclear Plant, Unit 2	110	50-341	Enrico Fermi Atomic Power Plant, Unit 2	179
50-302	Crystal River Nuclear Plant, Unit 3	112	50-344	Trojan Nuclear Plant	180
50-304	Zion Nuclear Power Station, Unit 2	<b>1</b> 14	50-346	Davis-Besse Nuclear Power Station, Unit 1	182
50-305	Kewaunee Nuclear Power Plant	116	50-348	Joseph M. Parley Nuclear Plant, Unit 1	184
50-306	Prairie Island Nuclear Station, Unit 2	117	50-352	Limerick Generating Station, Unit 1	187
50-309	Maine Yankee Atomic Power Plant	119	50-353	Limerick Generating Station, Unit 2	188
50-311	Salem Nuclear Generating Station, Unit 2	121	50-354	Hope Creek Nuclear Station, Unit 1	189
50-312	Rancho Seco Nuclear Generating Station	124	50-355	Hope Creek Nuclear Station, Unit 2	190
50-313	Arkansas Nuclear One, Unit 1	126	50-356	Univ. of Illinois LOPRA Research Reactor	191
50-315	Donald C. Cook Nuclear Power Plant, Unit 1	128	50-358	William II. Zimmer Nuclear Station, Unit 1	191
50-316	Donald C. Cook Nuclear Power Plant, Unit 2	130	50-361	San Onofre Nuclear Station, Unit 2	192
50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	131	50-362	San Onofre Nuclear Station, Unit 3	195
50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	133	50-363	Forked River Nuclear Station, Unit 1	197
50-320	Three Mile Island Nuclear Station, Unit 2	135	50-364	Joseph M. Farley Nuclear Plant, Unit 2	197
50-321	Edwin I. Hatch Nuclear Plant, Unit 1	143	50-366	Edwin I. Hatch Nuclear Plant, Unit 2	199
50-322	Shoreham Nuclear Power Station	145	50-367	Bailly Generating Station	202
50-323	Diablo Canyon Nuclear Power Plant, Unit 2	146	50-368	Arkansas Nuclear One, Unit 2	204
50-324	Brunswick Steam Electric Plant, Unit 2	148	50-369	William B. McGuire Nuclear Station, Unit 1	207
50-325	Brunswick Steam Electric Plant, Unit 1	150	50-370	William B. McGuire Nuclear Station, Unit 2	209

Docket	Name	Page	Docket	Name	Page
50-373	LaSalle County Station, Unit 1	211	50-440	Perry Nuclear Power Plant, Unit 1	246
50-374	LaSalle County Station, Unit 2	213	50-441	Perry Nuclear Power Plant, Unit 2	248
50-376	North Coast Nuclear Plant, Puerto Rico	214	50-443	Seabrook Nuclear Station, Unit 1	250
50-378	Caorso Nuclear Station, Italy	215	50-444	Seabrook Nuclear Station, Unit 2	251
50-382	Waterford Generating Station, Unit 3	215	50-445	Comanche Peak Steam Electric Station,	251
50-387	Susquehanna Steam Electric Station, Unit 1	216		Unit 1	
50-388	Susquehanna Steam Electric Station, Unit 2	218	50-446	Comanche Peak Steam Electric Station, Unit 2	255
50-389	St. Lucie Plant, Unit 2	219	50.462		<b>5-0</b>
50-390	Watts Bar Nuclear Plant, Unit 1	221	50-452	Greenwood Energy Center, Unit 2	259
50-391	Watts Bar Nuclear Plant, Unit 2	222	50-453	Greenwood Energy Center, Unit 3	259
50-395	Virgil C. Summer Nuclear Station, Unit 1	224	50-454	Byron Station, Unit 1	259
50-397	WPPSS Nuclear Project, Unit 2	226	50-455	Byron Station, Unit 2	260
50-400	Shearon Harris Nuclear Power Plant, Unit 1	228	50-456	Braidwood Station, Unit 1	261
50-401	Shearon Harris Nuclear Power Plant, Unit 2	229	50-457	Braidwood Station, Unit 2	262
50-402	Shearon Harris Nuclear Power Plant, Unit 3	230	50-458	River Bend Station, Unit 1	263
50-403	Shearon Harris Nuclear Power Plant, Unit 4	231	50-459	River Bend Station, Unit 2	264
50-404	North Anna Power Station, Unit 3	231	50-460	WPPSS Nuclear Project, Unit 1	265
50-405	North Anna Power Station, Unit 4	232	50-461	Clinton Power Station, Unit 1	266
50-409	La Crosse Boiling Water Reactor	232	50-462	Clinton Power Station, Unit 2	268
50-410	Nine Mile Point Nuclear Station, Unit 2	234	50-466	Allens Creek Nuclear Station, Unit 1	269
50-412	Beaver Valley Power Station, Unit 2	235	50-467	Allens Creek Nuclear Station, Unit 2	271
50-413	Catawba Nuclear Station, Unit 1	235	50-471	Pilgrim Nuclear Power Station, Unit 2	271
50-414	Catawba Nuclear Station, Unit 2	236	50-472	Pilgrim Nuclear Power Station, Unit 3	271
50-416	Grand Gulf Nuclear Station, Unit 1	237	STN-50-482	Wolf Creek Generating Station	271
50-417	Grand Gulf Nuclear Station, Unit 2	240	STN-50-483	Calloway Plant, Unit 1	272
50-423	Millstone Nuclear Power Station, Unit 3	242	STN-50-485	Sterling Power Project, Nuclear, Unit 1	273
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	242	STN-50-486	Calloway Plant, Unit 2	273
50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	243	STN-50-488	Perkins Nuclear Station, Unit 1	274
50-431	Genkai, Unit 1, Japan	243	STN-50-489	Perkins Nuclear Station, Unit 2	275
50-433	Univ. of California at Santa Barbara	243	STN-50-490	Perkins Nuclear Station, Unit 3	276
	Research Reactor		STN-50-491	Cherokee Nuclear Station, Unit 1	276
STN-50-437	Floating Nuclear Plant	243	STN-50-492	Cherokee Nuclear Station, Unit 2	277
50-438	Bellefonte Nuclear Plant, Unit 1	244	STN-50-493	Cherokee Nuclear Station, Unit 3	277
50-439	Bellefonte Nuclear Plant, Unit 2	245	STN-50-498	South Texas Project, Unit 1	277
					•

Docket	Name	Page	Docket	Name	Page
STN-50-499	South Texas Project, Unit 2	280	STN-50-567	Yellow Creek Nuclear Plant, Unit 2	302
50-500	Davis-Besse Nuclear Power Station, Unit 2	283	STN-50-574	Bagnac Nuclear Power Project, Philippines	303
50-501	Davis-Besse Nuclear Power Station, Unit 3	283	50-582	Sundesert, Unit 1	303
STN-50-502	Haven Nuclear Plant, Unit 1	283	50-583	Sundesert, Unit 2	303
STN-50-508	WPPSS Nuclear Project, Unit 3	283	STN-50-592	Palo Verde Nuclear Station, Unit 4	303
STN-50-509	WPPSS Nuclear Project, Unit 5	284	STN-50-593	Palo Verde Nuclear Station, Unit 5	303
50-510	Blue Hills Station, Unit 1	284	50-599	Carroll Facility I	304
50-511	Blue Hills Station, Unit 2	284	50-600	Carroli Facility II	304
50-513	WPPSS Nuclear Project, Unit 4	284	70-0008	Battelle Columbus Laboratories	304
50-514	Pebble Springs Nuclear Plant, Unit 1	285	70-0025	Rockwell International Corp.	304
50-515	Pebble Springs Nuclear Plant, Unit 2	285	70-0027	Babcock & Wilcox Co.	304
STN-50-516	Jamesport Nuclear Station, Unit 1	285	70-0033	Texas Instruments, Inc.	304
STN-50-517	Jamesport Nuclear Station, Unit 2	286	70-0036	Combustion Engineering, Inc.	305
STN-50-518	Hartsville Nuclear Plant, Unit 1	286	70-0135	Babcock & Wilcox Co.	305
STN-50-519	Hartsville Nuclear Plant, Unit 2	287	70-0143	Nuclear Fuel Services, Inc.	306
STN-50-520	Hartsville Nuclear Plant, Unit 3	288	70-0258	Univ. of Illinois at Urbana-Champaign	307
STN-50-521	Hartsville Nuclear Plant, Unit 4	290	70-0312	Univ. of Massachusettes	307
STN-50-522	Skagit Nuclear Power Project, Unit 1	291	70-0343	Rutgers the State University of New Jersey	307
STN-50-523	Skagit Nuclear Power Project, Unit 2	291	70-0349	Northwestern Univ. at Evanston-Chicago	307
STN-50-528	Palo Verde Nuclear Station, Unit 1	291	70-0364	Parks Township Site, Babcock & Wilcox Co.	307
STN-50-529	Palo Verde Nuclear Station, Unit 2	292	70-0371	United Nuclear Corp.	308
STN-50-530	Palo Verde Nuclear Station, Unit 3	294	70-0398	Dept. of Commerce	308
50-536	Gosgen, Switzerland	295	70-0575	Lebanon Valley College	308
50-537	Clinch River Breeder Reactor	296	70-0600	Seattle Univ.	308
STN-50-546	Marble Hill Nuclear Station, Unit 1	296	70-0687	Union Carbide Corp.	308
STN-50-547	Marble Hill Nuclear Station, Unit 2	297	70-0710	Merrimack College	308
STN-50-553	Phipps Bend Nuclear Plant, Unit 1	299	70-0734	General Atomic Co.	309
STN-50-554	Phipps Bend Nuclear Plant, Unit 2	300	70-0754	Vallecitos Nuclear Center	309
STN-50-556	Black Fox Station, Unit 1	301		General Electric Co.	
STN-50-557	Black Fox Station, Unit 2	301	70-0820	United Nuclear Corp.	309
50-559	Maanshan Nuclear Station, Unit 2, Taiwan	301	70-0824	Babcock & Wilcox Co.	310
50-564	Nuclear Fuels Recovery and Recycle Center	301	70-0925	Cimarron Facility, Kerr-McGee Corp.	310
STN-50-566	Yellow Creek Nuclear Plant, Unit 1	302	70-0959	Nuclear Fuel Services, Inc.	310

Docket	Name	Page	Docket	Name	Page
70-0984	Pacific Northwest Laboratory	310	70-2322	Edlow International Co.	315
70-1007	General Electric Co.	310	70-2375	Pacific Gas & Electric Co.	315
70-1097	General Electric Co.	310	70-2478	Transnuclear, Inc.	315
70-1100	Combustion Engineering, Inc.	311	70-2479	Transnuclear, Inc.	316
70-1113	General Electric Co.	311	70-2520	West Virginia Univ. Medical Center, Morgantown, WV	316
70-1120	Westinghouse Electric Co.	311	70-2554	Valley Hospital, Ridgewood, NJ	316
70-1143	Westinghouse Electric Corp.	311	70-2560	Oklahoma Osteopathic Hospital, Tulsa, OK	316
70-1151	Westinghouse Electric Corp.	311	70-2500	Berrien General Hospital, Berrien Center, MI	
70-1167	Northwestern Oklahoma State Univ.	312	70-2399	Commonwealth Edison Co.	316
70-1193	Cunarron Facility, Kerr-McGee Corp.	312			316
70-1201	UF-6 Conversion Facility,	312	70-2621	Riverside Hospital, Newport News, VA	316
	Babcock & Wilcox Co.		70-2623	McGuire Spent Fuel Pool, Duke Power Co.	316
70-1220	General Electric Co.	312	70-2705	St. Francis Medical Center Hospital, Lynwood, CA	316
70-1257	Mixed Oxide Fabrication Plant, Exxon Nuclear Co., Inc.	312	70-2786	General Electric Co.	316
70-1308	Morris Operations, General Electric Co.	313	70-2883	Hanna Mining Co.	316
70-1309	Morris Operations, Sources & Standards, General Electric Co.	314	70-2885	Commonwealth Edison	317
70-1327	UF-6 Conversion Facility, Allied-General	314	70-2892	Auxilio Mutuo Hospital	317
	Nuclear Services Corp.		70-2908	Veterans Administration Hospital, San Diego, CA	317
70-1349	Hospital Pavia	314	70-2909	Westinghouse Electric Corp. Power Systems	317
70-1377	Hanna Mining Co.	314	70-2910	Tennessee Valley Authority	317
70-1397	St. Mary's Hospital, Richmond, VA	314		·	
70-1401	Veterans Administration Hospital, Dallas, TX	314	70-2913	Tennessee Valley Authority	317
70-1417	Greater Southeast Community Hospital,	314	70-2914	Hanna Mining Co.	317
70.1407	Washington, DC		70-2932	Texas Utilities Generating Co.	317
70-1432	Recycle Fuels Plant, Westinghouse Electric Corp.	314	71-0002	Chem-Nuclear Systems, Inc.	317
70-1470	Veterans Administration Hospital,	315	71-0017	Rhode Island Atomic Energy Commission	317
	Los Angeles, CA		71-0018	Nuclear Assurance Corp.	317
70-1729	Fuel Recovery & Storage Station, Allied- General Nuclear Services Corp.	315	71-0035	Rockwell International	317
70-1738	Pacific Gas & Electric Co.	315	71-0082	Kerr-McGee Nuclear Corp.	317
70-1739	Tri-State Motor Transit Co.	315	71-0108	Univ. of Missouri	317
70-1821	Plutonium Production Facility, Allied-	315	71-0109	Union Carbide Corp.	318
	General Nuclear Services Corp.		71-0112	Dept. of the Navy	318
70-2192	Pittston Co, Coal Group	315	71-0138	Battelle Columbus Laboratories	318
70-2313	Nuclear Fuel Services	315	71-0192	Nuclear Packaging, Inc.	318

Docket	Name	Page	Docket	Name	Page
71-0198	Nuclear Fuel Services, Inc	318	71-9018	Model BU-6, General Electric Co.	320
71-0244	NL Industries, Inc.	318	71-9019	Model. BU-7, General Electric Co.	320
71-0370	Amersham Corp.	318	71-9022	Model CE-250-2, Combustion Engineering	320
71-0382	Dept. of the Interior, Geological Survey	318	a1 000a	Co., Inc	
71-0385	Dept. of the Navy, Naval Nuclear Power	318	71-9027	Model 741, Technical Operations, Inc.	320
71.0204	Unit Port, Hueneme, CA	210	71-9032	Model 650, Technical Operations, Inc.	320
71-0394 71-0395	Nuclear Sources & Services, Inc.	318	71-9033	Model: 660 & 660E, Technical Operations, Inc.	320
/1-0393	Dept. of the Navy, Naval Facilities Engineering Command	318	71-9034	Model: TRIGA-1, General Atomic Co.	320
71-0396	Atcor Washington, Inc.	318	71-9035	Model: 680, Technical Operations, Inc.	320
71-4888	Model: Sentinel -25A, B, C, C3, D, E, F, Teledyne Energy Systems	318	71-9036	Model: C-1, Source Production Equipment Co.	320
71-4986	Model: RA-2, Exxon Nuclear Co., Inc.	318	71-9037	Model: TRIGA-2, General Atomic Co.	320
71-5088	Model: D34710-1, U.S. Nuclear, Inc	318	71-9039	Model: 715, Technical Operations, Inc.	320
71-5442	Model: LA-36, Babcock & Wilcox Co.	318	71-9044	Model: GE-1600, General Electric Co.	320
71-5450	Model: RCC-1, -2, -3, Westinghouse Electric Corp.	319	71-9049	Model: GE-500, General Electric Co.	320
71-5740	Model: ORNL-TRU-CF, Shipping Container,	319	71-9074	Model: AP-100, Anefco, Inc.	321
71.5740	Dept. of Energy	317	71-9080	Model: HN-600, Hittman Nuclear &	321
71-5862	Model. Sentinel-100F, Teledyne Energy Systems	319	~	Development Corp.	
71-5926	Model: 100, General Electric Co.	319	71-9081	Model: CNSI-1600, Chem-Nuclear Systems, Inc.	321
71-5942	Model: GE-700, General Electric Co.	319	71-9094	Model: CNSI-14-195-H, Chem-Nuclear	321
71-5957	Model: BMI-1, Dept. of Energy	319		Systems, Inc.	
71-5971	Model: GE-200, General Electric Co.	319	71-9096	Model: CNSI-21-300, Chem-Nuclear Systems, Inc.	321
71-5980	Model: GE-600, General Electric Co.	319	71-9097	Model: CNSI-14-195L, Chem-Nuclear	321
71-5998	Model: GE-400, General Electric Co.			Systems, Inc.	V
	•	319	71-9108	Model: AL-33-90, Atcor, Inc.	321
71-6058	Model: B3-I, Nuclear Engineering Co.  Model: 6144, Nuclear Engineering Co.	319	71-9111	Model: CN6-80A, Chem-Nuclear	321
71-6144	, ,	319		Systems, Inc.	
71-6357	Model: NNFD-10, Babcock & Wilcox Co.	319	71-9113	Model: 7-100, Chem-Nuclear Systems, Inc.	321
71-6400	Model: Super Tiger, Westinghouse Electric Corp.	319	71-9116	Model: CN6-80B, Nuclear Packaging,	321
71-6458	Model: BU-5, General Electric Co.	319		Inc.	
71-6581	Model: 51032-1 & 1A, Exxon Nuclear Co., Inc.	319	71-9136	Model: GE-9136, General Electric Co.	321
71-6717	Model: 6717 B	320	71-9508	Model: DOT SPEC 6M, Dept. of Energy	321
71-9001	Model: 1F-300, General Electric Co.	320	71-9853	Model: ORNL - BNL - NBS, Unirradiated Fuel Container,	321
71-9009	Model: FL 10-1, General Electric Co.	320		Dept. of Energy	

	,		
		,	
			1
			, , , , , , , , , , , , , , , , , , ,
			, 1

## ALPHABETIC ARRANGEMENT OF DOCKET 50 ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Allens Creek Nuclear Station, Unit 1	50-466	269	Brunswick Steam Electric Plant, Unit 1	50-325	150
Allens Creek Nuclear Station, Unit 2	50-467	271	Brunswick Steam Electric Plant, Unit 2	50-324	148
Arkansas Nuclear One, Unit 1	50-313	126	Byron Station, Unit 1	50-454	259
Arkansas Nuclear Onc, Unit 2	50-368	204	Byron Station, Unit 2	50-455	260
Army Materials Research Reactor	50-47	13	Calloway Plant, Unit 1	STN-50-483	272
Duane Arnold Energy Center	50-331	164	Calloway Plant, Unit 2	STN-50-486	273
Babcock & Wilcox Co. Test Reactor	50-99	14	Calvert Cliffs Nuclear Power Plant,	50-317	131
Bagnac Nuclear Power Project, Philippines	STN-50-574	303	Unit 1	50.210	122
Bailly Generating Station	50-367	202	Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	133
Barnwell Reprocessing Plant	50-332	166	Caorso Nuclear Station, Italy	50-378	215
Beaver Valley Power Station, Unit 1	50-334	169	Carroll Facility I	50-599	303
Beaver Valley Power Station, Unit 2	50-412	235	Carrolt Facility II	50-600	304
Bellefonte Nuclear Plant, Unit 1	50-438	244	Catawba Nuclear Station, Unit 1	50-413	235
Bellefonte Nuclear Plant, Unit 2	50-439	245	Catawba Nuclear Station, Unit 2	50-414	236
Beznau Nuclear Station, Unit 1, Switzerland	50-273	72	Catholic Univ. of America Research	50-77	14
Big Rock Point Nuclear Power Plant	50-155	16	Reactor	am. 100 101	
Black Fox Station, Unit 1	STN-50-556	301	Cherokee Nuclear Station, Unit 1	STN-50-491	276
Black Fox Station, Unit 2	STN-50-557	301	Cherokee Nuclear Station, Unit 2	STN-50-492	277
Blue Hills Station, Unit 1	STN-50-510	284	Cherokee Nuclear Station, Unit 3	STN-50-493	277
Blue Hills Station, Unit 2	50-511	284	Clinch River Breeder Reactor	50-537	296
Braidwood Station, Unit 1	50-456	261	Clinton Power Station, Unit 1	50-461	266
Braidwood Station, Unit 2	50-457	262	Clinton Power Station, Unit 2	50-462	268
Browns Ferry Nuclear Power Station,	50-259	50	Columbia Research Reactor	50-222	30
Unit 1			Columbia Univ. Research Reactor	50-208	24
Browns Ferry Nuclear Power Station, Unit 2	50-260	53	Comanche Peak Steam Electric Station, Unit 1	50-445	251
Browns Ferry Nuclear Power Station, Unit 3	50-296	106	Comanche Peak Steam Electric Station, Unit 2	50-446	255

Name	Docket	Page	Name	Docket	Page
Donald C. Cook Nuclear Power Plant,	50-315	128	Grand Gulf Nuclear Station, Unit 1	50-416	237
Unit 1			Grand Gulf Nuclear Station, Unit 2	50-417	240
Donald C. Cook Nuclear Power Plant, Unit 2	50-316	130	Greenwood Energy Center, Unit 2	50-452	259
Cooper Nuclear Station	50-298	108	Greenwood Energy Center, Unit 3	50-453	259
Cornell Univ. Research Reactor	50-157	19	Haddam Neck Plant	50-213	24
Cornell Univ. Zero Power Reactor	50-97	14	Shearon Harris Nuclear Power Plant, Unit 1	50-400	228
Crystal River Nuclear Plant, Unit 3	50-302	112	Shearon Harris Nuclear Power Plant,	50-401	229
Davis-Besse Nuclear Power Station, Unit 1	50-346	182	Unit 2		220
Davis-Besse Nuclear Power Station,	50-500	283	Shearon Harris Nuclear Power Plant, Unit 3	50-402	230
Unit 2  Davis-Besse Nuclear Power Station,	50-501	283	Shearon Harris Nuclear Power Plant, Unit 4	50-403	231
Unit 3	00001	200	Hartsville Nuclear Plant, Unit 1	STN-50-518	286
Diablo Canyon Nuclear Power Plant, Unit 1	50-275	72	Hartsville Nuclear Plant, Unit 2	STN-50-519	287
Diable Canyon Nuclear Power Plant,	50-323	146	Hartsville Nuclear Plant, Unit 3	STN-50-520	288
Unit 2			Hartsville Nuclear Plant, Unit 4	STN-50-521	290
Dresden Nuclear Power Station, Unit 1	50-10	10	Edwin I, Hatch Nuclear Plant, Unit 1	50-321	143
Dresden Nuclear Power Station, Unit 2	50-237	30	Edwin I, Hatch Nuclear Plant, Unit 2	50-366	199
Dresden Nuclear Power Station, Unit 3	50-249	39	Haven Nuclear Plant, Unit 1	STN-50-502	283
Joseph M. Farley Nuclear Plant, Unit 1	50-348	184	Hope Creek Nuclear Station, Unit 1	50-354	189
Joseph M. Farley Nuclear Plant, Unit 2	50-364	197	Hope Creek Nuclear Station, Unit 2	50-355	190
Enrico Fermi Atomic Power Plant, Unit 2	<b>50-3</b> 41	179	Humboldt Bay Power Plant, Unit 3	50-133	15
James A. Fitzpatrick Nuclear Power	50-333	166	Indian Point Station, Unit 1	50-3	8
Plant	GM11 50 407	242	Indian Point Station, Unit 2	50-247	37
Floating Nuclear Plant	STN-50-437	243	Indian Point Station, Unit 3	50-286	87
Florida West Coast Nuclear Group, Inc.	50-152	16	Jamesport Nuclear Station, Unit 1	STN-50-516	285
Forked River Nuclear Station, Unit 1	50-363	197	Jamesport Nuclear Station, Unit 2	STN-50-517	286
Fort Calhoun Station, Unit 1	50-285	86	Kewaunee Nuclear Power Plant	50-305	116
Fort St. Vrain Nuclear Generating Station	50-267	62	La Crosse Boiling Water Reactor	50-409	232
General Electric Test Reactor	50-70	13	LaSalle County Station, Unit 1	50-373	211
Genkai, Unit 1, Japan	50-431	243	LaSalle County Station, Unit 2	50-374	213
Robert Emmet Ginna Nuclear Plant,	50-244	33	Limerick Generating Station, Unit 1	50-352	187
Unit 1	30-244	33	Limerick Generating Station, Unit 2	50-353	188
Gosgen, Switzerland	50-536	295	Maanshan Nuclear Station, Unit 2, Taiwan	50-559	301

Maine Yankee Atomic Power Plant50-309119Omaha Veterans Administration Hospital Research Reactor50-13115Manhattan College Research Reactor50-19920Oregon State Univ. Research Reactor50-24333Marble Hill Nuclear Station, Unit 1STN-50-546296Oyster Creek Nuclear Power Plant50-21926Marble Hill Nuclear Station, Unit 2STN-50-547297Palisades Nuclear Plant50-25547Massachusetts Institute of Technology50-2011
Manhattan College Research Reactor 50-199 20 Oregon State Univ. Research Reactor 50-243 33  Marble Hill Nuclear Station, Unit 1 STN-50-546 296  Marble Hill Nuclear Station, Unit 2 STN-50-547 297  Massachusetts Institute of Technology 50-20 11
Marble Hill Nuclear Station, Unit 1 STN-50-546 296  Marble Hill Nuclear Station, Unit 2 STN-50-547 297  Massachusetts Institute of Technology 50-20 11
Marble Hill Nuclear Station, Unit 2 STN-50-547 297  Palisades Nuclear Plant 50-255 47  Massachusetts Institute of Technology 50-20 11
Massachusetts Institute of Technology 50-20 11
Research Reactor Palo Verde Nuclear Station, Unit 1 STN-50-528 291
William B. McGuire Nuclear Station, 50-369 207 Palo Verde Nuclear Station, Unit 2 STN-50-529 292 Unit 1
William B. McGuire Nuclear Station, 50-370 209  William B. McGuire Nuclear Station, 50-370 209
Unit 2 Palo Verde Nuclear Station, Unit 4 STN-50-592 303
Midland Plant, Unit 1 50-329 160 Palo Verde Nuclear Station, Unit 5 STN-50-593 303
Midland Plant, Unit 2 50-330 162 Peach Bottom Atomic Power Station, 50-171 19 Unit 1
Midwest Fuel Recovery Plant 50-268 64 Peach Bottom Atomic Power Station, 50-277 74
Millstone Nuclear Power Station 50-245 35 Unit 2 Unit 1
Peach Bottom Atomic Power Station, 50-278 76  Millstone Nuclear Power Station, 50-336 173 Unit 3  Unit 2
Pebble Springs Nuclear Plant, Unit 1 50-514 285 Millstone Nuclear Power Station, 50-423 242
Unit 3 Pebble Springs Nuclear Plant, Unit 2 50-515 285
Monticello Nuclear Generating Plant 50-263 56 Pennsylvania State Univ. Research 50-5 9 Reactor
National Bureau of Standards Reactor 50-184 20 Perkins Nuclear Station, Unit 1 STN-50-488 274
National Naval Medical Center 50-170 19 Perkins Nuclear Station, Unit 2 STN-50-489 275
Nine Mile Point Nuclear Station, 50-220 28 Unit 1 Perkins Nuclear Station, Unit 3 STN-50-490 276
Nine Mile Point Nuclear Station, 50-410 234 Perry Nuclear Power Plant, Unit 1 50-440 246
Unit 2 Perry Nuclear Power Plant, Unit 2 50-441 248
North Anna Power Station, Unit 1 50-338 174 Phipps Bend Nuclear Plant, Unit 1 STN-50-553 299
North Anna Power Station, Unit 2 50-339 177 Phipps Bend Nuclear Plant, Unit 2 STN-50-554 300
North Anna Power Station, Unit 3 50-404 231 Pilgrim Nuclear Power Station, Unit 1 50-293 99
North Anna Power Station, Unit 4 50-405 232 Pilgrim Nuclear Power Station, Unit 2 50-471 271
North Carolina State Univ. PULSTAR 50-297 108 Reactor Pilgrim Nuclear Power Station, Unit 3 50-472 27
North Coast Nuclear Plant, Puerto Rico 50-376 214 Plum Brook Reactor - Mock-up 50-185 20
Nuclear Fuels Recovery and Recycle Center 50-564 301 Plum Brook Research Reactor Facility 50-30 1
Oconec Nuclear Station, Unit 1 50-269 64 Point Beach Nuclear Plant, Unit 1 50-266 66
Oconce Nuclear Station, Unit 2 50-270 66 Point Beach Nuclear Plant, Unit 2 50-301 110
Oconee Nuclear Station, Unit 3 50-287 90 Prairie Island Nuclear Station, Unit 1 50-282 84

Name	Docket	Page	Name	Docket	Page
Prairie Island Nuclear Station, Unit 2	50-306	117	Virgil C. Summer Nuclear Station, Unit 1	50-395	224
Purdue Univ. Research Reactor	50-182	20		50-582	20.3
Quad-Cities Station, Unit 1	50-254	45	Sundesert, Unit 1	50-583	303
Quad-Cities Station, Unit 2	50-265	58	Sundesert, Unit 2	50-280	30.3 79
Rancho Seco Nuclear Generating	50-312	124	Surry Power Station, Unit 1 Surry Power Station, Unit 2	50-280	81
Station	50.102	20			
Rhode Island & Providence Plantations AEC	50-193	20	Susquehanna Steam Electric Station, Unit 1	50-387	216
River Bend Station, Unit 1	50-458	263	Susquehanna Steam Electric Station, Unit 2	50-388	218
River Bend Station, Unit 2	50-459	264	Texas A&M Univ. Research Reactor	50-59	13
H. B. Robinson Plant, Unit 2	50-261	55	Texas A&M Univ. Research Reactor	50-128	13
Rockwell International Corp. Critical Facility	50-147	16	Three Mile Island Nuclear Station, Unit 1	50-289	91
RPI Critical Experiment	50-225	30	Three Mile Island Nuclear Station, Unit 2	50-320	135
Salem Nuclear Generating Station,	50-223	70	TRIGA Thermionic Prototype Reactor		30
Unit 1	30-212	70	Trojan Nuclear Plant	50-227	180
Salem Nuclear Generating Station, Unit 2	50-311	121	Turkey Point Plant, Unit 3	50-344 50-250	41
San Onofre Nuclear Station, Unit 1	50-206	22	Turkey Point Plant, Unit 4	50-251	43
San Onofre Nuclear Station, Unit 2	50-361	192	UCLA Training Reactor	50-231	16
San Onofre Nuclear Station, Unit 3	50-362	195	Union Carbide Research Reactor		13
Seabrook Nuclear Station, Unit 1	50-340	179	Univ. of California at Irvine Research Reactor	50-54	153
Seabrook Nuclear Station, Unit 1	50-443	250	Univ. of California at Santa Barbara Research	50-326	243
Scabrook Nuclear Station, Unit 2	50-444	251	Reactor	50-433	243
Sequoyah Nuclear Plant, Unit 1	50-327	153	Univ. of California Research Reactor	50-224	30
		157	Univ. of Florida Training Reactor	50-83	14
Sequoyah Nuclear Plant, Unit 2	50-328 50-322	145	Univ. of Illinois LOPRA Research Reactor	50-356	191
Shoreham Nuclear Power Station  Skagit Nuclear Power Project, Unit 1		291	Univ. of Lowell Research Reactor	50-223	30
Skagit Nuclear Power Project, Omt 1	STN-50-522	291	Univ. of Maryland Research Reactor	50-166	19
South Texas Project, Unit 1	STN-50-523	277	Univ. of Missouri Research Reactor	50-123	14
South Texas Project, Unit 2	STN-50-498		Univ. of Missouri Research Reactor	50-186	20
State Univ. of New York Research	STN-50-499	280	Univ. of Oklahoma Research Reactor	50-112	14
Reactor	50-57	13	Univ. of Washington Research Reactor	50-139	16
Sterling Power Project, Nuclear, Unit 1	STN-50-485	273	Univ. of Wisconsin Research Reactor	50-156	19
St. Lucie Plant, Unit 1	50-335	171	U. S. Geological Survey Research Reactor	50-274	72
St. Lucie Plant, Unit 2	50-389	219	Vermont Yankee Nuclear Power Station	50-271	68

Name	Docket	Page	Name	Docket	Page
Virginia Polytechnic Institute Training Reactor	50-124	14	WPPSS Nuclear Project, Unit 1	50-460	265
Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	242	WPPSS Nuclear Project, Unit 2	50-397	226
Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	243	WPPSS Nuclear Project, Unit 3	STN-50-508	283
Washington State Univ. Research Reactor	50-27	12	WPPSS Nuclear Project, Unit 4	50-513	284
Waterford Generating Station, Unit 3	50-382	215	WPPSS Nuclear Project, Unit 5	STN-50-509	284
Watts Bar Nuclear Plant, Unit 1	50-390	221	Yankee-Rowe Nuclear Power Station	50-29	12
Watts Bar Nuclear Plant, Unit 2	50-391	222	rankee-Nowe rancical rower station	30-27	12
Westinghouse Critical Experiment	50-87	14	Yellow Creek Nuclear Plant, Unit 1	STN-50-566	302
Westinghouse Test Reactor	50-22	11	Yellow Creek Nuclear Plant, Unit 2	STN-50-567	302
West Valley Reprocessing Plant	50-201	20	William H. Zimmer Nuclear Station, Unit 1	50-358	191
Wolf Creek Generating Station	STN-50-482	271	Zion Nuclear Power Station, Unit 1	50-295	103
Worcester Polytechnic Institute Research Reactor	50-134	15	Zion Nuclear Power Station, Unit 2	50-304	114

	·		
		•	1

## **DOCKETED ITEMS**

#### LOW LEVEL RADWASTE DISPOSAL SITES

#### DOCKET 27-010 BEATTY, NV

8009110578 Notice of nonroutine event involving Agreement State or agreement math 80-30 State of NV reported three incidents of low level raduasts shipments which did not conform w/ regulatory requirements Hoeting scheduled for 800910-11 KERR.8 W. LUBENAU.1. O Office of State Programs, Director 80/09/05 in

#### DOCKET 27-039 SHEFFIELD, IL . NUCLEAR ENGINEERING CO

- 8009040055 Forwards Waste Packaging Insp Rept 15000039/80-10 on 80070B No noncompliance noted 8TOHR.J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/07/16 2pp
- --8009040068 Waste Packaging Insp Rept 15000039/80-10 on 800708 No noncompliance noted Major areas inspected compliance w/DOT // NRC regulations POTTER.J P. BROWN.R A Region 2. Atlanta. Fuel Facility & Materials Safety Branch 80/07/15 4pp
- 8009110099 Forwards Waste Packaging Insp Rept 15000039/80-12 on 800617-20 No noncompliance noted STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Bafety Branch 80/07/29 2pp
- --8009110208 Waste Packaging Insp Rept 15000039/80-12 on 800617-20 No noncompliance noted Major areas inspected shipping paper requirements, radiation levels & removable contamination, DDT & NRC requirements for external package features MACARTHUR, T C , POTTER. J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/07/28 5pp
- 8009090331 Petition for review of ASLAB 800812 decision affirming ASLB order which dismissed application for expansion Alleges error in decision that ASLB action did not constitute major faderal action Certificate of Svc encl
  CANNON.J M. HANAT.S W. Nuclear Engineering Co., Inc., (subs of Teledyne. Inc.) GANNON,J M. Mid-America Legal Foundation
  80/07/02 12pp
- 8009220179 Advises that Geo-Ctrs.Inc will visit site on 800908-12 to collect independent info using subsurface pulsed radar detection equipment SMITH.R D Low Level Waste Licensing Branch 80/09/03 ip
- B009230055 Advises that Geo-Ctrs.Inc will visit site on B00908-12 to collect independent info using subsurface pulsed radar detection equipment
  SMITH.R D Low Level Waste Licensing Branch 80/09/03 ip
- B009090400 Order granting extension until 800917 for Commission to elect whether to review ALAB-606 re low level radwaste disposal site HOYLE.J C Office of the Secretary of the Commission B0/09/05
- 8009120409 Order re 8000928 prehearing conference, determining issues in controversy re passession of SNM & unilateral termination of license Discovery requests to be made by 801010, objections by 801020, responses by 801101 motions by 801115 GOODHOPE, A C Atomic Safety and Licensing Board Panel 80/09/09 3pp
- 8009250002 Motion for clarification of ASLB 800909 prehearing conference order which determined issues to be litigated Guestions relationship between unilateral termination, appropriate termination & possession W/Certificate of Svc LESEY.R P Antitrust Division 80/09/23 7pp

- 8009300019 Order granting extension until 801006 for Commission to consider petition for review CHILK-S J Office of the Secretary of the Commission 80/09/24
- DOCKET 27-047 BARNWELL, SC . CHEM-NUCLEAR SYSTEMS
- 8009100067 Provides SC Bureau of Radiological Health w/signed copy of statement of cooperation to establish basis for preparation of joint environ assessment SHITHERD Low Level Waste Licensing Branch 80/06/30 1p
- --8009100072 Forwards signed copy of statement of cooperation to establish basis for preparation of joint environ assessment. Statement of work is acceptable SHEALY.H O South Carolina, State of, 80/05/27 ip
- --B009100076 Statement of cooperation between State of BC (Agreement State) & NRC to establish basis for preparation of joint environ assessment for low level waste disposal operation SHEALY.H G South Carolina, State of SMITH.R D Low Level Waste Licensing Branch 80/06/19 2pp
- DOCKET 27-048 RICHLAND, WA . NUCLEAR ENGINEERING CO
- 8009110650 PNO-V-80-061 on 800728.State of WA banned Radiac Research Corp from use of disposal site at Richland, WA Action is based on noncompliance identified by state & NRC inspectors THOMAS.R.D Region 5, San Francisco, Office of the Director 80/07/28. 10
- 8009290123 Forwards Waste Packaging Insp Rept 15000046/80-65 on 800527-30 & notice of violation DAVIS.A D Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/08/18 2pp
- --8007270126 Notice of violation from unsp on 800527-30
  \* Region 3, Chicago, Office of the Director 80/07/23 ip
- --8009290131 Waste Packaging Insp Rept 15000046/80-45 on 800527-30
  Noncompliance noted failure to meet strong, tight package
  requirement contained in DUT regulation
  LOVENDALE,P C . THUMAS,R D Region 3. Chicago, Office of the
  Director BODK,H E Region 3. Chicago, Fuel Facility & Materials
  Safety Branch 80/07/23 2pp
- 8009120125 Forwards closure plan for Hanford commercial low level waste disposal facility Intent is to continue to operate facility until lease termination or facility capacity is reached, whichever comes first DE POIX.V P Nuclear Engineering Co , Inc., (subs. of Teledyne, Inc.) 80/08/20 3pp
- --B009120137 "Closure Plan Hanford Commercial Low Level Waste Disposal Facility, Hanford Reservation, WA " \* Law Engineering Testing Co B0/05/28 10pp
- ---B009120144 Informs of staff position on status of License 16-17204-01 re continued disposal of SNM at Richland, HA low level radwaste disposal site Requests preliminary site closure design plan
  MARTIN, J B Division of Haste Management 80/07/31 3pp
- --9009120156 Responds to 791219 itr re 1968 license renewal application NRC denied application Rejects proposed License 16-19204-01. No basis for NRC jurisdiction exists re author activities at Hanford.

  NEEL, J N Nuclear Engineering Co . Inc . (subs. of Teledyne, Inc.) 80/02/04 3pp

- 8009300312 Ack receipt of 800822 ltm informing NRC of steps taken to correct violations noted in IE Imap Rept 50-344/80-17 BOOK/H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/09/12 1p
- --8009300314 Responds to NRC 800806 ltr re violations noted in IE Insp Rept 50-344/B0-17 Corrective actions procedure implemented requiring checklist be used during inse of drums prior to shipment to verify proper labeling 600DNIN.C Portland General Electric Co 80/08/22 3pp
- --8009390318 Forwards IE Insp Rept 50-344/80-17 on 800517 & notice of violation 800X.H E. Region 5. San Francisco, Fuel Facility & Materials Safety Branch 80/08/06 2pp
- --8009300319 Natice of violation from insp on 800619, # Region 5, San Francisco, Office of the Director 80/08/05 Pan
- --8009300324 IE Insp Rept 50-314/60-17 on 800619 Noncompliance noted failure to mark two drums "Radioactive-LSA" & one container appeared to fail requirement of strong tight package FONG. T. HENSLAMSKI.F. A. Region 5. San Francisco. Office of the Director BOOK.H E. Region 5. San Francisco. Fuel Facility & Materials Safety Branch. 80/08/05 7pp

#### DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0299 UNION CARBIDE CORP

- 8009020498 Forwards NUREO-0702. "FES re Operation of Gas Hills U Project." & FR notice of availabilities SCARANO.R A Uranium Recovery Licensing Branch 80/08/20 ip
- --8009020504 "FES Re Operation of Oas Hills U Project" # Division of Waste Management NUREC-0702 80/07/31 252pp
- 8008130375 Forwards "A-9 Pit.Leaky Aquifer Tests " Test indicated hydrologic communication through mudstone unit which separates upper & lower wand river formations WOND.Y Union Carbide Corp 80/08/05 ip
- --8008130378 "A-7 Pit,Leaty Aquifer Tests " Three oversize drawings encl RICE:T . HOFFMAN.O L. Hydro-Engineering 80/08/05 41pp
- 8004160549 Farwards rept for QC testing of evaporation pends includes work performed 800717-30 H6NG,T Union Carbide Corp 80/08/07 45pp
- 8009240721 Forwards 18 Insp Rept 40-0279/80-01 on 800522-29 No noncompliance noted. BROWN, Q D Region 4. Dallas, Fuel Facility & Materials Safety Branch 80/08/16 2pp
- --8009240729 IE Insp Rept 40-0299/80-01 No noncompliance noted Major areas inspected. U mill operations, radiation protection program, facilities & equipment, training, environ monitoring & internal review HUSTAIN, M. J. Region 4. Dailas, Office of the Director GORDON, C. Office of State Programs, Director BROWN, O. D. Region 4. Dailas, Fuel Facility & Materials Bafety Branch 80/08/13 Spp
- 8009090390 Ferwards FES on Gas Hills U project W/o enci. Linehan. J J Uranium Recovery Licensing Branch 80/08/18 is
- 8009/10770 Forwards final rept. "Eask Cas Hills, MY.U Millsite Evaluation " # Barr Engineering Co 80/08/25 ip
- --8009110774 "East Gas Hills, WY, U Killsite Evaluation "
   Barr Engineering Co 80/08/25 20pp
- '109170373 Responds to 800215 & 0609 ltrs commenting on DES Addresses specific concerns re wildlife & vegetation, wildlife & cattle sposore pathways & monitoring wells CARANG, R A Uranium Recovery Licensing Branch. 80/08/27 8pp
  - 109170376 Submits comments re-wildlife & vegetation & cattle & wildlife exposure pathways for consideration in connection w/final E18.

    ANIELBON.L.J National Wildlife Federation 80/02/15 7pp

- 8009120390 Forwards Miller Testing Co results in response to NRC request for lab pinhole test conducted on clay sample taken from liner matl used for evaporation ponds Sample results show intermediate dispersivity

  WONG.T Union Carbide Corp 80/09/08 2pp
- 8009300281 Notification of contract execution "Union Carbide East Gas Hills, WY U Mill Site," awarded to Barr Engineering Co HAIRSTON.C Technical Assistance Contracts Branch FIN B-6941-0 80/07/07 ip
- ~~8009300284 Contract "Union Carbide East Gas Hills.WY U Hill Site "
  awarded to Barr Engineering Co
  BARR, D W Barr Engineering Co DOUGHERTY, D J Fechnical
  Assistance Contracts Branch FIN B~6941~0 80/09/09 Spp

#### DOCKET 40-0672 NUCLEAR METALS, INC

8009120595 States understanding per 800804 telcon confirming 800801 commitments on upgrading low level waste packages prior to shipment for burial NRC must be informed within 24-h if specified actions are not in accordance w/actual plans GRIER.8 H Region 1, Philadelphia, Office of the Director 80/08/07 ip

#### DOCKET 40-0791 UNITED TECHNOLOGIES, INC.

8009300537 Responds to IE Bulletin 80-22, "Failures of Hestinghouse Type W-2 Spring Return to Neutral Control Switches " No Automation Industries source assemblies owned or operated MANITYNIECKI.P United Technologies Corp., Pratt & Whitney Aircraft Group 50/09/24 ip

#### DOCKET 40-1162 WESTERN NUCLEAR. INC

- 8009260041 Forwards tailings dam insp rept for 800728-0803 BDQDEN.0 Western Nuclear, Inc. (subs. of Phelps Dodge Corp.) BO/08/05 4pp
- 8009180193 Forwards IE Insp Rept 40-1162/80-01 on 800714-15 No noncompliance noted BROWN-8 O Region 4, Dallas, Fuel Facility & Materials Safety Branch 80/08/08 2pp
- --B009180203 IE Insp Rept 40-1162/80-01 on 800714-15 No noncompliance noted Major areas inspected training facilities & equipment, internal exposure control environ monitoring fire protection & waste mgt
  BROWN, 0 D Region 4, Dalias, Fuel Facility & Materials Safety
  Branch WILBORN, L, SHOPENN, N M Region 4, Dallas, Office of the Director 80/08/04 App
- 8009180419 Forwards Bplit Rock mill tailings dam insp rept for 800804-10 BODDEN.G Western Nuclear, Inc. (subs. of Phelps Dodge Corp.) 80/08/11, 4pp
- 8009190550 Forwards Split Rock mill tailings dam insp rept for 800911-17 BBQDED.O Høstern Nuclear, Inc. (subs. of Phelps Dodge Corp.) 80/08/19 4pp
- 8009020420 Responds to inquiry made during 800813 meeting in Denver re Commission authority to deal w/license violations Cites relevant acts Congress has increased agency authority to impose civil forfeitures REIS.E.J Hearing Branch 3. 80/08/28 ip
- 6007300141 Forwards trailings dam insp rept for 800825-31 BOGDEN, 0 Western Nuclear, Inc. (subs of Phelps Dodge Corp.) 80/09/03 ip
- 8009120407 Order directing MY Outdoor Council to file suppl to 800625 amended petition to intervene w/specified contentions.by 801010 Applicant & NRC responses shall be filed by 801031 after which prehearing conference will be scheduled WOLFE.8 J Atomic Safety and Licensing Board Panel 80/09/09 Rpp
- DOCKET 40-1341 EDGEMONT URANIUM MINE. TVA & MINES DEVELOPMENT, INC.
- 800722003B Forwards "Semiannual Effluent Release Rept Number 10, Jan-June 1980" & errata sheet MILLS,L M Tennessee Valley Authority 80/08/13 1p

- --8009220041 "Semiannual Effluent Release Rept Number 10. Jan-June 1980" & errata sheet
  - \* Tennessee Valley Authority RH-BD-4-ED2 B0/07/31 Bpp
- 8009120562 Responds to 800721 request for DES re Edgemont U mill decommissioning Statement being prepared Recipient being placed on distribution list TRAGER.E A Uranium Recovery Licensing Branch 80/08/27 ip
- --8009120565 Requests DES re decommissioning of Edgemont U mill LEMSKE,B Affiliation Unknown 80/07/21 lp
- 8009300277 Responds to NRC 800828 request by forwarding procedures for in-site permeability packer testing performed during gastechnical study info required for review of preliminary geotechnical study rept MILLS,L M Tennessee Valley Authority 80/09/03 ip
- --8009300280 "In-Site Permeability Packer Testing"
  \* Yennessee Valley Authority 80/09/03 4pp
- DOCKET 40-2061 WEST CHICAGO FACILITY, KERR-MCGEE CORP
- 8009040087 Forwards rept of special survey performed 791127.800110 & 17 & ANL bloassay measurements on individuals who have been accupants of facility bldg KEPPLER.J G Region 3. Chicago. Office of the Director 80/07/17 10ms
- --8009040099 Requests that W-1 bldg at 185 West Mashington Street.West Chicago, IL, be removed from license Bldg has been surveyed for radiation & is within decontamination guidelines Radiological survey encl CRAIO, L Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp ) 74/06/13 7pp
- --8009040104 Advises NRC that gamma-ray spectrometric analysis was performed on three samples from West Chicago to qualitatively determine which nuclides were present GOLCHERTIN W Argonne National Laboratory 79/12/21 ip
- --8009040109 "Ovidelines for Decontamination of Facilities & Equipment Prior to Release for Unrestricted Use or Termination of Licenses for Byproduct, Source or SNM " 4 Atomic Energy Commission 73/12/31 25pp
- 8009050358 Advises of restrictions & objections re proposed plan of Kerr-McQee Chemical Co to install incinerator for purpose of reducing vol of thorium contaminated matl disposed of by burial RENNELBIA.E Illinois, State of 80/07/29 3pp
- 8009260021 Objects to proposed onsite burial of nuclear matts on behalf of City of West Chicago RENNELS,A E Illinois, State of 80/08/05 ip
- 8009300218 Forwards comments on Kerr-McGee Chemical Corp revised plan for decommissioning & stabilizing facilities Environ sampling program for Kress Creek is not adequate to identify possible deleterious effects from plan implementation MCGUIRE, J Environmental Protection Agency 80/08/ii i3pp
- 8009160132 Ack receipt of 800729 comments on Kerr-McGee application for amend of license, authorizing incineration of therium wastes at West Chicago site Info required for Commission approval encl
  CROW, W T Uranium Fuel Licensing Branch 80/08/12 2pp
- 8009190118 Forwards 800715 survey of bldg at 185 West Washington Avenue:West Chicago, IL. on 791127, 800110, 17 & 0513 DAVIS:A B Region 3. Chicago, Fuel Facility & Materials Safety Branch. 80/08/20 ip
- --B009190121 IE special survey of bldg at 185 West Mashington Avenue.West Chicago, IL on 791127, 800110, 17 & 0513 Major areas of contamination ctr sewer pipe, drain pipes, duct in microfilm developing room, two areas of attic floor & others NICHOLSONN A. SHATTERLY, L. W. Region 3, Chicago, Office of the Director DAVIS.A. B. Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/07/15 10pp,
- --8009190123 "Radiological Survey for Kerr McGer Facility, W-1 Bldg, West Chicago, IL GUTWEIN, E.E., TROUTNAN, M. Eberline Instrument Corp. 74/05/06

- 8009180440 Responds to 800807 request for matls referred to in 800715 memo to file re-criteria related to waste disposal & site decommissioning NIKON.W A Uranium Fuel Licensing Branch 80/09/03 2pp
- --8009180447 Forwards "Fuel Processing & Fabrication Branch Interim Land Cleanup Criteria for Decommissioning U Mill Sites " ROUSE.L C Fuel Process & Fab Branch (Pre 790727) 78/05/24 to
- --8009180449 "Fuel Processing & Fabrication Branch Interim Land Cleanup Criteria for Decommissioning U Mill Sites " \* Advanced Fuel & Spent Fuel Licensing Branch 78/05/24 24pp
- ---8009180453 "Ouidelines for Decontamination of Facilities & Equipment Prior to Release for Unrestricted Use or Termination of Licenses for Byproduct, Source or SNN "
  Division of Fuel Cycle & Material Safety 75/11/30 Spp
- DOCKET 40-2259 PATHFINDER MINES CORP
- 8007170077 Advises that License SUA-172 is amended by revision of Condition 39, authorizing transfer of tailings samples for environ research purposes
  8CARANO,R A Uranium Recovery Licensing Branch 80/06/26 1p
- 8009180027 Forwards IE Insp Rept 40-2259/80-02 on 800721 No noncompliance noted BRCMN.9 D Region 4, Dallas. Fuel Facility & Materials Safety Branch 80/08/08 1p
- --8009180033 IE Insp Rept 40-2259/80-02 on 800721 No noncompliance noted Major areas inspected const activities in progressinsp & testing records re license conditions & SER requirements BROWN.0 Region 4. Delias. Fuel Faculity & Materials Safety Branch QALLAGHER.E J Region 3. Chicago. Office of the Director 80/08/11 13pp
- B009260045 Notifies of delay in completion of Tailings Dam 4 Excavation required to properly prepare foundation has increased over that estimated by design engineers Requests meeting during who of B00825 NUGENTLE L Pathfinder Mines Corp 80/08/13 2pp
- 8009030510 Notifies that 10% placement of embankment fill on Tailings Dam 4 will be completed on approx 800918.per License SUA-672 Requests info re insp plans NUGENT.E L Pathfinder Mines Gorp 80/08/28 ip
- 8009110402 Forwards "Semiannual Effluent Monitoring Rept, Jan-June 1980" NUJENT.E L Pathfinder Mines Corp 80/08/29 1p
- --8009110404 "Semiannual Effluent Monitoring Rept, Jan-June 1980 "
  4 Pathfinder Mines Corp 80/08/29 9pp
- --8009110407 "General Land Use Within 5 Mile Distance of Lucky McMill "
  \* Pathfinder Mines Corp 90/08/27 ip
- 8009160349 Responds to Point 2(a) of summary of conclusions & commitments per 800912 telcon & 0825 meeting Total vol of liquid stored upstream, effective 800829, summarized NUGENT.E L. Pathfinder Mines Corp 80/09/12 ip
- 8009190393 Notifies that Chen & Associates will complete design review re tailings Dam 4 by 801015 Data will be forwarded following review NUGENT.E.L. Pathfinder Mines Corp. 80/09/15 ip
- DOCKET 40-2940 NL INDUSTRIES. INC.
- B007120132 Forwards NL Nuclear route w/revised guidance NUREG-0541, reflecting latest amend to interim rule for physical protection of irradiated reactor fuel in transit Requirements must be implemented by B00703 M/o encis MCCORKLE.G W Physical Security Development Branch 80/07/07 ip
- 8009120201 Ack receipt of 800709 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-2940/79-01 KINNEMAN, J D Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/07/31 ip

- --B009120220 Responds to NRC 791204 ltr re violations noted in IE Insp Rept 40-2940/79-01 Corrective actions smear test performed on mfg parts & personnel instructed on how to perform smear VUMBACO, F J NL Industries. Inc 80/07/09 20p
- --8009120222 Discusses IE Insp Rept 40-2940/79-01 on 791108-09 & forwards notice of violation MCCLINTOCK.R O Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/12/04 2pp
- --8009120223 Notice of violation from insp on 791108-09 Noncompliance noted smear surveys not routinely performed to assure plating free of radicactive contaminants Region I, Philadelphia, Office of the Director 79/12/04 ip

#### DOCKET 40-3392 ALLIED CHEMICAL CORP.

- 8009150165 IE Insp Rept 40-3392/80-01 on 800617-19 No noncompliance noted Major areas inspected facility changes & mods audits; safety committees, training, internal exposure control & transportation activities vianiportation activities FISHER N L Region 3, Chicago, Fuel Facility & Materials Safety Branch PECKIC C, Region 3, Chicago, Office of the Director 30/07/24 Spp
- 800930024; Reiterates request for current NRC or agreement state ficense to receive contaminated 55-gallon U ore concentrate empty drums Also expresses interest in visiting facility AJ Cipolla 800701 itr encl CIPOLLA, AJ Allied Chemical Corp 80/08/19 2pp

#### DOCKET 40-3459 ATLAS MINERALS

- 8009110739 Responds to NRC 800717 itr re violations at mill Corrective actions sample meter will be placed upon NRC location designation SWANBY.O T Atlas Kinerals 80/08/07 ip
- 8009080472 Act receipt of 800807 ltr informing NRC of steps taken to carrect violations noted in IE Insp Rapt 40-3453/80-02 BROWN.C D Region 4. Dallas. Fuel Facility & Haterials Safety Branch 80/08/20 1p
- --8009080480 Responds to NRC 800717 ltr re violations noted in IE Insp Rept 40-3453/80-02 Corrective actions will be completed following further instructions from NRC re location of ampler
  'ANBY, G T Atlas Minerals 80/08/07 ip
  - )80475 Forwards IE Insp Rept 40-3453/80-02 on 800623-24 & notice of liation NNL-9, D. Region 4, Dallas, Fuel Facility & Materials Safety Inch 80/07/17 2pp
  - 380482 Notice of violation from insp on 800623-24 Region 4. Dallas, Office of the Director 80/07 80/07/15 10
  - 7080487 IE Insp Rept 40-3453/80-02 on 800623-24 Noncompliance noted onthly background sampling for Rn-222 not performed & regetation foliage not analysed for Ra-226 SROUN-0 D Region 4, Dallas, Fuel Facility & Materials Safety Branch WILBORN.L CAIN.C L Region 4, Dallas, Office of the Director 80/07/15 6pp
  - 70143 Informs requested monthly repts on river samples for Th-230 226 concentrations were mailed 800324 Provides location se ambient sir monitoring stations 0 T Atlas Minerals, 80/08/22 ip

#### 0-4348 COMMERCE, DEPT OF

293 Discusses IE Insp Repts 40-4348/80-01,30-03918/80-01, 894/80-01,30-03919/80-01 % 30-11675/80-01 on 800619-20 acompliance noted Major areas inspected selected is & procedures,measurements & observations fall,J D Region I, Philadelphia, Fuel Facility & Materials g Branch 80/06/11 2pp

- DOCKET 40-4492 FEDERAL AMERICAN PARTNERS (MINING)
- 8009110266 Forwards responses to 800522 & 0703 interrogatories, responses to questions arising from 800707 meeting & RAD data sheets Responses to Questions 34 & 35 of 800703 interrogatories are omitted, due to incomplete info PIERSON, O W Federal American Partners 80/08/29 210pp
- BO09020193 Advises that organization is on distribution list to receive Federal-American Partners' DES when completed & all EIS issued by Uransum Recovery Licensing Branch per B00723 request Natl Wildlife Federation 800723 ltr encl LINEHAN, J J Uranium Recovery Licensing Branch 80/08/11 ip
- --8009020200 Requests addition of name to distribution list to receive DES on Federal-American Partners' U mill & info restatus of relicensing & expension project DAMIELSON.L. J. Colorado State Univ 80/07/23 2pp
- 8009190779 Forwards "Preliminary Process Water Balance for Expanded Mill Operation," Figure 3 3-2 in environ rept revised 800800 ADAMS.DP Kaiser Engineers 80/08/12 200
- 8009170234 Forwards data sheets of principle parameters for radiological assessment PIERSON O W Federal American Partners 80/08/14 10pp
- 8009100193 Summary of B00717 meeting u/Federal-American Partners.GRNL & consultants in Silver Spring.MO re status of DES & outstanding requests for add1 info & outstanding environ review issues GILLEN,D // Uranium Recovery Licensing Branch 80/08/20 iipp
- 8009100654 Forwards water quality & air sampling data for 800101-0701 Drawing encl ANDRUS.N J . LANE.J R Federal American Partners 80/08/28 113pp.
- --8009100657 "Environ Monitoring Stations "
  \* Federal American Partners 80/08/27 ip

#### DOCKET 40-4826 NORTHWESTERN UNIV

- 8009110827 Requests amend to Licenses 12-00382-03,12-00382-05, 12-00094-06,SUD-556 & SNK-33D to reflect encl membership of radiation safety committee
  MILLER, D.R. Northwestern Univ 80/06/25 2pp
- -BOD9110831 Notifies that amend to Licenses 12-00382-03,12-00382-05, 12-00094-06,SUD-556 & BNM-330 is fee exempt COOPER.J. Region 3. Chicago, Office of the Director 80/06/30

### DOCKET 40-6659 PETROTOMICS CO , GETTY OIL

- 8009100069 Forwards data on whole body counts for 780201,0618,790905 & 0730
  PFAFF,S Getty Dil Co , Petrotomics Co Div 80/06/02 8pp
- 8009100188 Forwards IE Insp Rept 40-6659/80-02 on 800515-16 & 0603 & notice of violation SEYFRIT, K. V Region 4. Dallas, Office of the Director 80/06/18.
- --8009100191 Notice of violation from insp on 800515-16 & 0603 \* Region 4. Dallas. Office of the Director 80/06/18 2
- --B009100199 IE Insp Rept 40-6659/80-02 on B00515-16 & 0603 Noncompliance noted failure to obtain NRC approval prior to transferring tailings & failure to sample for radon in mill CAIN.C L Region 4. Dallas, Effice of the Director BROWN, 0 PRegion 4. Dallas, Fuel Facility & Materials Safety Branch 80/06/18 Spp
- ---8009100205 Ack receipt of 800710 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept A0-6659/80-02 Add1 info re use of half mask respirators required BRCWN.9 D Region 4, Dallas, Fuel Facility & Materials Safety Branch 80/07/28 ip

- --8009100212 Responds to NRC 800618 ltr re violations noted in IE Insp Rept 40-659/80-02 Corrective actions application for amend submitted to allow transfer of tailings to research facilities PFAFF,8 J Getty Oil Co . Petrotomics Co Div 80/07/10 2pp
- --8009100217 Ack receipt of 800710 & 0808 litrs informing NRC of steps taken to correct violations noted in IE Insp Rept 40-6659/80-02 SEYFRIT, K V Region 4, Dallas, Office of the Director 80/08/21
- --8009100222 Responds to NRC 800728 ltr re violation re half mask respirators noted in IE lnsp Rept 40-6659/80-02 Personnel instructed & areas posted where half mask respirators will not suffice H/o encl documentation
  PFAFF.8 J Oetty Oil Co , Petrotomics Co Div 80/08/08 1p
- 8008080187 Forwards Hydro-Engineering rept, "Geologic & Monitor Well Info for Petrotomics Tailings Reservoir Area " Rept info requested in Section 258 i of Amend 7 to License SUA-551 " Rent contains PFAFF, B J Cetty Dil Co , Petrotomics Co Div 80/07/30 1p
- ---8008080\$93 "Geologic & Monitor Well Info for Petrotomics Tailings Reservoir Area " Oversized drawing end 1 PLAYTON,S J Hydro-Engineering 80/07/31 10pp
- DOCKET 40-8027 KERR-MCGEE CORP
- 8009300656 Application for amend of License 508-1010, authorizing controlled release of hay grown on land fertilized w/raffinate Justification for amend encl SHELLEY,W J Kerr-McGeg Nuclear Corp 80/08/15 . 80/08/15 7pp
- DOCKET 40-8084 LISSON MINE, RIO ALGOM CORP
- 8009120603 "Rept of Ocotechnical Evaluation to Support Request for 5-Ft Dam Raise.Upper Tailings Pond Embankment Sys, Lisbon Valley Operations " \* Dames & Moore 80/08/2⊋ 40pp
- 8009100936 Discusses Region 4 enforcement action as result of recent insp Requests participation w/region in mgt meeting planned w/Rio Algom officials SCARAND,R A Uranium Recovery Licensing Branch. 80/08/25 ip
- BOD9300520 Discusses Dames & Moore "Rept of Geotechnical Evaluation to Support Request for 5-ft Dam Raise " Urges early approval for commencement of const LAWTON.M D Rio Algom. Ltd 80/08/27 2pp
- DOCKET 40-R092 NASA
- 8009300180 Forwards IE Bulletin 79-19, "Packaging of Low Level Radwaste for Transport & Burjal " Response remished for Transport & Burial "Response required
  SEYFRIT, K V Region 4, Dallas, Office of the Director 79/08/10
- --8009300185 Responds to IE Bulletin 79-19, "Packaging of Low Level Radwaste for Transport & Burial " Radwaste transferred to contractor JOHNSTON, R. B. National Agronautics & Space Admin 79/09/18 2pp
- DOCKET 40-8102 EXXON MINERALS CO. USA, EXXON CORP.
- 8007100288 Forwards hydrologic review of Exxon Minerals tailings disposal site at Highland Mine & Hill site Land Quality Div favors below grade disposal at Exxon site to minimize environ degradation for future tailings ACKERMAN. H C Hyoming. State of 80/07/29 26pp.
- B009020123 Summary of 800630,0701 & 02 site visits by WY Dept of Environ Quality.WY Mineral Co & Exxon to WY Mineral Irigaray Site:Exxon Highland Site & Rocky Mountain Energy Bear Creek to observe water quality monitoring program VANDELL,T D Uranium Recovery Licensing Branch 80/08/11 6pp

#### PROCKET 40-8113 UTAH, UNIV OF

- 8009150364 Act receipt of 800731 ltr informing NRC of steps taken to correct violations noted in 1E lnsp Repts 30-05219/80-02 & 30-14452/80-02 SU-14452/BU-VZ KINNEMAN.J D Region I. Philadelphia. Fuel Facility & Materials Safety Branch BO/OB/II ip
- --8009150373 Responds to NRC 800703 ltr re violations noted in IE Insp Repts 30-05219/80-02 & 30-14452/80-02 Corrective actions monthly & annual check list sys instituted & steps taken to document complete & proper evaluation procedures SCHULTZ.DF Teledyne Isotopes 80/07/31 2pp
- --R0091503R0 Discusses IE Insp Repts 30-05219/80-02 & 30-14492/80-02 on 800614 & forwards notice of violation KINNEMAN, J D. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/07/03 2pp
- --80091503B7 Notice of violation from insp on 800614 Noncompliance noted failurs to adequately evaluate 80032B release to sewage sys from holdup tank & failure to test sealed sources for leakage or contamination since 79082O \* Region 1, Philadelphia, Office of the Director 80/07/03 1p
- DOCKET 40-8180 OXLAHOMA, UNIV OF
- 8009260390 Forwards IE Bulletin 79-19, "Packaging of Low Level Radwaste for Transport & Burlal " Response required SEYFRIT.X V Region 4. Dallas, Office of the Director 79/08/10
- --8007260408 Responds to IE Bulletin, "Packaging of Low Level Radwaste for Transport & Burial " One shipment of radwaste made since 1978 JAMES, J Oklahoma, Univ of 79/10/16 2pp
- DOCKET 40-834B IN SITU URANIUM LEACHING PROJECT
- BOO9190767 Submits costs incurred & manpower expended for review of BOO125 license application EADIE,0 © Urenium Recovery Licensing Branch BO/09/02 1p
- DOCKET 40-8380 ROCKY MOUNTAIN ENERGY CD
- 8009240153 Forwards revised Table 1 to "Effluent Monitoring Rept.Jan-June 1980," re Pattern III water quality NEUMANN,M R Rocky Mountain Energy Co 80/08/12 2pp
- --8009260159 "Effluent Monitoring Rept, Jan-June 1980, " revised Table I re Pattern III water quality # Rocky Mountain Energy Co 80/08/12 5pp
- 8009240024 Forwards 800714 & 0805 assay results re Pattern III monitor wells No significant change in water quality since last rept Elavated vanadium levels will be corrected w/increased pumping rate NEUMANN, M R Rocky Mountain Energy Co 60/08/14
- 8009170237 Revises Table I from 800812 ltr Correct sulfate mean value in Monitor Well M-40 is 1,225 mg/liter Also, range for vanadium in Well M-41 roversed Correct low value is 0 05 mg/liter & correct high value is 0 7 mg/liter NEUMANN, M R Rocky Mountain Energy Co 80/08/15 ip
- DOCKET 40-8452 DEAR CREEK URANIUM CO
- 8009020123 Summary of 800630,0701 & 02 site visits by WY Dept of Environ Quality, WY Mineral Co & Exton to WY Mineral Irigaray Site.Exxon Highland Site & Rocky Mountain Energy Bear Greek to observe water quality monitoring program VANDELL, T D Uranium Recovery Licensing Branch 80/08/11 6pp
- 8009180072 Forwards IE Insp Rept 40-8452/80-01 on 800716-17 & notice of violation BROWN 0 D Region 4, Dallas, Fuel Facility & Materials Safety Branch BO/OB/13 2pp
- ---8009180076 Notice of violation from into on 800716-17 \* Region 4. Dallas, Office of the Director 80/08 80/08/12 10

- --8009180081 IE Insp Rept 40-8452/80-01 on 800716-17 Noncompliance noted failure to minimize dusting of tailings & to implement means to obtain quarterly gross beta measurements BROWN.0 D Region 4. Dallas. Evel Facility & Materials Safety Branch SHOPENN.N N. WILBORN.L. Region 4. Dallas. Office of the Director 80/08/12 8pp
- 8009180334 Authorizes travel costs & prof svct for R Williams trip to Silver Spring MD re meeting w//RC & licensee to discuss below grade tailings disposal plan SCARANO,R A Uranium Recovery Licensing Branch 80/08/20 Ip
- 8009030462 Forwards semiannual environ monitoring rept for period
- ending 800530 GLOSSOM.J N Bear Creek Uranium Co 80/08/29 ip
- ~-B009030465 Semiannual environ monitoring rept for period ending 800630 \* Bear Creek Uranium Co 80/08/29 10pp
- DOCKET 40-8502 IRIGARAY MINE, WYOMING MINING CORP
- 8009100671 Forwards revised 790508 rept on Irigaray mine excursion potential Changes reflect recent experiences
  DAVIS-D Hydrology Associates, Inc. 79/06/14 14pp
- 8008110036 Forwards 800710 to 14 ltrs to State of MY re leak in Evaporation Pend C & excursion status of Monitor Well 9M-22 Leakage minor Excursion status caused by sulfate (on MICHERS:D L Mycaing Mineral Corp 80/07/14 7pp
- --9008(10038 "Location of 9K-22 & Surrounding RB & Trend Wells "

  Wyoming Mineral Corp 80/07/11 1p
- 8008120614 Forwards 800710 shallow monitor zone status rept & 800714

  Itr re Shallow Monitor Well 988-14 Shallow zone data
  indicates that overall valves are responding to control/
  cleanup program Well 988-14 is off excursion status
  WICHERS.D L. Hyoming Mineral Corp. 80/07/23 20pp
- --800\$120620 "Location of Shallow Zone, Unit 1 Sand & Water Table, Monitor Walls. Units 4 & 5 Shallow Zone Control Program "

  \* Wyoming Mineral Corp 80/06/24 1p
- --8008120626 "Location of Shallow Zone, Unit 1 Band & Water Table. Monitor Wells: Units 4 & 5 Shallow Zone Control Program "

  # Wyoming Mineral Corp 80/06/24 19
- --8008120630 "Location of Shallow Zone.Unit 1 Sand & Water Table.Monitor Wells.Units 4 & 5 Shallow Zone Control Program " + Nyoming Mineral Corp 80/06/24 1p
- --8008120631 "Location of Shallow Zone, Unit I Sand & Water Table, Monitor Wails, Units 4 & 5 Shallow Zone Control Program " \* Myoming Mineral Corp 80/06/24 ip
- 8009170240 Submits rept per Condition 31 for License SUA-1341 Monitor Well 9K-22 is off excursion status Due to sudden increase in sulfate, conductivity & alkalinity & subsequent return to normal source & cause investigations are continuing WICHERS, D. L. Wyoming Mineral Corp. 80/08/01 2pp
- 8009020490 Orders cessation of pumping in all shallow zone wells by 800823 Neekly sampling program will be initiated to determine status of shallow zone excursions in monitor wells SM-4.5M-9.5M-12 & SM-44 MORROW.D Wyoming. State of 80/08/08 ip
- 8009020123 Summary of 800630,0701 & 02 site visits by MY Dept of Environ Quality, MY Mineral Co & Erzon to MY Mineral Irigaray Site:Erzon Highland Site & Rocky Mountain Energy Bear Greek to observe water quality monitoring program VANDELL.T D Granium Recovery Licensing Branch 80/08/11 App
- BODY150023 Confirms 800811 notification re 800807 chloride values in Shallow Unit 1 Sand Well SSM-4 Forwards table showing Initial value 5 most recent sample analysis for BSM Wells 1-5 Downward trend observed in all wells TIEFEL.E W Wyoming Mineral Corp 80/08/12 3pp
- 1009150530 Summarizes 800730 meetings w/E Tiepel & C Chien & NRC & response to data submittal re NRC questions on hydrology rept Urgas high quality & correct analysis in future hydrologic studies Aualits RV Davis data re leakage SCARANO, R A Uranium Recovery Licensing Branch 80/09/03 5pp

- 8009300191 Forwards requested Electric Logs LI-18.LP-17.LP-28.LP-43, KI-138 & KP-53 W/o encis WICHERS.D L Wyoming Mineral Corp 80/09/03 1p
- DOCKET 40-0540 AIR FORCE, DEPT OF
- 8009020533 IE Insp Findings & Licensee Ack on 800711 of License SUB-1282 Insp findings no noncompliance noted \* Region 2, Atlanta, Office of the Director 80/07/11 ip
- DOCKET 40-8584 UNION 76 MINERALS EXPLORATION CO
- 8009110850 Forwards Table 2, "Estimate of Cost of First Yr of Reclamation." from application for permit to mine ACOSTA, A.P. Union 76 Minerals Exploration Co. 80/07/28 2pp
- 8009180089 Forwards 1E Insp Rept 40-8984/80-01 on 800722 No noncompliance noted BROWN, G D Region 4, Dallas, Fuel Facility & Materials Safety Branch 80/08/08 ip
- --809180093 IE Insp Rept 40-8584/80-01 on 800722 No noncompliance noted Major areas inspected insp 2 testing records re license conditions & SER requirements BRONN, O Region 4. Dallas, Fuel Facility & Materials Safety Branck GALLAGHER, E.J. Region 3. Chicago, Office of the Director 80/08/04 23pp
- 8009150476 Ack receipt of 800724 ltr re QC program for urine specimens Request classified as requiring minor amend to License SUA-1350 Minor safety & environ amend fee required WEISC D License Fee Management Branch 80/08/21 ip
- 8009030470 Forwards fee for minor safety amend review is unine analysis GC program ACOBTA-A P Minerals Exploration Co (subs of Union Dil Co of California) 80708/25 ip
- DOCKET 40-8643 NUCLEAR DYNAMICS. INC
- 8009260363 Forwards IE Builetin 79-19. "Packaging of Low Level Radwasts for Transport & Burial " Response required SEYFRIT.K V. Region 4, Dailas, Office of the Director 79/08/10,
- --8009260495 Responds to IE Bulletin 79-i9. "Packaging of Low Level Radwaste for Transport & Burial " No radwaste generated STGICK.A F Nucor Corp 79/10/23 2pp
- DOCKEY 40-8591 ENERGY FUELS NUCLEAR, INC.
- 8009300409 Forwards "Annual Rept Meteorological & Air Quality 16 Observations.White Mesa U Project Near Blanding.UT, June 1979-1980." inadvertently omitted from semiannual effluent rept submitted by D Roberts on 800829 BAKER.C.E Energy Fuels Nuclear. Inc 80/09/25 ip
- --8007300414 "Annual Rept Meterological & Air Quality Observations, White MESA U Project Near Blanding, UT, June 1979-1980." \* Steams-Roger, Inc. 80/07/31. 216pp
- 8009180034 Notifies of Amend 3 to License SUA-1358, revising Conditions 11 & 38 to authorize addition of second crusher unit & to clarify environ monitoring program Other conditions remain unchanged Refs CE Baker 800414 request & 800507 telcon SCARAND, R A. Uranium Recovery Licensing Branch 80/06/04, 2pp
- 8009160845 Requests investigation to determine if Energy Fuels Nuclear, Inc is implementing conditions of license re avoidance, minimizing 8 mitigating adverse effects of project on White Mesa Archeological District MALL.L 8. Advisory Council on Historic Preservation 80/07/25
- 8007170139 Forwards determination of eligibility for inclusion in Natl Register of White Mese Archaeological District District is eligible for inclusion SHULL.C D Interior. Dept of 80/08/11 3pp
- 8009170127 Forwards documentation of insp of Cell 2 PVC liner installation & test results on underdrain inplace densities performed by D'Appolonia Consulting Engineers ROBERTS.H R Energy Fuels Nuclear, Inc 80/08/12, 3pp

8009300237 Submits rept in accordance w/Condition 39 of License 8UA-1358 Survey of land use within 5 miles of facility indicates that use of area has not changed Changing of ownership has occurred but land is still agricultural ROBERTS.D Energy Fuels Nuclear, Inc. 80/08/20 ip

B009100666 Forwards rept of measured concentration of principal radionuclides released to unrestricted area for Jan-June 1980
ROBERTS, D Energy Fuels Nuclear, Inc. 80/08/29 2pp

#### DOCKET 40-8692 COTTER CORP

8009170423 Forwards recent correspondence w/Cotter Corp & Dept of Environ Quality re Charlie Area U Mine reclamation efforts Unable to locate 800626 ltr from Cotter Corp MOUNEY, G Wyoming, State of 80/07/29 7pp

8009160651 Notifies of Amend 1 to License SUA-1370, authorizing reactivation of thin layer leach pilot plant facility to conduct second test in which approx 25 tons per day crushed U ore will be processed for 60 days over 45-day period SCARANQ.R A Uranium Recovery Licensing Branch 80/07/31 3pp

8009190781 Bafety/environ evaluation of Cotter Corp 800626 request for amend to License SUA-1370 authorizing second pilot plant scale test Recommends approval subj to indicated provisions ROTHFLEISCHJ, MILLER, HJ Uranium Recovery Licensing Branch 80/004109 Apr

8009150557 Responds to 800728 telcon re addl info on License Conditions 21 & 22 of RML 1370 & Amend i Radiological safety & environ sampling data collected in 1979 & description of pilot plant facilities encl SMITH.T C Cotter Corp 80/08/25 13pp

DOCKET 40-8693 OGLE PETROLEUM, INC

8007030455 Submits quarterly rept for May-Jul 1980 re U mining aperation under License BUA-1336 Operational summary, flow rates & monitoring data encl SAUNDERG. G A . CATCHPOLE. G J Ogle Petroleum, Inc 80/08/22 68pp

DOCKET 40-8697 ROCKY MOUNTAIN ENERGY CO

8009080453 Bubmits quarterly rept for Apr-June 1980 for Reno Creek in situ test facility SPIELE8.P Rocky Mountain Energy Co 80/07/31 8pp

DOCKET 40-8498 PLATEAU RESOURCES, LTD

8009260027 Submits effluent monitoring rept for Jan-June 1980 SCOTT, A D Plateau Resources, Ltd 80/08/22 ip

DOCKET 40-8721 ROCKY MOUNTAIN ENERGY CO

8008110042 Forwards "Alternative Analysis of Process Waste Disposal Options." as preliminary version of matl which will be included in revised environ rept NEUMANN, M R Rocky Mountain Energy Co 80/07/14 3pp

--8008110046 "Alternative Analysis of Process Waste Disposal Options " Seven oversise drawings encl \* Rocky Mountain Energy Co. 80/07/16 17pp

DOCKET 40-8724 CHEMTRON CORP

8009300112 Notifies that plant operations do not involve use of depleted U Responsibility for removal of depleted U at dump site should be placed on Chemetron Corp License SUB-852 ZELLNER, R J McGean Chemical Co , Inc 80/08/21 2pp

#### DOCKET 40-8743 CONOCO

800909019B Submits key ref document listing in support of Sand Rock Mill application
GUIGLEY.T W CONDCO.Inc (Continential Dil Co.) 80/07/30 3pp

8009150158 Requests archeological/paleontological clearance for Sand Rock Mill Project Section 1.741N.R75W & forwards "Results of Archaeological & Paleontological Surveys for Sand Rock Mill Project Southern Campbell County WY Related 1tr encl QUIGLEY, TW Conoco Coal Development Co 80/08/14 5pp

--8009150164 "Results of Archaeological & Paleontological Surveys for Sand Rock Mill Project Southern Campbell County, MY " GRANT,M , CARPENTER,K , LENNON,T J Hestern Cultural Resource Management inc , 80/07/15 96pp

BOO9160020 Forwards Sand Rock mill project application & environ rept. for immediate review Deficiencies required addl info & evaluation of proposed actions must be identified Proposes discussion of schedule & scape of work on 800826 Myo encls MILLER, HJ Uranium Recovery Licensing Branch 80/08/19 lp

8009150117 Advises of review completion of 800731 application for source math license w/supporting environ rept Documents acceptable for detailed review Scoping meeting scheduled on 801016 in Casper, WY Principal contact, K Hamill SCARAND, R A Uranium Recovery Licensing Branch 80/08/29 4pp

---8009150123 Notice of availability of environ rept & announcement of B01016 scoping meeting in Casper, WY re application for source natl license to construct & operate Sand Rock Mill project NRC DES will be available on 810301 SCARANO, R A Uranium Recovery Licensing Branch 80/08/27 2pp

#### DOCKET 40-8745 DOLE PETROLEUM

8009020552 Comments on DES, Section 4 5 1 re project No site specific air quality data obtained Time duration for expected atmospheric concentrations should be specified Internal memo encl RAFFELSON, C N Wyoming, State of 80/07/21 3pp

8009050362 Forwards drawing of initial survey locations for in-plant radiological monitoring program
CATCHPOLE:0 J Ogle Petroleum, Inc. 80/07/28 2pp

BCO9030258 Comments on draft EIS Inclusion of provision addressing need for human svc programs for inhabitants of vicinity recommended MASTER: W Health & Human Services, Dept of, 80/07/29 2pp

8009160546 Forwards comments from various state agencies on DES for consideration & use in preparing final analysis HARTMAN,D Wyoming, State of 80/07/29 23pp

8009170134 Discusses NRC DES on Ogle Petroleum proposed commercial in situ U mine Recommends NRC environ statement be modified to include groundwater restoration plan ACKERMAN,W C Wyoning, State of 80/08/04 2pp

8007170130 Discusses review of draft EIS for Bison Basin U in situ mining project Project will have little effect on radionuclides in environ STROUBE, N B HHS, Dept of, US Public Health Bervice 80/08/05

8009150592 Forwards latest proposal to DEG for well integrity testing Will forward revised pages to DEG application W/o encls CATCHPOLE.G J Ogie Petroleum. Inc. 80/08/06 ip

800902050B Comments on DES re Dale Petroleum, Inc Bison Basin In-Silv U Project NRC should recognize that U operations cause (solated, cumulative &/or synergistic environ impacts EASTD J Wyoming Outdoor Council 80/08/07 7pp

8009150955 Informs that Water Guality Div has no objections to approving Ogle Petroleum, Inc application to operate Bison Basin Project
MANCINI, A J Wyoming, State of 80/08/07 ip

8007020190 Forwards comment letters re Bison Basin Project DES Requeste appropriate reply to questions & comments Responses should be provided in sufficient detail to permit direct inclusion in FES Responses should be mailed before 800827 W/o ancis ROTHFLEISCH. J Uranium Recovery Licensing Branch 80/08/11 2pp

8009300202 Forwards requested Geophysical Logs OP-83, OP-86, OP-87, OP 60. OP-89, BBX-146, BBX-147 & OBX-149 & "Introduction to Well Log Analysis," for data interpretation M/o encls CATCHPOLE.O J Ogle Petroleur, Inc. 80/08/12 ip

- 800702051B Forwards MY Dutdoor Council 800807 ltr.WC Ackerman 800804 memo & NC Raffelson 800721 memo re Bison Basin Project DES M/o encls ROTHFLEISCH.J E Uranium Recovery Licensing Branch 80/08/13 ip
- 8009170144 Forwards review comments on DES re Ogle Patroleum Bison Basin Project Recommends dual cell design for waste pond sys for alternate holding area in event of leakage in primary cell WILLIAMS R E Environmental Protection Agency 80/08/18 8pp
- 8009030476 Notifies that response to Natl Wildlife Federation comments cannot be forwarded by 800822, due to large number of comments received Comments will be forwarded as soon as CATCHPOLE.O J Ogie Petroleum, Inc. 80/08/20
- 8009150209 Forwards State of MY Game & Fish Dept 800821 itr commenting on BES Requests reply to comments re addition field work fencing of access road & proposed reclamation practices ROTMFLEISCH. J. Uranium Recovery Licensing Branch 80/08/28 ip
- --8009150212 Comments on DES Recommends further field work to evaluate project impact on wildlife Requests documentation to support reclamation claims & assurances access road will not be fenced DEXTER.W D Wyoming, State of 80/08/21 2p
- 8009030385 Forwards approved WY Dept of Environ Quality mine permit application CATCHPOLE, G J Ogle Petroleum, Inc 80/08/29 14pp
- 80071603B3 Forwards responses to Natl Wildlife Federation 800718 comments re environ impact of project. General comments deal w/antelope migration properational monitoring downward migration & "no action" alternative CATCHPOLE,0 J Ogle Petrojeum. Inc. 80/09/03 25pp
- 8009160462 Forwards responses to HY Outdoor Council 800807 comments re commercial source matl license application Responses were not provided for comments dealing u/NRC policy issues or which referred to sections of DEG CATCHPOLE.O J Ogle Petroleum. Inc. 80/09/03 10pp
- 3009160386 Forwards responses to EPA draft comments re commercial source matl license application Responses were not provided for comments dealing w/NRC policy issues or sections of DES CATCHPOLES O J Ogle Petroleum. Inc
- 09160330 Forwards responses to listed comment ltrs transmitted by NRC 800811.13 & 28 itre
  CATCHPOLE, 0 J. Ogie Petroleum, Inc. 80/09/05 2pp
- 8009160331 Advises that no response is planned to F6 Lisella 800721 CATCHPOLE, Q J Ogla Petroleum, Inc. 80/07/05 1p.
- -8009160333 Advises that proposed project will not have any significant impact on endangered species in response to DDI 800723 itr CATCHPOLE, G J Ogle Petroleum. Inc. 80/09/05 ip
- --8009160334 Advises that no response is planned to W Haster 800729 ltr CATCHPOLE,O J Ogla Petroleum, Inc. 80/09/05 ip
  - POPTGOORER RESponds to LE Allen 800717 memo to D Hartman Permits for evaporation pends have been applied for & no const will begin until permits are received Nater supply for nonprocess activities comes from well permitted by state emgineer CATCHPOLE.G J Ogle Petroleum. Inc 60/09/05 2pp
  - 09180345 Advises that no reponse is planned to MY Dept of Health & Social Svc 800823 memo except that number of anticipated employees is approx 30 Cursory perusal of DE6 resulted in one miscanceptions
    ATCHPOLE, G J Ogle Petroleum, Inc. 80/09/05 in
  - 140048 Responds to Dept of Commerce 800701 ltr.including RB Rollins 3722 memo to UM Woods No geodetic control survey monuments within project area No plans to relocate monuments in inection w/Bison Basin project TCHPDLE: 6 J Ogle Petroleym. Inc. 80/09/03 lp
  - 160350 Responds to NA Lockstet 800803 comments re wellfield & nitaring Pumping wells for sampling more frequently than a period tends to produce excursions since two casing a must be pumped each time well is sampled CHPOLE.G J Ogle Petroleum. Inc 80/09/05 2pp

- --8009160354 Advises that no response is planned to WC Ackerman 800864 memo to RE Sundin since comments are more in form of comparisons rather than questions CATCHPOLE.G J Ogle Petroleum. Inc. 80/09/05 ip
- --B007160356 Advises that no response is planned to CN Raffelson 800721 memo to RE Sundin except to state that CP mentioned in last paragraph is being pursued CATCHPDLE.O J Ogle Petroleum, Inc 80/09/05 ip
- --8009160357 Responds to MY State Game & Fish Dept 800821 ltr re scope & nature of wildlife investigation In situ mining operation did not warrant intense survey typical of conventional mine CATCHPOLE. G J Ogle Patroleum, Inc. 80/09/05 4pp
- 8009170389 Submits changes to DES Related documentation encl GATCHPOLE.G J Ogle Petroleum, Inc. 80/09/15 Spp
- 8009190392 Forwards add1 data re surface water quality in vicinity of facility, in response to NRC 791204 ltr CATCHPOLE.Q J Ogle Petroleum, Inc 80709/15 3pp
- 8009220332 Submits responses to final EPA comments Preferred oxidizer utilized for Bison Basin Project is oxygen Hydrogen peroxide will be used as backup oxidizer Same pipeline will be buried & same portione will be on surface CATCHPOLE, O.J. Ogle Petroleum, Inc. 80/09/16 3pp
- 8009300457 Forwards map showing all exploration holes drilled & plugged w/bentonite & cement in response to 800908 ltr re commercial source matl license application Response to Item 6 transmitted on 800916 CATCHPOLE.Q J Ogle Petroleum, Inc. 80/09/22 3pp
- DUCKET 40-8748 KERR-MCKEE NUCLEAR CORP
- 8009150575 Forwards 800806 ltr not received by NRC re establishing baseling groundwater quality values FREEMAN, M.D. Kerr-McGee Nuclear Corp. 80/08/21 1p
- --8009150577 Responds to 800701 ltr re establishing baseline groundwater quality values Min of three samples to be taken from each monitor well w/samples analyzed for excursion parameters FREEHAN.M D Kerr-NcGee Corp. 80/08/06 ip
- 8009100473 Confirms 800820 beloon w/G France & advises of status of licensing review In-depth review of application to begin MILLER, H J Uranzum Recovery Licensing Branch 80/08/25 ip

#### DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-3 INDIAN POINT STATION, UNIT 1

F Security, medical, emergency & fire protection plans

- 8009230167 Requests that all personnel be reminded of purpose of emergency notification sys 3 health physics network Sys installed for govt use during emergency ORIER, B H Region 1, Philadelphia, Office of the Director 80/08/22 3pp
- G Adjudicatory correspondence
- 8007120374 Order granting extension until 800926 for Commission to review ALAB-436 & relevant portions of ALAB-561 CHILK:S J Office of the Sacretary of the Commission 80/09/10
- 8009300320 Order granting extension until 801024 for Commission to review ALAB-436 t ALAB-561, CHILK S J Office of the Secretary of the Commission 80/09/26
- H General correspondence
- 8009180448 Responds to 800319 1tr requesting public debate re issues appropriate to evacuation of large population ctrs near plants 80/04/21

- --8009180462 Requests public debate re issues appropriate to evacuation of large population ctrs near plants Expresses confidence in attempts by Commissioners to represent public concerns EMORY. A Affiliation Unknown 80/03/19 ip
- 8009040404 Forwards patition reflecting deep concern re safety of facility CINQUEMANI, D.K., CINQUEMANI, F.L. Affiliation Unknown 80/08/28
- 8009110218 Forwards response to 800728 ltr requesting assistance in answering constituent questions is nuclear power & effects of radiation DIRCKS.W J. Office of the Executive Director for Operations 80/08/28 4pp
- P Operating license stage documents & correspondence
- 8009300169 "Rept of Zion/Indian Point Study Vol 2." informal rept STEVENSON, M Q Los Alamos Scientific Laboratory FIN A-7015 NUREG/CR-1411 V2 80/04/30 165pp Available at NTIS
- 8009020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D O Division of Licensing 80/07/31 7pp
- BOOTOBOORO Forwards draft NUREC-0676. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl W/o NUREG EISENHUT
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D O Division of Licensing 80/08/07 60pp
- 8009190794 Forwards revised Westinghouse STS 3 9 8 2.3 9 10 & Bases 3/4 9 8 & 3/4 9 10 to require 23 ft of water over top of reactor pressure vassel flange during movement of fuel assemblies or control rods Written response required NOVAK.T M Assistant Director for Operating Reactors 80/08/15 in
- --8009190817 Revised Westinghouse STS 3 9 8 2.3 9 10 & Bases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods

  \* Assistant Director for Operating Reactors 80/06/23 21pp
- 8009090383 Forwards "Rept on Evaluation of Thermal Plume Studies of Indian Point Nuclear Generating Station" Objectives of thermal plume program have been fulfilled Rept available in Central Files only ZARAKAS,P Consolidated Edison Co of New York 80/08/29 ip
- 8009120502 "Rept of Zion/Indian Point Study," Vol 1 MURFIN.W B Sandia Laboratories FIN A-1218 NUREG/CR-1410 VI 80/08/31 400pp.
- 8009250266 Forwards current training course outlines re heat transfer, fluid flow & thermodynamics in response to NRC 800328 ltr ZARAKAS:P Consolidated Edison Co of New York 80/09/17 30pp
- G Inspection reports, IE Bulletine & correspondence
- 8007090242 Responds to IE Bulletin 80-16 Unit 2 has no specified transmitters installed Unit 1 shut down since 741031 & in defueled condition ZARAKABLP Consolidated Edison Co. of New York 80/07/30 2pp
- 8009120187 Responds to IE Bulletin 79-03A re longitudinal weld defects in SA-312 or A-312 Type 300 stainless steel piping Unit 1 is in defueled condition Unit 2 piping satisfies criteria re allowable stress ZARAKAS.P Consolidated Edison Co of New York. 80/08/06 2pp
- 8009030073 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER.9 H Region 1, Philadelphia, Office of the Director 80/08/15 1p

- 8009180339 Forwards IE Circular 80-18, "IOCFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GREER, B H Region 1, Philadelphia, Office of the Director 80/08/29 in
- 800912017i Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-600S & K-DON 6005 Circuit Breakers " No written response required GRIER B H Region 1. Philadelphia, Office of the Director 80/08/27 1p
- 8009090423 Responds to IE Bulletin 80-15, "Possible Loss of Emergency Natification Sys W/Loss of Offsite Power" Insp revealed loss of emergency natification sys on 800602 due to poor mater generator brush contact
  ZARAKAS
- BOD9230778 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required ORIER.B H Region 1. Philadelphia, Office of the Director BO/09/10 lp
- 8005240304 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls "No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/09/12 ip
- R Periodic operating reports & related correspondence
- 8009030382 Forwards "Effluent & Waste Disposal Semiannual Rept, Jan-June 1980 "
  ZARAKAS: P Consolidated Edison Co of New York 80/08/27 la
- --8009030396 "Effluent & Waste Disposal Semiannual Rept. Jan-June 1980 "

  \* Consolidated Edison Co. of New York 80/08/29 43pp
- B009230432 Forwards daily record of fash collections for Aug 1980, including daily species breakdown & total weight Unit 2 & 3 circulators were run for entire month Unit 1 circulators were run on B00808, 10, 13, 17, 19, 21, 23, 30 & 31 ZARAKAS,P Consolidated Edison Co of New York B0/09/15 1g
- --8009230433 Daily record of fish collections from intake screens for Aug 1980 \* Consolidated Edison Co. of New York B0/09/19 Spp
- 8009240452 Forwards quarterly rept on "Seismic Monitoring Network In Victoity of Indian Point NY, Consolidated Edison Project. Mar-May 1980 " ZARAKAS.P Consolidated Edison Co of New York 80/09/15 lp
- --8009240455 "Seismic Monitoring Network in Vicinity of Indian Point.NY. Consolidated Edison Project.Mar-May 1980 " \* Noodward-Clyde Consultants. Inc 80/08/15 44pp
- S Reportable occurrences. LERs δ related correspondence
- 8005140025 PNS-1-80-003 on 800321.local telephone company received bomb threat re facility from unidentified male caller Search was conducted but no bomb was found Threat was repeated on 800321 but no bomb was found Threat was repeated on 800321 but no bomb was found Region 1. Philadelphia, Office of the Director 80/03/24 1p
- 8009030610 RO on 800804, circulating water sys discharge temp esceeded Tech Specs limit Caused by high ambient river temps, high discharge temps & broken circulating water pump Demand load & discharge temp reduced ZARAKAS,P Consolidated Edison Co of New York 80/08/28 2pp
- DOCKET 50-5 PENNSYLVANIA STATE UNIV RESEARCH REACTOR
  F Security, medical, emergency & fire protection plans
- 8007030601 Forwards replacement for Table of Contents submitted w/physical security plan on 800731 Table of Contents withheld (ref 10CFR2 790)
  LEVINE.8 H Pennsylvania State Univ 80/08/27 ip
- H Ceneral correspondence
- 8009100490 Comments on RM 50-5 public should be advised of advantages & disadvantages of implementing Pu recycle NRC should not have terminated afforts on GESMO fuels DECHER.U Affiliation Unknown BO/09/03 ip

- Q Inspection reports, IE Bulletins & correspondence
- 8009240231 Forwards IE Info Notice 80-32. "Clarification of Certain Requirements for Exclusive-Use Bhipments of Radioactive Matis " No written response required GRIER.8 H Region 1. Philadelphia, Office of the Director 80/09/12 ip
- DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT I F Security, medical, emergency & fire protection plans
- 8009230288 Requests that all personnel be reminded of purpose of emergency motification sys & health physics network Sys installed for govt use during emergency KEPPLER.J 9 Region 3. Chicago. Office of the Director 80/08/22
- 8009100378 Forwards review of util generating station emergency plan & draft ltr requesting addi info & commitments from util PAGAND, F Q Emergency Preparedness Licensing Branch 80/08/28,
- 8009120453 Notifies that Comm Ed does not wish to participate in proposed study re review of people-related problems in nuclear safeguards Responses would be misleading, reflecting inexperience & short-term problems

  ABEL, J S Commonwealth Edison Co 80/09/02 ip
- A Operating license stage documents & correspondence
- 7910110018 Notification of 790918 meeting w/util in Bethesda.HD to discuss impact of free standing l(quid requirements for solid waste
  LO.R Environmental Evaluation Branch (Fre 791030) 79/09/17 2pp
- 8006300604 Ltr to all BWR licensess forwarding "For Comment" edition of NUREO-0619. "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking " Comments will be evaluated by NRC prior to final implementation W/o encl EISENHUT.D O Division of Licensing 80/06/05 22pp
- O9110554 Suppls NRC 800707 request for proposed Tech Specs changes rescram discharge vol vent & drain valves, & reactor protection sys & control rad block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT, D. G Division of Licensing 80/07/22 22pp
- 309020297 Submits interim criteria for shift staffing to all GL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D Q Division of Licensing, 80/07/31 7pp
- B0090B00B0 Forwards draft NUREQ-0696, "Functional Critaria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for macking criteria of NUREQ-0676 encl 4/o NUREQ EISENHUT, D 0 Division of Licensing 80/08/01 119pp
- B009230032 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISEMHUT.D 0 Division of Licensing 80/08/07, 60pp
- 8009020456 Forwards evaluation of util response to NRC 800223 request for info re primary coolant sys pressure isolation valves. Two specific Event 5 valve configurations do not exist at factities.

  CRUTCHFIELD,D. Operating Reactors Branch 5 80/08/12 3pp
- --8009020463 "Primary Coolant Sys Pressure Isolation Valves," technical evaluation rept
  NGELL.P N , STILMELL.T C Franklin Institute/Franklin Research
  Center NRC-03-79-118 80/07/21 4pp
- ~8007020467 "Primary Coolant Sys Pressure Isolation Valves," technical avaluation rept
  NOELL, P N. STILMELL, T C Franklin Institute/Franklin Research
  Center NRC-03-79-118 80/07/21, 5pp
- -8009020470 "Primary Coolant Sys Pressure Isolation Valves." technical evaluation rept NOELL-P.N. STILHELL.T C Franklin Institute/Franklin Research Center NRC-03-79-118 80/07/21 4pp

- --8007020473 "Primary Coolant Sys Pressure Isolation Valves," technical evaluation rept NOELL,P N , STILMELL,Y C Franklin Institute/Franklin Research Center NRC-03-79-119 80/07/21 4pp
- --8009020474 "Primary Coolant Sys Pressure Isolation Valves," technical evaluation rept NOELL.P N , STILMSLL.T C Franklin Institute/Franklin Research Center NRC-03-79-118 80/07/21 4pp
- 8009180428 Forwards evaluation of SEP Topic XV-20, "Radiological Consequences of Fuel Damaging Accidents (Inside & Outside Containment) " Suggested mods incorporated into evaluation CRUICHFIELD.D Operating Reactors Branch 5 80/08/12 6pp
- B009150401 Confirms 800811 discussion re arranging 800821 meeting w/util in Chicago.IL re facility cooling lake dike seepage & remedial action to be taken KEPPLER.J G Region 3, Chicago. Office of the Director 80/08/[5
- 8009110746 Notification of 800916 meeting w/BEP owners group to discuss NRC initial review & recommendations for site-specific ground response spectra & owners group program plans for seismic functional qualification of Class IE equipment LEVIN, H A Division of Engineering 80/08/26 1p
- 8009120404 Forwards Attachments 1-5 to util 800630 ltr re facility electric distribution sys voltage adequacy Ltr inadvertently transmitted w/o attachments JANECEK/R F Commonwealth Edison Co 80/08/28 6pp
- 8009110250 Requires submittal of ATMS emergency operating procedure for NRC review Generic analysis should confirm ATMS mitigation capability described in Vol. 3 of NUREG-0440 Commission will determine required mods & implementation schedules TEDESCO.R L. Assistant Director for Licensing 80/08/29 3pp
- 8007240555 Forwards final critique of 800617 SEP exercise Critique discusses problem areas identified during exercise & presents corrective actions W/o critique DELGEOROE, L.O. Commonwealth Edison Co. 80/08/27 ip
- 8009110376 Comments on NRC 800612 evaluation re SEP Topic V-5,RCFB Leakage Detaction Info provided re air sampling sys.leak detaction sys & reactor drain tank instrumentation.Plant is in compliance w/Reg Guide 1,45 JANECEK.R F Commonwealth Edison Co 80/09/02 2pp
- B009290143 Notification of B00926 meeting w/utils & Kerr-McGee Chemical Corp in Bethesda.MD to discuss review & recommendations for site specific ground response spectra & program plans for seismic functional qualification of Class IE equipment ALLIBON.D P Systematic Evaluation Program Branch 80/09/08 3pp
- 8009240022 Natification of second rescheduling until 801003 for meeting w/SEP owners group & KMC. Inc to discuss NRC initial review of site-specific ground response spectra & util program for seismic functional qualification of Class IE equipment ALLISON.D P Systematic Evaluation Program Branch 80/09/10 Spp
- 8009290335 Responds to DO Eisenhut 800804 ltr re seismic plan Complete seismic evaluation program will be provided to NRC for review & approval before restarting unit JANFCEKIR F Commonwealth Edison Co 80/09/11 1p
- 8009220293 Forwards analysis of 30 t 60-day corrosion test results re test pracedures for NS-1 solidified waste JANECEK.R F. Commonwealth Edison Co 80/09/12 4pp
- 8009290334 Responds to 800701 itr to DL Peoples re SEP Topic 8-3 B.dc power sys bus voltage monitoring & annunciation Typographical error noted in Section 5.Ref 2 which should be Reg Guide 1 47 not 1 74 JANECEK, R. J. Commonwealth Edison Co. 80/09/17 1p
- 8009230463 Forwards proposed Tech Sper changes re implementation of TMI Lessons Learned, Category A requirements, in response to NRC 800702 request Dresden Unit 1 Tech Spec changes will be submitted 90 days prior to scheduled startup JANECEK,R F Commonwealth Edison Co 80/09/18 3pp
- --8007230466 Proposed Tech Spec changes re implementation of TMI-2 Lessons Learned Category A items \* Commonwealth Edison Co 80/09/10 29pp

- 8009250292 Requests addl 60-90 days for review to determine whether as-built facilities differ from basis in NRC assessment Addl time would allow for reproduction, distribution & review methods to function properly

  JANC
- Q Inspection reports: IE Bullatins & correspondence
- 8009100143 Forwards IE Insp Repts 50-010/80-12.50-237/80-12 & 50-249/80-16 on 800609-0703 No noncompliance noted HEISHMAN.R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/07/23 2pp
- --8009100148 IE Insp Repts 50-010/80-12,50-237/80-12 & 50-249/80-16 on 800609-0703 No noncompliance noted Major areas inspected operational safety verification & monthly maint & surveillance observations SPESSARD,R L , BARKER,J L , TONGUE,T H Region 3, Chicago, Office of the Director 80/07/23 4pp
- 8009020109 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " SA-312 pipe not present in operating plants Final confirmation from suppliers anticipated by 800915 re const plant piping sys NAU0HTDN, W F Commonwealth Edison Ca 80/08/07. 2pp
- 8009030231 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/08. Region 3. Chicago, Office of the Director 80/08/15
- 8009260395 Forwards IE Insp Repts 50-010/80-13.50-237/80-14 & 50-249/80-18 on 800707-0801 & notice of violation HEISHMAN.R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/08/18 2pp
- ---8009260399 Notice of violation from insp on 800707-0801
  \* Region 3, Chicago, Office of the Director BD/08/ 80/08/18 10
- --8009260404 IE Insp Repts 50-010/80-13.50-237/80-14 & 50-249/80-18 on 800707-0801 Noncompliance noted failure of licensed operators to keep themselves cognizant of design changes BARKER, J. L. STREETER, J. F. SPESSARD, R. Region 3. Chicago. Office of the Director 80/08/18 11pp
- 8009190495 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE BNR Facilities " No specific action or response requested KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/20
- 8009120060 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR" Written response required
- KEPPLER, J Q Region 3, Chicago, Office of the Director 80/08/22
- 8009180551 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER.J @ Region 3, Chicago, Office of the Director, 80/08/22
- 8007230074 Forwards IE Info Natice 80-31. "Maloperation of Gould-Brown Bover1 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required KEPPLER.J G. Region 3. Chicago. Office of the Director 80/08/28
- 8009120117 Advises that Suppl 3 to IE Bulletin 80-17. "Failure of Control Rods to Insert During Scram at BWR." was sent to listed utils on 800822 PAPPAS.H Region 3. Chicago, Office of the Director 80/08/29
- 8009170411 Forwards response to IE Bulletin 80-15 re possible loss of emergency notification sys w/loss of offsite power Review revealed inoperability of Dresden sys Investigation being conducted Operating Order 26-80 changed.

  JANACEK.R F Commonwealth Edison Co 80/08/29, 4pp.
- B009180446 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Identified relays are not used in facility. No action required Twenty-four manhours expended on review RAUSCH

- 8009230478 Forwards Revision 1 to IE Bulletin 79-26. "Boron Loss From BUR Control Blades" Written response required KEPPLER.J O Region 3: Chicago, Office of the Director 80/08/29
- 8009260109 Forwards response to IE Bulletin BO-17.Suppl 3. "Failure of 76 of 185 Control Rods to Fully Insert During Boram at BWR "
  Procedure at Dresden 2 & 3 changed to require immediate
  manual scram when air pressure reaches 60 psi
  RAUSCH.T J Commonwealth Edison Co 80/09/02 4pp
- 8009240133 Forwards IE Circular 80-21, "Regulation of Refueling Crews ! No written response required

  KEPPLER, J G Region 3. Chicago, Dffice of the Director 80/09/10
- 8009300200 Forwards response to IE Bulletin 80-20 No Westinghouse Type M-2 control switches are used in safety-related sys at Dresden, Guad Cities & LaSalle County Responses for Zion & RAUSCH.T J Commonwealth Edison Co 80/09/15
- R Periodic operating reports & related correspondence
- 8009030456 Forwards semiannual rept of radioactive effluent discharges % solid radwaste, for Jan-June 1980 SCOTT,D J Commonwealth Edison Co 80/08/20 1p
- --8007030467 Semiannual rept of radioactive effluent discharges & tolid radwaste, for Jan-June 1780 \* Commonwealth Edison Co 80/08/20 15pp
- 8009230713 Forwards monthly operating repts for Aug 1980 SCDTT.D J Communwealth Edison Co 80/09/12 1p
- --8007230720 Monthly operating repts for Aug 1980 CIESZKIEWICZ,S Commonwealth Edison Co 80/09/03 15pp
- V Operator Examinations
- 8009300287 Forwards preliminary topical outlines of proposed modules on thermal hydraulics & core damage mitigation to be included in revised reactor operator training program per 800328 request NAUOHTON,N F Commonwealth Edison Co 80/09/15 7pp
- DOCKET 50-20 MASSACHUSETTS INST OF TECH RES REACTOR F Security, medical, emergency & fire protection plans
- 8009080198 Forwards rewrite & revision of physical security plan Plan withheld (ref 10CFR2 790) CLARK.L Massachusetts Institute of Technology 80/08/28 ip
- G Inspection reports, IE Bulletins & correspondence
- 8009240227 Forwards IR Info Notice 80-32. "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls "No written response required GRIER, BH Region i, Philadelphia, Office of the Director.
- R Periodic operating reports & related correspondence
- 8009030565 Forwards "MIT Research Reactor Annual Rept. Jul 1979-June CLARK, L Massachusetts Institute of Technology 80/08/27 ip
- --8009030569 "MIT Research Reactor Annual Rept.Jul 1979-June 1980 " \* Massachusetts Institute of Technology 80/08/26 27pp
- DOCKET 50-22 WESTINGHOUSE TEST REACTOR
- Q Inspection reports, IE Bulletins & correspondence
- 8009240252 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matis " No written response required ORIER, B M Region 1, Philadelphia, Office of the Director 80/09/12 ip
- 8009250257 Forwards annual insp rept of retired Westinghouse Test Reactor for 1780 DIPIAZZA.R.P W Westinghouse Electric Corp B0/09/19

- DOCKET 50-27 WASHINGTON STATE UNIV RESEARCH REACTOR
  P Operating license stage documents & correspondence
- 8009150191 Forwards request for add1 info needed for Structural Engineering Tranch to determine appropriateness of allowing operation of facility for next 20 yrs YEDESCO.R L Assistant Director for Licensing 80/09/05 2pp
- 800930D391 Informs that response to 800905 ltr is in progress re design procedure of reactor fuel storage pools Appropriate info being obtained from Campbell Engineers in Spokane, HA WILSDN.U E Washington State Univ 80/09/23 lp
- R Periodic operating reports & related correspondence
- 8009030528 Forwards annual rept of operation for Jul 1979-June 1980 WILSOM WE Washington State Univ 80/08/25 ip
- --8009030530 "Annual Rept on Operation of Washington State Univ TRIGA Reactor, Jul 1979-June 1980 " HAWLEY, S. C. Washington State Univ. 80/08/25 9pp
- DOCKET 50-29 VANKEE-ROHE NUCLEAR FOWER STATION

  F Security, medical, emergency & fire protection plans
- 6009230200 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency GRIER, B H Region 1, Philadelphia, Office of the Director 60/08/22 | 3pp
- O Adjudicatory correspondence
- 8009300551 Forwards order for license mod.requiring supporting info to support environ qualification of safety-related electrical equipment info should be submitted by 801101 CRUTCHFIELD.D Operating Reactors Branch 5 80/08/29 2pp
- --800930053 Order for mod of license, requiring supporting info re environ qualification of safety-related electric) equipment EISENHUT.D O Division of Licensing 80/08/29 6pp
- P Operating license stage documents & correspondence
- 8007090033 Discusses void formation in vessel head during 800611 natural circulation cooldown event Requests opinion repotential for voiding phenomenon in util designed NSSS CHECK.P S Assistant Director for Plant Systems 80/07/28 2pp
- B009020297 Submits interim criteria for shift staffing to all OL & CP licensess & applicants, per NRC 800507 ltr Discusses administrative provisions for amergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D O Division of Licensing 80/07/31 7pp
- B009080080 Forwards draft NUREQ-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT.D @ Division of Licensing B0/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons tearned is unjustified Previous determination should be disregated Requested submittal should include proposed class of amend EISENHUT, D C Division of Licensing 80/08/07 60pp
- 8009050497 Informs that NRC evaluation confirmed that two specific Event 5 valve configurations discussed in NRC 800223 ltm.do not exist at facility NRC activities re valve configurations finalized for facility Technical evaluation rept and CRUTCHFIELD, D Operating Reactors Branch 5 80/08/12 3pp
- --800705050! "Primary Coolant Sys Pressure Isolation Valves, Yankee Rowe Unit 1," technical evaluation rept NGELL,P N : STILWELL,T C Franklin Institute/Franklin Research Center NRC-03-79-118 80/07/21 4pp
- 8009190794 Forwards revised Westinghouse STS 3 9 8 2.3 9 10 % Bases 3/4 9 8 % 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Whitten response required, NOVAK.T M Assistant Director for Operating Reactors 80/08/15

- --8009190817 Revised Westinghouse STS 3 9 8 2.3 9 10 & Bases 3/4 9 8 4 3/4 9 10 requiring 23 ft of water over top of reactor pressure vassel flange during movement of fuel assemblies or control rods # Assistant Director for Operating Reactors 80/06/23 21pp
- 8007120284 Forwards request for info re adequacy of station electric distribution sys voltages Requests response within 75 days of ltr receipt CRUICHFIELD. D Operating Reactors Branch 5 80/08/20 4pp
- 8007020021 Requests deferment of encl listed surveillance testing until rescheduled refueling outage in Spring 1981 Performance of testing during current cold shutdown conditions would significantly increase personnel exposure HEIDER.L H Yankee Atomic Electric Co 80/08/26 2pp
- 8009110746 Notification of 8009t6 meeting w/8EP owners group to discuss NRC initial review & recommendations for site-specific ground response spectra & owners group program plans for seismic functional qualification of Class IE equipment LEVIN.H A Division of Engineering 80/08/26 1p
- 8009030651 Forwards proprietary version of Westinghouse rept
  "Preliminary Metallurgical Analysis of Generator End Number
  One Disc From Yankee Rowe Nuclear Plant " Rept withheld
  (ref 100ER2 790)
  KAY. J A Yankee Atomic Electric Co 80/08/29 1p
- 8009100542 Forwards info supplementing 800827 ltr re turbine disc failure analysis Discs 1 & 2 on both generators & governor ends have been removed No detectable cracking exists in remaining discs Info withheld (ref 10CFR2 790) KAYJ J A Yankee Atomic Electric Co 80/09/05 7pg
- 8009290143 Notification of 800924 meeting w/utils & Kerr-McGse Chemical Corp in Bethesda.MD to discuss review & recommendations for site specific ground response spectra & program plans for seismic functional qualification of Class IE equipment ALLISON.D P Systematic Evaluation Program Branch 80/09/08 3pp
- 8009240022 Notification of second rescheduling until 801003 for meeting w/SEP owners group & KMC. Inc to discuss NRC initial review of site-specific ground response spectra & util program for setwaic functional qualification of Class IE equipment ALLISON.D P Systematic Evaluation Program Branch 80/09/10 3pp
- BOOPIBO383 Responds to NRC BOO804 request for info re seismic evaluation & plant upgrade program Includes info re reactor support mods, steam generator supports, probabilistic risk assessment & seismic analysis KAY, J A Yankee Atomic Electric Co 80/09/12 2pp
- G Inspection reports, IE Bulletins & correspondence
- 9009090526 Responds to IE Hulletin 79-03A Steam welded A312 pipe not used in facility Review of piping spec has determined use is permitted; however in all cases pipe wall thickness is based on use of 85% of code allowable MOODY, DE Yankee Atomic Electric Co 80/07/22 ip
- 8009080522 Responds to IE Bulletin 80-16 Rosemount Model 1151 & 1152 pressure transmitters would not be exposed to input pressures that could result in anomalous signals during normal operation, anticipated transients or accidents MODDY, B E Yanker Atomic Electric Co 80/07/29 2pp
- 8009030063 Forwards Revision I to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/08/15 ip
- 8009180057 Forwards IE Circular 80-18, "10CFR50 59 Bafety Evaluations for Changes to Radwaste Treatment Sys," No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80708/22 ip
- 8009120216 Forwards 1E Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DDN 6008 Circuit Breakers " No written response required. ORIER B H Region 1. Philadelphia, Office of the Director 80/08/27 10
- 9009240050 Forwards IE Circular BO-21. "Regulation of Refueling Crews " No written response required GRIER.D.H Region 1. Philadelphia. Office of the Director 90/09/10 ip

24 Jements for Exclusive—Use Shipments of Radioactive
11 Jements for Exclusive—Use Shipments of Radioactive
12 Jements for Exclusive—Use Shipments of Radioactive
12 Jements for Exclusive—Use Shipments of Radioactive
13 Jements Region 1. Philadelphia. Office of the Director
14 Jements Region 1. Philadelphia. Office of the Director
15 Jements Region 1. Philadelphia. Office of the Director
16 Jements Region 1. Philadelphia. Office of the Director
17 Jements Region 1. Philadelphia. Office of the Director
18 Jements Region 1. Philadelphia. Office of the Director
18 Jements Region 1. Philadelphia. Office of the Director
18 Jements Region 1. Philadelphia. Office of the Director
18 Jements Region 1. Philadelphia. Office of the Director
19 Jements Region 1. Philadelphia. Office of Region 19 Jements Reg

ET 50-47 ARMY MATERIALS RESEARCH REACTOR
Tast Pection reports, IE Bulletins & correspondence

240277 Forwards IE Info Notice 80-32, "Clarification of Certain quirements for Exclusive-Use Shipments of Radioactive も1 %" No written response required IER、BH Region i, Philadelphia, Office of the Director / 07/12 ip

E T 50-54 UNION CARBIDE RESEARCH REACTOR

d J wdicatory correspondence

O 4 O250 Petition to participate as interested state NY State Energy
is vested w/authority to coordinate regulatory programs
fecting atomic energy activities Petition is not request
thering Certificate of Svc enel
IFSBERG, S B New York, State of 80/08/27. 3pp

1 > 0.160 Response stating no objection to NY State Energy Ofc 800827 title in the participate as interested state in proposed OL. The wall proceeding Certificate of Svc encl CHMANN.R o Rulemaking & Enforcement Division 80/09/15 2pp

Pection reports, IE Bulletins & correspondence

1 OO66 Ack receipt of 800727 ltr informing NRC of addl steps the note correct violations noted in IE insperent. Symmetric civil penalty

ELLO, V Office of Inspection & Enforcement, Office of the \$80/08/21, ip

240268 Forwards IE Info Notice 80-32, "Clarification of Certain to I rements for Exclusive-Use Shipments of Radioactive to a "No written response required LER.8 H Region 1, Philadelphia, Office of the Director 19

DOCKEY 50-57 STATE UNIV OF NEW YORK RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8009160338 Forwards PULSTAR Reactor Requalification Program estimated decommissioning costs financial rept & security plan for protection of SNM of low strategic significance Security plan withheld (Feef 100FR2 770)
HENRY, L. G. New York, State Univ. of, Suffalo 80/09/11 8pp

I Financial information

BOO916033B Forwards PULSTAR Reactor Requalification Program, estimated decommissioning costs financial rept & security plan for protection of SNM of low strategic significance Security plan withheld (raf 10CFR2 790)

HENRY, L O New York, State Univ of, Suffalo 80/09/11 8pp

--B009160340 "PULSTAR Reactor (R-77) Requalification Program for Licensed Reactor Operators & Licensed Senior Reactor Operators." Revision 5 ORLOSKY,P M , WICKHORST,P M New York, State Univ of Buffalo 75/03/12 6pp

P Operating license stage documents & correspondence

8009040376 Informs NRC of current status of application for renewal of License R-77 Mazard summary rept, operator requalification program 2 physical security plan have been completed New Tech Epecs are nearing completion

HENRY, L G New York, State Univ of Duffalo 80/08/29 2pp

G Inspection reports. IE Bulletins & correspondence

8009240238 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required ORIER.8 H Region 1, Philadelphia, Office of the Director 80/09/12 ip

V Operator Examinations

BO09160338 forwards PULSTAR Reactor Requalification Program, estimated decommissioning costs, financial rept & security plan for protection of SNM of low strategic significance Security plan withheld (ref 100FR2 790)

HENRY, L Q New York, State Univ of, Buffalo 60/09/11 8pp

--B009160340 "PULSTAR Reactor (R-77) Requalification Program for Licensed Reactor Operators & Licensed Senior Reactor Operators," Revision 5 ORLOSKY,P M , WICKHORST,P M New York, State Univ of, Buffalo 75/03/12 600

DOCKET 50-59 TEXAS A&M UNIV RESEARCH REACTOR

R Periodic operating reports & related correspondence

B009030568 Forwards "Annual Operations Rept of TX A&M Univ AQN-201M Training Reactor, June 1979-May 1980 " COCHRAN.R G Texas A & M Univ B0/08/27. 1p

~-8009030572 "Annual Operations Rept of TX A&K Univ AGN-201 Training Reactor,June 1979 - May 1980 " 2G&ICZYKSKI,J Texas A & M Univ 80/08/27 9pp

DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

O Advisory Committee on Reactor Safeguards reports & correspondence

8009150236 Forwards comments re seismic design considerations for GETR Inadequate info re reactor site precludes comments or suggestions for alternative considerations TRIFOUNDCHD California, Univ of, Los Angeles 80/06/23 2pp

8009150242 Submits comments on 800516-17 meeting on GETR Requests copy of EDAC 117-253-01, Revision 1 Probabilistic effects of presentation of combining vibratory motion u/uplift ware unclear

\* White, M P Consulting Engineer 80/07/11 ip

- P Operating license stage documents & correspondence
- 8009050487 Summary of 800730 meeting u/OE in Bathasda.MD re ongoing structural evaluation of GETR Issuance of SER addressing GETR sys & structural analysis & landslide evaluation expected by oid-Oct NELSON.C C Operating Reactors Branch 3 80/08/12 16pp
- 8009030639 Forwards revised table of total C( levels in facility waters during normal operation, including (oddine isotope activities excluded in 800806 ltm Also forwards calculations which include loddine isotopes & revised organ doses
  DARMITZELLR W General Electric Co 80/08/28 4pp
- 8009040255 Forwards "GETR Landslide Stability Analysis " DARMITZEL.R W General Electric Co 80/08/29 2pp
- --8007040256 "GETR Landslide Stability Analysis "
  4 Earth Sciences Associates 80/08/31 93pp
- 8009180474 Forwards "GETR Response to Add1 Info Request re Seismic Scram Sys." concerning Item 2 of RW Danitrel 800814 submittal to D3 Eisenhut Affirmation encl DARRITZELIR W General Electric Co 80/09/16 2pp
- --8009180477 "CETR Response to Add1 Info Request re Seismic Scram Sys " ≠ Engineering Decision Analysis Company, Inc. EDAC 117-258 03 80/09/15 25pp
- 8009250245 Forwards response to NRC ltr.received on 800919, requesting addl info re fuel elements & fueled capsules No fuel or equipment capsule failure occured due to design seismic events

  DARMITZEL.R W General Electric Co 80/09/23 App
- DOCKET 50-77 CATHOLIC UNIV OF AMERICA RESEARCH REACTOR

  O Inspection reports, IE Bulletine & correspondence
- 0007240215 Forwards IE Info Notice 80-02, "Clarification of Certain Requirements for Exclusiva-Use Shipments of Radioactive Matis "No written response required GRIER.B H Region 1. Philadelphia, Office of the Director 80/09/12 1p
- DOCKET 50-83 UNIV OF FLORIDA TRAINING REACTOR

  P Operating license stage documents & correspondence
- 8009160389 Responds to 800807 ltr re addl licensing documentation SAR in final stages or assembly & will be submitted by 801031 Discusses SAR status
  DIALN J Florida. Univ of Gainesville 80/07/10 200
- DOCKET 50-87 WESTINGHOUSE CRITICAL EXPERIMENT

  O Inspection reports, IE Builetins & correspondence
- 8009100085 Forwards IE Insp Rept 50-087/80-05 on 800627 No noncompliance noted DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/07/23 2pp
- ~-B009100091 IE Ensp Rept 50-087/80-05 on 800627 No noncompliance noted Major areas inspected qualifications, audits & radiation protection procedures
  FISHER, W L. Region 3. Chicago, Fuel Facility & Materials Safety Branch HEUTER, L. J. Region 3. Chicago, Office of the Director 80/07/18 6pp
- DOCKET 50-97 CORNELL UNIV ZERO POWER REACTOR
- F Security, medical, emergency & fire protection plans
- 8007230643 Matl in support of application to renew & amend License R-80 "Financial Rept.1978-1979," "Final Safeguards Rept. Bupp 1." proposed Amend 8 to Tech Spec & license & proposed exergency plan encl CODAE, N.D. Cornell Univ. 80/09/15 19pp
  - (009230668 Proposed emergency plan for Licenses R-80 & R-89 \* Cornell Univ 80/09/01 16pp

- P Operating license stage documents & correspondence
- 8009230643 Mgtl in support of application to renew & amend License R-80 "Financial Rept. 1978-1979." "Final Safeguards Rept. Supp I." proposed Amend 8 to Tech Spec & license & proposed energency plan encl COUKE, W D Cornell Univ 80/09/15 19pp
- --8009250668 Proposed emergency plan for Licenses R-80 & R-89 \* Cornell Univ 80/09/01 16pp
- Q Inspection reports. IE Bulletins & correspondence
- 8009240221 Forwards IE Info Notice 80-32. "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Hatls "No written response required ORIER.B H Region i, Philadelphia. Office of the Director 80/09/12 ip
- BOCKET 50-97 BASCOCK & WILCOX TEST REACTOR

  P Operating license stage documents & correspondence
- 8007030443 Forwards Tech Specs incorporating changes proposed by 790501-02 ltrs & submitted in connection w/780303 request for renewal of License R-47 OLSEN: A F Babcock & Wilcox Co 80/08/27 lp
- --8009030446 Tech Specs incorporating changes proposed by 790501-02 1%11 5 submitted in connection w/780303 request for renewal of License R-47 \* Babcock & Wilcox Co 79/05/31 44pp
- DOCKET 50-112 UNIV OF OKLAHOMA RESEARCH REACTOR

  R Periodic operating reports & related correspondence
- BO09100577 Annual operating rept for Jul 1979-June 1980 JAMES. J Oklahoma. Univ of BO/09/02 2pp
- 8009260432 Submits annual rept for Jul 1979-June 1980 JAMES, J Oklahoma, Univ of 80/09/02 2pp.
- POPERATION OF MISSOURI RESEARCH REACTOR
  POperating license stage documents & correspondence
- 8009090399 Forwards revised Toch Bpecs completing submittal for Univ of MO.Roila reactor relicensing ELLIOTT, A E Missouri, Univ of, Rolla 80/09/03 ip
- --8009090403 Revised Tech Spacs for Univ of MO.Rolla Reactor \* Missouri, Univ of Rolla 80/09/03 25pp
- DOCKET 50-124 VIRGINIA POLYTECH INST TRAINING REACTOR

  P Operating license stage documents & correspondence
- 8009300459 Application for amend of License R-62, changing Tech Bpece to permit tests of one i3-plate element w/o exceeding k limit Safety analysis encl PARKINSON. T F Virginia Tech 80/09/17 4pp
- DOCKET 90-128 TEXAS A&M UNIV RESEARCH REACTOR
- R Periodic operating reports & related correspondence
- 6009030350 Forwards revised App III to "Sixteenth Progress Rept of TX A&M Univ Nuclear Science Ctr." 1979 consisting of summaries of health physics support, effluent releases, environ survey program radiation & contamination control program FELTZ, D & Texas A & M Univ 80/08/28 ip
- --8009030353 Revised App III to "Sixteenth Progress Rept of TX A&M Univ Nuclear Science Ctr." 1979 consisting of summaries of health physics support, effuent releases, environ survey program, radiation & contamination control program \* Texas A & M Univ BO/08/28 29pp

DOCKET 50-131 OMAHA VET ADMIN HOSP RESEARCH REACTOR F Security, medical, emergency & fire protection plans

8009160434 Requests revisions & addl info re physical security plan for protection of SNM of low strategic significance Description of insp procedures & revised plan pages required by 800930 MILLER, J. R. Standardization & Special Projects Branch 80/08/26

B009260280 Forwards Revision 2 to physical security plan Revision withheld (ref 100FR2 790)
TURCOTTE,R L Vet Admin Hosp Omaha.NE 80/09/15 ip

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3 F Security, medical, emergency & fire protection plans

8009030337 Notifies of 800819,22 & 30 regional workshops re development normanday Notifies of 800819.22 & 30 regional workshops re develof guidance for acceptable method for coping wemergencies at facility Requests that representative be sent Subj areas to be discussed include function of facilities & location ENGELERN, R H Region S. San Francisco. Office of the Director 80/08/12 2pp

#### P Operating license stage documents & correspondence

B009110554 Suppls NRC B00707 request for proposed Tech Specs changes re scram discharge vol vent & drain valves. & reactor protection sys & control rod block limit switch surveillance requirements Class III licanse fee to be submitted w/change EISENHUT,D Q Division of Licensing 80/07/22 22pp

8009020297 Submits interim criteria for shift staffing to all GL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D Q Division of Licensing 80/07/31 7pp

8009080080 Forwards draft NUREC-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days, Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT, D O Division of Licensing 80/08/01 119pp

8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D O Division of Licensing 80/08/07 60pp

8007170637 Forwards IB Alterman trip rept re field & trench observations in vicinity of plant JACKBON, R E Geosciences Branch 80/09/12 tp

--8009190639 Forwards trip rept re field 8 trench observations in vicinity of plant New fault was found 700 ft from plant ALTERMAN. I B Geosciences Branch 80/09/10 20pp

#### G Inspection reports, IE Bulletins & correspondence

8009080082 Forwards response to LE Bulletin 80-14, "Degradation of BHR Scram Discharge Vol Capability " Record review showed no instances of bent float assemblies or water hammer damage Required surveillance procedures performed regularly CRANE,P A Pacific Gas & Electric Co 80/07/28 3pp

8009240299 Forwards IE Info Notice 80-29, "Broken Bluds on Terry Turbine Bleam Inlet Flange," No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/08/07 ip

8007030288 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Hatrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required ENGELKEN,R H Region 5, Ban Francisco, Office of the Director 80/08/15 1p

BO07270305 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No written response required EMOELKEN,R H Region 5, San Francisco, Office of the Director BO/08/18, 4pp

8009120029 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR " No written response required
ENDELKEN, R H Region 5. San Francisco, Office of the Director 80/08/22

8009160181 Forwards IE Circular 80-18, "10CFR50 59 Bafety Evaluations for Changes to Radwaste Treatment Sys " No written response required
ENGELKEN, R H Region 5. San Francisco. Office of the Director

800912045B Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-600S & K-DON 600B Circuit Breakers "
No written response required ENGELKEIN R H Region S, Sen Francisco, Defice of the Director 80/08/27 ip

8007180130 Forwards Revision 1 to IE Bulletin 79-26, "Boron Loss From BMR Control Blades " Written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/08/27 1p

#### R Periodic operating reports & related correspondence

8009080333 Forwards "Radioactive Effluent Release & Waste Disposal Semiannual Rept, Jan-June 1980" & Environ Radiation Study Repts 75 & 76 GRANE, P A Pacific Gas & Electric Co 80/09/04

--8009080334 "Radioactive Effluent Release & Haste Disposal Semiannual Rept. Jan-June 1980 " \* Pacific Gas & Electric Co 80/09/04 15pp

--8009080335 Rept 75, "Environ Radiation Study in Vicinity of Humboldt Bay Power Plants Eurekas CA: Quarter Ending 791231." CAYOT, R F , BROWNRIOG, D L , LORENZ, R W Pacific Oas & Electric Co 80/05/09 19pp

--8009080336 Rept 74, "Environ Radiation Study in Vicinity of Humboldt Bay Power Plant, Eureka. CA. Quarter Ending 800331 " CAYOT. R F . BROWNRIGO. D L . LORENZ, R W Pacific Gas & Electric Co 80/07/10 19pp

8009120449 Forwards monthly operating rept for Aug 1980 WEEKS, E D Pacific Qas & Electric Co 80/09/08 2pp

--B00912045; Monthly operating rept for Aug 1980 BAUM, P W Pacific Gas & Electric Co B0/09/04 3pp

8009230551 Forwards supplemental info for efflyent & waste disposal semiannual rept for 1978, in response to NRC 800825 ltr Supplemental info available in Central Files unly CRANE, P.A. Pacific Gas & Electric Co. 80709715

S Reportable occurrences, LERs & related correspondence

8009120349 Forwards LER 80-004/03L-0 Pacific Cas & Electric Co 80/09/08 ip

---8009120419 LER 80--004/03L-O on 800807.screen wash pump motor in adjacent fossil unit overheated & breaker would not trip Caused by breaker was & inattention to preventive maint Screen wash pump breakers to be replaced GETTY. B G Pacific Gas & Electric Co 80/09/04 ip

#### V Operator Examinations

8009050321 Forwards "Licensed Operator & Senior Operator Training Programs." Administrative Procedure B-155. in response to NRC 800328 ltr Emergency operating procedures also revised to incorporate pertinent recommendations CRANE,P A Pacific Cas & Electric Co 80/08/20 1p

--8009050324 "Licensed Operator & Senior Operator Training Programs."
Administrative Procedure B-135
\* Pacific Gas & Electric Co 80/08/20 9pp

DOCKET 50-134 WORCESTER POLYTECH INST. RESEARCH REACTOR F Becurity, medical, emergency & fire protection plans

8009020018 Forwards physical security plan Plan withheld (ref 10GFR2 790) WILBUR, L C Worcester Polytechnic Inst 80/06/12 1p

- Q Inspection reports, IE Bulletins & correspondence
- 8009240250 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Ecclusive-Use Shipments of Radioactive Matis "No written response required GRIER.B H Region i. Philadelphia. Office of the Director 80/09/12 ip

DOCKET 50-137 UNIV OF WASHINGTON RESEARCH REACTOR
F Security, medical, emergency & fire protection plans

8009040240 Submits security plan Plan withheld (ref 10CFR2 790) VALENTE,F A Seattle Univ 80/08/27 3pp

ODCKET 50-142 UCLA TRAINING REACTOR

G Adjudicatory correspondence

- 8007040203 Supplemental contentions to 800522 petition to intervene Alleget omission of essential info by applicant resevere reactor damage I lack of spare parts Supporting documentation & Certificate of Syc encl
  HERSCH.D Committee to Bridge the Oap 80/08/25 140pp
- 8009170192 Provides background info re Director's decision under 10CFR2 206 denying Committee to Bridge the Cap petition to shutdown research reactor NRC did not exempt univ from code requirements N/o encl decision
  TEDESCO.R L Assistant Director for Licensing. 80/09/29 3pp
- B009040292 Forwards documents he early licensing & operation to be used in present application for DL renewal Licensee physical security plan withheld (ref 10CFR2 790) Same documents sent to all parties except applicant M/o encis
  GRAY.U R Hearing Branch I 80/09/02 ip
- GOO7230016 Response in opposition to Committee to Bridge The Gap supplemental petition to intervene Discusses irrelevancy & lack of merits of contentions & expresses desire to explain & elaborate concerns at prehearing conference WDODS-O R , MELMICK, C , REIDHAAR, D L California, Univ of, Berkeley SO/09/09 200p
- ~~8009230018 "UCLA Reactor is Safe" Exhibit B Fifteen of 22 pages

  ★ California, Univ of, Berkeley 80/01/03 15pp
- --B009230021 Certifies typ of response to Committee to Bridge The Cap supplemental petition to intervene, on 800909 CDSTALUPES,Y California, Univ of, Berkeley 80/09/09 2pp
- 8009240456 Forwards list of primary areas of contention & corrected typographical errors contained in "Committee to Bridge Gap Supplemental Contentions to Petition for Leave to Intervene" Requests that J Bay be maintained on svc list HIRSCH.D Committee to Bridge the Gap 80/09/15 Spp
- 8009180469 Statement in support of Committee to Bridge The Gap admission as intervenor due to submittal of one good contention Individual positions re Contentions 1 - 23 listed Certificate of Svc enci LAVERTY, J H Hearing Branch 1 80/09/16 37ap
- 8009230747 Forwards NRC response to Committee to Bridge The Cap contentions re application for Dicense renewal M/o enci LAVERTY, J. H. Hearing Branch 1 80/09/18 1p
- P Operating license stage documents & correspondence
- 8009140321 Forwards info re facility location, restricted areas, emission monitoring, sampling sys & seismic test, in response to NRC 800731 ltr "Atmospheric Dispersion of Arm41 from UCLA Nuclear Reactor" encl WEOST, W.F. California, Univ. of, Los Angeles 80/09/05 30pp
- ~-8009160322 "Atmospheric Dispersion of Ar-41 from UCLA Nuclear Reactor "
  RUBIN.K F California, Univ of, Los Angeles 76/12/31 64pp

- DOCKET 50-147 ROCKWELL INTL CORP CRITICAL FACILITY

  G Inspection reports, IE Bulletins & correspondence
- 8009240407 Forwards IE Insp Rept 50-147/80-01 on 800603-04 & 11 No noncompliance noted BOOK.H & Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/07/11 2pp
- --8007240533 IE Insp Rept 50-147/80-01 on 800603-04 & 11 No noncompliant noted Major areas inspected meter & smear surveys of facility, review of records of radiation surveys instruments & techniques
  CURTIS.J R . MENBLAWSKI.F Region 5, San Francisco, Office of the Director BOOK.H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/07/11 pp

DOCKET 50-152 FLORIDA WEST COAST NUCLEAR GROUP INC

G Inspection reports, IE Buildtins & correspondence

8007230387 Forwards IE Circular 80-20, "Changes in Safe-Slab Tank Dimensions " No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/08/21

DOCKET 50-155 BIO ROCK POINT NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

- 8009230295 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Bys installed for got use during emergency KEPPLER. J G Region 3. Chicago. Office of the Director 80/09/22
- G Adjudicatory correspondence
- 8009040262 Forwards documents re aircraft crash risks & military low level training routes in response to 800724 ltr NRC applied acceptance criteria of std review plan re case of 852 bomber crash into facility
  MODRE, J E Hearing Branch 2 80/08/29 2pp
- --B009040269 Bubmits updated analysis of risks associated w/accident involving aircraft on low level training route Probability of crash in three nautical mile square enclosing plant is less than one in one hundred million per yr NICHOLS, D.L. Air Force, Dept of B0/01/19 7pp
- ---8009040274 Advises that Air Force training route is being adjusted so that centerline of route will pass 12 miles west of plant at closest point DDD flight info re military training routes encl
  KANTOR, F Accident Analysis Branch 80/02/11 App
- 6009110802 Motion for withdrawal of appearance as counsel due to financial burden Intervenor intends to remain as party w/o counsel despite unfair imbalance of power wORDAN.W S , SHELDON K P , WEISS, E R Christa-Haria 60/09/05
- 8009110365 Forwards motion for withdrawal of appearance as counsel in spent fuel pool expansion proceeding Clients cannot afford lawyer NRC should realize impact of imbalance of resources on ability of public to trust NRC decision in case M/o encl JORDAN.W 8 Sheldon: Harmon & Weiss. 80/09/08 1p
- 8009150339 Forwards util response to Interrogatory 3-5, including Tech Specs, procedures & requested documents Requests that Page 41 of response to Interrogatory 3-6, aubmitted 800822; be corrected to documents indicated Related correspondence GALLO, J Isham, Lincoln & Beale 80/09/10 2pp
- --8007150344 Util response to Interragotory 3-5 propounded by Christa-Maria, et al Certificate of Svc.affidavits. Tech Specs, procedures & related correspondence encl GALLO, J Consumers Power Co GALLO, J. Isham, Lincoln & Beale 80/07/09 550pp
- 800916043B Forwards ASLB 800912 memorandum & order & ASLAB 800912 order Requests brief amicus be filled on 801020 or 1124 depending on council position Motion for deadline extensions may be filled if necessary W/o encis
  BISHQP,C J Atomic Safety and Licensing Appeal Panel 80/09/12

- 8009160525 Notice of assignment of ASLAB in spent fuel pool expansion proceeding AS Rosenthal, Chairman, JH Buck & TS Moore, members
  - BISHOP,C J Atomic Safety and Licensing Appeal Panel 80/09/12
- 8009170175 Memorandum & order directing NRC to prepare EIS per NEPA re add1 operation arising from spent fuel pool expansion Intervenor O'Neill Contention 8 admitted but will not be subj to discovery prior to DES Refers rulings to ASLAB GROSSMAN, H., PARIS, O. H., SHON, F.J. Atomic Gafety and Licensing Board Panel 80/09/12 19pp
- 8009220185 Forwards notices of appearance by J Gallo,PP Steptoe & P Thornton on behalf of GPC Certificate of Svc encl OALLO,J Isham, Lincoln & Beale 80/09/17 ip
- --8007220216 Notice of appearance on behalf of CPC GALLO, J Consumers Power Co 80/09/17 ip
- ---8007220217 Notice of appearance on behalf of CPC STEPTOE.P.P. Consumers Power Co. 80/09/17 ip
- --8009220218 Notice of appearance on behalf of CPC THORNTON, P Consumers Power Co 80/09/17 3pp
- 8009230030 Order substituting Page 19 of ASLB 800912 memorandum & order on NEPA raylew re spent fuel pool expansion GROSSMAN, H Atomic Safety and Licensing Board Panel 80/09/18 ip
- ---8009230033 Substitute Page 15 of ASLB 800912 memorandum & order on NEPA review re-spent fuel pool expansion \* Atomic Safety and Licensing Board Panel 80/09/12 1p
- 8009260650 Informs of temporary withdrawal from proceedings re facility installation of storage racks for spent fuel Withdrawal caused by harassment & consequent mental stress to family \* Christa-Maria 80/09/23 2pp
- 8009300033 Forwards memorandum of 800923 conference call between ASLS & parties except J D'Neill re spent fuel pool expansion proceeding OROBEMAN. H Atomic Safety and Licensing Board Panel 80/09/24 ip
- ---8009300036 Memorandum of 800923 conference call between parties except J O'Neill re spent fuel pool expansion proceeding Addresses Christa-Maria temporary withdrawal assistance to intervenors & further scheduling re safety issues GROSSMAN,H Atomic Safety and Licensing Board Panel 80/09/24
- J Insurance & indemnity information
- 8007230443 Forwards Endorsement 82 to NELIA Policy NF-117 IRELAND.J H Consumers Power Co 80/09/16 4pp
- P Operating license stage documents & correspondence
- 8009110554 Suppls NRC 800707 request for proposed Tech Specs changes re scram discharge vol vent & drain valves. & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT.D 0 Division of Licensing 80/07/22 22pp
- 8009020297 Submits interim criteria for shift staffing to all DL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D 0 Division of Licensing 80/07/31 7pp
- 8007080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities," Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0676 encl W/o NUREO EIBENHUT.D O Division of Licensing 80/08/01 119pp
- 8009020340 Bummary of 800728 meeting w/util in Charlevoix County.MI re licensee proposed risk assessment of facility Mod to surveillance testing of diesel generator proposed by NRC was also discussed PAULSON,U A Operating Reactors Branch 5 80/08/06 4pp
- --8009020343 "Procedure to Determine Extent of Core Damage (For 0% to 100% Core Meltdown) "

  \* Consumers Power Co 80/06/10 5pp

- BO09230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittel should include proposed class of amend EISENHUT.D © Division of Licensing BO/08/07 60pp
- 8009050500 Forwards Amend 33 to License DPR-6.safety evaluation & notice of issuance & availability
  PAULSON, II A Operating Reactors Branch 5 80/08/11 2pp
- --8009050504 Amend 33 to License DPR-6, changing surveillance requirements for verifying operability of power operated valves in containment spray sys PAULSON.W A Operating Reactors Branch 5 80/08/11 5pp
- --8009050507 Safety evaluation supporting Amend 33 to License DPR-6

  # Office of Nuclear Reactor Regulation, Director 80/08/ii App
- --809950509 Notice of issuance & availability of Amend 33 to License DRR-6 PAUSEM, W.A. Operating Reactors Branch 5 80/08/11 2pp
- BOO9040088 Confirms that two specific Event 5 valve configurations do not exist at facility Review efforts on other configurations continuing CRUICHFIELD.D Operating Reactors Branch 5 BO/08/12 3pp
- --8009040103 "Primary Coolant Sys Pressure Isolation Valves, Big Rock Point," technical evaluation rept NDELL,P N , STILHELL,T C Franklin Institute/Franklin Research Center NRC-03-79-118 B0/07/21 4pp
- 8009110746 Notification of 800916 meeting w/SEP owners group to discuss NRC initial review & recommendations for site-specific ground response spectra & owners group program plans for seismic functional qualification of Class IE equipment LEVIN:H A Division of Engineering 80/08/26 ip
- 8009150042 Notification of 800908-11 meetings at plant sites w/utils to discuss environ qualification of electrical equipment PAULSON-W A Operating Reactors Branch 5 80/08/27 2pp
- B009100374 Forwards corrected tables to util 791203 response to MRC request for add1 info on proposed Tech Bpec changes to radiological effluents
  HOFFMANN D P Consumers Power Co 80/08/28 3pp
- 8009030490 Responds to NRC 800808 ltr on generic concerns re adequaty of station electric distribution sys voltages Dffsite power sys & onsite distribution sys are sufficiently capable to automatically start & operate all required safety loads HOFFMAN D P Consumers Power Co 80/08/29 11pp
- 8007040423 Natifies of procedural problem in complying w/NRC 800023 memorandum & order re electrical equipment qualification Emergency radiation assessment sys cannot invoke IEEE 323-1974 Best components consistent w/order will be used HOFFMAN. B P Consumers Power Co 80/09/02 3pp
- 8009100973 Discusses proposed increase in emergency diesel generator start time acceptance criteria per 800225 Tech Spec change request Approval will provide increase in power output & allow time use for reporting & failure rate determination HOFFMAN.D P Consumers Power Co 80/09/02 2pp
- 8009100521 Forwards design descriptions of containment pressure & water level instrumentation mods in response to NRC 790913 ltm specifying requirements for plant mods resulting from TMI Lessons Learned Identification of NRC concerns requested HOFFMAN D P Consumers Power Co 80/09/05 41pp
- 8009290143 Notification of 800926 meeting w/utils & Kerr-McGee Chemical Corp in Bethesda.MD to discuss review % recommendations for site specific ground response spectra & program plans for seismic functional qualification of Class IE equipment ALLISON.D P Systematic Evaluation Program Branch 80/09/08 3pp
- BOO9240022 Notification of second rescheduling until BO1003 for meeting w/SEP owners group & KMC, Inc to discuss NRC initial review of site-specific ground response spectra & util program for setsmic functional qualification of Class IE equipment ALLISON, D.P. Systematic Evaluation Program Branch BO/09/10 Tpp
- EIOO7250278 Forwards corrected Tech Spec Page 7.Section 3 5 i(d) & Page 143.Section 1i 4 3 45 to replace errors identified during review grior to implementation of Amend 33 to License DPR-6 HOFFMAN, D P Consumers Power Co

- --8009250279 Corrected Tech Spec Page 7. Section 3 5 1(d) & Page 143-Section 1) 4 3 48 + Consumers Pewer Co 80/09/12 2pp
- 8009300231 Forwards "Sys Design & Functional Description of Big Rock Point Plant Steam Drum/Reactor Vessel Level Instrument Mod." FD-CPM-002.Revision 1 Addl layer instrumentation deferred pending completion of overall risk assessment HOFFMAN.D P Consumers Power Co 80/09/18 2pp
- ~-B009300235 "Sys Design & Functional Description of Big Rock Point Plant Steam Drum/Reactor Vessel Level Instrument Mod." Revision 1 → Energy Incorporated FD-CPH-092 Rt 80/09/09 18pp
- G inspection reports: IE Builetins & correspondence
- 8009040540 Forwards IE Bulletin 80-07. Suppl 1. "BNR Jet Pump Assembly Failure " Response required KEPPLER, J G Region 3. Chicago. Defice of the Director 80/05/14
- 8009120504 Forwards IE Insp Rept 50-155/80-08 on 800611-26 No noncompliance noted DAVIS.A B Region 3, Chicago. Fuel Facility & Haterials Safety Branch 80/08/01 2pp
- --8009120509 IE lasp Rept SD-(55/80-08 on 800411-26 No noncompliance noted Major areas inspected results of previous sample collection ESSIG.T H. JANUSKA.A Q Region 3. Chicago, Office of the Director 80/08/01 4pp
- 8007030229 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER. J O Region 3. Chicago. Office of the Director 80/08/15 to
- 8009150494 Forwards JE Info Natice 80-30. "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain 6E BMR Facilities " No specific action or response requested KEPPLER.J G Region 3. Chicago. Office of the Director 80/08/20
- 8007120035 Forwards Suppl 3 to IE Bulletin BD-17, "Failure of Control Rods to Insert During Scram at BWR" Written response regusted
  KEPPLER. J G Ragion 3. Chicago. Office of the Director 80/08/22
- B009170415 Forwards IE Circular 80-18. "10CFRS0 59 Bafety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director B0/08/22
- 8009110817 Ack receipt of 800718 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-155/80-04
  KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/26
- --B009(10820 Forwards response to NRC 800613 ltr re violations noted in IE Insp Rept 50-195/80-04 Corrective actions high radiation areas securely locked technical personnel training improved & noble gas monitoring increased H0FFMAN.D P Consumers Power Co 80/07/18 8pp
- 8009180102 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Identified relays are not used in facility Receipt of bulletin Revision 1 does not change response

  HOFFMAN. B P Consumers Power GO 80/08/28 1p
- 8009230093 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover( 480 Volt Type K-600S & K-DON 600S Circuit Breakers " No written response required KEPPLER, J Q Region 3: Chicago. Office of the Director 80/08/28
- 8009230489 Forwards Revision 1 to IE Bulletin 79-26. "Boron Loss From BUR Control Blades" Hritten response required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/08/29 1p

- 8009260125 Forwards response to IE Bulletin 80-17. Suppl 3. "Failure of 76 of 185 Control Rods to Fully Insert During Stram at BMR "Facility Stram discharge sys meets requirements w/o addl mods or surveillance HOFFMAN.D P Consumers Power Co 80/09/02 3pp
- 8009260146 Forwards response to IE Bulletin 80-15. "Possible Loss of Emergency Notification Sys (ENS) w/Loss of Offsite Power"
  Util expediting correction of health physics line power source w/MI Bell Telephone Co
  HOFFMAN.D P Consumers Pawer Co 80/09/02 4pp
- 8009240096 Forwards IE Circular 80~21, "Regulation of Refueling Crews "
  No written response required
  KEPPLER.J G Region 3, Chicago, Office of the Director 80/09/10
  ia
- R Periodic operating reports & related correspondence
- 8007030544 Forwards "Semiannual Radioactive Effluent Release Rept," Jan-June 1980 HOFFMAN.D P. Consumers Power Co. 80/08/27 In
- --8009030547 "Semiannual Radioactive Effluent Release Rept." Jan-June 1980 4 Consumers Power Co 80/08/27 12pp
- 8 Reportable occurrences, LERs & related correspondence
- 8009020070 Farwards LER 80-021/03L-0 HOFFMAN, D P Consumers Power Co 80/08/25 1p
- --B009020077 LER B0-021/03L-0 on 800729 following intermittent automatic test circuit alarms, sensor channel D of reactor depressurizing sus was removed from svc to vent level transmitter LT31B3 Caused by minor callbr shift # Consumers Power Co 80/08/25 ip
- 8007020266 Forwards LER 80-023/01T-0 HOFFMAN, D P Consumers Power Co 80/08/26 1p
- --800902027: LER-80-023/01T-0 on 800812, review of reactor containment design for steam line breaks in primary sys indicated that containment atmosphere temp can exceed temp criteria previously used Operating instructions revised \* Consumers Power Co. 80/08/26 20pp
- 8007090458 Forwards LER 80-022/03L-0. HOFFMAN, D.P. Consumers Power Co. 80/09/05 1p
- --8009090474 LER 80-022/031-0 on 800807, during monthly specific gravity checks, cells 38.39 % 56 of reactor depressurizing battery for channel C had low readings Cause not known Cell units 13 % 19 replaced Channel C restored on 800813 + Consumers Power Co 80/09/05 ip
- 8009190098 Forwards LERs 80-024/03L-0,80-025/03L-0,80-026/03L-0 & 80-027/03L-0 Consumers Power Co 80/09/12 19
- --8009190101 LER 80-024/03L-0 on 800814, after periodic automatic test circuit alarms, reactor depressurizing sys sensor channel D was removed from syc to vent reactor water level transmitter LT3189 Gaused by minor calibr shift in transmitter 4 Consumers Power Co 80/09/12 lp
- ---8009190105 LER 80-025/03L-0 on 800819, after periodic automatic test circuit alarms, reactor depressurising sys sensor channel D was removed from syc to yent reactor water level transmitter LT3183 Caused by minor calibr shift in transmitter \* Consumers Power Co 80/09/12 1p
- --8009190124 IER 80-026/03L-0 on 800820, after periodic automatic test circuit alarms, reactor depressurizing sys sensor channel D was removed from syc to vent reactor water level transmitter LT3183 Gaused by minor callbr shift in transmitter \* Consumers Power Co 80/09/12 ip
- --8007170127 LER 80-027/03L-0 on 800814.after periodicautomatic test circuit alarms, reactor depressurizing sys sensor channel D was removed from syc to vent reactor water level transmitter LTG183 Caused by minor calibr shift in transmitter & Consumers Power Co. 80/09/12 1p

DOCKET 50-156 UNIV OF WISCONSIN RESEARCH REACTOR

😆 Reportable occurrences, LERs & related correspondence

SICO9040397 Advises of noncompliance w/10CFR85 3 from 800627-0818 Util submitted renewal application for License SDP-3278 on 800424.but license expired before NRC final action Appropriate personnel notified that license was invalid CASHWELL,R J Hisconsin, Univ of, Madison 80/08/26 1p

DOCKET 50-157 CORNELL UNIV RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

E3009230643 Mat1 in support of application to renew & amend License R-80 "Financial Rept.1978-1979." "Final Safeguards Rept. Supp 1." proposed Amend 8 to Tech Spec & license & proposed emergency plan anci COUME.W D Cornell Univ 80/09/15 19pp

I Financial information

EDO09230443 Matl in support of application to renew & amend License R-BO "Financial Rept. 1978-1979." "Final Safeguards Rept. Bupp 1." proposed Amend 6 to Tech Spec & license & proposed emergency plan encl COUKE, W D Cornell Univ BO/09/15 19pp

₩ Utility Final Safety Analysis Report (FSAR) & amends

EDO09230643 Matl in support of application to renew & amend License R-80 "Financial Rept,1978-1979," "Final Safeguards Rept, Supp 1." proposed Amend 8 to Tech Spec & license & proposed emergency plan encl COUKE.W D Cornell Univ 80/09/15 19pp

P Operating license stage documents & correspondence

EIOO9230643 Hat1 in support of application to renew & amend License R-BO "Financial Rept.1978-1979," "Final Safeguards Rept. Supp I:" proposed Amend B to Tech Spec & license & proposed emergency plan encl CODKE, M D Cornell Univ BO/09/15 19pp

🔾 Inspection reports, IE Bulletins & correspondence

BO09240221 Forwards IE Info Notice 80-22. "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required ORIERS H Region 1. Philadelphia. Office of the Director 80/09/12 1p

COCKET 50-166 UNIV OF MARYLAND RESEARCH REACTOR

F. Operating license stage documents & correspondence

BO09080474 Forwards FR notice of proposed renewal of license, in response 800523 application Existing license will not be deemed expired until present application determined MILLER, J R Standardization & Special Projects Branch 80/08/11 2pp

---8009080478 Notice of proposed renewal of license extending expiration date until 200627 Request for hearing & petitions to intervene may be filed subj to regulations
MILLERJR Standardization & Special Projects Branch 400/08/11

Q Inspection reports, 16 Bulletins & correspondence

8009240247 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls "No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/09/12 ip

V Operator Examinations

B009110317 Advises that licensee June 1980 requalification program is unacceptable w/o encl documentation re presently approved program COLLING.P F Operator Licensing Branch 80/09/02 1p

DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

F Security, medical, emergency & fire protection plans

800929016B Forwards emergency plan TYLER:PE Defense.Dept of: Defense Intelligence Agency 80/09/26 10

--8009290171 Emergency plan for TRIGA reactor ANDERSON, F. Dames & Moore 80/09/03 37pp

P Operating license stage documents & correspondence

8009030450 Forwards proposed Amend 17 to Tech Specs, specifying safety limits & limiting conditions, surveillance requirements, design features & administrative requirements Replaces previous focument in docket file

TYLER, P. E. Defense, Dept. of, Defense Nuclear Agency 80/09/01 1p

--8009030452 Proposed Amend 17 to Tech Specs, specifying safety limits & limiting conditions, surveillance requirements, design features & administrative requirements
4 Defense, Dept of, Defense Nuclear Agency 80/08/29 60pp

8009290359 Forwards EIA data for renewal of License R~84 TYLER,P E Defense,Dept of, Defense Nuclear Agency 80/09/26 11pp

Q Inspection reports, IE Bulletins & correspondence

8009240275 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matis "No written response required GRIER, B H Region i, Philadelphia, Office of the Director 80/09/12 ip

V Operator Examinations

8009190195 Forwards proposed "Reactor Operator Requalification Program" for review per NUREG-0094
TYLER.P E Defense.Deot of, Defense Nuclear Agency 80/09/17 1p

--8009190199 Proposed "Reactor Operator Requalification Program"

\* Defense Dept of, Defense Nuclear Agency 80/09/17 22pp

DOCKET 50-17: PEACH BOTTOM ATOMIC POWER STATION, UNIT 1

E NRC Safety Evaluation Report (SER), suppls & correspondence

8009020053 Forwards draft comments on SER Items 3 2 3(1)-(4),3 2 9. 3 2 13-15 & 3,2 4 from fire protection review Final Item 3 1 8(2) wiil be sent shortly HALL,R E Brookhaven National Laboratory 80/08/21 Spp

F Security, medical, emergency & fire protection plans

B009250274 Requests permission to record conversations on dedicated telephone connection installed between facilities & NRC Bethesda.MD headquarters COUNEY.M J Philadelphia Electric Co 80/04/18 ip

- 8009070364 Forwards amended fire protection review. Item 3 ( i re Area & cable spreading room fire detection sys HALL.R E Argonne National Laboratory 80/07/15 2pp
- 8007090362 Forwards comments on tire protection review Items 3 2 3(1). (2). (3). (4).3 2 9.3 2 13.3 2 14.3 2 15 & 3 2 4 re fire detection sys & ventilation ducts Final Item 3 1 8(2) comments will be sent shortly HALL.R E Brookhaven National Laboratory 80/08/21 6pp
- 8009230189 Requests that all personnel be reminded of purpose of emergency notification sys t health physics network Sys installed for govt use during emergency GRIER. B H Region 1. Philadelphia, Office of the Director 80/08/22 3pp
- 8009090424 Forwards info on Item 3 2 8(1) & (2) re fire barrier penetration seals for fire protection review HALL,R E Brookhaven National Laboratory 80/08/26 2pp
- R Periodic operating reports & related correspondence
- 8009020245 Forwards "Peach Buttom Atomic Power Station Thermal Mapping Rept 80-3 for 900715,23 & 31 <sup>1</sup> WILLSEY,W B Philadelphia Electric Co 80/08/26 1p
- --8009020246 "Peach Bottom Atomic Power Station Thermal Mapping Rept 80-3 for 800715.23 & 31 " \* Philadelphia Electric Co 80/08/26 Spp
- DOCKET 50-182 PURDUE UNIV RESEARCH REACTOR
  P Operating license stage documents & correspondence
- 8009100550 Forwards Amend 4 to License R-87 MILLER, J. R. Standardization & Special Projects Branch 80/09/28 Jpg
  - 8009100653 Amend 4 to License R-67, revising physical security plan MILLER J R Standardization & Special Projects Branch 80/08/28 2pp
- ICKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR
  Security, medical, emergency & fere protection plans
- 8009100504 Submits security info Info withheld (ref 10CFR2 790) CARTER R S Commerce, Dept of, National Bureau of Standards 80/09/04 1p
- G Inspection reports, fE Bulletins & correspondence
- 8009240278 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required SRIER.8 H Region 1, Philadelphia, Office of the Director 30/09/12 ip
  - 19240281 Forwards IE Info Notice 80-32. "Clarification of Certain lequirements for Exclusive-Use Shipments of Radioactive Natis " No written response required RIER, B H Region I. Philadelphia, Office of the Director 10/09/12 tp
  - KET 50-185 PLUM BROOK REACTOR MOCK-UP
  - 9020431 Seeks NRC response to 800317 request for issuance of ismantling order & termination of Licenses TR-3 & R-93 unding for project was included in FYB1 budget Lack of NRC ismantling orders prevents contracting of work NRC INEDICT.DE National Aeronautics & Space Admin 80/08/25 2pp
  - ET 50-186 UNIV OF MISSOURI RESEARCH REACTOR
  - 10586 Discusses deviation from Tech Specs 3 6, requiring samples for test hole to hold rigidly in place during reactor action Review of importance of visual verification of pie loadings conducted w/entire operating staff IBBEN, J C , BRUGGER, R M Missouri, Univ of, Columbia 80/09/18

- R Periodic operating reports & related correspondence
- 8009030212 Forwards "Annual Rept.June 1979 June 1980" & "Std Operating Procedures " Repts available in Central Files only KCKIBBFN.J C Missouri, Univ of, Columbia 80/08/27 ip
- S Reportable occurrences. LERs & related correspondence
- 8009040404 RO on 800803, entire holding tank failed to meet primary fech Specs Caused by inadvertent entry of approx 400 gallons of water failing to meet primary specs Holdup tank drained & water meeting primary specs returned to tank MCKIBBEN.J C , BRUGGER.R M Missouri. Univ of. Columbia 80/08/29
- 8009040418 RG on 800829, primary inlat isolation valve 5078 failure to shut when securing primary sys following shutdown Caused by separation of lower seat from metal insert in Schrader valve tonsequent blockage of skaust part MCKIBBEN, J.C., BRUGGER, R.M. Missouri, Univ. of, Columbia 80/08/29 4an
- --8009040417 RU on 750620, investigation of Schrader 9725 series threeway solenoid valve indicated valve could fail if lower seal separated from metal insert & prevent air from being exhausted Mfg confirmed problem through testing JULIAN.C A , ALGER, D M Missouri, Univ of, Columbia 75/06/20 6pp
- DOCKET 50-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC
- 8009240271 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required GRIER B if Region 1, Philadelphia, Office of the Director 80/09/12 ip
- DOCKET 90-199 MANHATTAN COLLEGE RESEARCH REACTOR

  G Inspection reports, IE Bulletins & correspondence
- 8007240225 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/09/12 1p
- DOCKET 50-201 WEBF VALLEY REPROCESSING PLANT
  F Security, medical, emergency & fire protection plans
- 8007230215 Requests that all personnel be reminded of purpose of emergency motification sys & health physics network Sys installed for govt use during emergency GRIER, B H Region 1. Philadelphia, Office of the Director 80/08/22 3pp
- G Adjudicatory correspondence
- 8009080468 Urges strong support & cooperation to implement insp & evaluation program re condition of high level liquid waste storage sys
  DIRCKS.U J Office of Nuclear Material Safety & Safeguards
  80/06/26. 4pp
- 8009170366 Comments on rulemaking 50-5 re mixed oxide fuel GESMO & other recycle-related licensing proceedings should continue Positive affirmative action to approve licenses recommended KIRK, W F William F Kirk 80/08/28 4pp
- 8009160224 Requests OEBMO re fuels be completed Info is needed for future decisions re reprocessing of spent nuclear fuel VILLEMY.G R Affiliation Unknown 80/09/08 ip
- 8009160420 Comments on rulemaking 50-5 GESMO proceedings should be reopened to provide early procedural framework for subsequent licensing RICHARDS,R B General Electric Co 80/09/08 2pp
- 8009300514 Expresses concern re-respensing of DESMO & other related licensing proceedings for reprocessing sites FEIQ.D Affiliation Unknown 80/09/13 1p

- B009220226 Comments on rulemaking 50-5 GESMO proceedings should be respensed Technical, economic & safety issues must be addressed in order for decisions to be made re use of mixedweitzberg. A Affiliation Unknown 80/09/15
- 8009260641 Urges resumption of GESMO hearings BOLON, A.E. Affiliation Unknown 80/09/16
- --8009260646 Opposes reprening of GESMO hearings BURRELL, A Affiliation Unknown 80/09/13
- --8009260652 Urges reopening GESMO & recycle-related proceedings & consideration of expanding scope to include recycle of LWR fuel in breeder reacturs
  MCCORMACK.M House of Rep 80/09/22 2pp
- 8009300525 Forwards comments in response to Commission 800807 order re terminated GESMO proceedings Reopening would be inimical to natl security & defense & at odds w/nonproliferation objectives
  BIALIK, E. I. New York, State of 80/09/23 7pp
- 8009300540 Comments on reopening of QESMD proceedings Addl use of nuclear generated electricity should be paced to preserve significant quantities of hydrocarbon reserves for use as raw matts in future chemical mfg BURRIS,L American Institute of Chemical Engineers 80/09/23 2pp
- 8009300549 Request extension of time for comment on Commission 800807 order re respening OESMO proceeding HOLDEN.R B Allied General Nuclear Services 80/09/23 1p
- 8009300541 Supports reopening of GESMO & other recycling license proceedings
  PRICE, J.E. Affiliation Unknown 80/09/23 ip
- H Coneral correspondence
- 8009100490 Comments on RM 50-3 public should be advised of advantages & disadvantages of implementing Pu recycle NRC should not have terminated efforts on GEBMO fuels
  DECHER.U Affiliation Unknown 80/09/03 1p
- P Operating license stage documents & correspondence
- 8009120545 Forwards 800710 ltr on behalf of NY State Energy R&D Authority re Western NY Nuclear Syc Ctr GITLEN,P H Berle,Butiel,Kass & Case 80/07/10, 1g
- --8009120549 Responds to NRC 800605 ltr re Western NY Nuclear Svc Ctr Recognizes requirements of provisional OL are independent of various contractual provisions & obligations that exist between NFS & NY State R&D authority LAROCCA, J.L. New York, State of 80/07/10 3pp
- 8007100202 Bummary of 800717 meeting w/NFS & NY Energy Research & Development Authority in West Valley, NY re facility issues associated w/work by contractor, Rockwell Hanford Operations TINO,W W Advanced Fuel & Spent Fuel Licensing Branch 80/07/22 Jop
- Q Inspection reports, IE Bulletins & correspondence
- 8007110684 Forwards JL Larocca 800710 ltr re matters involving Western NY Nuclear Svc Ctr on behalf of NY State Energy R&D Authority GITLEN,P H Berle, Butsel, Kass & Case BO/07/10 ip
- --B009110692 Responds to NRC B00626 ltr re program for insp & evaluation of facilities for storage of high level liquid radwaste Advised plant that failure to repair pan-leak constitutes default of obligations under general agreement LAROCCA.JL New York: State of 80/07/10 2pp
- 8009250356 Ack receipt of 800701 ltr informing NRC of steps taken to correct violations noted in JE Insp Rept 50-201/80-04 Ltr withheld (ref 10CFR2 790) MARTIN.W.O Region 1. Philadelphia, Safeguards Branch 80/08/05
- --8009250359 Forwards nonproprietary version of IE Insp Rept 50-201/80-04 on 800519-21 Notice of violation withheld (ref 10CFR2 790)
  MARTIN, W O Region 1. Philadelphia. Safeguards Branch 60/06/17

- ~~8009250263 Nonproprietary version or IF Insp Rept 50-201/80-04 on 800519-21 Noncompliance noted failure of contract security guard to sign in when on duty Details withheld (ref 100FR2 790) 10CFR2 790) DEVLIN, J W Region 1. Philadelphia, Safeguards Branch KCDECHA, L M Region 1. Philadelphia, Office of the Director 80/06/11 ip
- 8009230412 Forwards IE Circular 80-20, "Changes in Safe-Slab Tank Dimensions " No written response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/08/21 4pp
- R Periodic operating reports & related correspondence
- 8009120601 Forwards SPDES discharge monitoring rept for May 1980 DUCKKORTH, J P Nuclear Fuel Services, Inc. (subs. of Getty Gil Co.) ĺρ 80/06/05
- --8009120404 SPDE8 discharge monitoring rept for May 1980
  DUCKMORTH, J.P. Nuclear Fuel Services, Inc. (subs. of Getty Dil. Co.) 80/06/26 Spp
- 8009170378 Forwards "Fifty-third Quarterly Environ Monstoring Rept. Apr-June 1980 "

  DUCKWORTH, J P Nuclear Fuel Bervices, Inc , West Valley Reprocessing Plant 80/07/18 1p
- --8009170382 "Fifty-third Quarterly Environ Monitoring Rept. Apr-June Nuclear Fuel Services, Inc . Hest Valley Reprocessing Plant
- 8009110648 Forwards SPDES discharge monitoring rept.Jul 1980 DUCKKORTH.J P Nuclear Fuel Services, Inc. (subs. of Oetty Gil Co.) 80708704 19
- --8009110652 SPDES discharge monitoring rept.Jul 1980
  \* Nuclear Fuel Services. Inc. (subs. of Getty Gil Co.) 80/08/04
- U Congressional/Executive Correspondence
- 8009150020 Responds to Subcommittee on Nuclear Regulation 780906 ltr re Senator Stafford request for hearing to discuss 1972 momo re pressure suppressing containments. UCS criticisms re ATMS safety problems & Most Valley insp problems HENORIE, J M Commission 80/08/18 2pp
- O'REILLY. J.P. Atomic Energy Commission, Directorate of Regulatory Operations 72/09/20 ip
- ---8009150098 Discusses actions taken in response to anonymous allegation re facility leakages Rept should include ref to litr & allegations which AEC investigated Recommends establishment of local PDR Routing slips enci ENGELKEN.R H Atomic Energy Commission, Directorate of Regulatory Operations 72/09/21 App
- --8009150107 Discusses unannounced insp of facility, investigating allegations re leakage accidents from stacks & pending lawsuit on overexposure No substance to allegation on stack leakage No overexposure to radiation indicated ENGELKEN.R # Abomic Energy Commission, Directorate of Regulatory Operations 72/10/04 lp
- --B009150112 Summarizes /20919-29 followup insp results Three violations do not constitute hazard Inquiry made into allegations in 720903 ltr Licensee will be reinspected on Priority I basis EPSTE(I). E Atomic Energy Commission, Directorate of Regulatory Operations 73/01/05 ip
- --B009150118 Forwards Insp Rept 50-201/72-03 Person referred to in anonympus ltr was H Baadeek Info re overe;posure of const workers was relayed to State of NY on 720921 U/o encl rept NELSON, P R Atomic Energy Commission, Directorate of Regulatory Operations 73/01/05 lp
- ~~8009150121 Forwards notice of violation cited in IE Imap Rept 50-201/72-03 on 720919-23 t 26-29 NELSON, P R Atomic Energy Commission, Directorate of Regulatory Operations 73/01/05 2pp
- --8009150127 Notice of violation from 11sp on 720919-23 & 26-29

  4 Atomic Energy Commission, Directorate of Regulatory Operations 73/01/05

- --8009150132 Ack receipt of AEC 730105 itr relitems of nancompliance cited in Insp Rept 50-201772-03 on 720919-23 & 26-29 Corrective actions operators were reprinanced for actions & proper methods for solution transfers were reviewed DUCKMORTH, J. P. Nuclear Fuel Services, Inc., West Valley Reprocessing Plant 73/01/26 2pp
- --8009130138 Act receipt of 730126 itr informing AEG of actions taken to correct items of noncompliance noted in Insp Rept 50-201/72-03 Corrective actions will be verified during next insp NELSON.P R Atomic Energy Commission. Directorate of Regulatory Operations 73/03/30 3Pp
- --8009190139 Ack receipt of Insp Rept 50-201/72-03 No objection lodged to publication in PDR MILLER R N Nuclear Fuel Services, Inc. (subs. of Getty 0:1 Co.) 73/04/05 1p

-9080409 Submits summary of Dingell subcommittee markup session on lest Valley waste solidification bill. HR 6865 Bill as mended passed by subcommittee LARK.A T Advanced Fuel 5 Spent Fuel Licensing Branch 80/08/22

JCKET 50-205 SAN GNOFRE NUCLEAR STATION, UNIT 1
Socurity, medical, emergency & fire protection plans

8009030358 Notifies of 800819, 22 & 30 regional workshops re development of guidance for acceptable method for coping w/emergencies at facility Requests that representative be sent Subj areas to be discussed include function of facilities & location ENGELERIA H Region 5. San Francisco, Office of the Director 80/08/12 2pp

09230342 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency ENGELKEN,R H Region 5. San Francisco, Office of the Director 80/08/22 Spp

09030387 Forwards revised safeguards contingency plan per NRC 791211 & 800324 requests Plan withheld (ref 10CFR2 79D) BASKIN-K P Southern California Edison Co 80/08/28 2pp

)9050286 Forwards Revision 1 to security force training & qualification plan Plan withheld (ref. 10CFR2 790) BASKHLK P. Southern California Edison Co. 80709703 1p

### Adjudicatory correspondence

)09300253 Forwards order for mod of license, requiring info to support environ qualification of safety-related electrical equipment Briefings were held w/all interested licensees during wk of 800717 CRUTCHFIELD.D Operating Reactors Branch 5 80/08/29 2pp

-B009300258 Order for mod of License DPR-13, requiring info to support environ qualification of safety-related electrical equipment EISENHUT, D O Division of Licensing 80/08/29 App

#### Ceneral correspondence

009050359 Urges NRC not to issue low power fuel loading license for Unit 2 LITFINIK Affiliation Unknown 80/08/28 ip

NOOPLIGGOOD Opposes low level testing & licensing of facility, since no evacuation plan possible MARTINEZ, PR Affiliation Uninown 80/08/29 1p

3009120444 Opposes licensing of facility for low level testing due to undue risks posed to health & safety of public & environ RROMN,P Affiliation Unknown 80/08/29 1p

3009050350 Expresses apposition to nuclear energy & licensing of Unit & COHEN.P Affiliation Unknown 80/09/03 ip

8009110430 Opposes granting low power loading license to avoid evacuation plan requirements
PULIDG.M Affiliation Unknown 80/09/03 ip

- P Operating license stage documents & correspondence
- 8009120505 Notification of contract execution, Mod 5 to "Simulation of Earthquake Ground Motions for San Onofre" Contractor K Aki
  MCNULTY, A Administrative Contracts Branch FIN 8-6531 80/04/01
- --8009120514 Mod 5, extending pariod of performance & adding addl funds to "Simulation of Ground Motions for San Onofre" AMI, K Massachusetts Institute of Technology PERLMAN, J Administrative Contracts Branch FIN 8-6591
- 8009090880 Advises that list of 60 additionally populated areas have been included in enci revised guidance document, NUREQ-0861, per NRC amend interim rule for physical protection of irradiated reactor fuel in transitie
- B009020297 Submits interim criteria for shift staffing to all GL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D Q Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREO-Q696. "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation achedule for meeting criteria of NUREO-0696 enci W/o KUREO EISENMUT.D O Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D O Division of Licensing 80/08/07 60pp
- 800910000B Notification of cancellation of 800B26 meeting w/util in Bethesda.MD to discuss requirements for change over from safety injection to recirculation mode operation NOWICK1.SJ Operating Reactors Branch \$ 80/08/11 2pp
- 8007190794 Forwards revised Westinghouse STS 3 9 8 2.3 9 10 % Bases 3/4 9 8 5 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NOVAK.T H Assistant Director for Operating Reactors 80/08/15
- --8009190817 Revised Westinghouse STS 3 9 8 2:3 9 10 & Bases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods \*\*Assistant Director for Operating Reactors \*\*80/06/23 21pp
- 8009020063 Forwards response to NRC 800523 itr requesting response to FSAR Questions 361 65 re comparative analysis of results of site-specific earthquake program & empirical evaluations for facility

  BASKIN, K.P. Southern California Edison Co. 80/08/21, 15pp
- 8009020082 Forwards repts referenced in 800428 submittal re seismic adequacy of plant per 800711 telcon request BABKIN, K P Southern California Edison Co 80/08/21 2pp
- ~-8009020085 "Reduction in Free Field Ground Motion Due to Presence of Etructures," submitted to Southern CA Edison Co \* TERA Corp 80/08/91 17pp
- ~-B009020091 "Experimental Investigations~Correlation W/Analysis" presented at 770711-15 proceedings of Natl Science Foundation workshop, Univ of CA. Berkeley SHEPPHERD. R. UENNINGS, P. C. California Institute of Technology 77/07/11 20pp
- --8009020096 "Seismic Performance of Piping in Past Earthquakes." submitted for presentation & publication at 800915-i7 Speciality Conference on Civil Engineering & Nuclear Power in Knozville-TH CLOUD.R L. Rubert L. Cloud Associates, Inc. 80/09/15 29pp
- --BOO9020100 "On Instrumental vs Effective Acceleration & Design Coefficients." presented at 790822-24 proceedings of Second UB Natl Conference on Earthquake Engineering, Stanford Univ.CA BLUMEJ A John A Blume & Associates, Engineers (subs URB Corp 1 79/08/22 15pp

- 8009110746 Notification of 800916 meeting w/SEP numers group to discuss NRC initial review & recommendations for site-specific ground response spectra & owners group program plans for seismac functional qualification of Class IF equipment LEVIN.H A Division of Engineering 80/08/26 ip
- 8009120547 Notification of 800903 meeting w/util in Bethesda.MD to discuss util submittal for steam generator repairs NOWICKI.S J Operating Reactors Branch 5 80/08/26 2pp
- 8009030634 Forwards application for Amend 92 to License DPR-13, consisting of Proposed Changes 97.98 & 99 to Tech Specs License amend fee encl DIEFCH, R Southern California Edison Co 80/08/27 2pp
- --8009030637 Application for Amend 92 to License DPR-13.consisting of Proposed Changes 97.98 & 99 to Tech Specs Certificate of Syccenci DIETCH.R Southern Celifornia Edison Co 80/08/27 Spp
- --8009030644 Proposed Changes 97.98 & 99 to Tech Spec 3 7 re auxiliary electrical supply. Tech Spec 3 3 re safety injection & containment spray sys & Tech Specs 5 0 & 6 0 re administrative controls

  \* Southern California Edison Co 80/08/27 12pp
- 8009100417 Summary of 800724 meeting w/applicants to discuss analysis of Imperial Valley earthquake of Oct 1979 ROOD: H Licensing Branch 3 80/08/27 16pp
- 8009:50420 Natification of contract execution "Followon to Simulation of Earthquake Ground Motions for San Gnofre Nuclear Oenerating Station," awarded to E Luco LITTLE, M Administrative Contracts Branch FIN 8-6898-0 80/08/27
- ---8009150424 Contract "Followen to Simulation of Earthquake Ground Motions for San Onefre Nuclear Generating Station." awarded to E'Luco
  LUCG, J E Luco, J E PERLMAN, J Administrative Contracts Branch
  FIN B-6898-0 80/08/27 5pp
- 8009240052 Notification of contract execution "Followon to Simulation of Earthquake Ground Motions for San Onofre Nuclear Oenerating Station " Contractor R Hermann LITLE, M Administrative Contracts Branch FIN 8-6898-0 80/08/28 tp.
- --8009240057 Contract "Followen to Simulation of Earthquake Oround Motions for San Onofre Nuclear Opperating Station: "awarded to R Hermann HERMANN, R St Louis Univ PERLMAN, J Administrative Contracts Branch FIN 8-4898-0 80/08/28 5pp
- E0090B0343 Responds to NRC 800728 ltr requesting util provide plan concerning evaluation of cable trays Criteria for re-evaluation will be determined based upon cable tray test program results Action plan encl
  BASKIN,K P Southern California Edison Co 80/08/29 3pp
- 8007070463 Forwards add1 info on effects of non-Category A equipment failure requested at 800804-05 meeting w/NRC & LLL.
  BASKIN, K P Southern California Edison Co 80/08/27 App
- H009190361 Forwards "Steam Cenerator Repair Rept " BASKIN,K P Southern California Edison Co 80/08/29 3pp
- --8009190365 Errata to "Steam Generator Repair Rept," nonproprietary version

  4 Westinghouse Electric Corp SE-SP-58(80) ERR 80/08/29 ip
- --B009190374 Forwards "Steam Generator Repair Rept," proprietary & nonproprietary versions Application & affidavit for Uthholding encl
  ANDERSON.T M Wastinghouse Electric Corp B0/09/11. 10pp
- --8009190378 "Steam Generator Repair Rept," nonproprietary version AKIN.R C , ROSENTHAL.W P. Westinghouse Electric Corp SE-SP-58(80) 80/09/30 380pp
- 8009090552 Advises that responses to NRC 800723 request for add1 info re steam generator & reactor coolant pump supports should be available for submittal by 800919 BASKIN.K P Southern California Edison Co 80/09/02 ip

- 8009160230 Forwards Page 24 of "Simulation of Earthquake Ground Motions for San Dnoffe Nuclear Generating Station. Unit 1. Suppl II "Page 24 was inadvertently omitted from rept submitted on 800808 BASKIN N P Southern California Edison Co 80/09/05 1p
- --8009160231 Page 24 of "Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station.Unit 1.5uppl 1[ " Page 24 was inadvertently omitted from rept submitted on 600808 + Del Mar Technical Associates 80/09/05 ip
- 8009170238 Confirms understanding based on 800905 discussions during mpt meeting at util ofcs.re actions to be taken for correction of observed weaknesses in radiation protection program NRC should be notified if understanding incorrect ENGELKEN.R R Region 5. San Francisco, Diffice of the Director 80/09/05 2pp
- BOOTOB0322 Forwards additinfo restructural topics in response to NRC 790816 ltm Design wind velocity of 100 miles/h was used for containment sphere BAEKIN-K P Southern California Edison Co 80/07/08 15pp
- ---B009080326 "Addendum 2 to Guality/Safety-Related Civil Structural Const Spec for Sphere Encl Project for Southern CA Edison Co SDM98-1 " Bill of matl for storage tanks dtd 640526 & related matl encl # Bechtel Power Corp (subs of Bechtel Corp ) 77/03/29 507pp
- 8009290143 Notification of 800926 meeting w/utils & Kerr-McGee Chemical Corp in Bethesda,MD to discuss review & recommendations for site specific ground response spectra & program plans for seismic functional qualification of Class IE equipment ALLISON.D P Systematic Evaluation Program Branch 80/09/08 Opp
- 8009250022 Notification of second reschaduling until 801003 for meeting w/SEP owners group & KMC. Inc to discuss ARC initial review of site-specific ground response spectra & util program for seismic functional qualification of Class IE equipment ALLISON.D P Systematic Evaluation Program Branch 80/09/10 3pp
- 8009190402 Responds to NRC 800815 request to review facility Tech Specs to ensure that 23 ft of water is over top of reactor pressure vessel flange during movement of fuel assemblies or control roof Facility is in compliance DASKIN,K P Southern California Edison Co 80/09/11 1p
- BOO9170336 Notifies that actions required in NRC 800702 ltr re license amend application concerning implementation of TMI Lessons Learned requirements cannot be accomplished by BO0712 License amend application will be submitted by 810116 BASKIN,K P Southern California Edison Co 80/09/12 1p
- 8009290348 Responds to 800703 itr requesting addlinfore differences in Unit I design from SEP assessments Description of safety injection sys should be clarified in terms of alternate method in event of preferred path failure
  BASKIN, K P Southern California Edison Co 80/09/22 2pp
- 8009300377 Forwards response to 800723 request for addl info re steam generator & reactor coolant pump supports

  8ASKIN,K P Southern California Edison Co 80/09/23 5pp
- 8009300362 Bubmits current status of structural evaluations & summary of program for evaluation of piping & equipment Detailed evaluations of plant structures are scheduled for completion in June 1981
  BASKIN K P Southern California Edison Co 80/09/24 3pp
- BOO930044B Ack receipt of 800B29 request for addl info re failure of salt water cooling sys Input from several engineers & operating entities required to complete request Response will be submitted BOI00B BASKIN.K P. Southern California Eduson Co 80/09/24 ip
- G Inspection reports, IE Bulletins & correspondence
- 8009090Bii Reschedules response to Item 2 of IE Bulletin 80-04.

  "Analysis of PWR Main Stream Line Break w/Continued Feedwater Addition " Response will be forwarded by 800801, pending MSLB core response reanalysis OTTOSON, H L Southern California Edison Co 80/07/16 2pp.
- 8009170207 Forwards response to 1E Bulletin 80-11. "Masonry Hall Design " Describes masonry walls at facility that are in proximity to or have attachments from safety-related piping equipment DTTOSON, H L Southern California Edison Co 80/07/17 6pp

- 8909150011 Responds to Item 2 of IE Bulletin 80-04 re analysis of reactivity increases due to main steam line break inside or outside containment Previous response validated OTTOSON, H.L. Southern California Edison Co. 80/08/04 2pp
- 8009160830 Responds to IE Bulletin 79-13 Revision 2, "Cracking in Feedwater Sys Piping " Radiograph exam performed on all feedwater notile to reducer by reducer to pipe welds w/no deficiencies noted of TOSEND. H. I. Southern California Edison Co. 80/08/07 3cc
- 80092A0297 Forwards IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange" No written response required ENGELKEN,R M Region 5, San Francisco. Office of the Director 80/08/07 1p
- 8009020448 Summary of 800710 meeting w/util in Bethasda.MD re results of steam generator insps & corrective actions
  NDHICKLS J Operating Reactors Branch 2 80/08/08 48pp
- 8009030283 Forwards Revision I to IE Bulletin 80-19, "Faitures of Morcury-Netted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required ENGELXEN.R H. Region 5, San Francisco, Office of the Director
- 8009160521 Responds to IE Bulletin 80-19. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E "Mercury-wetted relays not used in Factity reactor protective sys OTTOSON.H L Southern California Edison Co 80/08/15 is
- 8009290457 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " ENGELKEN,R H Region 5, San Francisco, Office of the Director SO/08/18 4pp
- 8009160:84 Forwards IE Circular 80-18. "IOCFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys ' No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/08/22 1a
- 8009120443 Forwards IE info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-4003 & K-DON 4005 Circuit Breakers" No written response required EffELKEN,R M Region 5. San Francisco, Office of the Director 80/08/27 tp
- R Periodic operating reports & related correspondence
- B009030333 Forwards "San Chofre Nuclear Generating Station Semiannual Operating Rept," for Jan~June 1980 OTTOSON:H L Southern California Edison Co 80/09/27 ip
- --8007030535 "San Onofre Nuclear Generating Station Semiannual Operating Rept." for Jax-June 1980 \* Southern California Edison Co \* San Diego Oas & Electric Co 80/08/27 7pp
- 8009090265 Forwards monthly operating rept for Aug 1980 CURRAN-J M Southern California Edison Co 80/09/04, lp
- S Reportable occurrences, LERs & related correspondence
- 6009020078 Forwards LER 80-031/03L-0 OTTOSON.H L Southern California Edison Co 80/08/21 3pg
- --BD09020083 LER BD-031/03L-0 on 800728 during routine equipment rotation, south saltwater cooling pump discharge valve failed to open automatically Caused by installation of soleroid valve operator w/urong size spring Valve replaced CURRAM, J M Southern California Edison Co 80/08/19 ip
- BOOGISO139 PMO-V-80-067 on BOOGO2, licensee reported that workers involved in steam generator head entries may have radiation exposures in excess of 3 rem per quarter Largest exposure is 7 rem Caused by monitoring thest instead of head YUMAS.G. HENSLANSKI,F Region 5, San Francisco, Office of the Director 80/09/02 200
- 009260509 Forwards LER 80-032/01T-0 HAYNES.J 6 Southern California Edison Co 80/09/16 3pp

- --8009260513 t.ER 80-033/017-0 on 800902, actuation of safety injection block switch followed by loss of offsite power indicated sequencer test box would not perform as designed Caused by design deficiency Rodesign is underway CURRAN, J M Southern California Edison Co 80/09/14 3pp
- 8009300615 PNO-V-80-069 advertisement in Southern CA newspaper offering \$100.00 per day for work involving exposure to radiation has attracted media attention Region 5 is closely monitoring steam generator repairs

  YUHAS.C P. WENSLAMENI, F. Region 5. San Francisco, Office of the Director 80/09/16 ip

# DOCKET 50-208 COLUMBIA UNIV RESEARCH REACTOR

- G Inspection reports, IE Bulletins & correspondence
- 8009240218 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required CRIER, B.H. Region 1, Philadelphia, Office of the Director 80/09/12 ip

#### DOCKET 50-213 HADDAM NECK PLANT

- f Security, medical, emergency & fire protection plans
- 8009230169 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency ORIER, B H Region i, Philadelphia, Office of the Director 80/03/22.
- P Operating license stage documents & correspondence
- 8009020297 Submits interim criteria for shift staffing to all DL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT,D Q Division of Licensing 80/07/31 7pp
- B0090B00B0 Forwards draft NUREQ-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREQ-0696 encl W/o NUREQ EISENHUT, D O Division of Licensing 80/08/01 119pp
- 8009(20707 Forwards agenda of 800821 meeting at util ofcs to discuss assessment of regulatory performance GRIER.D H Region 1. Philadelphia. Office of the Director 80/08/04 2pp
- 9009230052 Informs that exemption from fee re licensing action associated 6/7M1-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D O Division of Licensing 80/08/07 60pp
- 8009190794 Forwards revised Westinghouse STS 3 9 8 2,3 9 10 & Bases 3/4 9 8 & 3/4 9 10 to require 23 it of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NDVAK.T M Assistant Director for Operating Reactors 80/08/15 to
- ~-8009190817 Revised Westinghouse STS 3 9 8 2.3 9, 10 3 Bases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods 4 Assistant Director for Operating Reactors 80/06/23 21pp
- 8009100454 Advises that mgt meeting w/NRC in Berlin,CT has been rescheduled for 800911 Agenda encl ORIER,B H Region 1, Philadelphia, Office of the Director 30/08/20 2pp
- 8007020231 Forwards add1 info to Questions 2.3 % 4 re adequacy of station electric distribution sys voltages per Crutchfield 800701 itr Response to Question 1 will be submitted by 801126 COUNSIL. 0 , FEE, W F Connecticut Yankee Atomic Power Co 80/08/21 7ag
- 8009110746 Natification of 800916 meeting w/SEP owners group to discuss NRC initial review & recommendations for site-specific ground response spectra & owners group program plans for selsmic functional qualification of Class IE equipment LEVIN, H.A. Division of Engineering 80/08/26 ip

- B009030532 Advises that NRC 800728 request for SEP licensees to specifically address issue of seismic support criteria for internally attached components of safety-related electrical equipment not feasible approach CCUNBLIM G. FEELM F. Northeast Nuclear Energy Co. (4ubs. of Northeast Vtilities). 80/08/27 2pp
- 8009030641 Discusses implementation status of automatic initiation auxiliary feedwater Control-grade scheme is installed & will be made operable after NRC review & approval Final safety-grade design will be forwarded Class IV amend fee encl COUNSIL.N & Connecticut Yankee Atomic Power Co 80/08/27 4pp
- --8009030646 Proposed revisions to Tech Spec 3 8 for operation of turbine cycle Revisions specify conditions of turbine cycle equipment necessary to insure capability to remove decay heat from reactor core

  \* Connecticut Yankee Atomic Power Co 80/08/27 6pp
- 8009030378 Advises that util will not meet deadline for implementation of NUREG-0578 requirements re emergency procedures & retraining for accidents & transients NRC feedback needed COUNSIL W G COUNSIL W G COUNSIL W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/08/28 2pp
- B009120257 Responds to NRC B0070B ltr re SEP Topics III-10 A,V-II A,VI-4,VI-7 C 1 & VIII-3 B Concurs w/NRC conclusions.except for Topic VIII 3 B Control room contains battery fuse open alarm in addition to alarms noted in NRC assessment COUNBIL.W 0 . FEE.W F Connecticut Yankee Atomic Power Co B0/09/04 2pp
- 8009290143 Notification of 800924 meeting w/utils & Kerr-McGee Chemical Corp in Bethasda,MD to discuss review & recommendations for site specific ground response spectra & program plans for seismic functional qualification of Class IE equipment ALLISON,D P Systematic Evaluation Program Branch 80/07/08 3pp
- 8009260022 Notification of second rescheduling until 801003 for meeting w/SEP numers group & KMC. Inc to discuss NRC initial review of site-specific ground response spectra & util program for seismic functional qualification of Class IE equipment ALLISON, D.P. Systematic Evaluation Program Branch 80/09/10 3pp
- 8009180357 Forwards implementation status of Category B TMI-2 Lessons Learned requirements for each facility Schedules specifically identify items where requirement cannot be met or schedule is not feasible COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/09/15 43pp
- 8007230621 Submits add1 info re seismic re-evaluation program Significant progress has been achieved Modeling of structures is approx 75% complete & RCS is approx 76% complete COUNSIL.N O FEE.N F Connecticut Yanked Atomic Power Co 80/09/15 Spp
- BO09290351 Application for amend to Licenses DPR-61.DPR-21 & DPR-65, incorporating revisions to Tech Specs for RCS per TMI-related requirements Fee encl COUNSIL, W G COUNSIL, W G COUNSIL, W G Northeast Utilities B0/09/16 App
- --B009290354 Proposed revisions to Tech Bpecs 3 3 for RCS operational components

  \* Connecticut Yankes Atomic Power Co 80/09/30 5pp
- --8009270358 Proposed revisions to Tech Bpecs 3 ii for containment \* Connecticut Yankee Atomic Power Co 80/09/30 App
- --8009290362 Proposed revisions to Tech Specs 6 3 for administrative controls of facility staff qualifications
  4 Connecticut Yankee Atomic Power Co 80/09/30 3pp
- --8009290367 Proposed revisions to Tech Specs 6 0 for administrative controls
  \* Connecticut Yankee Atomic Power Co 78/12/08 4pp
- ---9009290372 Proposed revisions to Tech Specs 3/4 4 3 for limiting condition for operation of RCS relief sys
  \* Connecticut Yankse Atomic Power Co 78/12/08 3pp
- --8009290377 Proposed revisions to Tech Spect 3/4 4-3a re limiting conditions for operation of RCS relief valves-operating \* Connecticut Yankee Atomic Power Co 80/09/30 jp

- --8009290381 Proposed levisions to Tech Specs 3/4 4 4 for limiting conditions for operation of RCS pressurizer \* Connecticut Yankoe Atomic Power Co 80/09/30 2pp
- --8009290384 Proposed revisions to Tech Specs 3/4 4 5 for RCS steam generators
  \* Connecticut Yankee Atomic Pawer Co 80/09/30 ip
- --8009290387 Proposed revisions to Tech Specs 6 0 for administrative controls

  \* Connecticut Yankee Atomic Power Co 80/09/30 Jap
- 8009260478 Forwards util petition for declaratory ruling re Power Facility Evaluation Council jurisdiction over proposed spent resin storage facility Action on petition withheld, pending investigation of issue of superseding federal authority POND, 0 D Connecticut, State of 80/09/17 8pp
- Q Inspection reports, IE Bulletins & correspondence
- 8009120247 Responds to IE Bulletin 80-16 No Resemble 1151 or 1152 pressure transmitters w/Codes A or D installed or planned to be installed in safety or nonsafety-related application COUNSIL, If G Connecticut Yankee Atomic Power Co. 80/07/30 2pp
- 8009110474 Responds to IE Bulletin 79-13 b forwards summary rept of insp of feedwater sys piping No unacceptable piping companents identified COUNBIL:0 9 Connecticut Yankee Atomic Power Co 80/08/01 Spp
- 8009030113 Forwards Revision 1 to IE Builetin 80-19, "Failures of Mercury-Metted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/08/15 Ip
- 6009020015 Forwards results of May 1980 steam generator tube insp GRAVES R H Connecticut Yantoe Atomic Power Co 80/08/22 ip
- ---B009020016 "Steam Generator Tube Inservice Insp." for May 1980

  \* Connecticut Yankee Atomic Power Co 80/05/31 75pp
- 8009180003 Forwards IE Circular 80-18, "10CFRSO 59 Safety Evaluations for Changes to Radwaste Treatment Bys " No written response required GRIER.6 II Region 1, Philadelphia, Office of the Director 80/08/22 1p
- 8009120174 Forwards IE Info Notice 80-31. "Maloperation of Gould-Blown Bover: 480 Volt Type K-6008 & K-DDN 6008 Circuit Breakers" No written response required GRIER, B H Region I. Philadelphia. Office of the Director 80/08/27 ip
- 8009230779 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required GRIER, B H Region i, Philadelphia, Office of the Director 80/09/10 ip
- 8009240303 Forwards JE Info Notice 80-32. "Clarification of Certain Requirements for Exclusive-Use Bhipments of Radioactive Matls " No written response required ORIER.18 It Region 1. Philadelphia. Office of the Director 80/09/12 ip
- R Periodic operating reports & related correspondence
- 8009040380 "Semiannual Radioactive Effluent & Waste Disposal Rept," Jan-June 1980
  - \* Connecticut Yankee Atomic Power Co 80/06/30 55pp
- 8009180175 Forwards monthly operating rept for Aug 1980 GRAVES.R H Connecticut Yankee Atomic Power Co 80/09/10 1p
- ---9009180180 Monthly operating rept for Aug 1980 \* Connecticut Yankee Atomic Power Co 80/09/10 9pp

- DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT F Security, medical, emergency & fire protection plans
- 8009230174 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Bys installed for govt use during emergency GRIER, B H Region 1. Philadelphia. Office of the Director 80/08/22 Opp

### G Adjudicatory correspondence

- 8009300265 Forwards order for mod of license, requiring info to support environ qualification of safety-related electrical equipment Briefings were held w/all interested licensees during which 600717 CRUICHFIELD.D Operating Reactors Granch 5 80/08/27 2pp
- --8009300269 Order for mod of license requiring info to support environ qualification of safety-related electrical equipment EISENHUL D 0 Division of Licensing 80/09/29 App
- 8009190299 Responds to FOIA request for 15 documents listed in bibliography of NUREO-0625, "Rept of Siting Policy Task Force" Documents 6-8 % 13 are available in PDR Forwards remaining documents FELTON, J M Division of Rules and Records 80/09/04 ip
- --8009190587 Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants for determination of site acceptability by adequacy of engineered safety features.

  MINDOUE, R B Office of Standards Development, Director SECY-79-362 79/06/04 7pp
- ---8009190630 Requests that encl. "Differences in Procedures for Estimating Atmospheric Dispersion Conditions at Inland & Coastal Sites," be sent to appropriate Boards SCINTO, JF Hearings Division 79/04/04 lapp
- 8009090395 Memorandum i order, ALAB-612, remanding ASLB 800222 order for further proceeding per ALAB-611 Relationship between significant upresolved generic safety issue & reactor operation under scruting must be resolved BIEMDP.C J Atomic Safety and Licensing Appeal Panel 80/09/05
- 8009110807 Memorandum & order advising NRC to file add1 info by 80103i re unresolved generic safety issues, per ASLB 800905 order which remanded proceeding LAZOR M Atomic Safety and Licensing Board Panel 80/09/09 2pp

### H General correspondence

- 8009020187 Responds to 800623 itr re RE Cunningham comments on cracks detected in core spray sys spargers Sparger strengthened during Fall 1978 outage Interim measures for neuly found cracks acceptable IE Bulletin 80-13 describes requirements DIRCKS.H J Office of the Executive Director for Operations 80/08/07 2pp
- 8009020191 Requests consideration of encl RE Cunningham 1tr commenting on cracks in core spray sys sparger BRADLEY, B Genate 80/06/23 3pp

#### Operating license stage documents & correspondence

- 10116018 Notification of 790918 meeting w/util in Bethesda.MD to discuss impact of free standing liquid requirements for soled waste
- Environmental Evaluation Branch (Pre 791030) 79/09/17 2pp
- J09090879 Advises that list of 60 addl heavily populated areas have been included in encl revised guidance document.NUREG-0561, per NRC amend rule for physical protection of irradiated reactor fuel in transit.seffective 800703 W/o encl
  MCCORKLE.O W Physical Security Licensing Branch 80/07/07 19
- B009110554 Suppls NRC B00707 request for proposed Tech Specs changes re scram discharge vol vent & drain valves, & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT.D @ Division of Licensing 80/07/22 22pp

- 8009020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D G Division of Licensing 80/07/31 7pp
- 8007080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT, D G Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated m/TMI-2 Lessons Learned is unjustified Previous ASSOCIATED WITHING CHART RESERVED FROM FEE FE ITEMSING A ASSOCIATED WITHING LESSONS LEARNED IS UNJUSTIFIED PREVIOUS determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D G Division of Licensing 80/08/07 60pp
- 8007150506 Forwards request for add1 info from licensee, based upon review of facility inservice testing program Requests meeting w/util on 800723-24
  BDSMAVR U Mechanical Engineering Branch 80/08/20 12pp
- 8009240593 Forwards "Mark I Containment Long-Term Program SER, Resolution of Generic Technical Activity A-7," NUREG-0461 CRUTCHFIELD, D Operating Reactors Branch 4 80/08/20 2pp
- 8009150031 Advises that 800807 Change Request 91 to form new mgt organization is considered to have safety significance & requires Class III amend fee Requests that add1 sum be remitted to NRC DIGOS,R K License Fee Management Branch 80/08/22 1p
- 8009110746 Notification of 800916 meeting w/SEP owners group to discuss NRC initial review & recommendations for site-specific ground response spectra & owners group program plans for seismic functional qualification of Class IE equipment LEVIN.H A Division of Engineering 80/08/26 ip
- 8009020360 Notifies that 800825 Tech Spec Change Request 91 does not alter basic responsibility of util re facility operation Figure 6.2 I cited as ref to proposed mgt reorganization FINFROCK, I R Jersey Central Power & Light Co 80/08/27 ip
- 8009150046 Notification of 800909 meeting w/util in Bethesda.MD to discuss pipe breaks outside containment PAULSON.W A Operating Reactors Branch 5 80/09/02 2pp
- 8009290143 Notification of 800926 meeting w/utils & Kerr-McGee Chemical Corp in Bethesda, MD to discuss review & recommendations for site specific ground response spectra & program plans for seismic functional qualification of Class IE equipment ALLISON, D.P. Systematic Evaluation Program Branch 80/09/08 3pp
- 8009260022 Notification of second rescheduling until 801003 for mesting w/SEP owners group & KMC. Inc to discuss NRC initial review of site-specific ground response spectra & util program for seismic functional qualification of Class IE equipment ALLISON, D.P. Systematic Evaluation Program Branch 80/09/10 3pp
- 800719042! Forwards info re turbine disk intergrity in response to NRC 800611 ltr Table re nominal water chemistry of condensate turbines enci FINFRGCK, I R Jersey Central Power & Light Co 80/09/15 i3pp
- 8009220283 Forwards addl Class 3 amend fee in response to NRC 800807 FINFROCK, I R Jersey Central Power & Light Co 80/09/15 2pp
- 8009290365 Requests changes to App A of License DPR-16 Sections 1 0: 3 5:4 5 & 6 0 to Tech Specs will be revised & Sections 3 13 5 4 13 will be added in response to NRC 800702 itr re NUREO-0578 Category A items Certificate of Syc encl FINFROCK: R Jersey Central Power & Light Co 80/09/23 4pp
- --8009290367 Tech Spec changes for Sections 1 0.3 5.4 5 & 6 3 & addl Sections 3 13 & 4 1.3 to App A of License DPR-16 Clarifying shift technical advisor program # Jersey Central Fower & Light Co 80/09/23 13pp
- 8009300261 Responds to NRC 800905 1tr re TMI-2 Lessons Learned requirements Requests that implementation data of some items be extended Alternative schedules & justification for two itens and FINEROCK,I R Jersey Central Power & Light Co 80/09/26 App

- 8009300270 Ack receipt of 800829 itr re environ qualification of safety-related electrical equipment Util is currently reviewing electrical & mechanical equipment qualifications & will submit supporting info no later than 801101 FINFRUCK. I R Jersey Central Power & Light Co 80/09/26 tp
- @ Inspection reports, IE Bullstins & correspondence
- 3009100034 Forwards IE Insp Rept 50-219/80-11 on 800318-19 Noncompliance noted GRIER, B H Region I, Philadelphia, Office of the Director 80/07/08 2pp
- --H009100044 IE Insp Rept 50-219/80-11 on 800318-19 Noncompliance noted failure to use engineering controls & procedures & to perform surveys in accordance w/100F20 201(b) to assure compliance w/100F20 10(a)(3) MNAPP.P J Region 1. Philadelphia. Fuel Facility & Materials Bafety Branch NIMITZ.R L Region 1. Philadelphia. Office of the Director 80/05/02 15pp
- 8009150119 Forwards IE Insp Rept 50-219/80-20 on 800913-15 No noncompliance noted SHITH.0 H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/07/14 2pp
- ---8009150124 IE Insp Rept 50-217/80-20 on 800513-15 No noncompliance noted Major areas inspected program for GC of analytical measurements & performance on radiological analyses of split actual seffluent samples BORES.R J Region 1. Philadelphia, Fuel Facility & Materials Safety Branch KOTTAN.J J Region 1. Philadelphia. Office of the Director 80/07/10 7pp
- BO09090165 Ack receipt of BO0610 ltr informing NRC of steps taken to correct violations noted in IE Inap Rept 50-219/80-03 QRIER, B.H. Region 1. Philadelphia, Office of the Director BD/07/28 ip
- --8009090181 Responds to NRC 800519 ltr re violations noted in IE Insp Rept 50-219/80-03 Corrective actions breathing air fittings used for purposes other than radiation protection confiscated FINFROCK.I R Jersey Central Power & Light Co 80/06/10 6pp
- --8009090169 Forwards IE Insp Rept 50-219/80-03 on 800121-25 % notice of violation Details withheld (ref 100FR2 790) ORIER, B H Region 1, Philadelphia, Office of the Director 80/05/19 2pp
- --8009070184 Notice of violation from insp on 800121-25 \* Region 1, Philadelphia, Office of the Director 80/04/02 3pp
- --8009090189 IE Insp Rept 50-219/80-03 on 800121-25 Noncompliance noted failure to perform evaluation of radiation hazards, use respiratory protection equipment & label radioactive matl Pg 15-16 withheld (ref 10CFR2 790) NIMTZ:R L Region 1, Philadelphia. Office of the Director 80/04/02 17pp
- BOOT110509 Forwards IE Insp Rept 50-219/80-22 on 800602-06 No noncompliance noted BRUNNER,E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/07/30 2pp
- --B009i105i8 IE Insp Rept 50-219/80-22 on 800402-06 No noncompliance noted Major areas inspected licensee action on previous findings pips support & restraint sys & primary containment integrated lask rate tost.

  CAPHION D L Region 1, Philadelphia, Reactor Operations Nuclear Support Branch, REKITO, W A Region 1, Philadelphia, Office of the Director 80/07/29 · 10pp
- BOO9090235 Responds to IE Bulletin 79-03A No fusion welded stainless steel pipe installed in any safety-related sys ROBS,D,A Jersey Central Power & Light Co BO/08/01 ip
- BOO9120179 Responds to IE Bulletin BO-17 re failure of control rods to fully insert during scram No significant amount of water detected Applicable procedures revised to insure safety No action required re ATWS FINFROCK, IR Jersey Central Power & Light Co BO/08/06 2pp
- E009230104 Responds to IE Bulletin 80-17, Supp A.1-A.5 Analysis showed adequacy of as-built scram discharge vols w/vent & drain sys Addi analyses will be performed & NRC will be provided w/description if deficiencies identified FINFROCK, I.R. Jersey Cantral Power & Light Co. 80/08/07 2pp

- 8009090031 Responds to IE Bulletin 80-19. "Failures of Mercury-Wetted Matrix Relays in Reactor Protection Sys of Operating Nuclear Power Plants Designed by C-E "Facility dues not utilize mercury-wetted relays in safety-related equipment FINFROCK, I R Jersey Central Power & Light Co 80/08/13 1p
- 8009030068 Forwards Revision I to IE Bulletin BO-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required ORIER,B H Region I, Philadelphia, Office of the Director 80/08/15 ip
- 8009160510 Responds to Item B 1 of IE Bullstin 80-17, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR "
  Continuous waste level monitoring sys will not be installed by 800901 due to extended lead time for matl FINFROCK, I R Jersey Central Power & Light Co 80/08/15 2pp
- 8009120087 Forwards Suppl 3 to 16 Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BMR " Written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/08/22 ip
- 8009180006 Forwards 1E Circular 80-18, "10CFR90 59 Bafety Evaluations for Changes to Radwaste Treatment Bys " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director BO/08/22 ip
- B009120227 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DDN 6008 Circuit Breakers " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/08/27 1p
- 8009230493 Forwards Revision 1 to IE Bullatin 79-26, "Boron Loss From PWR Control Blades " Written response required GRIER, B H. Region 1, Philadelphia, Office of the Director 80/08/29 1a
- 8009230782 Forwards IE Circular 80-21, "Regulation of Refueling Crews " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/09/10 Ip
- 8009240345 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required ORIER, B H Region i, Philadelphia, Office of the Director 80/09/12 ip
- 8009300345 Ack receipt of full payment of civil penalties, in response to NRC 800708 ltr w/notice of proposed imposition of civil penalties Corrective actions documented in 800731 ltr will be examined during future insp
  8TELLO.V Office of Inspection & Enforcement, Office of the Director 80/09/17 lp
- R Periodic operating reports & related correspondence
- 8007090348 Forwards Semiannual Rept 80-1. "Radioactive Effluent Releases, Jan-June 1980" ROSS, D.A. Jersey Central Power & Light Co. 80/09/02 1p
- --8009090371 Semiannual Ropt 80-1, "Radioactive Effluent Releases, Jan-June 1980 " \* Jersey Central Power & Light Co 80/09/02 100pp
- 8009230541 Forwards monthly operating rept for Aug 1980 ROSS:D A Jersey Central Power & Light Co 80/09/16 ip
- --8009230564 Monthly operating rept for Aug 1980 MCCLAIN.C M Jersey Central Power & Light Co 80/09/16 9pp
- S Reportable occurrences, LERs & related correspondence
- 8009090354 Forwards LER 80-033/03L-0, ROSS,D A Jersey Central Power & Light Co 80/08/14 ip
- --8009090381 LER 80-033/03L-0 on 800806,24-h after reactor mode switch was placed in RUN, torus oxygen concentration found in excess of 5% Caused by torus oxygen analyzer out of callbr & reduced flow capability of nitrogen purge sys
  ROSS, D A Jersey Central Power & Light Co 80/08/28 4pp

- 8009020379 Forwards Nonroutine Environ Operating Rept 50-219/80-5 FIN-ROCK.1 R Jersey Central Power & Light Co 80/08/26 1p
- 8009020392 Forwards Nonroutine Environ Operating Rept 50-219/80-6 FINFROCK, I R Jersey Central Power & Light Co 80/08/26 Ip
- --8009020398 Nonroutine Environ Operating Rept 50-219/80-6 on 600811.at steady state power.condenser discharge temp exceeded 106 F Caused by shift in meteorological conditions Load reduction initiated & temp stabilized 

  Jersey Central Power & Light Co 80/08/26 2pp
- B009030340 Nonroutine Environ Operating Rept 50-219/80-5 Total of ten dilution pump trips occurred between B00808 & B00912 Caused by high lubricating oil temp Evaluation completed for upgrading cooling water sys FINFROCK, I R Jersey Central Power & Light Co 80/08/26 3pp
- 8009090351 Forwards LER 80-028/03L-0 ROSS.D A Jersey Central Power & Light Co 80/08/28 1p
- --8009090365 LER 80-028/03L-0 on 800730, while performing monthly surveillance testing of reactor high pressure scram sensors. RED3C & REO3D were found to trip at lower than specified pressure values Caused by sensor repeatability ROSS.D A Jersey Central Power & Light Co 80/08/28 3pp
- 8009090353 Forwards LER 80-034/03L-0 RDSS, D.A. Jersey Central Power & Light Co. 80/09/02 1p
- 8009160471 Forwards LER 80-035/03L-0 ROSS.D A Jersey Central Power & Light Co. 80/09/10 1p
- --8009160474 LER 80-035/03L-0 on 800814 during containment spray sys automatic actuation test-high drywell pressure switches IP-15A & IP-15D tripped at higher than specified setpoint of 2 psig Caused by instrument repeatability ROSS:D A Jersey Central Power & Light Co 80/07/10 3pp
- 8009230481 Forwards LER 80-036/03L-Q ROSS.D A Jersey Central Power & Light Co 80/09/15 1p
- ~8009230488 LER 80-036/03L-0. on 800815 & 16 stack releases were not continuously monitored due to failure of stack gas sample sys Caused by loose motor cooling fan on sample pump "B" Sample pump titter replaced & motor cooling fan tightened R085:0 A Carolina Power & Light Co 80/09/15 Spp
- 3009260447 LER 90-037/03L-0 on 800B17 during standby gas treatment sys SOTS surveillance testing. SOTS 2 tripped Caused by misaligned welding lead run across tubing below duct Welding lead realigned & functionally tested ROSS. D A Jersey Central Power & Light Co 80/09/18 3pp
- '300404 Nonroutine Environ Operating Rept 80-7 on 800901.02 & 04, or individual dilution pump trips occurred during which operative or reserve pump could not be started within quired 15 minutes Caused by component failure
  NFROCK, I R Jersey Central Power & Light Co 80/09/19 2pp
- 300522 Forwards LER 80-039/03L-0 NFRCCK, I.R. Jersey Central Power & Light Co 80/09/25 3pp
- 09300528 LER 80-039/03L-0 on 800829, during low pressure main steam line functional test & calibr.RE238 & 23D pressure switches actuated at valve above Tech Spec limits Caused by instrument repeatability Switches reset to desired limit CROS8Y.P J Jersey Central Power & Light Ca 80/09/26 lp
- 300941 LER 80-021 has been cancelled. Jersey Central Power & Light Co 80/09/25. 2pp

- 80D9300564 Forwards LER 80-038/03L-0 FINEROCK, I R Jørsey Central Power & Light Co 80/09/25 3pp
- --8009300557 LER 80-038/03L-0 on 800826 during surveillance testing of reactor triple low water level sensors.RE188 tripped at level less conservative than Tech Spec limits Caused by sensor repeatability Sensor reset within prescribed limits QUINTENZ.T E Jersey Central Power & Light Co 80/09/25 ip
- T Hearing transcripts on non-antitrust matters
- 8009030162 Transcript of B00822 hearing before NJ Dept of Energy, Board of Public Utils in Newark, NJ, re application for electric svc rate increase Pp 313-470 \* New Jersey, State of B0/08/22 158pp
- DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

  F Security, medical, emergency & fire protection plans
- 8009230184 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency GRIER, B H Region 1. Philadelphia, Office of the Director 80/08/22 Spp
- 8009240515 Ack receipt of 800807 request for mod of fire protection implementation schedules Response amends App R rulemaking IPPOLITO.T A Operating Reactors Branch 2 80/09/15 2pp
- G Adjudicatory correspondence
- 8007220013 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by BOLIO1.

  IPPOLITO. A Operating Reactors Branch 2 80/08/29 2pp
- --8009220014 Order for mod of License DPR-63 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101
  EISENHUT, D O Division of Licensing 80/08/29 App
- P Operating license stage documents & correspondence
- 8009110554 Buppls NRC 800707 request for proposed Tach Spacs changes rescram discharge vol vent & drain valves. & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT.D © Division of Licensing 80/07/22 22pp
- 8009020297 Bubmits intorim criteria for shift staffing to all OL & CP licensess & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D 0 Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0694 encl M/o NUREG EISENHUT.D G Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D Q Division of Licensing 80/08/07 60pp
- 8009170389 Advises that two specific Event 5 valve configurations do not exist at facility per review of response to NRC 800923 ltr "Primary Coolant Sys Pressure Isolation Valves," technical evaluation rept encl 1PPOLITO
- --8009170402 "Primary Coolant Sys Pressure Isolation Valves," technica evaluation rept NOELL.P N. 9TILWELL,T C Franklin Institute/Franklin Research Center NRC-03-79-118 80/07/21 5pp
- 8009190788 Forwards NUREG-0661, "Mark I Containment Long-Term Program SER Resolution of Generic Technical Activity A-7" Rept discusses generic suppression pool hydrodynamic load definition W/o encl [PPOLITO,T A Operating Reactors Branch 2 80/08/20 2pp

- 8009190770 Summary of 800821 meeting w/util at plant site re crack in reactor bldg wall PQLK,P J Operating Reactors Branch 2 80/08/26 App
- 8009180547 Advises that response to NRC 791109 ltr re ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture is acceptable No further action necessary IPPOLITO,T A Operating Reactors Branch 2 80/09/05 2pp
- 8009240991 Ack receipt of 800628 ltr re util commitment to meet NUREG-0378 Clarification ltr revising requirements & other TMIrelated problems was forwarded in NRC 800905 ltr Notifies of 800922 meeting to discuss TMI action plan IPPOLITO.TA Operating Reactors Branch 2 80/09/09 2pp
- 8009180340 Forwards application to amend License DPR-63, changing Tech Specs Sections 3 6.4 6 % 6 0 Fee encl THOMAS, E 8. LeBoeuf: Lamb, Leiby & MacRae 80/09/17 2pp
- --8009180344 Application to amend License DPR-63, changing Tech Specs Sections 3 6,4 6 & 6 0 re accident monitoring instrumentation & min shift crew composition DISE,D P. Niagara Mohawk Power Corp 80/09/16 2pp
- --BD09180348 Proposed Tech Specs 3 6.4 6 5 6 0 re accident monitoring instrumentation & min shift crew composition Supporting info encl

  \* Niegara Mohawk Power Corp 80/09/16 13pp
- 8009250403 Submits supplemental response to NRC 800620 ltr re plant shielding design review per NUREO-0378 Solenoids for air operated valves 201 2-03 & 201 2-32 in N-2 purge sys will be relocated Original proposal impractical DISE.D P Niagara Mohawk Power Corp 80/09/17 lp
- G Inspection reports, IE Bulletins & correspondence
- 3009160240 Forwards IE Insp Rept 50-220/80-06 on 800623-27 No noncompliance noted MARTIN.W G Region 1, Philadelphia, Safeguards Branch 80/07/24 200
- --8009160242 IE Insp Rept 50-220/80-06 on 800623-27 No noncompliance noted Major areas inspected approved physical security plan, security program audit 2 security organization Details withheld (ref 10CR2 790)
  BAILEY,R J. Region 1, Philadelphia, Office of the Director DELVIN.J W. Region 1, Philadelphia, Safeguards Branch. 80/07/17
- GOO9220158 Forwards response to LE Bulletin 80-14. Items 1-6, re scram dump vol sys No instances of switch degradation identified Operating Procedure Ni-OP-5 revised to include logging requirement in case of valve inoperability LEMPGES, T.E. Niagara Mohawk Power Corp. 80/07/25 3pp
- 8009070668 Responds to IE Bulletin 80-16 Investigations determined no transmitters installed or to be installed u/specified output Codes A or D LEMPGES-T E Niegara Mohawk Power Corp 80/07/28 ip
- B009120263 Forwards response to IE Bulletin B0-17. Supp 1, re control rod scram sys, Item A Scram discharge vol sys w/associated vant & drain sys are believed to be reliable & adequate to ensure safety, based on series of analyses Affidavit encl LEMP0ES. T & Niagara Mohawk Power Corp 80/08/07 10pp
- 8009030099 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required ... GRIER.B.H Region 1, Philadelphia, Office of the Director 80/08/15 ip
- 8009160808 Describes proposed mod to scram discharge vol vent & drain sys in response to IE Bulletin 80-17. Suppl 1. Item B i Dedicated vent & drain line will be utilized to svc scram discharge vol Detailed description to be sent by 800901 LEMPGEB.T E Niagara Mohawk Power Corp 80/08/15 2pp
- BD09160513 Advises that based on 800814 telcon w/NRC extension granted until 800905 for util to address IE Bulletin 80-15. Item 3 & submit written rept required by Item 6 LEMPGES, T E Niagara Mohawk Power Corp 80/08/15 ip
- 8009120097 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR " Written response required ORIER.B H Region 1, Philadelphia, Office of the Director 80/08/22 ip

- 8009180022 Forwards IE Circular 80-i8, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/08/22 io
- 8009090281 Responds to IE Bulletin 80-19, Revision 1. "Failures of Mertury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Relays are not used at facility
  LEMPGES.T E Niagara Mohawk Power Corp 80/08/27 1p
- 8009120230 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover: 480 Volt Type K-6005 & K-DON 6005 Circuit Breakers " No written response required GRIER: B H Region 1, Philadelphia, Office of the Director 80/08/27 ip
- B009300622 Responds to IE Bulletin 80-19 No mercury-wetted relays installed at facility Eight manhours expended on bulletin LEMPGES,T E Niagara Mohawk Power Corp 80/08/27 ip
- 8009090264 Responds to IE Bullstin 80-17, Suppl 2, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR " Special Operating Procedures Ni-BDP-15, Malfunction of Control Drive Sys & Ni-DP5, Control Rod Driveline Sys were revised LEMPGES,T E Niagara Mohawk Power Corp 80/08/29 Jpp
- B009230495 Forwards Revision 1 to IE Bulletin 79-26, "Baron Loss From BMR Control Blades " Written response required GRIER, B H Region 1, Philadelphia, Office of the Director B0/08/29 ip
- 8009230792 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required ORIER.8 H Region 1, Philadelphia. Office of the Director 80/09/10 lp
- 8009240346 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required GRIER. B H Region 1. Philadelphia. Office of the Director 80/09/12 ip
- R Periodic operating reports & related correspondence
- 8009160213 Forwards "Radioactive Effluent Release Semiannual Rept.Jan-June 1980 " ROMAN, T W Niagara Mohawk Power Corp 80/08/29 ip
- --8009160214 "Radioactive Effluent Release Semiannual Rept.Jan-June 1980 " \* Nilagara Mohawk Power Corp 80/08/29 50pp
- 8009150297 Forwards monthly operating rept for Aug 1980 & narrative rept of operating experience for Aug 1980 & JuliAug, Sept & Oct 1979 LEMPGES, T. E. Niagara Mohawk Power Corp. 80/09/08 3pp
- --8009150299 Monthly operating rept for Aug 1980 ROMAN:T W Niagara Mohawk Power Corp 80/09/08 3pp
- 8009250331 Forwards corrected monthly operating rept for Aug 1980 LEMPGES: T E Niagara Mohawk Power Corp 80/09/17 ip
- --8009250332 Corrected monthly operating rept for Aug 1980 \* Niagara Mohawk Power Corp 80/09/17 lp
- S Reportable occurrences, LERs & related correspondence
- B009160460 Forwards LER 80-016/03L-0 LEMPGES,T E Niagara Mohawk Power Corp B0/09/05 1p
- --8009160467 LER 80-016/03L-0 on 800808, during turbine anticipatory bypass reactor scram switches 02-138 & D surveillance setpoints found out of tolerance Caused by instrument drift Switches readjusted Monthly testing planned HARRISON, P Niagara Mohawk Power Corp 80/09/05 1p
- GOO9150265 Forwards LER BO-018/03L-0 LEMPGEB: T.E. Niagara Mohawk Power Corp. BO/09/08 1p
- --8009130264 LER 80-018/03L-0 on 800808, during normal operation, emergency dissel generator 103 fuel oil day tank low level alarm was received Caused by inadvertent opening of day tank drain valve Tank refilled 011 valve sys locked HARRISON.P Niagara Mohawk Power Corp 80/09/05 2pp

- 8009180268 Forwards LER 80-019/04T-0
  BARTLETT, J. Hiagara Mohawk Power Corp. 80/09/10 ip.
- --8009180278 LER 80-019/04T-O on 800827.during NRC insp at normal operation, discovered removable bottom door seals of outer door of reactor bidg track bay were not installed properly Caused by personnel error HARRISCH.P Niagara Mohawk Power Corp 80/09/09 2pp
- B009300491 Forward: LER 80-017/03L-0 LEMPGES,T E Niagara Mohawk Power Corp 80/09/18 ip
- --B009300495 LER B0-017/03L-0 on B00822 during normal operation.excessive outboard seal water leakage observed on Reactor Feedwater Pump II Caused by normal seal degradation Maint performed & pump returned to svc HARRISOLP Niagara Mohawi Power Corp B0/09/19 1p

#### V Operator Examinations

- 8009120408 Forwards Administrative Procedures APN-10A & 10B.which document licensed operator training & retraining programs

  No ravision to training program is warranted

  DISE,D P Niagara Mohawk Power Corp 80/09/05 ip
- --8009120413 Administrative Procedure APN-10A, Revision 2. "Training of Licensed Operator Candidates " ROMAN, T N . PERKINS, T J , BRYANT, H M. Niagara Hohawk Power Corp BO/05/07 Spp
- -8009120417 Administrative Procedure APN-10B.Revision 2, "Licensed NRC Operator Retraining "
  804841,T W., PERKINS.T J., BRYANT,W M. Niagara Mohawk Power Corp 80/05/07 20pp
- CME1 50-222 COLOMBIA RESEARCH REACTOR

  Inspection reports, & Bulletins & correspondence
- O9120254 Responds to IE Dulletin 79-03A re longitudinal weld defects in SA-312. Type 304 stainless steel pipe SA-312 piping used at facility satisfies criteria Sys pressure-temp values lower than reduced allowable code NOVARRO, J P Long Island Lighting Co 80/08/04 2pp
- CKET 50-223 UNIV OF LONELL RESEARCH REACTOR

  Inspection reports. IE Bulletins & correspondence
- 09240242 Forwards 1E Info Notice BD-32. "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matis " No written response required GRIER, BH Region 1. Philadelphia, Office of the Director 1.
- ESCUPITY, medical, emergency & fire protection plans
- )09020049 Forwards revised Page 15 of proposed security plan Plan withheld (ref 10CFR2 790)
  KAPLAN.S II California, Univ of, Berkeley 80/08/25 2pp

### Operating license stage documents & correspondence

- 1009020040 Application for changes to Amend 2 of License R-101.allowing possession of enriched U other than fuel elements, use of Puberyllum sources for activities other than reactor operation & Tech Spec changes re control rod drop times KAPLAN.5 N California, Univ of, Berkeley 80/08/07 Spp
- 8009180505 Forwards assessment of conservative assumptions in evaluation of DBA.in response to 800717 request re Ofc of Policy Evaluation analysis Limiting jose to thyroic probably conservative by at least three orders of magnitude DENTON.HR Office of Nuclear Reactor Regulation, Director 80/08/13 4pp

- DOCKET 50-225 API CRITICAL EXPERIMENT

  F Security, medical, emergency & fire protection plans
- 8009020012 Forwards critical experiments facility security plan Plan withheld (ref 100FR2 790) Telcon w/P Trimble informed of shipment of excess SNM to Dak Ridge,TN MELSON.PR Rensselser Polytechnic Inst 80/08/22 1p
- O Inspection reports, IE Bulletins & correspondence
- 8009240234 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radinactive Matls "No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/09/12 1p
- DOCKET 50-227 TRIGA THERMIONIC PROTOTYPE REACTOR
  P Operating license stage documents & correspondence
- 8007i60583 Discusses projected fuel utilization for Tarapur reactors Current supply of fuel in India is adequate for four refuelings & would permit scheduled operation of TAPS II to Aug 1791 5 TAPS I to Feb 1782 PETERSON
- DOCKET 50-237 BREBDEN NUCLEAR POWER STATION, UNIT 2

  F Security, medical, emergency & fire protection plans
- 800723028B Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Bys installed for gout use during emergency KEPPLER, J G Region 3. Chicago, Office of the Director BO/08/22 3oo
- 8007100378 Forwards review of util generating station emergency plan & draft ltr requesting addl info & commitments from util PAOANO.F O Emergency Preparedness Licensing Branch 80/08/28 500
- 8009120483 Notifies that Comm Ed does not wish to participate in proposed study re review of people-related problems in nuclear safeguards Responses would be misleading, reflecting inexperience & short-term problems

  ABEL, J S Commonwealth Edison Co 80/09/02 ip
- Q Adjudicatory correspondence
- 8009040200 Advises that subsequent to discussions w/NRC & applicant, State of IL Second Amended Contentions 2, 3, 4, 5(B), 6, 7, & B are admissible Second Amended Contention 10 should be held until 801001 while security plan is reviewed by IL SEKULER, 8 N Illinois, State of 80/08/27 2pp
- --8009040208 Notice of filing & svc of second amended contentions SEKULER, S N . FAHNER, T C Illinois, State of 80/08/27 2pg
- --8009040218 Second amended contentions alleging absence of demonstrated need for spent fuel pool storage expansion Claims inadequacy of monitoring equipment & inadequacy of assessment re rack corrosion frough of svc encl
  SEKULER, S N , FAHNER, T C Illinois, State of 80/08/27 App.
- 80091108]3 Memorandum & order rejecting State of IL 800827 Second Amended Contention i Directs util & NRC to respond to ASLB question re status of spent fuel storage capacity Ruling on Second Amended Contention 10 held in abeyance until 801101.
  LIYTLE, L W. REMICK, F J. WOLF, J F Atomic Safety and Licansing Board Panel 80/09/09. 8pp
- 8009300007 Notice of appearance in spent fuel pool mod proceeding Certificate of 8vc encl BARTH.C A Hearing Branch 3 80/09/26 2pp
- 8007300045 Response to 800909 inquiry re applicability of Commission 730916 policy statement, "Intent to Prepare OEIS on Handling & Storage of Spent LWR Fuel " Not applicable due to Issuance of GEIS in Aug 1779. Certificate of Svc encl GDDDARD,R J Hearing Branch 2 80/09/26 Spp

3

### H General correspondence

- 8009110218 Forwards response to 800728 ltr requesting assistance in answering constituent questions re nuclear power & effects of radiation
  DIRCKS,W J Office of the Executive Director for Operations
- P Operating license stage documents & correspondence
- 7910110018 Notification of 790918 meeting w/util in Bethesda.MD to discuss impact of free standing liquid requirements for solid waste
  LO,R Environmental Evaluation Branch (Pro 791030) 79/09/17 2pp
- 8009110954 Suppls NRC 800707 request for proposed Tach Specs changes re scram discharge vol vent & drain valves. & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT.D 0 Division of Licensing 80/07/22 22pp
- 8009020297 Submits interim criteria for shift staffing to all GL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for Emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D Q Division of Licensing 80/07/31 7pp
- BCD7080080 Forwards draft NUREG-0676, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl W/o NUREG EIGENHUT, b G Division of Licensing 80/08/01 117pp
- 8009230052 Informs that examption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D 0 Division of Licensing 80/08/07 60pp
- 8009020456 Forwards evaluation of util response to NRC 800223 request for info re primary coolant sys pressure isolation valves. Two specific Event 5 valve configurations do not exist at facilities. CRUICHFIELD, D. Operating Reactors Branch 5 80/08/12 3pp
- --8009020467 "Primary Coolant Sys Pressure Isolation Valves," technical evaluation rept NOELLP N, STILMELL,T C Franklin Institute/Franklin Research Center. NRC-03-79-118 80/07/21 5pp
- 8009120279 Forwards evaluation of SEP Topic V-i1 A, "Requirements for Isolation of High & Low Pressure Sys," to be used in integrated safety assessment May be revised to reflect as-built conditions, design changes or NRC criteria mod CRUTCHFIELD, D Operating Reactors Branch 5 80/08/12 6pp
- 8007120281 Forwards evaluation of SEP Topic VIII-3 B, "DC Power Sys Bus Voltage Monitoring & Annunciation " Requests notification if as-built facility differs from licensing basis assumed in assessment GRUTCHFIELD.D Operating Reactors Branch 5 80/08/12 5pp
- 8009180060 Forwards evaluation of SEP Topic III-10A, "Thermal Overload Protection for Motors of Motor Operated Valves " Assessment may be revised to reflect as-built conditions, facility design changes or NRC criteria mod CRUTCHFIELD.D Operating Reactors Branch 5 80/08/12 6pp
- 80091B0312 Forwards evaluation of SEP Topic VI-10 B. "Shared Engineered Bafety Features" Requests to be informed if as-built facility differs from licensing basis CRUTCHFIELD.D Operating Reactors Branch 5 80/08/12 18pp
- 8009150401 Confirms 800811 discussion re arranging 800821 meeting w/util in Chicago. IL re facility cooling lake dike seepage & remedial action to be taken KEPPLER.J O Region 3. Chicago, Office of the Director 80/08/15
- BOO9160216 Responds to BOO616 ltr re SEP Topic XV-16, "Radiological Consequences of Small Lines Carrying Primary Coolant flutside Containment " Questions 1-4 addressed by encl table entitled, "Small Lines Penetrating Containment "

  JANECEK,R F. Commonwealth Edison Co BO/OB/18 4pp
- 8009180252 Forwards NUREO-0661, "Mark I Containment Long-Tarm Program EER Resolution of Generic Technical Activity A-7" Rept discusses generic suppression pool hydrodynamic load definition W/o encl IPPOLITO.T A Operating Reactors Branch 2 80/08/20 2pp

- 8009020105 Forwards NUTECH Rept COM-0708-03, "Evaluation of 18-Inch Containment Isolation Valves for Dreaden Station, Units 2 % 3 % Guad Cities Station, Units 1 & 2," In response to NRC 771022 & 23 ltrs re containment vent & purge valves JANFCEK, R F Commonwealth Edison Co 80/08/22 1p
- --8009020111 "Evaluation of 18-Inch Containment Isolation Valves for Dresden Station,Units 2 % 3 % Quad Cities Station,Units 1 % 2 " GERBER, D. A., DEARDORFF. P. E., MARTIN-J.B. Nuclear Technology, Inc (Nutech) CCM-0708-03 80/05/14 116pp
- 8009090349 Forwards add1 response re SEP environ qualification of electrical equipment per NRC request JANECEK, R Commonwealth Edison Co 80/08/22 41pp
- 8009110746 Notification of 800916 meeting w/SEP owners group to discuss NRC initial review & recommendations for site-specific ground response spectra & owners group program plans for seismic functional qualification of Class IE equipment LEVIN.H A Division of Engineering 80/08/26 ip
- 8009120404 Forwards Attachments 1-5 to util 800630 ltr re facility electric distribution sys voltage adequacy Ltr inadvertently transmitted w/o attachments JANECEK,R F Commonwealth Edison Co 80/08/28 6pp
- 8009110250 Requires submittal of ATWS emergency operating procedure for NRC review Generic analysis should confirm ATWS mitigation capability described in Vol 3 of NUREG-0460 Commission wil) determine required mods & implementation schedules TEDESCO.R L. Assistant Director for Licensing 80/08/29 3pp
- 8009240555 Forwards final critique of 800619 SEP exercise Critique discusses problem areas identified during exercise & presents corrective actions M/o critique DELQEORGE.L.O Commonwealth Edison Co. 80/08/29 1p
- 8007110376 Comments on NRC 800612 evaluation re SEP Topic V-5,RCPB Leakage Detection Info provided re air sampling sys, leak detection sys & reactor drain tank instrumentation Plant is in compliance w/Reg Quide 1 45

  JANECEK.R F Commonwealth Edison Co 80/07/02 2pp
- 8007070374 Forwards add1 info re min critical configuration in support of B00515 application to amend Licenses DRR-19, 25, 27 & 30, changing requirements for source range monitor count rates JANECEK, R F Commonwealth Edison Co 80/09/03 Spp
- 8009180501 Forwards Amends 49,44,58 & \$3 to Licenses DPR-19.DPR-25, DPR-29 & DPR-30,respectively.safety evaluation & notice of issuance & availability IPPOLITO,T A Operating Reactors Branch 2 80/09/08 2pp
- --9009180506 Amends 49,44,58 & 53 to Licenses DPR-19,DPR-25,DPR-29 & DPR-20,respectively,revising Tech Specs to allow count rate on source range monitor channels below 3 counts per second when there are two or less fuel assemblies in quadrant IPPOLITO,T A. Operating Reactors Dranch 4 80/09/08 22pp
- --8009:80516 Safaty evaluation supporting Amends 49,44.58 % 53 to Licenses DPR-19,DPR-25,DPR-29 % DPR-30, respectively \* Office of Nuclear Reactor Regulation, Director 80/09/08 4pp
- --8009180526 Notice of issuance & availability of Amends 49,44,58 \$ 53 to Licenses DPR-19.DPR-25.DPR-29 & DPR-30.respectively IPPOLITO.T A Operating Reactors Branch 2 80/09/08 2pp
- 8009290143 Notification of 800926 meeting w/utils & Kerr-McGee Chemical Corp in Dethesda.MD to discuss review & recommendations for site specific ground response spectra & program plans for seismic functional qualification of Class IE equipment ALLISON.D P Systematic Evaluation Program Branch 80/09/08 3pp
- 8009240022 Nutification of second rescheduling until 801003 for meeting w/SEP owners group & KMC, Inc to discuss NRC initial review of site-specific ground response spectra & util program for seismic functional qualification of Class IE equipment ALLISON, D.P. Bystematic Evaluation Program Branch 80/09/10 3pp
- 8007230469 Forwards proposed Tech Spec changes re implementation of TMI Lessons Learned. Category A requirements, in response to NRC 800702 request Dresden Unit 1 Tech Spec changes will be submitted 90 days prior to scheduled startup JANECEK, R F Commonwealth Edison Co 80/09/18 3pp
- --8009230466 Proposed Tech Spec changes re implementation of TMI-2 Lessons Learned Category A items \* Commonwealth Edison Co 80/09/10 27pp

- 8009280292 Requests add1 60-90 days for review to determine whether as-built facilities differ from basis in NRC assessment Addl time would allow for reproduction, distribution & review methods to function properly JAMECEK, R.F. Commonwealth Edison Co. 80/09/19 1p
- 8009240465 Forwards Inst of Nuclear Power Operations rept. "Evaluation of Dresden Nuclear Power Station"

  LEE. B. Commonwealth Edison Co. 80/09/23 fp
- --8009260468 "Evaluation of Dresden Nuclear Power Station "

  \* Institute of Nuclear Power Operations EA 80-01 80/09/12
  40pp
- Q Inspection reports, IE Builetins & correspondence
- 8009040517 Forwards IE Bulletin 80-07, Suppl 1, "BHR Jet Pump Assembly Failure " Response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/14 lp
- 8007040432 Provides add1 response to IE Bulletin 80-17 Results of analysis of ATMS w/o recurculation pump trip encl Analyses required no deratings to remain below svc level C limit JANECEK, R F Commonwealth Edison Co 80/07/14 Spp
- 8009100143 Forwards IE Insp Repts 50-010/80-12,50-237/80-12 & 50-249/80-16 on 800609-0703 No noncompliance noted HEISHMAN,R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/07/23 2pp
- --8009100148 IE insp Repts 50-010/80-12.50-237/80-12 & 50-249/80-16 on 800609-0703 No noncompliance noted Hejor areas inspected operational safety verification & monthly maint & surveillance observations SPESSARO,R L , BARKER,J L , TONOUE,T M Region 3, Chicago, Office of the Director 80/07/23 App
- 8009020107 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " SA-312 pipe not present in operating plants Final confirmation from suppliers anticipated by 800915 re const plant piping sys NAUGHTON, N F Commonwealth Edison Co 80/08/07 2pp
- 8009170230 Forwards response to IE Bulletin 80-17. Suppl 1. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR" Scram discharge vol piping, scram instrument vol piping & drain piping meet requirements re downward pitch PEOPLES, D. L. Commonwealth Edison Co. 80/08/07 4pp
- 8009030231 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E "Written response required REPPLER.J G Region 3, Chicago, Office of the Director 80/08/15 lp
- 8009110545 Responds to IE Bulletin 80-08, "Eram of Containment Liner Penetration Welds," supplementing 800709 response Corrects Zion response re-rings used for field circumferential butt weld Reviews accuracy of other statements ABEL. J S Commonwealth Edison Co 80/08/15 4pp
- 8009110562 Responds to Suppl 1 to IE Bulletin 80-17. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR "
  Util will not have continuous SDV water level monitoring systematical for the functional by 800501

  JANECEK.R F Commonwealth Eduson Co. 80/08/15 2gp
- 800916048! Submits supplementary response to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds," correcting statement made in DL Peoples 800709 ltr Further review not necessary ABEL, J S Commonwealth Edison Co 80/08/15 4pp
- 6009260375 Forwards IE Insp Repts 50-010/80-13,50-237/80-14 & 50-249/80-18 on 800707-0801 & notice of violation HEIGHMAN,R F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/08/18 2pp
- --8009260399 Notice of violation from insp on 800707-0801, \* Region 3, Chicago, Office of the Director 80/08/18 tp
- --8009240404 IE Insp Repts 50-010/60-13,50-237/80-14 & 50-249/80-18 on 800707-0801 Noncompliance noted failure of licensed operators to keep themselves cognizant of design changes BARKER.J L. STREETER.J F. SPESSARD.R L Office of the Director 80/08/18 11p

- 8009090013 Submits addit response to IE Bulletin 80-17. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at DHR "
  Procedures have been developed to monitor scram discharge vol for residual water on daily basis
  JANECEK, R. F. Commonwealth Edison Co. 80/08/20 1p
- 8009150495 Forwards IE Info Notice 80~30. "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain QE BHR Facilities " No specific action or response requested KEPPLER, J O Region 3, Chicago, Office of the Director 80/08/20
- 8009120060 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR " Written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/08/22
- 8009180551 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluation for Changes to Radwaste Treatment Sys " No written response required KEPPLER. J Q Region 3. Chicago, Office of the Director 80/08/21 to
- 8009230094 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/08/28
- 8009170411 Forwards response to IE Bulletin 80-15 re possible loss of emergency notification sys w/loss of offsite power Review revealed inoperability of Dresden sys Investigation being conducted Operating Order 26-80 changed JANACSK. R F Commonwealth Edison Co 80/08/29 4pp
- 8009180466 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Identified relays are not used in facility No action required Twenty-four manhours expended on review RAUSCH. T J Commonwealth Edison Co. 80/08/29 1p
- B009230478 Forwards Revision 1 to IE Bulletin 79-26, "Boron Loss From BMR Control Blades " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director B0/08/27 to.
- 8009170421 Responds to IE Bulletin 80-17. Suppl 1 re failure of control rods to fully insort during scram at BMR Vent sys will provide reliable source of air during draining. Bys will be steadily purged until mods installed

  JANECEK, R F Commonwealth Edison Co. 80/09/02. 2pp
- 8009260109 Forwards response to IE Bulletin 80-17. Suppl 3, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR."

  Procedure at Dresden 2 & 3 changed to require immediate manual scram when air pressure reaches 60 psi RAUSCH.T J Communuealth Edison Co 80/09/02 4pp
- 8009290504 Responds to NRC 791213 request for add1 info in response to IE Bulletin 79-02. "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Expansion anchor test results show installation of anchors acceptable JANECEK,R F Commonwealth Edison Co. 80/09/05 17pp
- 6009240133 Forwards IE Circular 80-21, "Regulation of Refueling Crew1 " No written response required KEPPLER: J Q Region 3. Chicago. Office of the Director 80/09/10
- 8009300200 Forwards response to IE Bullatin BD-20 No Westinghouse Type W-2 control switches are used in safety-related sys at Dresden, Guad Cities & LaSolle County Responses for Zion & Byron are encl RAUSCH,T J. Commonwealth Edison Co. 80/09/15 & ADD
- R Periodic operating reports & related correspondence
- 8007030456 Forwards semiannual rept of radioactive effluent discharges 1 solid radwaste, for Jan-June 1980 SCOTT.D J Commonwealth Edison Co 80/08/20 ip
- --8009030467 Semiannual rept of radioactive effluent discharges & solid radwasterfor Jan-June 1980 \* Commonwealth Edison Co 80/08/20 15pp
- 80092307f3 Forwards monthly operating repts for Aug 1980 SCOTT, D J Commonwealth Edison Co 80/09/12 ip

- --8009230720 Monthly operating repts for Aug 1980 CIESZKIEWICZ: 8 Commonwealth Edison Co 80/09/03 15pp
- S Reportable occurrences, LERs & related correspondence
- 8009030509 Forwards LER 80-028/03L-0 SCOTT, D.J. Commonwealth Edison Co. 80/08/14 ip
- --8009030514 LER 80-028/03L-0 on 800727, during test of control rod driveline C-ii, overtravel alarm came up & rod position indication was lost Caused by detachment of inner filter Driveline C-ii will be replaced at next refueling autage HOLLAND.P Commonwealth Edison Co 80/08/15 ip
- 8009020381 Forwards LER 80-029/03L-0 800TT.D J Commonwealth Edison Co 80/08/18 1p
- --8009020388 LER 80-029/03L-0 on 800728, during normal operation, water found leaking from weld on instrument line off Rx water cleanup sys Caused by thermal cracking due to insufficient clearance on weld socket Weld partially ground out CIESZKIEWICZ, 8 Commonwealth Edison CO 80/08/18 ip
- 8009230476 Forwards LER 80-030/03L-0 SCOTT, D. J. Commonwealth Edison Co. 80/09/15 in
- --B0072306B7 LER B0-030/03L-0 on B00B18,2A LPCI pump mechanical seal leaked during torus cooling operations Caused by dirt between sealing surfaces Pump seal replaced & tested ZIRWAB,K Commonwealth Edison Co B0/09/15 2pp
- 8009300468 Forwards LER 80-031/03L-0 800TT:D J Commonwealth Edison Co 80/09/19 1p
- --8009300473 LER 80-031/03L-0'on 800827, diesel driven fire pump overheated & unavailable for longer than 7-day limit Overheating caused by faulty cooling water heat exchanger Heat exchanger replaced No further evidence of overheating KORCHYNSKY.M Commonwealth Edison Co 80/09/19 ip
- 8009300472 Forwards LER 80-032/03L-0 SCOTT,D J Commonwealth Edison Co 80/09/25 1p
- --B009300478 LER B0-032/03L-0 on 800827, during GA audit, discovered that diesel fuel tank samples were not being taken on monthly basis Caused by lack of definition on surveillance sheet Sheets revised to include sampling frequency KORCHYNSKY,M Commonwealth Edison Co B0/09/19 ip
- T Hearing transcripts on non-antitrust matters
- 8009100084 Transcript of 800819 prehearing conference in Chicago.IL Pp 1-72 \* Atomic Safety and Licensing Doard Panel 80/08/19 75pp
- V Operator Examinations
- 8009300287 Forwards preliminary topical outlines of proposed modules on thermal hydraulics & core damage mitigation to be included in revised reactor operator training program per 800328 request
  NAUGHTON.W F Commonwealth Edison Co 80/09/15 7pp
- DOCKET 50-243 DREGON STATE UNIV REBEARCH REACTOR
- F Security, medical, emergency & fire protection plans
- 8009300184 Submits info supporting amend to physical security plan Info withheld (ref 100FR2 790) WAND, C H. SMITH, C V Ohio State Univ 80/09/19 4pp
- R Periodic operating reports & related correspondence
- 8009300192 Forwards "GR State Univ TRIGA Reactor Annual Rept" for Jul 1979-June 1980 WANG,C H Ohio State Univ 80/09/08 ip
- --BOD9300197 "OR State Univ TRIGA Reactor Annual Rept" for Jul 1979-June 1980 ANDERSON, T V , JOHNSON, A G , BENNETT, S L Ohio State Univ 80/08/31 121pp

- DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1
  F Security, medical, emergency & fire protection plans
- 8009190655 Forwards suppl to 800214 ltr re vital area analysis results w/list of vital areas & equipment Requests review of security plan to assure adequate protection of vital areas & equipment Encl withheld (ref 10CFR2 790)

  CRUTCHFIELD.D Operating Reactors Branch 5 80/08/22 tp
- BOO9230196 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency GRIER-B H Region i, Philadelphia, Diffice of the Director BO
- 8009160317 Forwards info re security plan Plan withheld (ref 10CFR2 790) WHITE.L D Rochester Gas & Electric Corp 80/09/10 2pp
- G Adjudicatory correspondence
- 8009300247 Forwards order for mod of license, requiring info to support environ qualification of safety-related electrical equipment Briefings were held w/all interested licensees during who of 800717 GRUTCHFIELD.D Operating Reactors Branch 5 80/08/29 2pp
- --B00930025i Order for mod of License DPR-18, requiring anfo to support environ qualification of safety-related electrical equipment EISENBUT.D & Division of Licensing 80/08/29 App
- P Operating license stage documents & correspondence
- 8009170295 Forwards "Piping Stress Analysis Rept.RHR Sys, Section 250 "
  Analysis results & support loads reflect layout arrangement
  shown on encl Isometric C-381-354, Sheet 1, Revision D Anq
  mods to layout of sys will warrant remalysis of piping sys
  NODN.F Westinghouse Electric Corp 80/07/18 ip
- --BO09170296 "Piping Stress Analysis Rept.RHR Sys.Section 250 "
  NO.C . MASSIE:W A . LOCEFF.F Westinghouse Electric Corp
  SDTAR-80-05-05 80/07/31 80pp
- 8009170298 Forwards "RE Ginna Nuclear Power Plant, Beismic Upgrading Program Piping Stress Analysis, Main Steam Sys, Section 200 " Minor design changes or const mods will generally not affect stress results & support recommendations NODN,F Westinghouse Electric Corp 80/07/18 App
- --B009170301 "RE Ginna Nuclear Power Plant Seismic Upgrading Program Piping Stress Analysis Main Steam 89s Bection 200 " Main steam containment drawing encl MASSIE.W A. DREYER, E.P. LOCEFF, F. Westinghouse Electric Corp SDTAR-80-05-08 80/07/31 142pp
- 8009170312 Forwards "Piping Stress Analysis Rept,RHR Sys. Section 200 " Analysis results & support loads reflect layout arrangement shown in encl isometric C-381-334, Sheet I. Revision D Any mods to layout will warrant re
- ---8009170314 "Piping Stress Analysis Rept.RHR Sys, Section 200 " MASSIE, W A , NO.C , LOCEFF.F Westinghouse Electric Corp 8DTAR-80-05-03 80/07/31 138pp
- BO09020297 Submits interim criteria for shift staffing to all GL & CP licansees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days ETBENHUT, D O Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl N/o NUREG EISENHUT.D G Division of Licensing 80/08/01, 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lassons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D Q Division of Licensing 80/08/07 60pp.

- 8009190794 Forwards revised Westinghouse STB 3 9 8 2,3 9 10 & Bases 3/4 9 8 % 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel france during movement of fuel assemblies or control rods Written response required ROVAK.T M. Assistant Director for Operating Reactors 80/08/15
- --8009190817 Revised Westinghouse STS 3 9 8 2,3 9 10 & Bases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods

   Assistant Director for Operating Reactors 80/06/23 21pp
- 8007230757 Forwards cubrent SEP Topics 3-10 A.6-7 C 1.6-7 F & 3-3 B Assessments compare facility w/current NRC licensing criteria Requests proposed Tech Spec change to prevent transfer of all four instrument buses to same source CRUICMFIELD.D Operating Reactors Branch 5 80/08/20 22pp
- 8009020026 Notifies that revised definition of "operable" should not be incorporated into Tech Specs w/o adding corresponding action statements Revision may be deferred for incorporation w/further Tech Spec changes
  WHITE
- 800911074& Notification of 80091& meeting w/8EP owners group to discuss NRC initial review & recommendations for site-specific ground response spectra & owners group program plans for setemic functional qualification of Class IE squipment LEVIN.H & Division of Engineering 80/08/26 1p
- 8009030474 Submits info confirming that util meets requirements for TMI Lessons Learned requirements litem 2 i 8 b rs increased range of radiation monitors Literature describing monitors encl for review
  WHITE, L D Rochester Gas & Electric Corp. 80/08/27 5 pp.
- B009030545 Discusses task action plan re asymmetric LQCA loads Specified repts support conclusion that under worst combination of loadings including SBE effects realistically possulates flaw will not cause guillotine breat WHIYER D Rochester Gas & Electric Corp 80/08/27 2pp
- 909030485 Submits info describing current status & schedules re anchorage & support of safety-related electrical equipment HMITE.L.D. Rochester Gas & Electric Corp. 60/08/28 2pp
- 19040413 Forwards application for amend to License BPR-18 consisting of changes to Tech Specs for control rod misalignment certificate of svc encl PARON:RS LeBourf, Lamb. Leiby & MacRae 80/09/03 4pp
- -8009040414 Application for amend to License DPR-18 consisting of Tech Specs changes re-control rod misalignment WHITE.L D Rochester Gas & Electric Corp 80/08/29 2pp
- --8609040415 Revised Tech Specs 3 5,3.10 & 4 1 for control rod position indication sys \*\* Rochester Gas & Electric Corp #60/08/29. 17pp
- B009090513 Responds to NRC B00B11 request for info re generic review of degraded grid voltage All low-voltage, 125-volt ac Class IE buses are supplied from either uninterruptable power source or regulated 480/125-volt transformers.
  WHITE-L D Rochester Gas & Electric Corp 80/09/03 ip.
- T009090377 Forwards inservice pump & valve testing program for Jan 1981 - Dec 1990.App C to GA manual WHITE.L D Rochester Cas & Electric Corp 80/09/04. ip.
  - 090903B2 Inservice pump & valve testing program for Jan 1981 Dec 990.App C to OA manual WDERSON.C R Rochester Qas & Electric Corp 80/09/02 28pp
- J90551 Advises that response to NRC 800702 ltr.requesting submittal license amend application incorporating model Fech Specs e TMI Lessons Learned Category A items will not be completed until late Oct 1980 WHITE, L D Rochester Gas & Electric Corp 80/09/05 ip
- 8005290143 Notification of 800926 meeting w/utils & Kerr-McGee Chemical Corp in Bethesde.MD to discuss review & recommendations for site specific ground response spectra & program plans for seismic functional qualification of Class IE equipment ALLISON, D.P. Systematic Evaluation Program Branch 80/09/08 Spp

- BOO9160539 Forwards stress repts for A RHR&B mainstream piping inside containment Analyses are part of seismic upgrade program & incorporate several proposed piping sys mode Analyses do not represent current as-built plant configuration W/encl WHITE.L D Rochester Gas & Electric Corp 80/09/09 ip
- 8009170303 Application for amend to License DPR-18, adding requirements for undervoltage protection WHITE:L D Rochester Gas & Electric Corp 80/09/09 3pp
- --B009170304 Proposed Tech Spec Pages 3 5-4a & 4 1-7 replacing enc) Pages 2 3-4 through 2 3-10 re undervoltage protection Submitted as Amend 14 to License DPR-18 Util safety evaluation encl \* Rochester Gas & Electric Corp
- 8009260022 Notification of second rescheduling until 801003 for meeting w/SEP owners group & KMC. Inc to discuss NRC initial review of site-specific ground response spectra & util program for selsmic functional qualification of Class IE equipment ALLISON. D P Systematic Evaluation Program Branch 80/09/10 Gpp
- 8009300365 Forwards comments on NUREO-0696, "Functional Criteria for Emergency Response Facilities " Detailed criteria require revision to provide more effective & cost-effective sys WHITE,L D Rochester Gas & Electric Corp 80/09/19 13pp
- O Inspection reports. IE Bulletins & correspondence
- 8007160220 Forwards IE Insp Rept 50-244/80-07 consisting of 800815 meeting in Ontario.NY GRIER: BH Region I, Philadelphia, Office of the Director 80/07/26 2pp
- --B009160223 IE Insp Rept 50-244/80-07, consisting of 800515 meeting in Ontario, NY Areas addressed regulatory performance JOHNSON, D.F., KISTER, H.B. Region 1, Philadelphia, Office of the Director 80/07/22 App
- 8009220326 Responds to IE Bulletin 80-16 re potential misapplication of pressure transmitters Rosemount 1151 & 1152 pressure transmitters not used or planned for use in safety-related areas SADDOCK, H G Rochester Gas & Electric Corp 80/07/29 ip
- 8009:10485 Suppls response to IE Bulletin 79-03A Lists fittings on safety-related stainless steel sys Calculated wall thickness based on 100% code allowable stress WHITE.L D Rochester Gas & Electric Corp 80/08/05 2pp
- B009030090 Forwards Revision I to IE Bulletin 80-19, "Failures of Kercury-Wetted Matrix Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/08/15 ip
- 8009240186 Ack receipt of 800807 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/80-06 SMITH O H Region i. Philadelphia, Fuel Facility & Materials Safety Branch 80/08/17 lp
- --8009240192 Responds to NRC 800717 ltr re violations noted in IE Insp Rapt 50-244/80-06. Corrective actions procedure established to obtain permission to deviate from radiation work permit WHITE, L. D. Rochester Oas & Electric Corp. 80/08/07 3pp
- --8007240196 Forwards IE Insp Rept 50-244/80-06 on 800429-0502 & notice of violation SMITH, G M Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/07/17 2pp
- --8009240200 Notice of violation from insp on 800429-0502 \* Region 1. Philadelphia, Office of the Director 80/07/14 ip
- --8007240205 IE Insp Rept 50-244/80-06 on 800429-0502 Noncompliance noted failure to follow radiation protection procedures in accordance w/Tech Spec 6 11 & intentionally handling contaminated math w/o protective gloves.

  WNAPP,P J Region 1, Philadelphia, Fuel Facility & Materials Safety Branch SERABIN,J A Region 1, Philadelphia, Office of the Director 80/07/14 13pp
- 8009180050 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required. GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/08/22. 1p

- 8009120243 Forwards IE Info Notice 80-3i. "Maloperation of Gould-Brown Boveri 480 Volt Type K-6005 & K-DON 6005 Circuit Dreakers " No written response required ORIER.B H Region I. Philadelphia. Office of the Director BO/08/27 ip
- 8009240048 Forwards IE Circular 80-21, "Regulation of Refueling Crews " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/09/10 ip
- 8009170311 Submits info re steam generator insp program in response to NRC 800708 request Multifrequency eddy current exam will be performed on 100% of inlet tubes including first support plate intersection in A & 8 steam generators by 801101 WHITE,L D Rochester Gas & Electric Corp 80/09/12 1p
- 8009240361 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls "No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/09/12 ip
- R Periodic operating reports & related correspondence
- 8009180265 Forwards semiannual radioactive effluent rept for Jan-June 1980 WHITEL D Rochester Gas & Electric Corp 80/08/29 in
- --8009180272 Semiannual radioactive effluent release rept for Jan-June 1980 \* Rochester Gas & Electric Corp 80/08/29 5pp
- S Reportable occurrences, LERs & related correspondence
- 8009020346 Forwards updated LER 79-015/01X-1 WHITE.t. D Rochester Gas & Electric Corp 80/08/25 1p
- --8009020351 Updated LER 79-015/01X-1 on 790724 during piping sys insp per IE Bulletin 79-14 found pipe supports not installed per Tech Specs Caused by lack of documented approvals for field changes Fipe supports reworked to establish acceptability HUTTON.J C Rochester Gas & Electric Corp 80/08/25 lipp
- V Operator Examinations

11

- 8009050274 Forwards "Operator Requalification Program," Procedure A-102 14,Revision 3.in response to NRC 800328 1tr MHITE.L D Rochester Gas & Electric Corp 80/08/22 ip
- --800905027B "Operator Requalification Progrem," Procedure A-102 14, Revision 3 \* Rochester Cas & Electric Corp 80/05/21 14pp
- 8009020086 Forwards documentation of implementation of NRC 800828 suggestions re operator licensing requirements Shift manning requirements, resulting from TMI action plan, will be responded to in separate itr
  WHITE, L.D. Rockester Gas & Clectric Corp. 80/08/25 4pp
- DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

  F Security, medical, emergency & fire protection plans
- 8008280056 Notification of 800819.20 & 22 workshops in Valley Forge,PA, Chicago, IL & Atlanta.GA: respectively, to solicit public comment re NUREQ-0696, "Functional Criteria for Emergency Response Facilities"

  ORIER. B H Region 1, Philadelphia, Office of the Director 80/08/11 2pp
- 8009230180 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Signistalled for govt use during emergency ORIER, BH Region I. Philadelphia. Office of the Director 80/08/22 Gpp.
- P Operating license stage documents & correspondence
- 8009110554 Buppls NRC 800707 request for proposed Tech Specs changes be stram discharge vol yent & drain valves, & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT,D O Division of Licensing 80/07/22 22pp

- 8009020157 Submits draft interim reliability evaluation program, P
  If re procedure & schedule, event tree parts & guide for
  selecting component failure rates per 800612 meeting
  concerns
  EISENBUT. D G Division of Licensing 80007/25 Upp
- 8009020297 Submits interim criteria for shift staffing to all Bi licensees & applicants, per NRC BOOSO7 lin Discusses administrative provisions for emergency & evertine work Development & implementation to be reviewed within 90 days EISENHUT, D.Q. Division of Licensing 80/07/d1 /pp
- 8009080080 Forwards draft NUREO 0696, "Functional Criteria for Emergency Response Facilities." Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/o NUREO EISENMUT. D 0 Division of Licensing 80/08/61 11/pp
- 8009120709 Forwards agends of 800821 meeting at util ofce to diese assessment of regulatory performance ORIGE.B H. Region 1. Philadelphia. Office of the Director 80/08/04 2pp
- 8009230052 Informs that exemption from fee relicenting actions associated w/TML~2 Lessons Learned is unjustified Previous determination should be disregarded flaquested submittal should include proposed class of Amend EISENHUT, D. G. Division of Licensing 400/01/07 //Opp
- 8009020311 Submits schedule for 5 months of interim reliability availablen programs annotated to highlight potential NRC participation Anticipated start date scheduled for 800915 EISREMUT, D. O. Division of Licensing 80708715 App
- B007100454 Advises that mgt meeting w/NRC in Derlin,CT has been rescheduled for 800911 Agenda encl ORIER,B N Region 1, Philadelphia. Office of the Birectur 80/08/20 2pp
- 8009240596 Forwards "Mark 1 Containment Long-Term Program (H.R. Resolution of Generic Technical Activity A-7 " NURLO-OAA1 W/o enc.)
  CRUTCHFIELD, D. Operating Reactors Tranch 4 HO/00/20 Upp
- 8009020286 Submits info superseding 7912AH & 8008HA Info re IHI a Short-Term Lessons Learned implementation of Item 2 2 Ab, shielding design review mode COUNSIL-W O, FEC. H F Northeast Nuclear Energy Co. Isubs or Northeast Utilities? 80/08/28 App
- 8009110746 Notification of 800916 meeting w/SLP numers group to dance initial review & recommendations for site specific ground response spectra & owners group program plans for selsmic functional qualification of Cless II. equipment LEVIN, H.A. Division of Engineering 100/08/26 b
- BOD9030378 Advises that util will not meet deadline for implements of NUREG-0578 requirements to emergency procedures to retraining for accidents to transferts NRC feedback needed COMSILW Connecticut Yankee Atumic Fouer Co. CCRRSH. U. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) BO/09/28.
- BOO9110245 Informs of discrepancies between facility to iterative to used in BEP Topic III-4: "Electrical Penetrations of Hearton Containment " Util concludes that subj penetrations meet current requirements no design change hienned COUNSIL-N O , FEE, M F Northeast Nuclear Liberty Co taubs of Northeast Utilities) BOO9227 Spp
- 8009170434 Forwards add1 info re BEP Topic III-6 re setemic design review per NRC request Oversize encls include general arrangement drawings for burbins bidg. Battery charger drawings & specs, switchgeer panel & control red driveline CGUNSIL-W O, FEE,W F Northeast Bucker Energy Co taubs of Northeast Utilities)
- 8009190670 Requests Class III fee for plant thecific review of NR) O610 ltrs requesting relief from inservice insp & tasting program requirements Request (nvolves consideration of single safety issue D1008,R M License Fee Management Branch 80/09/02 &
- 8009090636 Proposed amend to License DPR-21 incorporating enri fee Spec changes to enable full core off-load to be performed during sweath refueling outage. Heload 7 licensing submittal uit be provided under separate cover Afficavit enci COUNSIL, if G. FEE, M.F. Northeast Nuclear Energy Co. (auba of Northeast Utilities)

- --8009090642 Tech Spec changes for full core off-load re limiting condition for operation & surveillance requirements \* Northeast Utilities 80/09/30 App
- 8009290143 Notification of 800926 Meeting w/utils & Merr-McGee Chemical Corp in Bethesda MD to discuss review & recommendations for site specific ground response spectra & program plans for seismic functional qualification of Class IE equipment ALLISON, D.P. Systematic Evaluation Program Branch 80/09/08 3pp
- 8009300297 Proposed amend to License DPR-21 for Reload 7 Supplemental changes will be provided by 800930 Related proprietary rept NEDE-20992-5p will be forwarded under separate cover Supporting documentation & proposed Tech Spec changes encl COUNSIL-N 0 Northeast Utilities 80/09/09 5pp
- ---80093G0302 "Supplemental Reload Licensing Submittal for Millstone Unit 1 Reload 7 " \* General Electric Co Y1003J01A09 80/06/30 19pp
- --BD09300307 "LOCA Analysis Rept for Millstone Unit 1 Nuclear Power
  - General Electric Co NEDO-24085-1 Rt 80/07/31 32pp
- --80093003il Proposed Tech Spec changes for Killstone 1.Reload 7 re max average planar linear heat generation rate limits \* Northeast Utilities 80/09/09 100pp
- 800924057: Forwards NEDE-20592-5P. "STR Bundle Submittal.Hillstone i Segmented Test Rod Bundle." Suppl 5 Rept is app to Reload 7 license amend submitted on 800909 Rept available in Central Files only COUNSIL, W 6 CDUNSIL, W G Northeast Nuclear Energy Co. (subs of Northeast Utilities) 80/09/10 3pp
- 80092600g2 Notification of second rescheduling until 801003 for meeting w/SEP numers group & KHC. Inc to discuss NRC initial review of site-specific ground response spectra & util program for sessmic functional qualification of Class IE equipment ALLISON.D P Systematic Evaluation Program Branch 80/09/10 3pp
- 009190427 Discusses reasons for inability to fully support NRC plans b schedules for interim reliability evaluation program input into contractor selection process should be permitted COUNSIL.H Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/09/12 2pp
- O09180357 Forwards implementation status of Category B TMI-2 Lessons Learned requirements for each facility Schedules specifically identify items where requirement cannot be met or schedule is not feasible COUNSIL-H O Connecticut Yankee Atomic Power Co COUNSIL-H O Northeast Nuclear Energy Co (subs of Northeast Utilities) B0/09/15 43pp
- O09290351 Application for amend to Licenses DPR-61, DPR-21 & DPR-65, incorporating revisions to Tech Specs for RCS per TMI-related requirements Fee encl TOWNSIL.W O Connecticut Yankes Atomic Power Co COUNSIL.W G fortheast Utilities 80/09/16 6pp
- 1009290367 Proposed revisions to Tech Specs & O for administrative
- Connecticut Yankes Atomic Power Co 78/12/08 4pp
- )09300239 Forwards "Millstone Nuclear Power Station,Unit 1 Inservice Insp & Testing Program for 10-yr Interval 801228-901228 " Program is based on existing inservice insp & testing
- rogram 1. oct. rogram GUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast tilities) COUNSIL.W O Northeast Utilities 80/09/18 2pp
- \_009300245 "Millstone Nuclear Power Station Unit 1 Inservice Insp & Testing Program for 10-yr Interval.801228-701228 " Program is based on existing inservice insp & testing program.

  4 Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/09/3Q 70pp
- 1 Inspection reports. IE Bulletins & correspondence
- 8009090:1: Forwards IE Bulletin 80-07,8upp1 1, "BWR Jet Pump Assembly Failure "Response required.

  ORIER,8 H. Region 1, Philadelphia, Office of the Director 80/05/13 1p
- 8009150082 Forwards IE Insp Repts 50-249/80-10 % 50-336/80-07 on BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/07/14 2pp

- --8009190088 IE Insp Repts 50-245/80-10 & 90-336/80-07 on 800601-0705
  No noncompliance noted Major areas inspected control room,
  accessable portions of Unit 1 reactor & intake bldgs.Unit 2
  encl & condensate polishing facility
  KEIMIO.R R Region 1. Philadelphia, Reactor Operations Nuclear
  Support Branch SHEDLOSKY.J T 7 IMMERMAN.R P Region 1.
  Philadelphia. Office of the Director 80/07/11 7pp
- 8009120197 Responds to IE Bulletin 80-14 re degradation of scram discharge vol capabilities No degradation instances found No vent or drain valves failure identified Procedures re valve operability changed Surveillance for level switches revised COUNSIL-N 0 . FEE. W F Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/27 3pp
- 8009230749 Responds to 1E Dulletin 80-i6 re Rosemount pressure transmitters identified transmitters will be installed in facility analysis shall identify erroneous indications No corrective actions required COUNSIL.N 6. FEE.W F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/07/31. 3pp
- 8009090017 Responds to IE Bulletin 80-17. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BMR " Daily monitoring of scram discharge vol will continue until permanent continuous monitoring sys is operational COUNSIL.W 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/08/07 4pp
- 8009150465 Discusses 800805 meeting w/util re physical protection program insp findings & forwards outline of corrective actions Encl withheld (ref 10CFR2,790) ORIER, B H Region 1, Philadelphia, Office of the Director, 80/08/07 1p
- 800903008i Forwards Revision i to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required QRIER.D H Region I, Philadelphia, Office of the Director 80/08/15 | 1p
- 8009120090 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR" Written response required R H B,RBIRD qi Cer-Region 1. Philadelphia. Office of the Director
- 8009180017 Forwards IE Circular 80~18, "10CFR50 59 Bafety Evaluations for Changes to Radwaste Treatment Bys " No written response required GRIER, B. H. Region 1, Philadelphia, Office of the Director BO/08/22 1p
- 8009120190 Forwards IE Info Notice 80-31, "Maloperation of Qould-Brown Boveri 480 Volt Type K-6008 % K-DON 6008 Circuit Breakers " No written response required CRIER,B H Region i, Philadelphia, Office of the Director 80/08/27 ip
- H009230519 Forwards Revision 1 to IE Bulletin 79-26, "Boron Loss From BWR Control Blades " Written response required ORIER,B K Region i, Philadelphia, Office of the Director 80/08/27 ip
- 8009230791 Forwards IE Circular 80-21, "Regulation of Refueling Crews " No written response required 60-21, "Regulation of Refuel No written response required 60REERBH Region 1, Philadelphia, Office of the Director 60/09/10 ip
- 8007240317 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls" No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 60/09/12 ip
- 8009300239 Forwards "Millstone Nuclear Power Station, Unit 1 Inservice Insp & Testing Program for 10-yr Interval 801228-901228 " Program is based on existing inservice insp & testing program CDUNBIL,W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) CDUNBIL.W 0 Northeast Utilities 80/09/18 2pp
- --8009300245 "Milistone Nuclear Power Station, Unit i Inservice Insp & Testing Program for 10-yr Interval, 801228-901228 " Program is based on existing inservice insp & testing program \* Northeast Nuclear Energy Co. (subs of Northeast Utilities) 80/09/30 70pp

## R Periodic operating reports & related correspondence

- 8009020283 "Semiannual Radioactive Effluents Release Rept.Jan-June. 1980 "
  Northeast Nuclear Energy Co (subs of Northeast Utilities)
  80/08/29 100pp
- 8009190456 Forwards monthly operating rept for Aug 1980 MRDCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/09/08 Ip
- --8009190439 Monthly operating rept for Aug 1980 HARRAN,O Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/09/03 7pp
- S Reportable occurrences, LERs & related correspondence
- B009020377 Forwards LER 80-012/03L-0 MRQCZKA;E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/08/22 ip
- --8009020383 LER 80-012/03L-0 on 800725,while performing routine surveillance, average power range monitor (APRM) channel 5 was reading 10% below Tech Spec Cause unstated APRM adjusted to proper value & observed to insure stable reading BIGIARELLI.M J Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/08/22 3pp

#### DOCKET 50-247 INDIAN POINT STATION, UNIT 2

- F Security, medical, emergency & fire protection plans
- 8009090884 Requests participation in NRC study of people-related problems in nuclear safeguards Request includes NRC visit to facility to interview security mpt personnel Confidentiality of info will be maintained during all phases of study VARQA/S A Operating Reactors Branch 1 80/08/14 2pp
- 8009230167 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency GRIER. B H Region i, Philadelphia, Office of the Director 80/08/22 3pp

#### G Adjudicatory correspondence

- 8009090337 Add1 response to FOIA request for TMI~2, "Startup Problem Rept" & intervenor Citizens Committee for Protection of Environ Proposed Findings of Fact & Conclusions of Law re Indian Point 2 Forwards intervenor filing FELTON, J M Division of Rules and Records 80/08/12 1p
- --8009090342 Forwards nonproprietary version of intervenor.Citizens Committee for Protection of Environ proposed findings of fact & conclusions of law re facility Finding 15 & portions of Finding 5 deleted to protect public health & safety ROISMAN.A Z Berlin, Roisman & Kessler 72/02/08 ip
- --B009090363 Nonproprietary version of proposed findings of fact & conclusions of law re plant security Includes memorandum in support of questions certified to ASLB & suppl to reply brief.
  ROISMAN.A Z Citizens Committee for Protection of the Environment ROISMAN.A Z Barlin, Roisman & Ressler 72/02/08 155pp
- B009220009 Forwards order raquiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 901101 VARGA.8 A Operating Reactors Branch 1 B0/08/29 3pp
- --8009220011 Order for mod of License DPR-26 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101
  EISENHUT, D 0 Division of Licensing 80/08/29, 6pp
- 8009120394 Order granting extension until 800926 for Commission to review ALAB-436 & relevant portions of ALAB-961 CHILK.S J Office of the Secretary of the Commission 80/09/10 1p
- 8007300320 Order granting extension until 801024 for Commission to review ALAB-436 & ALAB-561 CHILK:8 J Office of the Secretary of the Commission 80/07/26 3pp

#### H General correspondence

- 800918044B Responds to 800319 itr requesting public debate re issues appropriate to evacuation of large population ctrs near plants
  DENION. H. R. Office of Nuclear Reactor Regulation. Director 80/04/21 3pp
- ---8009180462 Requests public debate re issues appropriate to evacuation of large population ctrs near plants Expresses confidence in attempts by Commissioners to represent public concerns EMORY, K Affiliation Unknown 80/03/19 ip

## P Operating license stage documents & correspondence

- 8009300169 "Rept of Zion/Indian Point Study Vol 2." informal rept STEVENBON: M G Los Alamos Scientific Laboratory FIN A-7015 NUREG/CR-1411 V2 80/04/30 165pp Available at NTIS
- B009020297 Submits interim criteria for shift starfing to all CL & CP licensees & applicants.per NRC B00507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D © Division of Licensing 80/07/31 7pp
- 8009030174 Confirms 800723 telcon re meteorological sys for facility Another telephone line would be acceptable as interim functional back-up communications link.but unacceptable as permanent solution Radio or satellite would be acceptable VARCA.S A Operating Reactors Branch 1 80/07/31 2pp
- 8007080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl W/o NUREG EISENHUT.D 6 Division of Licensing 80/08/01 119pp
- 8009230092 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENRUT.D G Division of Licensing 80/08/07 AOpp
- 8009190794 Forwards revised Westinghouse STS 3 9 8 2.3 9 10 & Bases 3/4 9 8 8 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control reds Written response required NDVAK.T M Assistant Director for Operating Reactors 80/08/15 ip
- --8009190817 Revised Mostinghouse STS 3 9 8 2,3 9 10 & Mases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods
  4 Assistant Director for Operating Reactors 80/06/23 21pp
- 8009100060 Forwards request for addl info re LOPAR fuel VAROA, B A Operating Reactors Branch 1 80/08/19 3pp
- 8009030616 Forwards "Profilometry of Steam Generator Tubes," describing R&D work leading to development of profilometry & summarizing results of special examinations of Steam Generator 24 during 1979 refueling outage ZARAKAS.P Consolidated Edison Co of New York 80/08/20 1p
- --8009030618 "Profilometry of Steam Generator Tubes "
  \* Consolidated Edison Co. of New York 80/08/31 200pp
- 8009190819 Requests long-term solution to correct electrical override/ bypass problem NRC review determined that manual sys-level actuation features for containment isolation % spray will not function after automatic safety signals reset VAROA.8 A Operating Reactors Branch 1 80/08/20 3pp
- 8009030559 Discusses NRC 800227.0410,0611,0702,07 & 28 requests re changes to util Tech Specs Util will submit one package addressing all concerns by 801107 ZARAKAS.P Consolidated Edixon Co of New York 80/08/26 ip
- 8007080327 Submits response to 60-day Interim Action Items C 5(2) & (3) re gas turbines Improved maint & testing will be implemented Includes schedule for completion of overall improvement program
  ZARAKAS.P Consolidated Edison Co of New York 80/08/27 2pp

- 8009030458 Responds to NRC 600721 request for info re fracture—toughness design of steam generator & reactor coolant pump supports at facility Westinghouse advises that required response uith not be available until 810301 ZARAKAS.P Censolidated Edison Co of New York 60/08/28 1p
- 8009100631 Forwards Amend 62 to License DFR-26, safety evaluation & notice of issuance & availability
  VARQA S A Operating Reactors Branch 1 80/08/28 2pp
- --8009100638 Amend 62 to License DPR-26, reducing number of snubbers required by Tech Specs, reflecting redesign of support sys of certain safety-related pipe lines VARGA. S A Operating Reactors Branch 1 80/08/28 19pp
- ~~8007100641 Safety evaluation supporting Amend 62 to License DPR-26 a Office of Nuclear Reactor Regulation, Director 80/08/28 3p;
- --8009100645 Notice of issuance & availability of Amend 62 to License DPR-26 NEIGHBORS,J D Operating Reactors Branch | 80/08/28 29p
- 8009190134 Forwards Amend 63 to License DPR-26, safety evaluation & notice or issuance & availability EISER-UVI.D © Division of Licensing 80/08/28 3pp
- --B009190140 Amend 63 to License DPR-26, revising Tech Specs re primary containment leakage testing ELISCHUTID 2 Division of Licensing 80/08/28 32pp
- ~~8009190143 Safety evaluation supporting Amend 63 to License DPR-26 → Davision of Licensing 80/08/29 4pp
- --8009190151 Notice of issuance & availability of Amend 63 to License DPR-26 VARGA,S A Operating Reactors Branch 1 80/08/28 2pp
- 80070903B3 Forwards "Rept on Evaluation of Thermal Plume Studies of Indian Point Nuclear Generating Station " Objectives of thermal plume program have been fulfilled Rept available in Central Files only ZARAKAS, P Consolidated Edison Co of New York 80/08/29 ip
- 107070484 Provides status of valve qualification program for ontainment purge & pressure relief isolation valves equested by NRC 800702 ltr % of evaluation of SRP & 2 4, evision 1 issues Response will be provided by 810105 ARAKAS,P Consolidated Edison Co of New York 80/08/29 i
- P120042 Confirms util commitment to staff 791023 interim position on ontainment purging & venting \*ARGA-SA Licensing Branch 1 80/08/27 2pp
- OP120502 "Rept of Zion/Indian Point Study," Vol 1 NURFIN.W B Sandia Laboratories FIN A-1218 NUREG/CR-1410 VI 80/08/31 400pp
- 9009120626 "Task Force Rept on Interim Operation of Indian Point " BERNERO,R M , BLOND,R M , PRITCHARD,H C Office of Policy Evaluations NUREG-0715 80/08/31 78pp Available at NTIS \$3.75
- 3009090505 Forwards table outlining effects of combining SSE & LOCA responses in analysis of Unit 2 RCS for postulated LOCAs.in response to NRC 800731 ltr ZARAKAS.P Consolidated Edison Co of New York 80/09/03 3pp
- 09180144 Discusses two risk studies currently underway Preliminary assessment of Indian Point risk profile contained in SECY 80-283 Zion risk profile assessment will combine accident sequence evaluation & containment failure analysis ERNST, M.L. Assistant Director for Technology Review 80/09/11
- 230451 Forwards corrected response to Question 4 to 800720 ltr backfitting of severe accident mitigation features YIE.J P Power Authority of the State of New York nsolidated Edison Co. of New York 80709716 3pp
- 250266 Forwards current training course outlines re heat transferd of flow & thermodynamics, in response to NRC 800328 ltm ARAS.P Consolidated Edison Co. of New York 80/09/19 30pp
- 00084 Forwards response to 800820 itr re manual systemel uation features for containment isolation 5 containment and Discusses proposed mod to containment ventilation lation circuitry

  AKAS.P. Consolidated Edison Co. of New York 80/09/22 2pp

- 8009300481 Notifies of planned change to Tech Spec 4 2 . Item 7 2 re surveillance specimen removal schedule Change would provide better data to evaluate effects of radiation on reactor vessel Amend application will be filed shortly ZARAKAS,P Consolidated Edison Co of New York 80/09/24 1p
- Q Inspection reports. IE Bulletins & correspondence
- 8007120195 Forwards IE Insp Rept 50-247/80-01 on 800203-0329 No noncompliance noted BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/07/08 2pp
- --B009120210 IE Insp Rept 50-247/80-01 on 800203-0329 No noncompliance noted Major areas inspected physical security,minor seismic event turbine rotor disc insp & plant tour KISTER.H Region i. Philadelphia, Reactor Operations Nuclear Support Branch REBELOWSKI.T Region I. Philadelphia, Office of the Director 80/07/07 10pp
- B009100847 Forwards IE Insp Rept 50-247/80-04 & on 800330-0510 No noncompliance noted BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch B0/07/18 2pp
- --8009100853 IE Insp Rept 50-247/80-04 on 800330-0910 No nencompliance noted Major areas inspected safety injection pump functional test scheduled emergency drill & selected aspects of physical security plans & procedures REBELOWSKI.T Region i. Philadelphia, Office of the Director KISTER.H Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/07/15 16p
- 8007090242 Responds to IE Bulletin 80-16 Unit 2 has no specified transmitters installed Unit 1 shut down since 741031 & in defueled condition ZARAKASIP Consolidated Edison Co of New York 80/07/30 2pp
- 8007120187 Responds to IE Bulletin 77-03A re longitudinal weld defects in SA-312 or A-312 Type 300 stainless steel piping Unit 1 is in defueled condition Unit 2 piping satisfies criteria re allowable stress
  ZARAKAS.P Consolidated Edison Co of New York 80/08/06 2pp
- 8009030073 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Notted Matrix Rolays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER.8 H Region 1. Philadelphia. Office of the Director 80/08/15 1p
- 8007180337 Forwards IE Circular 80-18, "10CFR50 57 Safety Evaluations for Changes to Radwasta Treatment Sys " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/08/22 ip
- 8009120171 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bovert 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers" No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/08/27 1p
- 8009090423 Responds to IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys W/Loss of Offsite Power" Insp revealed loss of emergency notification sys on 800602 due to poor motor generator brush contact ZARAXAS,
- 8009230778 Forwards IE Circular 80-2i, "Regulation of Refueling Crews" No written response required GRIER.8 Region 1, Philadelphia, Office of the Director 80/09/10 ip
- 8009240304 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required GRIER.8 H Region 1, Philadelphia, Office of the Director 80/09/12 1p
- R Periodic operating reports & related correspondence
- 8009030382 Forwards "Effluent & Waste Disposal Semiannual Rept, Jan-June 1980 " ZARAKAS, P Consolidated Edison Co of New York 80/08/29 1p
- ---8007030386 "Effluent & Waste Disposal Semiannual Rept, Jan-June 1980." \* Consolidated Edison Co of New York 80/08/29 43pp

- 8009230432 Forwards daily record of fish collections for Aug 1980, including daily species breakdown & total weight Unit 2 & 3 circulators were run for entire month Unit 1 circulators were run on 800808, 10, 13, 17, 19, 21, 23, 30 & 31 ZARAKAS,P Consolidated Edison Co of New York 80/09/15 1p
- --8009230433 Daily record of fish collections from intake screens for Aug 1980 • Consolidated Edison Co of New York 80/09/13 5pp
- 8009230568 Forwards monthly operating rept for Aug 1980 IARAMAB:P Consolidated Edison Co of New York 80/09/15 1p
- --8009230571 Monthly operating rept for Aug 1980 EICH.E Consolidated Edison Co of New York 80/09/11 7pp
- 8009240452 Forwards quarterly rept on "Seismic Monitoring Network in Vicinity of Indian Point NY.Consolidated Edison Project, Mar-May 1980 " ZARAKAS:P Consolidated Edison Co of New York 80/09/15 1p
- EMMANASIP CONSCITUATES EGISON CO OF NEW FORK BOJO7715 IP
- --8009240455 "Seismic Monitoring Network in Vicinity of Indian Point, NY, Consolidated Edison Project Mar-May 1980 " \* Woodward-Clyde Consultants, Inc 80/08/15 44pp
- S Reportable occurrences. LERs & related correspondence
- 8005140025 PNS-I-80-003 on 800321.local telephone company received bomb threat re facility from unidentified male caller Search was conducted but no bomb was found Threat was repeated on 800321 but no bomb was found \* Region 1. Philadelphia, Office of the Director 80/03/24 lp
- 8009030610 RD on 800804, circulating water sys discharge temp syceeded Tech Specs limit Caused by high ambient river temps, high discharge temps & broken circulating water pump Bemand load & discharge temp reduced IARAKAS.P Consolidated Edison Co of New York 80/08/28 2pp
- 8007120353 Forwards LER 80-006/79X-1 ZARAKAS/P Consolidated Edison Co of New York 80/07/05 1p
- --8009120381 LER 80-006/99X-1 on 800603 during normal plant operation, all offsite electrical power was lost to site Caused by lightning strike on sys transmission tower Faulted conditions were cleared & normal svc restored MAKEPEACE, J M Consolidated Edison Co of New York 80/09/05 25on
- 8009160365 Forwards LER 80~009/03L~0 ZARAKAS,P Consolidated Edison Co of New York 80/09/10 ip
- --B009160369 LER 80-009/03L-0 on 800B10, following manual plant shutdown, spurious safety injection signal caused startup of three emergency dissel generators Caused by premature operation of series overcurrent tripping device Device replaced MAKEPEAGE, J M Consolidated Edison Co of New York 80/09/10 20p.
- 8009300524 Forwards LER 80-010/04X-0 ZARAKAS,P Consolidated Edison Co. of New York 80/09/22 1p
- --B009300530 LER 80-010/04X-0 on B00910, green vegetable sample from Unit vicinity demonstrated radioactivity in excess of area historic levels Cause not determined Assures that corrective action will be taken upon discovery of cause Cansolidated Edison Co of New York 80/09/19 3pp
- DOCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

  F Security, medical, emergency & fire protection plans
- 8009230288 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/22 3pp
- 8009100378 Forwards review of util generating station emergency plan & draft ltr requesting addl into & commitments from util PAGANO,F 0 Emergency Preparedness Licensing Branch 80/08/28 500

- 8009120453 Notifies that Comm Ed does not wish to participate in proposed study re review of people-related problems in nuclear safeguards Responses would be misleading reflecting insperience & short-term problems
  ABELJ 8 Commonwealth Edison Co 80/09/02 1p
- G Adjudicatory correspondence
- 8009040200 Advises that subsequent to discussions w/NRC % applicant. State of IL Second Amended Contentions 2,3,4,5(8),6,7, & B are admissible Second Amended Contention 10 should be held until 801001 while security plan is reviewed by IL SEKULER 8 N 1111nois, State of 80/08/27 2pp
- --8009040208 Notice of faling & svc of second amended contentions SEKULER,S N , FAHNER,T C Illinois, State of 80/08/27 2pg
- --8009040218 Second amended contentions alleging absence of demonstrated need for spent fuel pool storage expansion Claims (nadequacy of monitoring equipment b inadequacy of assessment re rack corrosion Proof of svc encl
  SEKULER.S N. FAHNER.T C Illinois, State of 80/08/27 App
- 8009220015 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 IPPOLITO.T A Operating Reactors Branch 2 80/08/29 2pp
- --8007220017 Order for mod of Licenses DPR-27 & BPR-30 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment info should be submitted by 801101 EISENBUT.D 0 Division of Licensing 80/08/27 6pp
- 8009ii0Bi3 Memorandum & order rejecting State of IL B00827 Second Amended Contention 1 Directs util & NRC to respond to ASLB question re status of spent fuel storage capacity Ruling on Second Amended Contention 10 held in abeyance until B01101 LITTLE.L W . REMICK.F J . WOLF.JF Atomic Safety and Licensing Board Panel 80/09/09 Spp
- 8009300603 Forwards 800919 order revising 800929 order for mod of DLs. In entirety
  EISERWINTO O Division of Licensing 80/09/19 2pp
- --R009300614 Order revising 800829 order for mad of QLs DPR-29 & DPR-30, published in 800912 FR, in entirety Info re IE Dulletin 79-018 shall be filed by 801101 Request for hearing will not stay order effective 800919 UCS petitions discharged EISENHUT, D & Division of Licensing 80/09/19 App
- --9009300619 Order revising 800829 order for mod of OL DPR-25, published in 800912 FR, in entirety Info responsive to IE Bullotin 79-018 shall be submitted by 801101 Request for hearing will not stay order effective 800919 UCS petitions discharged EISENHUT, D & Division of Licensing 80/09/19 4pp
- B009300007 Notice of appearance in spent fuel pool mod proceeding Certificate of Svc encl BARTH.C A Hearing Branch 3 80/09/26 2pp
- 8009300045 Response to 800909 inquiry re applicability of Commission 750916 pulicy statement. "Intent to Propare GEIS on Handling & Starage of Spent LNR Fuel" Not applicable due to issuance of GEIS in Aug 1979 Certificate of Evc encl GODDARD, RJ Hearing Branch 2 80/09/26 5pp
- P Operating license stage documents & correspondence
- 8007110854 Supplis NRC 800707 request for proposed Tech Specs changes re scram discharge vol vent & drain valves. & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT.D O Division of Licensing 80/07/22 22pp
- 8009020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 70 days EISENHUT, D G Division of Licensing 80/07/31 7pp
- 80090B00B0 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT

- 8009230052 Informs that exemption from fee re licensing action associated w/FMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D. G. Division of Licensing 80/08/07 60pp
- 6009020456 Forwards evaluation of util response to NRC 800223 request for info re-primary coolant sys pressure isolation valves. Two specific Event 5 valve configurations do not exist at facilities.

  CRUICHFIELD.D Operating Reactors Branch 5 80/08/12 3pp
- --8009020470 "Primary Copiant Sys Pressure Isolation Valves." technical evaluation rept HOELL,P N., STILWELL,T C. Franklin Institute/Franklin Research Center NRC-03-79-118 B0/07/21 4pp
- 8009150401 Confirms 800811 discussion re arranging 800821 meeting w/util in Chicago. It re facility cooling lake dike seepage 5 remedial action to be taken XEPPLER. J O Region 3. Chicago. Office of the Director 60/08/15
- 8009180252 Forwards NUREG-0661, "Mark I Containment Long-Term Program SER Resolution of Generic Technical Activity A-7" Rept discusses generic suppression pool hydrodynamic load definition W/o encl [PPOLITO, T A Operating Reactors Branch 2 80/08/20 2pp
- 8009020105 Forwards NUTECH Rept CCM-0708-03. "Evaluation of 18-1mch Containment Isolation Valves for Dresden Station,Units 2 % 3 % Quad Cities Station.Units 1 & 2." in response to NRC 791022 % 23 ltrs re containment vent & purge valves JANFCEK.R F Commonwealth Edison Co 80/08/22 19
- --8009020111 "Evaluation of 18-Inch Containment Isolation Valves for Dresden Station,Units 2 & 3 & Quad Cities Station,Units 1 & 2 " GERBER, D A , DEARDDRFF,P E , MARTIN, J B Nuclear Technology, Inc (Nutech) COM-0708-03 80/05/14 116pp
- P009120404 Forwards Attachments (-5 to util 800630 itr re facility electric distribution sys voltage adequacy Ltr advertently transmitted w/o attachments VECEK.R F Commonwealth Edison Co 80/08/28 6pp
  - 10250 Requires submittal of ATMS emergency operating procedure for review Generic analysis should confirm ATMS mitigation ability described in Vol 3 of NUREG-0460 Commission will emmine required mods & implementation schedules ESCO.R L Assistant Director for Licensing 80/08/29 3pp
  - 240555 Forwards final critique of 800619 BEP exercise Critique scusses problem areas identified during exercise & esents corrective actions W/o critique
  - )9090394 Forwards add1 info re min critical configuration in support of 800515 application to amend Licenses DPR-19,25,27 & 30, changing requirements for source range monitor count rates JANECEK, R F Commonwealth Edison Co 80/09/03 Bpp
- 109180501 Forwards Amends 49,44,58 & 53 to Licenses DPR-19, DPR-25, 19R-29 & DPR-30, respectively, safety evaluation & notice of source & availability POLITO, T A Operating Reactors Branch 2 80/09/08 2pp
  - D9180506 Amends 49, 44,58 & 53 to Licenses DPR-19, DPR-25, DPR-29 & DPR-30, respectively, revising Tech Specs to allow count rate on source range monitor channels below 3 counts per second when there are two or less fuel assemblies in quadrant IPPOLITO.T A Operating Reactors Branch 4 80/09/08 22pp
    - 180516 Safety evaluation supporting Amends 49.44,58 & 53 to enses DPR-19.DPR-25.DPR-29 & DPR-30.respectively Office of Nuclear Reactor Regulation, Director 80/09/08 4pp
    - 0528 Notice of issuance & availability of Amends 49,44,58 & 53 to nses DPR-19,DPR-25,DPR-29 & DPR-30,respectively ITO,T A Operating Reactors Branch 2 80/09/08 2pp
    - 3 Forwards proposed Tech Spec changes re implementation of TMI Learned Category A requirements, in response to NRC request Dresden Unit 1 Tech Spec changes will be d 90 days prior to scheduled startup 9 F Commonwealth Edison Co 80/09/18 3pp
      - r Proposed Tech Spec changes re implementation of TMI-2 Learned Category A items inwealth Edison Co 80/09/10 29pp

- 8009250292 Requests add1 60-90 days for review to determine whether as-built facilities differ from basis in NRC assessment Add1 time would allow for reproduction distribution & review methods to function properly

  JANFCEKUR F Commonwealth Edison Co 80/09/19 1p
- 8009260465 Forwards Inst of Nuclear Power Operations rept, "Evaluation of Dresden Nuclear Power Station"

  LEE,B Commonwealth Edison Co 80/09/23 lp
- --8009260468 "Evaluation of Dresden Nuclear Power Station"

  \* Institute of Nuclear Power Operations EA 80-01 80/09/12
  40pg
- G Inspection reports. IE Bulletins & correspondence
- 8009040517 Forwards IE Bullstin 80-07, Suppl 1, "BWR Jet Pump Assembly Failure" Response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/14
- 8007040632 Provides addl response to IE Bulletin 80-17 Results of analysis of ATMS w/o recirculation pump trip encl Analyses raquired no deratings to remain below svc level C limit JANECEK, R F Commonwealth Edison Co B0/07/14 App
- B009100143 Forwards IE Insp Repts 50-010/80-12,50-237/80-12 & 50-249/80-16 on 800607-0703 No noncompliance noted HEISHMAN,R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/07/23 2pp
- --8009100148 IE Insp Repts 50-010/80-12.50-237/80-12 & 50-249/80-16 on 800609-0703 No noncompliance noted Major areas inspected operational safety verification & monthly maint & surveillance observations
  SPESSARD, R. L., BARKER, J. L., TONGUE, T. M. Region 3, Chicago, Office of the Director. 80/07/23 4pp
- B009020109 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " SA-312 pipe not present in operating plants Final confirmation from suppliers anticipated by 800915 re const plant piping sys NAUOHTON, W F Commonwealth Edison Co 80/08/07 2pp
- 8009170230 Forwards response to IE Bulletin 80-17. Suppl 1, "Failure of 74 of 185 Control Rods to Fully Insert During Scram at BWR "
  Scram discharge vol piping. scram instrument vol piping & drain piping meet requirements re dounward pitch PEOPLES. D. L. Commonwealth Edison Co. 80/08/07 4pp
- 8009030231 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER. J & Region 3, Chicago. Office of the Director 80/08/15
- 8009110545 Responds to IE Bulletin 80-08, "Exam of Containment Liner Penetration Wolds," supplementing 800709 response Corrects Zion response re rings used for field circumferential butt weld. Reviews accuracy of other statements ABEL.J S Commonwealth Edison Co 80/08/15 4pp
- 8007110562 Responds to Suppl 1 to IE Bulletin 80-17. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR "
  Util will not have continuous SDV water level monitoring sys installed 8 functional by 800701

  JANECEK, R F Commonwealth Edison Co 80/08/15 2pp
- 8009160681 Submits supplementary response to IE Bulletin 80-08. "Examination of Containment Liner Penetration Nelds," correcting statement made in DL Peoples 800709 ltr Further review not necessary ABEL. J S Commonwealth Edison Co 80/08/15 4pp
- 8009260395 Forwards IE Insp Repts 50-010/80-13,50-237/80-14 & 50-237/80-18 on 800707-0801 & notice of violation HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/08/18 2pp
- --8009260399 Notice of violation from insp on 800707-0801
  \* Region 3, Chicago, Office of the Director 80/08/18 ip
- --8009260404 IE Insp Repts 50-010/80-13.50-237/80-14 & 50-249/80-18 on 800707-0801 Noncompliance noted failure of licensed operators to keep themselves cognitant of design changes BARKER, J E. STREETER, J F. SPESSARD, R L. Region 3. Chicago, Office of the Director 80/08/18 11pp

- 8009090013 Submits addi response to IE Bulletin BO-17. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at IBWR "
  Procedures have been developed to monitor scram discharge vol for residual water on daily basis
  JANECEK,R F Commonwealth Edison Co 80/08/20 1p
- BOO9150495 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE BWR Facilities "No specific action or response requested KEPPLER.J G Region 3, Chicago, Office of the Director BO/08/20
- 8009120060 Forwards Buppl 3 to IE Bulletin 80-17. "Failure of Control Rods to Insert During Scram at BWR " Written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/08/22
- 8009180551 Forwards IE Circular 80-18, "10CFR80 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER, J.G. Region 3. Chicago, Office of the Director 80/08/22
- 8009230094 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers" No written response regulared KEPPLER.J O Region 3. Chicago, Office of the Director 80/08/28
- 8009170411 Forwards response to IE Bulletin 80-15 re possible loss of emergency notification sys w/loss of offsite power Review revealed inoperability of Dresden sys Investigation being conducted Operating Order 26-80 changed JANACEK.R F Commonwealth Edison Co 80/08/29 4pp
- 8009180466 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Identified relays are not used in facility No action required Twenty-four manhours expended on review RAUSCH:T J Commonwealth Edison Co 80/08/27 ip
- 8009230478 Forwards Revision 1 to IE Bulletin 79-26, "Boron Loss From BWR Control Blades " Written response required KEPPLER.J G Region 3, Chicago, Défice of the Director 80/08/29
- BOO9170421 Responds to IE Bulletin 80-17. Suppl 1. re failure of control rods to fully insert during scram at BWR Vent sys will provide reliable source of air during draining. Sys will be steadily purged until mods installed JANECEK.R F. Commonwealth Edison Co. 80/09/02 2pp
- 8009260109 Forwards response to IE Bulletin 80-17. Suppl 3, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR "Procedure at Dresden 2 & 3 changed to require immediate manual scram when air pressure reaches 60 ps1
  RAUSCH, T J Commonwealth Edison Co 80/09/02 4pp
- 8009250904 Responds to NRC 791213 request for addl info in response to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Expansion anchor test results show installation of anchors acceptable JANECEK.R F Commonwealth Edison Co. 80/09/05 17pp
- 8009240133 Forwards IE Circulat 80-21. "Regulation of Refueling Crews " No written response required MEPPLER, J O Region 3. Chicago, Office of the Director 80/09/10
- 8009300200 Forwards response to IE Bulletin 80-20 No Westinghouse Type W-2 control switches are used in safety-related sys at Bresden, Quad Cities & LaBalle County Responses for Zion & Byron are encl RAUSCH, T J C Commonwealth Edison Co 80/09/15 And
- R Periodic operating reports & related correspondence
- 8009030456 Forwards semiannual rept of radioactive effluent discharges 8 solid radwaste, for Jan-June 1980 SCOTT, D J Commonwealth Edison Co 80/08/20 1p
- --8009030467 Semiannual rept of radioactive effluent discharges & solid radwaste,for Jan-June 1980 \* Commonwealth Edison Co 80/08/20 15pp
- 8009230713 Forwards monthly operating repts for Aug 1980 800TT,D J Commonwealth Edison Co 80/09/12 1p

- ---8009230720 Monthly operating repts for Aug 1980 CIESZKIEWICZ, S Commonwealth Edison Co 80/4 80/09/03 1500
- T Hearing transcripts on non-antitrust matters
- 8009100084 Transcript of 800819 prehearing conference in Chicago, IL Pp 1-72 \* Atomic Safety and Licensing Board Panel 80/08/19 75pp
- V Operator Examinations
- 8009300287 Forwards preliminary topical outlines of proposed modules on thermal hydraulics & core damage mitigation to be included in revised reactor operator training program per 800328 request . Commonwealth Edison Co 90/09/15 7so
- DOCKET 50-250 TURKEY POINT PLANT, UNIT 3 F Security, medical, emergency & fire protection plans
- 8007070862 Requests participation in NRC study of people-related problems in nuclear safeguards Request includes NRC visit to facility to interview security personnel Confidentiality of info will be maintained during all phases of study VAROA.S A Operating Reactors Branch 1 80/08/14 2pp
- 8009230261 Requests that all personnel be reminded of surpose of emergency notification sys & health physics network Bys installed for govt use during energency D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22
- G Adjudicatory correspondence
- B009190046 Motion for order to show cause why facility should not be shutdown by B00731 to inspect 8 repair steam generator Util B00630 request for extension until Oct 1980 to perform insp should be denied Certificate of Svc encl BARRACK.T. BRODKS.R. HOSKINS.W Affiliation Unknown 80/07/30 1800
- 8009150084 Ack receipt of 800730 petition on behalf of certain residents & homeowners of south FL requesting that NRC issue order to show cause to util Petition is being treated under 10CFR2 206 DENION, HR Office of Nuclear Reactor Regulation, Director 80/08/15 2pp
- --8009150089 Notice of request for action under 10CFR2 206 by 800730 patition on behalf of residents in south FL for NRC to issue to util order to show cause why facility should not be shut down by 800731 for insp & repair DENTON-H R Office of Nuclear Reactor Regulation, Director
- -8009150095 Motion for order to show cause why facility should not be shut fown by 800731 to perform steam generator insp & repair, on behalf of certain residents & homeowners in south FL Certificate of 8vc & util press release encl HODDER, M H Hodder, M H FLAXMAN, C A Flaxman, C A 80/07/30
- 8009020073 Forwards Ft. Power & Light Co comments on 800730 petition for show cause order re 800731 facility shutdown for steam generator insp & repair REIS-H F Lowenstein, Newman, Reis, Axelrad & 7011 80/08/27 1p
- -8009020079 Comments opposing 800730 petition for show cause order re 800731 facility shutdown for steam generator insp & repair Potition is w/o merit & should be dismissed & Florida Power & Light Co 80/08/27 15pp
- B009190267 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 VARGA.S A Operating Reactors Branch 1 80/08/27 2pp
- --8007190275 Order for mod of Licenses DPR-31 & DPR-41 to add info which fully responds to MRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101 EISENHUT, D O Division of Licensing 80/08/27 App
- 8007250024 Advises that contrary to 800702 ltr.DES re proposed OLs amend to permit steam generator repair will be issued by 801031 COLDBERG.S C Hearing Branch 2 80/09/23 1p

8007270180 Motion to participate as interested state in proceeding Review of EIA safety evaluation & EIS may reveal areas of unague concern to petitioner SALYMERS, P. L. GINIBURG, R. A. Dade County, Fi 80/09/24 2pp

## M Ambitrust correspondence

- 8CG930376 Response before US Court of Appeals for BC Circuit, in apposition to petitioners' motion for expedited consideration of Civil Action 80-1099 Certificate of Svaeral Related correspondence Dim.H. 860w-1941, J.A. Florida Power & Light Co. BYN.H. Covington & Burling 80/09/25 5pp.
- F Operating license stage documents & correspondence
- egg705:027 Discusses void formation in vessel head during 800611 natural circulation codidoun event Requests opinion repotential for voiding phenomenon in C-E designed NSSS CHECKIPS Assistant Director for Plant Systems 80/07/28 2pp
- 8059020297 Submits interin criteria for shift staffing to all OL & CP licensess & applicants per NRC 800507 Itr Discusses administrative provisions for energency & overtime work Development & implementation to be revised within 90 days ESSECRUT. D C Division of Licensing 80/07/31 7pp
- BCC90B0CSO Forwards draft NUREG-0695. "Functional Criteria for Emergency Response Facilities Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0595 encl W/o NUREG ERSENAUT D G Division of Licensing 80/08/01 119pp
- BOGT230052 Informs that elemption from fee re licensing action associated w/IMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENMUT, D G Division of Licensing 80/08/07 40pp
- 8009190794 Forwards revised Westinghouse STS 3 9 8 2.3 9 10 & Bases 3/4 9 8 6 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Mritten response required NOVAK.TH Assistant Director for Operating Reactors 80/09/15 1p
- --8009190917 Revised Westinghouse STS 3 9 8 2.3 9 to & Bases 3/4 9 8 to 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during novement of fuel assemblies or control rods

  4 Assistant Director for Operating Reactors 80/06/23 21pp
- E039150429 Forwards formal request for addl info re design mod to add undervoltage relay protection sys to present loss of voltage scheme NOVAX.T H Assistant Director for Operating Reactors 80/08/18 dpp
- 8009090C91 Forwards request for add) info re adequacy of station electric distributor sys voltages VARGA. B a Operating Reactors Branch 1 80/08/19 5pp
- 8009130436 Forwards requests for addl info re environ statement on proposed steam generator repair Outstanding areas include accident evaluation endangered species distribution & destrerativation of VARCA.S A Operating Reactors Branch I 80/08/22 8pp
- 8309030236 Forwards responses to NRC 800717 questions concerning radwaste From condensate polishing demineralizing sys UHRIG.R E Florida Power & Light Co 80/08/29 7pp
- 8009090257 Responds to NRC 800729 request for info re lou fracture toughness info is being prepared by AE Rept will be provided by 800930 UNRIG.R E Florida Power & Light Co 80/09/05 1p
- 8009120049 Notification of 800917 meeting w/util at plant site to discuss steam generator repair program GRDTENHUIS:N Operating Reactors Branch 1 80/09/08 2pp
- 8009190908 Notsfication of 800930 environ site visit w/util to plant outfall canal sys & associated areas around facilities GROTENGRUIS, H Operating Reactors Branch I 80/09/11 2pp
- 8009160378 Responds to NRC 800702 ltr ne TMI-related Tech Specs Proposed specs have been drafted & forwarded to omsite & affisite raview committees for review & approval URIO, R E Fiorida Power & Light Co 80/09/12 1p

- 8009190206 Application for amend of Liconses BPR-31 & DPR-41, revil Tech Specs to include definition of "operability" & to clarify application of limiting conditions for apprations Amend is submitted in response to NRC 800410 lt; UHRIGR E Fiorida Power & Light Co 80/09/12 1p
- --8009190209 Proposed Tech Specs, Section 1 re definition of "operal & Section 3 re limiting conditions for operation Safety evaluation enc! 

   Florida Power & Light Co 80/09/12 21pp
- 8009260015 Confirms arrangements for site visits on 80091/ & 30 rs steam generator repair program at plants VARQA-S A Operating Reactors Branch 1 80/09/12 App
- 8009290343 Discusses util response to NRC 800819 & 18 requests for info re adequacy of station electric distribution systematics and the state of th
- 8009300129 Forwards responses to NRC request for add1 info re occurrence of endangered species at facility Steam generator repairs will not adversely affect crocodiles & turtles Add1 response contained in nonradiological environ rept for 1979 UARIG.R E Florida Power & Light Co 60/09/24 Spp
- 8009300177 Forwards response to request for add1 info re mccident evaluation for steam generator repair UHRIO,R E Florida Power & Light Co 80/09/24 8pp
- @ Inspection reports, IE Builetins & correspondence
- 8009100049 Forwards IE Bulletin 80-18. "Maint of Adequate Him Ficw Through Centrifugal Charging Pumps Following Secondary Dide High Energy Line Rupture " Written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director (60/07/2)
- 8009020195 Submits response to IE Bulletin 79-03A Completed Answir to be forwarded by 801001 UHRIG.R E Florida Power & Light Co 80/08/08 Ip
- 8007030300 Responds to IE Bulletin 79-03A, "Longitudinal Held Defects in ASKE SA-312. Type 304 Stainless Steel Pipe " Preliminary info indicates seam welding piping in safety-related syswill meet code allowable stress criteria UHRIG.R E Florida Power & Light Co 80/08/08 ip
- 8009030158 Forwards Revision i to IE Bulletin 80-19, "Pailures of Mercury-Netted Matrix Relays in Reactor Protective 8us of Operating Nuclear Power Plants Designed by C-F " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 800/09/15 pc
- 8009160639 Responds to IE Bulletin 79-17 re pipe cracks in steenant borated water sys Visual & ultrasonic examinations revealed no unresolved indications of stress corrosion in identified circumferential welds

  UHRIO:R E Florida Power & Light Co 80/08/20 ip
- 8009160639 Responds to IE Bulletin 79-17 re pipe cracks in stagmant borated water sys Visual & ultrasonic examinations revealed no unresolved indications of stress corrosion in identified circumferential welds

  UHRIG.R E Florida Power Corp. 80/08/20 [p
- B009160143 Forwards IE Circular 80-18, "10CFR50 59 Befety Evalvation for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 100/08/22
- 8009120486 Ack receipt of 800804 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept\* 50-250/80-20 & 50-251/80-17 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/25 ip
- --8009120491 Responds to NRC 800703 ltr re violations noted in JE lrij Repts 50-250/80-20 % 50-251/80-17 Corrective actions written Instructions w/specific details on implementation of Spec 5177-M-53 issued to contractor welders UHR10, R E Florida Power & Light Co 80/08/04 2pp
- --8009120495 Forwards IE Insp Repts 50-250/80-20 & 50-251/80-17 on 800527-29 & 0603-04 & notice of violation MRPHY/C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/03 2pp

--8009120497 Notice of violation from insp on 800527-29 & 0603-04
\* Region 2. Atlanta, Office of the Director 80/06/27 ip

reality.

a present

5 .,

fp,

4

5a

17/44

1 12

111

41

- --8009120499 IE Insp Repts 50-250/80-20 & 50-251/80-17 on 800527-29 & 0603-04 Noncompliance noted failure to follow weld electrode procedural requirements
  HERDIAR Region 2. Atlanta, Reactor Construction & Engineering Eupport Branch ECONUMOS, N Region 2. Atlanta, Office of the Director 80/06/27 6pp
- 8009120515 Ack receipt of 800728 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-250/80-19 & \$0-251/80-20 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/08/25 ip
- --8009120520 Responds to NRC 800627 ltr re violations noted in 1E Insp Repts 90-250/80-19 & 50-251/80-20 Corrective actions each item will be evaluated & implemented in accordance w/ guideline UHRIGAR E Florida Power & Light Co 80/07/28 3pp
- --8009120526 Forwards IE Insp Repts 50-250/80-19 & 50-251/80-20 on 800604-06 & notices of violation & deviation MURPHY, C E Region 2, Atlanta. Reactor Construction & Engineering Support Branch 80/06/27 2pp
- --8009120531 Natice of violation from insp on 800604-06
  \* Region 2. Atlanta. Office of the Director 80/06/27 ip
- --8007120535 Notice of deviation from insp on 800604-06
  \* Region 2. Atlanta. Office of the Director 80/06/27 ip
- --8007120537 IE Insp Repts 50-250/80-19 & 50-251/80-20 on 800604-06
  Noncompliance noted inadequate fire brigade training
  program & fire protection administrative control procedures
  CONLON.TE Region 2. Atlanta, Reactor Construction & Engineering
  Support Branch MILLER.W H Region 2. Atlanta. Office of the
  Director 80/06/27 6pp
- 8009110121 Ack receipt of 800806 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/80-23 t 50-251/80-23 KENNA, W B Region 2. Atlanta, Safeguards Branch 80/08/27 lp
- --8009110166 Responds to NRC 800711 ltr re viglations noted in IE Insp Repts 50-250/80-23 & 50-251/80-23 Corrective actions withheld (ref 10CFR2 770) UHRIG-R E Florida Power & Light Co 80/08/06 ip
- --8009110169 Forwards IE Insp Repts 50-250/80-23 & 50-251/80-23 on 800616-20 & notice of violation Notice of violation withheld (ref 10CFR2 790) KENNAN B Region 2, Atlanta, Safeguards Branch 80/07/11 2pp
- --8009110173 IE Insp Repts 30-250/80-23 & 50-251/80-23 on 800616-20
  Noncompliance noted failure to maintain positive control
  over all designated vehicles Details withheld
  (ref 10CFR2 790)
  TILLMAN.A., HOWELL.J.C. Region 2. Atlanta, Office of the Director
  GILLESPIE, F.P. Region 2. Atlanta, Safeguards Branch 80/07/11
  1p
- B009120300 Forwards IS Info Notice B0-31, "Maloperation of Gould-Brown Boveri ABO Volt Type K-6008 & K-DQN 6008 Circuit Breakers"

  No written response required
  O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/27

  1p
- 8009120671 Responds to IE Bulletin 80-19. Revision 1 re failures of mercury-wetted matrix relays in reactor protective sys Identified relays are not used in facility Four manhours expended for review UHRIG.R E Florida Power & Light Co 80/09/02 1p
- 8009110853 Submits response to IE Bulletin 80-04 Final response to bulletin will be submitted by 801001
  UHRIG.R E Florida Power & Light Co 80/09/03 ip
- 8009240412 Forwards response to IE Bulletin 80-15 re possible loss of emergency notification sys w/loss of offsite power Onsite extensions powered by reliable power supply Thirty-three manhours expended on review & corrective action Waffidavit UHRIG.R E Florida Power & Light Co 80/09/04 App
- 8009250209 Forwards response to NRC ltr re violation noted in IE Insp Repts 50-250/80-18 & 50-251/80-18 Corrective actions expansion anchors for listed supports will be reinspected No proprietary info in rept UHRIO,R E Florida Power & Light Ca 80/09/08 2pp

- g009290277 Forwards IE Circular 80-21, "Regulation of Refueling Crews"
  No written response required
  O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/10
  Soo
- R Periodic operating reports & related correspondence
- BOD9090290 Forwards "Radioactive Effluent Release Data, Jan-June 1980" & "Environ Radiological Monitoring Program Summary, Jan-June 1980 " UMRIG, R E Florida Power & Light Co 80/09/03 1p
- --8009090306 "Radioactive Effluent Release Data, Jan-June 1980 " → Florida Power & Light Co 80/08/14 17pp
- --8009090311 "Environ Radiological Monitoring Program Summary, Jan-June
  - ◆ Florida Power & Light Ca 80/09/03 Bpp
- 8009170279 Forwards monthly operating repts for Aug 1980 SCHMIDT, A D Florida Power & Light Co 80/09/06 ip
- --8007170281 Monthly operating repts for Aug 1780 CHILSOM V T Florida Power & Light Co 80/07/06 15pp
- 8 Repartable occurrences, LERs & related correspondence
- 8009120350 Forwards LER 80-015/03L-0 5CHMIDT, A D Florida Power & Light Co 80/09/02 1p
- --8009120385 LER 80-015/03L-0 on 800802, during power operation & in preparation to increase vol in accumulators, safety injection pump 3A failed to start following manual initiation Caused by broken support for driving pawl PACE,P L Florida Power & Light Co 80/09/02 2pp
- 8009300490 Forwards LER 80-016/03L-0 8CHMIDT,A D Florida Power & Light Co 80/09/12 Lg
- --8009300494 LER 80-016/03L-0 on 800813, process radiation monitors R-11 & R-12 were out of svc Caused by air sampling blower suction line becoming plugged & overheating Mod to substitute blower w/longer duty cycle being prepared PACE,PL Florida Power & Light Co 80/09/12 lp

# DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

- F Security, medical, emergency & fire protection plans
- 8009090862 Requests participation in NRC study of people-related problems in nuclear safeguards Request includes NRC visit to facility to interview security personnel Confidentiality of info will be maintained during all phases of study VARGA. S A Operating Reactors Branch 1 80/09/14 2pp
- 8009230261 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during amergency O'REILLY, J.P. Region 2, Atlanta, Office of the Director 90/09/22 ip
- G Adjudicatory correspondence
- 8009190267 forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 VAROA. B A Operating Reactors Branch 1 80/08/29 2pp
- --8009190275 Order for mad of Licenses DPR-31 & DPR-41 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment info should be submitted by 801101 EISENHUT.D & Division of Licensing 80/08/27 App
- 9009250024 Advises that contrary to 800702 ltr.DES re proposed OLs amend to permit steam generator repair will be issued by 801031 GQLDBERG,S C Hearing Branch 2 80/09/23 1p
- 8009290180 Motion to participate as interested state in proceeding Review of EIA safety evaluation & EIS may reveal areas of unique concern to petitioner SAUNDERS, B L , GINSBURG, R A Dade County, FI 80/09/24 2pp

#### M Antitrust correspondence

- 8009300476 Response before US Court of Appeals for DC Circuit.in papersition to petitioners' motion for sipedited consideration of Civil Action 80-1099 Certificate of Svc and Related correspondence DYA.H . BQUKNIGHT.J A Florida Power & Light Co DYM.H . Covington & Burling 80/09/25 5pp
- P Operating license stage documents & correspondence
- 8009050029 Discusses void formation in vessel head during 800611 natural circulation cooldown event Requests opinion repotential for voiding phenomenon in C-E designed NSSS CHECK.P S Assistant Director for Plant Systems 80/07/28 2pp
- 8009020297 Submits interim triteria for shift staffing to all DL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D G Division of Licensing 80/07/31 7pp
- 6007080080 Forwards draft NUREG-0676, "Functional Criteria for Emergency Response Facilities" Cornents requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl W/o NUREG E15ENHUT, D G Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D.G. Division of Licensing 80/08/07 40pp
- 8009190794 Forwards revised Westinghouse STS 3 9 8 2,3 9 10 & Bases 3/4 9 8 % 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NDVAW, T M Assistant Director for Operating Reactors 80/08/15 ip
- --8009190817 Revised Westinghouse STS 3 9 8 2.3 9 10 & Bases 3/4 9 8 5 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods
  \* Assistant Director for Operating Reactors 80/06/23 21pp
- 8009150429 Forwards formal request for addl info re design mod to add undervoltage relay protection sys to present loss of voltage schame NDVAK.T M Assistant Director for Operating Reactors 80/08/18 680
- 8009090091 Forwards request for addl info re adequacy of station electric distributor sys voltages
  VARGA.S A Operating Reactors Granch 1 80/08/19 5pp
- 8009190436 Forwards requests for additinfore environ statement on proposed steam generator repair Outstanding areas include accident evaluation, endangered species distribution & demineralization VAROA.8 A Operating Reactors Branch 1 80/08/22 8pp
- 8009030236 Forwards responses to NRC 800717 questions concerning radwaste from condensate polishing demineralizing sys UHRIG.R E Florida Power & Light Co 80/08/29 7pp
- 8009090257 Responds to NRC 900729 request for info re low fracture toughness info is being prepared by AE Rept will be provided by 800930 UHRIO, R E Florida Power & Light Co 80/09/05 ip
- 8009120049 Notification of 800917 meeting w/util at plant site to discuss steam generator repair program GNOTENHUIS.M Operating Reactors Branch 1 80/09/08 2pp
- GOO9190908 Notification of 800930 environ site visit w/util to plant outfallicanal sys & associated areas around facilities GROTENHUIS, M. Operating Reactors Branch 1. 80/09/11. 2pp
- 8009160378 Responds to NRC 800702 ltr re TMI-related Tech Specs Proposed specs have been drafted & forwarded to onsite & offsite review committees for review & approval UHRIG.R E Florida Power & Light Co 80/09/12 tp.

- 8009190206 Application for amend of Licenses DPR-31 & DPR-41, revising Tech Specs to include definition of "operability" & to clarify application of limiting conditions for operations Amend is submitted in response to NRC 800410 ltr UHRIO.R E Florida Power & Light Co 80/09/12 1p
- --8009170207 Proposed Tach Space, Section I re definition of "operability" | & Section 3 re limiting conditions for operation Safety evaluation enc) + Florida Power & Light Co 80/09/12 21pp
- 8009260015 Confirms arrangements for site visits on 800917 & 30 resteam generator repair program at plants VAROA.5 A Operating Reactors Branch i 80/09/12 2pp
- 8009290343 Discusses util response to NRC 800819 & 18 requests for info re adequacy of station electric distribution sys voltages A/E info expected by Oct 1980 Response to 800819 & 20 requests planned for 801101 & 15, respectively UHRIO.R E Florida Power & Light Co 80/09/24 ip
- 8009300129 Forwards responses to NRC request for add1 info re occurrence of endangered species at facility Steam generator repairs will not adversely affect crocodiles & turtles Add1 response contained in nonradiological environ rept for 1979 UHRIG.R E Florida Power & Light Co 80/09/24 Japp
- 8009300177 Forwards response to request for add1 info re accident evaluation for steam generator repair UHRTO.R E Florida Power & Light Co 80/09/24 8pp
- Q Inspection reports. IE Bulletins & correspondence
- 8009:00049 Forwards IE Bulletin 80-i8, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rugture "Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/07/24
- 8009020195 Submits response to IE Bulletin 79-03A Completed answer to be forwarded by 801001 UMRIG.R E Florida Power & Light Co 80/08/08 1p
- 8009030300 Responds to IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Preliminary into indicates seam welding piping in safety-related sys will meet code allowable stress criteria UHRIQ.R E Florida Power & Light Co 80/08/08 1p
- B009030138 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director B0/08/15 in
- 8009160639 Responds to IE Bulletin 79-17 re pipe cracks in stagnant borated water sys Visual & ultrasonic examinations revealed no unresolved indications of stress corrosion in identified circumferential welds

  UHRIO.R E Florida Power & Light Co 80/08/20 ip
- 8009160143 Forwards IE Circular 80-18, "10CFR90 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22
- 8009120486 Ack receipt of BOO804 itr Informing NRC of steps taken to correct violation noted in IE Insp Repts 50-250/80-20 & 50-251/80-17 MURPHY/C E Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch 80/08/25 1p
- ---8009120491 Responds to NRC 800703 ltr re violations noted in IE Insp Repts 50-250/80-20 & 50-251/80-17 Corrective actions written instructions, w/specific details on implementation of Spec 5177-M-53, issued to contractor weiders UHRIG, R E Florida Power & Light Co 80/08/04 2pp
- --8009120495 Forwards IE Insp Repts 50-250/80-20 & 50-251/80-17 on 800527-29 & 0603-04 & notice of violation MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/03 2pp

1

--8009120497 Natice of violation from insp on 800527-29 & 0603-04 \* Region 2, Atlanta, Office of the Director 80/06/27. ip

- --B009120499 IE Insp Repts 50-250/B0-20 & 50-251/B0-17 on 800527-29 & 0603-04 Noncompliance noted failure to follow weld electrode procedural requirements
  HERDT.A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch ECONDMOS N Region 2. Atlanta, Office of the Director 50/06/27 & 5pp
- 8009120515 Ack receipt of 800728 ltr informing NRC of steps taken to correct violations noted in 16 Insp Repts 50-250/80-19 & 50-251/80-20 MURPHY.C E Region 2. Atlanta Reactor Construction & Engineering Support Branch 80/08/25 1p
- --B009120520 Responds to NRC 800627 ltr re violations noted in IE Insp Regts 50-250/80-19 & 50-251/80-20 Corrective actions each item will be evaluated & implemented in accordance w/ guideline UHRIG:RE Florida Power & Light Co 80/07/28 3pp
- --8009120526 Forwards IE Insp Repts 50-280/80-19 & 50-251/80-20 on 800604-06 & notices of violation & deviation MURFHY.CE Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/06/27 2pp
- --8009120531 Notice of violation from insp on 800404-04
  \* Region 2. Atlanta, Office of the Director 80/06/27 ip
- ---BD09120535 Notice of deviation from insp on 800604-06 \* Region 2. Atlanta. Office of the Director 80/06/27 ip
- ---8009120539 IE Insp Repts 50-250/80-19 % 50-251/80-20 on 800604-06 Noncompliance noted inadequate fire brigade training program & fire protection administrative control procedures CONLON.TE Region 2. Atlanta, Reactor Construction & Engineering Support Branch MILLER,W H Region 2. Atlanta, Office of the Director 80/06/27 6pp
- 8009110121 Ack receipt of 800806 1tr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/80-23 & 50-251/80-23 KENNA: N B Region 2. Atlanta: Safeguards Branch 80/08/27 1p
- --8009110146 Responds to NRC 800711 ltr re violations noted in IE lnsp Repts 50-250/80-23 & 50-251/80-23 Corrective actions withheld (ref 10CFR2 790) UMRIO.R E Florida Power & Light Co 80/08/06 1p
- ~-8009110169 Forwards IE Insp Repts 50-250/80-23 & 50-251/80-23 on 800616-20 & notice of violation Notice of violation withheld (ref 10CFR2 790)
  KENNA,W B Region 2, Atlanta, Bareguards Branch 80/07/11 2pp
- --8009110173 IE Insp Repts 50-250/80-23 & 50-251/80-23 on 800616-20 Noncompliance noted failure to maintain positive control over all designated vehicles Details withheld (ref 10CFR2 790)
  TILLMAN.A. HUNELL, J. C. Region 2, Atlanta, Office of the Director GILLEBPIE, F. P. Region 2, Atlanta, Safeguards Branch 80/07/11
- SD09120308 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Bover1 480 Volt Type K-6008 & K-DBN 6005 Circuit Breakers "
  No written response required O'REILLY, J.P. Region 2: Atlanta, Office of the Director 80/08/27 to
- B009120671 Responds to IE Bulletin 80-19, Revision 1 re failures of mercury-wetted matrix relays in reactor protective sus Identified relays are not used in facility Four manhours expended for review UHRIGR E Florida Power & Light Co 80/09/02 1p
- 8009110953 Submits response to IE Bulletin 80-04 Final response to bulletin will be submitted by 801001 UHRIGAR E Florida Power & Light Co 80/09/03 tp
- 8009240412 Forwards response to IE Bulletin 80-15 re possible loss of emergency notification sys w/loss of offsite power. Onsite extensions powered by reliable power supply Thirty-three manhours expended on review & corrective action W/affidavit UHRIG.R.E Florida Power & Light Cq 80/09/04 4pp
- 8009250209 Forwards response to NRC ltr re violation noted in IE Insp Repts 50-250/80-18 & 50-251/80-18 Corrective actions expansion anchors for listed supports will be reinspected No proprietary info in rept UHRIG.R.E Florida Power & Light Co 80/09/08 2pp

- 8009290277 Forwards IE Circular 80°21, 'Regulation of Refueling Crews " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/10 Spp
- R Periodic operating reports & related correspondence
- 8009070290 Forwards "Radioactive Effluent Release Data, Jan-June 1980" & "Environ Radiological Monitoring Program Summary, Jan-June 1980 "
  UHRIO.R E Florida Power & Light Co 80/09/03 lp
- --8009090304 "Radioactive Effluent Release Data, Jan-June 1980 "
  + Florida Power & Light Co 80/08/14 17pp
- --8007090311 "Environ Radiological Monitoring Program Summary, Jan-June 1980 " + Florida Power & Light Co 80/07/03 8pp
- 8009170279 Forwards monthly operating repts for Aug 1980 SCHMIDT.A D Florida Power & Light Co 80/09/05 ip
- ~~8009170281 Monthly operating repts for Aug 1980 CHILSON,V T Florida Power & Light Co 80/09/06 15pp
- S. Reportable occurrences, LERs & related correspondence
- 8009120313 Forwards LER 80-011/03L-0 SCHMIDT.A D Florida Power & Light Co 80/09/02 1p
- --8009120315 LER 80-011/03L-0 on 800818, during surveillance testing, six ionization detectors in 4W electrical penetration room found inoperable Caused by improper installation of upgrade to fire protection sys PACE, PL Florida Power & Light Co 80/09/02 2pp
- DOCKET 50-254 GUAD-CITIES STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8009230288 Requests that all personnel be reminded of purpose of emergancy notification sys & health physics network Sys installed for govt use during emergency KEPPLER.J O Region 3. Chicago, Office of the Director 80/08/22 3pp
- 8009100378 Forwards review of util generating station emergency plan & draft ltr requesting addl info & commitments from util PAGANO, F O Emergency Preparedness Licensing Branch 80/08/28 5pp
- G Adjudicatory correspondence
- 8009220015 Forwards order requiring info supporting environ qualification of safety-related electrical equipment. Requests submittal of info by 801101 [PPDLITO, 7 A Operating Reactors Branch 2 80/08/27 2pp
- --8007220017 Order for mod of Licenses DPR-29 % DPR-30 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment, Info should be submitted by 80:101
  EISENHUT, D 0 Division of Licensing 80/08/29 App
- 8009300603 Forwards 800919 order revising 800829 order for mod of OLs. in entirety EISEMHUT, D & Division of Licensing 80/09/19 2pp
- --8009300614 Order revising 800829 order for mod of OLs DPR-29 & DPR-30, published in 800912 FR, in satirety Info re IE Bulletin 79-018 shall be filed by 801101 Request for hearing will not stay arder effective 800919 VCS petitions discharged EISENHUT, D O Division of Licensing 80/09/17 App
- P Operating license stage documents & correspondence
- B009110554 Suppls NRC B00707 request for proposed Tech Specs changes re screm discharge vol vent & drain valves, & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EIBENHUT,D 0 Division of Licensing 80/07/22 22pp

- 8009020177 Submits interim criteria for shirt staffing to all DL & CP licenses? applicants.per ARC 800507 ltr Discusses administrative provisions for energency abvertime work Development & inplementation to be reviewed within 90 days EISENHUT, D.G. Division of Licensing 80/07/31 7pp
- 8007080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities" Cornents requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0595 ent W/o NUREG EISENHUT.D O Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISERHUT.D G Division of Licensing 80/08/07 40pp
- 6309020454 Forwards evaluation of util response to NRC 800223 request for info re primary coolant sys pressure isolation valves. Two specific Event 5 valve configurations do not exist at facilities. CRUTCHFIELD. D. Operating Reactors Branch 5 80/08/12 3pp
- --8009020473 "Prinary Coolant Sys Pressure Isolation Valves." technical evaluation rept "DELL.P.N. STILKELL.T.C. Franklin Institute/Franklin Research Center NRC-03-77-118 80/07/21 4pp
- E007(B0252 Forwards NUREG-066), "Mark I Containment Long-Term Program SER Pesolution of Generic Technical Activity A-7 " Rept discusses generic suppression pool hydrodynamic load definition M/o enc! 1PPOLITO T A Operating Reactors Branch 2 80/08/20 2pp
- 8009020105 Forwards NUTECH Rept COM-0708-03, "Evaluation of 18-inch Containment Isolation Valves for Bresden Station, Units 2 & 3 5 Guad Cities Station, Units 1 & 2." in response to NRC 791022 ± 23 ltrs re containment vent & purge valves JANECEK, R F Commonwealth Edison Co 80/08/22 ip
- ---BOG7020111 "Evaluation of IB-Inch Containment Isolation Valves for Dresden Station.Units 2 & 3 & Quad Cities Station.Units 1 & 2 "

  GERBER.D A , DEARDORFF.P E , HARTIN.J B Nuclear Technology. Inc. (Nutech) COM-070B-03 B0/05/14 116pp
- 8007120404 Forwards Attachments 1-5 to util 800630 ltr re facility alectric distribution sys voltage adequacy Ltr inadvertently transmitted u/o attachments
  JAFECEK.R F Commonwealth Edison Co 80/08/28 App
- 8009080338 Application for amend of License DPR-29, changing Tech Specs to support review of future releads Cycle 6 operation is scheduled to begin 80123 Class III fee encl
  JAPECEM.R F Commonwealth Edison Co 80/09/02 App
- --8007080341 Proposed Tech Specs to support review of future reloads, including Tech Specs 1 1/2 1 re fuel cladding integrity, 1 2/2 2 re safety limits 1/4 1 re reactor protection sys & 3 2/4 2 through 3 5/4 5 re limiting conditions for operation a Commonwealth Edison Co 60/09/02 47pp
- 8009090034 Forwards addl info re min critical configuration in support of 800915 application to amend Licenses DPR-19,25,29 \$ 30, changing requirements for source range monitor rount rates JANeCEK.R F Commonwealth Edison Co 80/09/03 5pp
- B007180501 Forwards Amends 49, 44,58 & 53 to Licenses DPR-19, DPR-25, DPR-27 & DPR-30, respectively, safety evaluation & notice of issuance & availability IPPOLITO, T A Operating Reactors Branch 2 80/09/08 2pp
- --8009180506 Amends 49, 44,58 % 53 to Licenses BPR-19, BPR-25, DPR-29 & DPR-30, respectively, revising Tech Specs to allow count rate on source range monitor charnels below 3 counts per second when there are two or less fuel assemblies in quadrant IPPOLITO.T A Operating Reactors Branch 4 80/09/08 22pp
- ---BOO9180516 Safety evaluation supporting Amends 49,44,58 & 53 to Licenses DPR-19,DPR-25,DPR-29 & DPR-30,respectively • Office of Nuclear Reactor Regulation, Director 80/09/08 4pp
- --8009180526 Notice of issuance & availability of Amends 49,44,58 & 53 to Licences DRR-19,DRR-25,DRR-29 & DRR-30,respectively IPPOLITO,T A Operating Reactors Branch 2 80/09/08 2pp

- 8009230463 Forwards proposed Tech Spec changes re implementation of TMI Lessons Learned.Category A requirements in response to NRC 800702 request Dresdem Unit i Tech Spec changes will be submitted 90 days prior to scheduled startup JANECEK.R F Commonwealth Edison Co 80/09/18 3pp
- --8009230466 Proposed Tech Spec changes re implementation of TMI-2 Lessons Learned Category A Items \* Commonwealth Edison Co 80/09/10 29pp
- Q Inspection reports, 1E Bulletins & correspondence
- 8009190166 Forwards IE Investigation Rept 50-254/79-31 on 791205-800115 No noncompliance noted KEPPLER, J G Region 3. Chicago, Office of the Director 80/02/14
- --8009170171 IE Investigation Rept 50-254/79-31 on 791205-800115 No noncompliance noted Major areas investigated circumstances surrounding closure of two core spray suction valves to ECCS NORELIUS, C.E., SPESSARD, L., MCCARTEN, J.B. Region 3, Chicago, Office of the Director 80/02/04 13pp
- 8009040517 Forwards IE Bulletin 80~07, Suppl 1, "BWR Jet Pump Assembly Failure" Response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/05/14
- 8007040632 Provides add1 response to IE Bulletin 80-17 Results of analysis of ATMS w/o recirculation pump trip encl Analyses required no deratings to remain below svc level C limit JANECEK, R F Commonwealth Edison Co 80/07714 App
- 8009020109 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASKE SA-312 Type 304 Stainless Steel Pipe " SA-312 pipe not present in operating plants Final confirmation from suppliers anticipated by 800915 re const plant piping sys NAUGHTON, W F Commonwealth Edison Co 80/08/07 2pp
- 8009170230 Forwards response to IE Bulletin 80-17, Suppl 1, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR "
  Scram discharge vol piping, scram instrument vol piping & drain piping meet requirements re downward pitch
  PEOPLES, D. L. Commonwealth Edison Co. 80/08/07 4pp
- 8009260488 Forwards IE Insp Repts 50-254/80-18 & 50-265/80-20 on 800714-18 & notice of violation Notice of violation withheld (ref 10CFR2 790)
  HIND.J A Region 3. Chicago, Safeguards Branch 80/08/12 2pp
- --8009280495 IE Insp Repts 50-254/80-18 % 50-265/80-20 on 800714-18 Noncompliance noted failure to establish compensatory measures for failed sacurity-related equipment & to control access to vital areas Details withheld fref 100FR2 790) HIND.J A Region 3. Chicago. Safeguards Branch 60/08/11 2pp
- 8007030231 Forwards Revision 1 to IE Bulletin 80-17, "Failures of Mercury-Metted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/08/15 ip
- 8009110545 Responds to IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds," supplementing 800709 response Corrects Zion response re rings used for field circumferential butt weld Reviews accuracy of other statements ABEL.J 8 Commonwealth Edison Co 80/08/15 4pp
- 8009110362 Responds to Suppl 1 to IE Bulletin HO-17, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR"
  Util will not have continuous BDV water level monitoring sysinstalled & functional by 800901
  JANECEK,R F Commonwealth Edison Co 80/08/15 2pp
- 8007160681 Submits supplementary response to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds," correcting statement made in DL Peoples 800709 ltr Further review not necessary ABEL, J S Commonwealth Edison Co 80/08/15 4pp
- 8009270123 Forwards Waste Packaging Insp Rept 15000046/80-65 on 800927-30 & notice of violation DAVIS.A 9 Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/08/18 2pp
- --8007270126 Notice of violation from insp on 800527-30 \* Region 3, Chicago, Office of the Director 80/07/23 ip

- ~-8009290131 Waste Packaging Insp Rept 15000046/80-65 on 800527-30 Noncompliance noted failure to meet strong, tight package requirement contained in DOT regulation LOVENDALE,P C , THOMAS.R D Region 3, Chicago, Office of the Director BOOK.H E Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/07/23 2pp
- 8009:10732 Ack receipt of 8008:2 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-254/80-16
  HIND.J A Region 3. Chicago, Safeguards Branch 80/08/20 ip
- --8009110737 Responds to NRC 800721 ltr re violations noted in IE Insp Rapt 50-254/80-16 Corrective actions withheld (ref 10CFR2 790) ABEL JB Commonwealth Edison Co 80/08/12 lo
- 8009150495 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain OE BWR Facilities " No specific action or response requested KEPPLER.J Q Region 3, Chicago, Office of the Director 80/08/20
- 8007120060 Forwards Suppl 3 to 1E Bulletin 80~17, "Failure of Control Rods to Insert During Scram at BWR" Written response required

  KEPPLER.J G Region 3, Chicago, Office of the Director 80/08/22

KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/22

- 8009180551 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Bys " Na written response required
  - REPPLER. J O Region 3. Chicago, Office of the Director 80/08/22
- 8009230094 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bovert 480 Volt Type K-600S & K-DON 600S Circuit Breakers " No written response required XEPPLER. J O Region 3, Chicago, Office of the Director 80/08/28
- BOO9100659 Ack receipt of 800715 ltr informing NRC of steps taken to correct violation noted in 800420 IE inspired & payment of civil penalty
  BTELLOV Office of Inspection & Enforcement, Office of the Director 80/08/29 2pp
- 6009170411 Forwards response to IE Bulletin 80-15 re possible loss of emergency notification sys w/loss of offsite power Review rewailed inoperability of Dresden sys Investigation being conducted Operating Order 26-80 changed

  JANACEK,R F Commonwealth Edison Co 80/08/29 4pp
- 8009(80466 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Identified relays are not used in facility No action required Twenty-four manhours espended on review RAUSCH.T J. Commonwealth Edison Co 80/08/29 1p
- 8009230478 Forwards Revision 1 to IE Bulletin 79-26, "Boron Loss From BWR Control Blades " Written response required KEPPLER, J 0 Region 3, Chicago, Office of the Director 80/08/29
- 800917042i Responds to IE Bulletin 60-17, Suppl fire failure of control rods to fully insert during scram at BWR Vent sys will provide reliable source of air during draining Bys will be steadily purged until mods installed JANECEK, R F Commonwealth Edison Co 80/09/02 2pp
- 9009250107 Forwards response to IE Bulletin 80-17.Suppl 3. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at DWR "
  Procedure at Dresden 2 & 3 changed to require immediate manual scram when air pressure reaches 60 psi
  RAUSCH.T J Commonwealth Edison Co 80/09/02 4pp
- GOO9290504 Responds to NRC 791213 request for add1 info in response to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Expansion anchor test results show installation of anchors accoptable JANECEK,R F Commonwealth Edison Co 80/09/05 17pp
- 8009240133 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/09/10 ip

- 8009300200 Forwards response to IE Bulletin 80-20 No Westinghouse Type M-2 control switches are used in safety-related sys at Dresden. Quad Cities & LaSaile County Responses for Inon & Byron are encl RAUSCH.T J Commonwealth Edison Co 80/09/15 App
- R Periodic operating reports & related correspondence
- 8009030448 Forwards semiannual rept of radioactive effluent discharges & solid radwaste for Jan-June 1980 KALIVIANAKIS,N Commonwealth Edison Co. 80/08/13 ip
- --8009030453 Semiannual rept of radioactive effluent discharges & solid radwaste, for Jan-June 1980 \* Commonwealth Edison Co 80/08/13 20pp
- 8009140272 Forwards monthly operating repts for Aug 1980 KALIVIANAKIS,N Commonwealth Edison Co 80/09/02 ip
- --8009160276 Monthly operating repts for Aug 1980 BROWN, B., TUBBS, B. Commonwealth Edison Co. 80/09/02 22pp
- BOO9120253 Forwards changes, tests & experiments completed during Aug 1980 KALIVIANAKIS, N Commonwealth Edison Co 80/09/08 2pp
- 8 Reportable occurrences, LERs & related correspondence
- 8009020390 Forwards LER 80-01//03L-0 KALIVIANAKIS,N Commonwealth Edison Co 80/08/04 ip
- --B009020396 LER 80-017/03L-0 on B00716, alarm in control room indicated vacuum breaker valve 60-1601-20B opened Valve position indicating lights inoperable Caused by coil burnup in air actuator solenoid Valve closed & defective coil replaced STEFFES.C Commonwealth Edison Co. 80/08/06 2pp
- 8009080422 Forwards LER 80-018/03L-0 KALIVIANAVIS,N Commonwealth Edison Co 80/08/19 1pp
- --8009080427 LER 80-018/03L-0 on 800805, main chimney offgas sample pump tripped Backup pump tripped also, producing low flow alarm Caused by excessive vane wear on pump rotors HAFERA, T Commonwealth Edison Co 80/08/15 2pp
- 8009120391 Forwards LER 80-019/03L-0 KALIVIANAKIS.N Commonwealth Edison Co 80/08/25 ip
- ---8009120399 LER 80-019/03L-0 on 800817, while operating at 400 MW, after performance of reactor core isolation cooling monthly pump operability surveillance test, flow controller was left in manual Caused by operator failure to readjust to automatic KOPACZ, J Commonwealth Edison Co 80/08/25 2pp
- V Operator Examinations
- 80093002B7 Forwards preliminary topical outlines of proposed modules on thermal hydraulics & core damaga mitigation to be included in revised reactor operator training program per B0032B request NAUGHTON.W F Commonwealth Edison Co B0/09/15 7pp
- DOCKET 50-255 PALISADEB NUCLEAR PLANT
- F Security, medical, emergency & fire protection plans
- 8007230275 Requests that all personnel be reminded of purpose of amergency notification sys & health physics network Sys installed for govt use during emergency KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/22
- BOO9110428 Submits revised description of reactor coolant pump oil leak originally submitted in 800502 tr Installation of oil leak collection sys has been completed Additions to correct design omissions will be completed by BO1101 HOFFMAN.D P Consumers Power CO 80/09/09 2pp
- G Adjudicatory correspondence
- E009090446 Provides status rept of discovery & other prehearing matters re civil penalty proceeding per 800229 memorandum & order Addl info was submitted to licensee on 800818 in response to 800722 memorandum & order MURPHY.P N Isham. Lincoln & Beale 80/09/03 2pp

- 5009110017 Second round of interrogatories & request for production of documents directed to util Requests inno re steps taken by PD Story when rilter was replaced & circumstances relocked-open value condition Certificate of Svc encl BURNES G Rulemaking & Enforcement Division 60/09/09 9pp
- B009260260 Response to CPC 800920 second round of interrogatories Explains seriousness of breach of containment integrity re protection of public & consequences of LOCA Identifyes penalty factors W/affidavit.resume & Certificate of Svc BRYAN.6 E Office of Inspection & Enforcement. Office of the Director 80/09/24 20pp
- J. Insurance & indemnity information
- 8009160292 Forwards executed Endommenent 55 to MELIA Policy NF-179 reflecting 307 shutdown credit for facility from 790909-800522
  - IRELAND, J H Consumers Power Co 80/09/15 2pp
- P Operating license stage documents & correspondence
- 8009110575 Forwards Amend 59 to provisional OL BPR-20, safety evaluation b notice of issuance & availability CRUICHFIELD D Operating Reactors Branch 5 80/07/29 Bpp
- --8007;10581 Amend 59 to provisional License BPR-20, deleting Tech Specs Table 4 12. Item 12-5 requirement for quarterly stroking of valves associated u/operation of safety injection & refueling tank level suitch interfocts CRUICHFIELD.D Operating Reactors Branch 5 80/07/29 App
- --8007110599 Safety evaluation supporting Amend 57 to provisional License DRR-20 • Operating Reactors Branch 5 80/07/29 3pp
- --8009110594 Notice of issuance & availability of Amend 59 to provisional License DPR-20 CRUTCHFIELD D Operating Reactors Branch 5 80/07/29 2pp
- 8009020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants.per ARC 800507 ltr Discusses administrative provisions for emergency & overtime work Bevelopmant & implementation to be reviewed within 90 days EISEMMUT.D G Division of Licensing 80/07/31 7pp
- S009080080 Forwards draft NUREO-0696. "Functional Criteria for Energency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 enci W/o NUREO EISENHUT, D G Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D.G. Division of Licensing 80/08/07 60pp
- 8009110746 Notification of 800916 meeting w/SEP owners group to discuss MRC initial review & recommendations for site-specific ground response spectra & owners group program plans for seismic functional qualification of Class IE equipment LEVIN.H A Division of Engineering 80/08/26 Ip
- 8009160430 Immediate action ltr resteam generator level indication Power level will not exceed 55% full power until matter is resolved Power operation will continue only while both availiary feed pumps are operable MEPPLER. J. G. Region 3. Chicago, Office of the Director 80/08/26
- 8009030430 Advises that util is committing to increasing strength of spacer grids supplied by Erzon Nuclear Co starting w/Reload J in late 1982 or early 1983 Cavity shield wall analysis rapt will be submitted by 801114 H
- B009040423 Notifies of procedural problem in complying w/NRC 800523 menorandum & order re electrical equipment qualification Emergency radiation assessment sys cannot involve IEEE 323-1974 Bast components consistent w/order will be used HOFFMAN, D.P. Consumers Power Co. 80/09/02 3pp
- 3009230769 Notification of 800903 meeting w/util in Bethesda.MD to discuss util arguments for lifting 55% power limit VILLALVA.! Office of Inspection & Enforcement. Office of the Director 80/09/02 2pp

- 8009290224 Immediate action ltr reaffirms discussions & agreements reached during 800903 meeting in Bethesda.MD re reactor power level, steam generator level indication auxiliary feedwater flour rates & water hammer KEPPLER.J 0 Region 3, Chicago, Office of the Director 80/09/04
- B009290143 Notification of B00926 meeting w/utils & Kerr-McGee Chemical Corp in Bethesda, MD to discuss review & recommendations for site specific ground response spectra & program plans for sessmic functional qualification of Class IE equipment ALLISON, D P Systematic Evaluation Program Branch 80/09/08 3pp
- 8009260022 Notification of second rescheduling until 801003 for meeting w/SEP owners group & KMC. Inc to discuss NRC initial review of site-specific ground response spectra & util program for seismic functional qualification of Class IE equipment ALLISON.D P Systematic Evaluation Program Branch 80/09/10 3pp
- 8007160500 Requests remittance of fee for 800425 request for relief from inservice pump testing requirements.per NRC 800724 ltr Fee due in 15 days MILLER.W O License Fee Management Branch 80/09/12 lp
- 8007230440 Advises that wide range steam generator level instrumentation will be installed during 1781 refueling outage as a result of evaluation requested in NUREG-0635. Item X & 3 3 4(c)
  FROST, S R Consumers Power Co 80/09/18 1p
- 8009230436 Responds to NRC 800611 & 0702 Tech Spec change requests providing for redundancy in decay heat removal capability & TMI Tech Spec changes Internal review & approval should be complete by 801103 Changes will be submitted after approval HOFFMAN, D P Consumers Power Co 80/09/19 ip
- 8007230458 Responds to NRC 800728 request for action plan to resolve questions re-seismic design of cable trays Response by RE Schaffstall of KMC. Inc on 800828 for SEP owners group constitutes util response
  HOFFMAN. D P Consumers Power Co 80/09/19 ip
- 8009290364 Forwards Class III fee payment per 10CFR170 22.in response to NRC 800912 request Amend fee applicable to updating inservice pump testing program to 1977 edition of ASME Boiler & Pressure Vassel Code Section XI M/o encl HOFFHAN.D P Gonsumers Power Co 80/09/23 2pp
- O Inspection reports, IE Bullatine & correspondence
- 8009030208 Forwards IE Insp Rept 50-255/80-10 during June & notice of deviation HEIBHMAN,R F Region 3. Chicago, Reactor Operations Nuclear Bupport Branch 80/07/17 2pp
- ---8009050211 Notice of deviation from inap during June.
  \* Region 3. Chicago, Office of the Director 80/07/17 ip
- --80070502i6 IE Insp Rept 50-255/80-10 during June Noncompliance noted failure to man control room w/two licensed personnel JORGENISEN, BL. HELLER-J K., BOYD, D C. Region G. Chicago, Office of the Director B0/07/17 7pp
- B009100132 Forwards IE Insp Rept 50-255/80-09 on 800624-25 & notice of violation
  HEISHKAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/07/21 2pp
- ---8009100134 Notice of violation from insp on 800624-25 \* Region 3, Chicago, Reactor Operations Nuclear Support Branch 50/07/18 ip
- --8009100140 IE Insp Rept 50-255/80-09 on 800624-25 Noncompliance noted failure to follow procedures for documentation & training BAKER, K R Region 3, Chicago, Reactor Operations Nuclear Support Branch SCHULZ,R D., SWANSON,E R Region 3, Chicago, Office of the Director 80/07/18 3pp
- 8009290109 Forwards IE Insp Rept 50-255/80-11 on 800722-24 No noncompliance noted HEISHMAN,R F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/08/11 2pp
- --8009290118 IE Insp Rept 50-255/80-11 on 800722-24 No noncompliance noted Hajor areas inspected core thermal power evaluation, reactivity measurement & critical boron concentration CHOULES,N C. CHOWLE T. Region 3, Chicago, Office of the Director STREETER.J F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/08/11 3pp

- 8009030229 Forwards Revision I to IE Bulletin 80-19, "Failures of Mercury-Wetted Matris Relays in Reactor Protective Sys of Operating Nuclear Power Plants Dosigned by C-E " Written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/08/15 1p
- 8009030115 Acv receipt of 800423 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-255/80-08
  HEISHMAN.R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/08/19 1p
- --B009030117 Responds to NRC 800701 ltr re violations noted in IE Insp Rept 50-253/80-08 Corrective actions shift supervisory personnel instructed to verify proper completion of turnover check sheets HOFFMAN.D P Consumers Power Co 80/07/23 3pp
- 8009300217 Forwards IE Insp Rept 50-255/80-13 during Jul 1980 & notice of violation HEISHMAN.R F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 80/08/19 2pp
- --8009300221 Notice of violation from insp during Jul 1780
  4 Region 3, Chicago, Office of the Director 80/08/18 in
- --8009300224 IE Insp Rept 90-255/80-i3 during Jul 1980 Noncompliance noted failure to adhere to administrative procedures for equipment control BGYD.D C . JUROENSEN.B L . HELLER, J K Region 3, Chicago, Office of the Director 80/08/18 7pp
- 8009110727 Ack receipt of 800808 ltr informing NRC of steps taken to correct violation noted in IE insp Rept 50-255/80-10 HEISHMAN.R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/08/20 lp
- --8009110730 Responds to NRC 800717 ltr re violations noted in IE lnsp Rept 50-255/80-10 Corrective actions standing orders to maintain two operators in control room issued HOFFMAN.D P Consumers Power Co 80/08/08 ip
- B009170415 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER.J O Region 3, Chicago, Office of the Director 80/08/22
- 8009020242 Requests extension to 800923 for response to deficiency noted in IE Insp Rept 50-285/80-09 HDFFMAN D P Consumers Power Co 80/08/25 ip
- 8009030624 Forwards final inservice insp rept covering 790908-800528 HOFFMAN, D.P. Consumers Power Co. 80/08/27 ip
- --8009030627 Final inservice insp rept covering 790908-800528 Includes data submitted by Southwest Research Institute MARTIN.8 E . CHERBA.R B . ADAMS.A. Consumers Power Co 80/08/18 5000
- 8007230073 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers "
  No written response required 
  KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/28, to
- 8009090548 Responds to IE Bulletin 80-15 Emergency notification sys powered from instrument bus Y-Oi, Breaker 42, from affects power & is automatically powered by 1-1 generator upon loss of offsite power FROST, 8 R Consumers Power Co 80/09/04 4pp
- 8009240096 Forwards IE Circular 80-21, "Regulation of Refueling Crews "
  No written response required
  KEPPLER, J. O Region 3, Chicago, Office of the Director 80/09/10
  ip
- 8009290160 Discusses IE insp on 800729 & forwards notice of violation & notice of proposed imposition of civil penalty STELLO.V Office of Inspection & Enforcement, Office of the Director 80/09/16 3pp
- --8009290162 Notice of violation from insp on 800729 Noncompliance noted plant operated at high power w/two high pressure safety injection pumps & one low pressure pump inoperable & Office of Inspection & Enforcement, Office of the Director BO/09/16 2pp

- --B009270164 Notice of proposed imposition of civil penalty for item of noncompliance noted in IE insp or 800727

  4 Office of Inspection & Enforcement, Office of the Director 80/09/16 ip
- R Periodic operating reports & related correspondence
- 8009120457 Forwards monthly operating rept for Aug 1980 KENNEDY, D M. Consumers Power Co. B0/09/05 ip
- --8009120462 Monthly operating rept for Aug 1980 BODTKE,P J Consumers Power Co 80/09/08 3pp
- BOO9160370 Bimonthly status rept for Aug-Bept 1780 Bechtel Corp is preparing final design details for long-term cooling mods Mods scheduled for 1981 outage MOFPMAN.D P Consumers Power Co 80/09/12 ip
- 8009230512 Forwards addition & corrections to summary of radioactive affilients released from facility during 1970 DICKSON.M O Consumers Power Co 80/07/17 5pp
- S Reportable occurrences. LERs & related correspondence
- 8007020132 Ack receipt of 800731 telcon re-corrective actions taken as result of 800726 & 27 event involving ECCS containment sump suction valve CV-3030 Discusses NRC understanding of corrective actions Immediate action Itr
  KEPPLER, J O Region 3. Chicago, Office of the Director 80/07/31
- 8009030583 Forwards LER 80-027/017-0 HDFFMAN, D.P. Consumers Power Co. 80/08/27 ip
- --8009030594 LER 80-027/01T-0 on 900812, during venting of quench tank to waste gas surge tank, unplanned gaseous release occurred w/o min holdup Caused by broken pin which held diaphragm to operating shaft Pin replaced of Consumers Power Co 80/08/27 ip
- 8007080404 Forwards LER 80-027/017-0 HOFFMAN, D P Consumers Power Co 80/09/02 1p
- --R009080414 LER 80-029/01f-0 on 800819, during normal operation, CV-3031 was stroked closed & immediately reopened Caused by failure to follow procedural requirements related to plant conditions needed to parform test # Consumers Power Co 80/09/02 ip
- 8009080418 Forwards LER 80-028/03L-0 HOFFMAN, D.P. Consumers Power Co. 80/09/02 1p
- --8009080426 LER 80-028/03L-0 on 800807, during normal power operations.

  Tow level alarm received from switch on SI tank A (T 82 A)

  Apparently caused by slow leakage from tank Inaccuracy of analog channel attributed to liquid loss in ref leg

  \* Consumers Power Co 80/09/02 ip
- 8007080432 Forwards updated LER 80-023/03x-1 HDFFMAN.D P Consumers Power Co 80/09/02 1p
- ---8009080437 Updated LER 80-023/03X-1, on 800710, containment high radiation detectors RE 1805 & 1807 determined inoperable No apparent cause for failure Detectors disassembled, cleaned & recoated & are now functional

  + Consumers Power Co. 80/09/02 ip
- 8009120384 Forwards LER 80-030/03L-0 HOFFMAN, D.P. Consumers Power Co. 80/09/08 1p
- --8009120388 LER 80-030/03L-0 on 800811 during normal operation, discovered indicating lamps for CV-04378 b CV-04388 (indine removal sys tanks outlet valves) were not lit Caused by moisture in junction box resulting in blown fuses 4 Consumers Power Co. 80/09/08 1p
- BO09190565 EN-80-040 on 800916, notice of violation & notice of proposed imposition of civil penalties will be issued to licenses, based upon alleged items of noncompliance re operation of reactor plant sys

  BROCKETT, T W , THOMPSON D Office of Inspection & Enforcement, Office of the Director 80/09/12 | Ip
- 8009220285 Forwards NPDES noncompliance notification re turbine sump oil separator waste HOFFMAN D P Consumers Power Co BQ/09/16 la

```
--8009220289 NPDES noncompliance notification on 800816.weekly grab sample indicated 27 3 mg/l oil & grease Caused by oil separator sys ineffectively removing component oil in floor drains Oil absorbent pads will be placed throughout plant FOBES.R L Consumers Power Co 80/09/09 lp
 8009230612 Forwards updated LER 80-027/01Y-1
HOFFMAN,D P Consumers Power Co 80/09/1
                                                                                            90/09/17 in
 --8009230618 Updated LER 80-027/01X-1 on 800812 during venting of quench tank to waste gas surge tank gaseous release occurred w/o 15 day min holdup Caused by leaking isolation valve & valve pin disassenbly Pin replaced + Consumers Power Go 80/09/17 ip
 8009240488 Forwards LERs 80-031/017-0 & 80-032/03L-0 FROST, S R Consumers Power Co 80/09/23 1s
 --8009260492 LER 80-031/01T-0 on 800826, group 1 control rads withdrew 121 inches which resulted in unplanned reactivity insertion Caused by loss of both primary & secondary data loggers Laggers restored & control rods reinserted + Consumers Power Co 80/09/23 1p
 --8009260496 LER 80-032/03L-0 on 800826.primary data logger ceased
performing control rod scans & secondary data logger typer
became stuck Cause unknown Failure corrected by resetting
4 Consumers Power Co 80/09/23 Ip
 8009300484 Forwards LER 80+033/01T-0
HGFFMAN, D Consumers Power Co 80/09/25 1p
 --8007300487 LER 80-033/01T-0 on 800911 during control rod exercising.Rod
31 was misaligned Caused by rod insertion length Procedures
revised to lessen insertion & remain within Tech Spec
           requirements
HOFFMAN, D.P. Consumers Power Co. 80/09/25 1p
           HOFFMAN, D. P.
 8009300492 Forwards EER 80-034/03L-0
HOFFMAN, D P Consumers Power Co
                                                                                              80/09/26 1p
 --8009300499 LER 80-034/03L-0 on 800826.during pretest review of check
          valve inservice insp survaillance, procedures required closing & reopening of SIRW tank outlet valves Caused by inadequate procedures Procedures revised ROFFMAN, D P Consumers Power Co 80/07/26 ip
 DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1
 F Security, medical, emergency & fire protection plans
 8009120121 Forwards request for addl info re guard training & qualification Enci withheld (ref 100FR2 790) IFPOLITO, TA Operating Reactors Branch 2 80/08/22 2pp
 8009230267 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for goot use during emergency of the Director 80/08/22
8009250272 Discusses util 800509 response re responsibility matrix of safeguards contingency plan, including interrelationships of contingency actions NRC cannot give formal approval until info is specifically submitted for approval PPDLITO, T A Operating Reactors Branch 2 80/09/09 2pp
 G Adjudicatory correspondence
8009220018 Forwards order requiring into supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 IPPOLITO.T A Operating Reactors Branch 2 80/08/29 2pp
--8009220019 Order for mod of Licenses DPR-33, DPR-52 & DPR-68 to add info
which fully responds to NRC request for info re environ
qualification of safety-related electrical equipment Info
should be submitted by 800101
EISENHUT, D 0 Division of Licensing 80/08/29 App
```

8009300316 Responds to 800808 ltr to JF Abearne re cheating on NRC OL exams while employed at facilities Allegation to be subj of inquiry headed by B Marsh
STELLOV Office of Inspection & Enforcement, Office of the Director 80/09/19 ip

H General correspondence

```
--- 8009300322 Alleges cheating on NRC GL exams at facility Ltr to HJ Green
           offering to expose cheating encl
SMITH, G Affiliation Unknown $
                                                                                     .
.80/08/08 3no
 --B009300325 Guestions safety design of facilities
SMITH O Affiliation Unknown 80/09/24 lp
 --8009300327 Informs of unreported RO at facility re high radiation in
            offgas sys
SMITH,O Affiliation Unknown 80/09/24 ip
 I Financial information
8009090543 Forwards Annual Financial Rept 1979
CRDSS,J L Tennessee Valley Authority 80/09/04 ip
 --8009090563 Annual Financial Rept 1979
* Tennessee Valley Authority 80/09/04 44pp
 P Operating license stage documents & correspondence
8007110554 Suppls NRC 800707 request for proposed Tech Specs changes re
scram discharge vol vent 3 drain valves. & reactor
protection sys & control rod block limit switch surveillance
requirements Class III license fee to be submitted w/change
EISENHUT.D G Division of Licensing 80/07/22 22pp
8009020277 Submits interim criteria for shift staffing to all DL & CP licensees & applicants, per NRC 800507 ltr Discussee administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D & Division of Licensing 80/07/31 7pp
 8009080080 Forwards draft NUREG-0696. "Functional Criteria for
     NOVOROUSE Formards great NURGE-0090. "FUNCTIONAL Criteria 
Emergency Response Facilities "Comments requested within: 
days Proposed implementation schedule for meeting criteria 
of NUREO-0676 encl M/o NUREO 
EISENHUTJD 0 Division of Licensing 80/08/01 119pp
8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lossons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D Q Division of Licensing 80/08/07 60pp
8009020318 Submits schedule for first 5 months of interim reliability evaluation program, annotated to highlight patential NRC participation Anticipated start date scheduled for 800915 EISENHUT, D O Division of Licensing 80/08/15 4pp
8009030406 Application to amend Licenses DPR-33, DPR-52 & DPR-68, changing Tech Specs re containment sys MILLS, L M Tennessee Valley Authority 80/08/19 2pp
--8009030411 Proposed Tech Specs 3 7 & 4 7 re limiting conditions for operation & surveillance requirements for containment sys

* Tennessee Valley Authority 80/08/19 47pp
8007190697 Forwards NUREO-D661, "Mark I Containment Long-Term Program SER Resolution of Generic Technical Activity A-7 " Rept discusses generic suppression pool hydrodynamic load definition H/o encl IPPOLITO.T A Operating Reactors Branch 2 80/08/20 2pp
8007070367 Forwards response to NRC 800425 ltr requesting that util confirm conclusions of analysis re min ECCS equipment availability w/dc gower supply failure CRDS8.J L Tennessee Valley Authority 80/07/03 2pp
8009090555 Forwards corrected page to proposed Tech Specs 3 7 & 4 7 re
containment sys integrated leak testing, originally submitted
      an 800819
      CROSS, J.L. Tennessee Valley Authority 80/09/03
---8007070560 Corrected page to proposed Tech Specs 3 7 & 4 7 re
containment sys integrated leak testing, originally submitted
                 Tennessee Valley Authority 80/07/03 ip
8009160219 Forwards changes to Tech Specs Section & O for OL amend re
administrative controls, in response to NRC 800702 ltr to all
BWR licensees Changes are based on model specs provided in
Encl I to ltr Fee encl
MILLS.L M Tennessee Valley Authority 80/09/09 2pp
```

- ---8009160221 Proposed changes to Tech Spec Section 6 O re administrative controls based on model specs in NRC 800702 ltr to all BWR licensees
  - Tennessee Valley Authority 80/09/09 9pp
- BOO9170206 Forwards comments re extent of util participation in interim reliability evaluation program Phase II study, in response to D9 Eisenhut 800725 itr to H0 Parris Decision on util performance of risk assessment will be made by mid-Oct 1980 MiLLS.L M Tennessee Valley Authority 80/09/09 3pp
- 8009240545 Ack receipt of response to NRC 791109 questions re ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture Response is acceptable IPPOLITO.T A Operating Reactors Branch 2 80/09/10 2pp
- BOO9240601 Confirms util commitment to NRC 791023 "Interim Position on Containment Purging & Venting Pending Resolution of Isolation Valve Operability "Util position will remain in effect pending completion of NRC long-term review IPPOLITO.T A Operating Reactors Branch 2 80/09/10 2pp
- 8009220210 Notifies that 800731 application to amend Licenses DPR-33. DPR-52 & DPR-68 has not yet appeared as FR notice Info requested re schedula for licensing & FR notice publication MILLS, L M Tennessee Valley Authority 80/09/16 2pp
- BOOG190488 Application to amend Licenses DPR-33 & DPR-52 Forwards proposed Tech Spec changes clarifying requirements for RHR sxc water sys & adding spec which allows standby coolant capability to be inoperable for specified period MILLS, L M Tennessee Valley Authority 80/09/17 2pp
- ---8009190495 Proposed changes to Tech Bpecs clarifying requirements for RHR syc water sys & adding spec which allows standby coolant capability to be inoperable for period not to exceed 10 days \* Tennessee Valley Authority 80/09/17 10pp
- 8009300400 Forwards technical questions re implementation of interim policy on 10CFR50 & 51 MILLS,L M Tennessee Valley Authority 80/09/23 3pp
- 8009300147 Requests amend to DPR-33.DPR-52 & DPR-68.consisting of Tech Spec changes re reactor protection sys MILLS.L M Tennessee Valley Authority 80/09/24 2pp
- --B009300156 Proposed Tech Specs 1 0.3 3 & 4 3 re reactor protection sys 4 Tennessee Valley Authority B0/09/24 15pp
- 8009300353 Revises util 791106 schedule for shipment of motor generator sets to be installed as part of LPCI sys power supply mods Generator sets will be installed during Fall 1980 Unit 3. Spring 1981 Unit 1 & Spring 1982 Unit 2 outages MILLB.L H Tennessee Valley Authority 80/09/24 ip
- G Inspection reports. IE Bulletins & correspondence
- 8009090073 Forwards IE Bulletin 80-07. Suppl 1, "BWR Jet Pump Assembly Failure" No response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/13
- BO09020184 Submits response to IE Bulletin 77-03A No SA-312 or A-312. Type 300 series fusion welded pipe is in use or planned for use in safety-related sys MILLS.L M Tennessee Valley Authority B0/08/06 ip
- 8007020222 Forwards IE Insp Repts 50-259/80-32,50-260/80-25 \$
  50-276/80-26 on 800628-0704 No noncompliance noted
  O'REILLY,J.P Region 2, Atlanta, Office of the Director 80/08/08
- --8009020225 IE Insp Repts 50-259/80-32,50-260/80-25 & 50-296/80-26 .09020225 IE Insp Repts 50-259/80-32,50-260/80-25 & 50-296/80-26 on 800828-0704 No noncompliance noted Major areas inspected licensee investigation of Unit 3 failure to fully insert control rods after 800628 scam
  DANCE-H.C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/08/08 18pp
- 8009030146 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P. Region 2, Atlanta, Office of the Director 80/0 Region 2. Atlanta, Office of the Director 80/08/15

- 8009020133 Forwards response to IE Bulletin 80-17. Suppl 1 re failure of control rods to insert during scram at BHR Item B 1 scram discharge header sys will be modified to preclude necessity of level monitoring w/exception of instrument vol KILLS.L M Tennessee Valley Authority 80/08/18 2pp
- 8009160045 Forwards IE Info Notice 80-30. "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE BWR Facilities "No respectfic action or response requested

  O'REILLY, J P Region 2. Atlanta, Office of the Director BO/08/19
- 8009190603 Ack receipt of 800815 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/80-22. 50-269/80-16 & 50-296/80-17 "ENNA.W B Region 2. Atlanta, Safeguards Branch 80/08/21 1p
- --8009190610 Forwards response to NRC 800717 ltr re violations noted in IE Insp Repts 50-259/80-22.50-260/80-16 & 50-296/80-17 Encl uithheld (ref 10CFR2 790) MILLS,L M Tennessee Valley Authority 80/08/15 ip
- --8009190617 Ack receipt of 800710 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/80-22, 50-260/80-16 & 50-296/80-17 Notes commitment to provide addi response within 20 days KENNA,N B Region 2. Atlanta, Safeguards Branch 80/07/17 ip
- --8009190643 Forwards response to NRC 800616 ltr re violations noted in IE Insp Repts 50-259/80-22.50-260/80-16 & 50-276/80-17 Encl withheld (ref 10CFR2 790)
  MILLS,L M Tennessee Valley Authority 80/07/10 ip
- --8009190646 Forwards IE Insp Repts 50-259/80-22,50-260/80-16 & 50-296/80-17 on 800519-23 & notice of violation Notice of violation withheld (ref 10CFR2 790) KENNA, W B Region 2, Atlanta, Safeguards Branch 80/06/16 2pp
- --8009190451 LE Insg Repts 50-259/80-22,50-240/80-16 \$ 50-294/80-17 on 100119031 It. Insp. Repts 50-20740-22.50-20760-16 of 30-216760-20 ROOS19-23 Noncompliance noted incomplete vital area barrier, inadequate lock installation by absence of portable radio in vehicle escort Details withheld (ref 10CFR2 790) TILLMAN, A. TOBIN, W.J., OILLESPIE, F.P. Region 2, Atlanta, of the Director 80/06/16 ip Region 2. Atlanta, Office
- 8009120082 Forwards Suppl 3 to IE Bulletin 80-17. "Failure of Control Rods to Insert During Scram at BWR" Written response required G'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/08/22
- 8009160153 Forwards IE Circular 80-18 "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required D'REILLY, J P Region 2, Atlanta, Orfice of the Director 80/08/22
- 8009250075 Responds to 1E Bulletin 80-14. "Degradation of BWR Scram Discharge Vol Capability " Corrects error in 800728 response re Item A 1 One instance of broken rod on ball float also occurred MILLS, L M Tennessee Valley Authority 80/08/26 ip
- 8009120340 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/27
- 8007180068 Submits response to IE Bulletin 80-17 No mercury-wetted matrix relays are in use in reactor protection sys MILLS.L. K Tennessee Valley Authority 80/08/27
- 8009180087 Bubmits response to IE Bulletin 80-19 No mercury-wetted matrix relays are in use in reactor protection sys MILLS-L M Tennesses Valley Authority 80/08/29
- 8009230921 Forwards Revision 1 to IE Bulletin 79-26, "Boron Loss From BWX Control Blades " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/29
- 8009240261 Forwards response to IE Bulletin 80°17 re failure of control rods to fully insert during scram at BWR Plant instructions changed on 800827 to provide for manual scram & functional test Thisty-file manhours expended in bulletin review MILLS,L M Tennessee Valley Authority 80/08/27 3pp

- 8009240383 Forwards response to IE Bulletin 80-15 re possible loss of emergency notification sys w/loss of off-site power Design change request submitted Administrative procedure issued to comply w/requirements
  HILLS.L K Fennessee Valley Authority 80/08/29 4pp
- 8007240446 Forwards response to IE Bulletin 80-17 re failure of control rods to fully insert during scram at BWR Vent mod being coordinated w/overall scram discharge header sys review & mod program Schedule estimates will be provided MILLS.L M Tennesses Vailey Authority 80/08/27 3pp
- 8009260375 Forwards IE Circular 80-21. "Regulation of Refueling Crews"
  No written response required
  O'REILLY. J P Region 2. Atlanta. Office of the Director 80/09/10
  Sno
- 8009300529 Forwards Progress Rept 4 for IE Bulletin 80-06 re engineered safety features reset controls Mtt.LS.L M Temessee Valley Authority 80/09/10 7pp
- B009300060 Ack receipt of B00819 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-259/80-24, 50-2&3/80-18 & 50-294/80-19 LEWIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/09/(1 1g
- ---8009300057 Forwards response to NRC 800724 ltr re violation noted in IE Insp Repts 50-259/80-24,50-260/80-18 & 50-296/80-19 Corrective actions outdated surveillance instruction sheets replaced w/current revisions MILLS.L M Tennessee Valley Authority 80/08/19 2pp
- --8009300072 Forwards IE Insp Repts 50-259/80-24.50-260/80-18 & 50-294/80-19 on 800503-0601 & notice of violation LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclea: Support Branch. 80/07/24 2pg
- --8009300075 Natice of violation from insp on 800503-0401 \* Region 2. Atlanta, Reactor Operations Nucleas Support Branch 89/07/15 ip
- --800930008t IE Insp Repts 50-259/80-24,50-260/80-18 & 50-296/80-19 on 800503-0601 Noncompliance noted failure to use latest revision of surveillance instruction data sheet SULLIVAN.R F. CHASE.J W. Region 2. Atlanta. Office of the Director DANGE.H C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/07/15 7pp
- R Persodic operating reports & related correspondence
- 8009110352 Forwards "Radiological Impact Assessment, Browns Ferry Nuclear Plant-Jan-June 1980 " MILLS.L M Tennessee Valley Authority 80/08/29 1p
- --8009110353 "Radiological Impact Assessment Browns Ferry Nuclear Plant. Jan-June 1980" 4 Tennessee Valley Authority RH-80-5-8F-3 80/08/29 44pp
- BOO9170274 Forwards monthly operating repts for Aug 1980 ABERCROMBIE.H Tebnessee Valley Authority B0/09/17 ip
- --8009170277 Monthly operating repts for Aug 1980 ABERCROMBIE, H., THOM, T., GREEN, D. Yennessee Valley Authority 80/09/01 30pp
- S Reportable occurrences. LERs & related correspondence
- 8009190765 PND-78-147 on 780818, one of six air compressors experienced massive failure resulting in rapid loss of control air pressure to all units Caused by large hole in cylinder head State of AL notified Media attention anticipated KLINGER.O . NDLAN.F . SMIETEK. J Office of Inspection & Enforcement, Office of the Director 78/08/18 Ip
- BOO9190753 Provides interim assessment of PNO-78-147 re partial failure to scram event Margin of safety inherent in licensed design basis should be promptly restored Improved temporary measure acceptable pending permanent mods MICHELSON, C Director's Office 80/08/18 3pp
- 9009030488 Forwards LER 80~058/03L-0 CALHOUN, J R Tennessee Valley Authority 80/08/28 1p

- --9009030496 LER 80-058/03L-0 on 800728 during normal operation while performing SI 4 1 A-14 pressure switches PS-1-81A & 8, turbine first stage pressure permissive, setpoints found set above Tech Spec I limit Caused by instrument drift \* Tennessee Valley Authority 80/08/28 2pp
- 8009030558 Forwards LER 80-057/03L-0 CALHOUN, J R Tennessee Valley Authority 80/08/30 1p
- --9009030566 LER 80-057/03L-0 on 800730, during past two refueling outages, required Tech Spec 4 6 6 6 testing was not performed Caused by testing not being identified as outage work item Insp wiil be completed at next refueling outage \* Tennessee Valley Authority 80/08/27 2pp
- 8009090557 Forwards LER 80-059/03L-0 CALHOUN J R Tennessee Valley Authority 80/09/04 1p
- --B007090565 LER 80-059/03L-0 on 800810, during normal operation, lightning caused Athens 161 kV line to trip momentarily Cooling tower transformer tripped causing loss of 4 kV tie board Cause of transformer trip unknown Athens line re-energized

  \* Tennessee Valley Authority 80/09/04 2pp
- 8009190445 Forwards LER 80-060/03L-0 CALHOUN,J R Tennessee Valley Authority 80/09/12 1p
- --8009190524 LER 80-060/OGL-O on 800814 during normal operation,8 core spray pump area cooler fan thermostat T8-64-73 setting was above Tech Spec limit, Caused by setpoint being moved Thermostat reset Caution signs posted to prevent recurrence Tennessee Valley Authority 80/09/12 ip
- 8009190467 Forwards LER 80-061/03L-0 CALHOUN, J R Tennessee Velley Authority 80/09/12 ip
- ~-8009190819 LER 80-061/03L-0 on 800814.during normal operation, thermal overload on 1A residual heat removal area cooler fan breaker tripped Caused by thermal overload being improperly set Overload reset & properly adjusted a Tennessae Valley Authority 80/09/12 2pp
- 8009230705 Forwards LER 80-063/03L-0 CALHOUN, J R Tennessee Valley Authority 80/09/16 ip
- --9009230714 LER 80-063/03L-0 on 800820, during normal operation, CAM-1~RH-90-251 for turbine bldg roof vent removed from svc for period exceeding 1-h due to failure of Schwitzer Series 325 Model 145473 vacuum pump Pump replaced \* Tennessee Valley Authority 80/09/16 2pp
- 8009180400 LER 79-010 has been cancelled \* Tennesses Valley Authority 80/09/17, ip
- 8009180402 LER 79-014 has been cancelled \* Tannessee Valley Authority 80/09/17 ip
- 8009230716 Forwards LER 80-064/03L-0 CALHOUN, J R Tennessee Valley Authority 80/09/17 ip
- ~-8009230728 LER 80-064/03L-0 on 800B20, during normal operation, CAM-1-RM-90-249 for turbing bldg roof vents removed from syc for period exceeding 1-h Caused by personnel error Personnel cautioned to observe time limit

  \* Tennessee Valley Authority 80/09/17 2pp
- 8009290345 Forwards LER 80-065/03L-0 CALHOUN, J.R. Tennesses Valley Authority 80/09/22 ip
- --8009290347 LER 80-065/03L-0 on 800828, during normal operation, wind direction indication was lost at elevation 887 min/sec Limiting condition for operation was entered Caused by noisy potentiometer Potentioneter was replaced

  \* Tennesses Valley Authority 80/09/22 2pp
- 8009300562 Forwards LER 80-068/01T-0 CALHQUN.J R Tennessee Valley Authority 80/09/22. 1p
- ~-8009300567 LER 80-068/01T-0 on 800901, fire protection sys insp not performed as required by Tach Spec Caused by failure to obtain consultant sycs within specified time interval, Insp to be performed at earliest possible date CALHOUN, J.R. Tennessee Valley Authority 80/09/22 ip
- 8009300516 Forwards LER 80-069/03L-0 CALHOUN, J. R Tennessee Valley Authority 80/09/26 1p

- --8009300521 LER 80-069/03L-0 on 800902. while performing SI 4 2 A-17, Channel B of refueling ione isolation static pressure permissive & static pressure logic sys damper O-PDC64-8 failed to close Contacts adjusted

  \* Fennessee Valley Authority 80/09/26 2pp
- DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8009120121 Forwards request for add1 info re guard training & qualification Enc1 withheld (ref 100FR2 790)
  1PPOLITO,T A Operating Reactors Branch 2 80/08/22 2pp
- BO09230267 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency 0'RETILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22
- 8009250272 Discusses util 800509 response re responsibility matrix of safeguards contingency plan, including interrelationships of contingency actions NRC cannot give formal approval until info is specifically submitted for approval IPPDLITO,T A Operating Reactors Branch 2 80/09/09 2pp

### Q Adjudicatory correspondence

- BO07220018 Forwards order requiring info supporting environ qualification of safety-related electrical aquipment Requests submittal of info by BO1101 [PFOLITO, T A Operating Reactors Branch 2 B0/08/29 2pp
- --8009220019 Order for mod of Licenses DPR-33, DPR-52 & DPR-68 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 80101
  EISENHUT, D 0 Division of Licensing 80/08/29 App

## H General correspondence

- B009300316 Responds to 800808 ltr to JF Ahearns re cheating on NRC OL same while employed at facilities Allegation to be subj of inquiry headed by B Marsh STELLO.V Office of Inspection & Enforcement, Office of the Director 80/09/19 lp
- --8009300322 Alleges cheating on NRC OL exams at facility Ltr to HJ Green offering to expose cheating encl BMITH, O Affiliation Unknown BO/08/OB 3pp
- --- 8009300325 Questions safety design of facilities SMITH. 0 Affiliation Unknown 80/09/24 ip
- --8009300327 Informs of unreported RD at facility re high radiation in offgas sys. SMITH, G Affiliation Unknown 80/09/24 ip

# f Financial information

- 8009090543 Forwards Annual Financial Rept 1979 80/09/04 1p Tennesses Valley Authority
- --8009090563 Annual Financial Rept 1979 Tennessee Valley Authority BO/09/04 44pp
- P Operating license stage documents & correspondence
- B009ii0554 Suppls NRC B00707 request for proposed Tech Specs changes re scram discharge vol vent & drain valves, & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT.D Q Division of Licensing 80/07/22 22pp
- 8009020297 Bubmits interim criteria for shift staffing to all DL & CP licensess & applicants, per NRC 800507 ltm Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D 9 Division of Licensing 80/07/31 7pp
- 90090B00B0 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/o NUREO EISERHUT, D O Division of Licensing 80/08/01 119pp

- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D G Division of Licensing 80/08/07 60pp
- 8009030406 Application to amend Licenses DPR-33.DPR-52 & DPR-68. changing Tech Specs re containment sys MELLS.L M Tennessee Valley Authority 80/08/19 2pp
- --8009030411 Proposed Tech Specs 3 7 & 4 7 re limiting conditions for operation & surveillance requirements for containment sys \*\* Tennessee Valley Authority 80/08/19 47pp
- 8009190697 Forwards NUREG-0661, "Mark I Containment Long-Term Program SER Resolution of Generic Technical Activity A-7 " Rept discusses generic suppression pool hydrodynamic load definition W/o encl IPPOLITO.T A Operating Reactors Branch 2 80/08/20 2pp
- 8009030508 Application for amend to License DPR-52, changing Tech Specs to reflect new primary containment atmospheric hydrogen instrumentation to be installed during upcoming refueling outage Changes suppl 800714 changes MILLS,L M Tennessee Valley Authority 80/08/29 2pp
- --8009030514 Proposed Tech Specs 3 7.4 7 & Table 3 2 F re containment sys Description of primary containment hydrogen monitoring sys encl
  - Tennesses Valley Authority 80/08/29 5pp
- B009090367 Forwards response to NRC 800425 ltr requesting that util confirm conclusions of analysis re min ECCS equipment availability w/dc power supply failure CROSS.J L Tennessee Valley Authority B0/09/03 2pp
- 8009090555 Forwards corrected page to proposed Tech Specs 3 7 % 4 7 re containment sys integrated leak testing, originally submitted on 800819 on 800819 CROSS.J.L. Tennessee Valley Authority 80/09/03 3pp
- --8009090960 Corrected page to proposed Tech Specs 3 7 & 4 7 recontainment sys integrated leak testing originally submitted on 800819
  - Tennessee Valley Authority BO/09/03 ip
- 8009140219 Forwards changes to Tech Specs Section & O for OL, amend re administrative controls in response to NRC 800702 ltr to all BYR licensees Changes are based on model specs provided in Encl i to ltr Fee encl MILLS.L
- ---8009160221 Proposed changes to Tech Spec Section 6 0 re administrative controls based on model specs in NRC 800702 ltr to all BUR
  - Tennessee Valley Authority 80/09/09 9pp
- 8007240545 Ack receipt of response to NRC 791107 questions re ECCS evaluation models dealing w/fuel cladding.swelling & incidence of rupture Response is acceptable IPPOLITO.T A Operating Reactors Branch 2 80/09/10 2pp
- 8009240501 Confirms util commitment to NRC 791023 "Interim Position on POYAYOUI CONTINA UTI COMMITMENT TO NEW 791023 "Interim Po Containment Purging & Venting Pending Resolution of Isolation Valve Operability " Util position will remain in effect pending completion of NRC long-term review IPPQLITG.T A Operating Reactors Branch 2 80/09/10 2pp
- 8009220210 Notifies that 800731 application to amend Licenses DPR-33, DPR-52 & DPR-68 has not yet appeared as FR notice Info requested re schedule for licensing & FR notice publication MILLS, L M Tennessee Valley Authority 80/09/16 2pp
- 8009190488 Application to amend Licenses DPR-33 & DPR-52 Forwards proposed Tech Spec changes clarifying requirements for RHR svc water sys & adding spec which allows standby coolant capability to be inoperable for specified period MILLS.L M Tennessee Valley Authority 80/09/17 2pp
- --B009190495 Proposed changes to Tech Specs clarifying requirements for RHR svc water sys & adding spec which allows standby coolant capability to be inoperable for period not to exceed 10 days \* Tennessee Valley Authority 80/09/17 10pp
- 8009300400 Forwards technical questions re implementation of interim policy on 10CFR50 t 51
  MILLS.L M Tennessee Valley Authority 80/09/23 3pp

- 8009300147 Requests amend to DPR-33.DPR-52 % DPR-68.consisting of Tech Spec changes re reactor protection sys MILLS, LM Tennessee Valley Authority 80/09/24 2pp
- --8009300156 Proposed Tech Specs 1 0.3 3 & 4 3 re reactor protection sys \*\* Temposee Valley Authority 80/07/24 15pp
- 8009300353 Revises util 791106 schedule for shipment of motor generator sets to be installed as part of LPCI sys power supply mods Generator sets will be installed during Fall 1980 Unit 3, Spring 1981 Unit 1 S. Spring 1982 Unit 2 outages
  MILLS,L M Tennossee Valley Authority 80709724 1p
- Q Inspection reports, IE Bulletins & correspondence
- 8009090073 Forwards IE Builetin 80-07, Suppl 1, "SWR Jet Pump Assembly Failure" No response required
  O'REILLY.J P Region 2, Atlanta, Office of the Director 80/05/13 lp
- 8007020184 Submits response to IE Bullatin 79-03A No SA-312 or A-312. Type 300 series fusion welded pipe is in use or planned for use in saraty-related sys MILLS, L M Tennessee Valley Authority 80/08/06 ip
- 8009020222 Forwards IE Insp Repts 50-259/80-32,50-260/80-25 & 50-276/80-26 on 800628-0704 No noncompliance noted O'REILLY, J P Region 2, Atlanta, Défice of the Birector 80/08/08 2pp
- ~~8009020225 [E Insp Repts 50~259/80~32.50~260/80~29 & 50~296/80~26 on 800628~0704 No noncompliance noted Najor areas inspected litensee investigation of Unit 3 Failure to fully insert control rods after 800628 scam
  DANCE.H C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/08/08 18pp
- 8009030146 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Natrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Mritben response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/15 in
- 8009020133 Forwards response to IE Bulletin 80-17. Suppl 1 re failure of control rods to insert during scram at BWR I tem B 1 scram discharge header sys will be modified to practude necessity of level monitoring whenception of instrument vol MILLS.L K Tennessee Valley Authority 80/08/18 2pp
- B00916C045 Forwards IE Info Notice 80-30. "Potential for Unacceptable Interaction Between Control Rod Drive Scram Furction & Nonessential Control Air at Certain GE BUR Facilities " No specific action or response requested O'REILLY.J P Region 2. Atlanta. Office of the Director B0/08/19
- 8009190603 Ack receipt of 800815 ltr informing NRC of steps taken to correct violations noted in 16 Insp Repts 50-259/80-22, 50-260/80-16 & 50-296/80-17 KENNA,W 3 Region 2. Atlanta. Safeguards Branch 80/08/21 1p
- --8009190610 Forwards response to NRC 800717 ltr re violations noted in IE Insp Repts 50-259/80-22,50-260/80-16 & 50-296/80-17 Encl uithheld (ref 10CFR2 790) MRLLS.L M Tennessee Valley Authority 80/08/15 ip
- --B009190617 Ack receipt of B00710 ltr informing NRC of steps taken to correct violations noted in JE Insp Repts 50-259/80-22, 50-260/80-16 & 50-296/80-17 Nates commitment to provide additections within 20 days KENNA.N B Region 2. Atlanta, Safeguards Branch 80/07/17 ip
- --8009190643 Forwards response to NRC 800616 ltr re violations noted in IE Insp Repts 50-289/80-22,50-260/80-16 \$ 50-296/80-17 Encl withheld (ref 100FR2 790) MILLS.L. M Tennessee Valley Authority 80/07/10 [p
- -8009190646 Forwards IE Insp Repts 50-259/80-22,50-260/80-16 & 50-296/80-17 on 800519-23 & notice of violation Notice of violation withheld (ref 10CFRZ 790)
  KENNA.H B Region 2. Atlanta, Safeguards Branch 80/06/16 2pp
- 8009190651 IE Insp Repts 50-259/80-22,50-260/80-16 & 50-296/80-17 on B00319-23 Noncompliance noted incomplete vital area barrier, inadequate lock installation & absence of portable radio in vehicle escort Details withheld (ref 10CFR2 790) FILLMAN, A. TOBIN.W J. GILLESPIE.F P Region 2, Atlanta, Office of the Director 80/06/16 (p

- 8009120082 Forwards Suppl 3 to IE Builetin 80-17, "Failure of Control Rods to Insert During Scram at 84R" Written response required 0'REILEV.J.P. Region 2. Atlanta, Office of the Director 80/08/22
- O'REILLY, J.P. Region 2. Atlanta. Office of the Director 60/09/22
- 8009160153 Ferwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Bys " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/22 ip
- 8009250075 Responds to IE Bulletin 80-14, "Degradation of DWR Scram Discharge Vol Capability " Corrects error in 800728 response re Item A i One instance of broken rod on ball float also occurred MILLS:L M Tennessee Valley Authority 80/08/26 ip
- 8009120340 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Voit Type K-6008 & K-DON 6008 Circuit Breakers " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/27
- 8009230521 Forwards Revision 1 to IE Bulletin 79-26. "Boron Loss From BUR Control Blades" Written response required D'REILLY.J P Region 2. Atlanta. Office of the Director 80/08/29 1p
- 8009240261 Forwards response to IE Bulletin 80-17 re failure of control rods to fully insert during scram at BWR Plant instructions changed on 800827 to provide for manual scram & functional test Thirty-five manhours expended in bulletin review MILLS.L M Tennessee Valley Authority 80/08/29 3pp
- 8009240383 Forwards response to IE Bulletin 80-15 re possible loss of emergency notification sys w/loss of offsite power Design change request submitted Administrative procedure issued to comply w/requirements

  MILLS.L M Tennesse Valley Authority 80/08/29 4pp
- 8007240444 Forwards response to IE Bulletin B0-17 re failure of control rods to fully insert during scram at BWR Vent mod being coordinated w/overall scram discharge header sys review & mod program Schedule estimates will be provided MILLS.L M Tennessee Valley Authority 80/08/27 3pp
- 8009260375 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/10-588
- 8007300527 Forwards Progress Rept 4 for IE Bullstin 80-06 re engineered safety features reset controls MILLS.L M Tennessee Valley Authority 80/07/10 7pp
- 8009306060 Ark receipt of 800819 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-259/80-24, S0-269/80-18 & 50-276/80-19 LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/09/11 Ip
- --8009G00067 Forwards response to NRC 800724 ltr re violation noted in IE Insp Repts 50-259/80-24,50-260/80-18 & 50-296/80-19 Corrective actions, outdated surveillance instruction sheets replaced w/current revisions MILLS.L M Tennessee Valley Authority 80/08/19 2pp
- --8009300072 Forwards IE Insp Repts 50-259/80-24,50-260/80-18 & 50-276/80-19 on 800803-0601 & notice of violation LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/07/24 2pp
- --8009300075 Notice of violation from insp on 800503-0601 \* Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/07/15 1p
- ---80093000B1 IE Insp Repts 50-259/80-24,50-260/80-18 \$ 50-296/80-19 on B00503-Q601 Noncompliance noted failure to use latest revision of surveillance instruction data sheet SULLIVAN,R F, CHASE,J. W Region 2, Atlanta, Office of the Director DANCE,H.C Region 2, Atlanta, Reactor Operations Nuclear Support Branch B0/07/15 7pp
- R Periodic operating reports & related correspondence
- 8009110352 Forwards "Radiological Impact Assessment Browns Ferry Nuclear Flant, Jan-June 1980" MILLS, I. N Tenessee Valley Authority 80/08/29 1p

- --B009110353 "Radiological Impact Assessment Browns Ferry Nuclear Plant. Jan-June 1980" \* Yennessee Valley Authority RM-80-5-8F-3 80/08/29 44pp
- 8009170274 Forwards monthly operating repts for Aug 1980 ABERCROMBIE, H Tennessee Valley Authority 80/09/17 1
- --8009170277 Monthly operating repts for Aug 1980 ABERCROMBIE.H , THOM, T , GREEN, D Tennessee Valley Authority 80/09/01 30pp
- S Reportable occurrences, LERs & related correspondence
- 8009190765 PNO-78-147 on 780818, one of six air compressors experienced massive failure resulting in rapid loss of control air pressure to all units Caused by large hole in cylinder head State of AL, notified Media attention anticipated KLINGER: 0 , NOLAN.F , SNIEZEK, J Office of Inspection & Enforcement, Office of the Director 78/08/18 ip
- 8007190753 Provides interim assessment of PNO~78-147 re partial failure to scram event Margin of safety inherent in licensed design basis should be promptly restored Improved temporary measure acceptable pending permanent mods
  MICHELSON, C Director's Office 80/08/18 3pp
- 8009090467 Forwards LER 80-031/01T-0 CALHQUN, J R Tennessee Valley Authority 80/08/29 ip
- --8009090481 LER 80-031/01T-0 on 800811 during normal operation, two nodes in fuel assembly T2 396 exceeded upper boundary limits for max average planar linear heat generation rate Caused by failure to incorporate revised limits into Tach Specs

  Tennesse Valley Authority 80/08/29 2pp
- BOO9070445 Forwards LER 80-030/03L-0 CALMOUN.J R Tennessee Valley Authority 80/09/04 1
- --8007070462 LER 80-030/03L-0 on 800811. during normal operation, performing Surveillance Instruction 4 2 B 69. pressure switches PE-3-204A & PS-3-204B found outside limits Caused by setpoint drift Switches recalibr & tested & Tennessee Valley Authority 80/07/04 2pp
- 8009090490 Forwards LER 80-032/03L-0 CALHOUN.J R. Tennessee Valley Authority 80/09/05 ip
- --8009090509 LER 80-032/03L-0 on 800812, w/unit at steady state 94%, performing surveillance instruction 4 5 E i d & e, HPCI turbine tripped Caused by failure of teflon sheet portion of rupture disc, resulting in inadequate protection # Tennessee Valley Authority 80/09/05 2pp
- 8009160432 Forwards LER 80-033/03L-0 GALHOUN,J R. Tennessee Valley Authority 80/09/08 Lp
- --8007160440 LER 80-033/03L-0 on 800815.w/unit at 93% power in steady state operation.indicated leak on RHR heat exchanger 28 found during T1-36A Probably caused by leaking gasket.due to incose flange nuts as result of thermal cycling & vibration a Tennessee Valley Authority 80/09/08 2pp
- 8009160454 Forwards LER 80-034/03L-0 CALHOUN, J R Tennesses Valley Authority 80/09/08 1p
- ---8009160466 LER 80-034/03L-0 on 800815.w/unit at 94% power in steady state operation, RHR heat exchange 2C found leaking during TI-36A Caused by loose lock nuts & full nuts due to thermal cycling & vibration resulting in gasket leak \* Tennessee Valley Authority 80/09/08 2PP
- 8009190440 Forwards LER 80-035/03L-0 CALHOUN, J R Tennessee Valley Authority 80/09/12 ip
- --ECO7170454 LER 80-035/03L-0 on 800830, during normal operation while performing TI-36, increase in pressure on shell side of RHR heat exchanger 2D was detected Caused by leaking check valve between heat exchangers

  \* Tennessee Valley Authority 80/07/12 3pp
- 8009180399 LER 79-020 has been cancelled \* Tennessee Valley Authority 80/09/17 ip
- 8009300548 Forwards LER 80-036/03L-0 CALHOUN, J. R Tennessee Valley Authority 80/09/26 ip

- --8009300554 LER 80-036/03L-0 on 800829, while performing S I 4 7 4, H2E76-39 hydrogen monitor for drywall would not calibr Caused by sensor type 47E22642862 failure Sys will be replaced

  \* Tennessee Valley Authority 80/09/26 2pp
- DOCKET 50-261 H B ROBINSON PLANT, UNIT 2
- F Security, medical, emergency & fire protection plans
- 8009230252 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency O'REILLY.J P Region 2. Atlanta. Office of the Director 80/08/22
- G Adjudicatory correspondence
- 8009230124 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 VARGA.B A Operating Reactors Branch 1 80/08/29 2pp
- ---8009230130 Order for mod of License DPR-23 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by Bolioi EISENHUT; D O Division of Licensing 80/08/29 App
- H General correspondence
- 8009120437 Advises of BWR owners group organizational changes & that future correspondence be forwarded to DB Waters Future requests for util action should be addressed to individual licensees & applicants
  WATERS,D B Carolina Power & Light Co 80/09/02 2pp
- BO09120437 Advises of BWR owners group organizational changes & that future correspondence be forwarded to DB Waters Future requests for util action should be addressed to individual licensees & applicants
  WATERS,D B Carolina Power & Light Co 80/09/09 2pp
- P Operating license stage documents & correspondence
- 8009020277 Submits interim criteria for shift staffing to all GL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D O Division of Licensing 80/07/31 7pp
- 9007080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/o NUREO EISENHUT, D O Division of Licensing 80/08/01 117pp
- 8009230052 Informs that exemption from fee re licensing action associated w/YMI-2 Lessons Learned is unjustified Previous datermination should be disregarded Requested submittal should include proposed class of amend.
  EISENHUT, D & Division of Licensing 80/08/07 40pp
- 8008210180 Responds to 800709 ltr requesting interpretation of ANSI N45 2 10 rm longhand signature on certificates of conformance Recommends forwarding details to ASME for official interpretation HAASS.W P Guality Assurance Branch 80/08/12 Ip
- 8009190794 Forwards revised Hestinghouse STS 3 9 8 2/3 9 10 % Bases 3/4 9 8 % 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NDVAW.T M Assistant Director for Operating Reactors 80/08/15 ip
- --8009190817 Revised Westinghouse STS 3 9 8 2,3 9 10 % Bases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods

  \* Assistant Director for Operating Reactors 80/06/23 21pp
- 8009180107 Forwards Amend 48 to License DPR-23, safety evaluation & notice of issuance & availability
  VARGA.8 A Operating Reactors Branch 1 80/08/27 2pp

- -- SQOPIBOLIS Amend 48 to License DPR-29, revising Tech Specs re control red postsion indication sys misalignment limits VARGA, S.A. Operating Reactors Branch I 80/08/29 7pp.
- ~~8009160118 Safety evaluation supporting Amend 40 to License DPR-23 \* Office of Nuclear Reactor Regulation, Director 80/08/29 2pp
- --900(80)22 Notice of issuance & evailability of Amend 48 to License DPR-23 NEIGHBURS, J.D. Operating Reactors Branch 1 80/08/29 2pp
- 8009250262 Submits application for amend revising util 791003 proposed U. amend re degraded grid voltage Error in 1tem 8 a due to difference in setpoint rounding for Tech Specs & mod UTLEY.E £ Carolina Power & Light Co 60/09/19 2pp
- G. Inspection reports, IE Bulletins & correspondence
- 8009100042 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rugture " Written response required O'AEJLLY. J P Region 2. Atlanta. Office of the Director 80/07/24 Ip
- 9007020178 Submits response to IE Bulletin 79-03A re longitudinal weld defects in SA-012 stainless steel pipe Required info will be provided by 800722 FURR. B J Carolina Power & Light Co 80/08/05 lp
- 8007030307 Requests extension until 800722 to respond to IE Bulletin 79-03A. "Langitudinal Held Defects in ASME SA-312. Type 304 Stainless Steel Pipe "Bactground info necessary to perform engineering evaluation was only recently received FURR. 8 J Carolina Power & Light Co 80/08/06 ip.
- 8009300051 Forwards IE Insp Rept 50-261/80-15 on 800624-0702 No noncompliance noted LEMIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/08/14 2pp
- --8009300063 IE Insp Rept 50-261/80-15 on 800624-0702 No noncompliance noted Major areas inspected general plant operations, follows insp of outstanding items & review of plant safety committee meeting minutes.
  WHITENER, H. L., QUICK, D.R. Region 2, Atlanta, Office of the Director 80/08/14 3pp
- B009030169 Forwards Revision 1 to IE Bulletin B0-19, "Failures of Hercury-Metted Hatris Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Mritten response required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/08/15 19
- 80093DDG69 Forwards 1E Insp Rept 50-261/80-16 on 800707-18 No noncompliance noted LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/08/15 2pp
- --8009300073 IE Insp Rept 50-26/80-16 on 800707-18.No noncompliance noted Major areas inspected operations, followup of LERs & bulleting SKKD20.J L . KELLDGO.P J Region 2, Atlanta, Office of the Director. 80/08/15 Spp
- 8009240349 Responds to IE Bulletin 80-20 No Westinghouse Type M-2 switches, incorporating use of normally closed contact in neutral or automatic start position, used in safety-related applications
  FURR, B J Carolina Power & Light Co 80/09/21. 1p
- 8009160124 Forwards IE Circular 80-18, \*100FR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/08/22 to
- 8009120228 Responds to IE Bulletin 80-19 Mercury-Wetted matrix relays are not used in reactor protection sys FURR. B J Carolina Power & Light Co 80/09/26 19
- GOOG120270 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6005 & K-DON 6005 Circuit Breakers." No written response required. O'ARRILLY, J. P. Region 2, Atlanta, Office of the Director 80/08/27

- G009110271 Responds to IE Bulletin 79-01B, supplementing G00707 response Forwards 90-day rept re environ qualification of electrical equipment EURY.L W Carolina Power & Light Co 80/08/29 15pp.
- 8009270207 Forwards IE Circular 80-21. "Regulation of Refueling Crew."
  No written response required
  U'REILLY. J P Region 2. Atlanta, Office of the Director 80/07/0
  5pp
- R Periodic operating reports & related correspondence
- BOO7149255 Forwards monthly operating rept for Aug 1980 STARKEY, R. B Carolina Power & Light Co 80/09/10 ip
- --8009160258 Monthly operating rept for Aug 1980 WATFORD, M Carolina Pawer & Light Co 80/09/07 3pp
- S Reportable occurrences. LERs & related correspondence
- 8009030459 Forwards LER 80-017/03L-0 STARKEY,R B Carolina Power & Light Co 80/08/29 ip
- --9007030443 LER BO-017/03L-O on B00730, while performing air flow test, CPL-PT-24 O, positioner on Orad-U-Motor failed to function progerly Caused by accumulation of moisture in air supply line. Orad-U-Motor & positioner were removed from svc STARKEY, R B Carolina Power & Light Co B0/08/27 2pp
- 8009150286 Forwards LER 80-018/03L-0. STARKEY,R B Carolina Power & Light Co 80/09/10 1p
- --8009150287 LER 80-018/03L-0-on 800811, w/unit in refueling shutdown condition & while performing refueling period test CPL-PT-2 1, valve PCV-1716 failed to close due to isolation averride switch being on Cause not determined STARKEY, R B Carolina Power & Light Co 80/09/10 2pp
- 8009190469 Forwards updated LER 80-015/017-1 STARKEY,R B Careline Power & Light Co 80/09/15 ig
- --8009190477 Updated LER 80-015/01T-1 on 800823, three Westinghouse ands NBFD-315 relays used in reactor protection sys failed within 28 days Caused by open circuit & short circuit coil failures STARKEY, R B Carolina Power & Light Co 80/09/15 2pp
- 8009230301 Forwards LER 80-019/03L-0 8TARKEY.R B Carolina Power & Light Co. 80/09/19 10
- --8009250304 LER 80-019/03L-0 on 800822 during refueling outage shutdow small pinhole leaks & linear defects on campy seel welds discovered Geovee by weld degradation Defects repaired & nondestructive examination performed STARKEY.R 9 Carolina Power & Light Co. 80/09/19 4pp
- DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT
  F Becurity, medical, emergency & fire protection plans
- 8007030688 Forwards IE Health Physics Appraisal Rept 50-263/80-11, notice of violation & significant appraisal findings KEFPLER.J G Region 3. Chicago, Office of the Director 80/08/07 4pp
- --B009030491 Notice of violation from health physics appraisel on 800609-20 \* Region 3. Chicago, Office of the Director 80/08/01 ip.
- --8009030&95 IE Health Physics Appraisal Rept 50-2&3/80-li Noncompliand noted inadequate radiation area access controls & inadequate posting of radiation areas MILLER.D.E. LOVENDALE, P.C. FISHER.W.L. Region 3, Chicago, Office of the Director 80/08/01 2&pp
- 8009030381 Forwards Revision 1 to safeguards contingency plan Plan withheld (ref 10CFR2 790) MAYER.L.O Northern States Power Co 80/08/20 ip
- 8008260337 Forwards draft upgraded emergency plan MAYER, L D Northern States Power Co 80/08/21, 1p
- --8008260340 Draft upgraded emergency plan \* Northern States Power Co 80/08/15 130pp

11

, <sub>1</sub>

1

- BOO9030524 Requests that completion date for fire protection mod be extended to BOI031 due to unanticipated problems in project design b heavy consultant & operating staff work loads MAYER.L. O. Northern States Power Co. BO/08/22 ip
- 8009230305 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency KEPPLER.J O Region 3, Chicago, Office of the Director 80/08/22 300.
- 8007020055 Forwards 800410 "Emergency Preparedness Evacuation Time Estimates." Revision 1 Conforms to revised vehicle per hour capacity of state highway & country roads within 10-mile radius of facility
  MAYER.L D Northern States Power Co 80/08/25 ip
- 8007020009 Forwards add1 info re two fire protection mods planned for facility Complete failure of turbine lube oil reservoir unlikely During emergency. 12-inch drain line can be used to drain reservoir to outside underground tank MAYERIL D Northern States Power Co 80/08/26 2pp
- 8009240700 Notifies that facility security plan does not establish assequate commitment to meet code requirements Amend incorporating encl change is required within 60 days IPPOLITO.T A Operating Reactors Branch 2 80/09/09
- BOO9260017 Transmits emergency planning info to be made available to public at LPDR in Minneapolis.MN W/o encl SOUDER, J L. Division of Rules and Records 80/09/11 1p
- SCO9190479 Requests add1 time for completion of work re fire protection mods Problem w/reactor core isolation cooling has become one of qualify(ng,)rocuring & engineering new control logic sys Task shold be completed by May 1981 MAYER:L O Northern States Power Co 80/09/12 2pp
- G Adjudicatory correspondence
- 8009240012 Responds to FOIA request for nine categories of documents re AEC amend to 10GFR50 87(c) proposed on 701028 & adopted on 710814 Forwards documents listed in App A responding to Items 1-5 Bearch is continuing for addi records FELTON, J H Division of Rules and Records 80/08/21 2pp
- --B009240125 Requests settlement of privilege controversy in proceeding re-submission of rulings to ASLB Pending settlement ASLB cannot rule on util license for operation w/reactor vessel head in place Refs encl GEYER, J. C. GREULING.E. DEALE, V.B. Atomic Safety and Licensing Board Fanel. 70/10/06 18pp
- 8009220098 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 IFFOLITO.T A Operating Reactors Branch 2 80/08/29 2pp
- --8009220101 Order for mod of License DPR-22 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101
  EIGENHUT, D G Division of Licensing 80/08/29 App
- BOQ9080518 Memorandum & order ALAB-611.concurring w/ASLB conclusion that facility may continue to operate safely pending resolution of ATMS issue NRC shall suppl record re unresolved generic safety issues by 801015, BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/09/03 22pp.
- GOO9120403 Hemorandum amending Footnate II on Page 16 of ASLAB 800903 memorandum & order ALAB-611 Publication printed copy will reflect amend BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/09/10
- P Operating license stage documents & correspondence
- EOO9110554 Supple NRC 800707 request for proposed Tech Specs changes re scram discharge vol vent & drain valves, & reactor prefection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT.D 0 Division of Licensing 80/07/22 22pp

- 8009020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D G Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/o NUMEO EISENHUT,D 9 Division of Licensing 80/08/01 119pp
- 8009230092 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D O Division of Licensing 80/08/07 40pp
- 8009040125 Advises that two specific Event 5 valve configurations do not exist at facility per review of response to NRC 800223 ltr "Primary Coolant Sys Pressure Isolation Valves." technical evaluation rept encl IPPOLITO,T A Operating Reactors Branch 2 80/09/08 3pp
- --BC09040129 "Frimary Coojant Sys Pressure Isolation Valves, Northern States Power Co.Monticello Unit 1." technical evaluation rept NOELL.P N , STIMELL,T C Franklin Institute/Franklin Research Center NRC-03-79-118 80/07/21 Spp
- 8009230243 Forwards NUREO-0661, "Mark I Containment Long-Term Program SER Resolution of Generic Technical Activity A-7 " Rept describes NRC review results re generic suppression pool hydrodynamic load definition N/o encl
- 8009090776 Advises that util response to NRC 791109 ltr re portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture is acceptable No further action necessary IPPOLITO.T A Operating Reactors Branch 2 80/08/22 2pp
- 8009090375 Responds to NRC 800425 request for evaluation to consider loss of equipment due to water spiilage No addl ECCS equipment would be affected by water spiilage Util 800530 list of equipment remains unchanged MAYER, L O Northern States Power Co 80/08/28 tp
- 8009120579 "Degraded Grid Protection for Class IE Power Sys For Monticello Nuclear Generating Plant," technical evaluation rept CLEVELAND, C J EG&G Idaho, Inc FIN A-6256 8009120579 80/08/31 14a0
- 8009240110 "Technical Evaluation Rept on Degraded Orid Protection for Class IE Power Sys for Monticello Nuclear Generating Plant," Revision 2 CLEVELAND, C J EGAG Idaho, Inc FIN A-6256 8009260110 80/08/31 14pp
- 8009190084 Advises that commitments to NRC 791023 "Interim Position on Containment Purging & Venting Pending Resolution of Isolation Valve Operability." are acceptable & u[]] remain in effect pending completion of NRC long-term review IPPOLITO.T A Operating Reactors Branch 2 80/09/03 2pp
- BD09190486 Natifies of delay until B01114 for submittal of proposed Tech Specs for Lessons Learned Category A requirements, requested by NRC 800702 ltr MAYER,L O Northern States Power Co 80/09/12 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 8009090050 Forwards IE Bulletin 80-07. Suppl 1, "BWR Jet Pump Assembly Failure" No response required KEPPLER, J 0 Region 3. Chicago. Office of the Director 80/05/14 to
- 8009090088 "Response to 1E Bulletin 79-01B," re environ qualification of Class IE equipment # EDS Nuclear, Inc 01-0910-1087 80/05/28 210pp
- 8009030210 Forwards Revision 1 to IE Bulletin 80~19, "Failures of Mercury-Watted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C~E " Written response required KEPPLER. J G Region 3, Chicago, Office of the Director 80/08/15

- 8007(10534 Responds to IE Bulletin 80-17, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BNR " Matls presently on order to provide sys to continuously nonitor water level in scram discharge vols GILBERTS, D.E. Northern States Power Co. 80/08/15 29p
- 8009150466 Forwards IE Info Notice 80-30. "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE BWR Facilities " No specific action or response requested KEPPLER, J O Region 3. Chicago. Office of the Director 80/08/20 in
- B009120057 Forwards Suppl 3 to IE Bulletin 80-17. "Failure of Control Rods to Insert Buring Scram at SWR" Written response required KEPPLER. J G Region 3. Chicago, Office of the Director 80/08/22
- 8009170433 Forwards IE Circular 80-18 "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/08/22
- 8009110499 Responds to IE Bulletin BO-19. Revision i. "Failures of Mercury-Natted Matrix Relays in Reactor Protective Sys of Operating Auclear Power Plants Designed by C-E." No mercury-wetted relays used in reactor protection sys at facility OILBERTS, D.E. Northern States Power Co. 80/08/26 1p
- 8009170441 Responds to IE Bulletin 80-17 re failure of control rods to fully insert during scram at 3HR Potential design studies for improvement of venting sys performed Required mods will be completed during 1981 refueling outage, prior to startup OILBERTS.D E Northern States Power Co 80/08/28 2pp
- 6009180007 Responds to 1E Bulletin 80-17 re failure of control rods to fully insert during scram at BHR Procedure revisions incorporating requirements issued Scram rept revision implementing functional testing issued GIBERTS, D.E. Northern States Power Co. 60/08/28 2pp
- 8009230044 Forwards IE Info Notice 80-31. "Haloperation of Could-Brown Bover: 480 Voit Typo K-4005 & K-DOM 4005 Circuit Breakers" " No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/08/28
- 8009170413 Forwards response to IE Bulletin 79-018 re environ qualification of Class IE equipment Substantial efforts in progress to obtain required data Complete response will be submitted by 801101 GILBERTS. D 6 Northern States Power Co 80/08/29 2pp
- 009230483 Forwards Revision ( to IE Bulletin 79-26. "Boron Loss From TWR Control Blades " Written response required TPPLER. J G Region 3. Chicago. Office of the Director 80/08/27
  - 250408 Act receipt of 800827 ltr informing NRC of steps taken to rect violations noted in IE Insp Rept 50-263/80-11
    PLER.J C Region 3. Chicago: Office of the Director 80/09/09
  - 009250411 Responds to NRC 800807 ltr re violations noted in IE Insp Rept 50-263/80-f1 Corrective actions addl health physics staff to be hired & mgt support reinforced GLEERTS, D.E. Northern States Power Co. 80/08/27 9pp
- 6009240112 Forwards IE Circular 80-21, "Regulation of Refueling Craws " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/09/10
  - reriodic operating reports & related correspondence
  - 050348 Forwards "Effluent & Waste Disposel Semiannual Rept." n 1980-June 1980 VERL O Northern States Power Co 80/08/27 1p
  - 09050355 "Effluent & Waste Disposal Semiannual Rept," Jan-June 1980 \* Northern States Power Co 80/08/29 13pp
  - 7090282 Forwards monthly operating rept for Aug 1980 WER.L.O Northern States Power Co 80/09/05 ip
  - 109090287 Monthly operating rept for Aug 1980 MEGENER, D. Northern States Power Co. 80/09/05 4pp

- 8009300234 Errata to "Environ Monitoring & Ecological Studies Program
  Rept.1979 " Figures 2 2-3 through -7 have drafting error in
  legend Solid line should be identified as Sector A & dashed
  line as Sector B
  WARD.E C Northern States Power Co 80/09/25 ip
- S Reportable occurrences, LERs & related correspondence
- 8009030380 Forwards LER 80~025/03L-0 MAYER.L 0 Northern States Power Co 80/08/28 1p
- --8009030401 LER 80-025/03L-0 on 800729 during normal operation, while performing surveillance test, outboard HPCI steam supply valve operator failed Caused by breakdown of motor winding insulation Motor replaced w/upgraded insulation OVERLID.T W Northern States Power Co 80/08/28 1p
- 8009230632 Forwards LER 80~026/03L-0 MAYER. L O Northern States Power Co 80/09/16 1p
- --8009230641 LER 80-026/03L-0 on 800817, while performing surveillance test on outboard MSIV, AD-2-86A, valve closed in 9-s Caused by binding of piston in 4-way assembly Replaced 4-way assembly MSIV actuating assemblies will be rebuilt DVERLID. TW Northern States Power Co 80/09/16 1p
- 8009230420 Forwards LER 80-028/03L-0 MAYER, L O Northern States Power Co 80/09/19 1p
- --8009230630 LER 80-028/OSL-0 on 800825, while performing surveillance test, operator observed steam leak in elbow in drain line to condenser Caused by pinhole failure due to erosion from high velocity steam Leaking elbow & proximate elbows replaced OVERLID.T W Northern States Power Co 80/09/19 lp
- 8009260626 Forwards LER 80-D27/03L-0 MAYER.L O Northern States Power Co 80/09/22 ip
- --8009260640 LER 80-027/03L-0 on 80823, during monthly surveillance, 42-12 test control rod could not be withdrawn after partial insertion Caused by closed drive withdraw riser isolation valve CRD-102 Valve opened & rod was operable NIERQBE, C F Northern States Power Co 80/07/22 ip
- DOCKET 50-265 QUAD-CITIES STATION, UNIT 2
- F Security, medical, emergency & fire protection plans
- 8009230288 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys (nstalled for govt use during emergency KEPPLER, J 9 Region 3, Chicago, Office of the Director 80/08/22 3pp
- 8009100378 Forwards review of util generating station emergency plan & draft ltr requesting addl info & commitments from util PAGANO.F G Emergency Preparedness Licensing Branch 80/08/20 5500
- G Adjudicatory correspondence
- 8009220013 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 IPPOLITO, T A Operating Reactors Branch 2 80/08/29 2pp
- --8009220017 Order for mod of Licenses DPR-29 & DPR-30 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101 EISENKUT,D 0 Division of Licensing 80/08/29 6pp
- 8009300603 Forwards 800919 order revising 800829 order for mod of OLIin entirety EISENHUT, D O Division of Licensing 80/09/19 2pp
- --8009300614 Order revising 600829 order for mad of GLs DPR-29 & DPR-30, published in 800912 FR in entirety Info re IE Bulletin 79-018 shall be filed by 801101 Request for hearing will not stay order effective 800919 VCS petitions discharged EISENHUT.D G Division of Licensing 80/09/19 App

1

- P Operating license stage documents & correspondence
- BOOP110554 Suppls NRC BOO707 request for proposed Tech Specs changes re scram discharge vol vent & drain valves. & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EIBERHUT.D O Division of Licensing 80/07/22 22pp
- 8009020297 Submits interim criteria for shift staffing to all DL & CP licenses & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D O Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0676, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-06696 encl W/o NUREG EISENHUT
- BOO9230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D Q Division of Licensing BO/08/07 60pp
- BD09020456 Forwards evaluation of util response to NRC 800223 request for info re primary coolant sys pressure isolation valves. Two specific Event 5 valve configurations do not exist at facilities. CRUTCHFIELD, D Operating Reactors Branch 5 80/08/12 3pp
- --BD09020474 "Primary Coolant Sys Pressure Isolation Valves," technical evaluation rept NOELL:P N. STILWELL.T C Franklin Institute/Franklin Research Center NRC-03-79-118 80/07/21 4pp
- 8009180232 Forwards NUREG-0661, "Mark I Containment Long-Term Program SER Resolution of Generic Technical Activity A-7" Rept Giscusses generic suppression pool hydrodynamic load definition M/o encl IPPOLITO.T A Greating Reactors Branch 2 80/08/20 2pp
- BOO9020105 Forwards NUTECH Rept COM-0708-03, "Evaluation of 18-inch Containment Isolation Valves for Dresden Station,Units 2 % 3 & Quad Cities Station,Units 1 & 2," in response to NRC 791022 % 23 itrs re containment yent & purge valves JANECEX,R F Commonwealth Edison Co 80/08/22 ip
- --BOD9020111 "Evaluation of 18-Inch Containment Isolation Valves for Dresden Station,Units 2 & 3 & Quad Cities Station,Units 1 & 2 " GERBER.D A Nuclear Technology, Inc (Nutech) CDM-0708-03 80/05/14 116pp
- 8009120404 Forwards Attachments 1-5 to util 800630 ltr re facility electric distribution sys voltage adequacy Ltr inadvertently transmitted w/o attachments JANECEN.R F Commonwealth Edison Co 80/08/28 6pp
- 8009090394 Forwards add1 info re min critical configuration in support of 800515 application to amend Licenses DPR-19.25.29 & 30, changing requirements for source range monitor count rates JANECEK.R F Commonwealth Edison Co 80/09/03 5pp
- BOO9180501 Forwards Amends 47,44,58 & 53 to Licenses DPR-19,DPR-25, DPR-29 & DPR-30,respectively,safety evaluation & notice of issuance & availability IPPQLITO,T A Operating Reactors Branch 2 80/09/08, 2pp
- --BOO9180506 Amends 49,44,58 & 53 to Licenses DPR-19,DPR-25,DPR-29 & DPR-30, respectively, revising Tech Specs to allow count rate on source range monitor channels below 3 counts per second when there are two or less fuel assemblies in quadrant IPPOLITO,T A Operating Reactors Branch 4 80/09/08 22pp
- --8009180516 Safety evaluation supporting Amends 49,44,58 & 53 to Licenses DPR-19,DPR-25,DPR-27 & DPR-30,respectively \* Office of Nuclear Reactor Regulation, Director 80/09/08 4pp
- --BO09180526 Notice of issuance & availability of Amends 49,44,58 & 53 to Licenses DPR-19,DPR-25,DPR-29 & DPR-30,respectively IPPOLITO,T A Operating Reactors Branch 2 80/09/08 2pp
- 8009230463 Forwards proposed Tech Spec changes re implementation of TMI Lessons Learned Category A requirements in response to NRC 800762 request Dresden Unit 1 Tech Spec changes will be submitted 90 days prior to scheduled startup JANECEK:R F Commonwealth Edison Co 80/09/18 3pp

- --8007230466 Proposed Tech Spec changes re implementation of TMI-2 Lessons Learned Category A tems # Commonwealth Edison Co 80/09/10 29bo
- Q Inspection reports. IE Bulletins & correspondence
- 8007040517 Forwards IE Bulletin 80-07. Suppl 1. "BWR Jet Pump Assembly Failure " Response required MEPPLER, J G Region 3, Chicago, Office or the Director 80/05/14 in
- 8004040632 Provides addl response to IE Bulletin 80-17 Results of analysis of ATKS w/o recirculation pump trip encl Analyses required no deratings to remain below svc level C limit JANECEK.R F Commonwealth Edison Co 80/07/14 6pp
- 8009020109 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " SA-312 pipe not present in operating plants Final confirmation from suppliers anticipated by 800915 re const plant piping sys NAUGHTON, W F Commonwealth Edison Co 80/08/07 2pp
- BOO9170230 Forwards response to IE Bulletin 80-17. Suppl 1. "Failur# of 76 of 185 Control Rods to Fully Insert During Scram at BWR "
  Scram discharge vol piping, scram instrument vol piping & drain piping meet requirements re downward pitch PEOPLES, D. L. Commonwealth Edison Co. 80/08/07 4pp
- BOO7030231 Forwards Revision 1 to IE Bulletin 80-19, "Fallures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/08/15 ip
- B009110545 Responds to IE Bulletin B0-0B, "Exam of Containment Liner Penetration Welds," supplementing 800709 response Corrects Zion response re rings used for field circumferential butt weld Reviews accuracy of other statements ABELJ S Commonwealth Edison Co 80/08/15 4pp
- 8009110562 Responds to Suppl 1 to IE Builetin 80-17, "Failure of 75 of 195 Control Rods to Fully Insert During Scram at BWR" Util will not have continuous SDV water level monitoring systematiled & functional by 800901 JANECEK.R F Commonwealth Edison Co 80/08/15 2pp
- 8009160681 Submits supplementary response to [E Bulletin 80~08, "Examination of Containment Liner Penetration Welds." correcting statement made in OL Peoples 800709 ltr Further review not necessary ABEL.J S Commonwealth Edison Co. 80/08/15 4pp
- 8009290123 Forwards Waste Packaging Insp Rept 15000046/80-65 or 800527-30 & notice of violation DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Sa Branch 80/08/18 2pp
- --8009290124 Notice of violation from insp on 800527-30
  \* Region 3, Chicago, Office of the Director 80/07/23
- --8009290131 Waste Packaging Insp Rept 15000046/80-65 on 800 Noncompliance noted failure to meet strong tight packag/ requirement contained in DDT regulation LOVENDALE,P C , THOMAS,R D Region 3, Chicago, Office Director BOUK,H E Region 3, Chicago, Fuel Facility Safety Branch 80/07/23 2pp
- 8009190495 Forwards IE Info Notice 80-30, "Potential for Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE BNR Facilities specific action or response requested KEPPLER, J G Region 3, Chicago, Diffice of the Directo ip
- 8009120060 Forwards Suppl 3 to IE Sulletin 80-17, "Fail: Rods to Insert During Scram at BWR" Written response required KEPPLER, J G Region 3, Chicago, Office of the Direct
- 8009100551 Forwards IE Circular 80-18, "10CFR50 59 S for Changes to Radwaste Treatment Sys " No written required KEPPLER, J Q Region 3, Chicago, Office of the Dir 10

- 8304230694 Forwards IE info Notice 60-31. "Maloperation of Gould-Brown Bover: 450 Voit Type K-6005 & K-D04 6005 Circuit Breakers" No written response required KEPFLER, J.G. Region 3 Chicago, Orrice of the Director 80/08/28
- 2007100559 Ack receipt of 800715 itr informing NRC of steps taken to correct violation noted in 800620 IE insp rept & payment of civil penalty
  SIELLO V Office of Inspection & Enforcement, Office of the Director 80708/29 2pp
- E007170411 Forwards response to LE Bulletin BO-15 re possible loss of energency notification sys u/loss of offsite power Review revealed imperability of Dresden sys investigation being conducted Operating Order 22-60 changed

  JANACEX.F F Commonwealth Edison Co 80/08/29 4pp
- 8009180466 Responds to IE Bulletin 80-19 ra failures of mercury-wetted matrix relays in reactor protective sys Identified relays are not used in facility No action required Twenty-four manbours espended on review HAUSCH.T J Commonwealth Edison Co. 80/08/29 ip
- 8009230478 Forwards Pevision 1 to 18 Bulletin 79-26, "Boron Loss From 84R Centrol Blades' Mritton response required KEPPLER.J G Region 3. Chicago Office of the Director 80/08/29
- 6009170421 Responds to IE Bulletin 80-17. Suppl 1.re failure of control rods to fully insert during scram at BWR Vent sys will provide reliable source of air furing draining. Sys will be steadily purged until mods installed.

  JAMECER R F Commonwealth Edison CO. 80/09/02. 2pp
- 8005260109 Forwards response to IE Bulletin BO-17. Suppl 3. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR "
  Procedure at Dresden 2 & 3 changed to require inmediate manual scram when air pressure reaches 60 psi
  RAUSCH 7 J Componwealth Edison CO 80/09/02 4pp
- 8009250504 Responds to NRC 791213 request for add1 info in response to IE Bulletin 79-02 "Pipe Support Base Plate Designs Using Concrete Eipansion Anchor Bolts " Eipansion anchor test results show installation of anchors acceptable JANFCEK.R F Componwealth Edison Co 80/09/05 17pp
- 8009240133 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required
  KEFPLER J G Region 3, Chicago, Office of the Director 80/09/10
  1p
- 8009300200 Forwards response to IE Bulletin 80-20 No Mestinghouse Type W-2 control suitches are used in safety-related sys at Dresden. Quad Cities & LaSalle County Responses for Zion & Byron are encl
  RAUSCH T J Commonwealth Edison Co 80/09/15 6pp
- R Periodic operating reports & related correspondence
- 8009030448 Forwards semiannual rept of radioactive effluent discharges & solid radwaste, for Jan-June 1980 MALIVIANKIS:N Commonwealth Edison Co. 80/08/13 1s
- --8007690453 Semiannual rept of radioactive effluent discharges & solid rad\_aste.for Jan-June 1980 \* Cornonwealth Edison Co 80/08/13 20pp
- E009160272 Forwards monthly operating repts for Aug 1980 KALIVIANAKIS.N Commonwealth Edison Co 80/09/02 1p
- --8009160276 Monthly operating repts for Aug 1980 BROWN 8 . TUBBS, 8 Commonwealth Edison Co 80/09/02 22pp
- 8009120293 Forwards changes, tests & experiments completed during Aug 1983 KALIVIANAKIS,N Commonwealth Edison Co 80/09/08 2pp
- S Reportable occurrences, LERs & related correspondence
- 8007080378 Forwards LER 80-016/03L-0 KALIVIA/AXIS N Commonwealth Edison Co 80/08/11 2pp
- --8009080407 LER 80-018/03L-0 on 800723 discovered that pressure switch PS-2-261-30C would trip at 841 psig, under limit of 850 psig Caused by instrument drift Pressure switch recalibr & tested satisfactorily

  KAN.S Commonwealth Edison Co 80/08/11 lp

- 8009080412 Forwards LER 80-036/03L-0 KALIVIANAKIS N Commonwealth Edison Co 80/08/13 2pp
- --8009080417 LER 80-036/03L-0 on 800724, during testing, pressure switch PS-2-1622B was found to actuate at 20 3 rather than 13 8 inches of water Caused by setpoint drift Switch replaced STEFFES,C Commonwealth Edison Co
- 8009220268 Forwards LER 80-018/017-0 KALIVIANAKIS,N Commonwealth Edison Co 80/09/11 1p
- --8009220271 LER 80-018/01T-0 on 800829, while performing HPCI egerability test, discovered that HPCI motor gear unit would not come off high speed stop Coused by failure of component in flow controller replaced KODI.M Commonwealth Edison Co 80/09/08 2pp
- V Operator Examinations
- 8009300287 Forwards preliminary topical outlines of proposed modules on thermal hydraulics & core damage mitigation to be included in revised reactor operator training program per 800928 request NAUGHTON W F Commonwealth Edison Co 80/09/15 7pp
- DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1

  F Security, medical, emergency & fire protection plans
- 8009110619 Requests participation in study of people-related problems in nuclear safeguards Study involves collection of data on licensee security forces & practices EISENHUT.D G Division of Licensing 80/07/25 2pp
- 9009030542 Forwards safeguards contingency plan Plan withheld (ref 10CFR2 790) BURSTEIN, 5 Wisconsin Electric Power Co 80/08/22 1p
- 8009230314 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/22 3oo
- 8009260215 Responds to 800822 request for info re emergency notification sys & health physics network & requests clarification of notification requirements FAY.C N Wisconsin Electric Pawer Co 80/09/05 3pp
- 8009290177 Forwards security measures for proposed sewage treatment plant Encl withheld (ref 10CFR2 790) BURSTEIN,8 Hisconsin Electric Power Co 80/09/17 ip
- G Adjudicatory correspondence
- 8007080348 Discusses 800808 Itr authorizing restart & alluding to informal understanding between NRC & licensee re future insp Expresses belief that action thwarts meaningful public participation
  FALK:K M Wisconsin's Environmental Decade 80/08/26 2pp
- 8009190352 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 CLARK, R A Operating Reactors Branch 3 80/08/29 2pp
- ~-8009190357 Order for mod of Licenses DPR-24 & DPR-27 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101 EISENHUT.D.Q Division of Licensing 80/08/29 App
- 8009230255 Response to WI Environ Decade 800826 ltr on acceptability of certain test results re steam generator tube integrity. Admits that NRC legal arguments against right to hearing are groundless Certificate of Svc encl
  CYR.K D Rulemaking & Enforcement Division 80/09/17 4pp
- B009230447 Ack receipt of B00826 ltr re facility Since ltr deals w/ matters currently before ABLB.Commission comments inappropriate at this time MURRAY.J P Rulemating & Enforcement Division 80/09/19 ip

BOO93004iO Notifies that util has been served u/MI Environ Decade, Inc BOOBOB ltr to Senator Proxmire & Congressman Zablock; Ltr alleges corrosion problem in steam generator tubes Ltr encl O'NEILL,J H. Shaw, Pittman, Potts & Trowbridge BO/09/25 7pp

#### H Coneral correspondence

- 8009050424 Responds to Laague Against Nuclear Dangers 800715 1tr re relocating local PDR to Two Rivers.WI Two Rivers library will house documents re Wood County special repts NRC 1979 Annual Rept encl SGUDER.J L. Division of Rules and Records 80/08/15 22pp
- --9009050426 Requests submitted on behalf of League Against Nuclear Dangers, concerning relocation of local PDR to Manitowoc, WI Lists types of documents & specific documents that should be retained at Univ of WI library DIXON.G Affiliation Unknown 80/07/18 3pp
- 9009110411 Requests establishment of LPDR in Madison, WI, on behalf of WI Public Svc Commission State agency personnel will review replacement of steam generators at Point Beach Unit 1 in 1981 or 82 Related correspondence VORK-8 , PARSONS, EM , NUNNERY, W. J. Wisconsin, State of 80/08/24 20a
- 8009260187 Forwards FR notice of relocation of facility LPDR from Univ of WI Library, Stevens Point to Joseph Mann Library, Two Rivers.WI FELTON.J M Division of Rules and Records 80/09/09 2pp

## P Operating license stage documents & correspondence

- 8009020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D O Division of Licensing 80/07/31 7pp
- BOOPQBOOBO Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/o NUREO EISENHUT.D Q Division of Licensing 80/08/01 119pp
- 8007020497 Responds to NRC 800708 ltr re weldments in Graver tanks Evaluations show that connections & penetrations would withstand design loading conditions assuming as-found configuration BURSTEIN B Wisconsin Electric Power Co 80/08/04 3pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Provious determination should be disregarded Requested submittal should include proposed class of amend EISENRUT, D O Division of Licensing 80/08/07 60pp
- BOOTO40279 Forwards safety evaluation re facility steam generator tube degradation Based on review of util steam generator tube insp. Unnecessary to place further restriction on resumption of facility operation CASE. E. G. Office of Nuclear Reactor Regulation, Director BD/08/08 7ap
- --9009040305 Safety evaluation re facility steam generator tube degradation \* Diffice of Nuclear Reactor Regulation, Director 80/08/08 7pp
- 8009190794 Forwards revised Westinghouse 8TB 3 9 8 2.3 9 10 8 Bases 3/4 9 8 & 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NDVAK.T M Assistant Director for Operating Reactors 80/08/15
- --B007190B17 Revised Westinghouse STS 3 9 B 2.3 9 10 & Bases 3/4 9 B & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods

  + Assistant Director for Operating Reactors 80/06/23 21pp
- 8009030498 Requests permission to suppl WI Environ Decade previous fillings supporting adjudicatory hearing re petitioner preliminary contentions NRC 800808 ltr authorizes facility restart w/o offer for adjudicatory hearing FALK.K M Wisconsin's Environmental Decade 80/08/26 2pp

- -8009030501 Notifies that restrictions re facility operation resumption not necessary per review of util 800805 steam generator tube insp results Conditions of 791130 order \$ 800103 mods to 791130 order remain in effect Safety evaluation not encl CASE.E 0 Office of Nuclear Reactor Regulation. Director 80/08/08
- 8009120575 Forwards requests for addi info re adequacy of station electric distribution sys voltages to continue review Response requested within 45 days or ltr receipt CLARK.R A Operating Reactors Branch 3 80/09/08 App
- B007160442 Responds to NRC 800819 itr re IAEA design info questionnaire to be utilized in submittal of installation info by facilities Compiling data will require significant effort NRC should utilize existing info in files BURSTEIN, S Wisconsin Electric Power Co 80/09/11 1p
- 8009230660 Responds to 800815 request for review of Tech Specs & procedures assuring that exposure or fuel assemblies & control rods cannot occur during transfer w/plant in refueling shutdown mode Changes to Tech Specs unnecessary FAY.C W Wisconsin Electric Power Co 80/09/15 2pp
- 8009230666 Notifies NRC that util unable to comply w/800714 request re Tech Specs applicable to implementation of TMI-2 Lessons Learned Category A items Initial review of model Tech Specs completed FAY.C W Wisconsin Electric Power Co 80/09/18 3pp
- 8009250249 Application to amend Licenses DPR-24 & DPR-27, changing Tech Specs 15 1,15 3 & 15 6, re limiting conditions for operations, definitions of operatility & administrative structure
  BURSTEIN,S Wisconsin Electric Power Co 80/09/19 3pp
- --8009250253 Tech Spec Change Request 64.consisting of proposed Tech Specs 15 1.15 3 & 15 5 re limiting conditions for operations, definition of operability & administrative structure 4 Wisconsin Electric Power Co 80/09/19 Spp
- 8007270341 Proposed Change 45, modifying 770728 request to amend Licenses DPR-24 & DPR-27 to incorporate Tech Spec changes Changes modify trip & time delay setting for undervoltage protection circuitry BURSTEIN. S Wisconsin Electric Power Co 80/07/22 2pp
- --8009270342 Tech Spec change for Item 7 of Table 15 3 5-1 % Item 3a of Table 15 3 5-3 re time % trip delay settings for undervoltage protection sys 4 Wisconsin Electric Power Co 80/09/22 2pp
- B009300461 Forwards comments on draft NUREG-0494, "Functional Criteria for Emergency Response Facilities " NUREG should include alternate methods of satisfying functional requirements FAY.C W Wisconsin Electric Power Co B0/09/22 6pp
- Q Inspection reports. IE Bulletins & correspondence
- B00929G011 Forwards IE Insp Repts 50-266/80-10 & 50-301/80-10 on 800604-27 & notices of violation, App A & B App B withheld (ref 100FR2 790)
  KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/11
- --8007290013 Notice of violation App A from insp on 800604-27 \* Region 3. Chicago. Office of the Director 80/08/05 ip
- --B009290015 IE Insp Repts 50-266/80-10 & 50-301/80-10 on 800604-27 & 0708 Noncompliance noted RHR pumps operability impaired & engineered safety feature crossconnected Details withheld (ref 10CFR2 790)
  SMITH.J D. QULDEMGND.W G. WARNICK.R F. Region 3. Chicago, Office of the Director 80/08/05 12pp
- 8009030219 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/08/15
- B009290017 Forwards IE Insp Repts 50-266/80-13 & 50-301/80-13 on 800717 & 22 No noncompliance noted DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/08/19 2pp

- --8009290018 IE Insp Repts 50-246/80-13 & 50-301/80-13 on 800717 & 22
  No noncompliance noted Major areas inspected confirmatory
  measurements
  JANUSKA:A C , ESSIG.T H Region 3. Chicago, Office of the Director
  80/08/15 4pp
- 8007180520 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys ' No written response required

  KEPPLER.J G Region 3, Chicago, Office of the Director 80/08/22
- 8009110557 Responds to 1E Bulletin 80-18. "Maint of Adequate Min Flow Thro Centrifugal Charging Pumps Following Secondary Bide High Energy Line Rupture " Corrective actions are not necessary FAY.C W Wisconsin Electric Power Co 80/08/26 2pp
- 8009230089 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Bover! 480 Volt Type K-6005 & K-DDN 6008 Circuit Breakers " No written response required KEPPLER. J G Region 3. Chicago. Office of the Director 80/08/28
- 8009180158 Responds to IE Sulletin 80~19 re failures of mercury-wetted matrix relays in reactor protective sys Identified relays not used in facility
  FAY.C W Wisconsin Electric Power Co 60/08/29 ip
- 8009240124 Forwards (E Circular 80-21, "Regulation of Refueling Crews" No written response required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/09/10
- 8009300305 Responds to IE Bulletin 80-20 Identifies safety-related equipment control circuits utilizing Westinghouse Type W-2 switches w/spring-return-to-meutral position All but four circuits have been modified to indicate switch closure BURSTEIN.S Wisconsin Electric Power Co 80/09/16 2pp
- R Periodic operating reports & related correspondence
- 8009090539 Forwards "Semiannual Monitoring Rept, Jan-Jun, 1980 " FAY. C W Wisconsin Electric Power Co 80/08/29 1p
- --8007090545 "Semiannual Monitoring Rept, Jan-Jun, 1980" \* Wisconsin Electric Power Co 80/09/29 15pp
- 8009140302 Forwards monthly operating repts for Aug 1980 FAY, C W Wisconsin Electric Power Co 80/09/09 19
- --8009160304 Monthly operating repts for Aug 1980 FAY.C W Wisconsin Electric Power Co 80/09/04 9pp
- U Congressional/Executive Correspondence
- 8009020950 Expresses conterns re potential consequences from stoam generator tube degradation Full adjudicatory hearing needed Requests to be informed of continuing development STROHL. J. BERGER, D. MODDY, J. Wisconsin. State of 80/08/22 tp
- 8009290002 Responds to 800822 ltr urging full adjudicatory hearings on plant safety issues Commission has referred similar WI Environ Decade request to ABLB for determination Further Commission comment is imappropriate pending ABLB decision MURRAY, J P Rulemaking & Enforcement Division 80/09/09 ip
- ---G009290004 Responds to 800B22 ltr urging full adjudicatory hearings on plant safety issues Commission has referred similar WI Environ Becade request to ASLB for determination Further Commission comment is imappropriate pending ASLB decision MURRAY. J P Rulemaking & Enforcement Division 80/07/09 ip
- --B009290605 Responds to B00822 ltr urging full adjudicatory hearings on plant safety issues Commission has referred similar WI Environ Decade request to ASLB for determination Further Commission comment is inappropriate pending ASLB decision RVRRAY.J P Rulemaking & Enforcement Division 80/09/09 ip
- '009240470 Urges NRC to order full-scale adjudicatory hearing on safety concerns re degradation of steam generator tubes Related correspondence MUNIS.M L. Wisconsin, State of 80/09/16 1p

- DOCKET 50-267 FORT ST VRAIN NUCLEAR GENERATING STATION

  F Security, medical, emergency & fire protection plans
- 8007230731 Advises that list of 60 add1 heavily populated areas has been included in encl revised guidance document, NUREO-0561 Amend rule for physical protection of irradiated reactor fuel for transit will be effective 800829 W/o encl MCCORKLE. 6 W Physical Security Licensing Branch 80/07/QB ip
- 8009020153 Invites participation in 800822 workshop in Atlanta, 6A to solicit comment re proposed functional criteria for smergency response facilities in NUREQ-0696 Discussion to include location, size & staffing of emergency ctr SEYFRIT. K V Region 4, Dallas, Ofrico of the Director 80/08/12
- G Adjudicatory correspondence
- 8009230127 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 MILLER, J.R. Standardization & Special Projects Branch 80/08/29
- --8009230129 Order for mod of License DPR-34 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101
  EISENHUT, D 0 Division of Licensing 80/08/29 App
- 8009240194 Responds to NRC 800829 order modifying License DPR-34 to require info by 801101 re environ qualifications of IE electrical equipment in operation sys exposed to high energy line break ambience Hearing requested re order FULLER.J K Public Service Co of Colorado 80/09/17 3pp
- P Operating license stage documents & correspondence
- 8009020277 Submits interim criteria for shift staffing to all OL & CP licensees & applicants,per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT,D Q Division of Licensing 80/07/31 7ρρ
- 80090B00B0 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 entl W/o NUREO EISENHUT, D O Division of Licensing 80/08/01 119pp
- B009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D G Division of Licensing B0/08/07 40pp
- 8007040504 Forwards Amend 22 to License DPR-34 & safety evaluation TEDE8CO.R L Assistant Director for Licensing 80/08/19 2pp
- ---8009040507 Amend 22 to License DPR-34 revising diesel fuel storage requirements, updating company reorganization & altering fire protection Tech Specs
  TEDESCO.R L Assistant Director for Licensing 80/08/19 51pp
- ---8009040513 Safety evaluation supporting Amend 22 to License DPR-34 \* Office of Nuclear Reactor Regulation, Director 80/09/19 35pp
- B009150427 Forwards safety evaluation & statement of NRC positions re safety-related electrical equipment for licensee response Requests comparison w/corrent emergency power sys design & plant mods to meet NRC positions TEDESCO-R L Assistant Director for Licensing 80/08/25 3pp
- --B009150431 Bafety evaluation & statement of NRC positions re emergency power sys for operating reactors \* Assistant Director for Licensing 80/08/25 12pp
- 8009030540 Responds to NRC 800802 ltr requesting addl info re thermal stresses in core support blocks. Net effect of analytical models & assumptions on stresses not clear at present Short-term efforts in progress Results to be reviewed FULLER, J K Public Service Co of Colorado 80/08/29 App

- \$009140344 Informs that immediate Amend 22 implementation not feasible due to time difference between issuance % receipt Requests that amend provisions be made effective 801025 & amended \$R 5 4 1 effective date be determined mutually w/NRC WAREMBOURG,D Public Service Co of Colorado 80/09/08 4pp
- QCQ9160364 Requests relief from LCO 4 3 10 for 60 days, after return to power, to check & readjust hangers & snubbers for main steam & cold & hot reheat lines Many hangers will require new position settings which must be made at full steam WAREMBOURO, D Public Service Co of Colorado 80/09/08 2pp
- 8009160314 Forwards "Fort St Vrain Initial Approach to Power Tests (B-Series)," Interim Rept 16 for period ending 800822 WAREMBOURG, D Public Service Co of Colorado 80/09/09 lp
- ~~8009i603i6 "Fort St Vrain Initial Approach to Power Tests (B-Series)."
  Interim Rept 16 for period ending 800822

   Public Service Co of Colorado 80/08/22 2pp
- 8009230689 Comments on NUREO-0696 document late considering number of significant changes imposed to criteria of NUREOS-0578 & 0694 which were utilized by nuclear industry in planning emergancy response facilities HAREHBOURG, D Public Service Co of Colorado 80/09/16 10pp
- Inspection reports, IE Bulletins & correspondence
- 8009220318 Discusses objectives & conclusions re helium circulator C-2102 insp Forwards QA Co rept.QA-C15847.re insp results Requests review of proposed inservice insp program in draft Tech Specs submitted 800331 HAREMBOURG.D Public Service Co of Colorado 80/07/02 2pp
- ~~800922032i "Exam of Helium Circulator C-2102 " RDSENBERG,R General Atomic Co (subs of Gulf Gil Co ) GA-C15847 80/04/30 75pp
- B009020221 Responds to IE Bulletin 80-11 re masonry walls in proximity to or that have attachments w/safety-related piping or equipment Util completed investigation of all concrete masonry block walls in turbine & reactor bldgs
  SWART.F E Public Service Go of Colorado 80/07/07 3pp
- ---8007050467 Notice of violation from insp on 800616-17

  \* Region 4, Dallas, Office of the Director 80/07/11 2pp
- --8007050477 IE Insp Rept 50-267/80-14 on 800616-19 Noncompliance noted failure to document qualifications of personnel performing calibrs on measuring & test equipment & failure to provide record of test equipment GAGLIARDD, JE Region 4, Dallas, Reactor Operations Nuclear Support Branch YANDELL, LA, WESTERMAN, TF Region 4, Dallas, Office of the Director 80/07/11 7pp
- 8009100033 Forwards IE Insp Rept 50~267/80-12 on B00601-30 & notice of violation MADSEN, G L. Region 4, Dallas, Reactor Operations Nuclear Support Branch B0/07/16 2pp
- --8009100057 Notice of violation from insp on 800601-30 \* Region 4, Dallas, Office of the Director 80/07/12 2pp
- --8009100055 IE Insp Rept 50-267/80-12 on 800601-30 Noncompliance noted failure to follow procedures, failure to implement equipment control procedure & failure to maintain records required by Tach Spec 4 2 9.

  OAOLIARDO, JE . WEBTERMAN, T F. DICKERSON, M W. Region 4, Dallas, Office of the Director 80/07/12 13pp
- 8009180140 Forwards IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches " Written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/07/31
- g009180192 Forwards IE Bulletin 80-19, "Failure of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required SEYFRIT.K V Region 4, Dallas, Office of the Director, 80/07/31 1p

- 8009260286 Forwards IE Info Notice 80-29. 'Broken Studs on Terry Turbine Steam Inlet Flange "No written response required SEYFRIT, X V Region 4, Dallas, Office or the Director 80/08/07 in
- 800925045B Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Mercury-Natted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E 'Mritten response required SEYFRIT.X V Region 4, Dallas, Office of the Director 80/08/15
- 8009300274 Forwards IE Insp Rept 50-267/80-15 on B00701-30 % notice of violation MADSEN.G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/08/18 2pp
- --8009300279 Notice of violation from insp on 800701-30
  \* Region 4, Dallas, Office of the Director 80/08/13 ip
- ---8009300282 IE Insp Rept 50-267/80-15 on 800701-30 Noncompliance noted failure to comply w/requirements of radiation work permit DICKERSON,M W. COLLINS.R E , WESTERMAN,T F Region 4, Dallas, Office of the Director 80/08/13 8pp
- 8007170403 Forwards IE Circular 80-18, "10CFR50 57 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required SEYRIT, K V Region 4, Dallas, Office of the Director 80/08/22
- BO09100B36 Ack receipt of B00B07 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-267/80-14 MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch B0/08/25 ip
- --B009100841 Responds to NRC 800714 ltr re violations noted in 1E lasp Rept 50-267/80-14 Corrective actions review panel established to survey cases of suspected deficiencies by personnel involved in tests LEE, D R Public Service Co of Colorado B0/08/07 2pp
- BO09150450 Specifies followup actions re IE Info Notice 79-04 Util should review electric power sys to determine capacity of offsito power sys Background info re event & guidelines for calculations encl
  TEDESCO.R L Assistant Director for Licensing 80/08/25 8pp
- 8009190433 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover: 480 Volt Type K-6005 t K-DDN 6008 Circuit Breakers" No written response required SEY-RIT.K V Region 4, Dallas, Office of the Director 80/08/27
- 8009170185 Ack reteipt of 800806 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-267/80-12 MADSEN.O L Region 4. Dallas. Reactor Operations Nuclear Support Branch 80/09/02 ip
- --8009170187 Responds to NRC 800716 itr re violations noted in IE Insp Rept 50-267/80-12 Corrective actions seals installed in three unsealed valves, defective pen repaired, status card replaced & use of log sheet implemented LEE.O R Public Service Co of Colorado 80/08/06 2pp
- R Periodic operating reports & related correspondence
- 8009260227 Forwards "Environ Radiation Surveillance Program, Summary Rept for Jan-June 1980" SWART.F E Public Service Co of Colorado 80/08/27 ip
- --8009260233 "Environ Radiation Surveillance Program, Summary Rept for Jan-June 1980 "
  JOHNSON, J E Colorado State Univ SHART, F E Public Service Co of Colorado 80/08/29 132pp
- 8009140290 Forwards monthly operating rept for June 1980 WAREMBOURG,D Public Service Co. or Colorado 80/09/03 4pp
- 8009160272 Forwards monthly operating rept for Aug 1980 WAREMSOURG,D Public Service Co of Colorado 80/09/08 19
- --8009160299 Monthly operating rept for Aug 1980 OAHM, J W Southwestern Public Service Co 80/09/02 5pp
- BOO9160286 Forwards revised monthly operating rept for Aug 1980 WAREMBOURG,D Public Service Co of Colorado 80/09/09 ip

- --8009160288 Monthly operating rept for Aug 1980
  GAMM.J W Public Service Co of Colorado 80/09/02 5pg
- 8009230723 Forwards monthly operating rept for Jul 1980
  WAREMBDURG D Public Service Co of Colorado 80/09/15 to
- 8009260369 Forwards Page 1 revision to monthly operating repts for Mar & Apr 1980 WAREMBOURG D Public Service Co of Colorado 80/09/18 2op
- ---8009260372 Revised Page 1 for monthly operating rapt for Mar 1980 \* Public Service Co of Colorado 80/09/18 ip
- ---8009260374 Revised Page 1 for monthly operating rept for Apr 1980 \* Public Service Co of Colorado 80/09/18 ip
- 8009260378 Forwards monthly operating rept for Aug 1980 WAREMOURGED Public Service Co of Colorado 80/09/18 2pp
- --8009260386 Monthly operating rept for Aug 1980 GARK.J W Public Service Co. of Colorado 80/09/02 10pp
- 8 Reportable occurrences. LERs & related correspondence
- 8009030625 Forwards LER 80-043/03L-0
  MAREMBOURG D Public Service Co of Colorado 80/08/27 5pp
- --8009030640 LER 80-049/03L-0 on 800728 during plant rise-to-powerout-gassing of oxidents from core resulted in degraded mode operation of LCO 4 2 10 Caused by residual moisture from leakage past HV-21392 5 primary coolant circulation trip GAHM.J W Public Service Co of Colorado 80/08/27 ip
- 8009230598 Forwards LER 80-045/03L-0 WAREMBOURG, D. Public Service Co. of Colorado 80/09/15 4pp
- --8009230404 LER 80-045/03L-0 on 800816, fitting on hydraulic oil line ruptured spraying oil on hot steam pipes & producing heavy smoke Fitting ruptured due to normal usage & was replaced Valve group was isolated to prevent add1 oil loss # Public Survice Co of Colorado 80/09/15 lp
- 8009230608 Forwards LER 80-044/03L-0 WAREMBOURG,D Public Service Co of Colorado 80/09/15 4pp
- --8009230614 LER 80-044/03L-0 on 800816.while operating at 30% power, boiler feed pump A was removed from svc dur to unstable governor controls Boiler feed pump B was out of svc also Caused by governor worm goar being loose on shaft # Public Bervice Co of Colorado 80/09/15 ip
- 8009230597 Forwards LER 80~046/03L-0 WAREMBBURG,D Public Service Co of Colorado 80/09/19 App
- --8009230607 LER 80-046/03L-0 on 800820, w/plant operating at approx 25% thermal power.PCRV cooling water outlet temp exceeded 120 F iimit Caused by isolation of cooling water due to operation of wrong controllers. Controllers reset to proper position 9AK4.J W Public Service Co of Colorado 80/09/17 lp
- 8009300556 Forwards LER 80-047/03L-0 WAREMBOURG,D Public Service Co or Colorado 80/09/24 7pp
- --8009300563 LER 60-047/03L-0 on 800825 several hydraulic snubbers were found imporable Caused by improper hot position adjustment on constant support hangers Snubbers repaired or readjusted QIDSON, J W Public Service Co of Colorado 80/09/24 1p
- DOCKET 50-268 MIDWEST FUEL RECOVERY PLANT

  P Operating license stage documents & correspondence
- 8007(90049 Advises that list of 60 add1 heavily populated areas has been included in encl revised guidance document.NUREG-0561, per NRC amend rule for physical protection of irradiated reactor fuel in transit.effective 800703 M/o encl MCCORKLE.G W Physical Security Licensing Branch 80/07/07 ip

- DOCKET 50-269 GCONEE NUCLEAR STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8009230256 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/22 to
- G Adjudicatory correspondence
- 8009260664 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 REID.R W Operating Reactors Branch 4 80/08/29 2pp
- ---8007260667 Order for mod of Licenses DPR-38.DPR-47 & DPR-55 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101 E19ERHUT, D & Division of Licensing 80/08/27 App
- J Insurance & indemnity information
- 8009190424 Forwards Endorsement 58 to NELIA Policy NF-182 & Endorsement 43 to MAELU Policy NF-61 SANDERS:F D Duke Power Co 80/08/25 3pp
- 8009300428 Advises that invoices for facility indemnity fees should be addressed to WD Parker, not AC Thies PARKER, W G Duke Power Co 80/09/24 ip
- P Operating license stage documents & correspondence
- 8009150070 Responds to 800523 recommendations concerning lessons learned from 800226 transient at Crystal River Submits results of investigations re use of atmospheric dump valve at Sconee Units 1-3, AR Unit 1, Davis-Besse Unit 1 & TMI-1 DENTON, HR Office of Nuclear Reactor Regulation, Director 80/07/21 2pp.
- --8009150079 Discusses 800226 transient at facility Recommends investigation to determine whether atmospheric dump valve design deficiency is present in other B&W plants MICHELSON, C Director's Office 80/05/23 2pp
- 8007030343 Discusses void formation in vessel head during 800611 natural circulation cooldown event Requests opinion repotential for voiding phenomenon in 85W designed NB6S CMECK.P 8 Assistant Director for Plant Systems 80/07/28 2pg
- BOO9020297 Bubmits interim criteria for shift staffing to all OL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D G Division of Licensing 80/07/31 7pp
- 8007080080 Forwards draft NUREQ-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl W/o NUREG EISENHUT
- 8007230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D @ Division of Licensing 80/08/07 60pp
- 8009040085 Requests written confirmation of appraisal of critical electrical power generation situation in region served by Duke Power Co NOVAN.T K Assistant Director for Operating Reactors 80/08/11
- BOO7160501 Forwards Amends 86,86 & 83 to Licenses DPR-38,DPR-47 & DPR-55,respectively,safety evaluation 8 notice of issuance & availability REID.R W Operating Reactors Branch 4 80/08/20 2pp
- --8009160502 Amends 86.86 & 83 to Licenses DPR-38,DPR-47 & DPR-55, respectively,incorporating test frequency requirements of 10CFR50.App J.into containment leak test program REID.R W Operating Reactors Branch 4 80/08/20 7pp

- --8009160506 Safety evaluation supporting Amends 86,86 & 83 to Litenses

  OPR-3B, DPR-47 & DPR-55 respectively

  Gffice of Nuclear Reactor Regulation, Director 80/08/20 2pp
- --8009140507 Notice of issuance & availability of Amends 86.86 & 83 to Licenses DPR-38, DPR-47 & DPR-55, respectively REID.R W Operating Reactors Branch 4 80/08/20 2pp
- BO09160805 Notification of 800903 meeting w/util & Franklin Research Ctr in Bethesda, MD to review NUREQ-057B, Items 2 1 7 A&B FAIRTILE, M B Operating Reactors Branch 4 80/08/21 ip
- OCO9020025 Forwards BAW regt. "Evaluation of Instrumentation to Detect Inadequate Core Cooling Prepared for 177 Cumers Group," supplementing earlier util submittals re Lessons Learned litem 2 i 3 b No addl instrumentation needed W/o encl PARKER, W O Duke Power Co 80/08/26 ip
- BO09100489 Informs NRC that revised radiological ETS "Offsite Dose Calculation Manual" & proposed process control program for solid waste sys will be forwarded by B00930 PARKER, W O Duke Power Co 80/09/03 ip
- BO09190154 Advises of NRC review of util B00328 submittal re standby shutdown facility Pages 2-1.5-1.5-2.5-3.4-3 & 7-1 should be withheld per 10CFR2 790 Util should resubmit document w/deletions within 30 days
  REID.R W Operating Reactors Branch 4 B0/09/09 2pp
- 8009250434 Informs of acceptability of response to NRC 791109 ltr reportions of ECCS evaluation models dealing w/fuel cladding suelling & incidence of rupture REID:R ti Operating Reactors Branch 4 80/09/09 2pp
- 8009230724 Disagrees w/NRC 800909 ltr re classification of Standby Shutdown Facility licensing document Document should be withheld (ref 10CFR2 790) No nonpropietary version will be submitted PARKER. W O Duke Power Co 80/09/17 ip
- 8009300486 Forwards response to NRC 800611 request for change in facility Tech Specs, providing for redundancy in decay heat removed capability No changes necessary to Tech Specs PARKER, N O Duke Power Co. 80709724 Spp
- O Inspection reports, IE Bulletins & correspondence
- 800910005B Forwards IE Builetin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/07/24 1p
- B009040640 Responds to IE Bulletin 80-16 Resembnt Model 1151 \$ 1152 pressure transmitters w/output codes A or D are used for indicating reactor coolant pressure & providing input to control steam generator level PARKER, W D Dute Power Co 80/07/30 3pp
- 8009030175 Forwards Revision 1 to 1E Bulletin B0-19, "Failures of Marcury-Wetted Matrix Relays in Reactor Protective Eys of Operating Nuclear Power Plants Designed by C-E " Written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/15 to
- 8009160137 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required 0'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22 to
- B009170233 Responds to IE Bulletin 80-19, Revision 1, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Review indicates relays are not in use at facility PARKER, W O Duke Power Co 80/08/22 1p
- 8009100801 Ack receipt of 800623 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/80-17, 30-270/80-12 & 50-287/80-11 LEMIS R C Region 2, Atlanta. Reactor Operations Nuclear Support Branch 80/08/26 ip
- --8009100807 Responds to NRC 800823 ltr re violations noted in IE lnsp Repts 50-269780-17.50-270780-12 & 50-287780-11 Corrective actions incidents involving failure to perform surveillance are being reviewed & new procedures will be established PARKER.W O Dute Power Co 80/06/23 3pp

- ---8009100811 Forwards TE Insp Repts 50-269/80-17.59-270/80-12 & 50-287/80-11 on 800401-30 & notice of violation LEWIS,R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/05/23 2pp
- --8009100813 Notice of violation from insp on 800401-30
  \* Region 2. Atlanta. Office of the Director 80/05/23 ip
- --8009100816 IE Insp Repts 50-269/80-17.50-270/80-12 & 50-287/80-11 on 800401-30 Noncompliance noted failure to submit 30-day repts when surveillance test frequency was missed MARTIN.R D. Region 2. Atlanta, Reactor Operations Nuclear Support Branch JAPE.F Region 4. Dallas, Office of the Director 80/05/23 11pp
- 8009030605 Submits Revision 3 to util 90~day response to 1E Bulletin 79 018 re Class IE equipment environ qualification Raychem heat shrink tubing, scotth Cast-9, transmitter 0~ring seals & lubricating grease to be replaced during refueling outage THIES A C Dute Power Co 80/08/27 2pp
- 8009110698 Responds to IE Sulletin 80-15 Emergency notification system reviewed Sys is powered by onsite power, but does not have backup onsite emergency power Emergency power supplied by telephone Company PARKER, W D Buke Power Co 80/08/27 2pp
- 8009120343 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Valt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/27
- 8009140833 Ack receipt of 800623 ltr & 0806 supplemental response informing NRC of steps taken to correct violations noted in IE Insg Repts 50-269/80-15 \$50-270/80-10 MURPHY.C & Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/09/04 ip
- --8009160540 Responds to NRC 800710 ltr requesting supplemental response to IE Insp Rept 50-270/80-10 Corrective actions Block 40303 will be modified to meet ASME requirements PARKER.W O Dute Power Co 80/08/06 2pp
- --8009160535 Ack receipt of 800623 ltr responding to 800522 notice of violation Understands supplemental response will be provided by 800803 MURPHY.C E Region 2. Atlanta. Reactor Construction >> Engineering Support Branch 80/07/10 1p
- --8007160541 Responds to NRC 800522 ltr re violations noted in IE losp Repts 50-269/80-i5 & 50-270/80-10 on 800415-17 & 21-23 Corrective actions design of calibr blocks reviewed & will be modified to meet ASME requirements PARKER.N O Duke Power Co 80/06/23 2pp
- --8009160537 Forwards IE Insp Repts 50-269/80-15 & 50-270/80-10 on 800415-17 & 21-23 & notice of violation MURPHY, C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/22 app
- --8009160550 Notice of violation from insp on 800415-17 & 21-23 \* Region 2, Atlanta, Office of the Director 80/05/15 ip
- --8007160552 IE Insp Repts 50-267/80-15 & 50-270/80-10 on 800415-17 & 21-23 Woncompliance noted improperly designed inservice insp calibr blocks
  ECONUMOS.N Region 2. Atlanta, Office of the Director 80/05/15
  7pp
- 8009290297 Forwards IE Circular 80-21. "Regulation of Refueling Crows " No written response required O'REILLY, J P Region 2, Atlanta, Orfice of the Director 80/09/10
- 8009300616 Ack receipt of 800825 itr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-269/80-23. 50-270/80-20 3 50-287/80-17 LEMIS, R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/09/16 1p
- --8009300626 Forwards response to NRC 800730 ltr re violations noted in IE Insp Repts 50-267/80-23.50-270/80-20 \$ 50-287/80-17 Corrective actions informed operations personnel that use of correct & verified procedures must be ascertained FARKER.W D Duke Power Co 80/08/25 3pp

- --8009300630 Forwards IE Insp Repts 50-269/80-23 % 50-270/80-20 % 50-287/80-17 on 800602-30 % notice of violation LEMISR C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/07/30 2pp
- ~-8009300631 Notice of violation from insp on 800602-30 \* Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/07/28 ip
- --8009300640 IE Insp Repts 50-289/80-23,50-270/80-20 & 50-287/80-17
- Noncompliance noted use of Unit 1 procedure to perform periodic test on Unit 2 procedure to perform periodic test on Unit 2 procedure to perform ARTIN.R D. Region 2, Atlanta, Office of the Director MARTIN.R D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 60/07/28 13pp
- R Periodic operating reports b related correspondence
- 8009020044 Forwards "Radioactive Effluent Release Semiannual Rept," Jan-June 1980 PARKER, W O Duke Power Co 80/08/25 1p
- --8009020047 "Radioactive Effluent Rejease Semiannual Rept," Jan-June 1780 R Dute Power Co 80/09/25 App
- 8009090577 Forwards revision to "Radioactive Effluent Release Semiannual Rept," Jan-June 1980 PARKER, W.O. Duke Power Co. 80/09/03 4pp
- --8009090582 Revision to "Radioactive Effluent Relgase Semiannual Rept," Jan-June 1980 Duke Power Co 80/09/03 3pp
- 9009190462 Forwards monthly operating repts for Aug 1980 PARKER.W O Duke Power Co 80/09/15 ip
- ~~8009190473 Monthly operating tepts for Aug 1980 #EAVIS.5 A Duke Power Co 80/09/15 17pp
- S Reportable occurrences, LERs & related correspondence
- 8009030445 Forwards LER 60-024/03L-0 PARKER. W O Duke Power Co 80/03L 80/09/29 300
- --8007030449 LER 80-024/03L-0 on 800731 cable controlling automatic initiation of HPSW pumps was taken out of svc to continue excavation of svc storage facility (SSF) cable trench Caused by conduit hank encased in concrete crossing trench route JONES, J Ł Duke Power Co 80/08/29 1p
- 8009120414 Forwards LER 80-025/03L-0 PARKER.W 0 Dute Power Co 80/09 80/09/05 3pg
- --8009120436 LER 80-025/03L-0 on 800807, keause hydro unit 2 failed to close-in automatically into overhead line Caused by dirty contacts on relay K5 Contacts cleared Replacement relays ordered although not required for safe operation JUNES, J L. Duke Power Co. 80/09/05 ip
- 8009160477 Forwards LER 80-026/03L-0 PARKER: W 0 Duke Power Co 80/09/10 3pp
- -8009160480 LER 80-026/03L-0 on 800811. HPSW pump B declared imperable & removed from svc when water discovered leaking from cooler casing Gaused by ension created by constant water flow Cooler b housing replaced Solenoid valves added JONES. J L Duke Power Co 80/09/10 1p
- DOCKET 50-270 DOONEE NUCLEAR STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8009230296 Requests that all personnel be reminded of purpose of smergency notification sys & health physics network Sys installed for govt use during smergency O'REJELY, J P Region 2. Atlanta, Office of the Director 80/08/22
- G Adjudicatory correspondence
- 8009260664 Forwards order requiring info supporting environ qualification or safety-related electrical equipment Requests submittal of info by 801101 REID,R W Operating Reactors Branch 4 80/08/29 2pp

- --B009260667 Order for mod of Licenses DPR-38,DPR-47 & DPR-55 to add info which fully responds to NRC request for info re environ qualification of safety-related ejectrical equipment info should be submitted by 801101 EISENHUT, D G Division of Licensing 80/08/29 6pp
- J Insurance & indemnity information
- 8009190424 Forwards Endorsement 58 to NELIA Policy NF-182 & Endorsement 43 to MAELU Policy MF-61 SANDERS FD Duke Power Co 80/08/25 3pp
- 8009300428 Advises that invoices for facility indemnity fees should be addressed to WD Parker, not AC Thies PARKER, N 0 Duke Power Co 80/09/24 ip
- P Operating license stage documents & correspondence
- 8009150070 Responds to 800523 recommendations concerning lessons learned from 800226 transient at Crystal River Submits results of investigations re use of atmospheric dump valve at Oconse Units 1-3, AR Unit 1. Davis-Resse Unit 1 & TMI-1 DENTON-H R Diffice of Nuclear Reactor Regulation, Director 80/07/21 2pp
- 8007050343 Discusses void formation in vessel head during 800611 natural circulation cooldown event Requests opinion repotential for voiding phenomenon in B&M designed NSSS CHECK.P 8 Assistant Director for Plant Systems 80/07/28
- 8009020297 Submits interim criteria for shift staffing to all DL & CP licensees & applicants, per NRC 800507 Itr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUR, D & Division of Licensing 80/07/31 7pp
- 8007080080 Forwards draft NUREG-0596, "Functional Criteria for Defounded rather a rest indicated and continue to the rest in the second of the second second
- BOO7230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D G Division of Licensing 80/08/07 40pp
- B007040085 Requests written confirmation of appraisal of critical electrical power generation situation in region served by Duke Power Co NGVAK.T M Assistant Director for Operating Reactors B0/08/11
- 8009160501 Forwards Amends 86.86 % 83 to Licenses DPR-38,DPR-47 % DPR-55 respectively, safety evaluation & notice of issuance & availability REID,R W Operating Reactors Branch 4 80/08/20 2pp
- --8009160502 Amands 86.86 & 83 to Licenses DPR-38.DPR-47 & DPR-58. respectively, incorporating test frequency requirements of 10CFR30, App J, into containment leak test program REID.R W Operating Reactors Branch 4 80/08/20 7pp.
- --8009160506 Safety evaluation supporting Amends 86,86 & 83 to Licenses DPR-38,DPR-47 & DPR-55, respectively \* Office of Nuclear Reactor Regulation, Director 80/08/20 2pp
- --8009160507 Notice of issuance & availability of Amends 86,86 & 83 to Licenses DPR-38,DPR-47 & DPR-55,respectively REID:R U Operating Reactors Branch 4 80/08/20 2pp
- 8009160505 Notification of 800903 meeting w/util & Franklin Research Ctr in Bethesda, MD to review NUREG-0578, Items 2 i 7 A&B FAIRTILE, M B Operating Reactors Branch 4 80/08/21 ip
- 8009020025 Forwards B&W rept. "Evaluation of Instrumentation to Detect Inadequate Core Cooling Prepared for 177 Owners Oroup." supplementing earlier util submittals re Leasons Learned Item 2: 1 3 b No addl instrumentation needed W/o encl PARKER.N D Duke Power Co. 80/08/26. Ip
- 8009100489 Informs NRC that revised radiological ETS "Offsite Dose Calculation Manual" & proposed process control program for solid waste sys will be forwarded by 800930 PARKERIN U Duke Power Co 80/09/03 ip

- 8009190154 Advises of NRC review of util 800328 submittal re standby shutdown facility Pages 2-1.5-1.5-2.5-3.6-3 & 7-1 should be withheld per 10CFR2 790 Util should resubmit document of deletions within 30 days REID.R W Operating Reactors Branch 4 80/09/09 2pp
- 8009250434 informs of acceptability of response to NRC 791109 ltr reportions of ECCS evaluation models dealing w/fuel cladding sucliing & incidence of rupture REID.R W Operating Reactors Branch 4 80/09/09 2pp
- 8007230724 Disagrees w/NRC 800909 ltr re classification of Standby Shutdown Facility licensing document Document should be withheld (ref 100FR2 790) No nonpropietary version will be submitted PARKER. H B Duke Power Co 80/09/17 ip
- 8009300486 Forwards response to NRC 800611 request for change in facility Tech Specs.providing for redundancy in decay heat removal capability No changes necessary to Tech Specs PARKER.N O Duke Power Co 80/09/24 3pp
- G Inspection reports, IE Bulletins & correspondence
- BOD9100058 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Contrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Written response required BYREILLY. J P Region 2, Atlanta, Office of the Director BO/07/24
- DO09040640 Responds to IE Bulletin 80-16 Rosemount Model 1151 & 1152 pressure transmitters w/output codes A or D are used for indicating reactor coolant pressure & providing input to control steam generator level PARKER, H D Duke Power Co 80/07/30 3pp
- 8009030175 Forwards Revision 1 to IE Sulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/15
- 8009i60137 Forwards 1E Circular 80-18, "IOCFR50 99 Safety Evaluations for Changes to Radwasto Treatment Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 60/08/22 to
- 8009170233 Responds to IE Bulletin 80-19. Revision 1. "Failures of Hercory-Netted Matrix Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E " Review indicates relays are not in use at facility PARKER. W O Duke Power Co 80/08/22 ip
- 8007100801 Ack receipt of 800623 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/80-17, 50-270/80-12 & 50-287/80-11 LEHIS.R C Region 2: Atlanta, Reactor Operations Nuclear Support Br
- --B009100807 Responds to NRC 800523 ltr re violations noted in IE Insp Repts 50-269/80-17,50-270/80-12 & 50-287/80-11 Corrective actions incidents involving failure to perform surveillance are being reviewed & new procedures will be established PARKER: N O Duke Power Co 80/06/23 3pp
- --B007100911 Forwards IE Insp Repts 50-269/80-17,50-270/80-12 & 50-287/80-11 on 800401-30 & notice of violation LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/05/23 2pp
- ---8007100813 Notice of violation from insp on 800401-30 • Region 2, Atlanta, Office of the Director 80/05/23 ip
- --8009100816 IE Insp Repts 50-269/B0-17,50-270/B0-12 & 50-287/B0-11 on B00401-30 Noncompliance noted failure to submit 30-day repts when surveillance test frequency was missed MARTIN-R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch JAPE,F Region 4, Dallas, Office of the Director B0/05/23.
- 8009030605 Bubmits Revision 3 to util 90-day response to IE Bulletin 79-01B re Class IE equipment environ qualification Raychem heat shrink tubing, scotch Cast-9, transmitter O-ring seals & Jubricating grease to be replaced during refusing outage THIES, A C Dute Power Co 80/08/27 2pp

- 8009110698 Responds to IE Bulletin 80-15 Emergency notification system reviewed Bys is powered by onsite power, but does not have backup onsite emergency power Emergency power supplied by telephone company PARKER, W O Duke Power Co 80/08/27 2pp
- 8009120343 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover! 480 Volt Type K-6005 & K-DON 6005 Circuit Breakers " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/27
- 8009160533 Ack receipt of 800623 itr & 0806 supplemental response informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/80-15 & 50~270/80-10 MMRPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/09/04 ip
- --8009160540 Responds to NRC 800710 ltr requesting supplemental response to IE Insp Rept 50-270/80-10 Corrective actions Block 40303 will be modified to meet ASME requirements PARKER, W.O. Duke Pawer Co. 80/08/06 2pp
- --8009160535 Ack receipt of 800623 ltm responding to 800522 notice of violation Understands supplemental response will be provided by 800803 KVRPHy.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/10 ip
- --8009160541 Responds to NRC 800322 ltr re violations noted in [£ Insp Repts 50-269/80-15 \$ 50-270/80-10 on 800415-17 & 21-23 Corrective actions design of calibr blocks reviewed & will be modified to meet ASME requirements PARKER. W O Dute Fower Co 80/06/23 2pp
- --8099160537 Forwards IE Insp Repts 59-269/80-15 & 50-270/80-10 on 800415-17 & 21-23 & notice of violation MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/22 2pp
- --8009160550 Notice of violation from insp on 800415-17 & 21-23 \* Region 2, Atlanta, Office of the Director 80/05/15 ip
- --B009160552 IE Insp Repts 50-269/80-15 & 50-270/80-10 on 800415-17 & 21-23 Noncompliance noted improperly designed inservice inspicalibr blocks

  ECOLOMOS, N Region 2, Atlanta, Office of the Director 80/05/15
- 8009290297 Forwards IE Circular 80-21, "Regulation of Refueling Craws" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/09/10
- 8009300616 Act receipt of 800825 ltr informing NRC of steps taken to correct violations noted in IE Insp. Repts 50-269/80-23. 50-227/80-20 t. 50-227/80-17 LEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Br
- --8009300626 Forwards response to NRC 800730 itr re violations noted in IE Insp Repts 50-269/80-23.50-270/80-20 % 50-287/80-17 Corrective actions informed operations personnel that use of correct % verified procedures must be ascertained PARKER.N O Duke Power Co 80/08/25 3pp
- --8009300630 Forwards IE Insp Repts 50-267/80-23 & 50-270/80-20 & 50-287/80-17 on 800602-30 & notice of violation LEMISR C Region 2: Atlanta. Reactor Operations Nuclear Support Branch 80/07/30 2pp
- --8009300631 Notice of violation from insp on 800602-30 # Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/07/28 ip
- --B009300640 IE Insp Repts 50-269/80-23,50-270/80-20 & 50-287/80-17 Noncompliance noted use of Unit 1 procedure to perform periodic test on Unit 2 GRDERS, W. JAPE, F. Region 2, Atlanta, Office of the Director, MARTIN, R. D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/07/28 (3pp
- R Periodic operating reports & related correspondence
- 8009020044 Forwards "Radioactive Effluent Release Semiannual Rept." Jan-June 1990 PARKER.W O Duke Power Co 80/08/25 Ip

- --8009020047 Radioactive Effluent Release Semiannual Rept." Jan-June
  - Duke Pouer Co 83/09/25 6pp
- BOC9090977 Forwards revision to "Radioactive Effluent Release Centaminual Rept " Jan-June 1980 PARKERIN D. Duke Power Co. 80/09/03 4pp
- -- E007070382 Revision to "Padicactive Effluent Release Semiannual Rept," Jan-June 1980 + Dule Pouer Co 80/69/03 3pp
- ECC9190352 Forwards monthly operating repts for Aug 1980 PASKER W D Duke Power Co 80/09/15 1p
- S Reportable occurrences. LERs & related correspondence
- 1009030469 Forwards LER 80-012/031-0 PARVER, W O Dyte Power Co 80/03/29 3pp
- --8009030474 LER 80-012/03L-0 on 800730, w/unit at 59% full power, concentrated boric acid storage tank pump failed to pump to letdown storage tank Cause unknown Pump was repaired by adding oil & increasing stroke of pump JONES, J. Dute Power Co. 80/08/29 ip
- 8009(20418 Forwards LER 80~013/03L-0 PARKER.W O Duke Power Co 80/09 80/09/04 3pp
- --5009120431 LER BO-013/03L-O on 800805.concentrated boric acid storage tank pump failed to pump to letdown storage tank Cause due to suction strainer blockage Suction strainer backwashed & gump verified operable JONES.J L Duke Power Co 80/09/04 1p
- 8007230494 Forwards LER 80-014/03L-0 PARMER.W D Duke Power Co 80/09/18 1p
- --8007230504 LER 80-014/03L-0 on 800822, concentrated boric acid storage JONES J. Dute Power Co. 89/09/19 Jpp
- 6009230509 Forwards LER 80-010/03L-0 PARKER-W B Duke Power Co 80/09/ 80/09/18 1p
- --8009230517 LER 80-010/03L-0 on 800820.2 Low Pressure Svc Water-19 valve failed to open from control room suitch after closing to perform operational valve functional test Caused by failure of torque switch preventing valve opening JONES. J t. Dute Power Co 80/09/19 2pp
- T Hearing transcripts on non-antitrust matters
- E009260313 Submittal of prepared testimony for first hearing session No attempts made to provide complete answers to ASLB 800908 memorandum & order me physical separation of THI units Centificate of Svc enci Related correspondence TROMBRIDGE. OF Metropolitan Edison Co TROMBRIDGE. OF Shaw, Pittman, Potts & Trowbridge 80/09/15 7pp
- --8007260365 "Small Break Operating Guidelines " Related correspondence.
   Babcock % Hilcox Co 69-1106001-00 79/11/30 48pp
- DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION F Security: medical, emergency & fire protection plans
- 9009230197 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for gove use during emergency CRIER. B H Region 1. Philadelphia. Office of the Director GRIER. B H Re. 80/08/22 3pp
- G Adjudicatory correspondence
- 8005220115 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101

  IPPOLITO.T A Operating Reactors Branch 2 80/08/29, 3pp

- --8009220117 Order for mod of License DPR-28 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101 EISENHUT, D.G. Divition of Licensing 80/08/29
- 8009300591 Forwards 800919 order revising 800829 order for mod of OL. in EISENHUT DG Division of Licensing 80/09/19 3pp
- -8009300598 Order revising 800929 order for mod of OL DPR-28, published in 800911 FR. in entirety Info responsive to IE Bulletin 79-01B shall be submitted by B01101 Request for hearing will not stay order effective 800919 UCS petitions discharged EISENHU, D 0 Divisson of Licensing 80/09/19 App
- P Operating license stage documents & correspondence
- 8009110554 Suppls NRC 800707 request for proposed Tech 8pecs changes re scram discharge vol vent 2 drain valves, 2 reactor protection sys 2 control rod block limit switch surveillance requirements Class III license fee to 5e submitted w/change EISENHUT,D G Division of Licensing 80/07/22 22pp
- 8009020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENMUT.D G Division of Licensing 80/07/31 7pp
- 80090B0080 Forwards draft NUREO-0696. "Functional Criteria for Emergency Response Facilities " Commonts requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl. M/o NUREO EISENHUT, D O Division of Licensing 80/08/01 119pp
- B009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D O Division of Licensing 80/08/07 60pp
- 8007040532 Advises that two specific Event 3 valve configurations do not exist at facility per review of response to NRC 800223 ltr "Primary Coolant Sys Pressure Isolation Valves," technical evaluation rept enc1
  IPPOLITO, T A Operating Reactors Branch 2 80/08/08 3pp
- ~~8009040544 "Primary Coolant Eys Pressure Isolation Valves." technical evaluation rept NDELL:P N , STILMELL:T C Franklin Institute/Franklin Research Center NRC-03-79-118 80/07/21 5pp
- 8009190951 Forwards "Mark 1 Containment Long-Term Program SER. Resolution of Generic Technical Activity A-7," NUREO-0661 W/o encl TPPDLITO T A Operating Reactors Branch 2 80/08/20 3pp
- 8009110259 Forwards Amend 57 to License DPR-28, safety evaluation & notice of issuance & availability IPPOLITO. Y A Operating Reactors Branch 2 80/08/22 2pp
- --B0091102B5 Amend 57 to License DPR-28, incorporating limiting conditions for operation expressing max average planar linear heat generation rate timits for fuel in Cycle 7 IPPOLITO.T A Operating Reactors Branch 2 B0/08/22 5pp
- --8009110287 Safety evaluation supporting Amend 57 to License DPR-28
  \* Office of Nuclear Reactor Regulation, Director 80/08/22 4
- --8009110290 Notice of issuance & availability of Amend 57 to License IPPOLITO, T A Operating Reactors Branch 2 80/08/22 2pp
- 8009080375 Proposed Change 90 to amend App A to License DPR-28.deleting containment air sampling sys valves 109-75A-Dit&2 & 109-76A & B from Yech Spec Table 4 7 2b & adding Valves VQ-23,VQ-26. 109-76A & B to Table 4 7 2a Fee and HEIDER.L H Vermont Yankee Nuclear Power Corp 80/08/28 App
- --8009080381 Proposed Change 90 to Tech Spec Tables 4 7 2 a & 4 7 2 b

  \* Vermont Yankee Nuclear Power Corp 80/08/28 2pp
- 8009090478 Responds to NRC 800818 request for add1 info re adequacy of station electrical distribution voltages Add1 60 days needed to provide info due to current in-house work schedule SMITH.R L. Vermont Yankes Nuclear Power Corp. 80/08/29 ip

- 6009120401 Application for Suppl 1 to Proposed Change 81 amending App A Tech Specs of License DRR-28 concerning reactor vessel pressure/temp limitations Class III fee encl HEIDER:L. H Vermont Yankee Nuclear Power Corp 80/09/05 Spp
- --8009120405 Proposed mods to Tech Specs 3 4 & 4 6 re RCS pressure & temp imitations & coolant chemistry & Figure 3 6 i were Vermont Yankee Nuclear Power Corp 80/09/05 4pp
- 8009240548 Confirms util commitment to NRC 791023 "Interim Position on Containment Purging & Venting Pending Resolution of Exolation Valve Operability "Util position util remain in effect pending completion of NRC long-term review IPPOLITO.T A Operating Reactors Branch 2 80/09/10 3pp
- 8009240977 Ack response to NRC 791109 questions re ECCS evaluation models dealing w/fuel cladding swelling & incidence of trupture Response is acceptable EPPOLITO.T A Operating Reactors Branch 2 80/09/10 3pp
- 9309306575 Forwards request for add1 info re RCS vents, needed within 60 days, for completion of review re NUREG-0578 requirements NOVAK, T M Assistant Director for Operating Reactors 80/09/10
- 8009180491 Application for Proposed Change 91 to Tech Specs in response to TMI Lessons Learned Category A stems Revises Tables 3 2 6 & 4 2 & to incorparate instrumentation monitoring requirements & Table & 1 i re shift technical advisor ME(DER, L H Vermont Yankee Nuclear Power Corp 80/07/12 3pp
- --E009180452 Proposed Change 91 to Tech Specs in response to TMI Lessons Learned Category A items Revises Tables 3 2 6 % 4 2 6 to incorporate requirements for monitoring instrumentation & Table 6 1.1 re shift technical advisor \* Vermont Yankee Nuclear Power Corp 80/09/12 6pp
- 8009240207 Describes util alternative for reactor recirculation pump lubrication sys protection, in response to NRC 800220 ltr Proposed method incorporates oil collection sys designed to utihate and Category I seismic event CCRMAY,W F Vermont Yankee Nuclear Power Corp 80/09/19 2pp
- BOO9260458 Forwards "Local Leak Test Program " Implementation of program will require piping mods Anticipated that compliance w/program will be achieved during Fall 1981 refueling outage MARSOLAIS,1. D. Vermont Yankee Nuclear Power Corp. 80/09/19 2pp
- --8009260461 "Local Leak Test Program"

  \*\* Vermont Yankee Nuclear Power Corp 80/09/19 13pp
- BO09260221 Submits add1 info supporting Proposed Change 79 re recirculation pump trip/analog trip sys Info details equipment qualification for radiation exposure & temp & method of radiation dose calculation SMITH.R L. Vermont Yankee Nuclear Power Corp 80/09/23 4pp
- G [Inspection reports, IE Bulletine & correspondence
- BCO9070101 Forwards IE Bulletin 80-07.Suppl 1, "BWR Jet Pump Assembly Failure" Response required GRIER, B H Region 1, Philadelphia, Office of the Director BO/05/13 ip
- B009150130 Forwards IE Insp Rept 50-271/80-09 on 800627 No nencompliance noted GRIER,B H Region 1, Philadelphia, Office of the Director 80/07/18 2pp
- --8009150137 IE Insp Rept 50-271/80-09 on 800627 No noncompliance noted. Major areas inspected systematic assessment of licensee performance program, radioactive matl transport & surveillance
  BRUNNER, E. J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch BDRES, R. J. COLLINS, S. J. Region 1. Philadelphia, Office of the Director 80/07/16 7pp
- BOO9020113 Responds to IE Bulletin 80-17. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR " Mods made to existing vent lines so that valve is effective regardless of component operability other than vent valve TRIBBLE.J E Vermont Yankee Nuclear Power Corp 80/07/28 2pp
- BO09190947 Forwards response to IE Bulletin 80-14 re degradation of BMR scram discharge vol capability No instances of level switches or vent & drain valve failure identified Bulletin required 10 manhours
  TRIBLE, J E Vermont Yankee Nuclear Power Corp 80/07/28 3pp

- 8009110467 Responds to IE Bulletin 79-03A, "Longitudinal Weld Defects in ABME SA-312. Type 304 Stainless Steel Pipe " Facility has determined that none of subj pipe is used or planned for use in safety-related sys MARSOLAISIL D Vermont Yankee Nuclear Power Corp 80/08/05 2pp
- 8009230100 Responds to IE Bulletin 80-17. Suppl 1 Continued analysis of scram discharge vols will identify changes necessary for improvement Operating procedure for control rod drive sys & standby liquid control sys revised
  HEIDERIL H Vermont Yankee Nuclear Power Corp 80/08/11 4pp
- 8009030066 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Morcury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/08/15 1p
- 8009100127 Responds to IE Bulletin BO-17. Suppl 1. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR " Installation of water level monitoring sys by 8009901 is not gossible for listed reasons TRIBBLE. J E Vermont Yankee Nuclear Power Corp 80/08/15 2pp
- 8009120114 Forwards Suppl 3 to IE Sulletin BO-17, "Failure of Control Rods to Insert During Stram at SWR " Written response required ORIER.B H Region 1, Philadelphia, Office of the Director 80/08/22 1p
- 8009180095 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ORIER.B H Region 1, Philadelphia, Office of the Director 80/08/22 1p
- 8009120215 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6005 & K-DON 6008 Circuit Breakers " No written response required ORIER.B H Region 1, Philadelphia, Office of the Director 80/08/27 1p
- 8009230514 Forwards Revision 1 to IE Bulletin 79-26, "Boron Loss From BWR Control Blades " Written response required GRIER.B H Region I, Philadelphia, Office of the Director 80/08/29 ip
- 8009240027 Forwards IE Circular 80-21, "Regulation of Refueling Crews." No written response required ORIER.B H Region 1, Philadelphia, Office of the Director 80/09/10 1p
- 8007240337 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required GRIER.8 H Region 1. Philadelphia, Office of the Director 80/09/12 ip
- R Periodic operating reports & related correspondence
- 8007090535 Forwards "Effluent & Waste Disposal Samiannual Rept. Radiological Impact on Man. Jan-June 1980 " SMITH.R L Vermont Yankee Nuclear Power Corp 80/09/04 1p
- --8007070540 "Effluent & Waste Disposal Semiannual Rept.Radiological Impact on Man.Jan-June 1780 " \* Vermont Yankee Nuclear Power Corp 80/07/04 50pp
- 8009160291 Forwards monthly operating rept for Aug 1780 CDNWAY, W F Vermont Yankee Nuclear Power Corp 80/09/08 1p
- S Reportable occurrences, LERs & related correspondence
- 8009050318 Farwards LER 80-019/01T-1 MURPHY,W P Vermont Yankee Nuclear Power Carp 80/09/02 ip
- ---8009050322 LER 80-019/017-1 on 800516:AEO0 radiation monitors 17-150 A

  B were made inoperative under controlled conditions while
  evaluating low augmented off-gas sys recombiner temps
  Caused by hydrogen recombination upstream of recombiners
  HURPHY:W P Vermont Yankee Nuclear Power Corp 80/09/02 5pp

- 8009190575 PND-1-80-126 on 800908, pictet line was set up at station entrance Licensed operators are honoring picket line Shift staffing plan prepared using supervisory personnel RAYMOND, II J. MARTIN, T. J. RRUNNER, E. J. Region 1. Philadelphia. Office of the Director 80/09/08 3pp
- U Congressional/Executive Correspondence
- 8009150020 Responds to Subcommittee on Nuclear Regulation 780906 ltr na Senator Stafford request for hearing to discuss 1972 memo re pressure suppressing containments.UCS criticisms re ATMS safety problems & West Valley insp problems HENDRIE.J M Commission 80/08/18 2pp
- --8009150039 Discusses AEC 720801 affidavit on rod drop accident Upgrading of rod worth minimizer or acceptance of faster scram times is proposed for ruture BHR reviews Temporary basis recommended in encl nemo acceptable HattORTE. J M Atomic Energy Commission. Deputy Director for Technical Review (Pre-1975) 72/08/04 Ep
- --8009150044 Advises that affidavit on facility rod drop accident allows temporary use of add) operator during startup Permanent fixes usli be required beyond 12-month period BONR 6 Atomic Energy Commission, Directorate of Licensing 72/08/01 1p
- DOCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 8009090882 Requests participation in NRC study of people-related problems in nuclear safeguards Request includes NRC visit to facility to interview security mgt personnel Confidentiality of info will be maintained during all phases of study VARGA.S A Operating Reactors Branch 1 80/08/14 2pp
- 80082803ii Forwards addl info re NUREO-0694 fire protection requirements that will not be met as identified in util 800808 1:19 thrs Addl justification in support of implementation schedule & oversized drawings enci MITIL.R L Public Service Electric & Gas Co of New Jersey 80/08/22 12pp
- --8009040374 "Containment Sump Level Transmitter.Installation Detail " Drawing Number 239086-8-9637-1R-IEC-0549-C2/0 \* Public Service Electric & Gas Co of New Jersey 80/06/24 ip
- --B009040375 "Auxiliary Bidg Reactor Containment & Fuel Handling Area. Elevation 100 Ft " Sheet 1 of 1 \* Public Service Electric & Gas Co of New Jersey 78/09/01 ip
- -8009040378 "Auxiliary Bldg.Elevation 84 Ft.Reactor Containment 78 Ft & 81 Ft & Fuel Handling Area Elevation 85 Ft & 89 Ft & Inches " Sheet 1 of (
  - Public Service Electric & Gas Co of New Jersey 78/09/05
- --8009040379 "Auxiliary Bldg & Reactor Containment Elevation 64 Ft " Public Service Electric & Gas Co of New Jersey 78/08/31 1p
- --8009040381 "Auxiliary Bldg & Reactor Containment Elevation 45 Ft & 9040081 "Mutissary way 5 Ft " Sheet 1 of 1 Poblic Service Electric & Gas Co of New Jersey 78/08/31 1p
- --8009040384 "Auxiliary Bidg & Reactor Containment Section A-A " Sheet 1
- of 1 \* Public Service Electric & Gas Co of New Jersey 77/01/26 1p
- --8009040385 "Auxiliary Bldg & Reactor Containment, Sections B-B & C-C " Sheet 1 of 1

  \* Public Service Electric & Gas Co of Naw Jersey 76/12/27 1p
- --8009040388 "Reactor Containment Slab at Elevation 78 Ft & Elevation 81 Ft " Sheet 1 of 5 \* Public Service Electric & Gas Co or New Jersey 75/06/23 1p
- --8009040392 "Reactor Containment Slab at Elevation 78 Ft & 81 Ft. Sections " Sheet 4 of 5 \* Public Service Electric & Gas Co. of New Jersey 70/12/01 ip
- --B009040394 "Reactor Containment Internat Walls & Reactor Foundation Plan Elevation 90 ft " Sheet 1 of 15 \* Public Service Electric & Gas Co. of New Jersey 71/07/06 1p

- ---B009040396 "Reactor Containment Internal Walls & Reactor Foundation Plan Elevation 94 Ft." as-built Sheet 2 of 15 \* Public Service Electric & Gas Co of New Jersey 76/03/23 10
- --- 8007040378 "Reactor Containment Internal Walls & Reactor Foundation Plan - Elevation 104 Ft " Sheet 3 of 15 \* Public Service Electric & Gas Co of New Jersey 74/08/08 1p
- --8009040399 "Reactor Containment Internal Walls & Reactor Foundation, Sections," as-built Sheet & of 15 \* Public Service Electric & Gas Co. of New Jersey 76/03/23 ip
- --8009040402 "Reactor Containment Internal Walls & Reactor Foundation. Sections " Sheet 5 of 15 \* Public Service Electric & Oas Co of New Jersey 75/06/24 ip
- --8009040403 "Reactor Containment.Reactor Pit " Sheet i of 2 \* Public Service Electric & Gas Co. of New Jersey 76/ 76/01/28 ls.
- --8007040405 "Reactor Containment, Reactor Pit," as-built Sheet 2 of 2 \* Public Service Electric & Gas Co of New Jersey 74/01/29 1
- --8009040407 "Reactor Containment Internal Walls & Reactor Foundation. Sections " Sheet 7 of 15 # Public Service Electric & Gas Co of New Jersey 71/03/10 ip
- ---8009040408 "Reactor Containment Internal Walls & Reactor Foundation, Reinforcement -- Plans & Sections," as-built Sheet 13 of 15 \* Public Service Electric & Gas Co of New Jersey 76/03/22 19
- --8009040410 "Reactor Containment Internal Walls & Reactor Foundation-Reinforcement Plans & Sections " Sheet 14 of 15 \* Public Service Electric & Oas Co of New Jersey 74/03/06. 1p
- --S009040411 "Reactor Containment Drain Trench Elevation 81 Ft & 78 Ft --Bump Pit Elevation 54 Ft & Inches & 72 Ft 7 Inches \* Sheet 1 of 1
  - Public Service Electric & Gas Co of New Jersey 77/08/08
- 8009230193 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency GRIER, B H Region 1, Philadelphia, Office of the Director 80/08/22 3pp
- **Q** Adjudicatory correspondence
- 8009190283 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 VARGA. S.A. Operating Reactors Branch 1 80/08/29 2pp
- --8009190269 Order for mod of License DPR-70 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted EISENHUT, DO Division of Licensing 80/08/29 App
- P Operating license stage documents & correspondence
- 8009090792 Advises that control rod guide thimble tube wear issue is resolved for 17 x 17 Westinghouse fuel assemblies at facility, based on encl\_evaluation Operating Reactors Branch 1. 80/07/22 4pp VARGA, S A
- 8009020297 Submits interim criteria for shift staffing to all OL & CP licensess & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D O Division of Licensing 80/07/31 7pp
- BOO9080080 Forwards draft NUREC-0496. "Functional Criteria for Emergency Response Facilities." Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREC-04976 encl. W/o NUREC EISEMHUT. D G Division of Licensing 80/08/01 119pp
- B009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend.

  EISENRUI-D G Division of Licensing 80/08/07 40pp

- 8009190774 Forwards revised Westinghouse STS 3 9 8 2.3 9 10 & Bases 3/4 9 8 & 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NOUVAK, T M Assistant Director for Operating Reactors 80/08/15
- --8009190817 Revised Westinghouse STS 3 9 8 2.3 9 10 5 Bases 3/4 9 8 5 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods
  \* Assistant Director for Operating Reactors 80/06/23 21pp
- B009150511 Forwards request for add1 info re plant electric distribution sys Details re capability of plant to operate w/one yower transformer out of svc needed to camplete NRC review VAROA,8 A Operating Reactors Branch 1 80/08/18 3pp
- 8009120513 Forwards questions pertaining to turtle specimen collected from intake structure at unit VARGA.S A Operating Reactors Branch 1 80/08/26 3pp
- 8009180518 Requests compliance w/QA procedures for sampling fuel oil described in Reg Guide 1 137 Justification needed reposition that diesel fuel oil need not be included in QA program Responser requested within 20 days VARQA,8 A Operating Reactors Branch 1 80/08/26 2pp
- BO09160401 Requests that util response to NRC B00702 ltr be delayed 90 days after formal issuance of Unit 2 Tech Specs Tech Spec amends per TMI Lessons Learned Category A requirements for Unit 1 will be implemented after issuance of Unit 2 CL 4. ISBLIZZI.FP Public Service Electric & Gas Co of New Jersey B0/09/09 1p
- BO09250260 Requests amend & analysis of change to License DPR-70 re encl safety Tech Specs for refueling operations Class III amend fee encl LIBRIZZI.F P Public Service Electric & Oas Co of New Jersey
- 8009270061 Submits description of alternative proposal for providing assurance that inadvertent failure of suction valve from auxiliary feedwater storage tank will not result in degraded condition of auxiliary feedwater sys
  HITLLR L Public Service Electric & Gas Co of New Jersey
  B0/09/23 2pp
- 8009300503 Advises of util review & plans re Cycle 3 reload core Postulated events are within allowable limits Application for amend to license is not required Reload core design will be verified during startup physics testing program LIBRIZZI.FP Public Service Electric & Gas Co of New Jersey BO/09/24 3pp
- 8009300512 Ack receipt of 800826 ltr requesting addl info re collection of loggerhead sea turtles & Kemp Ridley sea turtles Responses enci
  LIBRIZZI,FP Public Service Electric & Gas Co of New Jersey
  80/09/24 ip
- ---8009300518 Forwards list of questions re specimens of Atlantic loggerhead turtle & Kemp Ridley sea turtle Response requested within 30 days of receipt of ltr VAROA B A Operating Reactors Branch 1 80/08/26 19pp
- O Inspection reports, IE Bulletins & correspondence
- BOO9080330 Responds to IE Bulletin 80-05 Per 800606 response, subsequent investigation revealed two addl tanks which could be subjected to conditions' that might cause inward buckling SCINEIDER.FW Public Service Electric & Gas Co of New Jersey 80/07/29 ip.
- BOO9090230 Forwards add1 response to IE Bulletin 79-27 re loss on nonclass IE instrumentation Evaluation of feasibility of design mods completed & results encl BCHNEIDER: FW Public Service Electric & Cas Co of New Jersey 80/07/31 9pp.
- 8009030091 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required ORIER.B H Region 1, Philadelphia, Office of the Director BO/08/15 1p

- 8009180042 Forwards IE Circular 80-18, "(OCFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/08/22 1p
- 8009120206 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Typo K-6005 & K-DON 6005 Circuit Breakers " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/08/27 1p
- 8009240045 Forwards IE Circular 80-21, "Regulation of Rafueling Crews" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/09/10 ip
- B009240355 Forwards IE Info Notice B0-32. "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director B0/09/12 ip
- R Periodic operating reports & related correspondence
- 8009050290 Forwards "Radioactive Effluent Release Rept, Jan-June 1980 " LIBRIZZI,F P Public Service Electric & Oas Co of New Jersey 80/08/29 1p
- ---8009050294 "Radioactive Effluent Release Rept, Jan-June 1980 "

  \* Public Service Electric & Gas Co of New Jersey 80/08/31
  37pp
- 8009160298 Forwards monthly operating rept for Aug 1980 MIDURA.H J Public Service Electric & Gas Co of New Jersey 80/09/10 ip
- --8009160300 Monthly operating rept for Aug 1980 MILLER, L K Public Service Electric & Gas Co of New Jersey 80/09/10 18pp
- 9 Reportable occurrences. LERs & related correspondence
- 8009110663 PNO-1-80-110 on 800725, IBEN union went on strike Unit 1 operations are continuing w/licensed supervisory personnel All phone lines at facility have been disabled BRIOOS.L., KEIMIG.R., SRUNNER, E.J. Region 1, Philadelphia, Office of the Director 80/07/25 ip
- B009090593 Forwards LER 80-043/03L-0 LIBRIZZI.F P Public Service Electric & Gas Co of New Jersey B0/08/28 2pp
- --8009070575 LER 80-043/03L-0 on 800801, during routine surveillance of control console, water level in refueling water storage tank determined to be below min level (350,000 gallons) Cause due to addition of water to spent fuel pit Yank refilled NEWMAN.R J Public Service Electric & Gas Co of New Jersey 80/08/28 1p
- ---8009090589 Updated LER 79-004/03X-1 on 790103, during normal operations, status alarm panel indicated loop 1 steam pressure 100 psi less than loop 4 Steam pressure channels checked & loop 4 Channel 4 read 100 psi high Caused by frozen sensing line KAPPLE, A W Public Service Electric & Oas Co of New Jersey 80/09/02 ip
- 8009090587 Forwards updated LER 79-057/01X-1 LIBRIZZI,F P Public Service Electric & Gas Co of New Jersey 80/09/04 ip
- --8009090591 Updated LER 79-057/01X-1 on 790907, during IE Bulletin 79-14 insp of pipe hangers on Seismic I sys, three hangers found to hve broken weld, bolt & pipe guide Caused by irregular pulsations of charging pump 13, stressing supports KEPPLER, A W Public Sprvice Electric & Gas Co of New Jersey 80/09/04 2pp
- 8009120357 Forwards LER 80-044/03L-0 LIBRIZZI,F P Public Service Electric % Gas Co of New Jersey 80/09/04 2pp

# DOCKETED ITEMS

- ---8007120372 LER 80-044/03L-0 on B00805 during routine containment entry, containment air lock became inoperable Caused by broken roller on outer door Roller replaced & tested satisfactorily MURPHY.M J Public Service Electric & Gas Co of New Jersey 80/09/04 18
- 8009120375 Forwards (ER 80-045/03L-Q LIBRIZZI.F P Public Service Electric & Qas Co of New Jersey 80/09/04 2pp
- --8009120382 LER 80-045/03L-0 on 800805.air particulate detector pump seried Apparently caused by equipment failure Pump replaced MURPHY. M J Public Service Electric & Gas Co of New Jersey 80/09/04 2pp
- 8009120424 Forwards LER 80-044/03L-0 LIBRIZZI,F P Public Service Electric & Qas Co of New Jersey 80/09/04 2pp
- --800912042B LER 80-046/03L-0 on 800810.during routine operation, steam generator level feed flow-steam flow mismatch circuit 12 failed Caused by failure of companator in circuit Unit replaced 8 tested satisfactorily MURPHY.M J Public Service Electric & Oas Co of New Jersey 80/09/04 lp
- 8009300633 PNS-I-80-021 on 800910, potential act of sabotage may have occurred when high chloride concentrations were found in hydratine addition tank for auxiliary feed water after anonymous caller gave notice of such problems DEVLIN. J. MARTIN. W. KLEIMIG. R. Region I. Philadelphia, Office of the Director 80/09/12 ip

### V Operator Examinations

- 8009120669 Refers to 800801 discussion w/J Zupko & 800804 telcon w/F Schneider re training & qualification for position of shift technical advisor Qualifications for position documented in Suppl 4 to facility SER GRIER, B H Region 1, Phaladelphia. Office of the Director 80/08/05 10
- 8009180306 Summary of 800805 meeting u/applicant in Bethesda.MD re operator exam results KERRIOAN.J Licensing Branch 3 80/08/21 App
- 8009110323 Notifies that all reactor operators & senior reactor operators received low power test program training Lists operators not trained because unit taken to Mode & operation on 800808 due to control rod drive mechanism vent leakage ECKERTIR M Public Service Electric & Oas Co of New Jersey 80/09/05 1p
- 8007230368 Requests waiver of 6-month experience requirement for three interim shift technical advisors Maiver will expedite licensed operator staffing plan Personnel info encl available in Central Files only LIBRIZZIF P Public Service Electric & Oas Co. of New Jersey BD/09/10 2pp

#### DOCKET 50-273 BEZNAU NUCLEAR STATION, UNIT

- 4 Inspection reports, IE Bulletins & correspondence
- 8009150495 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE BHR Facilities " No specific action or response requested KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/20 in
- DUCKET SO-274 U.S. GEOLOGICAL SURVEY RESEARCH REACTOR
- O Inspection reports, IE Builetins & correspondence
- 8009150495 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Red Drive Scram Function & Nonessential Control Air at Certain OE BWR Facilities "No specific action or response requested KEPPLER. J O Region 3. Chicago, Office of the Director 80/08/20 to

- DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8009020263 Forwards response to questions re Catagory 1 concrete masonry walls, sample calculation 5 pertinent location drawings, in response to NRC 800421 ltr CRANE, P A Pacific Gas 5 Electric Co 80/08/27 32pp
- --8009020265 "Plan Area A Elevation 107 Ft "
  \* Pacific Gas & Electric Co 79/12/11 1p
- --8009020268 "Plan Area H Elevation 100 Ft "
  \* Pacific Gas & Electric Co 78/02/24 ip
- --B007020269 "Plan Area A Elevation 119 Ft "
  # Pacific Gas & Electric Co 80/07/15 ip
- --8007020270 "Plan Area H Elevation 115 Ft "

  \* Pacific Gas & Electric Co 79/09/22 1p
- --8009020272 "Plan Area H Elevation 128 Ft "
  \* Pacific Gas & Electric Co 78/10/30 1p
- --8009020274 "Plan Area K Elevation 185 Ft "
  \* Pacific Gas & Electric Co 78/11/01 ip
- --8009020275 "Finish Schedule & Interior Details "
  \* Pacific Gas & Electric Co 79/12/12 1p
- ---BO09020277 "Miscellaneous Concrete Block Details "
  # Pacific Oas & Electric Co 78/09/27 ip
- 8009110707 Forwards request for add1 info to continue review & evaluation for full power GL Info should be provided re low power turbine discs & rotors & evaluation of turbine missiles

  SCHMENCER, A Licensing Branch 3 80/08/27 7pp
- 8009090544 Advises that habitability aspects of facility control room comply w/requirements of Reg Quides 1 78 % 1 95 % BRP. Sections 2 2 1-3 % 6 4 as specified in NUREO-0660.per NRC 800507 request Conclusion confirmed in Suppl 9 to SER CRANE.P A Pacific Oas & Electric Co. 80/09/03 1p
- 8007180486 Forwards Revision 4 to "Description of Sys Interaction Program for Setsmically-Induced Events " Requests that recetpt of rept be ack CRANE.P A Pacific Gas & Electric Co 80/07/16 ip
- --8009180493 "Description of 8ys Interaction Program for Smismically-Induced Events," Revision 4 \* Pacific Gas & Electric Co 80/08/29 92pp
- 8009250268 Forwards response to NRC 800606 itr requesting addl info re shielding review containment monitors & iodine sampling at facilities Monitors are mutually redundant using separate power supplies from separate vital instrument busses CRANE.P A Pacific Gas & Electric Co 80/09/22 6pp
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8009090195 Forwards Suppl 10 to facility SER covering TMI-2-related matters W/O encl SCHMENCER,A Licensing Branch 3 80/08/15 5pp
- F Security, medical, emergency & fire protection plans
- 8009030337 Notifies of 800819,22 & 30 regional workshops re development of guidance for acceptable method for coping w/emergencies at facility Requests that representative be sent Subj areas to be discussed include function of facilities & location ENGELMEN.R H Region 5, San Francisco, Office of the Director 80/08/12 2pp
- 8009230337 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency ENGELKEN, RH Region 5, San Francisco, Office of the Director
- 8009150565 Requests additing to commitments to NRC evaluation of emergency preparedness program for conformance w/NUREG-0654 TEDESCO,R L. Assistant Director for Licensing 80/08/26 9pp

- B009090412 Requests clarification of apparent omission of 1tr of agreement between util & Field Ranch on Page 5-6 of Feb 1980 Energency Plan Revision 2. App 7 GCHMEMCER. A Licensing Branch 3 80/08/30 3pp
- BD09290049 Forwards S Schwencer 800910 memo to HR Denton ru alleged inaccuracies in emergency plan text Requests assistance in determination of substantiation of alleged inaccuracies TEDESCO.R L Division of Licensing 80/09/11 ip
- 8009220220 Forwards lighting maps of protected area of facility in response to NRC request Maps withheld (ref 10CFR2 790) ROSE.D & Los Alamos Scientific Laboratory 80/09/17 ip

## G Adjudicatory correspondence

- 8009030157 Executed amended affidavit of nondisclosure protecting licenses physical security plan Certificate of Svc encl LEMIS.W L Affiliation Unknown 80/08/20 app
- BOOGOGOÉBY Response in opposition to Governor of CA motion for revision of nondisclosure affidavit re security plan Takes exception to Governor of CA BOOBIA & 19 ltrs submitted in response to ASLAB order Certificate of Svc encl NDRTON.B., GEHR.A C., FURBUSH,M H. Pacific Gas & Electric Co BO/OB/21 7pp
- BD09020071 Motion for JE Luco & MD Trifunac to provide testimony by 800905 instead of B00902 Bacretarial help unavailable MORDLINORER, MS Office of the General Counsel B0/08/27 ip
- 8009030112 Order scheduling Sept-Nov 1980 security plan hearings Parties may move for supplemental evidence re issues reopened in seismic ALAB-998-by 800919 State of CA motion to revise nondisclosure affidavit denied BIBHOP.C J Atomic Safety and Licensing Appeal Panel 80/08/28
- 8009030699 Response to ASLB BOOBIA order re util motion to load fuel & for low power tests Covernor of CA & joint intervenors' replies should be stricken as failures to make substantive responses Certificate of Svc encl CRANE, P A , GEHR, A C , NORTON, B Pacific Gas & Electric Co 69/09/28 7pp
- BOO9110019 Request for 800925 site insp visit Becurity plan w/maps, diagrams & safeguards contingency plan must be available for seview by HH Brown.LC Lanpher,LO Giuffrida.RE White & DR Sievers who will undertake visit BROHN.R H , GEORGIOU.B S , LANPHER.L C California, State of BO/09/08 2pp
- BO09150404 Response to ASLB BO0B14 order re util BO0804 motion for low power tests Urges summary dismissal of motion Security & saismic issues not yet resolved & are needed for low power testing BROWN.H H . LANPHER.L C California, State of BROWN.H H . Hill Christopher & Phillips 80/09/11 4pp
- 8009160234 Response to ASLB 800814 order re util motion for low power testing Urges dismissal of motion due to reopening of record on security plan & seismic design Late discovery of Hosgri fault warrants consideration of Class 9 accidents FLEISCHAKER, D Ban Luis Obispo Mothers for Peace, FLEISCHAKER, D Fleischaker, D 8 80/09/ii 5pp
- 8009160360 Forwards JF Devine & RF Yerkes combined testimony w/latter prof qualifications,per ASLB 800819 memorandum & order Explains tvc process re repts mentioned in testimony XETCHEN,E 0 Hearing Branch 4 80/09/12 2pp
- --8009160363 Combined testimony in response to ASLB 800819 memorandum & order on Question 9 re geology & seismology repts New data & conclusions re LNO repts have no impact on USOS position RF Yerkes prof qualifications encl DEVINE.JF, YERKES.RF Interior.Dept of, Geological Survey 80/09/12 App
- B009190036 Forwards B00B19 FR notice re upgraded emergency plan reculations DAVIB:L D Hearing Branch 4 80/09/15 19pp
- BOG9220406 Response in opposition to util & NRC objections to State of CA 800902 statement of security plan issues upon which participation is requested Challenged subjs are responsive to ASLB 800808 fourth prehearing conference order BROWN, H H, LANPHER, L. C, GEORGIOU, B S California, State of 80/09/15 4pp

- 8009220262 Forwards plaintiff. San Luis Obispo Mothers for Peace, complaint for declaratory judgement, injunctive relief & mandamus, disqualifying JM Hendrie from further participation in OL proceedings
  FLEISCHAKER, D. Fleischaker, D. S. FLEISCHAKER, D. San Luis Obispo Mothers for Peace 80/09/16 20pp
- 8009230616 Correction to State of CA 800908 interrogatories directed to NRC re-security plan proceeding Certificate of Svc encl Related correspondence BRCWK.H H . LAMPHER.L C . GEORGIOU.B S California. State of 80/09/16 4pp
- 8009240544 Forwards RB Hubbard affidavit re need for Class 9 accident analysis to accompany joint intervenors' reply to ASLB 800814 order Related correspondence FLEISCHAKER, D Fleischaker, D S 80/09/19 1p
- ~-8009240546 Affidavit re need for Class 9 accident % sys reliability analyses of facility by util Analysis needed due to effect of reactor contamination on economic cost & health risks CEG 800320 ltr encl Related correspondence HUBBARD,R 8 MHB Technical Associates 80/09/17 1Bpp
- --8009240550 Submits conclusion of study on NRC regulations & policy re environ analysis of possible nuclear accidents under NEPA Typical EIS does not consider or analyse possibility of major accident in Class 9 category SPETH O Council on Environmental Quality 80/03/20 4pp
- 8009260469 Notice of 801020 evidentiary hearings in San Luis Obispo.CA re ASCAB 800624 decision.ALAB-578, which reopened seismic issues BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/09/23

#### H General correspondence

- 8007070534 Urges use of influence for speedy & successful approval of facility Industrial & agricultural production could be Jaopardized SLOTT, N Affiliation Uninown 80/07/23 ip
- 8009110382 Urges opening of facility as necessary enterprise in area Newspaper articles encl BRADBURY,V A Affiliation Unknown 80/08/05 4pp
- 8007170200 Responds to 800326 ltr to President Carter re delays in licensing process Delays attributed to seismic re-evaluation of facility, lessons learned from TM1 accident ty public hearings re safety & security SCHWENCER, A Licensing Branch 3 80/08/22 5pp
- 8009030581 Requests that facilities be certified for startup operations & plans for RY81-82 be devioped w/o delay.CA could face serious power shortages Electronics industry & aconomy could be adversely affected OARCIA.M California, State of 80/08/25 1p
- 8009090342 Urges denial of licensing Diablo Nuclear power plant & any other plants
  SCHUMGHER.J Affiliation Unknown 80/08/27 1p
- 8009100457 Ack receipt of 800705 ltr & forwards Friends of the Earth Class 9 petition & Director's decision on petition W/o encl SCHWENGER, A Licensing Branch 2 80/08/27 2pp
- --B009100463 Requests Director's decision on Friends of the Earth petition to consider Class 9 accidents in supplemental EIS FRIESEMA.H P Northwestern Univ B0/07/05 1ρ
- B009220042 Responds to 800319 ltr opposing licensing of facilities NRC has reacted positively in light of TMI accident to improve safety at all nuclear plants in operation & under const SCHMENCER, A Licensing Branch 3 80/09/03 ip
- 8009180248 Responds to 800422 ltr to President Cater re potential radiological risks at facility NRC has re-examined plant for conformance to fuel loading & low power testing requirements

  8008180248 Responds to 800422 ltr to President Cater re potential
- 8007270054 Forwards 800830 ltr to util requested by C Neiburger of Telegram Tribune on 800909 re alleged inaccuracies in emergency plan text Matter must be resolved prior to issuance of full power Cl.
  EISENHUT, D G Division of Licensing 80/09/10 1pp

- --8009290057 Responds to 800721 Itr expressing conterns to util emergency plan Agreement between Field Ranch & util the emergency evaruation route has been requested from util Matter util be resolved before NRC issues full power OL DEMYON. HR Office of Nuclear Reactor Regulation, Director BO/09/05 | 10
- B009300295 Responds to 790920 itr to President Carter to concern over effect of low level radiation, storage & transportation of high level radiaste & ability of plant to withstand seasons activity Fact sheets addressing concerns that MIRAGLIA.F Litensing Branch 3 80/09/19 opp
- --B0093gD305 Forwards misdirected T Gener 790920 ltr to President Carter re effects of low level radiation Requests response RATHKOPF.C L Energy. Dept of 80/01/22 3pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8009090514 Forwards Amend 85 to DL application, including matl for Chapters 4,13,14 & 17 of FSAR CRANE,P A Parific Gas & Electric Co 80/09/03 2pp
- --8009090520 Amend 85 to OL application including math for FSAR Chapters 4,13,14 & 17 SCHUYLER.J O Pacific Gas & Electric Co 80/08/28 7pp
- ~-B607090526 Revision to FSAR, including math re QA & conduct of operations for Chapters 4, 13, 14 & 17 \* Pacific Gas & Electric Co B0/08/31 403pp
- P Operating license stage documents & correspondence
- 800908080 Forwards draft hUREG-0696, "Functional Criteria for Emargancy Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 and W/o NUREG EISENHUT, D G Division of Licensing 80/08/01 119pp
- Q Inspection reports: IE Bulletins & correspondence
- 8009260299 Forwards IE Info Natice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange " No written response required ENGELXEN.R H Region S. San Francisco, Office of the Director 80/08/07 ip
- 6009230212 Forwards IE Insp Rept 50-275/80-15 on 800701-31 No noncompliance noted CREMS: J L Region 5. San Francisco, Reactor Operations Nuclear Support Branch 80/08/12 2pp
- --8007230217 IE Insp Rept 50-275/80-15 on 800701-31 No noncompliance noted Major areas inspected preoperational testing.plant tour.fire protection/grevention & operator training STERUBERG.D M. Region 5. San Francisco, Reactor Operations Nuclear Support Branch YOUNG.T. BAGAQLIO.M. Region 5. San Francisco, Office of the Director BO/08/11 4pp
- 8009030278 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Mercury-Metted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Hritten response required ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/208/15 1p
- 8009290305 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Stude " No written response required ENGELKER,R H Region 5, San Francisco, Office of the Director 80/08/18 4sp
- 8009160181 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ENDELKBUR H Region 5, San Francisco, Office of the Director 80/08/22 lp
- 800912045B Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover: 480 Volt Type K-600S i K-DDN 600S Circuit Breakers " No written response required ENGELERIR H Region 5, San Francisco, Office of the Director 80/08/27 ip
- T Hearing transcripts on non-antitrust matters
- 1009090779 Firstmony in response to ASLAS 800807 order, ALAB-604 LUCQ, E , NORDLINGER, M S Luca, J E 80/09/04 71pp

- 8009090652 Testimonų in response to ASLAB 800807 order, ALAB-604 TRIFUNAC,M Southern Callfornia. Univ of NORDLINGER,M B Office of the General Counsel 80/09/05 182pp
- --8009090656 "Preliminary Empirical Models for Scaling Absolute Acceleration Spectra" TRIFUNAC, M.D. ANDERSON. J.O. Southern California, Univ. 6# 77-03 77/08/31 143pp
- ~~8009090664 "Dependence of Pauedo Relative Velocity Spectra of Strong Motion Acceleration on Depth of Sedimentary Deposits," TRIFUNAC.M D., LEE,V W. Southern California, Univ. of CE~79~02 79/02/28 95pp
- --8009090672 "Dependence of Fourier Amplitude Spectra of Strong Motion Acceleration on Depth of Sedimentary Deposits " Supporting documentation encl TRIFUNAC.M D. LEE.V W. Southern California, Univ. of CE-78-14 78/12/31 130pp
- 8009160360 forwards JF Devine & RF Yerkes combined tastimony w/latter prof qualifications, per ASLD 800819 memorandum & order Explains svc process re repts mentioned in testimony KETCHENEO Hearing Branch 4 80/09/12. 2pp
- ~-8009160363 Combined testimony in response to ASLB 800819 memorandum & order on Guestion 9 re geology > seismology repts New data & conclusions re LNG repts have no impact on USOS position RF Yerkes prof qualifications encl BEVINE.J F. YERKES.R F. Interior.Dept of, Geological Survey 80/09/12 6pp
- U Congressional/Executive Correspondence
- 8009110514 Responds to 800530 ltr re facility licensing status Major const completion delays result of seismic re-evaluation & of TMI-2 Lessons Learned Task Force recommendations Facility will not be authorized to load fuel until approx 1981 DIRCKS.W J Office of the Executive Director for Operations. 80/08/21 2pp
- --8009110920 Urges prompt completion of necessary requirements for granting facility license Delays result in increase in constituent util bills Requests licensing status BHUMNAY,N D House of Rep 80/05/30, ip
- 8009220255 Provides status of MRC efforts re final licensing of facility Further actions will be required by ASLAB, ASLB & Commission
  DIRCKS W J Office of the Executive Director for Operations
  80/09/17 2pp
- DOCKET 50-277 PEACH BOTTON ATOMIC POWER STATION, UNIT 2

  E NRC Safety Evaluation Report (SER), supply & correspondence
- 8007020053 Forwards draft comments on SER ltems 3 2 3(1)-(4),3 2 9, 3 2 13-15 t 3 2 4 from fire protection review Final Item 3 1 8(2) will be sent shortly HALLRE Brootheven National Laboratory 80/08/21 5pp
- F Security, medical, emergency & fire protection plans
- 8009250274 Requests permission to record conversations on dedicated talephone connection installed between facilities & NRC Bethesda. KD headquarters

  GUONEY, If J Philadelphia Electric Co 80/04/18 ip
- 8009090364 Forwards amended fire protection review. Item 3 1 1 re Area 6 cable spreading room fire detection sys HALL:RE Argonne National Laboratory 80/07/15 2pp
- 8009040079 Forwards Suppl 1 to SER re fire protection program Evaluation approves certain proposed mods & resolves certain issues identified in NRC 790523 evaluation REID.R W Operating Reactors Branch 4 80/08/14 2pp
- --8009040083 Suppl 1 to SER re facility fire protection program
  \* Operating Reactors Branch 4 80/08/14 App
- 8009090362 Forwards comments on fire protection review Items 3 2 3(1), (2), (3), (4), 3 2 9, 3 2 13, 3 2 14, 3 2 15 6 3 2 4 re fire detection sys & ventilation ducts F;nal Item 3 1 8(2) comments will be sent shortly HALL.RE Brookhaven National Laboratory 80/08/21 6pp

- 8009230191 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Bys installed far govt use during emergency GRIER.B H Region i. Philadelphia. Office of the Director BO/08/22 3pp
- 8009090424 Forwards info on Item 3 2 8(1) & (2) re fire barrier penetration seals for fire protection review HALL,RE E Brookhaven National Laboratory 80/08/26 2pp
- 8009150478 Forwards revised plant security personnel training & qualification plan Plan withheld (ref 10CFR2 790)
  BRADLEY, E. J. Philadelphia Electric Co. 80/09/11 3pp
- 8009300230 Forwards Suppl 2 to safety evaluation re fire protection program in which mod schedule is in accordance w/Amends 53 % 53 to DPR-44 % DPR-56 respectively REID.R W Operating Reactors Branch 4 80/07/15 2pp
- --8009300235 Suppl 2 to safety evaluation supporting fire protection program
  4 Operating Reactors Branch 4 80/09/15 4pp

### Adjudicatory correspondence

- 80091903A2 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 REID.R W Operating Reactors Branch 4 80/08/29 2pp
- --B009190369 Order for mod of Licenses DPR-44 & DPR-56 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101
  EISENHUT.D 0 Division of Licensing 80/08/29 App
- P Operating license stage documents & correspondence
- BOOTII0554 Suppls NRC BOO707 request for proposed Tech Specs changes re scram discharge vol vent & drain valves. & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT.D O Division of Licensing 80/07/22 22pp
- 8009020297 Submits interim criteria for shift staffing to all GL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENRUT, D O. Division of Licensing 80/07/31 7pp
- BOOPOBOOSO Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/O NUREO EISENHUT
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D Q Division of Licensing 80/08/07 60pp
- 8009020154 Approves Class III fee refund for 800730 license amend re 800728 application for max permissible water temp in containment suppression pool MILLER.N D License Fee Management Branch 80/08/13 Ip
- 8009030352 Advises that high range noble gas monitors described in util 800102 & 0604 ltrs satisfy Lessons Learned Short-Term Item 2 1 8 b & TMI Action Plan Item III D 2 1 HEID-R U Operating Reactors Branch 4 80/08/14 2pp
- BOO9190953 Forwards "Mark I Containment Long-Term Program SER Resolution of Generic Technical Activity A-7," NUREG-0461. M/o encl REID: R W Operating Reactors Branch 4 80/08/20 2pp
- 8009130033 Forwards request for addl info on degraded grid voltage re NRC review of application to amend Tech Specs to provide second level of undervoltage protection w/time delay for safety-related loads REID.R N Uperating Reactors Branch 4 80/08/21 3pp
- 8009220384 Requests add1 fees re 800808 application proposing seismic munitoring Teck Bpccs Application requires Classes III & I fees pather than submitted Classes II & I fees DIGOS.R M. License Fee Management Branch 80/08/26 ip

- 8009250430 Informs of acceptability of response to NRC 791109 ltr reportions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of tupture REID.R W Operating Reactors Branch 4 80/09/09 2pp
- G009180304 Forwards application for amond of Licenses DPR-44 & DPR-56 changing Tech Specs in response to NRC 800702 ltr re THI Lessons Learned Category A requirements Class III fee encl BRADLEY,E J. Philadelphia Electric Co. 80/09/15 1p
- --8009180316 Application for amend of Licenses DPR-44 & 96 changing Tech Specs 3 2 F,4 2 F,6 2-2.6 3-6 5.6 14 & 6 15 in response to TMI Lessons Learned Task Force Category A requirements Ceptificate or Svc entil BAUER,E 0 , BRADLEY,E J Philadelphia Electric Co 80/09/15
- --8009180335 Proposed Tech Specs 3 2 F.4 2 F.6 2-2.6 3-6 5.6 14 % 6 15 re water level instrumentation & safety relief valve position indication Revision made in response to TMI Lessons Learned Task Force Category A requirements # Philadelphia Electric Co 80/09/15 7pp
- 8009300067 Forwards comments on NUREC-0696, "Functional Criteria for Emergency Response Facilities " Delay of implementation of data transmission requirements recommended until specific transmission requirements issued DOYER.V S Philadelphia Electric Co 80/09/23 App
- G Inspection reports. IE Bulletins & correspondence
- 8009090105 Forwards IE Bulletin BO-07, Buppl t, "BNR Jet Pump Assembly Failure " Response required GRIER, B H Region 1, Philadelphia, Office of the Director BO/05/13 1p
- 8009160225 Forwards IE Insp Repts 50-277/80-22 % 50-278/80-16, consisting of 800619 meeting in Philadelphia, PA GRIER, B H Region 1, Philadelphia, Office of the Director 80/07/21 1p
- --8009160229 IE Insp Repts 50-277/80-22 % 50-278/80-16, consisting of 800619 meeting Major areas addressed plant operations, radiation protection, refueling 8 radwaste operations; security & safeguards, surveillance 8 preoperational testing CGWOILL, C J. MCCABE, E C Region 1, Philadelphia, Office of the Director BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/07/17 7pp
- 8009150180 Forwards IE Insp Repts 50-277/80-21 & 50-278/80-15 on 800630-0703 No noncompliance noted BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/07/24 2pp
- --B009150184 IE Insp Repts 50-277/80-21 & 50-278/80-15 on 800630-0703
  No noncompliance noted Major areas inspected containment
  integrated leak rate procedure, containment leak rate test
  activities & surveillance of pips supports & restraints
  REKITO,W A. WIGGINS,J T. CAPHTON,D L. Region 1, Philadelphia,
  Reactor Operations Nuclear Support Branch 80/07/22 lipp
- B009100857 Forwards IE Insp Rept 50-277/80-20 on B00623-25 No noncompliance noted BRUNNER, E. J. Region I. Philadelphia, Reactor Operations Nuclear Support Branch B0/07/25 2pp
- --8007100861 IE Insp Rept 50-277/80-20 on 800623-25 No noncompliance noted Major areas inspected fuel handling activities including removal of fuel bundles from spent fuel pool & installation into reactor core BETTENHAUSENL . PETRONEC D Region i, Philadelphia, Office of the Director CAPHTON, D.L. Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/07/24 4pp
- 8009220376 Responds to IE Bulletin 80-16 re potential misapplication of pressure transmitters Rosemount 1191 & 1152 are utilized in facility Worst case analyses revealed that anomalous transmitter output would not violate design DALTROFF, S.L. Philadelphia Electric Co. 80/07/30 5pp
- BOOPO80833 Responds to IE Bulletin 79-14 Need identified for mod to, or addition of 24 supports to correct overstressed conditions in piping ar supports or overloading of concrete expansion bolts Nine of 24 items exceeded operability criteria DALTRUFF, B L Philadelphia Electric Co 80/08/01 2pp
- 8009150502 Responds to IE Bulletin 79-03A. "Langitudinal Weld Defects in ASKE SA-312 Type 304 Stainless Steel Pipe "Three piping component spools in reactor core isolation cooling pump sys do not exceed 85% of code allowable stresses DALTROFF, 8 L. Philadelphia Electric Co. 80/08/01 2pp

- 8009:20165 Responds to IE Bulletin 80-17 & Supp i re failure of control rods to fully insert during scram Mods added to provide positive venting capability for vent valves Design changes to scram sys may be warranted GALLAGHER, J W Philadelphia Electric Co 80/08/07 7pp
- 8009100121 Provides addl info re Item 6 c of util 800717 response to IE Bulletin 80-17, "Failure of 76 of 185 Control Rods to FUlly Insert During Screm at BMR " Operation of two standby liquid control sys pumps is unreviewed safety question DALTROFF, S.L. Philadelphia Electric Co 80/08/08 3pp
- 8009160619 Ack receipt of 800806 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/80-15 & 50-278/80-13 Util ltr to be withheld (ref 100FR2 790) MARTIN,N Q Region I, Philadelphia, Safeguards Branch 80/08/13 lp
- --8009160621 Forwards IE Insp Repts 50-277/80-15 & 50-278/80-13 on 800519-23 & 27 & notice of violation.Apps A & B App A withheld fref 10CFR2 790) GRIER, B H Region 1. Philadelphia. Office of the Director 80/07/14 | App
- --8009160623 Notice of violation. App B, from insp on 800519-23 & 29
   Region 1. Philadelphia. Office of the Director 80/06/27 1
- --8009160625 IE Insp Repts 50-277/80-15 & 50-278/80-13 on 800519-23 & 29 Noncompliance noted lack of lighting access control physical barriers & response Details withheld (ref 10CFR2 790) DEVLIN.J. Region 1. Philadelphi4. Safeguards Branch SMITH.O C Region 1. Philadelphia. Office of the Director 80/06/27. Ep
- 8009030076 Forwards Revision 1 to IE Bulletin 80-17, "Failures of Marcury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER, B H Region 1, Philadelphia. Office of the Director 80/09/15 1p
- 8009100090 Responds to IE Bulletin 80-17. Suppl 1. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR " Program for monitoring scram discharge vol established until instrumentation mod is completed DALTROFF.S L Philadelphia Electric Co 80/08/19 Spp
- 8009:10251 Updates environ qualification rept for Class IE electrical equipment, in response to IE Bulletin 79-018 forwards revised sys component evaluation work sheets, revised refs & revised environ equivalent room tabulation
  DALTROFF, S. L. Philadelphia Electric Co. 80/08/19 136pp
- 8009120103 Forwards Suppl 3 to IE Bullstin 80-17, "Failure of Control Rods to Insert During Scram at BWR " Written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/08/22 1p
- 8009189030 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/08/22 10
- 8009120237 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-600S & K-DON 600S Circuit Breakers " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/08/27 1p
- 8009230498 Forwards Revision 1 to IE Bulletin 79-24, "Boron Lose From BHR Control Slades " Written response required ORIER.9 H Region 1, Philadelphia, Office of the Director 80/08/29 1p
- 8009240043 Forwards IE Circular 80-21, "Regulation of Refueling Creus " No written response required ORLER.» H. Region 1, Philadelphia, Office of the Director 80/09/10 1p
- 8009240325 Forwards IE Info Notice BD-32. "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matie "No written response required GRIER:BH Region 1. Philadelphia. Office of the Director 80/09/12 ip

- R Periodic operating reports & related correspondence
- 8007020245 Forwards "Peach Bottom Atomic Power Station Thermal Mapping Rept 80-3 for 800715,23 & 31 " WILLSEY, W B Philadelphia Electric Co 80/08/26 1p
- --8009020246 "Peach Bottom Atomic Power Station Thermal Mapping Rept 80-3 for 800715,23 & 31 " \* Philadelphia Electric Co 80/08/26 &pp
- 8009080340 Forwards "Semiannual Effluent Releases Rept 9, Jan-June 1980 "ALDEN,N M Philadelphia Electric Co 80/08/29 ip
- --8009080342 "Semiannual Effluent Releases Rept 9. Jan-June 1980 " ULLRICH, W T Philadelphia Electric Co 80/08/29 7pp
- 8009160294 Forwards monthly operating rapts for Aug 1980 COONEY, M J Philadelphia Electric Co 80/09/10 5pp
- --8009160276 Monthly operating repts for Aug 1780 ALDEN,W M Philadelphia Electric Co 80/07/10 5pp
- S009160427 Forwards "Thermal Mapping Rept 80~4 for S00807" & "Thermal Monitoring Rept 80-5 for S00816" HILLSEY.W B Philadelphia Electric Co 80/09/10 ip
- ---BO07160431 "Thermal Mapping Rept 80-4 for 800807"
  \* Philadelphia Electric Co 80/07/10 4pp
- --8007160435 "Thermal Mapping Rept 80-5 for 800816 "
  Philadelphia Electric Co 80/09/10 4pp
- 8009180439 Forwards revised pages for monthly operating rapt for Aug 1980 COONEY,M J Philadelphia Electric Co 80/09/12 1p
- --8009180442 Revised pages to monthly operating rept for Aug 1980 re "Cause & Corrective Action" # Philadelphia Electric Co. 80/09/12 2pp
- 8009230567 Forwards "Thermal Mapping Rept 80-6 for 800821 & 25 for Thermal Monitoring Requirements " WILLSEY,W B Philadelphia Electric Co 80/09/18 1p
- ---8009230576 "Thermal Mapping Rept 80-6 for 800821 for Thermal Monitoring Requirements "
  -> Philadelphia Electric Co 80/07/18 5pp
- S Repo, table occurrences. LERs & related correspondence
- 8007020501 PNO-I-80-122 on B00815, unplanned release of gaseous radioactivity from Unit 3 reactor bidg vent occurred Release rate was 33% of Tech Spec limit Caused by malfunction of Unit 2 offgas sys during mods GREENHAN.E. BRUNNER.E.J Region 1, Philadelphia, Office of the Director 80/08/15 2pp
- BOOPOGOAGS LER BO-013/OGL~O on BOOBOI, during refueling outage, surveillance leak test results exceeded Tech Spec limits due to leakage failure of eight MBIVs Caused by improper seat contact due to damage to seats, plugs & guides COONEY,M J , WERGARD, A J Philadelphia Electric Co BO/08/29 1p
- DOCKET 50-278 PEACH BOTTOM ATCHIC POWER STATION, UNIT 3

  E NRC Safety Evaluation Report (SER), supple & correspondence
- B009020053 Forwards draft comments on BER Items 3 2 3(1)-(4),3 2 9, 3 2 13-15 & 3 2 4 from fire protection review Final Item 3 1 B(2) will be sent shortly HALL.RE Broothaven National Laboratory 80/09/21 Spp
- F Security, medical, emergency & fire protection plans
- 8009250274 Requests permission to record conversations on dedicated telephone connection installed between facilities & NRC Bethesia, MD headquarters
  CDUNEY, M J Philadelphia Electric Co 80/04/18 ip
- 8009090364 Forwards amended fire protection review. Item 3 1 1 re Area 6 cable spreading room fire detection sys HALL:R E Argonne National Laboratory 80/07/13 2pp

- 8009040079 Forwards Suppl 1 to SER re fire protection program Evaluation approves certain proposed mods & resolves certain issues identified in NRC 790523 evaluation REID.R 14 Operating Reactors Branch 4 80/09/14 2pp
- --8009040083 Suppl 1 to SER re facility fire protection program + Operating Reactors Branch 4 80/08/14 App
- 8009090362 Forwards comments on fire protection review Items 3 2 3(1), (2), (3), (4), 3 2 9, 3 2 13, 3 2 14, 3 2 15 & 3 2 4 re fire dataction sys & ventilation ducts Final Item 3 1 8(2) comments will be sent shortly MALL,R E Brookhaven National Laboratory 80/08/21 6pp
- 6009230191 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency GRIER, B H Region 1. Philadelphia, Office of the Director 80/08/22 3pp
- B007090424 Forwards info on Item 3 2 B(1) & (2) re fire barrier genetration seals for fire protection review HALL-R E Brookhaven National Laboratory 90/08/24 2pp
- B009150478 Forwards revised plant security personnel training b qualification plan Plan withheld (ref 100FR2 790) 3RADLEY, E.J. Philadelphia Electric Co. B0/09/11 3pp
- B009300230 Forwards Suppl 2 to safety evaluation re-fire protection program in which mod schedule is in accordance w/Amends 53 & 53 to DPR-44 & DPR-56, respectively REID.R H Operating Reactors Branch 4 B0/09/15 2pp
- --8009300235 Suppl 2 to safety evaluation supporting fire protection program
  4 Operating Reactors Branch 4 80/09/15 4pp
- O Adjudicatory correspondence
- 8009190362 Ferwards order requiring info supporting environ qualification of safety-related electrical equipment. Requests submittal of info by 801101 REID, R W Operating Reactors Branch 4 80/08/29 2pp
- --B009190369 Order for mod of Licenses DPR-44 & DPR-56 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101
  EISENHUT,D G Division of Licensing 80/08/29 App
- P. Operating license stage documents & correspondence
- 8009110554 Suppls NRC 800707 request for proposed Tech Specs changes re scram discharge vol vent & drain valves, & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT, D Q Division of Licensing 80/07/22 22pp
- 800902027 Submits interim criteria for shift staffing to all OL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for amergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D © Division of Licensing 80/07/31 7pp
- 8007080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREO EISENHUT, D Q Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded. Requested submittal should include proposed class of amend EISENHUT, D Q Division' of Licensing 80/08/07 60pp
- 8009020154 Approves Class III fee refund for 800730 license amend re 800728 application for max permissible water temp in containment suppression pool MILLER, W.D. License Fee Management Branch 80/08/13 ip
- 8009030352 Advises that high range noble gas monitors described in util 800102 & 0604 ltrs satisfy Lessons Learned Short-Term Item 2 1.8 b & TMI Action Plan Item III D.2 1 REID.R W. Operating Reactors Branch 4 80/08/14 2pp

- 8009050210 Forwards Amend 71 to License DPR-56, safety evaluation & notice of issuance & availability REID,R W Operating Reactors Branch 4 80/08/14 2pp
- --8009050217 Amend 71 to License DPR-56 revising Tech Spec 3 11 D 2 to permit inoperability of snubber on RHR sys lines for 800717-26 for repairs REID.R W Operating Reactors Branch 4 80/08/14 4pp
- --8009050219 Safety evaluation supporting Amend 71 to License DPR-36 \* Office of Nuclear Reactor Regulation. Director 80/08/14 2pp
- --8009050221 Notice of issuance & availability of Amend 71 to License DRR-56
  RFID.R W Operating Reactors Branch 4 80/08/14 2pp
- 8009190953 Forwards "Mark 1 Containment Long-Term Program SER Resolution of Generic Technical Activity A-7," NUREO-0661 W/o enci REID.R W Operating Reactors Branch 4 80/08/20 2pp
- 8009150033 Forwards request for add1 info on degraded grid voltage re NRC review of application to amend Tech Specs to provide second level of undervoltage protection w/time delay for safety-related loads REID,R W Operating Reactors Branch 4 80/08/21 3pp
- B0072203B4 Requests add1 fees re B00B0B application proposing seismic monitoring Tech Specs Application requires Classes III & I fees rather than submitted Classes II & I fees D100S,R M License Fee Management Branch B0/08/26 [p
- BOO9180304 Forwards application for amend of Licenses DPR-44 & DPR-56 changing Tech Specs in response to NRC 800702 ltr re TME Lessons Learned Category A requirements Class III fee encl BRADLEY, E J Philadelphia Electric Co 80/09/15 ip
- --80091B0316 Application for amend of Licenses DPR-44 & 56 changing Tech Specs 3 2 F.4 2 F.6 2-2.6 3-6 5.6 14 & 6 15 in response to TMI Lessons Learned Task Force Category A requirements Centuficate of Svc encl BAUER, E 0 , BRADLEY, E J Philadelphia Electric Co 80/07/15 Boo
- --8009180335 Proposed Tech Specs 3 2 F,4 2 F,6 2-2,6 3-6 5,6 14 & 6 15 re wate. level instrumentation & safety relief valve position indication Revision made in response to TMI Lessons Learned Task Force Category A requirements

  \* Philadelphia Electric Co 80/09/15 7pp
- B009300367 Forwards comments on NUREC-0696, "Functional Criteria for Emergency Response Facilities " Delay of implementation of data transmission requirements recommended until specific transmission requirements issued BDYER,V S Philadelphia Electric Co 80/09/23 App
- O Inspection reports, IE Bulletins & correspondence
- 8009300131 "Response to IE Bulletin 79-01D "
  \* Philadelphia Electric Co 80/04/15 350pp
- 8007090105 Forwards IE Bulletin 80-07, Suppl 1, "BNR Jet Pump Assembly Failure " Response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/05/13 1p
- 8007160225 Forwards IE Insp Repts 50-277/80-22 & 50-278/80-16, consisting of 800619 meeting in Philadelphia, PA ORIER, B H Region i, Philadelphia, Office of the Director 80/07/21 1p
- --8009160229 IE Insp Repts 50-277/80-22 % 50-278/80-16, consisting of B00619 meeting Major areas addressed plant operations, radiation protection, refueling t raduats operations, security & safeguards, surveillance & preoperational testing COWOILL.C J. MCCABE.E C Region I. Philadelphia, Office of the Director DRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/07/17 7pp
- 8009150180 Forwards IE Insp Repts 50-277/80-21 & 50-278/80-15 on 800630-0703 No noncompliance noted BRUNNER.E J Region i. Philadelphia, Reactor Operations Nuclear Support Branch 80/07/24 2pp

- --8009150184 IE Insp Repts S0-277/80-21 & 50-278/80-15 on 800630-0703
  No noncompliance noted Major areas inspected containment
  integrated leak rate procedure.containment leak rate test
  activities & surveillance of pipe supports & restraints
  REKITO.W A . WIGGING.J T . CAPHTON.D L Region i. Philadelphia.
  Reactor Operations Nuclear Support Branch 80/07/22 lipp
- 8007220376 Responds to IE Bulletin 80-16 re potential misapplication of pressure transmitters Rosemount 1151 & 1152 are utilized in Pacility Worst case analyses revealed that anomalous transmitter output would not violate design DALYROFF, B L Philadelphia Electric Co 80/07/30 5pp
- 8009080533 Responds to IE Bulletin 79-14 Need identified for mod to, or addition of 24 supports to correct overstressed conditions in piping or supports or overloading of concrete expansion bolts Nine of 24 items ecceeded operability cruteria DALTROFF, S.L. Philadelphia Electric Co. 80/08/01 2pp
- 8009150502 Responds to IE Bulletin 79-03A. "Longitudinal Reld Defects in ASME SA-312 Type 304 Stainless Steel Pipe " Three piping component spacis in reactor core isolation cooling pump sys do not exceed 85% of code allowable stresses DALTROFF.S L Philadelphia Electric Co 80/08/01 2pp
- 8009120165 Responds to IE Bulletsh 80-17 & Supp i re failure of control rods to fully ensert during scram Mods added to provide positive venting capability for vent valves Design changes to scram sys may be warranted OALLAGMER.J W Philadelphia Electric Co 80/08/07 7pp
- 8009100121 Provides add1 info re Item 6 c of util 800717 response to 1E Bulletin 60-17, 'Failure of 76 of 185 Control Rods to Fully insert During Scram at BUR" (Repration of two standby liquid control sys pumps as unreviewed safety question DALTROFF, St. Philadelphia Electric Co. 80/08/08 3pp
- 8009140619 Ack receipt of 800806 ltr informing NRC of steps taken to correct violations noted in IE Inap Repts 30-277/80-15 & 50-279/80-13 Util Itr to be withheld (ref 10CFR2.790). MARTIN.W O Region 1, Philadelphia, Safeguards Branch 80/08/13
- --8009160621 Forwards IE Insp Repts 50-277/80-15 & 50-278/80-13 on 800519-23 & 29 & notice of violation Apps A & B App A withhold (ref 100FR2 790)
  GRIER B H Region I, Shiladelphia. Office of the Director 80/07/14 | 2pp
- --8009160623 Notice of violation.App B.from insp on 800519-23 & 29
  \* Region 1. Philadelphia. Office of the Director. 80/06/27 1p
- --8009160625 IE Insp Repts 50-277/80-15 & 50-278/80-13 on 800519-23 & 29 Noncompliance noted lack of lighting access controliphysical barriers & response Details withheld (ref 10CFR2 790) DEVLIN.J Region I. Philadelphia. Safeguards Branch SMITH.Q C Region I. Philadelphia. Office of the Director 80/06/27 tp.
- 8009090015 Responds to [E Bullstin 80-17, "Failure of 76 of 185 Control Rods to Fully Insert During Stram at BUR." Stram tests for facility successfully completed on 800808 & 09 DALTROFF,S L Philadelphia Electric Co 80/08/14 App
- 8009030076 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required ORIER.B H Region 1. Philadelphia. Office of the Director 80/08/15 1p
- 8009100090 Responds to [E Bulletin 80-17. Suppl 1, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BMR " Program for monitoring scram discharge vol established until instrumentation mod is completed DALTROFF, B L Philadelphia Electric Co 80/08/19 Spp
- 8009110251 Updates environ qualification rept for Class IE electrical equipment, in response to IE Bulletin 79-018 Forwards revised sys component evaluation work sheets, revised refs & revised environ equivalent room tabulation
  DALYROFF, S L Philadelphia Electric Co 80/08/19 136pp
- 8009120103 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BMR" Written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/08/22 ip

- 8009180030 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GRIER, B K Region 1, Philadelphia, Office of the Director 80/08/22 1p
- 8009120237 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 i K-DON 6008 Circuit Breakers " No written response required GRIERABH Region 1, Philadelphia, Office of the Director E0/08/27 1p
- 800923049B Forwards Revision 1 to 1E Bullstin 79-26, "Boron Loss From BUR Control Blados "Writton response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/88/29 1p
- 8007240043 Forwards IE Circular 80~21, "Regulation of Refueling Craws"
  No written response required
  ORIER.B H Region 1, Philadelphia, Office of the Director
  BO/09/10 ip
- 8009240325 Forwards IE Info Notice 80-32. "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required ORIER.B H Region 1. Philadelphia, Office of the Director 80/09/12 1p
- R Periodic operating reports & related correspondence
- 8009020245 Forwards "Peach Bottom Atomic Power Station Thermal Mapping Rept 80-3 for 800715,23 & 31 " WILLSEY, H B Philadelphia Electric Co 80/08/26 ip
- --8009020244 "Peach Hottom Atomic Power Station Thermal Mapping Rept 80-3 for 800715.23 % 31 " \* Philadelphia Electric Co 80/08/26 App
- 8009080340 Forwards "Semiannual Effluent Releases Rept 9.Jan-June 1780 " ALDEN W H Philadelphia Electric Co 80/08/29 1p
- --8007080342 "Semiannual Effluent Releases Rept 9, Jan-June 1980 " ULLRICH, W T Philadelphia Electric Co 80/08/29 7pp
- 8009160294 Forwards monthly operating repts for Aug 1980 COONEY, M J Philadelphia Electric Co 80/09/10 5pp
- --8009160296 Monthly operating repts for Aug 1980 ALDEN, W M Philadelphia Electric Co. 80/09/10 Spp
- B009160427 Forwards "Thermal Mapping Rept 60-4 for 800807" & "Thermal Monitoring Rept 80-5 for 800816" WILLSEY,W B Philadelphia Electric Co 80/09/10 ip
- --B009160431 "Thermal Mapping Rept 80-4 for 800807 "
  \* Philadelphia Electric Co 80/09/10 App
- --8089160435 "Thermal Mapping Rept 80-5 for 800816 " \* Philadelphia Electric Co 80/09/10 App
- 8009180439 Forwards revised pages for monthly operating rept for Aug 1980 COUNCY, M. J. Philadelphia Electric Co. 80/09/12 ip
- --8007180442 Revised pages to monthly operating rept for Aug 1980 re
  "Cause & Corrective Action"
  \* Philadelphia Electric Co 80/09/12 2pp
- 8009230569 Forwards "Thermal Mapping Rept 80-6 for 800821 & 25 for Thermal Monitoring Requirements" WILLSEY.W B Philadelphia Electric Co 80/09/18 ip
- --8009230576 "Thermal Mapping Rept 80-6 for 800821 for Thermal Monitoring Requirements." \* Philadelphia Electric Co 80/09/18. Sep
- S Reportable occurrences, LERs & related correspondence
- BOO9020501 PNO-I-80-122 on BOOB15, unplanned release of gaseous radioactivity from Unit 3 reactor bldg vent occurred Release rate was 33% of Tech Spec limit Caused by malfunction of Unit 2 offgas sys during mods OREENNAN.E. BRUNNER.E. J. Region i. Philadelphia, Office of the Director BO/08/15 2pp.

- SOC9120330 LER 80-017/03L-0 on 800802, during surveillance test on PCIS normally open valves, drywell 2-inch valve A0-3509 failed to close Caused by tight packing on valve Packing & proper operation verified COONEY, M J Philadelphia Electric Co 80/09/01 ip
- 8009120369 LER 80-018/03L-0 on 800802, during surveillance test on PCIS NOTICEST LET BU-018/01-0 on BUOGUE, during surveillance mormally open valves w/unit at full power, reactor water cleanup sys return isolation valve MD-3-12-68 failed to close using control switch Cause not determined COCNEY.H J Philadelphia Electric Co 80/09/01 ip
- SOOPSA0439 LER BO-019/03L-0 on BOOB06, while performing surveillance test on RHR sys w/unit at power, MO-3-10-25A LPCI injection valve failed to open Caused by multiple full penetration cracks on Grive sleeve of type SMB-4 Limitorque operator COCNEY, N J Philadelphia Electric Co BO/09/05 ip
- 8009160441 LER 80-021/03L-0 on 800818, during PCIS logic sys functional testing w/slant shutdown, primary containment ventilation valve A0-3506 failed to close Caused by ASCO model 856756 solenoid valve stuck in energized position Valve cleaned COCNEY, M J Philadelphia Electric Co 80/09/09 1p
- 8009280621 LER 80-021/03X-1 on 800818, during PCIS logic sys functional testing w/plant shutdown.primary containment valve AC-3506 failed to close Caused by ASCO Model S56756 solenoid valve stuck in energized position Solenoid valve cleaned COUNEY.H J Philadelphia Electric Co 80/09/09 ip
- 8009190482 LER 80-020/03L-0 on 800815, while performing leak test, containment ventilation valve A0-35218 was found leaking excessively Caused by valve T-ring inflating before closure Air valves adjusted & valve tested CDONEY.M J Philadelphia Electric Co 80/09/12 ip
- BO092&0&16 LER 80-022/03L-0 on 800829, during core spray logic sys test.
  38 pump started O 3-s below Tech Spec time range Causad by agastat time delay relay setpoint drift Relay adjusted & testing resumed satisfactorily COONEY:M J Philadelphia Electric Co 80/09/19 1p
- DOCKET 50-280 SURRY POWER STATION, UNIT 1
- F. Security, medical, emergency & fire protection plans
- 8007030184 Forwards revised emergency plan Plan is based on existing metaorological capabilities 8 reflects criteria of NUREG-0.551 York County. VA emergency plan encl BAUM.E A Virginia Electric & Power Co 80/06/30 2pp
- --B007030202 Draft York County, VA radiological emergency response plan peacetime Plan withheld per Privacy Act
  # Virginia, State of 80/06/30 51pp
- --8007030207 Revised emergency plan
  # Virginia Electric & Power Co 80/06/16 800pp
- 8009190739 Requests participation in NRC study of people-related problems in nuclear safeguards Request includes NRC visit to interview security personnel Confidentiality of info will be maintained during all phases of study UARCA.S A Operating Reactors Branch 1 80/08/14 2pp
- SOOP230273 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network 8ys installed for govt use during emergency O'REILLY.JP Region 2, Atlanta, Office of the Director 80/08/22
- BOO9090274 Notifies that execution of util emergency drill has been deferred until B01231 NRC has not approved of revised radiological response plan & corporate emergency drill plan Extension will enable proper personnel training period BAUM.E A Virginia Electric & Power Co B0/09/04 2pp
- SOO9260043 Forwards facility emergency planning info W/o encl SOUDER, J L Division of Rules and Records 80/09/12 1p
- 8009230340 Forwards revised nuclear security personnel training & qualifications program Program withheld (ref 10CFR2 790)

  BYLVIA:B.R Virginia Electric & Power Co 80/09/19 1p

- Q Adjudicatory correspondence
- B009230121 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 VARGA.S A Operating Reactors Branch 1 80/08/29 2pp
- --8009230132 Order for mod of License DPR-32 & DPR-37 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101 EISENHUT,D G Division of Licensing 80/08/27 App Division of Licensing 80/08/29
- BOO9230013 Motion for stay of effectiveness of Amend 47 to OL, authorizing replacement of steam generators, pending appeal before US Court of Appeals for DC Circuit in which FES is challenged W/Civil pleadings & excerpts of NUREO-0523 DOUGHERTY, J B Potomac Alliance DOUGHERTY, J B Citizens Energy Forum DQUGHERTY, J B Dougherty, J B BO/09/18 ilipp
- H General correspondence
- 8007070436 Responds to enc1 Botetourt County Chamber of Commerce 800626 request to FERC for info re when facilities will be operational Lists status of plant operating schedules DENION, H R Office of Nuclear Reactor Regulation. Director DENION, H R 80/09/05 Зрр
- J Insurance & indomnity information
- 8007070384 Forwards Endorsement 1 to NELIA Binder EB-70 ANDREWS,C L Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/09/03 2pp
- P Operating license stage documents & correspondence
- B009020297 Submits interim criteria for shift staffing to all GL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D O Division of Licensing 80/07/31 7pp
- 8009100673 Forwards FEB for facility & notice of availability W/o FES VARQA, S A Operating Reactors Branch 1 80/07/31 2pp
- --8009100675 Notice of availability of FES for facility VARGALS A Operating Reactors Branch i 80/07/3i
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for NAMEMONDU FORMATOS BATT NORMANDONA, PURCTIONAL CRITERIA FOR Emergency Response Facilities "Comments requested unthin 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/a NUREO EISENHUT, D 0 Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re incensing action associated u/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D O Division of Licensing 80/09/07 60ep
- 8009090785 Approves util 800806 request to return facility to power operation in accordance w/provisions of Amend 59 Forwards safety evaluation re leaks in steam generator C. findings of subsequent insp & corrective actions VARCA.S A Operating Reactors Branch 1 80/08/08 2pp
- --8009090786 Bafety evaluation supporting continued operation of facility steam generators \* Operating Reactors Branch 1 80/08/08 3pp
- 8009190794 Forwards revised Westinghouse 8T8 3 9 8 2,3 9 10 \$ Bases 3/4 9 8 & 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NOVAK,T M Assistant Director for Operating Reactors 80/08/15
- --8009190817 Revised Heatinghouse STS 3 9.8 2.3 9 10 & Bases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or Assistant Director for Operating Reactors 80/06/23 21pp
- BOOPO20437 Application to amend Tech Specs in Licenses DPR-32 & DPR-37 Proposed changes will transfer independent review & audit responsibilities Amend fee encl FERGUSCH, J H Virginia Electric & Power Co BO/OB/28 Spp

- --800902044! Proposed changes to Tech Specs 6 i-1 through 6 3-1 for administrative controls of organization, safety & operation review Tech Specs will transfer independent review & audit responsibilities

  \* Virginia Electric & Power Co 80/09/28 12pp
- 6009180538 Forwards Amends 60 & 60 to Licenses DPR-32 & DPR-37. respectively Notice of issuance & availability
  VARGA,S A Operating Reactors Branch I 80/08/29 3pp
- --8009180545 Amends 60 % 60 to Licenses DPR-32 & DPR-37, respectively, revising Oct 1974 amends to allow passession of byproduct nati VARGA.S A Operating Reactors Branch 1 80/08/29 4pp
- --8009180552 Notice of issuance & availability of Amends 60 & 60 to Licenses DPR-32 & DPR-37, respectively NEIOMBORS.J D Operating Reactors Branch 1 80/08/29 2pp
- 8009290461 Forwards Amend 61 & 61 to Licenses BPR-32 & BPR-37, respectively. & notice of issuance & availability VARGA.S A Operating Reactors Branch 1 80/09/05 2pp
- --G009270464 Amends 61 & 61 to Licenses DPR-32 & DPR-37, respectively, to require implementation of safeguards contingency plan within 30 days of Commission approval VARCA: 3 A Uperating Reactors Branch 1 80/09/05 4pp
- --8009290468 Notice of issuance & availability of Amends 41 & 61 to Licenses DPR-32 & DPR-37, respectively VARGA:S A Operating Reactors Branch 1 80/09/05 2pp
- 8009180251 Forwards addI info re annual U feed requirements for range of discharge burnups to support proposed Tech Specs Change 85 to Licenses DPR-32 & DPR-37 Feed & SHU requirements shown in anci table considered conservative SYLVIA.B R Virginia Electric & Power Co 80/09/15 2pp SYLVIA, B R
- 8009190525 Submits info re maintaining min of 23 ft of water over reactor vessel flange during fuel movement, in response to NRC 800815 ltr Changes to Tech Specs to include RHR sys requirements identified in NRC 800615 ltr being reviewed SYLVIA-B R Virginia Electric & Power Co 80/09/16 2pp
- 8009220134 Forwards comments on NUREG-0696 in response to NRC 800801 request Implementation of requirements according to time schedule not considered feasible Requests meeting to discuss preliminary plan re effective emergency response factivities FERGUSON.J H Virginia Electric & Power Co 80/09/18 14pp
- 8009260278 Submits add1 info re proposed Tech Spec Change Request 85 Util will provide general evaluation of reactor operation to extended fuel burnups possible w/higher fuel enrichment by SYLVIA, BR Virginia Electric & Power Co 80/09/23 ip

## Q Inspection reports. IE Bulletins & correspondence

- 8009100056 Forwards SE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Funns Following Secondary Side High Energy Line Rupture "Written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/07/24
- 8009180148 Forwards IE Insp Repts 50-280/80-26 & 50-281/80-29 on 800709-10 No noncompliance noted MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/05 2pp
- --8009180162 IE Insp Repts 50-280/80-26 & 50-281/80-29 on 800709-10
  No noncompliance noted Major areas inspected IE Bulletins
  79-02 & 79-14 & licenses actions on previous insp findings
  COMPTOIR H Region 2, Atlanta, Office of the Director
  HERDT, A.R. Region 2, Atlanta, Reactor Construction & Engineering
  Support Branch 80/08/04. 4pp
- 8007020207 Forwards IE Insp Repts 50-280/80~23 & 50-281/80-24 on 800609-0703 % notice of violation LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/08/08 2pp
- --8099020216 Notice of violation from imag on 800609-0703 \* Region 2, Atlanta, Office of the Director 80/08/ 80/08/08

- --800902020 IE Insp Repts 50-280/80-23 & 50-281/80-26 on 800609-0703 Noncompliance noted failure to follow plant maint & mod procedures
  BURKE.D J Region 2, Atlanta, Office of the Director
  KELLOGO,P J Region 2, Atlanta, Reactor Operations Nuclear Support
  Branch 80/08/08 7pp
- 8007020242 Submits response to IE Bullotin 79-03A For North Anna, no SA-312 or A-312. Type 300 series fusion walded pipe in use at greater than 85% design stress For Surry, eight fittings determined in excess of 85% design stress SYLVIA, B R Virginia Electric & Power Co 80/08/09 2pp
- 8009030141 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/08 Region 2. Atlanta: Office of the Director 80/08/19
- 8009050422 Ack receipt of 800801 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/80-10 & 50-281/80-11 0'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22
- --800905043! Forwards IE Insp Repts 50-280/80-10 & 50-281/80-11 on 800505-09,12-16 & 20-23 & notice of violation O'REILLY, J P Region 2, Atlanta, Office of the Director 80/07/03 2pp
- --8009050436 Notice of violation from insp on 800505-09,12-16 & 20-23

  \* Region 2, Atlanta, Office of the Director 80/07/03 5pp
- --B007050441 IE Insp Repts 50-2B0/80-10 & 50-201/80-11 on 800505-09, 12-16 & 20-23 Noncompliance noted, failure to follow Tach Spec procedures, perform corrective actions, control vendor manuals & perform & document safety evaluation UPRIGHT.C M Region 2, Atlanta, Reactor Operations Nuclear Support Branch RULLMAN, W A. BELISLE, G A. Region 2, Atlanta, Office of the Director 80/07/03 32pp
- 8009160172 Forwards IE Circular 80-18, "100FR50 59 Bafety Evaluations for Changes to Radwaste Treatment Sys " No written response oracired
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22
- 8009i60473 Ack receipt of 800804 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 80-280/80-21 & 90-281/80-22 STOHR, J.P. Region 2, Atlanta. Fuel Facility & Materials Safety Branch 80/08/22 ip
- ---8009160487 Forwards IE Insp Repts 50-280/80-21 & 50-281/80-22 on 800603-06 & notice of violation STOHR.J P Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 80/07/07 2pp
- --8009160490 Notice of violation from insp on 800603-06 SYDHR, J P Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 80/07/07 1p
- --B009160497 IE Insp Repts 50-280/80-21 % 50-281/80-22 on 800603-04 Noncompliance noted failure to have written procedures for preparation of efficiency calibr stds for OE detectors FROUP.9 L. Region 2. Atlanta, Fuel Facility & Materials Safety Branch MENTGOMERY.D M. Region 2. Atlanta, Office of the Director 80/07/07 9pp
- 9009240180 Responds to NRC BD0728 request for continuing action re IE Bullstin 79-02, "Pipe Support Base Plats Designs Using Concrete Expansion Anchor Bolts " Estimated anchor bolt insp & testing echedule encl SPENCER, N C Virginia Electric & Power Co 80/08/24 2pp
- 8009120031 Responds to IE Bulletin 80-19 Surry Units 1 & 2 do not use mercury-wetted relays in reactor protection sys No response for North Anna Units 1 & 2 SYLVIA 9. R Virginia Electric & Power Co 80/08/27, 200
- BO09120314 Forwards IE Info Notice 80-31. "Maloperation of Quald-Brown Bover! 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/27.

# DOCKETED ITEMS

- 8009090528 Forwards response to NRC 800808 itr re violation noted in JE Insp Repts 50-280/80-23 & 50-281/80-26 Corrective action cleared trays & installed cable tray covers required by electrical maint procedures
  SYLVEA-B R Virginia Electric & Power Co 80/09/05 2pp
- 8009240099 Forwards response to IE Bulletin 80-15 re possible loss of emergency notification sys w/loss of offsite power Design change initiated to change power supply to vital bus Adainistrative Procedure 29 & revised Affidavit encl SYLVIA.B R Virginia Electric & Power Co 80/09/05 3pp
- 8009240493 Ack receipt of B00811 ltr informing NRC of staps taken to correct violations noted in IE Insp Repts 50-280/80-20 & 50-281/80-21 LEMIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/09/08 ip
- --8097240701 Responds to NRC 800715 ltr re violation noted in IE Insp Repts 50-280/80-20 & 50-281/80-21 Corrective actions trash removed from containment recirculation sump screens & proposed Tech Spec change submitted to NRC SYLVIA:8 R Virginia Electric & Power Co 80/08/11 3pp
- --8007240706 Forwards IE Insp Repts 50-280/80-20 & 50-281/80-21 on 800505-0606 & notice of violation LEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/07/15 2pp
- --B009240707 Notice of violation from insp on 800505-0606
  \* Region 2, Atlanta, Office of the Director 80/07/15 2pg
- ~-8097240713 IE Insp Repts 80-280/80-20 & 50-281/80-21 on 800505-0606 Noncompliance noted failure to follow operating procedures to maintain recirculating sump screens. & inadequate implementation of design control measures for mods RELLOGO,P J. BURKE,D J. Region 2. Atlanta, Office of the Director 80/07/15 App
- 8009250357 Forwards IE Insp Repts 50-280/80-33 & 50-281/80-36 on B00820-22 No noncompliance noted Insp summary only encl fref 10CFR2 790)
  KENNA,W B Region 2, Atlanta, Safeguards Branch 80/09/08 2pp
- --8009250360 IE Insp Repts 50-280/80-33 & 50-281/80-36 on 800820-22
  No noncompliance noted Major areas inspected access control,
  lighting & power supply Details withheld (ref 100FR2 790)
  HDDRG.D E Region 2, Atlanta, Office of the Director
  MCGUIRE,D R Region 2, Atlanta, Safeguards Branch 80/09/08 ip
- 8009260517 Forwards IE Circular 80-21, "Regualtion of Refueling Craws " No written response required O'AEELLY, J.P. Region 2. Atlanta, Office of the Director 80/09/10 5pp
- B009300ii6 Forwards response to IE Bulletin 80-20 Westinghouse Type W-2 control switch applications found Subj switches have been tisted satisfactorily SYLVIA, 8 R Virginia Electric & Power Co 80/09/15 3pp
- A Periodic operating reports & related correspondence
- 8009190437 Forwards monthly operating repts for Aug 1980 SYEVIA.B R Virginia Electric & Power Co 80/09/15 ip
- --B009190444 Monthly operating repts for Aug 1980
  WILSON, J. DUNN, S.D. Virginia Electric & Power Co. 80/09/08
  48pp
- 8 Reportable occurrences, LERs & related correspondence
- BCO9030525 Forwards LER 80-040/03L-0 MfLSON.J.L Virginia Electric & Power Co 80/08/28 ip
- ---8009030535 LER 80-040/03L-0 on 800731. In steady state operation, found that primary to secondary leakage through 1C steam generator was 0 33 gpm Caused by primary to secondary leakage through four steam generator tubes

  \* Virginia Electric & Power Co 80/08/28 2pp
- SO090R0344 Forwards LER 80-058/01T-0 HILSON,J.L Virginia Electric & Power Co 80/08/29 1p
- --8009020350 LER 80-058/01T-0 on 800819, w/unit at 90%, refueling water storage tank vol found different than assumed in 780629 order for mod Caused by failure to specify number of available galions in order Correct vol calculated WILBOH, J T Virginia Electric & Power Co 80/08/29 2pp

- --8009100262 LER 80-042/03L-0 on 800805, pump for drawing radiation samples from process vent sys from a triggered low flow alarm Caused by moisture condensation in pump area Pump pulled & replaced WILSON, J. Virginia Electric & Power Co 80/08/05 2pp
- 8009150274 Forwards LER 80-046/03L-0 WILSON, J.L. Virginia Electric & Power Co. 80/09/08 1p
- --8009150278 LER 80-046/03L-0 on B00807.during startup operations, containment varuum sys steam ejector was placed in svc w/o obtaining containment gaseous release form Caused by personnel error WILBUNJ L Virginia Electric & Power Co 80/09/08 2pp
- 8009220253 Forwards LERs 60-051/03L-0.80-054/03L-0 & 80-052/03L-0 WILSON: J L Virginia Electric & Power Co 80/09/12 ip
- --800722025B LER 80-051/03L-0 on 800813 discharge tunnol radiation monitor found out of svc during reloase of liquid waste test tan? A Caused by defective circuit card Replaced defective card WILSON, J L Virginia Electric & Power Co 80/07/12 2pp
- ~-8009280260 LER 80-054/03L-0 on 800815 during periodic testing motor operated valve SU-1020 failed to cycle Valve required to close on loss of offsite power coincident w/loss of coolant Caused by previous exposure of motor windings to water WILSON.J L Virginia Electric & Power Co 80/07/12 2pp
- ~~8009220263 LER 80~052/03L~0 on BOOS12.low flow alarm sounded on RM-QW 101 & 102 Process vent sys & RM-GW-101 & 102 were found to be full of water Caused by flooding of gas stripper Bys flushed & dried Pump & filter replaced WILSON, J L Virginia Electric & Power Co RO/09/12 2pp
- 8009190553 Forwards LERs 80-055/03L-0 & 80-014/03L-0 WILSON, J.L. Virginia Electric & Power Co. 80/09/15 1p.
- --8009190557 LER 80-055/O3L-0 on B00816, during performance of PT 15 2, MOV-FM-151A failed to indicate in closed position Investigation showed value in open position Probably caused by mechanical failure of value operator WILSON, J. L. Virginia Electric & Power Co. 80/09/15 2pp
- --8009170966 LER 80-014/03L-0 on 800816, w/reactor critical, discovered level in refueling water storage tank & CAT below min set by Tech Specs Caused by excessive makeup to 8 St accumulator w/o refilling
  WILSON-J L Virginia Electric & Power Co 80/09/15 Ppp
- 8009230645 Forwards LERs 80-056/03L-0 & 80-057/03L-0 WILSON, J & Virginia Electric & Power Co 80/09/17 fp
- --8009230461 LER BO-056/03L-0 on 800818 at 84% power, periodic lest 270 revealed low amperage for circuit 7.panel 8 Caused by damage to heat tracing tape during mechanical work nearby Defective tape replaced 2 verified uperablo WILSON.J.L. Virginia Electric 8 Power Co 80/09/17 2pp
- --B007230673 LER 80-057/03L-0 on 800B18.at B9% newer.periodic test 27D revealed low amperage reading for circuit 13A boron injection recirculation to boric acid tanks.panel 9 Caused by failure of heat tracing tape Design change initiated WILSOM, J. L. Virginia Electric & Power Co. 80/09/1/ 2pp
- DOCKET 50-281 SURRY POWER STATION, UNIT P
  F Security, medical, emergency & fire protection plans
- B007030184 Forwards revised emergency plan Plan is based on existing meteorological capabilities 3 reflects criteria of NUREG--0654 York County, VA emergency plan encl BAUM, E.A. Virginia Electric 8 Fower Co. 80/06/30 2pp
- --8007030207 Revised emergency plan \* Virginia Electric & Power Co 80/06/16 500pp
- 8009190739 Requests participation in NRC study of paople-related problems in nuclear safeguards Request includes NRC visit to interview security personnel Confidentiality of info will be maintained during all phases of study VARGA: S A Operating Reactors Branch 1 80/08/14 2pp

- 8009230973 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/08/22 in
- 8009090274 Notifies that execution or util emergency drill has been deferred until 801231 NRC has not approved of revised radiological response plan & corporate emergency drill plan Extension will enable proper personnel training period BAUM, E.A. Virginia Electric & Power Co. 80/09/04 2pp
- 8007260043 Forwards facility emergency planning info H/o enci SOUDER: J L Division of Rules and Records 80/07/12 ip
- 0009230343 Forwards revised nuclear security personnel training & qualifications program Program withheld (ref (00FR2 790) SYLVIA:8 R Virginia Electric & Power Co 80/09/19 ip

#### G Adjudicatory correspondence

- 8009230121 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 VAROA.8 A Operating Reactors Branch 1 80/08/29 2pp
- --BOO9230132 Order for mod of License DPR-32 & DPR-37 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by BO(10) EISENHUT.D 9 Division of Licensing 60/08/29 App
- 8009230013 Motion for stay of effectiveness of Amend 47 to OL.
  authorizing replacement of steam generators, pending appeal
  before US Court of Appeals for DC Circuit in which FEB is
  challenged W/Civil pleadings & excerpts of NUREQ-0523
  DOUGHERTY, J B Potomac Alliance DOUGHERTY, J B Citizens Energy
  Forum DOUGHERTY, J B Dougherty, J B 80/09/18 111pp

#### H General correspondence

- 8009090436 Responds to encl Botetourt County Chamber of Commerce 800626 request to FERC for info re when facilities will be operational Lists status of plant operating schedules BERION H R Office of Nuclear Reactor Regulation. Director 80/09/05 | 3pp
- J Insurance & indomnity information
- 8009090384 Forwards Endorsement i to NELIA Binder EB-70 ANDREWS,C L Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/09/03 2pp
- 8009160324 Submits payment of Invoice 1077-80, extending indemnity agreement for facility License DPR-32 to B10910
  BYLVIA:B R Virginia Electric & Power Co 80/09/12 tp
- P Operating license stage documents & correspondence
- 8009020297 Submits interim criteria for shift staffing to all DL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D & Division of Licensing 80/07/31 7pp
- 8009050505 Forwards Amend 59 to License DPR-37.safety evaluation by notice of issuance & availability
  VARGA.S A Operating Reactors Branch 1 80/08/01 2pp
- --8009050510 Amend 59 to License DPR-37, revising Tech Specs to reflect changes as result of mods made to alleviate NPBH problems w/low head safety injection 4 recirculation spray pumps VARQA:8 A Operating Reactors Branch 1 80/08/01 27pp
- ---BD09050516 Safety evaluation supporting Amend 59 to License DPR-97 \*\* Office of Nuclear Reactor Regulation, Director 80/08/01 13pp
- --809050519 Natice of issuance & availability of Amend 59 to License DPR-37 VAROALS A Operating Reactors Branch i 80/08/01 2pp
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 entl N/o NUREG EISENHUT.D G Division of Licensing 80/08/01 119pp

- 8009230092 Informs that exemption from fee re licensing action associated w/TMI+2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISE
- 8009190794 Forwards revised Westinghouse STS 3 9 8 2.3 9 10 & Bases 3/4 9 8 & 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control roofs Written response required NOVAK,T M. Assistant Director for Operating Reactors 80/08/15 1p
- --B009190B17 Revised Westinghouse STS 3 9 8 2.3 9 10 % Bases 3/4 9 8 % 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods
  \* Assistant Director for Operating Reactors 80/06/23 21pp
- 8009020437 Application to amend Tech Specs in Licenses DPR-32 & DPR-37 Proposed changes will transfer independent review & audit responsibilities Amend fee and! FERGUSON.J H Virginia Electric & Power Co 80/08/28 5pp
- --8009020441 Proposed changes to Tech Specs 6 1-1 through 6 3-1 for administrative controls of organization safety & operation review Tech Specs will transfer independent review & audit responsibilities

  \* Virginia Electric & Power Co 80/08/28 12pp
- 8009180538 Forwards Amends 60 % 60 to Licenses DPR-32 % DPR-37, respectively Notice of issuance & availability VARGA,S A Operating Reactors Branch 1 80/08/29 3pp
- --8009180545 Amends 60 % 60 to Licenses DPR-32 & DPR-37.respectively. revising Oct 1974 amends to allow possession of byproduct matl VAROA.S A Operating Reactors Branch 1 80/08/29 4pp
- --8009180552 Notice of issuance & availability of Amends 60 & 60 to Licenses DPR-32 & DPR-37, respectively NFIGHBORS, J D Operating Reactors Branch 1 80/08/29 2pp
- 8009270461 Forwards Amend 61 & 61 to Licenses DPR-32 & DPR-37, respectively, & notice of issuance & availability VAROA,S A Operating Reactors Branch 1 80/09/05 2pp
- --B009290464 Amends 61 & 61 to Licenses DPR-32 & DPR-37, respectively, to require implementation of safeguards contingency plan within 30 days of Commission approval VAROA.S A Operating Reactors Branch i B0/09/05 4pp
- --B009290469 Notice of issuance & availability of Amends 61 & 61 to Licenses DPR-32 & DPR-37, respectively VAROA.B A Operating Reactors Branch 1 80/09/05 2pp
- 8007160291 Forwards addl info re annual U feed requirements for ranga of discharge burnups to support proposed Tech Specs Change 85 to Licenses DPR-32 & DPR-37 Feed & SHU requirements shown in encl table considered conservative 8YLVIA.B & Virginia Electric & Power Co 80/09/15 2pp
- 8009170321 Forwards "Reactor Containment Bldg Integrated Leak Rate Test.Types A.B & C.Surveillance Test " SYLVIA.B R Virginia Electric & Power Co 80/09/16 1p
- --8009170323 "Reactor Containment Bldg Integrated Leak Rate Test. Types. A.B & C. Burveillance Test " \* Virginia Electric & Power Co 80/05/31 48pp
- 8009190525 Bubmits info re maintaining min of 23 ft of water over reactor vessel flange during fuel movement in response to NRC 800815 ltr Changes to Tech Specs to include RHR sys requirements identified in NRC 800611 ltr being reviewed BYLVIA.B R Virginia Electric & Power Co 80/09/16 2pp
- 8007220134 Forwards comments on NUREO-0676 in response to NRC 800801 request Implementation of requirements according to time schedule not considered feasible Requests meeting to discuss preliminary pian re effective emergency response facilities FEROUBON.J H Virginia Electric & Power Co 80/07/18 16pp
- 8009260278 Submits add1 info re proposed Tech Spec Change Request 85 Util will provide general evaluation of reactor operation to extended fuel burnups possible w/higher fuel enrichment by 810101 SYLVIA,8 R Virginia Electric & Power Co 80/09/23 1p

### Q Inspection reports, IE Bulletins & correspondence

- B009100056 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Written response required O'REJLLY, J P Region 2, Atlanta, Office of the Director B0/07/24 ip
- BOO9050056 Submits final response to IE Bulletin 79~02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchors " All anchor bolt design loads meet safety factors Base plates belief which do not meet criteria modified SPENCER.W C Virginia Electric & Power Co 80/08/04 5pp
- 8009180148 Forwards IE Insp Repts 50-280/80-26 & 50-281/80-29 on B00709-10 No noncompliance noted MURPHY.C E. Region 2. Atlanta: Reactor Construction & Engineering Support Branch 80/08/05 2pp
- --8009180162 IE Insp Repts 50-280/80-26 & 50-281/80-29 on 800709-10
  No noncompliance noted Major areas inspected IE Bulletins
  79-02 & 79-14 & licensee actions on previous insp findings
  COMPTON:R H Region 2. Atlanta. Office of the Director
  HERDIAR Region 2. Atlanta. Reactor Construction & Engineering
  Support Branch 80/08/04 App
- BOC9020209 Forwards IE Insp Repts 50-280/80-23 & 50-281/80-26 on BOOA09-0703 & notice of violation LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch BO/08/08 2pp
- --B007020216 Notice of violation from insp on 800607-0703
  \* Region 2, Atlanta, Office of the Director 80/08/08 ip
- --8009020220 IE Insp Repts 50-280/80-23 & 50-281/80-26 on 800609-0703
  Noncompliance noted failure to foliow plant maint & mod
  procedures
  BURKE,D J Region 2, Atlanta, Office of the Director
  KELLOGO,P J Region 2, Atlanta, Reactor Operations Nuclear Support
  Branch 80/08/08 7pp
- 8009020242 Submits response to IE Builetin 79-03A For North Anna, no SA-312 or A-312. Typa 300 series fusion welded pipe in use at greater than 85% design stress For Surry, eight fittings determined in excess of 85% design stress
  SYLVIA, B R Virginia Electric & Power Co 80/08/08 2pp
- 8009030141 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/15 1p
- 8009050422 Ack receipt of 800801 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/80-10 & 50-281/80-11 UfREILLY, J P Region 2, Atlanta, Office of the Director 80/08/22 ip
- --8009030431 Forwards IE Insp Repts 50-280/80-10 & 50-281/80-11 on 800505-09, 12-16 & 20-23 & notice of violation O'REILLY.J P Region 2, Atlanta, Office of the Director 80/07/03 2pp
- ---8009050436 Notice of violation from insp on 800505-09,12-16 & 20-23 \* Region 2. Atlanta. Office of the Director 80/07/03 5pp
- ---B009050441 IE Insp Repts 50-280/80-10 & 50-281/80-11 on 800505-09, 12-16 & 20-23 Noncompliance noted failure to follow Tech Spec procedures, perform corrective actions, control vendor manuals & perform & document safety evaluation UPRIGHT, C M Region 2, Atlanta, Reactor Operations Nuclear Support Branch RUHLMAN, M & BELISLE, G A Region 2, Atlanta, Office of the Director 80/07/03 32pp
- 8009140172 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys." No written response required
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22 ip
- 8009160473 Ack receipt of 800804 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 30-280/80-21 & 50-281/80-22 STORR.J P. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 80/08/22, 1p.

- --8039160487 Forwards IE Insp Repts 50-280/80-21 % 50-281/80-22 on 800603-06 % notice of violation STOHR. J P Region 2. Atlanta. Fuel Facility & Materials Safety Branch 80/07/07 2pp
- --8009160490 Notice of violation from insp on 800509:06 BTOHR: J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/07/07 ip
- --8009160497 IE Insp Repts 50-280/80-21 t 50-281/80-22 on B00603-06 Noncompliance noted failure to have written procedures for preparation of efficiency callbr stds for OE detectors TROUP, C L Region 2, Atlanta, Fuel Facility & Materials Safety Branch MUNTQUMERY, D M Region 2, Atlanta, Office of the Director 80/07/07 9pp
- B009120031 Responds to IE Bulletin 80-19 Surry Units 1 & 2 do not use mercury-wetted relays in reactor protection sys No response for North Anna Units 1 & 2 GYLVIA. B R Virginia Electric & Pauer Co 80/08/27 2pp
- 8009120314 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers "
  No written response required
  O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/27
- 8009090528 Forwards response to NRC 800808 itr re violation noted in IE Insp Repts 50-280/80-23 & 50-281/80-26 Corrective action cleared trays & installed cable tray covers required by electrical maint procedures SYLVIA.8 R Virginia Electric & Power Co 80/09/05 2pp
- 8007240397 Forwards response to IE Bulietin 80-15 re possible loss of emergency notification sys w/loss of offsite power Design change initiated to change power supply to vital bus Administrative Procedure 29 6 revised Affidavit encl SYLVIA:B R Virginia Electric & Power Co 80/09/05 3pp
- 8009240652 Ack receipt of 800821 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-281/80-24 LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/09/08 lp
- --8009240661 Responds to NRC 800729 Itr re violations noted in IE Insp Rept 50-281/80-24 Corrective actions startup time for auxiliary steam generator feed pumps brought into compliance w/acceptance criteria SYLVIA,8 R Virginia Electric & Power Co 80/08/21 3pp
- --8009240669 Forwards IE Insp Rept 50-281/80-24 on 800623-27 & notice of violation LENIS, C Region 2, Atlanta, Office of the Director 80/07/25 2pp
- --8009240675 Notice of violation from insp on 800623-27
  \* Region 2, Atlanta, Office of the Director 80/07/25 ip
- --8009240484 IE Insp Rept 50-281/80-24 on 800623-27 Noncompliance noted failure to adequately review test results
  KELLOGO,P J , SAVER,R C Region 2, Atlanta, Office of the Director 80/07/25 6pg
- 8009240693 Ack receipt of 800811 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/80-20 8 SG-281/80-21 LEWIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/09/08 ip
- --8007240701 Responds to NRC 800715 ltr re violation noted in IE Insp Repts 50-280/80-20 & 50-281/80-21 Corrective actions trash removed from containment recirculation sump screens & proposed Tech Epec change submitted to NRC BYLVIA,B R Virginia Electric & Power Co 80/08/11 3pp
- --8009240706 Forwards IE insp Repts 50-280/80-20 & 50-281/80-21 on 800505-0606 & notice of violation LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/07/15 2pp
- --B007240709 Notice of violation from insp on 800505-0404 4 Region 2, Atlanta. Office of the Director 80/07/15 2pp
- --8009240713 IE Insp Repts 50-280/80-20 & 50-281/80-21 on 800505-0606 Nancompliance noted failure to follow operating procedures to maintain recirculating sump screens, & Inadequate implementation of design control measures for mods KELLOGO,P J, BURKE,D J Region 2, Atlanta, Office of the Director 80/07/15 App

- GOO9250357 Forwards IE Insp Repts 50-280/80-33 & 50-281/80-36 on BO0820-22 No noncompliance noted losp surnary only encl (ref IOCFR2 790)
  - Region 2. Atlanta, Safeguards Branch 80/09/08 2pp
- --8009250350 IE Insp Repts 50-280/80-33 & 50-281/80-36 on 800820-22 No noncompliance noted Major areas inspected access control.
  Lighting & power supply Details withheld (ref 100FR2 790)
  MODRE. D E Region 2. Atlanta. Office of the Director
  MCGUIRE. D R Region 2. Atlanta. Safeguards Branch
- 8009260517 Forwards IE Circular 80-21, "Regualtion of Refueling Crews " ha unitten response required

  D REILL(.J P Region 2 Atlanta, Ornice of the Director 80/09/10
- 8009300116 Forwards response to 1E Builetin 80-20 Westinghouse Type W-2 control suitch applications found Subj Switches have been tested satisfactority SYLVIA, B R Virginia Electric & Power Co 80/09/15 3pp
- R Periodic operating reports & related correspondence
- 8009190437 Forwards monthly operating repts for Aug 1980 SYLVIA 3 R Virginia Electric & Power Co 80/09/15
- --8007190444 Monthly operating repts for Aug 1980 WILSON, J., DUNN, S.D. Virginia Electric & Power Co
- S Reportable occurrences. LERs & related correspondence
- 8009020088 Forwards updated LER 79-008/03X-1 WILSCN.J.L. Virginia Electric & Power Co. 80/08/25 (p.
- --8009020090 Updated LER 79-008/03%-1 on 790209, during surveillance check found deterioration of piping on low portion of rectrivilation spray subsystems Caused by chloride stress corrosion Piping replaced whomsensitized piping WILSON, J L Virginia Electric & Power Co 80/08/25 3pp
- 8009080351 Forwards LER 80-011/01T-0 WHESOM J L Virginia Electric & Power Co 80/09/02 ip
- ~800908036 LER 80-011/0(T-0 on 800819.at 12% power, steam flow transmitters (FI-474.475.484.485.494 & 495) isolated contrary to Tech 8pec-3 7 B Caused by transmitters being isolated following containment integrated leak rate test WICSON.J L Virginia Electric & Power Co 80/09/02 2pp
- 8009220248 Forwards LERs 80-012/03L,80-013/03L-0 & 80-015/03L-0 WILSOM, J L Virginia Electric & Power Co 80/09/12 1p
- --B007220309 LER 80-062/03L-0 on 800815, review of Unit 2 gipe support showed that seismic support for charging pump 2-CM-P-IB had not been installed Caused by administrative error Support HILSON, J L Virginia Electric & Power Co 80/09/12 2pp
- --8009220398 LER 80-013/03L-0 on 800815, during startup testing boric acid concentration of 13 8% was reported in 1-CH-TK-1C & 2-81-TK-2 Caused by pumping boric acid from boron evaporator buttoms tank to boric acid storage tank u/o sanpling WILSON.J L Virginia Electric & Power Co 80/09/12 2pp
- --8009220402 LER 80-015/03L-0 on 800816, after pressurization of accumulator tanks, level indicator for 'B" SI accumulator indicated 61% level, above Tech Spec mar of 58 3% Caused by condensation & high pressure in nitrogen feed line WILSON, J. Virginia Electric & Power Co 80/09/12 2pp
- 8009190553 Forwards LERs 80-055/03L-0 & 80-014/03L-0 WILSOM J L Virginia Electric & Power Co 80/09/15
- --8009190566 LER 80-014/03L-0 on B00816.w/reactor critical discovered 1091107060 LER GUTU14703-TO UN OVASSION TESTS OF THE STATE OF THE STAT n spees refilling SORAJ L Virginia Electric & Power Co 80/09/15 2pp WILSONAUL
- 8009240469 Forwards LERs 80-017/03L-0.80-019/03L-0.806-020/03L-0 Wilson, J. L. Virginia Electric & Power Co. 80/09/19 1p

- --8009240470 LER 80-017/03L-0 on 800820, during Unit 2 startup at 18% ooy2404/U LER 8D-01//03L-U on B00820.during Unit 2 start power.control room surveillance revealed terd reading i main steam flow transmitter Caused by partially closed equalizing valve Bistables tripped 5 valve closed BILSON, J Virginia Electric 5 Power Co 80/09/19 2
- ~-8009240471 LER 80-019/03L-0 on 80D822, during operation trip valve TV-SS-2068 would not stay closed when actuated from control room Caused by misadjusted limit switch Valve isolated & position limit switch readjusted WILSON.J L. Virginia Electric & Power Co 80/09/19 2pp
- --8009240473 LER 80-020/03L-O on 800822 after boric acid batching, chemist reported concentration above Tech Spec requirements Caused by transfer of batch tank to inservice bast Manual shutdown initiated & boric acid diluted to Tech Spec limits
  WILSON.J L Virginia Ejectric & Power Co 80/09/19 2pp
- 8009300498 Forwards LERs 80-022/03L-0 & 90-021/03L-0 WILSON, J.L. Virginia Electric & Power Co. 90/09/ 80/09/25
- --8009300504 LER 80-022/03L-0 on 800826, w/unit operating at steady state, Channel III flow computer, for steam generator steam flow FC 2474: failed Caused by loose printed circuit board & cold solder joint on filter capacitor. Board & Capacitor repaired WILSON, J L. Virginia Electric & Power Co 80/09/25 2pp
- --8009200508 LER 80-021/03L-0 on 800826, while attempting to pressurize Accumulator B using normal nitrogen supply, pressure fell below allowable limits Caused by leak & low pressure in nitrogen fill header Added pressure to sys & repaired leak WILSON, J. Virginia Electric & Power Co 80/09/25 2pp
- DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STAILON, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8009240239 Forwards Health Physics Appraisal Repts 30-282/80-08 & 50-306/80-09 on 800505-15, notice of violation & significant appraisal findings KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/12
- --8009240246 Notice of violation from health physics appraisal on Region 3, Chicago, Office of the Director 80/08/11 1p
- --8009240255 Health Physics Appraisal Repts 50-282/80-08 & 50-206/80-09 on 800505-15 Noncompliance noted inadequate radiation survey instrument use in high radiation area & inadequate offshift chemistry bradiation protection coverage FISHER.U. Region 3. Chicago, Fuel Facility & Materials Bafety Branch OREGER.LR. JANUSKAA G. Region 3. Chicago, Office of the Director 80/08/11 30pp
- 8008200282 Forwards final draft of upgraded emergency plan, consisting of corporate nuclear & plant emergency plans Delay in subnittal due to incorporation of new 10CFRSO rules MAYER.L O Northern States Power Co 80/08/15
- --8008200284 Final draft of upgraded emergency plan, consisting of corporate nuclear & plant emergency plans

  \* Northern States Power Co 80/08/15 225pp
- B009230305 Requests that all personnel be reminded of purpose of embrgency notification sys & health physics network Sys installed for govt use during emergency KEPPLER.J G Region 3. Chicago. Office of the Director B0/08/22
- 8009020072 Forwards "Evacuation Time Estimates From Areas Near Prairie Island Nuclear Generating Plant," Revision 1 MAYER.L O Northern States Power Co 80/08/25 1p
- ~-8009020076 "Evacuation Time Estimates From Areas Near Prairie Island Nuclear Generating Plant," Revision 1 \* Northern States Power Co 80/08/31, 18pp
- BOOP100930 Transmits emergency planning info to be made available to public at LPDR in Minneapolis, MN W/o encl SQUDER, J L Public Document Branch 80/07/04 ip
- 8009260016 Transmits emergency planning info to be made available to public at LPDR in Kinneapolis.MN W/o encl SOUDER.J L. Division of Rules and Records BO/09/11 1p

### G Adjudicatory correspondence

- 8009030726 Motion to hold proceedings in abeyance until 800923, when MN Pollution Control Agency will act on settlement Settlement. If adopted would result in withdrawal of hearing request BENECHAL. H. E. , OLSON, J. F. , SPANNAVS, W. Minnesota, State of 80/08/28 3pp
- --8009030728 Affidavit stating that proposed settlement will be placed on next MN Pollution Control Agency monthly meeting agenda or considered at special meeting for affirmative majority vote of board members

  BRIEMHURGT.L J Minnesota, State of 80/08/28 2pp
- B009190295 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by B01101 CLARK.R A Operating Reactors Branch 3 80/08/29 2pp
- --B009190304 Urder for mod of Licenses DPR-42 & DPR-60 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 80:101

  EIBENNUT,D O Division of Licensing 80/08/29 App
- 6009100427 Response in opposition to State of MN 800828 motion to hold spent fuel pool med proceeding in abeyance pending MN Follution Control Agency Board 800923 meeting Accepting settlement during meeting very remote W/Certificate of Svc SILBERGJE, BERNSTEIN, D.L. Northern States Power Co SILBERG, J E Shaw, Pittman, Potts & Trowbridge 80/09/04 7pp
- 8009110023 Response in support of State of MN motion to defer ASLB action until 800923 Settlement, if accepted during MN Pailution Control Agency 800923 meeting, would obviate proceeding Centificate of Svc encl BARTH, C A Hearing Branch 3 80/09/08 2pp
- BO09230525 Memorandum & order granting MN Pollution Control Agency
  B00928 motion in which deferral of action was requested
  pending Agency Board 800923 meeting Petitioner shall file
  reply to util objections by B01001 if settlement rejected
  LAZO,R H Atomic Safety and Licensing Board Panel 80/09/18 3pp
- 8009300039 Joint motion to terminate proceeding re OL amend application for spent fuel pool storage expansion Agreement incorporating certain language in OL amend has been reached between parties Contentions withdrawn SILBERO.J E Northern States Power Co OLGON.J F Minnesota, State of BARTH.C Hearing Branch 3 80/09/23 3pp
- P. Operating license stage documents & correspondence
- BOO9020277 Submits interim criteria for shift staffing to all UL & CP ticensess & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D & Division of Licensing 80/07/31 7pp
- BOO908008D Forwards draft NUREQ-0695. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 enci W/o NUREO EISENHUT.D O Division of Licensing 80/08/01 119pp
- GOO9230082 Informs that exemption from fee re licensing action associated u/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D.Q Division of Licensing 80/08/07 60pp
- 8009190794 Forwards revised Wastinghouse 8TS 3 9 8 2,3 9 10 & Bases 3/4 9.8 & 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NOVAK.T M Assistant Director for Operating Reactors 80/08/15
- --8009190817 Revised Westinghouse STS 3 9 8 2.3 9 10 & Bases 3/4 9 8 & 3/4 9.10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods

  \* Assistant Director for Operating Reactors 80/06/23 21pp
- BO09190745 Discusses review of util 800611 response to NRC 800507 ltr identifying five new TMI-2 requirements Review based on HR Denton 800328 ltr re qualifications of reactor operators Item (1) A la does not satisfy criteria CDLLINS,P F. Operator Licensing Branch 80/08/25 2pp

- 8009170082 Forwards Amends 42 & 36 to Licenses DPR-42 & DPR-60respectively.EIA & notice of issuance & availability CLARK.R A Operating Reactors Branch 3 80/08/27 3pp
- --8009170088 Amends 42 & 36 to Licenses DPR-42 & DPR-60, respectively, changing Tech Specs, App B, to permit addition of chlorination program for circulating water sys in order to destroy parasitic amoeba in sys CLARK, R A Operating Reactors Branch 3 80/08/27 6pp
- --8009170099 ElA supporting Amends 42 & 36 to Licenses DPR-42 & DPR-60, respectively # Office of Nuclear Reactor Regulation, Director #0/08/27 4pp
- --8009170092 Notice of issuance & availability of Amends 42 & 36 to Litenses DPR-42 & DPR-60, respectively # Operating Reactors Branch 3 80/08/27 1p
- 8009290421 Advises that 791109 response acceptable re ECCS evaluation models dealing offuel cladding swelling & incidence of rupture Na further action necessary CLARK, R A Operating Reactors Branch 3 80/09/10 2pp
- B009170341 Gubmits further response to NRC B00805 inquiries re proposed fuel surveillance program for refueling outage Fabrication methods used for gadolinia-bearing rods were typical of production-type fuel MAYER.L D Northern States Fower Co 80/09/12 3pp
- 8007190481 Notifies of delay until 801114 for submittal of proposed Tech Specs for Lessons Learned Category A requirements, requested by NRC 800702 ltr MAYERL O Northern States Power Co 80/09/12 2pp
- 8009300334 Forwards JC Lehr 800826 memo documenting EIA re 800826 issuance of Amends 42 & 36 to Licenses DPR-42 & DPR-60, respectively MARTIN.8 Operating Reactors Branch 3 80/09/12 ip
- --8009300340 Forwards compilation of telcons re 800821 license amend request Correspondence w/MN Pollution Control Agency & MN Dept of Matl Resources encl LEMR, J C Assistant Director for Environmental Technology 80/08/26 7pp
- 8009250244 Submits supplemental info to 800506 request for amend to Licenses DPR-42 & DPR-60 re SI actuation & power distribution limits Lists detailed responses to NRC questions MAYER-L. O Northern States Power Co 80/09/19 3pp
- G Inspection reports, IE Bulletins 3 correspondence
- 8007110620 Forwards IE Insp Rept 50-282/80-11 on 800710 No noncompliance noted FIORELLI,O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/22 2pp
- ---8009110627 IE Insp Rept 50-282/80-11 on 800710 No noncompliance noted Major areas inspected GA/OC program implementing procedures, work activities & records re steam generator tube nondestructive examinations
  DANIELSON.D H Region 3. Chicago, Reactor Construction & Engineering Support Branch WARD.K D Region 3. Chicago, Office of the Director 80/07/21 4pp
- 8009150076 Advises that response to Item 6 of IE Bulletin 79-17.
  Revision 1, was satisfactorily completed on Unit 1 in Jul
  1980 No corrective actions necessary
  OLLBERTS.D E Northern States Power Co 80/08/14 ip
- B007150218 Responds to IE Bulletin 80-19 re failure of mercury-wetted matrix relays No relays of type described are used in reactor protection sys at facility
  OILDERTS,DE Northern States Power Co 80/08/14 ip
- 8009260263 Forwards IE Insp Repts 50-202/80-13 & 50-306/80-13 on 800601-0731 No noncompliance noted HEISHMAN, R Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/00/14 2pp
- --8009260271 IE Insp Repts 50-282/80-13 % 50-306/80-13 on 800601-073£ No noncompliance noted Major areas inspected operation, maint-surveillance security & radiation protection FEIERABEND. C D , 8URORESS B L , LITTLE, W S Region 3, Chicago, Office of the Director 80/08/11 App

- 8009030210 Forwards Revision 1 to IS Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/15
- 8009110539 Responds to IE Bulletin 80-18, 'Possible Disconnect Mode 4 Automation Industries Inc Model 200-008 Sealed Source & Pigtail Assembly " High injection pumps assured min cooling GLRESTER. B E Northern States Power Co 80/08/15 ip
- 8009090019 Submits addit response to IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Facility does have containment penetration connections of type described Facility was built to ANSI BSI 1,1967 Summary rept encl GILBERTS, D.E. Northern States Power Co. 80/08/21 19pp
- 8009170433 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER.J G Region 3. Chicago, Ofrice of the Director 80/08/22
- 8009170405 Responds to IE Sulletin 80-15 re possible loss of emergency notification sys w/loss of offsite power New sys will be installed in Oct 1980 Test will be conducted upon completion of power supply sys Notification made on 800625 GILBERTS.D E Northern States Power Co 80/08/28 2pp
- 8007230066 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6005 & K-DON 6008 Circuit Breakers " No written response required KEPPLER, J C Region 3, Chicago, Office of the Director BO/08/28
- 8009100500 Forwards Revision 5 to "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ASME Code Section XI Requirements " MAYER.L. G. Northern States Fower Co.
- --8009100509 Revision 5 to "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ASME Code Section XI Requirements " + Northern Status Power Co 80/09/03 10pp
- 8009240112 Forwards IE Circular 80-21, "Regulation of Refueling Crews " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/10
- R Periodic operating reports & related correspondence
- B009090297 Forwards "Effluent & Waste Disposal Semiannual Rept for Jan-June 1980 " MAYER.L O Northern States Power Co 80/08/28 1p
- --8009090302 "Efrivent & Waste Disposal Semiannual Rept for Jan-June 1980 " + Northern States Power Co 80/08/28 9pp
- 8009140279 Forwards monthly operating repts for Aug 1980 MAYER-L O Northern States Power Co 80/09/08 1p
- --8007160282 Monthly operating repts for Aug 1980 HUNSTAD.A A Northern States Power Co 80/07/01 8pp
- S Reportable occurrences, LERs & related correspondence
- 8009090356 Forwards LER 80-024/031-0 MAYER.L D Northern States Power Co 80/09/05 19
- --80090903E8 LER 80-024/03L-0 on 800929, failure to perform inservice insp of safety norzle to shell weld of both reactor vessels was noted Cause due to equipment unavailability Rescheduling requested for 1983 & 1984 outages KRUMPOS.P J Northern States Power Co 80/09/05 1p
- 8009180422 RO BO-25 on 800904. w/unit in refueling shutdown ultrasonic axamination of steam generator support bolts revealed most bolts had crack indications Several bolts failed when detensioning was attempted Cause not determined TIERNEY,F P Northern States Power Co 80/09/05 2pp
- 8009230738 Forwards LER 80~025/01T-0 MAYER.L O Northern States Power Co 80/09/18 1p

- --8009230741 LER 80-025/01T-0 on 800904, during refueling shutdown, ultrashnic exam of steam generator support bolts revealed crask indications Unit 2 also inspected Caused by environ assisted cracking All Unit 1 bolts will be replaced \* Northern States Power Co 80/07/18 ip
- BOO9230743 Forwards LER 80-023/03L-0 MAYER, L O Northern States Power Co 80/09/19 1p
- ~-8009230750 LER 80-023/03L-0 on 800820, during review of surveillance gragram annual test. SP(185 for control room special ventilation flow verification found omitted for 1978-1980 Caused by personnel error Personnel will review rept HUNGTAD. A A Northern States Power Co 80/09/17 ip
- B009300551 Forwards updated LER 80-025/01T-1 MAYER, L 0 Northern States Power Co 80/09/25 1p
- --8009300558 Updated LER 80-025/01T-1 on 800904, ultrasonic examination of steam generator support bolts revealed that most had crack indications Preliminary cause suggests environmentally assisted cracking HUMSTAD, A A Northern States Power Co 80/09/25 ip
- 8009300573 Environ Event Rept 80-03 on 800820, during special chlorination program.certain levels of chlorine found outside circulating water sys that exceeded concentration limits in Tech Specs 2 4 1 HARD.P C Northern States Power Ca 80/09/25 4pp
- DOCKET 50-285 FORT CALHOUN STATION. UNIT 1

  F Security, medical, emergency & fire protection plans
- BOO9040076 Informs of need for revisions 8 add1 info re 800817 training 8 qualification plan Encl withheld (ref 100FR2 790)
  NDVAN.T H Assistant Director for Operating Reactors 80/08/11
- 8009020149 Invites participation in 800822 workshop in Atlanta 0A to sulicit comment re proposed functional criteria for emergency response facilities in NUREO-0696 Discussion to include location, size b staffing of emergency ctrs SEY-RIT.K V Region 4. Dallas, Office of the Director 80/08/12
- 8009120107 Confirms telcon re vital area analysis team & disposition of info in plant drawings Enci identifying info for team members withheld per Privacy Act Plant drawings will be withheld (ref 100FR2 790)
  CLARK, R A Operating Reactors Branch 3 80/08/15 2pp
- 8009090564 Forwards input on fire protection review, Items 3 1 18/3 2 4, 3 1 16/3 1 28 & 3 2 2 re cable separation, fire water supply, protection for stairways & open hatch & testing fire dotectors

  HALL, R E Brookhaven National Laboratory, 80/08/25 3pp
- O Adjudicatory correspondence
- 8009190336 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 CLARK.fl A Operating Reactors Branch 3 80/08/29 2pp
- --8009190343 Order for mod of License DPR-40 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101

  EISENHUT, D 0 Division of Licensing 80/08/29 App
- O Advisory Committee on Reactor Safeguards reports & correspondence
- E009030347 Forwards ACRS B00811 memo advising that ACRS does not object to NRC licensing facility to operate at power levels up to 1.500 MHt NRC is preparing related license amend WAONER.P C Operating Reactors Branch 3 80/08/13 2pp
- P Operating license stage documents & correspondence
- 8009020297 Bubmits interim criteria for shift staffing to all OL & CP licenses & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D Q Division of Licensing 80/07/91 7pp

- BO09080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/O NUREG EISENHUT, D 0 Division of Licensing 80/08/01 119pp
- BOO9230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D O Division of Licensing 80/08/07 60pp
- 8009190175 Forwards Amend 51 to License DPR-40.EIA & negative declaration CLARK, R A Operating Reactors Branch 3 80/08/28 2pp
- --8009190179 Amend 51 to License DPR-40 revising App B Tech Specs to delete certain environ monitoring & reporting requirements & increasing max & differential condenser cooling water discharge temp limits CLARK.R A Operating Reactors Branch 3 80/08/28 10pp
- ~~8009190182 Safety evaluation supporting Amend 51 to License DPR-40 \* Office of Nuclear Reactor Regulation, Director 80/08/28 2pp
- --8009190185 Negative declaration re issuance of Amend 51 to License DPR-40 CLARK,R A. Operating Reactors Branch 3 80/08/20 2pp
- 8009090581 Advises that Amend 51 to License DPR-40 became effective on 800828 when NPDES permit covering same subj was approved by NE Dept of Environ Control JONES.W C Omaha Public Power District 80/09/02 1p
- 8009150444 Informs of evaluation of current Tech Specs compared to STS re indine spiking & primary & secondary coolant activity level requirements in response to NRC 800722 ltr Ot amend will be forwarded by 801114

  JONES
- BO09290467 Advises that util response re ECCS evaluation models, dealing w/fuel cladding swelling & incidence of rupture.is acceptable CLARK.R L Operating Reactors Branch 3 80/09/10 2pp
- G Inspection reports. IE Bulletins & correspondence
- 8007020106 Responds to IE Bulletin 80-12 re decay heat removal sys operability facility fundamental design differences would prevent similar event at Fort Calhoun Shutdown cooling sys reviewed \$ decay heat removal sys operability ensured JONES.W C Gmaha Public Power District 80/06/26 App
- 8009180147 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Becondary Bide High Energy Line Rupture " Written response required 6EYFRIT,K V Region 4, Dallas, Office of the Director 80/07/24 ip.
- BOO9180105 Forwards IE Bulletin 80-20, "Failures of Westinghouse Type H-2 Spring Return to Neutral Control Switches " Written response required SEYFRIT.X V. Region 4, Dalles, Office of the Director 80/07/31
- BOO9180154 Forwards IE Bulletin 80-19, "Failure of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/07/31
- 8009260283 Forwards IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange" No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 60/08/07 1p.
- 8009260526 Forwards Revision 1 to JE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/08/15.
- 8009170401 Forwards IE Circular 80-18, "100FR50 59 Bafety Evaluations for Changes to Radwaste Treatment Sys " No written response required BEYFRIT.K V Region 4, Dallas, Office of the Director 80/08/22 tp.

- 8009120432 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover, 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers"

  No written response required

  SEYFRIT, K V Region 4, Dallas, Office of the Director 80/08/27
- BOO9190577 Forwards IE Insp Rept 50-285/80-14 on BOO811-15 No noncompliance noted Cover ltr only encl (ref 10CFR2 770) KELLY J A F Region 4. Dallas. Office of the Director BO/09/05 1p
- --8009:90584 IE Insp Rept 50-285/80-14 on 8008:1-15 No noncompliance noted Major areas inspected security plan, security program audit, security organization 8 access control Details withheid (ref 10CFR2 790) EVANS, A , KELLY, J A F Region 4, Dallas, Office of the Director 80/09/04 1p
- R Periodic operating reports & related correspondence
- B009030479 Forwards "Semiannual Rept for Tech Spec 5 9 4 5 App B." Jan-June 1980 JDNFS.W C Omaha Public Power District 80/08/29 1p
- --8007030486 "Semiannual Rept for Tech Spec 5 9 4 & App B." Jan-June 1980 STEVENS, S C Omaha Public Power District 80/08/29 190pp
- 8009230349 Forwards monthly operating rept for Aug 1980 JDNFS,W C Omaha Public Power District 80/09/08 19
- --B009230351 Monthly operating rept for Aug 1780 HICKLE, B J Omaha Public Power District 80/09/08 9pp
- 8009230721 Responds to NRC 800825 itr requesting verification of draft summary of radioactive effluent releases Requires corrections for liquid effluents of Sr-89 & Sr-90 for second quarter continuous & batch modes JCN+8,W C Omaha Public Power District 80/09/18 1p
- S Reportable occurrences, LERs & related correspondence
- 8009090525 Forwards LER 80-017/03L-0 STEVENS,S C Omaha Public Power District 80/08/27 1p
- --8009090934 LER 80-017/03L-0 on 800804, during normal power operation, personnel discovered setpoint selector switches for RMO-61, particulate radiation manitor. In wrong postion Caused by personnel error while performing test on radiation monitors CORE, M R Umaha Public Power District 80/08/25 4pp
- 8009090905 Forwards LER 80-D18/03L-0 STEVENS.8 C Omaha Public Power District 80/09/05 ip
- --8007070519 LER 80-018/03L-0 on 800808.while attempting to monitor gas space on VCT, inadvertent release of radioactive matl to auxiliary bldg environ occurred Caused by deteriorated surgical tubing on gas analyser Tubing replaced HYDE, K.C. Omaha Public Power District 80/09/05 4pp
- --8009300539 LER 80-021/03L-0 on 800910 transformer T4 of D6-1 failed Transformer feeds diesel oil immersion heater & alarm relays Caused by moveable armature located on immersion heater contractor Armature repaired MUELLER,R J Omaha Public Power District 80/09/11 App
- DOCKET 50-206 INDIAN POINT STATION, UNIT 3
  F. Becurity, medical, emergency & fire protection plans
- BD07020252 Requests 30-day extension for providing comments to NRC due on B00705 re security guard force training at facility MALTESE, M J. Power Authority of the State of New York 80/08/21
- BOOP230185 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Bys installed for govt use during emergency GRIER, B H Region 1. Philadelphia. Office of the Director BO

- 8009090773 Approves 800B15 request for extension to complete installation of add1 dry gape sprinklers in cable tunnel Barety evaluation encl VARGA.5 A Licensing Branch 1 80/08/27 2pp
- --8009090775 Safety evaluation supporting extension for completion of installation of addi dry page sprintlers in cable tunnel of Dffice of Nuclear Reactor Regulation, Director 80/08/27 Spp

### G Adjudicatory correspondence

- 8009190295 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801501 VARGA.S A Operating Reactors Branch 1 80/08/29 3pp
- ~~8009190260 Grder for mod of License DPR-64 to add info which fully nuriryado urage for mod of License DPR-64 to add info which responds to NRC request for info re environ qualification of safety-related electrical equipment lnfo should be submitted by 801101 EJEENHUI.D G Division of Licensing 80/08/29 App
- 8009120394 Order granting extension until 800926 for Commission to review ALAB-436 & relevant portions of ALAB-561 CHILK-S J Office of the Secretary of the Commission 80/09/10
- 0007300320 Order granting extension until 801024 for Commission to review ALAB-435 & ALAB-561 CHILK.S J Office of the Secretary of the Commission 80/07/26

### H Ceneral correspondence

- 8009180448 Responds to 600319 ltr requesting public debate re issues appropriate to evacuation of large population ctrs near
- --8009180462 Requests public debate ra issues appropriate to evacuation of large population ctrs near plants Expresses confidence in attempts by Commissioners to represent public concerns EMORY.X Affiliation Unknown 80/03/19 ip
- 8007110218 Forwards response to 800728 itr requesting assistance in answering constituent questions re nuclear power & effects of radiation
  DIRCKS.W J Office of the Executive Director for Operations DIRCKS, W J 0 80/08/28 4pp

### I financial information

6009120396 Forwards estimated cash flow & audited financial statements for 1979 BERRY,G T Pawer Authority of the State of New York 80/09/03

# P Operating license stage documents & correspondence

- 8009300169 "Rept of Zion/Indian Point Study Vol 2." informal rept STEVENBOR, M 0 Los Alamos Scientific Laboratory FIN A-7015 NUREG/CR-1411 V2 60/04/30 165pp Available at NTIS
- 8009050343 Discusses void formation in vessel head during 8006;1 natural circulation cooldown event Requests opinion re potential for voiding phenomenon in B&M designed NSSS CHECK.PS Assistant Director for Plant Systems 80/07/28 80/07/28 200
- 8009020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISERMUT.D O Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 ancl N/o NUREG EISENHUT, D 6 Division of Licensing 80/08/01 i19pp
- 9007090794 Forwards request for add1 info re fracture toughness design of steam generator & reactor coolant pump supports Facility has been classified as Group 1 plant in accordance nes been common common

- S009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disragarded Requested submittal should include proposed class of amend EISEMHUT.D G Division of Licensing BO/OS/O7 AOPP
- 8007190794 Forwards revised Westinghouse STS 3 9 8 2.3 9 10 to Bases 3/4 9 8 to 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NOVAK.T M Assistant Director for Operating Reactors 80/05/15
- --8009170817 Revised Westinghouse STS 3 9 8 2.3 9 10 8 Bases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Assistant Director for Operating Reactors 80/06/23 21pp
- 8009150515 Requests long-term solution to correct electrical override/ bypass problem NRC review found that manual sys-level actuation features for containment isolation 5 spray will not function after automatic safety signals reset VARGA.S A Operating Reactors Branch 1 80/08/20 3pp
- 8009220388 Advises that Ofc of Controller has been authorized to refund OUTHERDOR NAVISES that UTC or controller has been available.

  Class III amend fee sent withit 800025 application Refund authorized due to exemption re certain fire protection Tech Spec changes authorized by law b in public interest MILLER. W D License Fee Management Branch 80/08/25 ip
- 8009040420 Forwards details of proposed steam generator insp to be performed during mid-cycle outage as required by Amend 31 to OL Multi-frequency insp will be performed on 800 tubes in 32 steam generator hot leg (inlet)
  BAYNE.J P Power Authority of the State of New York 80/08/28 300
- 8009050273 Forwards info in response to NRC 800731 request re combination of SSE & LOCA responses for RCS Strain components of SSE & LOCA loads were combined since 88E responses were calculated elastically & LOCA inelastically BAYNE.J P Power Authority of the State of New York 80/0
- B009090383 Forwards "Rept on Evaluation of Thermal Plume Studies of Indian Point Nuclear Generating Station " Objectives of thermal plume program have been fulfilled Rept available in Central Files only ZARAKAS,P Consolidated Edison Co of New York 80/08/29 ip
- 8007090771 Confirms util commitments to NRC 791023 interim position on containment purging & venting Util position to remain in effect pending completion of long-term review VARGA,S A Decrating Reactors Branch 1 80/08/27 Jpp
- 8009120181 Forwards request for add1 info to complete review of electrical override/bypass aspects of engineered safety features VARGA.S A Operating Reactors Branch 1 80/08/29 Spp
- 8009120502 "Rept of Zion/Indian Point Study." Vol 1 MURFIN.N B Sandia Laboratories FIN A-1218 NUREO/CR-1410 VI. 80/08/31 400pp
- 8009120626 "Task Force Rept on Interim Operation of Indian Point " BERNERO,R M , DLOND,R M , PRITCHARD,W C Office of Policy Evaluations NUREG-0715 80/08/31 78pp Available at NTIS
- 8009120191 Forwards review & comments of dose calculation methods in offsite dose calculation manual (QDCM) Requests revised QDCM within 60 days Operating Reactors Branch 1 80/09/02 7pp
- 8009090506 Forwards table outlining effects of combining SBE & LOCA responses in analysis of Unit 2 RCS for postulated LOCAs, in response to NRC 800731 ltr
  ZARAKAS,P Consolidated Edison Co of New York 80/09/03 3pp
- 8009230230 Notification of 800910 meeting w/util in Bethesda.MD to discuss sus interactions study OLSHAN, L N Licensing Branch 1 80/09/05 2pp
- 8009290439 Forwards Amends 32 & 50 to Licenses DPR-64 & DPR-59, respectively, safety evaluation & notice of issuance & responsively. availability VARGA/S A Operating Reactors Branch 1 80/09/05 3pp

- --8009290446 Amends 32 & 50 to Licenses DPR-64 & DPR-59, respectively, changing organization charts & position titles & increasing mambership of safety review committee for both units VAROA.S A Operating Reactors Branch 1 80/09/05 26pp
- --8009290451 Safety evaluation supporting Amends 32 % 50 to Licenses

  DPR-64 & DPR-59; respectively

  \* Office of Nuclear Reactor Regulation, Director 80/09/05 3pp
- --8009290454 Notice of issuance & availability of Amends 32 & 50 to Licenses DPR-64 & DPR-59, respectively VARGA, S. A. Operating Reactors Branch 1 80/09/05 3pp
- BO09150254 Forwards "Cycle 3.Startup Physics Test Rept " Rept available in Central Files only BAYNE, J P Power Authority of the State of New York 80/09/11 1p
- 8009170325 Responds to NRC 800820 request for proposed long-term solution to correct blocking of manual sys-level actuation Asstures for containment isolation & containment spray Forwards sketches of actuation schemes & proposed solu BAYNE. J P Power Authority of the State of New York 80/09/11 400
- 8009180144 Discusses two risk studies currently underway Preliminary assessment of Indian Point risk profile contained in SECY 80-283 Zion risk profile assessment will combine accident sequence evaluation & containment failure analysis Assistant Director for Technology Review 80/09/11
- 8009240537 Forwards Amend 33 to License DPR-44 notice of issuance & availability VAROA.B A Operating Reactors Branch 1 80/09/12 4pp
- --8009260541 Amend 33 to Licanse DPR-64, requiring safeguards contingency plan be fully implemented within 30 days of Commission approval VARGA.S A Operating Reactors Branch 1 80/09/12 2pp
- --- 8009260545 Notice of issuance & availability of Amend 33 to License VARGA.8 A Operating Reactors Branch 1 80/09/12 2pp
- BOOGISODE4 Requests 6-month extension of due date for response to NRC BOOSO4 ltr re fracture-toughness design of steam generator & reactor coolant pump supports Addl time needed to obtain orginal support matl from original support lers

  BAYNE.J P Power Authority of the State of New York 80/09/15 1p
- BO09230451 Forwards corrected response to Question 4 to 800720 ltr re bactfitting of severe accident mitigation features BAYNE, J P Power Authority of the State of New York ZARAKAS, P Consolidated Edison Co of New York 80/09/16 3pp
- 8009250266 Forwards current training course outlines re heat transfer, fluid flow & thermodynamics, in response to NRC 800328 ltr ZARAKAS,P Consolidated Edison Co of New York 80/09/19 30pp
- 8009260442 Advises that staffing requirement to have three persons on-shift during all scheduled outages when unit is in cold shutdown mode will be deleted due to reduced potential for emergency during such periods BAYNE, J P Power Authority of the State of New York 80/09/23 [p
- G Inspection reports, IE Bulletins & correspondence
- 9009080537 Responds to IE Bulletin 80-16. "Potential Misapplication of Rosemount, Inc Models 1151 & 1152 Pressure Transmitters W/ Either A or D Output Codes " Models specified not used at ZULLA. 6 8 Power Authority of the State of New York 80/07/25
- BO09170936 Advises that response to IE Bulletin 80-14 will be consolidated w/reply to IE Bulletin 80-17 due to similarity of action items

  pASTERNAK, R J Power Authority of the State of New York 80/07/28
- BOO9220379 Forwards response to IE Bulletin 79-03A re longitudinal weld defects in ASME SA-312 Type 304 stainless steel pipe. All A-312 pipe used has seemless const SA-312 is not used in safety-related piping No action required BAYNE. J P Power Authority of the State of New York 80/07/29

- 8007220030 Responds to LE Bulletin B0-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protection Sys of Operating Nuclear Plants Designed by C-E " Relays are not used at facility ZULLA, S S Power Authority of the State of New York 80/08/08 1
- 8009030039 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required ORIER OH Region 1, Philadelphia, Office of the Director 80/00415 | 1 a Operating response requi ORIER, D.H. Re 199/15 1p
- 8009150303 Discusses IE insp on 800624-26 & forwards notice of violation b notice of proposed imposition of civil penalty STELLO.V Office of Inspection & Enforcement, Office of the Director 80/08/22 2pp
- --8009150306 Notice of violation from insp on B00524-26 Noncompliance noted failure to implement appropriate procedures for incore flux monitoring sys repair & neutron detector replacement & radiation overexposure to personnel

  4 Office of Inspection & Enforcement, Office of the Director 80/08/22
- ---8009150308 Natice of proposed imposition of civil penalties in amount of \$12,000 00 for items of noncompliance noted in IE insp on 800624-26 \* Office of Inspectson & Enforcement, Office of the Director 80/08/22 ip
- 8009180025 Forwards 1E Circular 80-18, "100FR50 59 Safety Evaluations for Changes to Radwaste Treatment Sus " No written response required GRIER.B H Region I. Philadelphia, Office of the Director 80/08/22 1p
- 9007120196 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover: 480 Volt Type K-6008 & K-DDN 6008 Circuit Breakers " No written response required GRIER B H Region 1, Philadelphia, Office of the Director 80/08/27 ip
- 8009230793 Forwards IE Circular 80-21. "Regulation of Refueling Crews " No written response required GRIER, B.H. Region 1, Philadelphia, Office of the Director 80/09/10 1p
- 8009240347 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Usa Shipments of Radioactive Matls " No written response required ORIER.B H Region I. Philadelphia, Office of the Director B0/09/12 1p
- R Periodic operating reports & related correspondence
- 8007030382 Forwards "Effluent & Waste Disposal Semiannual Rept. Jan-June ZARAKAS,P Consolidated Edison Co of New York 80/08/29
- ---8009030386 "Effluent & Waste Disposal Semiannual Rept.Jan-June 1980 "
  \* Consolidated Edison Co of New York 80/08/29 43pp
- 8009080323 Forwards "Effluent & Waste Disposal Semiannual Rept. Jan-June 1980 "
  ZULLA, S S Power Authority of the State of New York 80/08/29 1p
- --8009080325 "Effluent & Waste Disposal Semiannual Rept, Jan-June 1980 " # Power Authority of the State of New York 80/08/27 44pp
- 8009190442 Forwards monthly operating rept for Aug 1980 ZULLA, 8 8 Power Authority of the State of New York 80/09/15 10
- --8009190451 Monthly operating rept for Aug 1980
  CONNELL, C Power Authority of the State of New York 80/09/02 **4 գ գ գ**
- 8009230432 Forwards daily record of fish collections for Aug 1980, including daily species breakdown & total weight Unit 2 & 3 circulators were run for entire month Unit 1 circulators were run on 800808, 10,13,17,17,21,23,30 & 31 Consolidated Edison Co of New York 80/09/15 10 ZARAKAS, P
- ----BOD7230433 Daily record of fish collections from intake screens for Aug 1980 \* Consolidated Edison Co of New York 80/09/15 5pp

- 8009240452 Forwards quarterly rept on "Seismic Monitoring Network in Vicinity of Indian Point NY. Consolidated Edison Project. Mar-May 1980"

  ZARAKAS: P Consolidated Edison Co of New York 80/09/15 1p
- --8009240455 "Seismac Monitoring Network in Vicinity of Indian Point.NY, Consolidated Edison Project.Mar-May 1980 " \* Woodward-Clyde Consultants, Inc. 80/08/15 44pp
- S Reportable occurrences, LERs & related correspondence
- 8009020510 EN-80-038 on 800822, notice of violation & motice of proposed imposition of civil penalties of \$12.000 will be issued Action based upon alleged noncompliance recoverexposure of two individuals [BRGCKEIT,T W , THOMPSON.D Giffice of Inspection & Enforcement, Office of the Director 80/08/20
- 8009030610 RO on 800804.circulating water sys discharge temp exceeded Tech Specs limit Caused by high ambient river temps high discharge temps & broken circulating water pump Demand load & discharge temp reduced
  ZARAKAS.P Consolidated Edison Co of New York 80/08/28 2pp
- DOCKET 50-RB7 OCCNEE NUCLEAR STATION, UNIT 3
- F. Security, medical, emergency & fire protection plans
- 8007230256 Requests that all personnel be reminded of purpose of emergency motification sys & health physics network Sys installed for got use during smergency OfREILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22
- Q Adjudicatory correspondence
- 8007260664 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 REID,R W Operating Reactors Branch 4 80/08/27 2pp
- --8009260667 Order for mod of Licenses DPR-38, DPR-47 & DPR-55 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101 EISENHUF, D & Division of Licensing 80/08/29 App
- J Insurance & indemnity information
- 8009190424 Forwards Endorsement 58 to NELIA Policy NF-182 & Endorsement 43 to MAELU Policy MF-61 SANDERS, F D Duke Power Co 80/08/25 3pp
- 8007300428 Advises that invoices for facility indemnity fees should be addressed to WO Parker.not AC Thies PARKER.N O Duke Power Co 80/09/24 ip
- P Operating license stage documents & correspondence
- 8009150070 Responds to 800923 recommendations concerning lessons learned from 800225 transient at Crystał River Submits results of investigations re use of atmospheric dump valve at Occupie Units 1-3.AR Unit 1.Davis-Bess Unit 1 & THI-1 DENTON-H R Office of Nuclear Reactor Regulation, Director Zpp
- 8009020297 Submits interim criteria for shift staffing to all GL & CP licensees & applicants.per NRC 800907 itr Discusses administrative provisions for emergency & overtime work Davelopment & implementation to be reviewed within 90 days EISENHUT.D O Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for EISENNUT B Division of Licensing 80/08/01 119pp
- 8009230092 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D @ Division of Licensing 80/08/07 60pp

- 8009040085 Requests written confirmation of appraisal of critical electrical power generation situation in region served by Duke Power Co NGVAR, T M Assistant Director for Operating Reactors 80/08/13 Assistant Director for Operating Reactors 80/08/11
- 8009160501 Forwards Amends 86,86 % 83 to Licenses DPR-38,DPR-47 & DPR-55,respectively, safety evaluation & notice of issuance & availability Operating Reactors Branch 4 80/08/20 2pp
- --8009160502 Amends 86.86 % 83 to Licenses DPR-38, DPR-47 % DPR-55, respectively, incorporating test frequency requirements of 10CFR50, App Jinto containment leak test program REID.R N Operating Reactors Branch 4 80/08/20 7pp.
- --8009160506 Safety evaluation supporting Amends 86,86 & 83 to Licenses DPR-38,DPR-47 & DPR-55,respectively \* Office of Nuclear Reactor Regulation, Director 80/08/20 2pp
- --8009160507 Notice of issuance & availability of Amends 86.86 & 83 to Licenses DPR-38.DPR-47 & DPR-55, respectively REID.R W Operating Reactors Branch 4 80/08/20 2pp
- 8009160805 Notification of 800903 meeting w/util & Franklin Research Ctr in Bethesda MD to review NUREO-0578 Items 2 1 7 A&B FAIRTILE.N B Operating Reactors Branch 4 80/08/21 ip
- 8007030507 Forwards proposed revision to Tech Specs to support Unit 3 at full rated power during Cycle 6 & B&W rept, "Oconee Unit 3,Cycle 6 Reload Rept."

  PARKERS N D Duke Power Co 80/08/25 3pp
- --8007030513 Proposed Tech Specs revision for Cycle 6
  # Duke Power Co B0/08/25 23pp
- --8009030519 "Oconee Unit 3,Cycle 6 Reload Rept "
  # Babcock & Wilcox Co BAW-1634 80/08/31 80/08/31 3800
- 8009020025 Forwards B&W rept, "Evaluation of Instrumentation to Detect Inadequate Core Cooling Prepared for 177 Owners Group," supplementing earlier util submittals re Lessons Learned Item 2 1 3 b No addl instrumentation needed W/o encl PARKER,W O Duke Power Co 80/08/26 ip
- 8007;00489 Informs NRC that revised radiological ETS "Offsite Dose Calculation Manual" & proposed process control program for solid waste sys will be forwarded by 800730 PARKER:N D Duke Power Co 80/07/03 ip
- B009190154 Advises of NRC review of util 800928 submittal re standby shutdown facility Pages 2-1,5-1,5-2,5-3,4-3 & 7-1 should be uithheld per 10CFR2 790 Util should resubmit document w/ deletions within 30 days REID,R W Operating Reactors Branch 4 80/09/09 200
- 8007270434 Informs of acceptability of response to NRC 791109 ltr reportions of ECCS evaluation models dealing w/fuel cladding suelling & incidence of rupture REID.R W Operating Reactors Branch 4 80/09/09 2pp
- B009230707 Bubmits corrections to 800711 ltr re cracked steam generator manuay studs at Oconee 3 TAYLOR, J H Babcock & Wilcox Co 80/09/15 ip
- 8009230724 Disacrees w/NRC 800909 ltr re classification of Standby Shutdown Facility licensing document Document should be withheld (ref 10CFR2 790) No nonpropietary version will be submitted PARKER, N O Duke Power Co 80/09/17 1p.
- 8009300486 Forwards response to NRC 800611 request for change in facility Tech Specs.providing for redundancy in decay heat removal capability No changes necessary to Tech Specs PARKER.W O Duke Power Ca 80/09/24 3pp
- G Inspection reports, IE Bulletins & correspondence
- 8009100058 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/07/24

- SOOF040540 Responds to IF Bulletin 80-16 Resempent Model 1151 & 1152 pressure transmitters w/output codes A or D are used for indicating reactor coolant pressure & providing input to control steam generator level PARKER, N D Buke Power Co 80/07/30 3pp
- 8009030175 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/15 to
- 8009150137 Forwards IE Circular 80-18, "tOCFRSO 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22
- BDOOP170233 Responds to IE Bulletin 80-19, Revision 1, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Review indicates relays are not in use at facility PARKER, N.O. Dute Power Co. 80/08/22 ip
- SOO9100801 Ack receipt of 800623 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 90-269/80-17.
  50-270/80-12 & 50-287/80-11
  LEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/09/26 ip
- --8009100807 Responds to NRC 800523 ltr re violations noted in IE Insp Repts 50-269/80-17,50-270/80-12 & 50-287/80-11 Corrective actions incidents involving failure to perform surveillance are being reviewed & new procedures will be established PARKER, W.O. Duke Power Co. 80/06/23 3pp.
- --8099100B1| Forwards IE Insp Repts 50-269/80-17.50-270/80-12 & 50-287/80-11 on 800401-30 & notice of violation LEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/05/23 2pp
- --BOC9100B13 Notice of violation from insp on 800401-30
  # Region 2, Atlanta, Office of the Director 80/05/23 ip
- --BOO9100B16 IE Insp Repts 50-269/80-17,50-270/80-12 & 50-287/80-11 on BOO401-30 Noncompliance noted failure to submit 30-day repts when surveillance test frequency was missed MARTIN,R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch JAPE,F Region 4, Dallas, Office of the Director 80/05/23 11pp
- 8009030505 Submits Revision 3 to util 90-day response to IE Bulletin 79 018 re Class IE equipment environ qualification Raychem Agat shrink tubing, scotch Cast-9, transmitter O-ring seals & lubricating grease to be replaced during refueling outage THIES.A C Duke Power Ca 80/08/27 2pp
- BOO9110658 Responds to IE Bulletin 80-15 Emergency notification system eviewed Sys is powered by onsite power but does not have backup onsite emergency power Emergency power supplied by telephone company
  PARKER, U D Duke Power Co 80/08/27 2pp
- 8009120343 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover! 480 Volt Type K-6005 & K-DDN 6005 Circuit Breakers " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/27
- 8009290297 Forwards IE Circular 80-21, "Regulation of Refueling Crews"
  No written response required
  D'REICLY, J.P. Region 2, Atlanta, Office of the Director 80/09/10
  508
- 8009300616 Ack receipt of 800825 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/80-23, 50-270/80-20 & 50-287/80-17 LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Br
- --BO07300526 Forwards response to NRC 800730 ltr re violations noted in 1E Insp Repts 50-269/80-23,50-270/80-20 & 50-287/80-17 Corrective actions informed operations personnel that use of correct & verified procedures must be ascertained PARKER.N O Buke Power Co 80/08/25 3pp
- --8004300630 Forwards IE Insp Repts 50-269/80-23 & 50-270/80-20 & 50-287/80-17 on 800602-30 & notice of violation LEWIS,R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 60/07/30 2pp

- --8009300631 Notice of violation from insp on 800602-30 \* Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/07/28 1p
- --8009300640 IE Insp Repts 50-269/80-23.50-2/0/80-20 & 50-287/80-17 Noncompliance noted use of Unit 1 procedure to perform periodic test on Unit 2 ORDERS.W. JAPE.F. Region 2. Atlanta. Office of the Director MARTIN.R D. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/07/28 13pp
- R Periodic operating reports & related correspondence
- 8009020044 Forwards "Radioactive Effluent Release Semiannual Rept." Jan-Jure 1980 PARKER.W O Duke Power Co 80/08/25 1p
- --8009020047 "Radioactive Effluent Rejease Semiannual Rept." Jan-June 1980 \* Duke Power Co. 80/08/25 Apr
- 8009090577 Forwards revision to "Radioactive Erfluent Release Semiannual Rept." Jan-June 1980 PARKER.W O Duke Power Co 80/09/03 4pp
- --8009070582 Revision to "Radioactive Effluent Release Semiannual Rept."
  Jan-June 1980
  \* Duke Power Co 80/09/03 3pp
- BO09190462 Forwards monthly operating repts for Aug 1980 PARKER.W O Duke Power Co 80/09/15 1p
- ---8009190473 Monthly operating repts for Aug 1980 REAVIS, J A Duke Power Co 80/09/15 17pp
- S Reportable occurrences, LERs & related correspondence
- 8009150393 Updates RO-287/80-ii re cracked studs on once-through steam generator manuay B&W has completed examination of three cracked studs Final results will be documented in rept for util by mid-Sept PARKER, W O Duke Power Co 80/09/08 5pp
- BO09180395 Forwards LER 80-009/01T-2 PARKER, W D Duke Power Co 80/09/12 6pp
- --8009180409 LER 8D-009/01T-2 on 800710 after reactor trip, relay in A phase of normal source voltage monitor circuit of emergency power switching logic failed Caused by reactor trip & auxiliary power transfer Relay replaced & returned to syc PHILPOTT:F T Dute Power Co 80/09/12 lp
- B009260450 Forwards LER 80-012/01T-0 PARKER, W O Duke Power Co 80/09/22 3pp
- --8009260455 LER 80-012/01T-0 on 800909 discovered boron analysis on concentrated boric acid storage tank was not conducted as required Caused by personnel error Min concentration verified & appropriate disciplinary action taken JONES, J. L. Duke Power Co. 80/09/22 ip
- T Hearing transcripts on non-antitrust matters
- 8009260313 Submittal of prepared testimony for first hearing session No attempts made to provide complete amswers to ASLB 800908 memorandum & order re-physical separation of TMI units Certificate of Syc enci Related correspondence TROWBRIDGE. OF Metropolitan Edison Go TROWBRIDGE. OF Shaw, Pittman, Potts & Trowbridge 80/09/15 7pp
- ---8007260366 "Small Break Operating Guidelines" Related correspondence 4 Babcock & Wikcox Co 69-1106001-00 79/11/30 48pp
- DOCKET 90-289 THREE MILE ISLAND NUCLEAR STATION, UNIT E F Security, medical, emergency & fire protection plans
- 8009230175 Requests that all personnel be raminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency GRIER, B H Region 1. Philadelphia, Office of the Director 80/08/22 3pp

- B009290077 Forwards comments on emergency plan indicating need for addlenter by commitment to complete review Revision meeting NUREG-0654 evaluation criteria, must be provided within 45 days REID:R U Operating Reactors Branch 4 80/09/09 App
- G Adjudicatory coirespondence
- 80092&0301 Memorandum laying out grouping & sequence of hearing issues analysis & mod of plant design & procedures separation of Units I & 2.emergency planning & preparedness mgt capability & financial qualifications Comments welcomed REDURENIDE, C F Metropolitan Edison Co TROUBENIDE, S F Shaw, Pittman, Potts & Troubridge 80/07/18 lipp
- 8009160590 Requests that testimony re emergency preparedness for TMI-1 restart hearings be submitted as soon as possible GRIMES, B.K. Emergency Preparedness Program Office 80/07/29 2pp
- 8009020273 Notifies that math re util 800729 filing u/PA Public Util Commission, petition for extraordinary rate relief. transcripts of interim hearings & brief will be forwarded, per NGC 790921 & 1109 requests KETNER, M H Metropolitan Edison Co 80/08/20 1p
- 8009110528 Forwards NUREG-0578 NUREC-0585 NUREG-0680 & NUREG-0694
  Represents V Taulic Co of America petitioners in TMI-1
  restart proceeding M/o encls
  SOUDER.J. L. Division of Rules and Records 80/08/21 1p
- 8007020421 Forwards Exhibits JC-G, JC-H & index of exhibits filed on 800920 % 21 to keep NSC informed of significant ragulatory developments affecting General Public Utils companies SHGENEY.L E Jersey Central Power & Light Co 80/08/22 19pp
- 8009020052 Suppl response in opposition to Victaelic Company of America late intervention Review of second prehearing conference transcript 5 encl 800822 Harrisburg Evening News article indicates prior awareness of problem WCErtificate of Svc SHOLLY,S C Affiliation Unknown 80/08/23 Bpp
- 8007020407 Revision of Contention 5 per ASLB 800820 order Specifies aspects demonstrating that licensee is not technically qualified to operate facility re safety-related maint & repair Certificate of Svc encl MIDDFF.M P Three Mile Island Alert WIDDFF.M P Widoff, Reager, Sekbuitz 2 Adler 80/08/26 Spp
- 8007080332 Forwards info re costs of purchasing energy, in response to NRC 770921 & 1109 requests for info re significant developments affecting General Public Util companies in restart proceeding
  SWEENEY, L. E. Jersey Central Power & Light Co. 80/08/26 66pp
- 8009050427 Motion for supplemental interrogatories & request for documents directed to licenses & based on new info revealed in Met Ed publication "TMI Today," Aug 1980 issue,Page 2 Certificate of Svc encl SHOLLY,S C Affiliation Unknown 80/08/27 Spp
- 8009040278 Response to licensee interrogatories re Revision 2 of emergency plan Addresses evacuation conditions, staging area provisions, receiving points for patients & participation of surrounding counties Certificate of Svc encl CUNNINGHAM, J D Reuberry Township, York Haven PA CUNNINGHAM, J D Foz, Farr & Cunningham 80/08/28 7pp
- 8009050425 Motion for correction of record to include failures of instruments & equipment outside containment that contributed to TM1-2 accident Focuses on TM1-2 fuel pool which may endanger TM1-1 aperation

  LEWIS.M I Affiliation Unknown 80/08/28 3pp
- 8009040358 Response to ASLB 800820 order re UCS motions for summary disposition Suggests 800910 for response to motion on Contention 5 % 801001 for responses to motion on Contention 13 Certificate of Svc encl WEISS, ER Union of Concerned Scientists WEISS, ER Sheldon, Harmon & Weiss 80/08/29 3pp
- 800704036! Inquires whether Subparagraph d to Antinuclear Group Representing book Contention 4 was filed w/ASLB.re licensee diagnostic & analysis work Transcript of 791100 prehearing conference inficated addition at Pages 595-597 MDRAN.D M Atomic Safety and Licensing Board Panel 80/08/27 16
- 8009110450 Notifies of delay in Sept 1980 hearing re restart proceedings NRC is not prepared on first five items in NRC 790809 order Requests cooperation in assuring that further delays are obviated SHAPAR, H K Office of the Executive Legal Director 80/08/29 2p.

- 8007i60167 Suppl to 800804 response to licensee interrogatories re emergency plan in local counties Plans do not address evacuation during significant population changes Certificate of Svc anci SHOLLY, S C Affiliation Unknown 80/08/29 Spp
- B009260592 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by B0101 REID.R W Operating Reactors Branch 4 B0/08/29 App
- --8009260597 Order for mod of License DPR-50 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by B01101
  EISENNUT.D G Division of Licensing 80/08/29 &pp
- BO09040227 Motion for clarification of ASLB questions at BO0812-13 prehearing conference Addresses HPI sys pump operation to dissipate decay heat & feedwater sys vulnerability to nonsafety-grade sys W/Certificate of Syc SINGER.L N Hearing Branch 2 B0/09/02 App
- 8009040365 Response to UCS 800819 ltr seeking reconsideration of ASLB 800812-13 prehearing conference ruling which denied UCB motion for summary disposition Discusses UCS facts which do not entitle UCS to favorable decision W/Certificate of Svc 1RDWBRIDGE, G F Metropolitan Edison Co TROWBRIDGE, G F Shaw, Pittman, Potts & Trowbridge 80/09/02 9pp
- 8009050420 Memorandum & order danying Victaulic Company of America 800813 petition to intervens on grounds of lateness & lack of standing SMITH, I W Atomic Safety and Licensing Board Panel 80/09/02 ilbo
- 8009100431 Memorandum advising that SC Sholly will inspect licensee control room mock-up in lieu of 800827 request to suppl discovery re new info in TMI Today 800826 article Sholly 800827 request withdrawn Certificate of Svc encl TROWBRIDGE. 0 F Metropolitan Edison Co TROWBRIDGE, 0 F Shaw, Pittman, Potts & Trowbridge 80/09/03 Spp
- 8009120226 Response to licensee interrogatories re emergency plan.
  Revision 2 Testimony re Midas radiological assessment sys
  must be provided by licensee Supporting documentation &
  Certificate of Svc encl Related correspondence
  FELL.D M Anti-Nuclear Group Representing York PELL.D.M
  Feil.D M 80/09/03 12pp
- 8009120232 Application for subpoens duces tecum directed to RL Curry of York County Emergency Mgt Agency to give 800917 deposition & to bring log of 800716 test exercise Affidavit & Certificate of Svc encl Related correspondence.

  PELL, D M Anti-Nuclear Group Representing York PELL, D M.
  Pell, D M 80/09/03 7pp
- B009090249 Response stating no objection to TMI Alert 800B0B motion seeting free copy of hearing transcript ASLB 800B15 memorandum & order authorized such supply Certificate of Svc encl SINGER.L N Hearing Branch 2 80/09/04 4pp
- 8009110394 Forwards responses to NRC 790921 & 1109 requests for info re significant regulatory developments affecting General Public Utils companies in restart proceeding Federal executive agencies & rate coursel data requests encl SWEENEY,L E Jersey Central Power & Light Co 80/09/05 25pp
- B009110020 Notice advising that beginning B00915, discovery reading room will be open upon 24-h advance notice Room will be permanently closed on B01015 Hearing documents will be maintained in vicinity W/Certificate of Svc BLAKE, E.L. Metropolitan Edison Co. 80/09/08 5pp
- 8009110799 Memorandum & order forwarding contentions & ASLB questions to be heard at 801015 evidentiary hearing per ASLB 800815 memorandum & order. Directs parties to report corrections to contentions by 800915 Courtesy notification encl
  SMITH-I H Atomic Safety and Licensing Board Panel 80/09/08, 400a
- 8009160030 Revised emergency planning Contention 9 incorporating significant developments re York County 800827 revised emergency plan & release of FEMA 800812 rept to US President Certificate of Bvc encl
  SHOLLY.S C Affiliation Unknown 80/09/08 20pp

- 8009160371 Forwards Public Advocates Ofc 800903 data request, Dept of Army 800821 ltr to State of NJ Board of Public Utils, JB Kirsten 800826 ltr to Judge Manshall & third info request of Faderal Executive Agencies re TMI-1 restart proceeding SHE≅NEY,L E Jersey Central Power & Light Co 80/09/08 11pp
- BO09180436 Second final amended contentions re util. York & Dauphin Counties' emergency plans York plan evacuation routes not utind-dependent Util plan unacceptable due to lack of siren warning sys Certificate of Svc encl
  CUNNINGHAM. J.D. Newberry Township TMI Steering Committee 80/09/08
  30pp
- 800711078B Response stating no objection to M1 Lewis 800826 request for hearing transcript.if limited to portions dealing w/Lewis contention Objects to request re reconsideration of status as intervenor.

  SINGER, L N Hearing Branch 2 80/09/10 7pp
- 80091f0791 Response stating no objection to Environ Coalition on Nuclear Power 800922 request for free transcripts, if limited to 1-yr period starting 800725 ASLB not empowered to provide same for other than stated period N/Certificate of Svc SINGER.L N Hearing Branch 2 80/09/10 5pp
- BC09150041 Request for extension until 10 days after responses to UCS BC0805 motion re summary judgment, for UCS to file direct testimony on Contention 5 Contention does not relate to safety issues & has no hearing impact M/Certificate of Syc HEISS,E R. Union of Concerned Scientists WEISS,E R. Sheldon, Harmon & Heiss. 80/09/10 3pp
- B009170291 Responds to NRC 800921 & 1109 data requests re restart proceeding Forwards Administrative Law Judge recommended decision, Commission 800828 final order & PA Public Util Commission 800729 order initiating investigation Commission 800729 order initiating investigation KEINER, M H Metropolitan Edison Co 80/097/10 25pp
- 8009180131 Advises of issuance of Amend 57 to OL, revising ECCS design & surveillance requirements Mods to ECCS design involve matters re restart proceeding CUTCHIN.J M Hearing Branch 3 80/09/10 2pp
- 80091&0534 Memorandum & order requesting normal svc of written testimony & exhibits per ASLB 800815 order Extra copies of cross-exemination matl must be brought to hearing Free transcripts denied for prehearing & granted for hearing SMITH.I H Atomic Safety and Licensing Board Panel 80/09/11 3pp
- BC07170219 Request for extension until 801015 to respond to ASLB 800908 associated to the second to account to the second second to the second second
- 8009170302 Response in opposition to UCS 800910 request for extension to file direct testimony or Contention 5 Info needed to prepare testimony already filed by applicant & NRC Basis for extension obviated Certificate of Byc encl TROWBRIDGE, O F Hetropolitan Edison Co TROWBRIDGE, O F Shew. Pittman, Potts & Trowbridge 80/09/11 5pp
- BOO91B057: Second amended final addl Contentions 12,13,16,17,18 & 17 re Dauphin County emergency plan Plan deficient due to lack of Long-kerm mpt planning Affidavit & Certificate of Svc encl CURNINGHAM.J D. Newberry Township TMI Steering Committee 80/09/11
- BOO9160139 Response in support of licensee 800825 request to dismiss Environ Coalition on Nuclear Power Contentions 2-4,2-7,2-11, 2-43:2-20/2-30:2-26 & 2-28 due to failure to respond to applicant 800729 interrogatories. Certificate of Svc encl GRAY, J R Hearing Branch i 80/09/12 Spp
- 8009170137 Hemorandum & order granting licensee motion to compel Environ Coalition on Nuclear Power response to 800727 interrogatories re emergency plantRevision 2 Licensee may move for dismissal if answers are not filed in 10 days SMITH.! U Atomic Safety and Licensing Board Panel 80/09/12 2pp
- BOO9170182 Memorandum & order granting extension until 10 days after svc of NRC or licensee testimony, for UCS to file written testimony re Contention 5 Licensee & NRC written testimony and be filed by 801015 Addl extensions will be considered SMITM. I W Atomic Safety and Licensing Board Panel B0/09/12 2pp
- BOO9170198 Memorandum specifying ASLB questions to be addressed by NRC & licensee prior to & at hearing Questions of ASLB 800908 memorandum & order will be heard at first hearing segment Other parties may respond to questions if interest affected SHITH, I W Atomic Safety and Licensing Board Panel BO/09/12 9pp

- 8009170122 Forwards safety evaluation & Amend 58 to License DPR-50, revising Tech Specs on mot reorganization in shutdown status Changes may be modified by ASLB W/O encls SWANSON,D T Hearing Brench 1 80/09/15 1p
- 8009170165 Response in support of Antinuclear Group Representing York 800903 application for issuance of subpoena for RL Curry deposition Urges reasonable date for examination after 800917 Certificate of 8yc encl GRAY, J R Hearing Branch 1 80/09/15 7pp
- 8009170254 Request for add1 time to file testimony Info must be coordinated among witnesses Affected parties except Environ Coalition on Nuclear Power will not file testimony prior to NRC filing TOURTELLOTTE, J. Hearing Branch 4 80/09/15 1p
- --B009170296 Affidavit forwarding schedule for NRC testimony which will be filed on 800925 re core cooling & during Sept-Oct 1980 re equipment design & mods Certificate of Svc encl NOVALT M Assistant Director for Operating Reactors 80/09/15 Spp
- 8009180557 Memorandum & order granting State of PA extension until 801006 to present position on emergency planning contentions SMJTH, I W Atomic Safety and Licensing Board Panel 80/09/15 ip
- 8007230639 Request for 45-day extension to file direct testimony on Contention V(D) re emergency filtration of containment, due to change of counsel & involvement in answering interrogatories
  FELL.D M Anti-Nuclear Group Representing York 80/09/15 2pp
- 8007230628 Advises that York,PA LPDR will be closed on 800727 York TM1-1 & 2 documents will be available at restart hearing NRC must be informed by 800724 if parties object to course of action BMARIZ,L L Antitrust Division 80/09/16 3pp
- B009260175 Forwards info containing significant regulatory developments affecting General Public Util companies re restart proceeding Info consists of responses to Rate Counsel, FEA & DID requests SMELNEY, L. E. Jersey Central Power & Light Co. B0/09/16 31pp
- B009220408 Memorandom & order granting indefinite extension for NRC & intervenors to file testimony on UCS Contention 7. Sholly &(b) & 15 & Antinuclear Group Representing York Y(B) & Y(C) Util response to emergency planning may be filed on B00919 SMITH. I W Atomic Safety and Licensing Board Pane) B0/09/17 2pp
- 8009220411 Memorandum supplementing ASLN 800820 memorandum & order in which UCB motion for summary disposition of Contentions 5 & 13 was denied Cites & discusses authorities in support of ASLB discretionary action questioned by UCB SMITH, I W. Atomic Safety and Licensing Board Panel 80/09/17 3pp
- 8009230024 Memorandum & order directing NRC to report suggested schedule for remainder of proceeding NRC written testimony on contentions & issues must be filed by 800925 & 1002 Rept re failure to file timely testimony, may be made on 801010 SMITH, I # Atomic Safety and Licensing Board Panel 80/09/17 7pp
- 8007230449 Informs NRC of significant regulatory developments affecting General Public Utils companies Administrative Law Judge S Harshell initial decision enc1 SWEENEY:L E Jersey Central Power & Light Co 80/07/17 5pp
- 8007230434 Forwards Exhibits JC-600 & JC-601 filed in restart proceeding includes LS Reis testimony & "Certain Data Used in Determination of Fair Rate of Return." prepared by Reis & Chandler, Inc SMEENFY, L E Jersey Central Power & Light Co 80/07/18 44pp
- 8009250017 Response to contentions re emergency plan, Revision 2 Antinuclear Oroup Representing York Contention IIIA(L) untimely No new info presented in Newberry & SC Sholly contentions Certificate of Bvc encl 2AHLER, R E Metropolitan Edison Co ZAHLER, R E, Shaw, Pittman, Potts & Troubridge 80/09/18 10pp
- 8009240535 Submits list of people to be subpossed re Contention 5 & identifies work requests, maint log books & payroll register to be subpossed Brief Justifying subposses enci Related correspondence
  ADLER, T.A. Widoff, Reager, Selkowitz & Adler 80/09/19 2pp
- --8009240536 Outlines planned DJ Bonett: testimony re Contention 5 & work raquest summaries Related correspondence
  # Widoff, Reager, Sellowitz & Adlar 80/09/19 2pp

- --8007240538 Brief justifying subposens re Contention 5 Work request logs & Certificate of Svc enct Related correspondence ADLER.T A Metropolitan Edison Co ADLER.T A Widoff, Reager, Selvowit: & Adler 80/09/19 70pp
- 800924053: Forwards NRC subposma for sic upon AL Curry Cites appearance time discrepancy between recipient request & subposma Related correspondence
  SMITH: U Atomic Safety and Licensing Board Panel 80/09/22 1p
- --8009240532 Subpoons requiring appearance of RL Curry for 801002 oral exam Related correspondence SMITH, I W Atomic Safety and Licensing Doard Panel 80/09/22 200
- 8009260666 Request for extension until mid-Oct to respond to licensee interrogatories per ASLB 800912 order to compel Issues of emergency planning & evacuation plans will not be subj of hearing until substantially later N/Certificate of Svt JOHNSRUB, J H Environmental Coalition on Nuclear Power 80/09/22
- 8007300010 Motion for 2-wk extension to reply to licensee emergency planning interrogatories in response to ASLB 800712 order to campel Intervenor representative unreachable due to absence for personal matter Certificate of Svc encl Environmental Coalition on Auclear Power 80/09/22 PERKINS, J
- 8009300011 Forwards util 800916 inter-ofc memo organizing ASLB 801014 tour to facilities Svc list encl Related correspondence BLAKE.E L. Shau, Pittman. Potts & Trowbridge 80/09/22 7pp
- 8009300629 Notion for appointment of independent experts to determine questions of safety-related maint Bases request on Kemeny Commission rept. Vol IV.Page 105 % on NRC practices not assuring proper maint procedure Certificate of Svc encl ADLER.T A Three Mila Island Alert ADLER.T A Hidorf, Reager, Seikowitz & Adler 80/09/22 Spp
- --8009300632 Motion for right to submit surrebuttal testimony TMI Alert case must be presented out of sequence prior to NRC safety evaluation on maint issue, per ASLB previous ruling Centificate of Svc encl
  ADLER, T.A. ADLER, T.A. Three Mile Island Alert 80/09/22 3pp
- 8009260003 Response in opposition to portions of Newberry Township TMI Steering Committee Contentions 13 & 15 & all of Contentions 12...13 & 29 Does not object to 600908 & 11 contentions Requests status of prior contentions re-emergency planning GRAY.J R Hearing Branch 1 60/09/23 App
- --8009260004 Response in opposition to Environ Coalition on Nuclear Power DOYACOUN RESPONSE IN Opposition to Environ coalition on BOOPOB revised emergency planning Contentions 2-2 & 2-4
  Intervenor should be permitted to adopt SC Sholly revised
  Contention B-I H due to similarity & adequate specificity
  GRAY, J R Hearing Branch \$ 80/09/23 & 6pp
- --8009260006 Response stating no objection to SC Shally 800909 revised emergency planning contention Opposes admission of Portions B | B(4),B | G(14)-(23).8 | L & B | II A Cortificate of Svc ORAY, J.R. Hearing Branch 1 80/09/23 1100
- 8009260645 Memorandum & order granting extension until 80:003 for Antinuclear Group Representing York to file J Beyea testimony NRC & licensee may file cross-examination by 801015 Requests for relief will be considered if prejudiced SMIYH. U Atomic Safety and Licensing Board Panel 80/09/23 2pp
- 8007300022 Response in opposition to Environ Coalition on Nuclear Power 800717 motion for add1 time to respond to licensee interrogatories re emergency planning Good cause not shown Certificate of Svc encl
  ZAHLER.R E Metropolitan Edison Co ZAHLER.R E Shaw, Pittman, Potts & Trombridge 80/09/23
- 8009300617 Response in opposition to licensee 800918 objections to portions of revised emergency plan Contention 8 Contention arose from discovery on Contention 4 which revealed new problems re radiation dose readings W/Certificate of Syc SHCLLY 8 C Affiliation Unknown 80/09/20 14pp
- 8007300003 Memorandum & order re THI Alert Contention 5 Intervenor plan to offer 1.100 work orders unrealistic Burden of proof re pattern of deferred maint falls on licensee, Fifty work orders must be designated by 801003 Sets testinony filings SMITH.I W Atomic Safety and Licensing Board Panel 80/09/24 App

- G009300006 Memorandum & order directing Environ Coalition on Nuclear Power to respond to util interrogatories re emergency plan, by B01016 Intervenors' responses to util & NRC objections to emergency planning contentions shall be filed by B01016 SMITH.I W Atomic Safety and Licensing Board Panel 80/09/24 25 80/09/24 2pp
- 8009300015 Forwards 18 subpoenss directed to util employees for evidentiary hearing appearance per 800923 telcon & ASLB 800924 memorandum & order SMITH, I I? Atomic Bafety and Licensing Board Panel 80/09/24 1p.
- 8009300020 Request for extension until 801030 to file cross-examination plans per ASLB 800815 memorandum & order Urges further extension until 801103 for hand-delivery filing Certificate of Evc enci TROMBRIDGE.G F Metropolitan Edison Co TROWBRIDGE.Q F Bhaw. Pittman, Potts & Trowbridge 80/09/24 4pp
- 0009300417 Formards UCS direct testimony on Contentions 3 & 10 Fe Testart hearing Also forwards UCS interrogatories to NRC based on new info Testamony on Contention 5 will be provided pending receipt of NRC testimony WEIBS.E R Sheldon, Harmon & Weiss 80/09/25 1p
- --B009300420 Direct testimony of RD Pollard on behalf of UCB re UCB Contention 3 POLLARD, R D Union of Concerned Scientists 80/09/25 18pp.
- -8009300422 Direct testimony of RD Pollard on behalf of UCS re UCS Contention 10
  POLLARD, R D Union of Concerned Baientists 80/09/25 25pp
- --8009300423 UCB interrogatories requesting clarification of NUREO-0578 WEISB,E R Union of Concerned Scientists WEISB,E R Sheldon, Harmon & Weiss 80/09/25 10pp
- 8009300315 Question 11 directing licenses & NRC to present evidence that Page A-45 requirements of NUREQ-0578 are met ABLB not satisfied w/NRC findings in SER re Recommendation 2 1 9 C on transients & accidents SMITH, I II Atomic Safety and Licensing Board Panel 80/09/26 Lp

### H General correspondence

- 8009110642 Responds to Jonke 800218 ltr to President Carter expressing concerns re delay in TMI-1 return to svc & rate structure NRC has ordered that public hearings be conducted to determine whether facility should be operated REID.R W. Operating Reactors Branch 4 80/07/10 5pp
- 8007220208 Responds to LF Wirth 800323 itr to President Carter expressing concerns re delay in TMI-1 return to svc & rate structure NRC has ordered that public prehearings be conducted to determine whether facility should be operated REID.R W Operating Reactors Branch 4 80/07/10 2pp
- 8007090212 Responds to 800527 postcard re delay in returning facility to operation Public hearing to address issues appropriate to public health & safety scheduled for Fall 1980 REID, R U Operating Reactors Branch 4 80/07/15 ip
- --8007070216 Expresses concern for delay in returning facility to operation Nuclear power essential to economic health of country & state
  DULAN,V R Affiliation Unknown 80/05/27 1p
- 8007110637 Responds to CP Cole 800214 ltr to President Carter expressing concerns re rate structure NRC has ordered that public hearings be conducted to determine whether facility should be operated REID.R W Operating Reactors Branch 4 80/07/25 4pp
- 8009220188 Responds to LE Adam 800502 ltrs expressing concerns re delay in TMI-1 return to see NRC has ordered that public hearings be conducted to determine whether facility should be operated
  REID, R W Operating Reactors Branch 4 80/07/25 2pp
- --8009220190 Expresses concerns re delay in placing TMI-1 back into svc & rate structure prescribed for Met Ed ADAM.L E Affiliation Unknown 80/05/02 2pp
- 8009220198 Responds to J Folk 800520 ltr expressing concerns re delay in TKI-1 return to svc NRC has ordered that public hearings be conducted to determine whether facility should be REID, R W Operating Reactors Branch 4 80/07/25 2pp

- --8009220200 Expresses concerns re delay in placing TMI-1 back into svc FOLK, J. Affiliation Unknown 80/05/20 3pp
- 8009220201 Responds to O Albert 800510 ltr expressing concerns re delay in TMI-1 return to svc NRC has ordered that public hearings be conducted to determine whether facility should be operated REID, R & Operating Reactors Branch 4 80/07/25 2pp
- --8009220209 Expresses concerns re delay in placing TMI-1 back into ave ALBERT. G. Affiliation Unknown 80/05/10 2pp
- 8007220202 Responds to L. Lesh 800725 1tr expressing concerns re delay in TMI-1 return to svc & rate structure prescribed for Met Ed NRC has ordered that public hearings be conducted to determine whether facility should be operated REID.R N Operating Reactors Branch 4 80/07/25 2pp
- ---8009220211 Expresses concerns re delay in placing TMI-1 back into svc & rate structure prescribed for Met Ed LESH:L Affiliation Unknown 80/03/25 2pp
- 8009220203 Responds to E Knausman 800331 ltrs to President & NRC expressing concerns re delay in TMI-1 return to svc NRC has ordered that public hearings be conducted to determine whether facility should be operated PEID,R W Derating Reactors Branch 4 80/07/25 4pp
- --8009220207 Expresses concerns re delay in placing TMI-1 back into svc KMAUSMAN.E Affiliation Unknown 80/03/31 2pp
- 8009020465 Responds to postcards re release of Kr-85 Potential public health impact from using any proposed strategies for removing Kr-85 is negligible Purging method is quickest & tafest for workers to accomplish SNYDER.B J TMI Program Office 80/08/11 20p
- --8009020472 Expresses concern re release of Kr-85 from facility QL should be revoked Health of local people being damaged PETROSKY, J. A. Affiliation Unknown 80/08/26 2pp
- 8009030578 Responds to 800215 ltr urging revocation of util OL & permanent shutdown of facility Commission has ordered public hearing to determine if facility should be operated Forwards order outlining issues re public health & safety W/o encl SNYDER.B, J TMI Program Office 80/08/11 ip
- --8009030&80 Urges revocation of util QL & permanent shutdown of facility due to threat posed to public health & safety ALIHOUSE, V Affiliation Unknown 80/02/15 ip
- BOOTO306BI Responds to 800215 ltr urging revocation of util OL & permanent shutdown of Facility Commission has ordered public hearing to determine facility operation Forwards order outlining issues re-public health & safety H/o encl SNYDER.B J. TMI Program Office 80/08/11 ip
- --8009030483 Urges revocation of util OL & permanent shutdown of facility due to threat posed to public health & safety SMEENEY, A A Affiliation Unknown 80/02/15 3pp
- BO07100062 Responds to 791206 ltr re TMI cleanup operations Commission issued order on 800612 for temporary mod of license, authorizing controlled purging of Kr-85 from reactor bldg atsosphere
  BNYDER.B J TMI Program Office 80/08/11 2pp
- 8009230143 Responds to 800806 ltr urging expeditious restarting of facility No action will be taken until completion of public hearing re facility .

  INGRAM.F Office of Public Affairs 80/08/13 ip
- --8009230148 Urges restarting of facility NRC is being unfair to util & ratepayers by delay
  FRANCIS, G.P. Affiliation Unknown 80/08/06 ip
- 8009020293 Responds to 800212 telegram to President Carter requesting action to prevent major disaster at nuclear station Studies have resulted in addi licensee requirements SNYDER.B J TMI Program Office 80/08/14 3pp
- SO09020299 Responds to 800329 ltr expressing concerns re nuclear energy & opposing venting of radioactive gases & release of contaminated water Forwards summary of NUREO-0539; re population dose & health impact; & other mgtl W/o encl SHYDER, B J TMI Program Office 80/08/14 4pp

- ---B009020304 Expresses concerns re nuclear energy Opposes venting of radioactive gases & release of contaminated water ROGERS, L. Affiliation Unknown 80/03/29 3pp
- 8009090350 Urges that period for comment of EIS be extended for period not less than 90 days
  WALTERS,P.W., WALTERS,H.D. Affiliation Unknown 80/08/14 Lp
- 800910006B Responds to 790B16 ltr to President Carter re rejease of radioactive math from facility Only low or nondetectible levels currently permitted to be released Disposal of water processed by EPICOR-II to be discussed in programmatic EIB SNYDER.B J TMI Program Office 80/08/14 3pp
- ---8009100074 Forwards C Whitney 790816 1tr & newspaper article for proper handling RATHKOPF.C L. Energy, Dept. of 79/09/21 4pp
- B0090204BB Responds to encl L detiys B0032L telegram to President Carter re health effects of radiation from TMI Team of investigators has concluded that health effects from TMI accident represents minimal risk to offsite population BNYDER.B J TMI Program Office B0/00/t5 2pp
- 8009050366 Responds to 800225 ltm to First Lady me continuing operation of facilities Public hearing to be held to determine if facilities should be operated & conditions of restant M/o Commission 770809 order SNYDER. N J TMI Program Office 80/08/15 2pp
- 8009220049 Responds to enci 800505 ltm to President Camber unging revocation of facility OLs Public hearing will be held refuture operation of Unit 1 Licenses has not yet submitted proposal for overall recovery of Unit 2 SNYDER. U J TMI Program Office 80/00/15 App
- 8009030432 Forwards JW Zoller 800818 ltr unging that NRC return facility to operation as soon as possible after reasonable safety ansps GGDDLING, B Pennsylvania, State of 80/08/18 lp
- 8009090022 Responds to 800815 ltr urging expeditious reopening of facility Commission has directed that facility be kept in shutdown condition pending further order Evidentiary phase of public hearing re facility has not yet started INGRAM.F. Office of Public Affairs 80/08/20 ip
- --B007090024 Urges expeditious restarting of facility Cost of Suying electricity by util is being passed on to ratepayers ITSCHNER.L C Affiliation Unknown G0/09/15 ip
- 8009150324 Responds to 790701 ltr to NRC so TMI accident Commission has ordered public hearing to determine whether TMI-1 should be operated Communication difficulties attributed to impairment of info from control room to offsite groups SNYDER.B J TMI Program Office 80/08/22 4pp
- --8009190327 Expresses concern re TMI accident Util deliberately deceived public in crucial days following accident & should not be allowed to reopen TMI-1 WCODLEY:8 € Affiliation Unknown 79/07/01 4pp
- 8009150330 Responds to 800326 ltr re reopening of THI licenses has not submitted proposal for overall recovery of Unit 2 NHC 790702 order directed Unit 1 to remain in cold shutdown, pending outcome of restart hearing SNYDER, B J THI Program Office 80/08/22 2pp
- --8009150336 Requests cleanup & respening of THI RABUCK/B Affiliation Unknown 80/03/26 App
- GDO9150343 Responds to litr to NRC re reopening of TM1 facilities Public hearing will be held re TM1-1 restart licenses has not submitted proposal for everall recovery of TM1-2 SNYDER.B J TM1 Program Office BO/OB/22 2pp
- --B609150346 Expresses desire for TMI restart. Util followed all notification procedures on 790328 NRC & util should be supported in cleanup operation
  SMITH.J W. Affiliation Unknown 80/08/22 2pp
- 8007iA0101 Responds to encl 79103| ltr to President Carter relactions taken at TMI Licensees of all operating plants utilizing PMRs have been instructed to take actions relstatus of equipment procedures & facility designs
  SNYDER.B J TMI Program Office 80/08/22 4pp

- 8009170297 Responds to 800214 itr urging revocation of util OL NRC has ordered public hearing re TMI-1 restant Util has not submitted proposal for overall recovery of Unit 2 SNYOER. 2 J TMI Program Office 80708/22 1p
- 8009;7027i Responds to encl 8004ii ltr to President Carter re safety of TMI vicinity NRC.EPA & NEW investigations have shown affsite dose associated wiradioactive matl released from 790928-0429 represents minimal risk SNYDER.B J TMI Program Office 80/08/22 3pp
- 8009230194 Responds to ltr urging revocation of util OL NRC has ordered public hearing to determine Unit 1 operation feasability & possible restart conditions Licensee has not submitted proposal for overall recovery of Unit 2 SMYDER, B J THI Program Office 80/08/22 ip
- --8009230202 Urges revocation of util GL BRISCOE, G A Affiliation Unknown 80/08/22 ip
- 8009150321 Responds to postcard re-safe decommissioning of nuclear reactors & studies of reactor health effects Specific NRC actions include employment of full-time inspectors at TMI, licensee instruction & emergency preparedness planning SNYDER.B U TMI Program Diffice 80/08/25 2pp
- --8009150325 Requests safe decommissioning of all commercial nuclear reactors 5 performance of health impact studies to determine effects of nuclear energy KELLY, K. Affiliation Unknown 80/08/25 2pp
- 8009170004 Responds to 790810 itr re accident at TMI NRC has ordered public hearing to determine whether TMI-1 should be operated & under what conditions restart would take place Licensee has not yet submitted proposal for overall recovery SNYDER B J TMI Program Office 80/08/26 3pp
- ~-8009170011 Urges NRC to restore feeling of normalcy to community around TMI Recommends that NRC wait until all investigations are completed before reopening TMI-1 Any premature opening would suggest that economics come before public safety H-IVLY.B J Affiliation Unknown 79/08/10 Opp
- 8009260200 Responds to 8003ii 1tr to President Carter re delay in placing TMI-i back into svc & rate structure prescribed for util Public hearing on restart scheduled to begin in Fall 1980 to determine whether faccility should be operated REID.R U Operating Reactors Branch 4 80/09/09 4pp
- 8009290386 Responds to 800805 ltr re delay in placing TMI-1 back anto svc Commission orders of 800702 directed unit remain shutdown & restart hearing conducted on 801015 DENION, H R Office of Nuclear Reactor Regulation, Director 80/09/10 Ip
- --8009290389 Requests TMI-1 be allowed to return to svc TREAT, E H Affil(at(on Unknown 80/08/05 ip
- 8009300159 Responds to 1tr re excessive electric bill NRC does not set rates that utils charge for electricity Accident at Unit 2 also caused Unit 1 to be shut down Excerpt from BOE rept encl
  DENION-H R Office of Nuclear Reactor Regulation, Director 80/09/15 6pp
- --8009300163 Expresses concern to high util bills Paople on fixed incomes cannot afford cost of energy FASIG.F Affiliation Unknown 80/09/15 ip
- BOO9230441 Responds to ltr re J Zoller request for prompt return of facility operation Public hearing ordered to determine facility operability Based on proceeding status development of resord for restart decision not expected before 1981 KAMMERER.C Office of Congressional Affairs 80/09/18 2pp
- -8009230442 Requests response to encl J Zoller Itr requesting prompt return of facility operation CDDDLING.B House of Rep. 80/09/18 2pp
- Financial information
- 1009030301 Ack receipt of 790921 & 1205 financial info & forwards request for addl info to account for subsequent developments re financial plan & cost estimates

  NOVAK, T.M. Assistant Director for Operating Reactors

  80/08/11

- 8009020428 Forwards State of NJ Rate Counsel latest data request to keep NRC informed of significant regulatory developments affecting General Public Utils companies Kirsten, Friedman & Cherin 800818 forwarding ltr also encl SMEENEY, L E Jersey Central Power & Light Co 80/08/20 7pp
- 8009090&D2 Summary of 800814 meeting w/Met Ed & Ceneral Public Utils (OPU) at NRC re OPU financing plan over next 10 yrs Basis for plan: "Financial Forecast Reflecting Revised Estimate of TMI-2 Clean-up & Recovery" encl SILVER.H Operating Reactors Branch 4 80/08/26 5pp
- --8009090608 "Financial Forecast Reflecting Ravised Estimate of TMI-2 Clean-up & Recovery " Util 800808 press release encl \* General Public Utilities - GPU Service Corp 80/08/14 41pp
- 8007110374 Forwards responses to NRC 790721 & 1107 requests for infore significant regulatory developments affecting Deneral Public Utils companies in restart proceeding Federal executive agencies & rate counsel data requests encl SWEENEY, LE Jørsey Central Power & Light Co 80/07/05 25pp.
- 8009290357 Forwards util 800908 ltr to 8 Marshall re matter of petition for increase in levellised energy cost adjustment charge, per NRC 790921 request for ongoing info re significant regulatory developments
  SWEENEY, L. E. Jersey Central Power & Light Co. 80/09/10 11pp
- 8009;80370 Forwards Citibank,N A 800905 ltr notifying General Public Utils Corp of reduction in util credit availability.per 800910 telcon request CARRULL,D General Public Utilities OPU Service Corp 80/09/11
- BOO9260175 Forwards info containing significant regulatory developments affecting General Public Util companies re restart proceeding Info consists of responses to Rate Counsel.FEA & DOD requests
  BMEENEY.L E Jersey Central Power & Light Co 80/09/16 Sipp
- 8009230434 Forwards Exhibits JC-600 & JC-601 filed in restart proceeding Includes & Reis testimony & "Certain Data Used in Determination of Fair Rate of Return," prepared by Reis & Chandler, Inc.
  SMEENEY, L.E. Jersey Central Power & Light Co. 80/09/18 44p
- P Operating license stage documents & correspondence
- 8009150070 Responds to 800923 recommendations concerning lessons learned from 800226 transient at Crustal River Submits results of investigations re use of atmospheric dump valve at Oconea Units 1-3, AR Unit 1, Davis-Besse Unit 1 & TMI-1 DENION; R Diffice of Nuclear Reactor Regulation, Director 80/07/21 2pp
- 8009020297 Bubmits interim criteria for shift staffing to all CL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D G Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREQ-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days. Proposed implementation schedule for meeting criteria of NUREQ-0696 enci W/o NUREQ EISENHUT, D @ Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI+2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of Amend EISENHUT, D.O. Division of Licensing 80/08/07 60pp
- 8007030472 Forwards Revision 1 to 800521 "Process Control Program " Changes are based on discussions w/NRC HERBEIN.J 0 Metropolitan Edison Co 80/08/21 1p
- ~-8009030478 Revision 1 to "Process Control Program" re incontainer solidification.

  \* Hittman Nuclear \* Development Corp (subs Hittman Corp ) 80/08/21 130p
- 8009050275 Forwards Tech Spec Pages 4-41 & 4-42 re ECCS, inadvertently omitted from 800728 Amend 56 to License DPR-50 REID.R II Operating Reactors Branch 4 80/08/22 4pp
- --8009050281 Tech Spec Pages 4-41 & 4-42 re ECCS, inadvertently omitted from 800728 Amend 56 to License DPR-50

  \* Operating Reactors Branch 4 80/08/22 2pp

- )8 Forwards commitment dates, as requested during 800725 ejit meeting re near-term OL mgt review insp HERBEIN, J O Metropolitan Edison Co 80/08/25 2pp
- B00990421 Requests 45-day extension to comment period for programmatic EIS re TMI cleanup process Public hearing should be conducted prior to drafting of final version SHOLLY.S G Three Mile Island Public Interest Resource Center B0/08/27 2pp
- 8009030481 Forwards changed pages to 800807 Tech Spec Change Request 93 for License DPR-50 HERBEIN,J G Metropolitan Edison Co 80/08/28 ip
- --80090304B7 Changed pages to 800807 Tech Spec Change Request 93 re mgt reorganization 4 Metropolitan Edison Co 80/08/28 6pp
- BOOTOBO367 Informs NRC that Tech Spec Change Request 93 does not alter responsibility that util has for operation of unit MERBEIN, J 0 Metropolitan Edison Co 80/09/02 ip
- 8009120645 Forwards Amend 57 to License DPR-50, safety evaluation & notice of issuance & availability
  REID.R H Operating Reactors Branch 4 80/09/02 4pp
- ~-8009120548 Amend 57 to License DPR-50, revising Tech Specs to include surveillance requirements for high & low pressure safety injection systems. REID: R W Uperating Reactors Branch 4 80/07/02 5pp
- ~-8009120450 Safety evaluation supporting Amend 57 to License DPR-50 • Office of Nuclear Reactor Regulation, Director 80/09/02 3pp
- ~-8009120453 Notice of issuance & availability of Amend 57 to License DPR-50 REID.R W Operating Reactors Branch 4 80/09/02 2pp
- 8009170037 Requests Class III fee for review of 800807 application for amend to License DPR-80 Organizational changes were considered to be of safety significance MILLER: W O License Fee Management Branch 80/09/02 1p
- BO07270242 Requests response schedule to coordinate review of open items identified in SER since issuance of NUREG-0680 REID.R W Operating Reactors Branch 4 80/07/04 4pp
- 8009260359 Informs util that response to NRC 791109 ltr re portions of ECCB evaluation models dealing w/fuel cladding swelling & incidence of rupture is acceptable Util has adequately confirmed representations made by fuel supplier.

  REID.R W Operating Reactors Branch 4 80/09/09 4pp
- BO07160329 Forwards response to B00701 ltr re TML-1 fuel assembly holddown springs No feiled or damaged holddown springs identified B&W investigations revealed no significant safety concerns
  HUKILL-H D Metropolitan Edison Co B0/09/10 10pp
- BOO9170292 Forwards response to NRC 790921 & 1109 requests for info re significant regulatory developments affecting General Public Utils companies in restart proceeding SHEENEY,L E Jersey Central Power & Light Co 80/09/10 3pp
- --B007170273 Ltr to all operating nuclear power plants re followup actions resulting from NRC review of implementation of TMI-2 Lessons Learned Task Force short-term requirements Implementation schedule & exhibits encl EISENHUT.D O Division of Operating Reactors 80/09/13 79pp
- 8909160367 Informs that Phase 2 rept by B&W reviewed & found applicable to TMI-1 Rept demonstrates ability of TMI-1 to withstand effects of asymmetric LOCA loads
  HUXILL, H D Metropolitan Edison Co 80/09/11 2pp
- BOO9290155 Forwards human factors engineering control room design review Requests meeting during wk of 801006 to discuss, comment & suggest corrective actions REID,R W Operating Reactors Branch 4 80/09/16 12pp
- Q Inspection reports. IE Bulletins & correspondence
- 8009100875 Forwards IE Insp Rept 50-289/80-13 on 800509-0619 No mentempliance noted CARLSON,R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/21 2pp

- --8009100899 IE Insp Rept 50-289/80-13 on 800509-0619 No noncomple noted Major areas inspected licensee response to IE Bulletin 79-02, high pressure injected crossconnect mod & identification of safety-related sys & components CHAUDHARY, S., HOBREARTY, R. Region 1, Philadelphia, Office of Director ESPICTERS & Region 1, Philadelphia, Reactor Constr & Engineering Support Branch 80/07/11 Bpp
- 8009090237 Ack receipt of 800716 ltr informing NRC of steps taken correct violations noted in IE Insp Rept 50-289780-05 BRUNNER,E J. Region 1. Philadelphia. Reactor Operations Nuclea Support Branch 80/07/31 ip
- --8007070244 Forwards IE 1msp Rept 50-289/80-05 on 800227-29 No noncompliance noted BRUINER, E. J. Region 1. Philadelphia. Reactor Operations Nucl Support Branch 80/06/12 2pp
- --9009090250 IE Insp Rept 50-289/80-05 on 800227-29 No noncomplia noted Deviation noted failure to incorporate recommended restart requirements into established engineering dept procedures GREENMAN.E Region 1, Philadelphia, Reactor Operations Nucle Support Dranch NAPUDA.Q, PAOLIND.R Region 1, Philadelphia Office of the Director 80/06/04 7pp
- 8009030044 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wested Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Uritten response required ORIER, B M Region i, Philadelphia, Office of the Director 80/08/15 ip
- BOD9180013 Forwards IE Circular BO-18, "10CFR50 59 Safety Evaluat for Changes to Radwaste Treatment Bys " No written response required GRIER B H Region 1, Philadelphia, Office of the Director BO/08/22 1p
- 8009020013 Modifies 800814 response to IE Bulletin 80-16 re polen misapplication of certian Rosemount Models 1151 & 1152 pressure transmitters Four 1152 OP transmitters used w/A output code MERBEIN: J G Metropolitan Edison Co 80/08/25 3pp
- 8009120184 Forwards IE Info Notice BO-31, "Maloperation of Gould-Bovers 480 Volt Type K-5008 & K-DDN 5008 Circuit Breakers"
  No written response required
  GRIERS BH Region I. Philadelphia, Office of the Director
  80/08/27 ip
- 9009230790 Forwards IE Circular 80-21, "Regulation of Refueling C No written response required CRIER.B H Region 1, Philadelphia, Office of the Director 80/07/10 1p
- B009240316 Forwards IE Info Notice 80-32, "Clarification of Certa Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director B0/09/12 b
- R Periodic operating reports & related correspondence
- 8009090796 Forwards status rept for wk of 800810-16 CDLLINS.J T TMI Program Office 80/08/18 App
- 8007110316 Forwards supplemental info to "Effluent & Waste Dispos Semiannual Rept. Jan-June 1980," for IMI-1 & 2 & EPICOR-11 & supplemental info to "Effluent & Waste Semiannual Rept. 791015-1231," for EPICOR-11 HERBEIN, J O Metropolitan Edison Co 80/09/05 1p
- --8007i10318 Supplemental info to "Effluent & Waste Disposal Bemi Rept.Jan-June 1980" \* Metropolitan Edison Co 80/09/09 8pp
- ---8009110333 Supplemental info to "Effluent & Waste Disposal Semi Rept.Jan-June 1980" \* Metropolitan Edison Co 80/09/09 24pp
- --8007i10340 Supplemental info to "Effluent & Waste Disposal Semi Rept, Jan-June 1980," for EPICOR-II \* Matropolitan Edison Co 80/09/05 Spp
- --8007i10344 Supplemental info to "Effluent % Waste Disposal Hemi Rept, for 77i018-1231" re EPICOR-11 \* Metropolitan Edison Co 80/07/05 Bpp

- g009186264 TMI Program Ofc weekly status rept for wit of 800830-0906 COLLINS.J T TMI Program Office 80/09/08 App
- 8009220288 Forwards monthly operating rept for Aug 1980 MUKILL.H D Metropolitan Edison Co 80/09/15 tp
- --8009220291 Monthly operating rept for Aug 1980 MITCHELL, D. G. Metropolitan Edison Co. 80/09 B0/09/15 500
- 8009300550 Forwards tritsum results from TMI groundwater & soil samples obtained on 800530.0707.18 & 25 Results of analyses performed on soil samples from GW-138.0W-14 & GW-17 RIETHLE, W E General Public Utilities - GPU Service Corp 80/09/16
- 8009300399 Forwards "Executive Summary.TM1 Units 1 & 2 Liquid & Gaseous Releases for Jul 1980." addl data for liquid discharges to Susquehanna River for 1980 & explanation of TM1 effluent & dose assessment group monthly summary PORTER S W Porter-Gertz Consultants, Inc. 80/09/19 2pp
- --8009300401 "Esecutive Summary, TMI Units 1 & 2 Liquid & Gasebus Releases for Jul 1980 " Tables providing addit data for liquid discharge to Susquehanna River encl 4 Porter-Gerti Consultants, Inc. 80/09/19 13pp
- S Reportable occurrences. LERs 5 related correspondence
- 6009020305 Ack receipt of util ltrs reactions to correct intergranular stress corrosion pipe cracks & forwards safety evaluation Corrective actions are acceptable Util committed to submit Operating Reactors Branch 4 80/08/11 4pp
- -- 8009020308 Safety evaluation supporting actions taken on pipe cracks in borated water sys Derating Reactors Branch 4 60/08/11 4pp
- 8009120341 Forwards LER 80-015/047-1 HERBEIN, J G Metropolitan Edison Co 80/09/09 1p
- --8009120342 LER 80-015/04T-1 on 800721, w/unit in cold shutdown, actual river water temp change exceeded limit for approx 6-h Caused by calculation error in instrument loop used to measure river water outlet temp MITCHELL.D O Metropolitan Edison Co 80/09/09 2pp
- 8009300506 RO 80-17 determined insufficient documentation to demonstrate that brakes on motor operators for purge valve: AH-VI8 & AH-VIC environmentally qualified Redundant valves fully qualified TODLE, R J Metropolitan Edison Co 80/09/23 ip Metropolitan Edison Co 80/09/23 1p
- T Hearing transcripts on non-antitrust matters
- 8009020087 Forwards transcript of 800820 hearing, in response to NRC 790921 & 1109 requests for info re significant regulatory developments affecting General Public Util companies in SHEENEY, LE Jersey Central Power & Light Co 80/08/26 1p
- ~~8009020089 Transcript of 800820 hearing before NJ Dept of Energy, Board of Public Utils in Newark, NJ Pp 1-176
  \* New Jersey, State of 80/08/20 176pp
- 8009030431 Forwards transcript of NJ Board of Public Utils 800821-22 hearings in Newark.NJ re util potition for rate increases, per NRC 770921 request to be kept informed of significant regulatory developments
  SHEENEY.L E Jersey Central Power & Light Co 80/08/27 125pp
- 8009030392 Forwards transcripts for 800725 & 26 hearings per NRC 790921 & 1109 requests to be tept informed of significant SHEENEY. L. E. Jersey Central Power & Light Co. 80/08/29 60pp
- 8009030582 Forwards transcript of 800825-26 hearings before NJ Board of Public Utils in Newart.NJ re increase in rates for electric svc & for amend to levelized energy adjustment clause SKEENEY.L E Jersey Central Power & Light Co 80/08/29, 300pp
- 8009150252 Forwards transcript of NJ Board of Public Utils 800827 hearing re util request for rate increase; in response to NRC request for info on any significant regulatory developments Pp 678-729 SWEENEY, L. E. Jersey Central Power & Light Co. 80/09/02 47pp

- 8009110405 Forwards transcript of NJ Board of Public Utils 800903 hearing in response to NRC 790921 & 1109 requests for infore significant regulatory developments affecting General Public Utils companies Jersey Central Power & Light Co 80/09/05 94pp SWEENEY, L E
- 8009;70346 Forwards RG Fit:patrick testimony re UCS Contention 4.PC Hearn testimony re Sholly Contention 1.DF Thatcher testimony re Sholly Contention 6(a) & PO Stoddart testimony re Sholly Contention 5(ANORY Contention VID) & Lewis contention CUTCHIN.J M Hearing Branch 3 80/09/15 2pp
- --8009170349 Testimony in response to UCS Contention 4 demonstrating connection of pressurizer heaters to onsite emergency power supplies does not violate General Design Criteria 17 & will not degrade emergency power supply performance FITZPATRICK:R Power Systems Branch 80/09/15 7pp
- --8009;70391 Testimony in response to Sholly Contention i demonstrating containment isolation signals need not include safety-grade high radiation signal to assure automatic b timely isolation of reactor bldg vent b gurge or sump lines HEARN-P C Division of Safety Technology 80/09/15 opp
- --8009170354 Testimony in response to Sholly Contention 6(a) demonstrating that failure mode & effects analysis of instrumentation & control sys has been performed THATCHER.D F Instrumentation & Control Systems Branch 80/09/15 10pp
- --8007170358 Testimony in response to Sholly Contention 5, ANGRY Contention V(D). Lewis contention & Chesapeake Energy Alliance Contentions 5, 6 & 7 Certificate of Svc enci.
  STODDART.P 0 Assistant Director for Environmental Technology 68pp
- 800923G011 Direct testimony re Contention 4 Explains proper application of single failure criterion Connection of heaters in proposed manner violates General Design Criterion 1F Certificate of Svc enci POLLARD R D Union of Concerned Scientists 80/09/15, 18pp
- 8009260313 Submittel of prepared testimony for first hearing session No attempts made to provide complete answers to ABLE 800908 memorandum & order re physical separation of THE units Cartificate of Evc encl Related correspondence TROWBRIDGE, G F Ketropolitan Edison Co TROWBRIDGE, G F Shaw, Pittman. Potts & Trowbridge 80/09/15 7pp
- 8009240313 Bubmittal of prepared testimony for first hearing session No attempts made to provide complete answers to ABLB 800908 menorandum & order re physical separation of TMI units Certificate of Sec enci Relaked correspondence TROMBRIDGE, Q F Metropolitan Edison Co 80/09/15 7pp
- ---B009260320 Testimony in response to UCS Contentions 1 & 2 re natural & forced circulation Explains feasibility of adequate core cooling Prof qualifications encl Related correspondence KEATEN,R W. JONES,R C. Metropolitan Edison Co. 80/09/15 23pp
- --8009260322 Testimony in response to UCS Contention S & Environ Coalition on Nuclear Power Contention 1(e) re add L LOCA analysis Describes purpose, assumptions & results of analyses Prof qualifications encl Related correspondence JONES, R C , BROUGHTON, T C Metropolitan Edison Co 80/09/15 80/09/15
- --8009260329 Revision 3 to "ECCS Analysis of B&W 177-Fuel Assembly-Loop S " Related correspondence Babcock & Wilcox Co BAW-10103A R3 77/07/31 317pp.
- --8009260335 "Evaluation of Transient Behavior & Small RCB Breaks in 177 Fuel Assembly Plant," Vol 1. Section 6 0. Suppl 2 to 790507 rept Related correspondence \* Babcock & Milcox Co 79/05/12 22pp
- --8009260340 "Sys Response to Total Loss of Steam Cenerator Heat Sint " Related correspondence

  Babcock & Wilco, Co. 86-1103585-00 79/08/07 7pp
- --8009250352 "Analysis Summary in Support of Early Reactor Coolant Pump Trip " Related correspondence \* Babcock & Wilcox Co 79/08/21 53pp

- ---9009260359 "Supplemental Small Break Analysis." suppl to 790821
  "Analysis in Support of Carly Reactor Coolant Pump Trip "
  Related correspondence
  + Babrock & Wilcox Co 79/09/12 25pp
- --8009260366 "Small Break Operating Guidelines " Related correspondence # Babcock & Wilcox Co 69-1106001-00 79/11/30 48pp
- --8009260380 "Small Break W/Failed Power Operated Relief Valve " Related correspondence
  - correspondence # Babcock & Wilcox Co 86-1117679-000 80/02/11 14pp
- ----8009260388 Testimony in response to UCS Contention 7. Antinuclear Group Representing York Contention V(B) & SC Shally Contention 6(B) re detection of inadequate core cooling Prof qualifications encl Related correspondence KEATEN,R W. ROSS,M J., JONES,R C. Metropolitan Edison Co. 80/09/15 31pp
- --E009260394 Testimony in response to UCS Contention 10 & 8C Sholly Contention 3 re safety sys bypass & override Shows that operator intervention in safety function does not violate criteria Prof qualifications encl Related correspondence CLARK.PR.ROSS.MJ.PATTERSON.ES Metropolitan Edison Co 80/09/15 21pp
- --8007260376 Testimony in response to UCS Contentions 3:12 % 14 re safety classification Instrument failures re TMI-2 accident posed no threat to safety Prof qualifications encl Related correspondence KEATEN, R W. BRAULKE, O R. , BRAZILL, O J. Metropolitan Edison Co. 80/09/19 30pp
- --B009260400 Testimony in response to UCS Contentions 5 & 6 re valves & valve testing Power operated relief valve was not designed to fulfill safety function Prof qualifications encl Related correspondence CORREA, J H , UROUHART, G T , JONES, R C Metropolitan Edison Co B0/09/15 20pp
- --B009260402 "Overpressure Protection for B&W PWR " Related correspondence, 
  + Babcock & Wilcox Co BAW-10043 72/05/31 17pp
- --8009260411 Testimony in response to SC Sholly Contention 6(a) re integrated control sys Addresses complimentary evaluations of field data 5 results of sys analysis Prof qualifications encl Related correspondence BROUOHTON T 6 , BADAUSKAS, O J , JOYNER, L L Matropolitan Edison Co 80/09/15 12pp
- --8009260412 Testimony in response to BC Bholly Contention i recontainment isolation Discusses relevant TMI-2 experience & licensee actions to add initiation signals due to reactor trip Prof qualifications encl Related correspondence LANESE.L.C Metropolitan Edison Co 80/09/15 9pp
- --B009260414 Testimony in response to Lewis contention & Antinuclear Oroup Representing York Contention V(D) re filters Shows reduction of radioactive gases & minimization of leakage Prof qualifications encl Related correspondence.
  ITSCHNER.W F., BARLEY,R., MOORE.J. Metropolitan Edison Co 80/09/15 24pp
- --8009260417 Testimony 'in response to Sholly Contention 15 & Antinuclear Group Representing York Contention V(C) re control room design-human factors engineering Improvements can be made Prof qualifications encl Related correspondence UALSH.P 3. MEEK.W E., ESTRADA.H Metropolitan Edison Co 80/09/15 49pp
- --9009260421 Testimony in response to Sholly Contention i3 & Environ Coalition on Nuclear Power Contention 1(a) re adequacy of plant computer sys Computer performs no safety or control functions Prof qualifications encl Related correspondence HAMILTON,W P , KEATEN,R W Metropolitan Edison Co 90/09/15.

- --8009260439 Testimony in response to Shally Contention 5 & Environ Coalition on Nuclear Power Contention 1(d) re instrument ranges Lays out comparison showing adequacy of instrument ranges Prof qualifications encl Related correspondence BROUGHTON-T G . DUBIEL.R W , WILLIEMS,V H Metropolitan Edison Co 80/09/15 20pp
- --8009260443 Testimony in response to ASLB Question 8 & Chesapeake Energy Alliance Contention 5 re physical separation of Units 1 & 2 Addresses waste handling, restoration & decontamination Wyprof qualifications Related correspondence FUHRER.E C , MCGDEY.R J Metropolitan Edison Co 80/09/15 40pp
- 8009230445 Forwards transcript of 800829 hearing before NJ Dept of Energy, Board of Public Utils.Pp 724-860, in response to NRC 791109 request to be kept informed of significant regulatory developments affecting General Public Utils companies SWEENEY,L E Jersey Central Power & Light Co 80/09/16 137pp
- 8007300417 Forwards UCS direct testimony on Contentions 3 & 10 re restart hearing Also forwards UCS interrogatories to NRC based on new info Testimony on Contention 5 will be provided pending recopit of NRC testimony WEISS, E R Sheldon, Harmon & Weiss 80/09/25 ip
- --8009300420 Direct testimony of RD Pollard on behalf of UCS re UCS Contention 3 POLLARD, R D Union of Concerned Scientists 80/09/25 18pp
- --8009300422 Direct testimony of RD Pollard on behalf of UCS re UCS Contention 10 POLLARD.R D Union of Concerned Scientists 80/09/25 25pp
- U Congressional/Executive Correspondence
- 8007080346 Protests NRC decision not to permit psychological stress issue at restart hearings Failure to address issue would raise question re-credibility of including issue in Unit 2 cloanup hearing ERTEL, A E House of Rep. 80/09/03 2pp
- V Operator Examinations
- 8009030464 Forwards Administrative Procedure 1006, operator requalification program 8 status of requalification program for Unit II operators Replacement operator training program will be submitted upon completion HERBEIN.J Q Metropolitan Edison Co 80/08/08 2pp
- ---B007030469 "Administrative Procedure 1006.Revision 3," operator requalification program Status of requalification program for Unit II operators encl

  \* Metropolitan Edison Co 80/07/31 42pp
- 8009080240 Forwards operator requalification program per 800328 ltr HERBEIN.J G Metropolitan Edison Co 80/08/08 2pp
- DOCKET 50-293 PILORIM NUCLEAR POWER STATION, UNIT 1 E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8009020032 Forwards input to Item 3 1 19 of facility SER Licensee should demonstrate that all pips penetrations have fire resistance rating of 3-h All tests in 800529 submittal were for electrical penetrations HALL: R E Brookhaven National Laboratory 80/08/19 2pp
- F Security, medical, emergency & fire protection plans
- 8007090569 Forwards recommendation for Item 3 1 6/3 2 4 re cable combustibility for fire protection review Recommends that licensee be required to coat okonite & kerite cables HALL.RE Brookhaven National Laboratory 80/07/14 3pp
- 8009150437 Forwards comments on security force training & qualification plan Requests response within 45 days Comments withheld (ref. 10CFR2 790)
  1PPOLITO.T A Operating Reactors Branch 2 80/08/21 3pp
- 8009230162 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency GRIER, B H Region 1. Philadelphia, Office of the Director 80/08/22 Spp

- 8009170329 Forwards supplemental info re fire protection program, per NRC 800619 request MARIS\$, A V Boston Edison Ca 80/09/11 Bpp
- G Adjudicatory correspondence
- 8009300584 Forwards 800912 order revising 800829 order for mod of OL, in entirety
  EISENHUT, D Ø Division of Licensing 80/09/12 2pp
- --8009360588 Order revising 800829 order for mod of DL DPR-35, in entirety Info responsive to IE Bulletin 79-018 shall be submitted by 801101 Request for hearing will not stay order effective 800912 UCS 771104 & 780502 petitions discharged EISENHUT, D G Division of Licensine 80/09/12 &pp
- P Operating license stage documents & correspondence
- 8009110554 Suppls NRC 800707 request for proposed Tech Specs changes re scram discharge vol vent & drain valves. & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT.D G Division of Licensing 80/07/22 22pp
- 8009020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D G Division of Licensing 80/07/31 7pp
- 8007080080 Forwards draft NUREG-0676, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl M/o NUREG EISENHUT, D @ Davision of Licensing 80/08/01 119pp
- 8007120101 States understanding relactions to be taken per 800805 telcon on testing of D safety relief valve NRC must be informed unthin 24-h if specified actions are not in accordance w/actual plans GRIER, B H Region 1. Philadelphia, Office of the Director 80708/06 1p
- E009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested sybmittal should include proposed class of amend EISENHUT.D 0 Division of Licensing E0/08/07 60pp
- 8007050450 Informs that NRC evaluation confirmed two specific Event 5 valve configurations discussed in NRC 800223 ltr, do not exist at facility NRC activities re valve configurations finalized for facility Technical evaluation rept encl IFFOLITO.T A Operating Reactors Branch 2 80/08/08 3pp
- --8007030456 "Primary Coolant Sys Pressure Isolation Valves,Pilgrim Unit 1," technical evaluation rept NGELL,P N , STH.WELL,T C Franklin Institute/Franklin Research Center NRC-03-77-118 80/07/21 dpp
- B007040114 Forwards request for addl info re request for exemptions from 10CFRSO App J.containment leakage testing NOVAK.T M Assistant Director for Operating Reactors 80/08/12
- 8009150500 Forwards NUREG-0561, "Mark I Containment Long-Term Program Safety Evaluation Rept.Resolution of Generic Technical Activity A-7" Rept describes NRC review results & requirements N/o encl 1990LITD.T A Operating Reactors Branch 2 80/08/20 2pp
- BOO9150270 Application to amend License DPR-35 changing App A Tech Specs definition of "high radiation area" Proposed change allows flexibility in complying W/requirements Fee encl HOWARD. J E Boston Edison Go 80/09/01 Zep
- --8009180279 Proposed Tuch Spec & 13, changing definition of "high radiation area" \* Buston Edison Co 80/09/01 2pp.
- 8009150284 Application for Proposed Change 80-3 to License DPR-35, re definition of "operable" as applied to single failure criterion for safety sys Request is in response to IE Info Notice 79-35 t NRC 800410 ltr. Fee encl HOHARD, J E Boston Edison Co 80/09/01. 2pp

- --8009150285 Proposed Change 80-3 to App A Tech Bpecs, Section I re definition of "operable" as it applies to single failure criterion for safety sys \* Boston Edison Co 80/09/01 ip
- 8009180531 Requests submittal of program re baseline photographic survey of breakwater for comparison w/future conditions. Also requests proposed Toch Spec change re reporting requirements for approval Response requested within 90 days IPPOLITO.T A Operating Reactors Branch 2 80/09/03 3pp
- 8009160346 Forwards fee for 800403 application for Tech Spec changes per NRC 800702 request MRRISIA V Boston Edison Co 80/09/04 2pp
- 8009220193 Advises of meed for add1 response to NRC 790808 itr requesting analytical ½ test info re adequacy of station sys Response of 790808 was inadequate Response to encl should be provided within 45 days of itr receipt IPPOLITO, T A Operating Reactors Branch 2 80/09/04 App
- 6009180541 Advises that 800104 reaponse to NRC 791109 ltr re ECCS evaluation models dealing w/cladding swelling & incidence of rupture is acceptable No further action necessary IPPDLITO.T A Operating Reactors Branch 2 80/09/05 2pp
- 8009170166 Forwards final rept re operating experience of plant augmented offgas treatment sys Data was compiled during EG&G DL Inc 781010-13 site visit W/o encl.
  IPPOLITO,T A Operating Reactors Branch 2 80/09/09 2pp
- 8009240641 Confirms util commitment to NRC 791023 "Interim Position on Containment Purging & Venting Pending Resolution of Isolation Valve Operability " Util position will remain in effect pending completion of NRC long-term review IPPOLITO,T A Operating Reactors Branch 2 80/09/09 2pp
- 8009230453 Responds to NRC 800425 ltr Provides info to assure that GE 781101 analysis re min ECCS equipment availability w/dc power supply failure conservative re plant sys availability combinations Lists min ECCS components available MORISI.A V Boston Edison CO 80/09/16 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 8009090113 Forwards IE Bulletin 80-07, Suppl 1, "BNR Jet Pump Assembly Failure " Response required GRIER. B H Region 1. Philadelphia, Office of the Director 80/05/13 ip
- 8009100037 Forwards IE Insp Rept 50-293/80-09 on 800303-21 Noncompliance noted GRIER.B H Region 1. Philadelphia, Office of the Director, 80/07/09 2pp
- --8009100038 IE Insp Rept 50-293/80-09 on 800303-21 Noncompliance noted movement of irradiated fuel w/o secondary containment integrity & failure to log plant evolutions as required by station procedures
  MARTILLT T. Region i, Philadelphia, Reactor Operations Nuclear Support Branch KEHOE, D. ROBERTS, K. Region 1, Philadelphia, Office of the Director 80/06/12 9pp
- 8009100874 Forwards IE Insp Rept 50-293/80-21 on 800504-16 & 28-30. No noncompilance noted BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/07/23 2pp
- --8009100877 IE Insp Rept 50-293/80-21 on 800504-16 & 28-30 No noncompliance moted Major areas inspected refueling restoration planning & surveillance activities, stantup testing of new & modified sys & review of plant operations ROBERTS. F . RAMMOND.W Region I, Philadelphia, Office of the Director MARTIN.T T Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/07/18 App
- 8009020110 Responds to IE Bulletin 80-17 Supp 2. "Failure of Control Rods to Insert During Scram at BWR" Alternate vent path was provided to scram discharge vol vent sys within 49-h of 800719 telcon notsfication AMDOONINI.6 C Boston Edison Co 80/07/28 ip
- 8009080546 Responds to IE Bulletin 80-16 Util has not installed nor plans to install Rosemount Model 1151 or 1152 pressure transmitters
  AMDORNINI.G C Boston Edison Co 80/07/29 1p

- 8007050484 Responds to NRC 800708 notice of violations Corrective actions licensed operators given training meetings prior to recommencement of fuel handling ALUKONIS, J Boston Edison Co 80/08/01 2pp
- 8009090041 Ack receipt of 800711 ltr informing NRC of steps taken to correct violation moted in IE insp Rept 50-293/80-16
  CARLSON R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/01 lp
- --8009090048 Responds to NRC 800612 ltr re violations noted in IE Insp Rept 50-293/60-16 Corrective actions plant fire extinguisher surveillance procedure revised ANDOGNINI.G C Boston Edison Co 80/07/11 2pp
- --B009090058 Forwards IE Insp Rept 50-293/80-16 on 800421-25 & notice of violation CARLESON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/04/12 2pp
- --8009090062 Notice of violation from insp on 800421-25 Region 1, Philadelphia, Office of the Director 80/06/11 ip
- --9009090066 IE Insp Rept 50-293/80-16 on 800421-25 Noncompliance noted failure to follow plant fire extinguisher check procedure EBNETER:8 D Region 1. Philadelphia, Reactor Construction & Engineering Support Branch KOLTAY.P S Region 1. Philadelphia, Office of the Director 80/06/11 8pp
- B009090860 Responds to IE Bulletin 80-17 Fifty control rod drivelines selected for manual scram & 50 control rod drivelines selected for automatic scram Scram times reviewed to determine fastest slowest & average times for each scram ANDCONINI.O G Boston Edison Co 80/08/01 4pp
- 8009110297 Inservice insp rept.Vol 1, from Jan-Feb 1980 refueling outage Describes exam of selected components Forwards results of remote visual exam of selected components & manual exam of selected areas of facility RIO
- --E009110299 Inservice insp rept.Vol 1. from Jan-Feb 1980 refueling outage Describes remote visual exam of selected components at facility RIQQB.N W. DUNAVONT, D.W. LAUTZENHEISER Southwest Research Institute SQ/08/07 40pp
- ---B009110304 Inservice insp rept, Vol 1, from Jan-Feb 1980 refueling outage Describes manual exam of selected areas of facility R1008.H W , DUNAVONT.D W , LAUTZENHEISER Southwest Research institute 80/08/07 100pp
- 8009120036 Responds to IE Bullstin 80~17. Suppl 1. Section A. Items 2-5 Applicable procedure contains guidance to control room personnel on initiation of standby liquid control sys Procedure re-scram discharge vol revised. Affidavit encl ANDOONINI. G C Boston Edison Co 80/08/08 4pp
- 8009160516 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches " No subjectives used or planned for use in safety-related application at facility ANDGONINI.6 C Boston Edison Co 80/08/08 ip
- BOO9160519 Responds to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E "No subj relays used or planned for use in sys ANDOGNINI. Q C Boston Edison Co 80/08/08 ip
- 8009190940 Responds to IE Bulletin 80-17 re failure of certain control rods to fully insert during BWR scram Examination revealed absence of failure mode ANDUGNINI.0 C Boston Edison Co 80/08/12 4pp
- 6009190073 Ack receipt of 800715 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-293/80-20 BRUNNER E J. Region i, Philadelphia, Reactor Operations Nuclear Support Branch 60/08/13 ip
- --8009190076 Responds to NRC 800604 ltr re violations noted in IE Insp Rept 50-293/80-20 Corrective actions Procedure 8 7 1 4 will be revised to specify clearly actions to be taken by test director re leakages & valve lineup deviations AMBOGNINI, O C Boston Edison Co 80/07/15 2pp

- ---8009190078 Forward: IE Insp Rept 50-293/80-20 on 800504-08 & notace of violation BRUNNER,E J Region 5, Philadelphia, Reactor Operations Nuclear Support Branch 80/06/04 2pp
- --B009190079 Natice of violation from insp on 800504-08 \* Region 1, Philadelphia, Office of the Director 80/05/03 ip
- ---8009190081 IE Insp Rept 90-293/80-20 on 800504-08 Noncompliance noted failure to conduct containment integrated leak rate test prior to making repair & adjustment & to perform local leak rate test after maint CAPHTON.D L. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch REKITO.W A. Region 1. Philadelphia, Office of the Director 80/06/03 10pp
- BO09090034 Responds to IE Bulletin BO-19, "Failure of 76 of 185 Centrol Rods to Fully Insert During Scram at BWR" Util has ordered scram discharge header water level monitoring sys ANDOGNINI.G C Boston Edison Co 80/08/14 ip
- BOO9D30111 Forwards Revision 1 to IE Bulletin 80~19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER. B H Region 1, Philadelphia, Office of the Director 80/08/15 ip
- B009120084 Forwards Suppl 3 to IE Bulletin B0-17, "Failure of Control Rods to Insert During Stram at BMR" Written response required GRIER-B H Region 1, Philadelphia, Office of the Director B0/08/22 1p
- B009180568 Forwards IE Circular 80-10, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Bys " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/08/22 1p
- 8009120166 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6005 & K-DDN 6005 Circuit Breakers " No written response required ORIER, B H Region I, Philadelphia, Office of the Director 80/08/27 lp
- 8009230490 Forwards Revision 1 to IE Bulletin 79-26, "Boron Loss From BNR Control Blades " Written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/08/29 (p
- B009230775 Forwards IE Circular B0-21, "Regulation of Refueling Crews " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director B0/09/10 ip
- 8009240303 Forwards IE Info Notice 80-32. "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matis " No written response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/09/12 1p
- R Periodic operating reports & related correspondence
- 8009090261 Forwards "Radioactive Effluent & Waste Disposal Rept, Including Radiological Impact on Humans, Jan-June 1980 " MORISI A V Baston Edison Co 80/09/01 1p
- --8009090267 "Radioactive Effluent & Haste Disposal Rept.including Radiological Impact on Humans, Jan-June 1980 " BDMDON, T. L., ZIEMIANSKI, E. J. Boston Edison Co. 80/09/01 74pp
- 8009160267 Forwards monthly operating rept for Aug 1980 MACHON R D Boston Edison Co 80/09/11 1p
- --B009160271 Monthly operating rept for Aug 1980 WHITNEY, C O Boston Edison Co 80/09/11 6pp
- 8009300500 Forwards revision to monthly operating rept for Aug 1980 MACHON, R D Boston Edison Co 80/09/23 ip
- --8007300505 Revision to monthly operating rept for Aug 1780 \* Boston Edison Co 80/07/23 ip

- 8007170329 Forwards supplemental info re fire protection program.ppr NRC 800619 request MARISE, A V 30ston Edison Co 80/09/11 8pp
- G Adjudicatory correspondence
- 8009300584 Forwards 800912 order revising 800829 order for mod of OL. in entirety ElsENMUT.D O Division of Licensing 80/09/12 2pp
- --8009300588 Order revising 600827 order for mod of ØL DFR-35.in entirety Info responsive to IE Bulletin 79-018 shall be submitted by 601101 Request for hearing will not stay order effective 800912 UCS 77:104 & 780502 petitions discharged EISENHUT, D O Division of Licensing 60/09/12 6pp
- P Operating license stage documents & correspondence
- 8009:10554 Suppls NRC 800707 request for proposed Tech Specs changes re scram discharge vol yent & drain valves. & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT.D G Division of Licensing 80/07/22 22pp
- 8009020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants, per NRC 800507 ltm Discusses administrative provisions for emergency & overtime work Development % Implementation to be reviewed within 90 days EISENHUT, D G Division of Licensing 80/07/31 7pp
- B007080080 Forwards draft NUREQ-0676. "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl W/o NUREG EISENHUT, D G Division of Licensing 80/08/01 119pp
- 8009120101 States understanding relactions to be taken per 800805 telcon on testing of D safety relief valve RRC must be informed outbin 24-h if specified actions are not in accordance w/actual plans GRIER.8 H Region I. Philadelphia. Office of the Director 80/08/05 1p
- 8009230052 Informs that exemption from fee re licensing action associated w/TKI-2 Lessons Learned is unjustified Previous determination should be disregerded Requested submittal should include proposed class of amend EISENHUT. D O Division of Licensing 80/08/07 60pp
- 8007030450 Informs that NRC evaluation confirmed two specific Event 5 valve configurations, discussed in NRC 800223 ltr.60 not erist at facility NRC activities re valve configurations finalized for facility Technical avaluation rept encl IPPOLITG.T A Operating Reactors Branch 2 80/08/08 3pp
- --8009050456 "Primary Coolant Sys Pressure Isolation Valves,Pilgrim Unit I." technical evaluation rept NDELLE N. STILWELL T C Franklin Institute/Franklin Research Center NRC-03-79-118 80/07/21 App
- 8007040114 Forwards request for addl info re request for exemptions from tOCFR50 App J, containment leakage testing MDVAK.T M Assistant Director for Operating Reactors 80/08/12 4pp
- 8009180500 Forwards NUREG-0661. "Mark I Containment Long-Term Program Safety Evaluation Rept.Resolution of Generic Technical Activity A-7 " Rept describes NRC review results & requirements U/o encl IPPOLITO,T A Operating Reactors Branch 2 80/08/20 2pp
- 8009150270 Application to amend License BPR-35, changing App A Tech Specs definition of "high radiation area" Proposed change allows fleribility in complying w/requirements Fee encl HOWARD.J E Boston Edison Co 80/09/01 2pp
- --8009150279 Proposed Tech Spec 6 13 changing definition of "high realistion area" \* Boston Edison Co 80/09/01 2pp.
- 8009150284 Application for Proposed Change 80-3 to License DPR-35, re derinition of "operable" as applied to single failure criterion for safety sys Request is in response to IE Info Notice 79-35 & NRC 800410 ltr fee encl HGWARD, J E Boston Edison Co 80/09/01 2pp

- --8009150285 Proposed Change 80~3 to App A Tech Specs, Section 1 redefinition of "operable" as it applies to single failure criterion for safety sys 80/09/01 ip
- B009180531 Requests submittal of program re paseline photographic survey of breakwater for comparison w/future conditions. Also requests proposed Tech Spec change re reporting requirement for approval Response requested within 90 days IPPOLITO, 7 A Operating Reactors Branch 2 80/09/03 3pp
- 8009160346 Forwards fee for 800403 application for Tech Spec changes per NRC 800702 request MDRISI.A V Buston Edison Co 80/09/04 2pp
- 8009220153 Advises of need for add1 response to NRC 790B08 itr requesting analytical & test info re adequacy of station sys Response of 790B08 was inadequate Response to encl should be provided within 45 days of ltr receipt IPPDLITO.T A Operating Reactors Branch 2 80/09/04 App
- 8009180541 Advises that 800104 reaponse to NRC 791109 ltm re ECC8 evaluation models dealing w/cladding swelling & incidence of rupture is acceptable No further action necessary IPPOLITO, T A Operating Reactors Branch 2 80/09/05 2pp
- 8009170144 Forwards final rept re operating experience of plant augmented offgas treatment sys Data was compiled during £626,0 ID.Inc 781010-13 site visit W/o encl IPPOLITO.T A Operating Reactors Branch 2 80/09/09 2pp
- 8009240641 Confirms will commitment to NRC 791023 "Interim Position on Containment Purging & Venting Pending Resolution of Isolation Valve Operability " Util position will remain in affect pending completion of NRC long-term review IPPOLITO.T A Operating Reactors Branch 2 80/09/09. 2pp
- 8007230453 Responds to NRC 800425 ltr Provides info to assure that GE 781101 analysis re min ECCS equipment availability w/dc power supply failure conservative re plant sys availability combinations Lists min ECCS components available MORISI.A V. Boston Edison Co 80/07/16 2pp
- G Inspection reports. IE Bulletins & correspondence
- 8009090113 Forwards IE Bulletin 80~07. Suppl 1, "BNR Jet Pump Assembly Failure" Response required GRIER. B H Region 1. Philadelphia, Office of the Director 80/05/13 ip
- 9009100037 Forwards IE Insp Rept 50-293/80-09 on 800303-21. Noncompliance noted GRIER: B H Region 1, Philadelphia, Office of the Director 80/07/09 2pp
- --8009100038 IE Insp Rept 50-293/80-09 on 800303-21 Noncompliance noted movement of irradiated fuel w/o secondary containment integrity & failure to log plant evolutions as required by station procedures MARTH.T T Region 1, Philadelphia, Reactor Operations Nuclear Support Branch KEHOE.D, ROBERTS.K Region 1, Philadelphia, Office of the Director 80/06/12 9pp
- 9009100874 Forwards IE Insp Rept 50-293/80-21 on 800504-16 & 28-30 No noncompliance noted BRUNNER'E J Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/07/23 2pp
- --8009100877 IE Insp Rept 50-293/80-21 on 800504-16 & 28-30 No noncompliance noted Major areas inspected refueling restoration planning & surveillance activities, startup testing of new & modified sys & review of plant operations ROBERTS, K. P. RAYMOND. W. Region 1. Philadelphia, Office of the Director MARTIN.T T Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/07/18 6pp
- BO09020110 Responds to IE Bulletin BO-17 Supp 2. "Failure of Control Rods to Insert During Scram at BUR" Alternate vent path was provided to scram discharge vol vent sys within 48-h of BO0719 telcon notification ANDUGNINI.G C Boston Edison Co BO/07/28 1p
- 8007080544 Responds to IE Bulletin 80-14 Util has not installed nor plans to install Rosemount Model 1151 or 1152 pressure transmitters ANGGONINI.0 C Boston Edison Co 80/07/29 1p

- BOO9050484 Responds to NRC 800708 notice of violations Corrective actions licensed operators given training meetings prior to recommencement of fuel handling ALDKOMIS, J. Boston Edison Co. 80/08/01 2pp
- 8009090041 Ack receipt of 800711 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-293/80-16
  CARLSON.R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/08/01 Ip
- --8009090048 Responds to NRC 800612 ltr re violations noted in IE Insp Rept 50-293/80-16 Corrective actions plant fire extinguisher surveillance procedure revised ANDOGNIMI.0 C Baston Edison Co 80/07/11 2pp
- --800707005B Forwards IE Insp Rept 50-293/80-16 on 800421-25 & notice of violation CARLSON,R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/06/12 2pp
- --8009090062 Notice of violation from insp on 800421-25
  \* Region i, Philadelphia, Office of the Director 80/06/11 ip
- --8007070066 IE Insp Rept 50-293/80-16 on 800421-25 Noncompliance noted failure to follow plant fire extinguisher check procedure EBNETER, 8 D. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch KOLTAY, P. 8. Region 1, Philadelphia, Office of the Director 80/06/11 Spp
- 8009090460 Responds to IR Bulletin 80-17 Fifty control rod drivelines selected for manual scram & 50 control rod drivelines switceted for automatic scram Scram times reviewed to determine fastests slowest & average times for each scram ANDDONINI.Q.C Boston Edison Co 80/08/01 4pp
- BCO9510297 Inservice insp rept.Vol 1.from Jan-Feb 1980 refueling outage Describes exam of selected components Forwards results of remote visual exam of selected components & manual exam of selected areas of facility RIOSS:N W . FLACK.W L . LAUTZENHEISER Southwest Research Institute, BO/08/07 250pp
- ---BD09110299 Inservice insp rept.Vol 1.from Jan-Frb 1980 refueling outage Describes remote visual exam of selected components at facility RIOSEM W. DUNAVORN, D W. LAUTZENHEIBER Bouthwest Research Institute 80/08/07 60pp
- ---B009f10304 Inservice insp rept.Vol 1.from Jan-Feb 1980 refueling outage Describes manual exam of selected areas of facility RIOGS.M W . DUNAVONT.D W . LAUTZENHEISER Southwest Research Institute. B0/08/07 100pp
- 8009120036 Responds to IE Bulletin 80~17, Suppl 1. Section A, Items 2-5 Applicable procedure contains guidence to control room personnel on initiation of standby liquid control sys Procedure rescram discharge vol revised Affidavit encl ANDOGNINI.0 C Boston Edison Co 80/08/08 4pp
- BOO9140516 Responds to IE Bulletin 80-20, "Failures of Westinghouse Type M-2 Spring Return to Neutral Control Switches " No subj switches used or planned for use in safety-related application at facility, ANDOGNINI.0 C Boston Edison Co 80/08/08 ip
- 8009180519 Responds to IE Bulletin 80-19, "Failures of Mercury-Watted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " No subj relays used or planned for use in sys ANDOGNINI.G C Boston Edison Co 80/08/08 ip
- EOO9190940 Responds to IR Bulletin 80-17 re failure of certain control rods to fully insert during BWR scram Examination revealed absence of failure mode ARNODONINI.O C Boston Edison Co 80/08/12 4pp
- BOO9190073 Ack receipt of 800715 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-293/80-20
  BRUNNER.E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/08/13 1p
- --BO09190076 Responds to NRC 800604 ltr re violations noted in IE Insp Rept 50-293/80-20 Corrective actions Procedure B 7 1 4 will be revised to specify clearly actions to be taken by test director re leakages & valve | lineup deviations ANDDONINI.6 C Boston Edison Co 80/07/15 2pp

- --8009190078 Forwards IE Insp Rept 50-293/80-20 on 800504-08 & notice of violation DRUNNER:E J Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/06/04 2pp
- --8009190079 Natice of violation from insp on 800504-08
  \* Region 1, Philadelphia, Office of the Director 80/06/03 ip
- --8009170081 IE Insp Rept 50-293/80-20 on 800504-08 Noncompliance noted failure to conduct containment integrated leak rate test prior to making repair \$ adjustment \$ to perform local leak rate test after maint CAPHTON.D L. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch REKITOW A. Region 1. Philadelphia, Office of the Director 80/06/03 topp
- 8009090034 Responds to IE Bulletin 80~19. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BMR" Util has ordered scram discharge header water level monstoring sys ANDOSNINI.G C Boston Edison Co 80/08/14 ip
- 8009030111 Forwards Revision 1 to IE Bulletin 80-17, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operacting Nuclear Power Plants Designed by C-E " Written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/08/15 1p
- B007120084 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR" Written response required GRIER B H Region 1, Philadelphia, Office of the Director S0/08/22 1p
- 8009180568 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Raduaste Treatment Sys " No written response required GRIER, B R Region 1, Philadelphia, Office of the Director 80/08/22 1p
- 8009120166 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-00N 6005 Circuit Breakers" No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/08/27 ip
- 8009230490 Forwards Revision 1 to IE Bulletin 79-26, "Boron Loss From BUR Control Blades " Written response required ORIER, B H Region i, Philadelphia. Office of the Director 80/08/29 1p
- 8009230775 Forwards IE Circular 80-21, "Regulation of Refueling Crews " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/09/10 ip
- 8009240303 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Skipments of Radioactive Matls " No written response required GRIER,8 H Region 1, Philadelphia, Office of the Director 80/09/12 ip
- R Periodic operating reports & related correspondence
- 8009090261 Forwards "Radigactive Effluent & Waste Disposal Rept. Including Radiological Impact on Humans. Jan-June 1980 " MORISI.A V Boston Edison Co 80/09/01 ip
- --B007070267 "Radioactive Efficent & Waste Disposal Rept.Including Radiological Impact on Humans.Jan-June 1980 " SOLKDDN:AT L. ZIEMIANSKI:E J Boston Edison Co B0/07/01 74pp
- 8009140267 Forwards monthly operating rept for Aug 1980 MACHON,R D Boston Edison Co 80/09/11 1p
- --8009140271 Monthly operating rept for Aug 1980 WHITNEY. 9 0 Boston Edison Co 80/09/11 App
- 8009300500 Forwards revision to monthly operating rept for Aug 1980 MACHDN.R D Boston Edison Co 80/09/23 ip
- --8009300305 Revision to monthly operating rept for Aug 1980 \* Boston Edison Co -80/09/23 lp

```
--B0091604B3 LER B0-049/03L-0.on 800B10.salt svc water pump (SSN) P2088
tripped On 800B11 SSW P208E tripped Caused by thermal
overleads Permanent corrective actions under study
Haanuhile, inlet water temp decrease has alleviated problem
MCLQUGHLIN.M T Boston Edison Co 80/09/09 2pp
8 Reportable occurrences. LERs & related correspondence
6009090389 Forwards LER 60-042/04T-0
MCGUIRE.P J Reston Edison Co 60
                                                                          80/08/26 10
   -800907040! LER 80-042/047-0 on 800820, analyses rept indicated reportable concentration of Co-60 existed in mussel sample taken from plant discharge canal Caused by normal plant
        operation
MCLOUGHLIN, M T Boston Edison Co 80/08/26
8009030511 Forwards LER 80-043/04L-0
                              Boston Edison Co 80/08/28 1p
    MACHON, R. D.
 --8009030617 LER 90-043/041-0 on 800801, conductivity on outlet of
        demineralizer increased rapidly after placing D condensate
in syr Caused by lateral backing out & allowing media to
                     process
EY, 0 0 Boston Edison Ca 80/08/28 ip
         HHITKEY, O C
8009020382 Forwards LER 80-044/03L-0
MCGU(RE.P J Boston Edizon Co 80/08/29 1p
 --8009020386 LER 80-044/03L-0 on 800801 reactor core isolation cooling
         inboard isolation valve failed to close on reactor low
pressure signal Motor overload annunciator came in &
breaker tripped Caused by valve motor burn out
WHITNEY, G G Boston Edison Co 80/08/29 ip
8009030477 Forwards LER 80-046/93L-0.
MCGUIRE.P J Boston Edison Co 80/08/29 1p
--8009930483 LER 80-046/03L-O on 600802 during reactor shutdown, high
water level isolation main steam line drain valve MD-220-1
failed to isolate Caused by Incorrect setpoint on Varway
level suitch Suitch adjusted & recalibr
(WHITNEY.C O Boston Edison Co 80/08/27 ip
8007030596 Forwards LER 80-039/01T-0
MCGUIRE, P. J. Boston Edison Co. 80/08/29 16
--- 8007030597 LER 80-039/017-0 on 800820.calibr techniques for limiting
        safety sys setting & for average power range monitor found to be monconservative Cause unstated Interim administrative limits established pending final guidelines MCLAUGHLINH T Boston Edison Co. 80/08/29 ip
   )09030603 Forwards LER 80-038/01T-0
MCQUIRE,P J Boston Edison Co 80/08/29 1p
   -8009030607 LER 80-038/017-0.on 800818, made switch in shutdown trip
function of reactor protection sys failed when 8 vital motor
generator set tripped Gaused by relay 3A-K168 being
energized & relay SA-K178 being de-energized
MATHIS.C J Boston Edison Co 80/08/29 2pp
BOOP070422 Forwards LER 80-045/03L-0
MACHON R D Boston Edison Co 80
                                                                      80/09/02 1s
--8009090426 LER 80-048/03L-0 on 800804. after injecting furmanite into leaking packing gland on reactor core isolation cooling outboard (solation valve, valve would not close electrically. Probable cause was improper torque setting WHITNEY. 0 0 Boston Edison Co 80/09/02 1p
    J9090430 Forwards LER 80-047/03L-0
4ACHDN.R D Boston Edison Co 80/09/02 1p
     3009090433 LER 80-047/03L-0 on 800801, reactor vessel 203-3D did not
        respond to manual open signal Air operator assembly solenoid assembly & pilot assembly removed & tested No apparent cause determined Unit reassembled HATHIS: C J Boston Edison Co 80/09/02 3pp
         )70369 Forwards LER 80-048/03L-0
(HDN, R D Boston Edison Co. 80/09/05 1p
          19090376 LER 80-048/03L-0 on 800807.actuation of HPCI & reactor core
           olation cooling fire detectors did not annunciate alarms 
panel in control room Caused by dirt on bell-reducing 
diblity & bad bulb Sys repaired & returned to syc, 
LOUGHLIN. R T Boston Edison Co 80/09/05, [p
            0452 Forwards LER 60-049/03L-0
CN,R D Boston Edison Co 80,
```

80/09/09 1p

```
8009160404 Forwards LER 80-052/03L-0
MACHGILR D Boston Edison Co 80/09/11 1p
 --8009160410 LER 80-052/03L-0 on 800812, while calibr reactor coolant lest detection air sampling sys.particulate chamber cover retaining nuts were stripped Maint personnel replaced nuts MCLQUOHLIN.M T Boston Edison Co 80/09/11 ip
8009160447 Forwards LER 80-051/03L-0
MACHON, R D Boston Edison Co 80/09/11 1p
 --8609160455 LER 80-051/03L-0 on 800813, while performing surveillance test, reactor water level instrument LIS 263-728, switches 3 & 4, erceeded setpoint limit Caused by setpoint drift Instrument recalibr & returned to svc KCLOUGHLIN, M T Boston Edison Co 80/09/11 ip
8009170381 RO 80-090/01X-0 on 800907.during surveillance testing.diesel generator removed from svc when RBCCW pump P202D found inoperable Caused by ambiguous Tech Specs Tech Specs will be revised to clarify limiting condition of operation MCLOUGHLIN.M T Baston Edison Co 80/09/11 2pp
 8009160396 Forwards LER 80-053/03L-0
MECHON.R D Roston Edison Co 80/09/12 1p
 --8009160402 LER 80-053/03L-0 on 800814. HPCI enubber 23-3-36 was found
to be imperable Caused by low reservoir fluid Analysis by
engineering dept underway
MCLAUGHLIN. M T Boston Edison Co 80/09/12 ip
8009290284 Forwards LER 80-054/03L-0
MACHON, R D Boston Edison Co 80/09/18 ip
 --8009290317 LER 80-054/03.-D on 800901.changed station prognization of
           Tech Specs Caused by continuing efforts to improve mgt Amends to Tock Specs re organizational changes will be submitted for review & approval Organizational charts encl GRAHAM.E T Boston Edison Co 80/09/16 3pp
8007230732 Forwards LER 80-057/03L-0
MAGHON, R D Boston Edison Co 80/09/19 1p
--8009230739 LER 80-057/03L-0 on 800821.fluid drive pump tripped & battup & emergency dil pump did not start Caused by coil burnout on 125 volt DC Agastat relay model #2412 Relay replaced & design change initiated MCLAUGHLIN,M T Boston Edison Co 80/09/19 ip
8009240462 Forwards LER 80-056/03L-0
MACHULR D Boston Edison Co 80/09/19 Ip
 --8009240463 LER 80-056/03L-O on 800821. "A" 125-volt dc control battary
on panel C3 became inoperable Caused by faulty electronic
modules in battery charger voltage regulator Battery charger
repaired & returned to svc
                                                    Boston Edison Co 80/09/19 1p
B009240467 Forwards LER 80-055/03L-0
MACHON: R D Boston Edison Co 80/09/19 1p
--8009240468 LER 80-055/03L-0 on 800821,motor overload alarm was received on KO 1301-62 valve in reactor cooling isolation sys Caused by valve thermal overload device Evaluation of capacity rating of overloaded device being conducted MCLOVOHLIN.M.T. Buston Edison Co. 80/09/19 ip
B009260470 Forwards LER 80-050/01T-0
MACHON, R D Boston Edison Co 80/09/19 ip
--8009260475 LER 80-050/01T-0:on 8009(1, during mgt review, concluded that operation 5 maint on containment cooling sys had been conducted in less conservative manner than prescribed in Tech Specs Caused by sparse & ambiguous Tech Specs MCLOUGHLIN, M T Boston Edison Co 80/09/19 2pp
8009260481 Forwards LER 80-087/03L-0
MACHONAR D. Boston Edison Co 80
                                                                                       80/09/19 ip
```

- --8009260484 LER 80-057/03L-0 on 800821 during HPCI sys performance test, HPCI sys declared inoperable due to steam throttle valve sscillation Probably caused by dirt in sys Sys recalibr NCLOUGHLIN.M T Beston Edison Ca 80/09/19 1p
- 8009260480 Forwards LER 80-032/017-0 MACHON, R D Boston Edison Co 80/09/22 1p
- --B009260485 LER 80-032/01T on 800724.0E BIL 299 review revealed higher druwell ambient temp than used for original safeguard Yarway callbrs Caused by high temp due to inadequate druwell cooling Recallbr \$ survey of druwell ventilation conducted MATHIS,C J Boston Edison Co B0/09/22 ip
- 8009270283 Forwards LER 80-060/03L-0 MACHON, R D Boston Edison Co 80/09/24 1p
- --B009270313 LER 80-060/03L-0 on 800B25, while performing HPCI sys performance test. HPCI sys declared inoperable due to oscillating steam throttle valve Caused by dirt filtering through sys Sys recalibr MCLAUCHLIN. M Y Boston Edison Co 80/09/23 ip
- 8009300531 Forwards LER 80-061/03L-0 MACHON, R D Boston Edison Co 80/09/24 1p
- --8009300535 LER 80-061/03L-0 on 800825.core spray valve MD 1400-24A failed & prevented valve MD 1400-25A from being tested Caused by lack of lubrication Valve lubricated & returned to svc Valve insp scheduled during next outage MCCOU9HLIN.M T Boston Edison Co 80/09/24 2pp
- U Congressional/Executive Correspondence
- B009150020 Responds to Subcommittee on Nuclear Regulation 780906 ltr re Benator Stafford request for hearing to discuss 1972 memo re pressure suppressing containments: UCB criticisms re ATMS safety problems & West Valley insp problems HENDRIG: J M Commission 80/08/18 2pp
- ~-8007150074 Responds to request for view on util 731226 itr arguing "need for power" Util did not make substantive & specific case on need Most effective way to save fuel oil would be to shut down & repair core damage HENDRIE.J H Atomic Energy Commission. Deputy Director for Technical Review (Pre-1975) 74/02/04 ip
- --8009150081 Protests AEC 731217 determination & order requiring shutdown during wk of 731223 Action penalizes consumers Review & approval of licensee submittal must be expedited to avoid extended outages
  STASZESKY,F M Boston Edison Co 73/12/26 4pp
- ---8009158085 Responds to util 731226 ltr re facility shutdown Limited speration is justified in view of grobable fuel channel box degradation AEC will expedite review of licensing actions re raturn to power MUNTZING, L M Atomic Energy Commission 74/02/01 3pp
- V Operator Examinations
- 8009220250 Forwards revised Section 3 i 1. "Initial Operator Training." of facility training manual Complete revised training manual to be issued MATHIS.C J. Boston Edison Co. 80/09/12 ip
- --8009220252 Section 3.1 1. "Instial Operator Training." Revision 2
  4 Boston Edison Co 80/09/12 16pp
- DOCKET 80-295 ZION NUCLEAR POWER STATION, UNIT 1

  F. Security, medical, emergency & fire protection plans
- 8009230288 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys (Installed for govt use during emergency KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/22 3pp
- 8009100378 Forwards review of util generating station emergency plan & draft ltr requesting addl info & commitments from util PAGANO.F O Emergency Preparedness Licensing Branch 80/08/28 5pp

- G Adjudicatory correspondence
- 8009220088 Forwards order requiring into supporting environ qualification of safety-related electrical equipment Requests submittal of into by 801101 VAROA.S A Operating Reactors Branch 1 80/08/29 2pp
- --8009220091 Order for mod of Licenses DPR-39 & DPR-48 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment info should be submitted by 801101 EISENHUT, D O Division of Licensing 80/08/29 App
- 80090904/1 Forwards AB Johnson testimony,Pages 63-64 & 80-82.duo to difficulty in reading original submittal STEPIDE.P P Isham, Lincoln & Beale 80/09/03 ip
- --8009090487 Testimony of AB Johnson re proposed amends to increase upont fuel storage capacity Resubmitted Pp 63-64 & 80-82 JOHNSON, A B Brookhaven National Laboratory 80/09/03 5pp
- H General correspondence
- 8009180448 Responds to 800319 1tr requesting public debate re issues apprepriate to evacuation of large population ctrs near plants DENTON.H R Office of Nuclear Reactor Regulation. Director 800/04/21 3pp
- --8009180462 Requests public debate re issues appropriate to evacuation of large population ctrs near plants Expresses confidence in attempts by Commissioners to represent public concerns EMORY. K. Affiliation Unknown 80/03/19 ip
- 8009110P18 Forwards response to 800728 itr requesting assistance in answoring constituent questions re nuclear power & effects of radiation DIRCKS.W J Office of the Executive Director for Operations 80/09/28. 4pp
- P Operating license stage documents & correspondence
- 8009300169 "Rept of Zion/Indian Point Study Vol 2," informal rept STEVENSON,M G Los Alamos Scientific Laboratory IIN A-7015 NUREO/CR-1411 V2 80/04/30 165pp Available at NT[8
- 8007050032 Discusses void formation in vessel head during fi00611 natural circulation coeldown event Requests opinion repotential for voiding phenomenon in Westinghouse designed NSSS CHECK.PS Assistant Director for Plant Systems 80/07/28 2pp
- BOO9020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants, per NRC 800507 Itr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D G Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREO-0696. "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/o NUREO EISENHUT
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Provious determination should be disreparded Requested submittal should include proposed class of amend EISENHUT. D O Division of Licensing 80/08/0/ 40pp
- 8009050528 Forwards Amends 56 % 59 to Licenses DPR-39 % DPR-48, respectively, safety evaluation & notice of issuance & availability VARGALS A Operating Reactors Branch ! 80/09/08 Zpp
- --8009050531 Amends 56 & 53 to Licenses DPR-39 & DPR-48, respectively, revising & upgrading certain limiting conditions of operation & associated surveillance requirements for ventilation filter sys VAROA.8 A Operating Reactors Branch 1 80/08/08 22pp
- --8009050534 Bafety evaluation supporting Amends 56 \$ 53 to Licenses
  DPR-39 & DPR-48, respectively

  \* Office of Nuclear Reactor Regulation, Director 80/08/08 4pg
- --B00905053B Notice of issuance & availability of Amends 56 & 83 to Licenses DPR-39 & DPR-4B, respectively VARGA:S A Operating Reactors Branch 1 80/08/08 2pp

- 8009100178 Forwards request for add1 info re bypass & reset of angineered safety features MOVAK TM Assistant Director for Operating Reactors 80/08/14 4pp
- 8009190794 Forwards revised Westinghouse STS 3 9 8 2.3 9 10 & Bases 3/4 9 8 5 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required MOVAK, TM Assistant Director for Operating Reactors 80/08/15 to
- --8009190817 Revised Westinghouse STS 3 9 8 2 3 9 10 % Bases 3/4 9 8 % 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods # Assistant Director for Operating Reactors 80/06/23 21pp
- 8009110773 Forwards fech Spec Page 282 issued w/Anands 56 & 53 to Licenses SPR-38 & DPR-48, respectively on 800808 VARGA,S A Operating Reactors Bianch I 80/08/20 2pp
- --8009110777 Corrected Tech Spec Page 282 to Amends 56 & 53 to Licenses DPR-48 & DPR-48, respectively + Operating Reactors Branch ( 80/08/20 ip
- 8009150434 Act receipt of 800814 ltr re route approval for shipment of apent fuel rods Fee will be determined by prof manhours expended to conduct review MEISS.D License Fee Management Branch 80/08/22 1p
- 8009100607 Notification of 800827 meeting w/util in Bethesda.MD to allow util to respond to interim technical rept on equipment environ qualifications PREVES.E Operating Reactors Branch i 80/08/25 ip
- 8009030439 Forwards response to 800229 confirmatory order re implementation of A-month items Response includes LER review & evaluation of reliability & failure modes of selected sys & components NAUSHTON N F Commonwealth Edison Co 80/08/29 33pp.
- --8009030440 "Offsite Dose Calculation Sys " Compliance study re Item F 3 of 800229 confirmatory order encl GGLDERUJ C Commonwealth Edison Co BRADLEY, J P. Murray & Trettel, Inc LAHTI.G P Sangent & Lundy, Inc 80/07/31 532pp
- EOOPIROSO2 'Rept of Zion/Indian Point Study," Vol 1 MUREIN: IP Sandia Laboratories FIN A-1218 NUREG/CR-1410 VI EO/08/31 400pr
- BOO9080355 Forwards response to NRC BOO702 request for add1 info re backfitting of severe accident mitigation features. Oversize drawings available in Central Files only NAUGHTOM N F Commonwealth Edison Co. 80/09/03 13pp
- DO9110300 Submits add1 info re NRC 800125 request for util evaluation of asymmetric loads that could develop during LOCA Mechanistic fracture toughness of RCS discussed in Westinghouse 8005030 itr to NRC NRC NAUGHTON, W.F. Commonwealth Edison Co. 80/09/04 2pp
- 3009190468 Forwards addl info required to complete NRC review of util response to NUREC-0578. Items 2 1 8 a t 2 1 8 b re improved post-accident sampling capability & increased range of radiation monitors, respectively Oversize drawing encl. NAUGHTON, H F Commonwealth Edison Co 80/09/05 4pp
- --8009190474 "Auxiliary Bidg Ethaust Sys Control Diagram " • Sargent & Lundy, Inc. 3782 80/07/23 ip
- B009230385 Forwards Amends 57 & 54 to Licenses DPR-39 & DPR-48, respectively, safety evaluation & notice of issuance & availability
  VARGA.S A Operating Reactors Branch 1 80/09/09 2pp
- -8009230390 Amends 57 % 54 to Licenses DPR-37 & DPR-48 respectively, incorporating changes to Tech Specs to allow maint of circulating water pumps during operation VARGA.S A Operating Reactors Branch 1 80/07/09 8pp
  - 09230394 Safety evaluation supporting Amends 57 & 54 to Licenses PR-39 & DFR-48 respectively Operating Reactors Branch 1 80/09/09 4pp
  - 230379 Notice of issuance & availability of Amends 57 & 54 to censes DPR-39 & DPR-48 respectively RGALS A Operating Reactors Branch 1 80/09/09 2pp

- 8007180144 Discusses two risk studies currently underway Preliminary assessment of Indian Point risk profile contained in SECY 80-283 Zion risk profile assessment will combine accident saquence evaluation & containment failure analysis ERNST, M L Assistant Director for Technology Review 80/09/11
- BOO9190403 Forwards revised portions of inservice valve test program, per 800618 request Revisions do not change type or method of testing containment isolation valves Contains necessary info for meeting pump & valve inservice testing requirements NAUOHTON.W F Commonwealth Edison Co 80/09/11 83pp
- 8009300099 Forwards safety evaluation re proposed periodic testing performance of diesel generators at facilities Util 800522 request re acceptability of safeguard actuation tests prior to 800519 is acceptable VAROA.S A Operating Reactors Branch 1 80/09/11 3pp
- --8009300101 Safety evaluation supporting proposed periodic testing performance of diesel generators at facilities A Operating Reactors Branch 1 80/09/11 2pp
- 8009260213 Advises of delay until 801003 for submittal of Tech Specs upgraded to requirements of STS for Westinghouse PWR in response to NRC 800716 request Review scope & time more extensive than originally planned NAUOHTON N F Commonwealth Edison Co 80/09/18 ip
- 8009300267 Forwards "Ropt of Endurance Tests for Auxiliary Feedwater Pumps 1A,1B,1C,2A,2B,2C,Jan-Jume 1980 " NAUGHTON:N F Commonwealth Edison Co 80/09/23 1p
- --8009300273 "Rept of Endurance Tests for Auxiliary Feedwater Pumps 1A. 18.10.2A.2B.2C.Jan-June 1980." \* Communication Edison Co 80/06/30 51pp
- O Inspection reports, IE Bulletins & correspondence
- 8007020107 Responds to IE Bulletin 79-03A, "Langitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pips " SA-312 pipe not present in operating plants Final confirmation from suppliers anticipated by 800915 re const plant piping sys NAUGHTON, W.F. Commonwealth Edison Co. 800/08/07 2pp
- B009180012 Forwards IE Insp Repts 50-275/80-15 & 50-304/80-19 on 800722 No noncompliance noted FIORELITE Region 3. Chicago. Reactor Construction & Engineering Support Branck 80/08/07 2pp
- --8009180021 IE Insp Repts 50-295/80-15 & 50-304/80-15 on 800722 No noncompliance noted Major areas inspected documentation for instablation of spent fuel racks & containment liner penatration welds
  DANIELSON, D.H. Region 3. Chicago, Reactor Construction & Engineering Support Branch KEY, W.J. Region 3. Chicago, Office of the Director 80/08/05 App
- 8007030231 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/08/15
- BO09110545 Responds to IE Bulletin BO-OB, "Exam of Containment Liner Penetration Helds," supplementing B00709 response Corrects Zion response re rings used for field circumferential butt weld Reviews accuracy of other statements ABELJ S Commonwealth Edison Ca B0/OB/15 App
- 8009160681 Submits supplementary response to IE Bulletin 80-08: "Examination of Containment Liner Penetration Welds." correcting statement made in DL Peoples 800709 ltr Further review not necessary ABEL.J S Communwealth Edison Co 80/08/15 4pp
- 8007030126 Forwards IE Insp Repts 50-275/80-18 & 50-304/80-18 on 800730 & 31 No noncompliance noted HIND.J A Region 3, Chicago. Safeguards Branch 80/08/18 2pp
- --8009030133 IE Insp Repts 50-295/80-18 % 50-304/80-18 on 800730 % 31
  No noncompliance noted Major areas inspected physical
  security, physical barriers & previous insp findings Details
  withheld (ref 100FR2 790)
  HIND. J A Region 3, Chicago, Safeguards Branch MADEDA, Y J.
  CHRISTOFFER, G Region 3, Chicago, Office of the Director
  80/08/14 1p

- B009270425 Forwards IE Insp Repts 50-275/80-16 & 50-304/80-16 on B00804-05 & notice of violation HEISHMANAR F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/08/18 2pp
- --8009290428 Notice of violation from insp on 800804-05 \* Region 3. Chicaga, Office of the Director 80/08/15 ip
- --8009290436 IE Insp Repts 50-295/80-16 \$ 50-304/80-16 on 800804-05 Noncompliance noted failure to follow licensed operator requalification training program KCHLER.J E , SCHULZ.R D , BAKER,K R Region 3, Chicago, Office of the Director 80/08/15 3pp
- 800925033B Ack receipt of 800729 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/80-12 & 50-304/80-12 HEISHMAN:R F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/08/20
- --8009280344 Forwards response to NRC 800709 ltr re violations noted in IE lnsp Repts 50-295/80-12 & 50-304/80-12 Corrective actions info tag has been placed on gauge indicating that tank is empty at reading of 6% Recallbr complete by 801231 NAWHTON.W F Commonwealth Edison Co 80/07/29 3pp
- 8009180551 Forwards IE Carcular 80-18, "10CFRSO 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/22
- 8009230094 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/28
- 8009170411 Forwards response to IE Bulletin 80-15 re possible loss of emergency notification sys w/loss of offsite power Review revealed inoperability of Dresden sys Investigation being conducted Operating Order 26-80 changed JAMACEK, R F Commonwealth Edison Co 80/08/29 4pp
- 8009180466 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Identified relays are not used in facility. No action required Twenty-four manhours expended on review RAUSCH.T J Commonwealth Edison Co 80/08/27 ip
- B009250504 Responds to NRC 791213 request for add1 info in response to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Expansion anchor test results show installation of anchors acceptable JANECEK.R F Commonwealth Edison Co 80/09/05 17pp
- 8009240133 Forwards IE Circular 80-21. "Regulation of Refueling Crews " No written response required XEPPLER, J G Region 3. Chicago. Office of the Director 80/09/10 Ep
- 8009260656 Ack receipt of 800819 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/80-05 & 50-304/80-04 KEPPLER, J G Region 3. Chicago, Office of the Director 80/09/10 ip
- --8009260658 Responds to NRC 800727 ltr re violations noted in IE Insp Repts 50-295/80-05 & 50-304/80-04 Corrective actions mgt & mgt support of health physics program reviewed & changed to laplement regulations REED, C Commonwealth Edison Co 80/08/19 10pp
- 8009300200 Forwards response to IE Bulletin 80-20 No Westinghouse Type M-2 control switches are used in safety-related sys at Dresden duad Cities & LaBalle County Responses for Zion & Byron are encl RAUSCH.T J Commonwealth Edison Co 80/09/15 6pp
- A Periodic operating reports & related correspondence
- 8007030441 Forwards semiannual rept of radioactive effluent discharges & solid radwaste for Jan-June 1980 GRAESSER, K L Commonwealth Edison Co 80/08/07 1p
- --8009030444 Semiannual rept of radioactive effluent discharges & solid radwasts for Jan-June 1980 a Commonwealth Edison Co 80/08/07 35pp

- BO09090294 Forwards monthly operating repts for Aug 1980 GRAESSER.K L. Commonwealth Edison Co 80/09/09 (p
- --8009090278 Monthly operating rept for Aug 1980 CDOK, J M Commonwealth Edison Co 80/09/05 (1pp
- 8 Reportable occurrences. LERs A related correspondence
- 8009020447 Forwards LER 80 029/03X-1 GRAESSER, K. L. Commonwealth Edison Co. 80/09/04 Ip
- --8009020455 LER 80-029/03x-1 on 800531, while removing insulation to repair leak on discharge line to boric acid filter, heat trace on circuits OME 190/205 were damaged Caused by nicks to heat trace by maint personnel removing pipe insulation HAZELRIGO. 6 Commonwealth Edison Co 80/08/04 ip
- BO09120697 Part 21 rept re area monitor countrate assembly RP-2C which has within it electronic parts under excessive stress All purchasers of Class IE qualified units were notified of potential problem
  RICKARD.C L. General Atomic Co. (subs. of Gulf Gil Co.) BO/08/13
  3pp
- 8009020095 Forwards LER 80-026/03L-0 GRAESSER, K L Commonwealth Edison Co 80/08/14 1p
- --8009020401 LER 80-026/03L-0 on 800719, during normal operation. Class I pipe tunnel iodine monitor IRT-PRO78 failed low Caused by natural end-of-life of photo-multiplier tube Part replaced Monitor functionally tested 8 returned to ave.

  AKER.R E Commonwealth Edison Co 80/09/14 [p
- 8009020452 Forwards LER 80-031/03L-0 08AESSER.K L Commonwealth Edison Co 80/08/19 ip
- --R009020457 LER 80-031/03L-0 on 800718. Suring normal operation, auxiliary bidg area monitor ORT-AR09 failed law Caused by slight drift in monitor electrical 1010 point Zero point adjusted & monitor functionally tested & roturned to svc AKER.R E Commonwealth Edison Co 80/08/15 ip
- 8009120299 Forwards LER 80-003/04L-0 GRAESSER.K L Commonwealth Edison Co 80/08/29 lp
- --8007120331 LER 80-003/03L-0 on 800802.efter DB lake discharge tank release was started personnel noted that liquid release form did not include sample taken after 2.000 gallons of wastewater were added Caused by poor communitations GURUNATHAN.8 Commonwealth Edison Co 80/08/29 tp
- 8009120302 Forwards LER 80-004/03L-0 GRAESSER, K. L. Commonwealth Edison Co. 80/00/29 ip
- 8009120305 Forwards LTR 80-006/01T-0 GRAESSER, K L Commonwealth Edison Co 80/09/02 1p
- --B009120320 LER 80-006/01T-0 on 800821, charcoal filters serving fuel bidg were not available during nonrefueling modes of operation Caused by improper installation of dampers Dampers reinstalled per original design STAHMER.F Commonwealth Edison Co 80/07/02 tp
- 8009140408 Forwards LER 80-007/01T-0 GRAEBSER, K.L. Commenwealth Edison Co. 80/09/09 Ip
- --B007i60426 LER B0-007/01T-0 on B00B15, during normal operation while mods were performed on post-LOCA hydrogen recombiner piping, hydrogen purge fan IRVO20 was made inoperable Caused by failure of Const Dept to notify Operating Dept of mod POLANSKI, X Communicalth Edison Co. 80/09/09 2pp
- BOO9220349 Forwards LER 80-03B/03L-0 GRAFSSER: K L Commonwealth Edison Co UO/09/11 ip
- --B009220352 LER 80-038/03L-0 on 800820, during normal operation, operability surveillance for Pyra-Alarm Detectors could not be performed in prescribed interval Caused by insufficient amount of test gas to test all alarms EVERST, E J Commonwealth Edison Co 80/09/11 ip

- 8007220281 Forwards LCR 80-037/03L-0 ORAESSER.K L Commonwealth Edison Co 80/09/12 ip
- ~-B009220287 LER B0-037/03L-0 on 800812 during normal operation while performing monthly functional tests of 63AST reactor trip switches water set 11 psig off in nonconservative direction Caused by faulty test gauge CLARX, B Commonwealth Edison Co 80/09/12 lp

#### V Operator Examinations

- 8009300287 Forwards preliminary topical outlines of proposed modules on thermal hydraulics ⊅ core damage mitigation to be included in revised reactor operator training program per 800328 request NAUGHTON, N F Commonwealth Edison Co 80/09/15 7pp
- DOCKET 50-296 GROWNS FERRY NUCLEAR POWER STATION, URIT 3

  F. Security, medical, emergency & fire protection plans
- 8009120121 Forwards request for addl info re guard training & qualification Encl withhold (ref 10CFR2 770) IPPOLITO,T A Operating Reactors Branch 2 80/08/22 2pp
- BOOP230267 Requests that all personnel be reminded of purpose of emorgency notification sys & Acalkh physics network Sys installed for govt use during emergency O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/22
- 8009250272 Discusses util 800509 response re responsibility matrix of safeguards contingency plan, including interrelationships of contingency actions NRC cannot give formal approval until info is specifically submitted for approval IPPOLITO, T A Operating Reactors Branch 2 80/09/09 2pp

#### O Adjudicatory correspondence

- B009220018 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 | PPOLITO, T.A. Operating Reactors Branch 2 80/08/29 2pp
- --8009220019 Order for mod of Licenses DPR-33.DPR-52 % DPR-68 to add info which fully responds to NRC request for info re environ qualification of infety-related electrical equipment info should be submitted by 801101 EISEMHUT.D O Division of Licensing 80/08/29 App

## I Financial information

- 8009090343 Forwards Annual Financial Rept 1979 CROSS.J.L. Tennessee Valley Authority 80/09/04 ig
- --8007070963 Annual Financial Rept (779 \* Tennesses Valley Authority 80/09/04, 44pp
- P Operating license stage documents & correspondence
- 8007110554 Supple NRC 800707 request for proposed Tech Specs changes re scram discharge vol vent & drain valves. & reactor protection sys & control rod block limit switch surveillance requirements Class III liconse fee to be submitted w/change EIGENHUT.D O Division of Licensing 80/07/22 22pp
- 8007020277 Submits interim criteria for shift staffing to all GL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 70 days EISENRUT.D G Division of Licensing 80/07/31 7pp
- 8007090080 Forwards draft NUREO-0676, "Functional Criteria for Emergency Response Facilities," Comments requested within 90 days Proposed implementation schedule for meeting criteria of NUREO-0676 encl W/o NUREO EISENHUT, D O Division of Licensing, 80/08/01 117pp.
- 8009230052 Informs that examption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D G Division of Licensing 80/08/07 60pp

- 8009030406 Application to amend Licenses DPR-33.DPR-52 & DPR-68, changing Tech Specs re containment sys MILLS.I. M Tennessee Valley Authority 80/08/19 200
- --8009030411 Proposed Tech Specs 3 7 % 4 7 re limiting conditions for operation & surveillance requirements for containment sys # Tennessee Valley Authority 80/08/19 47pp
- 8009190697 Forwards NUREO-0661. "Mark I Containment Long-Term Program SER Resolution of Generic Technical Activity A-7" Rept discusses generic suppression pool hydrodynamic load definition W/o encl IPPOLITO:T A Operating Reactors Branch 2 80/08/20 2pp
- 8009020069 Application for expedited amend to License DPR-68 Forwards proposed revisions to Tech Specs re residual heat removal svc water sys & standby coolant supply capability Class III fee forthcoming Justification for changes encl
  MILLS.L M Tennessee Valley Authority 80/08/26 2pp
- --8009020074 Proposed revisons to Tech Specs re residual heat removal sycuator sys & standby coolant supply capability. Sections 3 5 & 4 5

  \* Tennessee Valley Authority 80/08/26 5pp
- 8007020406 Application for amend of License DPR-68, changing Tech Specs to accompdate Reload 3, Cycle 4 operation of Unit 3 Shutdown planned for 801020 to begin refueling outage w/restart on 801201 Class III fee encl
  MILLS.L H Tennessee Valley Authority 80/08/27 2pp
- ---8009020408 Proposed Tech Specs 1 2 & 2 2 re RCS integrity & 3 5 & 4 \$ re core & containment cooling sys Changes will accompdate Reload 3. Cycle 4 operation \* Tennessee Valley Authority 80/08/27 14pp
- ~-8007020412 "Supplemental Reload Licensing Submittal for Browns Ferry Nuclear Power Station Unit 3.Reload 3 " HILF.C L , ENOEL.R E General Electric Co Y1003J01A03 80/08/31 29pp
- 8009030631 Forwards addl justification for proposed Tech Specs changes in application to amend License DPR-68 submitted by 800826 ltr CROSS.J L Tennessee Valley Authority 80/08/28 3pp
- B009090367 Forwards response to NRC B00425 ltr requesting that util confirm conclusions of analysis re min ECCB equipment availability w/dc power supply failure CR09S.J L Tennessee Valley Authority 80/09/03 2pp
- B009090555 Forwards corrected page to proposed Tech Specs 3 7 & 4 7 recontainment sys integrated leak testing, originally submitted on 800819 CROSS, J. L. Tennessee Valley Authority 80/09/03 3pp
- --8009090560 Corrected page to proposed Tech Specs 3 7 & 4 7 re containment sys integrated leak testing originally submitted on B00819 \* Tennessee Valley Authority 80/09/03 1p
- 8009120245 Application to amend License DPR-68 Forwards proposed Tech Spec changes reflecting new primary containment atmospheric hydrogen monitoring instrumentation to be installed during upcoming refueling outage Requests approval by 801203 CROSS.J L Tennessee Valley Authority 80/09/05 2pp
- ---8009120249 Proposed Tech Spec changes re primary containment atmospheric hydrogen monitoring instrumentation to be installed during upcoming refueling outage Sys description & justification encl. 8 Tennessee Valley Authority 80/09/05 5pp
- 8009160219 Forwards changes to Tech Specs Section 6 0 for DL amend re administrative controls in response to NRC 800702 ltr to all BWR licensees Changes are based on model specs provided in Encl 1 to 1tr Fee encl MKLLS.L
- --B009160221 Proposed changes to Tech Spec Section 6 0 re administrative controls, based on model specs in NRC 800702 ltr to all BWR licensees # Tennessee Valley Authority 80/09/09 9pp
- 8007260324 Forwards Amend 34 to License DPR-68, safety evaluation & notice of issuance & availability
  IPPOLITO, T A Operating Reactors Branch 2 80/09/09 2pp

- ~~8009260331 Amend 34 to License DPR-68, changing Tech Specs to permit continued operation following isolation of residual heat removal sec water to Unit 2 residual heat removal heat erchanger IPPOLITOIT A Operating Reactors Branch 2 80/09/09 600
- --8009260336 Safety evaluation supporting Amend 34 to License DPR-68 \* Operating Reactors Branch 2 80/09/09 Spp
- --BD09260341 Notice of issuance & availability of Amend 34 to License IPPOLITO, T A Operating Reactors Branch 2 80/09/09 2pp
- 8009240545 Act receipt of response to NRC 791109 questions re ECCS evaluation models dealing w/fuel cladding.swelling & incidence of rupture Response is acceptable IPPOLITO.T A Operating Reactors Branch 2 80/09/10 2pp
- 8009240601 Confirms util commitment to NRC 791023 "Interim Position on Cantainment Purging & Venting Pending Resolution of Isolation Valve Operability "Util position util remain in effect pending completion of NRC long-term review IPPOLITO, T A Operating Reactors Branch 2 80/09/10 2pp
- 9009220210 Notifies that 800731 application to amend Licenses DPR-33, DPR-52 & DPR-68 has not yet appeared as FR notice Info requested me schedule for licensing & FR notice publication date
  MillB.L M Tennessee Valley Authority 80/09/16 2pp
- 8009300400 Forwards technical questions re implementation of interim policy on 10CFR50 & 51 MILLS.L M Tennessee Valley Authority 80/09/23 3pp
- 8009300429 Requests notification if concerns re GE GEXL critical power correlation & conservatism in predictions for 8x8 retrofit fuel remain as open item for facility Cycle 4 operation MILLS,L & Tennessee Valley Authority 80/09/23 2pp
- 8009300147 Requests amend to DPR-33 DPR-52 & DPR-68 consisting of Tech Spec Changes re reactor protection sys MILLS.L M Tennessee Valley Authority 80/09/24 2pp
- --8009300156 Proposed Tech Specs 1 0.3 3 & 4 3 re reactor protection sys \* Tennessee Valley Authority 80/09/24 15pp
- 8009300359 Revises util 791106 schedule for shipment of motor generator sets to be installed as part of LPCI sys power supply mods Cenerator sets will be installed during Fall 1980 Unit 3. Bpring 1982 Unit 1 & Bpring 1982 Unit 2 outages MILLB.L M Tennessee Valley Authority 80/09/24 1p
- @ Inspection reports, IE Bulletins & correspondence
- 8009090073 Forwards IE Bullatin 80-07, Suppl 1, "BWR Jet Pump Assembly O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/13
- 8009020184 Submits response to IE Bulletin 79-03A No 8A-312 or A-312.
  Type 300 series fusion welded pipe is in use or planned for use in safety-related sys
  MILLS.L M Tennessee Valley Authority 80/08/06 ip
- 8009020222 Forwards IE Insp Repts 50-259/80-32,50-260/80-25 & 50-296/80-26 on 800628-0704 No noncompliance noted O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/08
- --8009020225 IE Insp Repts 50-259/80-32,50-260/80-25 & 50-296/80-25 on 800628-0704 No noncompliance noted Major areas inspected licensee investigation of Unit 3 failure to fully insert control rods after 800628 scam DANCE, H.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/08/08 IBpp
- BD09030146 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Marcury-Weited Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/08/15
- BOO7020133 Forwards response to IE Bulletin 80-17. Suppl i re failure of control rods to insert during scram at BWR Item B i scram discharge header sys will be modified to praclude necessity of level monitoring wiscreption of instrument vol MILLS. L H Tennessee Valley Authority 80/08/18 2pp

- 8009160045 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE Bill Facilities " No specific action or response requested O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/19
- B009190603 Ack receipt of B00815 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/80-22, 50-246/80-16 & 50-276/80-17 KENNA, M. B. Region 2. Atlanta, Safeguards Branch 80/08/21 ip
- --8009190510 Forwards response to NRC 800717 ltr re violations noted in IE Insp Repts 50-259/80-22,50-260/80-16 & 50-296/80-17 Encl withheld (ref 10CFR2 790) MILLS,L M Tennessee Valley Authority 80/08/15 ip
- --8009190617 Ack receipt of 800710 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/80-22, 50-260/80-16 \$ 50-296/80-17 Notes commitment to provide addi-response within 20 days KENNA, W B Region 2, Atlanta, Safeguards Branch 80/07/17 ip
- --8009190443 Forwards response to NRC 800616 ltr re violations noted in IE Insp Repts 50-259/80-22,50-260/80-14 & 50-296/80-17 Encl withheld (ref 10CFR2 770) MILLS.L M Tennessee Valley Authority 80/07/10 Ip
- --8009190646 Forwards IE Insp Repts 50-259/80-22.50-260/80-16 5 50-296/80-17 on 800519-23 % notice of violation Notice of violation withheld (ref 10CFRZ 790) KENNA, W B Region 2, Atlanta, Safeguards Branch 80/06/16 2pp
- --B009190651 IE Insp Repts 50-259/80-22,50-260/80-16 & 50-296/80-17 on 800519-23 Noncompliance noted incomplete vital area barrier, inadequate lock installation & absence of portable radio in vehicle escort Details withheld (ref 100FR2 790) TILLMAN, A. TOBIN, W. J., OILLESPIE, F. P. Region 2. Atlanta, Office of the Director 80/06/16 ip
- 8009120082 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at 3WR " Written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22
- 8007(60153 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22
- 8009250075 Responds to IE Bulletin 80-14. "Degradation of DNR Scram Discharge Vol Capability " Corrects error in 800728 response re Item A i One instance of broken rod on ball float also occurred MILLS.L M Tennessee Valley Authority 80/08/26 ip
- BOO9120340 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover1 480 Volt Type K-6008 & K-DDN 6005 Circuit Breakers " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/27
- 8009230521 Forwards Revision 1 to IE Bulletin 79-26, "Beron Loss From BWR Control Blades " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/29
- 8009240261 Forwards response to IF Bulletin 80-17 re failure of control rods to fully insert during scram at BWR Plant instructions changed on 800827 to provide for manual scram & functional test Thirty-five manhours expended in bulletin review MILLB.L M Tennessee Valley Authority 80/08/29 3pp
- 8009240383 Forwards response to IE Bulletin 80-15 re possible loss of mergency notification sys w/loss of offsite power Design change request submitted Administrative procedure issued to comply w/requirements MFLLS.L M Tennessee Valley Authority 80/08/29 4pp
- 8009240446 Forwards response to IE Bulletin 80-17 re failure of control rods to fully insert during scram at BHR.Vent mod being coordinated w/overall scram discharge header sys roview & mod program Schedule estimates will be provided MILLS.L M Tennessee Valley Authority 80/08/29 3pp
- 8009260375 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/10

- E009300539 Forwards Progress Rept 4 for IE Bulletin 80-06 re engineered safety features reset controls MILLS:L K Tennessee Valley Authority 80/09/10 7pp
- 8007300010 Act receipt of 800819 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-259/80-24, 50-260/80-18 t 50-296/80-19 LEMIS.R C Region 2 Atlanta, Reactor Operations Nuclear Support Branch 80/09/11 ip
- --8009300067 Forwards response to NRC 800724 ltr re violation noted in IE Imsp Repts 50-259/80-24.50-260/80-18 & 50-276/80-19 Corrective actions outdated surveillance instruction sheets replaced w/current revisions MILLS
- --8009300072 Forwards IE Insp Repts 50-259/80-24,59-260/80-18 & 50-276/80-19 on 800563-0601 & notice of violation LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 60/07/24 2pp
- --8009300075 Notice of violation from insp on 800503-0601
   Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/07/15 1p
- --8009300081 IE Insp Repts 50-259/80-24,50-260/80-18 & 50-296/80-19 on 800503-0601 Noncompliance noted failure to use latest revision of survesilance instruction data sheet SULLIVAL, R. F. CHASE, J. W. Region 2. Atlanta, Office of the Director DANCE, H. C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/07/15 7pp
- R Periodic operating reports & related correspondence
- B009110352 Forwards "Radiological impact Assessment.Browns Ferry Nuclear Plant.Jan-June 1980 " MILLS.L M Tennessee Valley Authority 80/08/29 ip
- --B009110353 "Radiological Impact Assessment.Browns Ferry Nuclear Plant, Jan-June 1980 " \* Tennessee Valley Authority RK-80-5-8F-3 80/08/29 46pp
- BOO9170274 Forwards monthly operating repts for Aug 1980 ABERCROMOIE.H Tennessee Valley Authority BO/09/17 1
- --8009170277 Monthly operating repts for Aug 1980
  ABERCROMBIE.H . THOM.T . GREEN, D Tennessee Valley Authority
  B0/09/01 30pp
- S Reportable occurrences. LERs & related correspondence
- 8009190765 PNO-78-147 on 780818 one of six air compressors experienced massive failure resulting in rapid loss of control air pressure to all units Caused by large hole in cylinder head State of AL notified Hedia attention anticipated KLINGER, G. NOLAN, F. SNIETZEK, J. Office of Inspection & Enforcement, Office of the Director 78/08/18 lp
- 8009190753 Provides interim assessment of PNO-78-147 re partial failure to scram event Margin of safety inherent in licensed design basis should be promptly restored Improved temporary measure acceptable pending permanent mods
  MICHELSON. C Director's Office 80/08/18 3pp
- 8007030597 Forwards LER 80-028/03L-0 CALHOUN: J R Tennessee Vailey Authority 80/08/28 19
- --8009030604 LER 80-028/03L-0 on 800806, while performing Special Instructions 4 1 A-7. level switch LIS-3-203C, reactor water level switch 2, which traps reactor core isolation cooling, found to siceed Tech Spec limit Caused by instrument drift \* Ternessee Valley Authority 80/08/28 2pp
- 8009090314 Forwards LER 80-029/03L-0 CALHGUR, J R Tennessee Valley Authority 80/09/04 ip
- --B009090328 LER 80-029/03L-0 on 800802, Surveillance Procedure 2 1 performed w/computer valve improperly set resulting in use of previous day values for man average planar linear heat generation rate Caused by personnel error

  \* Tennessee Valley Authority B0/09/04 2pp
- 8009090332 Forwards LER 80-030/03L-0 CALHBUN, J. R. Tennesses Valley Authority 80/09/05 ip

- --8009090341 LER 80-030/03L-0 on 800813, during normal operation, performing Surveillance Instruction 4 i A 14, pressure switches PS-1-81-A & PB-1-91-A found set above limits Caused by setpoint drift Switches recalibr & tested \* Tennessee Valley Authority 80/09/05 2pp
- 8009160416 Forwards LER 80-031/03L-0 CALHOUN, J.R. Tennessee Valley Authority 80/09/08 1p
- --8009160422 LER 80-031/03L-0 on 800809, during performance of MRI 303, discovered that emergency equipment cooling water flow was below min allowed on 38 RHR pump seal heat exchanger Caused by mud & shells restricting flow in piping inlet

  \* Tennossee Valley Authority 80/09/08 2pp
- 8007180441 LER 79-016 has been cancelled COLLINS.M Tennessee Valley Authority 80/09/17 ip
- 8009230674 Forwards LER 80-032/03L-0 GALHOUN, J R Tennessee Valley Authority 80/09/18 1p
- ---8009230479 LER 80-032/03L-0 on 800825, while performing reactor core isolation cooling steam line space high temp SI 4 2 B-32, lead wires were accidentally pulled out of speed feedback magnetic pickup connector Caused by personnel error \* Tennessee Valley Authority 80/09/18 lp
- 8009230669 Forwards LER 80-034/03L-0 CALHOUN.J R Tennessee Valley Authority 80/09/19 1p
- --8007230675 LER 80-034/03L-0 on 800829, during normal operation, investigation of overload for RHR area cooler fans revealed overload for RHR pump area cooler fan 3A was set too high Cause instated Relay replaced

  \* Tennessee Valley Authority 80/09/19 2pp
- 8009300544 Forwards LER 80-035/03L-0 CALHOUN, J R Tennessee Valley Authority 80/09/26 1p
- ---8007300553 LER 80-035/03L-0 on 800901, "A" reactor recirculation pump tripped Caused undetermined Unit load reduced to 700 mW & pump restarted in A-h \* Tennessee Valley Authority 80/07/26 2pp
- DOCKET 90-297 NORTH CAROLINA STATE UNIV PULSTAR REACTOR
  P Operating license stage documents & correspondence
- 8009300296 Forwards Amend 6 to License R-120 & safety evaluation MILLER, J.R. Standardization & Special Projects Branch 80/09/17
- --B009300300 Amend 6 to License R-120, revising provisions re quality & form of SNM authorized MILLER.J R Standardization & Special Projects Branch 80/09/17
- --8009300301 Safety evaluation supporting Amend A to License R-120 MILLER.JR Standardization & Special Projects Branch 80/09/17
- R Periodic operating reports & related correspondence
- E009020352 Forwards "Annual Rept.Jul 1979 to Jul 1980 " COCKRELL.R 9 North Carolina State Univ 80/08/27 ip
- --8009020354 "Annual Rept. Jul 1979 to Jul 1980 " COCKRELL.R G , SRAY.T C North Carolina State Univ 80/08/27 26pp
- DOCKET 50-298 COOPER NUCLEAR STATION
- F Security, medical, emergency & fire protection plans
- 8009020195 Invites participation in 800822 workshop in Atlanta, QA to solicit comment re proposed functional criteria for emergency response facilities in NUREO-0.096 Discussion to include location, size & staffing of emergency ctrs SEYFRIT, K V Region 4, Dallas, Office of the Director 80/08/12 in
- 8009030551 Forwards security plan re guard training & qualification Plan uithheld (ref 10CFR2 790) PILANT.J M Nebraska Public Power District 80/08/29 2pp

#### G Adjudicatory correspondence

- 8009260576 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 | PPOLITO T A Operating Reacture Branch 2 80/08/29 2pp
- --B007260601 Order for mod of License DPR-46 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101
  FISENSRUT.D C Division of Licensing 80/08/29 App
- P Operating license stage documents & correspondence
- BOO9110554 Suppls NRC 800707 request for proposed Tech Specs changes re scram discharge vol vent & drain valves. & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT.D O Division of Licensing 80/07/22 22pp
- BOO9020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISERHUT, D G Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/a NUREG EISENHUT.D O. Division of Licensing 80/08/01 119pp
- BQD9230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D Q Division of Licensing 80/08/07 60pp
- 8009040176 Requests that Tech Specs be proposed re completed facility mods for fire protection described in Amend 56 to License DPR-46 Forwards 875 for guidance IPPOLITO, T A Operating Reactors Branch 2 80/08/11 2pp
- --8009040180 STS re fire protection \* Westinghouse Electric Corp 79/12/07 15pp
- 8007150503 Forwards NUREO-0661, "Mark I Containment Long-Term Program Safety Evaluation Rept.Resolution of Generic Technical Activity A-7 " Rept describes NRC review results & requirements M/o encl [PPOLITO.T A Operating Reactors Branch 2 80/08/20 2pp
- 8009190478 Forwards summary rept. "Primary Containment Integrated Leak Rate Test Performed 800523" PILANT, J M Nebraska Public Power District 80/08/27 ip
- --8009190493 "Primary Containment Integrated Leak Rate Test Performed
  - 4 Nebraska Public Power District 80/05/23 150pp
- 8009240544 Confirms util commitment to NRC 791023 "Interim Position on Containment Purging & Venting, Pending Resolution of Isolation Valve Operability "Util position will remain in effect pending completion of NRC long-term review IPPOLITO, T A Operating Reactors Branch 2 80/09/09 2pp
- BOO9240649 Ack receipt of response to NRC 791109 questions re ECCS, evaluation models dealing wifuel cladding swelling & incidence of rupture Response is acceptable IPPOLITO.TA Operating Reactors Branch 2 80/09/10 2pp
- 8009170287 Informs NRC that acceptance criteria for all startup physics bests have been met PILANTIJ M. Nebraska Public Power District 80/09/11 1p
- Q Inspection reports, IE Bulletins & correspondence
- BOO9990046 Forwards IE Bulletin 80-07, Suppl 1, "BWR Jet Pump Assembly Failure" No response required SEYERIT, K V Region 4, Dallas, Office of the Director 80/05/13
- 8009080937 Forwards 1E Insp Rept 50-298/80-10 on 800421 & notice of Violation BRCMN 0 D Region 4. Dallas, Fuel Facility & Materials Safety Branch 80/06/17 2pp

- --8009080557 Notice of violation from insp on 800421
  \* Region 4, Dallas, Office of the Director 80/06/12 in
- --8009080562 IE Insp Rept 50-278/80-10 on 80042[ Noncompliance noted radwaste shipment in excess of spec % in unapproved package BRONN.G D Region 4. Dallas. Fuel facility & Materials Safety Branch 80/06/12 ip
- --8009080569 Forwards Waste Packaging Insp Rept 15000027/80-54 on 800421 BOOK.R E Region 5. San Francisco. Fuel Facility & Materials Safety Branch 80/05/18 1p
- --B009080566 Waste Packaging Insp Rept i5000027/80-54 on 800421
  Noncompliance noted radwaste shipment in excess of spec & in
  unapproved package
  BOOK.IE E Region 5, San Fiencisco, Fuel Facility & Materials
  Safety Branch THOMAS.R D , BASSIN.N Region 5, San Francisco,
  Office of the Director 80/05/15 12pp
- 8009100674 Advises of 800708 expiration date for Item 2 re IE Bulletin BO-17. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BUR " Addi parameter is being considered to determine pressure variation during test scrams SEYFRIT.K V Region 4, Dallas, Office of the Director 80/07/07 ip
- --8009100677 Forwards IE Bulletin 80-17, 'Failure of 74 of 185 Control Rods to Fully Insert During Sciam at BWR " Written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/07/03
- 8009100031 Responds to IE Bulletin 80-08, 'Examination of Containment Liner Penetration Welds "Penetration weld adequacy assured by length of weld sycitest results show weld root & final pass soundness & acceptante not based on ultiasons; tests PILANT, J M Nebraska Public Power District 80/07/08 8pp
- BOD9180115 Forwards Suppl 1 to IE Bulletin 80-17, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BKR" No written response required SEYFRIT,K V Region 4, Dailas, Office of the Director 80/07/18
- 8009180117 Forwards Suppl 2 to IE Bulletin 80-17. "Failures Revealed by Yesting Subesequent to Failure of Control Rods to Insert During Scram at BNR " Written response required SEYFRIT.X V Region 4. Dallas. Office of the Director 80/07/22 19
- 8009020102 Responds to IE Bulletin 80-16 re Rosemount, Inc pressura transmitter misapplication Feedwater flow transmitters indirectly safety-related & used primarily for plant startup & shutdown Erroneous indication not expected PILANT, J M Nebraska Public Power District 80/07/24 4pp
- 8009020098 Responds to IE Bulletin 80-17.Suppl 2.re failure of control rods to insert during scram Swing check valve operation checked daily 8 meets positive venting requirement PILANT, J M Nebraska Public Power District 80/07/28 1p
- 8009020539 Forwards supplemental IE Info Notice 80-06. "Notification of Significant Events at Operating Power Reactor Facilities." No written response required SEYFRITIK V Region 4. Dallos. Office of the Director 80/07/29
- 8009020101 Rosponds to IE Bulletin 80-17,re failure of control rods to insert during scram Forwards special test procedure 80-9 sequence of events indicating that all equipment performed as designed ⊅ no corrective action necessary PILANT.J M Nebraska Public Power District 80/07/30 Spp
- 8009180108 Forwards IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches" (Fritten response required SEYFRITIK V Region 4, Dalles, Office of the Director 80/07/31 to
- 8009180157 Forwards IE Bulletin 80-19, "Failure of Mercury-Wetted Matrix Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E" Written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/07/31
- 8009260291 Forwards IE Info Notice 80-29, "Broken Stude on Terry Turbine Steam Inlet Flange " No written response required SEYPRIT,K V Region 4, Dallas, Office of the Director 80/08/07

- 007100842 Ack receipt of 800806 Itr informing NRC of steps taken to correct violations noted in IE lisp Rept 50-298/80-09 4MDSEN.G L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/08/13 ip
- --80091^0844 Responds to NRC B00714 ltr re violations noted in IE Insp Rept SD-298/80-09 Corrective actions training session on houseteeping & cleanup conducted for maint personnel PILANTIJ M Nebraska Public Power District B0/08/06 3pp
- 009230116 Forwards Revision I to 1E Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Hritten response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/08/ Region 4, Dallas. Office of the Director 80/09/15
- 009160035 Forwards IE Info Notice 80-30. "Potential for Unacceptable Interaction Between Control Rod Brive Scram Function & Nonessential Control Air at Certain OE BWR Facilities " No specific action or response requested SEY+RIT.K V Region 4. Daltas. Office of the Director 80/08/19
- 3009120026 Forwards Suppl 3 to 12 Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR" Written response required SEYFPIT,K V Region 4. Dailas, Office of the Director 80/08/22
- 3009170399 Forwards IE Circular 80-18 "10CFR50 59 Safety Evaluations for Changes to Radwasto Treatment Sys " No written response required BEYFRIY, N V Region A. Dallas. Office of the Director 80/08/22
- 2009;20429 Forwards IE Info Notice 80-31, "Malaperation of Gould-Brown Bovert 480 Valt Type K-6069 & K-DDN 6009 Circuit Breakers " No written response required SEY-RIII K V Region 4, Dallas, Office of the Director 80/08/27
- 8009180127 Forwards Revision 1 to IE Bulletin 79-26. "Boron Loss From BUR Control Blades" Written response required BEYFRIT.X V Region 4. Dallas, Office of the Director 60/08/29
- B009300605 Requests site orientation relevant to issuance of badges, escart dutios & emergency evacuation be afforded NRC personnel listed on enclosure SEYFRIT,X V Region 4. Dallas. Office of the Director 80/09/05
- R Periodic operating reports 3 related correspondence
- 8009160262 Forwards monthly operating rept for Aug 1980 LESSOR, L C Nebraska Public Power District 80/09/04 10
- 8009260282 Forwards "Semiannual Operating Rept Radioactive Efluents, for Jan-June 1980 PILANT, J M Nebraska Public Power District 80/09/10 2pp
- --8009260284 "Semiannual Operating Rept Radioactive Effluents." for Jan-June 1980 KFAY,N S . EVANS,A K Harleton Laboratories, Inc. 80/08/26
- 8 Reportable occurrences, LERs & related correspondence
- 9009050260 Forwards LER 80-028/03L-0 LESSOR,L C Nebraska Public Power District 80/08/11 2pp
- -8009050264 LER BO-02B/03L-O on B00713 while increasing power during normal operation, GE reactor vent monitor failed downscale Caused by two failed capacitors New capacitors installed & unit returned to operable status

  BCHEER, J. L. Nebraska Public Power District B0/08/11 1p
  - '050326 Forwards LER 80-029/03L-0 SSOR,L C Nebraska Public Power District 80/08/12 2pp

- --B009050331 LER B0-029/03L-0 on B00723, during performance of SP & 4 5 10. fire hydrant HT-1 could not be opened Caused by broken stem top section Section replaced & personnel instructed to avoid using unnecessary force when closing ALLEN.M D Nebraska Public Power District 80/08/12 ip
- 8009050252 Forwards LER 80-031/01T-0 LESSOR.L C Nebraska Public Power District 80/08/18 2pp
- --8009050255 LER 80-031/01T-0 on 800804, voltage transients were induced into turbine generator digital electrical hydraulic sys computer Reactor scrammed when MSIVs closed Caused by 345 kV distribution sys line fault SCHEER, J L Nebraska Public Power District 80/09/18 1p
- 8009050187 Forwards updated LER 80-008/03X-1 LEESUR.L C Nebraska Public Power District 80/08/20 3pp.
- --8009050190 Updated LER 80-008/03X-1 on 800312, during scheduled insp of reactor core isolation cooling turbine, two damaged buckets on wheel were discovered Caused by nonimpact type impringement of foreign object on wheel FLANNIGAN, R D Nebraska Public Power District 80/08/20 1p
- 8809050284 Forwards LER 80-030/03L-0 LESSOR, L C Nebraska Public Power District 80/08/21 2pp
- --B009050287 LER B0-030/03L-0 on B00Bi3, during normal surveillance testing of RHR motor operated valves RHR loop B suppression pool cooling inboard throttle valve would not operate Caused by failure of key between motor pinion gear & motor shaft BOAN, P F Nebraska Public Power District 80/08/21 1p
- 8009050199 Forwards LER 80-032/03L-0 LESSOR, L C Nebraska Public Power District 80/08/22 2pp
- --8009050203 LER 80-032/03L-0 on 800729, during performance of surveillance procedure 6 2 2 2 1, isolation of HPCI steam line occurred Cause not fully determined Probable cause due to transient in common sensing line LAWRENCE, L. I. Nebraska Public Power District 80/08/22 ip
- DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2 F Security, medical, emergency & fire protection plans
- 8009110619 Requests participation in study of people-related problems in nuclear safeguards Study involves collection of data on licenses security forces & practices EISEMHUT.D O Division of Licensing 80/07/25 2pp
- 8009030542 Forwards safeguards contingency plan Plan withheld (ref 10CFR2 770) BURSTEIN.8 Wisconsin Electric Power Co 80/08/22 ip
- 8007230314 Requests that all personnel be reminded of purpose of emergency motification sys & health physics network Bys installed for govt use during emergency KCPPLER.J O Region 3, Chicago, Office of the Director 80/08
- 8007260215 Responds to 800822 request for info re emergency notification sys & health physics network & requests clarification of notification requirements PAY: C.W. Wisconsin Electric Power Co. 80/09/05. 3pp
- 8009290177 Forwards security measures for proposed sewage treatment plant Encl withheld (ref 10CFR2 790) BURSTELM:8 Wisconsin Electric Power Co 80/09/19 1p
- Q. Adjudicatory correspondence
- 8009190352 Forwards order requiring into supporting environ qualification of safety-related electrical equipment Requests submittal of into by 801101 CLARK.R A Operating Reactors Branch 3 80/08/29 2pp
- --8009190357 Order for mod of Licenses DPR-24 & DPR-27 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment info should be submitted by GOIOI EISENHUT.D O Division of Licensing 80/08/29 6pp

#### H General correspondence

- 8007050424 Responds to League Against Nuclear Dangers 800715 ltr re relocating local PDR to Two Rivers,WI Two Rivers library will house documents re Wood County special repts NRC 1979 Annual Rept encl SOUDER.J L. Division of Rules and Records 80/08/15 22pp
- --B009030426 Requests submitted on behalf of League Against Nuclear Dangers, concerning relocation of local PDR to Manitowoc, NI Lists types of documents & specific documents that should be retained at Univ of NI library DIXON. O Affiliation Unknown 80/07/18 3pp
- 8009110411 Requests establishment of LPDR in Madison.WI.on behalf of WI Public Svc Commission State agency personnel will review replacement of steam generators at Point Beach Unit 1 in 1981 or 82 Related correspondence YORK.5 , PARSONS.E M , NUNNERY.W J Wisconsin, State of 80/08/26 20s
- 80092&0187 Forwards FR notice of relocation of facility LPDR from Univ of WI Library, Stevens Point to Joseph Mann Library, Two Rivers, WI FELTON, J & Division of Rules and Records 80/09/09 200
- P Operating license stage documents & correspondence
- 8009020297 Submits interim criteria for shift staffing to all OL & CP licenses & applicants.per NRC 800507 ltr Discusses administrative provisions for amergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D Q Division of Licensing 80/07/31 7pp
- BDD90800B0 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREO EISENHUT, D G Division of Licensing 80/08/01 119pp
- 8007020497 Responds to NRC 800708 ltr re weldments in Graver tanks Evaluations show that connections & penetrations would withstand design loading conditions assuming as-found configuration BURSTEIM, S. Wisconsin Electric Power Co. 80/08/04. 3pp
- BOO9230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D Q Division of Licensing 80/08/07 60pp
- 8007170774 Forwards revised Westinghouse STS 3 9 8 2,3 9 10 & Bases 3/4 9 8 & 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NOVAK.T M Assistant Director for Operating Reactors 80/08/15
- --8009190817 Revised Hestinghouse STS 3 9 8 2.3 9 10 & Basus 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods

  4 Assistant Director for Operating Reactors 80/06/23 21pp
- 8009120575 Forwards requests for addl info re adequacy of station attectric distribution sys voltages to continue review Response requested within 45 days of ltr receipt CLARK.R A Operating Reactors Branch 3 80/09/08 6pp
- BOO9160442 Responds to NRC 800819 ltr re IAEA design info questionnaire to be utilized in submittal of installation info by facilities Compiling data will require significant effort NRC should utilize existing info in files BURBIEIN.S Wisconsin Electric Power Co 80/09/11 ip
- 8007230560 Responds to 800815 request for review of Tech Specs & procedures assuring that exposure of fuel assemblies & control rods cannot occur during transfer w/plant in refueling shutdown mode. Changes to Tech Specs unnecessary FAY; C W Wisconsin Electric Power Co 80/09/15 2pp
- B009230666 Notifies NRC that util unable to comply w/800714 request re Tech Specs applicable to implementation of TMI-2 Lessons Learned Category A items Initial review of model Tech Specs completed FAY:C H Wisconsin Electric Power Co 80/09/18 3pp

- 8009250249 Application to amend Licenses DPR-24 & DPR-27 changing Tech Specs 15 1.15 3 & 15 6.re limiting conditions for operations, definitions of operability & administrative structure BURBTEIN'S Wisconsin Electric Power Co 80/09/19 App
- ~-8009250253 Tech Spec Change Request 64.consisting of proposed Tech Specs 19 1.15 3 & 15 6 re limiting conditions for operations definition of operability & administrative structure

  4 Wisconsin Electric Power Co 80/09/19 8pp
- 8005290341 Proposed Change 45 modifying 770728 request to amend Licenses DPR-24 5 DPR-27 to incorporate Tech Spec changes Changes modify trip & time delay setting for undervoltage protection circuitry BURSTEIN 8 Wisconsin Electric Power Co 80/09/22 2pp
- --8009270342 Tech Spec change for Item 7 of Table 15 3 5-1 & Item 3a of Table 15 3 5-3 re time & trip delay settings for Undervoltage protection sys \* Wisconsin Electric Power Co 80/09/22 2pp
- 8009300461 Forwards comments on draft NUREO-0696. "Functional Criteria for Emergency Response Facilities" NUREO should include alternate methods of satisfying functional requirements FAY.C W Wisconsin Electric Power Co 80/09/22 6pp
- G Inspection reports, IF Bulletins & correspondence
- B009290011 Forwards IE Insp Repts 50-266/B0-10 & 50-301/B0-10 on B00604-27 & notices of violation.App A & B App B withheld (ref 100FR2 790) KEPPLER.J G Region G, Chicago, Office of the Director 80/08/11 3pp
- --8007270013 Notice of violation. App A. from insp on 800604-27

  \*\* Region 3. Chicago, Office of the Director 80/08/85 ip
- --8009270015 IE Insp Repts 50-265/80-10 & 50-301/80-10 on 800604-27 & 0708 Noncompliance noted RMR pumps operability impaired & engineered safety feature crosscannected Details withheld (ref 10CFR2 790)
  SMITH.J D. GULDEMOND.W G. WARNICK.R F. Region 3. Chicago, Office of the Director 80/08/05 12pp
- G009030219 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Dosigned by C-E " Written response required KEPPLER.J G Region 9. Chicago. Office of the Director 90/08/15
- 8009R90017 Forwards IE Insp Repts 50-266/80-13 & 50-301/80-13 on 800717 & 22 No noncompliance noted DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Gafety Branck 80/08/19 2pp
- --8009270018 IE Insp Repts 50-266/80-13 & 50-301/80-13 on 800717 & 22 No nuncompliance noted Major areas inspected confirmatory measurements JANUSKA, A O , ESSIG, T H Region 3, Chicago, Diffice of the Director 80/08/13 4pp
- 8009180520 Forwards IE Circular 80-18, "10CFR50 57 Bafety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/08/22
- 8007110557 Responds to IE Bulletin 80-18, "Maint of Adequate Min Flow Thru Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Corrective actions are not necessary. FAY.C W Wisconsin Electric Power Co 80/08/26. 2pp
- 8009230089 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Carcuit Breakers" No written response required KEPPLER. J G Region 3. Chicago. Office of the Director 80/08/28
- 8009180158 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Identified relays not used in facility
  FAY.C.W Wisconsin Electric Power Co 80/08/29 ip

- 8009240124 Forwards IE Carcular 80-21, "Regulation of Refueling Crews" No written response required REPPLER.J G Region 3, Chicago, Office of the Director 80/09/10
- 8009300305 Responds to IE Bulletin 80-20 Identifies safety-related equipment control circuits utilizing Westinghouse Type W-2 switches w/spring-return-to-neutral position All but four circuits have been modified to indicate switch closure BURSTEIN, S Wisconsin Electric Power Co 80/09/16 2pp
- R Periodic operating reports & related correspondence
- 6009090539 Forwards "Semiannual Monitoring Ropt, Jan-Jun, 1980 " FAY.C W. Wiaconsin Electric Power Co. 80/08/29 1o
- --8009090545 "Semiannual Monitoring Rept. Jan-Jun. 1980 "
  + Wisconsin Electric Power Co 80/08/29 15pp
- 8009160302 Forwards monthly operating repts for Aug 1980 FAY: C W Wisconsin Electric Power Co 80/09/09 tp
- --8009160304 Monthly operating repts for Aug 1980
  FAY.C W. Wisconsin Electric Power Co. 80/09/04 9as
- U Congressional/Executive Correspondence
- 8007020050 Expresses concerns re potential consequences from steam generator tube degradation Full adjudicatory hearing needed Requests to be informed of continuing development STRONL.J. BERGER.D., NOODY.J. Misconsin, State of BO/08/22 1p
- DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

  F. Security, medical, emergency & rire protection plans
- 8009230258 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/22 to
- 8009030230 Responds to NRC 800624 ltm requesting revised site emergency plan Util will submit plan following review of State of FL draft "Radiological Emergency Plan for Fixed Nuclear Facilities," NUREG-0494 & NUREG-0544, Revision 1
  BAYNARD,P Y Florida Power Corp 80/08/24 3pp
- 8009180285 Submits security info re safeguards contingency plan Info withhold (ref 10CFR2 790) BAYNARD.P Y Fiorida Power Corp 80/09/15 2pp

# Adjudicatory correspondence

- 09190375 Forwards order requiring info supporting environ qualification of safety-related electrical equipment acquests submittal of info by 801101
  REID.R W Operating Reactors Branch 4 80/08/29 2pp
- 3009190380 Order for mod of License DPR-72 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101
  EISENHUT, D 6 Division of Licensing 80/08/29 App
- i General correspondence
- 8009020517 FOIA request for four categories of info re facility GIVEL.M S Affiliation Unknown 80/07/31 ip
- 009020511 Responds to FDIA request for four categories of info re facility Documents re [tems 1-3 can be found in PDR No documents were found re Item 4 FEETON. J K Division of Rules and Records 80/08/19 1p
- Operating license stage documents & correspondence
- 19150070 Responds to 800523 recommendations concerning lessons earned from 800226 transient at Crystal River Submits esults of investigations re use of atmospheric dump valve t Occnee Units 1-G-AR Unit 1.Davis-Besse Unit 1 & TMI-1 ENTON-HR Office of Nuclear Reactor Regulation, Director 2/07/21 200

- ---8009150079 Discusses 800226 transient at facility Recommends investigation to determine whether atmospheric dump valve design deficiency is present in other BMJ plants MIGHELSON, C Director's Office 80/05/23 2pp
- 8009020297 Submits interim criteria for shift staffing to all DL & CP licensees & applicants, por NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISERMUT, D & Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 ancl M/a NUREO EISEN
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Loarned is unjustified Provious determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D G Division of Licensing 80/08/07 60pp
- 8009240611 Add1 FOIA request for documents re util weld chemistry as surveyed by BSN GIVEL-M S Affiliation Unknown BO/08/25 1p
- 8009190582 Approves of 800730 request for relief from THI Lessons Learned Task Force Item 2 2 1 b S Johnson may be assigned as tuchnical advisor REID.8 W Operating Reactors Branch 4 80/09/02 2pp
- B009090442 Forwards response to NRC 800701 request for add1 info re fuel assembly holddown springs BAYNARD.P Y Florida Power Corp 80/09/03 5pp
- 8007090278 Forwards evaluation of instrumentation to detect inadequate core cooling Responses to IE Bulletin 79-03C & NUREO-0578, included operator guidelines & evaluation of supplemental instrumentation No addi instrumentation BAYNARD, P Y Florida Power Corp 80/09/04 24pp
- BO09250427 Informs of acceptability of response to NRC 791107 ltr reportions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture REID:R W Operating Reactors Branch 4 80/09/09 2pp
- B009240606 Add1 response to FOIA request for documents re weld chemistry at facility as surveyed by 18&W Forwards documents listed in App A Proprietary document is under review FELTON.J II Division of Rules and Records B0/09/11. 2pp
- --8009240617 Approves 770830 request for withholding info re reactor vessel matl surveillance program from public insp per 10CFR2 790 Info contains trade secrets or privileged commercial or financial info REID:R W Operating Reactors Branch 4 (Pre 791030). 77/12/07 Geo
- --B009240628 Forwards info re reactor vessel & associated surveillance specimen in response to NRC 770319 request Info contains weld chemistry info taken from existing matl test repts JH Taylor affidavit only encl
  STEWART.WP Florida Power Corp 77/08/30 2pp
- --B009240634 Affidavit of JH Taylor re procedures & criteria for classifying documents as proprietary (ref 10CFR2 790) TAYLOR, J H Babcock & Wilcox Co 77/08/12 7pp
- 8009170288 Application to amend App A to OL, changing aspects of NOREO-0578 including model license conditions & emergency feedwater initiation & flow monitoring Affidavit & Certificate of 8vc encl BAYNARD, P Y. Florida Power Corp 80/09/15 4pp
- --8009170289 Tech Specs 3/4 3-38, requesting changes re model license conditions, emergency feedwater institution & flow monstoring, diverse containment isolation & emergency power supply to pressurizer heaters
  + Florida Power Corp 80/09/15 24pp
- @ Inspection reports, IE Bulletins & correspondence
- 8009190786 Forwards response to IE Bulletin 79-018, "Environ Gualification of Class IE Equipment," Items 1-3 BAYNARD,P Y Florida Power Corp 80/04/21 223pp.

- B009100046 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/07/24
- 8009150104 Forwards IE Insp Rept 50-302/80-26 on 800630-0703 No noncompliance noted LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/07/25 2pp
- --8009150115 IE Insp Rept 50-302/80-26 on 800630-0703 No noncompliance noted Major areas inspected containment integrated leakage rate testing, safety-related piping support & restraint sys QUICK.D Region 2, Atlanta, Reactor Operations Nuclear Support Branch BROCKS.E H Region 2, Atlanta, Office of the Director 80/07/24 Spp
- BOC9030125 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/15 to
- 8009100933 Responds to IE Bulletin 80-19 & Revision 1.re failure of C-E mercury-wetted matrix relays in reactor protective sys Identified relays are not used in facility Twenty-four manhours expended on review ERECHT.R M Florida Power Corp 80/08/21 2pp
- 8009160113 Forwards IE Circular 80-18. "100FR50 59 Bafety Evaluations for Changes to Radwaste Treatment Sys " No written response required 0'REILLY.J.P Region 2. Atlanta. Office of the Director 80/08/22 to
- BOO9120258 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-600S & K-DDN 600S Circuit Breakers "
  No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/27
- 8009240176 Ack receipt of 800808 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/80-10 STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/08/28 1p
- --8007240184 Responds to NRC 600715 ltr re violations noted in IE Insp Rept 50-302/80-10 Corrective actions implementation of procedures to assure compliance w/requirements for radioactive matl tagging HARCOCK, J. A. Florida Power Corp. 80/08/08 2pp
- --8009240189 Forwards IE Insp Rept 50-302/80-10 on 800524-28 & notice of violation STOMR.JP Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/07/15 2pp
- --8009240195 IE Insp Rept 50-302/80-10 on 800524-28 Noncompliance noted failure to tag & identify radioactive mat1 w/appropriate labels PUCKETT.J M Region 2. Atlanta, Office of the Director OUSSON.A F Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 80/07/11 6pp
- BOO9170145 Ack receipt of 800829 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/80-29 KENNA.W B Region 2. Atlanta. Safeguards Branch 80/09/05 ip
- ---8009170147 Forwards IE Insp Rept 50-302/80-29 on 800707-11 & notice of violation Notice of violation withheld (ref 100FR2 790) XENNA/W B Region 2, Atlanta, Safeguards Branch 80/08/05 2pp
- --8009170152 IE Insp Rept 50-302/80-29 on 800707-11 Noncompliance noted tamper indicating capability could not be demonstrated for entire alarm sys & required security emergency drill not consucted Details withheld (ref 100FR2 790)
  OILLESPIE.F.P., HOMELL, J.C. Region 2, Atlanta, Safeguards Branch 80/08/04 1p
- 8009290274 Forwards IE Circular 80-21, "Regulation of Refueling Crews "
  No written response regulard
  d'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/10
  Spp

- 8009300143 Submits response to IE Bulletin 80-10 re contamination of nonradioactive sys On 800728, nitrogen sys became contaminated necessitating revised response to bulletin Will require until 801015 to respond to bulletin BAYNARD, P y Florida Power Corp 80/09/10 2pp
- R Periodic operating reports & related correspondence
- 8009030200 Forwards "Effluent & Waste Disposal Semiannual Rept," Jan-June 1980 HANCOK, J.A. Florida Pouer Corp. 80/08/29 2pp
- --8009030204 "Effluent & Waste Disposal Semiannual Rept." Jan-June 1980 POOLC.D . BAYNARD.P Florida Pouer Corp 80/08/26 59pp
- 8009220361 Forwards monthly operating rept for Aug 1980 BAYNARD, P Y Florida Power Corp 80/09/15 1p
- --8009220365 Monthly operating rept for Aug 1980 CULVER,M W Florida Power Corp 80/09/02 4pp
- S Reportable occurrences, LERs & related correspondence
- 8009020197 Part 21 rept re improper fluid provided w/reactor coolant gump hydraulic shock suppressors fluid will be changed to hydraulic fluid for use in radioactive environs HANCOCX.J A Florida Power Corp 80/08/07 3pp
- 8009030475 Forwards LER 80-031/04L-0 HARGGCK.J A Florida Power Corp 80/09/29 1p
- --80090304B2 LER 80-031/04L-0 on 800806, determined that established procedures were not adhered to in carrying out environ monitoring program Caused by contractor errors Procedures for three of eight identified areas will be clarified LANCASTER, F Florida Power Corp 80/08/25 4pp
- 8009030497 Forwards LER 80-032/03L-0 HANCGCK, J A Florida Power Corp 80/08/29 1p
- --B009030503 LER 80-032/03L-0 on 800805.while performing special load test emergency diesel generator in tripped when loaded Caused by actuation of field over-current relay below design setpoint Relay adjusted to proper value HEINAMDY.V A Florida Power Corp 80/08/28 2pp
- 8009030600 Farwards LER 80-033/03L-0 HANCOCK, J A Florida Power Corp 80/08/29 1p
- --8007030607 LER 80-033/03L-0 on 800803 following routine sampling of core flood tank A, sample isolation valve CFV-11 failed to close Caused by failed contact rotor in Limitorque operator Contact rotor 2 replaced to declared operable NEUSCHAEFER: C Florida Power Corp 80/08/28 2pp
- 8009050265 Forwards LER 80-034/04T-0 HANGGCK, J.A. Florida Power Corp. 80/09/02 1p
- --8009050268 LER 80--34/0AT-0 on 800820, max circulating water discharge temp exceeded 103 F for more than three consecutive hours Apparent cause was high temp of intake water & high power levels Temp lowered by increased water flow & reduced load HERNANDEZ.V A Florida Power Corp 80/08/28 2pp
- 8009110337 Forwards LER 79-102/03L~1 HANCOCK, J A Florida Power Corp 80/09/08 1p
- --B009110342 LER 79-102/03L-1 on 791023, following routine sampling of B core flood tank (CFT), B CFT sample isolation valve CFV-12 uould not close CFT isolation valve CFV-42, in closed position, isolated penetration Cause unknown NEUSCHAEFER, E Florida Power Carp B0/08/29 2pp
- 8009150280 Forwards LER 80-035/03L-0 HANCOCK, J A Florida Power Corp 80/09/11 ip
- ~~8009150282 LER 80-035/03L-0 on 800816, during startup operation, postaccident monitoring instrumentation found inoperable Caused by instrument drift Instrumentation recalibr & verified operable LANCASTER.K F Florida Power Corp 80/09/08 2pp
- 8009290290 Forwards LER 80-036/03L-0 HANGOCK, J A Florida Power Corp 80/09/24 1p

- --8009270305 LEP 80-036/03L-0 on 800827, "8" decay heat pump discharge throttle valve would not control flow in automatic Caused by water in sensing line Operability restored by blowing down sensing line & performing functional check htm://dxi08Z/V A Florida Power Corp 80/09/19 2pp
- T. Hearing transcripts on non-antitrust matters
- 8005260313 Submittal of prepared testimony for first hearing session No attempts made to provide complete answers to ASLB 800708 menorandun & order re physical separation of TMI units Certificate of Svc ent Related correspondence TRUMBRIDGE.O F Metropolitan Edison Co B0/09/15 7pp
- --8009260366 "Small Break Operating Quidelines " Related correspondence \* Babrock & Wilcox Co 69-1106091-00 79/11/30 48pp
- DOCKET 50-304 ZION NUCLEAR POWER STATION: UNIT 2

  F. Security, medical, emergency & fire protection plans
- 8009230288 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency KEPPLER, J G Region 3. Chicago. Office of the Director 80/08/22 3pp
- 8009100378 Forwards review of util generating station emergency plan & draft ltr requesting addl info & commitments from util FAGAND, F.G. Emergency Preparadness Licensing Branch 80/08/28 5on
- G Adjudicatory correspondence
- 8009220089 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 VARGA.S A Operating Reactors Branch 1 80/08/29 2pp
- --8009220091 Order for mod of Licenses DPR-39 & DPR-48 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101

  EISENHUT.D O Division of Licensing 80/08/29 App
- 8007090471 Forwards AB Johnson testimony Pages 63-64 & 80-82, due to difficulty in reading original submittal STEPTOE, P.P. Isham, Lincoln & Beale 80/07/03 1p
- --8009090487 Testimony of AB Johnson re proposed amends to increase spent fuel storage capacity Resubmitted Pp 63-64 & 80-82
  JOHNSON A B Brockhaven National Laboratory 80/09/03 3pp
- H General correspondence
- 800918044B Responds to 800319 ltr requesting public debate re issues appropriate to evacuation of large population ctrs near plants

  DENTEN, R Defice of Nuclear Reactor Regulation, Director. 80/04/21 3pp
- --8009180462 Requests public debate re issues appropriate to evacuation of large population ctrs near plants Expresses confidence in attempts by Commissioners to represent public concerns EMORY. K. Affiliation Unknown 80/03/19 ip
- 8009110218 Forwards response to 800728 itr requesting assistance in answering constituent questions re nuclear power & effects of radiation BIACKS. U J Office of the Executive Director for Operations 80/08/28 4pp
- P Operating license stage documents & correspondence
- 8009300169 "Rept of Zion/Indian Point Study Vol 2." informal rept STEVENSON,M 0 Los Alamos Scientific Laboratory FIN A-7015 NUREC/CR-1411 V2 80/04/30 165pp Available at NTIS
- 8009050032 Discusses void formation in vessel head during 800611 natural circulation cooldown event Requests opinion repotential for voiding phenomenon in Westinghouse designed NSSS CHECK.P S Assistant Director for Plant Systems 80/07/28. 2pp

- 8009020297 Submits interim criteria for shift staffing to all CL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Davelopment & implementation to be reviewed within 70 days EISENHUT, D O Division of Licensing 80/07/31 7pp
- BO09080380 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 entl W/o NUREO EISENHUT,D G Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D © Division of Licensing 80/08/07 40pp
- 8009050528 Forwards Amends 56 & 53 to Licenses DPR-39 & DPR-48, respectively, safety evaluation & notice of issuance & availability VARGA, S A Operating Reactors Branch 1 80/08/08 2pp
- --8009050531 Amends 56 & 53 to Licenses DPR-39 & DPR-48 respectively, ravising & upgrading certain limiting conditions of operation & associated surveillance requirements for ventilation filter sys

  VARGA, S. A. Operating Reactors Branch 1 80/08/08 22pp
- --8009050534 Safety evaluation supporting Amends 56 & 53 to Licenses

  OPR-39 & DPR-48, respectively

  \* Office of Nuclear Reactor Regulation, Director 80/08/08 4pp
- --8009050538 Notice of issuance & availability of Amends 56 & 53 to Licenses DPR-39 & DPR-48, respectively VARGA.5 A Operating Reactors Branch 1 80/08/08 2pp
- 8009100178 Forwards request for add1 info re bypass & reset of engineered safety features
  NOVAK.T M Assistant Director for Operating Reactors 80/08/14
- 8009190794 Forwards revised Westinghouse STB 3 9 8 2.3 9 10 & Bases 3/4 9 8 2/4 9 10 to require 23 ft of water over top of reactor pressure vessel flangs during movement of fuel assemblies or control rods Written response required NOVAK-T M Assistant Director for Operating Reactors 80/08/15
- --8009190817 Revised Westinghouse STB 3 9 8 2,3 9 10 & Bases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods

  \* Assistant Director for Operating Reactors 80/06/23 21pp.
- 8009110773 Forwards Tech Spec Page 282 issued w/Amends 56 & 53 to Licenses DPR-38 & DPR-48, respectively on 800808 VARGA.8 A Operating Reactors Branch 1 80/08/20 2pp
- --8009110777 Corrected Tech Spec Page 282 to Amends 54 & 53 to Licenset DPR-38 & DPR-48, respectively # Operating Reactors Branch 1 80/08/20, 1p
- 8007100007 Notification of 800827 meeting w/util in Bethesda,MD to allow util to respond to interim technical rept on equipment environ qualifications REEVES.E Operating Reactors Branch 1 80/08/25 1p
- 8009030439 Forwards response to 800229 confirmatory order re implementation of 6-month items Response includes LER review & evaluation of reliability & failure modes of selected sys & components NAUGHTON, W.F. Commonwealth Edison Co. 80/08/29. 33pp
- --B009030440 "Offsite Dose Calculation Sys " Compliance study re Item F,3 of 800229 confirmatory order encl GOLDEN.J C Commonwealth Edison Co BRADLEY,J P Murray & Trettel: Inc. LANTI.OP Sargent & Lundy. Inc. B0/07/91. 532pp
- 8009120502 "Rept of Zion/Indian Point Study," Vol 1 MVRFINM.B Sandia Laboratories FIN A-1218 NUREQ/CR-1410 Vi 80/08/31 400p
- 8007080355 Forwards response to NRC 800702 request for add1 info re backfitting of severe accident mitigation features Oversize drawings available in Central Files only NAUQHTON, W F Commonwealth Edison Co 80/09/03 13pp

- 8009110300 Submits add1 info no NRC 800125 request for util evaluation of asymmetric loads that could develop during LOCA Mechanistic fracture toughness of RCS discussed in Westinghouse 800630 ltr to NRC NAUGHTON,W F Commonwealth Edison Co 80/09/04 ≥pp
- 8009190468 Forwards add1 info required to complete NRC review of util response to NUREG-0570. Items 2 1 8 a & 2 1 8 b re improved post-accident sampling capability & increased range of radiation monitors, respectively Oversite drawing encl MAUCHTON. W.F. Commonwealth Edison Co. 80/09/05 App
- --8009190474 "Auxiliary Bldg Exhaust Sys Control Diagram "
  4 Sargent & Lundy, Inc 3782 80/07/23 ip
- 8009230385 Forwards Amends 57 & 54 to Licenses DPR-37 & DPR-48, respectively safety evaluation & notice of issuance & ivailability WAROA.S A Operating Reactors Branch 1 80/09/09 2pp
- ---8009230370 Amends 97 & 54 to Licenses DPR-39 & DPR-48 respectively, incorporating changes to Tech Specs to allow maint of circulating water pumps during operation VAROA.8 A Operating Reactors Branch 1 80/09/09 Bpp
- --8009230394 Safety evaluation supporting Amends 57 & 54 to Licenses DPR-39 & DPR-48 respectively # Operating Reactors Branch 1 80/09/09 4pp
- --809230379 Notice of issuance & availability of Amends 57 & 54 to Licenses DPR-37 & DPR-48, respectively VARGA, 8 A Operating Reactors Branch 1 80/09/09 2pp
- BOOGIBO144 Discusses two risk studies currently underway Proliminary assessment of Indian Point risk profile contained in BECY 80-203 Zion risk profile assessment will combine accident sequence evaluation & containment failure analysis EARSTIN L Assistant Director for Technology Review 80/09/11
- 8009190403 Forwards revised portions of inservice valve test program, par 800618 request Revisions do not change type or method of testing containment isolation valves Contains necessary info for meeting pump & valve inservice testing requirements MAUGHTON.W F Commonwealth Edison Co 80/09/11 83pp
- 8009300099 Forwards safety evaluation re proposed periodic testing performance of diesel generators at facilities Util 800522 request re acceptability of safeguard actuation tests prior to 800519 is acceptable VARGA.S A Operating Reactors Branch 1 80/09/11 3pp
- --8009300101 Safety evaluation supporting proposed periodic testing performance of diesel generators at facilities \* Operating Reactors Branch 1 80/09/11 2pp
- 80092&0213 Advises of delay until 801003 for submittal of Tech Specs upgraded to requirements of STS for Westinghouse PWR in response to NRC 800716 request Review scope & time more extensive than originally planned MAUGHTON. W F Commonwealth Edison Co 80/09/18 1p
- 8009300267 Forwards "Rept of Endurance Tests for Auxiliary Feedwater Pueps 1A: 1B: 1C: 2A: 2B: 2C: Jan-June 1980 " RAUGHTON: W F Commonwealth Edison Co 80/09/23 1p
- --8009300273 "Rept of Endurance Tests for Auxiliary Feedwater Pumps 1A.1B.1C.2A.2B.2C.Jan-June 1980 "
  \* Commonwealth Edison Co 80/06/30 Sipp.
- G Inspection reports, IE Bulletins & correspondence
- 8009020109 Responds to IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME 8A-312. Type 304 Stainless Steel Pipe " 8A-312 pipe not present in operating plants Final confirmation from suppliers anticipated by 800915 re const plant piping sys NAUGHTON, H F Commonwealth Edison Go 80/08/07 2pp
- 8009180012 Forwards IE Insp Repts 50-295/80-15 & 50-304/80-15 on 800722 No noncompliance noted FIORELLI.O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/08/07 2pp

- --8009180021 IE Insp Repts 50-295/80-15 & 50-304/80-15 an 800722 No noncompitance noted Major areas inspected documentation for installation of spent fuel racks & containment hiner penetration welds

  DANIELSUN, D.H. Region 3, Chicago, Reactor Construction & Engineering Support Branch KEY, N.J. Region 3, Chicago, Office of the Director 80/08/05 App
- 8009030231 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Mercury-Retted Matrix Relays in Reactor Protective Sys of Operating Auctear Power Plants Designed by C-E ' Written response required KEPPLER, J G Region 3, Chicago. Office of the Director 80/08/15 in
- 8009110545 Responds to IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds," supplementing 800709 response Corrects Zion response re rings used for field circumterential butt weld Reviews accuracy of other statements ABEL.J S Commonwealth Edison Co 80/08/15 4pp
- 8009160081 Submits supplementary response to 1E Bulletin 80-08. "Examination of Containment Liner Penetration Welds." correcting statement made in DL Peoples 800709 ltr Further review not necessary ABEL. J S Commonwealth Edison Co 80/08/15 4pp
- 8009030126 Forwards IE Insp Repts 50-275/80-18 & 50-304/80-18 on 800730 & 31 No noncompliance noted HIND, J A Region 3. Chicago, Safeguards Branch 80/08/18 2pp
- --8007030133 IE insp Repts 50-295/80-18 > 50-304/80-18 on 800730 & 31
  No noncompliance noted Major areas inspected physical
  security, physical barriers 3 previous insp findings Details
  withheld (ref 10CFR2 790)
  HIND, J A Region 3, Chicago, Safeguards Branch MADEDA, T J ,
  CHRISTOFFER, O Region 3, Chicago, Office of the Director
  80/08/14 10
- 8009290425 Forwards IE Insp Repts 50-275/80-16 % 50-304/80-16 on 800804-05 % notice of violation HEIBHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/08/18 2pp
- --8007270428 Natice of violation from insp on 800804-05 \* Region 3. Chicago, Office of the Director 80/08/15 ip
- --8009290436 IE Insp Repts 50-295/80-16 / 50-304/80-16 on 800804-05
  Noncompliance noted failure to follow licensed operator
  requalification training program
  KOHLER, J E , SCHULZ, R D , DAKER, K R Region 3, Chicago, Office of
  the Director 80/08/15 3pp
- 8009250338 Ack receipt of 800727 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/80-12 & 50-304/80-12 HEIBHMANR F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/08/20 1p
- --8009250344 Forwards response to NRC 800709 ltr re violations noted in IE Insp Repts 50-295/80-12 & 50-304/80-12 Carrective actions info tag has been placed on gauge indicating that tank is empty at reading of 6% Recalibr complete by 801231 NAUGHTON, W F Commonwealth Edison Co 80/07/29 3pp
- B0071B0551 Forwards IE Circular 80-18, "10CFR50 57 Safety Evaluations for Changes to Radwaste Treatment Bys " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director B0/08/22 in
- 8009230094 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6005 & K-DON 6006 Circuit Breakers " No written response required KEPPLER. J. G. Region 3, Chicago, Office of the Director 80/08/28
- 8009170411 Forwards response to IE Bulletin 80-15 re possible loss of emergency notification sys w/loss of affsite gawer Review revealed inoperability of Dresden sys Investigation being conducted Operating Order 26-80 changed JANACEK, R F Communwealth Edison Co 80/08/27 4pp
- 8009180466 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Identified relays are not used in facility No action required Twenty-four manhours expended on review RAUSCH-T J Commonwealth Edison Co 80/08/29 1p

- B009250504 Responds to NRC 791213 request for addl info in response to IE Bulletin 79-02. "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Expansion anchor test results show installation of anchors acceptable JAMECEK,R F Commonwealth Edison Co 80/09/05 17pp
- 8009240133 Forwards IE Circular 80~21, "Regulation of Refueling Crews" No written response required KEPPLER.J © Region 3, Chicago, Office of the Director 80/09/10 in
- 8009260656 Ack receipt of 800819 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/80-05 & 50-304/80-04 KEPPLER.J O Region 3. Chicago. Office of the Director 80/09/10
- --8007260658 Responds to NRC 800727 ltr re violations noted in IE Insp Repts 30-275/80-05 & 50-304/80-04 Corrective actions mgt & mgt support of health physics program reviewed & changed to implement regulations REED,C Commonwealth Edison Co 80/08/19. 10pp
- 8009300200 Forwards response to IE Bulletin 80-20 No Westinghouse Type W-2 control switches are used in safety-related sys at Dresden Ouad Cities & LaSalle County Responses for Zion & Byron are encl RAUSCHI J Commonwealth Edison Co 80/09/15 6pp
- R Periodic operating reports & related correspondence
- 8009030441 Forwards semiannual rept of radioactive effluent discharges t solid raduaste for Jan-June 1980 ORAFSSER.K.L. Commonwealth Edison Co. 80/08/07 1p
- --8009030444 Semiannual rept of radioactive effluent discharges & solid radwaste for Jan-June 1980 \*\* Commonwealth Edison Co 80/08/07 35pp
- 8007070274 Forwards monthly operating repts for Aug 1780 GRAFESER.K L. Commonwealth Edison Co. 80/07/05 lp
- ---8009090298 Monthly operating rept for Aug 1980 GOOK,J Is Commonwealth Edison Co 80/09/05 lipp
- 8 Reportable occurrences: LERs & related correspondence
- 8009020276 Forwards LER 80-007/01T-0 GRAEBSER, K L Commonwealth Edison Co 80/08/19 lp
- ---8007020279 LER 80-007/01T-0 on 800803.white performing containment isolation phase A final actuating relay continuity check, isolation valve seal water sys partially actuated.Caused by sloppy test switch Madel 40703-000R-C Switch to be replaced MADDEW.J J Commonwealth Edison Co 80/08/15 2pp
- 8009160293 Forwards LER 80-005/03L-0 GRAESSER, K L Commonwealth Edison Co 80/09/05 ip
- --8009160305 LER 80-005/03L-0 on 800805.NIS channel 41 declared inoperable due to large incore/excore difference Channel 43 out of syc for maint Plant operated w/min redundancy degree yiolated Cause Uniform Channel 43 returned & 41 removed NEALE.J B Commonwealth Edison Co 80/09/05 19
- BO09220274 Forwards LER 80-021/03L-0 GRAESSER,K L. Commonwealth Edison Co 80/09/11 ip
- --8009220278 LER 80-021/03L-0 on 800726, steam generator 2A steam flow channel 2F-512 failed to start indicating prior to placing unit on sys grid Caused by low output from square root Extractor 2FM-512B(Hagan Model 127-112) JENKINS.R A Commonwealth Edison Co 80/09/li 1p
- 8009230691 Forwards LER 80-003/03L-0 GRAFSSER, X L Commonwealth Edison Co 80/09/15 to
- --8007230704 LER 80-003/03L-0 on 800816.MSIV low pressure annunciator alarmed & cil pump would not run Caused by failed control power transformer Transformer replaced PRINTE, T A Commonwealth Edison Co 80/09/15 ip

- V Operator Examinations
- B009300287 Forwards preliminary topical outlines of proposed modules on thermal hydraulics & core damage mitigation to be included in revised reactor operator training program per 800328 request NAU9HTON.N F Commonwealth Edison Co 80/09/15 7pp
- DOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT
- F Security, medical, emergency & fire protection plans
- 800923031B Requests that all personnel be reminded of purpose of amergency notification sys & health physics network Sys installed for govt use during emergency KEPPLER. J O Region 3. Chicago, Office of the Director 80/09/22
- 8009180543 Requests interview & visit to facility to discuss security practices & to collect data for study of people-related problems in nuclear safeguards VARGA.S A Operating Reactors Branch 1 80/09/05 2pp
- 8009290173 Forwards security guard training & qualification manual Encl withheld (ref 10CFR2 790) MATHEMS, E. R. Wisconsin Public Service Corp. 80/09/24 2pp
- Q Adjudicatory correspondence
- 8009230120 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 VARGA.S A Operating Reactors Branch 1 80/08/29 2pp
- --8009230134 Order for mod of License DPR-43 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment info should be submitted by 801101
  EISENKUT, D G Division of Licensing 80/08/29 6pp
- P Operating license stage documents & correspondence
- 8009020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants,per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT,D Q Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREC-0676. "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0676 encl W/o NUREC EISENBUT.D & Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TM1-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT. D @ Division of Licensing 80/08/07 60pp
- B009100196 Forwards request for add1 info re loss of offsite power events VAR9A.S A Operating Reactors Branch 1 80/08/14 3pp
- BO09190794 Forwards revised Westinghouse BTS 3 9 8 2,3 9 10 & Bases 3/4 9 8 & 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NOVAKIT M Assistant Director for Operating Reactors BO/08/15 1p
- --8009190817 Revised Westinghouse STS 3 9 8 2.3 9 10 & Bases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods

  \* Assistant Director for Operating Reactors 80/06/23 21pp
- 8009100125 Forwards request for addl info re requirements for auxiliary feedwater sys Requests response within 45 days VARGA.S A Operating Reactors Branck 1 80/08/18 9pp.
- BOO9100064 Forwards request for add1 info re adequacy of station electric distribution sys voltages
  VARGA,S A Operating Reactors Branch 1 BO/OB/21 4pp

- 8009:20511 Requests submittal of Tech Specs defining operability for safety sys Requests submittal within 15 days VARCA: S.A. Operating Reactors Branch 1 80/08/22 2pp
- 8009090355 Forwards "Reactor Containment Bldg Integrated Leak Rate Test - 1980 "
  MATHENS, E. R. Wisconsin Public Service Corp. 80/09/04 ip
- --8007090358 "Reactor Containment Bldg Integrated Leak Rate Test 1980 "

  \* Wisconsin Public Service Corp \* Wisconsin Power & Light Co

  \* Madison Gas & Electric Co 80/06/30 33pp
- 8009180504 Forwards request for addl info re degraded grid voltage protection VAROA.S A. Operating Reactors Branch 1 80/09/05 4pp
- 8009110378 Application for Amend 42 to License DPR-43, revising Tech Specs, Section 6 re administrative controls to reflect reorganization of Nuclear Dept Fee encl MATHEWS E R Wisconsin Public Service Corp 80/09/08 2pp
- --8009110381 Proposed Tech Specs, Section 6 re administrative controls, reflecting reorganization of Nuclear Dept + Misconsin Public Service Corp 80/09/08 10pp
- G Inspection reports, IE Bulletine & correspondence
- 8909030323 Forwards IE Insp Rept 50-305/80-14 on 800610 & 30 No nortcongliance noted nortcongliance noted DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/07/14 2pp
- --8009030326 IE Insp Rept 50-305/80-14 on 800610 & 30 No noncompliance 009030325 to Insp Rept 50-305/80-14 on BUOSIO & 30 No moncor noted Major areas inspected confirmatory measurements including telephone discussion & closeout of results of previous sample collection & submission of spiked samples JANUSKA, 4 G . E8810, T H Region 3. Chicago, Office of the Director 80/07/15 4pp
- 8009160610 Forwards IE Insp Rept 50-305/80-15 on 800602-06,09-10,16-20, 23-27 & 30 & notice of violation HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/07/28 2pp
- ~-8009140A14 Notice of violation from insp on 800602-06.09-10.16-20.23-27
  - Region 3, Chicago, Office of the Director 80/07/24 1p
- --8009160616 IE Insp Rept 50-305/80-15 on 800602-06,07-10,16-20,23-27 & 30 Noncompliance noted failure to develop required maint procedure for repairs to residual heat removal pump HARNICK,R F. CHOULES,N C. TAMBLING,T N Region 3. Chicago, Office of the Director 80/07/24 App
- 8009030223 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required, REPPLER, J G Region 3, Chicago, Office of the Director 80/08/15
- 8009150462 Ack receipt of 800801 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-305/80-13 Forwards comments re Items 3 & 4, Comments withheld Region 3. Chicago: Safeguards Branch 80/08/21 2pp
- --8009150464 Responds to NRC ltr re violations noted in IE Insp Rept 50-305/80-13 Corrective actions withheld (ref 10CFR2 790) MATHENS, E.R. Wisconsin Public Service Corp 80/08/01 ip
- 8007180524 Forwards IE Circular 80-18, "10CFR50 87 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response KEPPLER. J & Region 3, Chicago, Office of the Director 80/08/22
- 8007230057 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bower( 480 Volt Type K-6005 & K-DON 6008 Circuit Breakers " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/08/28
- 8009260041 Clarifies 800713 response to IE Bulletin 79-18. "Audibility Problems Encountered on Evacuation of Personnel from High Moise Areas " Tests identified area where alarms were inaudible Design change to install speakers processed MATHEMS.E R Wisconsin Public Service Corp 80/09/04 ip

- 800926008t Responds to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E "No mercury-wetted relays in use or planned for use in sys Ten manhours expended MATHEWS:E R Wisconsin Public Service Corp 80/09/04 ip
- 8009240126 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required
  KEPPLER.J G Region 3. Chicago. Office of the Director 80/09/10
- R Periodic operating reports & related correspondence
- 900930506 Forwards "Semiannual Effluent Release Rept, Jan-June 1980" per Tech Spec 6 9 requirement MATHEMS E R Hisconsin Public Service Corp 80/08/29 ip
- ~-8009030512 "Seminannual Effluent Release Rept. Jan-June 1980 "

  → Wisconsin Public Service Corp 80/08/27 32pp
- 8009090273 Forwards monthly operating rept for Aug 1980 MATHEWS, E. R. Wisconsin Public Service Corp. 80/09/05 1p
- --8009090277 Monthly operating rept for Aug 1980 RUITER.G H Wisconsin Public Service Corp 80/09/01 5pp
- 8007300425 Advises of changes to effluent & waste disposal semiannual repts previously submitted for 1778 Changes should be made to Pages 1 0.2 0 & 3 0 as indicated Wasconsin Public Service Corp 80/09/25 1p MATHEWS E R
- S Reportable occurrences. LERs & related correspondence
- 8009240495 Forwards LER 80-031/03L-0 8 updated LER 80-029/01X-1 MATTHEWS, E R Wisconsin Public Service Corp 80/09/19 1p
- --8009240508 LER 80-031/03L-0 on 800822.during hot shutdown & startup after reactor trip caused by lightning strike, condensate water storage tank level wont below Tech Spec limit Caused by water usage coincident w/demineralizer regeneration SMOXER.C S Wisconsin Public Service Corp 80/09/19 1p
- --8007240901 Updated LER 80-027/01X-1 on 800715, w/facility at 100% power charcoal filter samples taken from Train II of spent fuel pit sweep ventilation sys failed to demonstrate 90% lodine removal efficiency Caused by natural degradation EMDKER, C S Wisconsin Public Service Corp 80/09/15 ip
- DOCKET 50-306 PRAIRIC ISLAND NUCLEAR STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8007240239 Forwards Health Physics Appraisal Repts 50-282/80-08 & 50-306/80-09 on 800809-15, notice of violation & significant appraisal findings KEPPLER.J G Region 3, Chicago, Office of the Director 80/08/12
- ---8009240246 Notice of violation from health physics appraisal on 800505-15
  - # Region 3, Chicago, Office of the Director 80/08/11 ip
- --8009240255 Health Physics Appraisal Repts 50-282/80-08 & 50-306/80-09 JUY240235 Health Physics Appraisal Repts 50-282/80-08 t 50-306/80-on 800505-13 Noncompliance noted inadequate radiation survey instrument use in high radiation area to inadequate offshift chemistry & radiation protection coverage FISHER.W.L. Region 3, Chicago, Fuel Facility & Materials Safety Branch GREGER, R. JANUSKA:A Q Region 3, Chicago, Office of the Director 80/08/11 30pp
- 800B2002B2 Forwards final draft of upgraded emergency plan, consisting of corporate nuclear & plant emergency plans Delay in submittal due to incorporation of new 10CFR50 rules MAYER.L. O. Northern States Power Co. 80/08/15 1p
- --8008200284 Final draft of upgraded emergency plan.commisting of corporate nuclear & plant emergency plans
  \* Northern States Power Co 80/08/15 225pp
- 8007230305 Requests that all personnel be reminded of purpose of emergency mobification sys & health physics network Sys installed for govt use during emergency KEPPLER. J G Region 3. Chicago, Office of the Director 80/08/22

- 8009020072 Forwards "Evacuation Time Estimates From Areas Near Prairie Island Muclear Generating Plant:" Revision ( MAYER.L D Northern States Power Co 80/08/25 1p
- --8007020076 "Evacuation Time Estimates From Areas Near Prairie Island Nuclear Generating Plant," Revision i • Northern States Power Co 80/08/31 18pp
- 8009100930 Transmits emergency planning info to be made available to public at LPDR in Minneapolis.MN W/o encl SOUDER, J L. Public Document Branch 80/09/04 1p
- 8009260016 Transmits emergency planning info to be made available to public at LPDR in Minneapolis, MN W/o encl SOUDER, J L Division of Rules and Records 80/09/11 1p

### Q Adjudicatory correspondence

- E009030726 Motion to hold proceedings in abeyance until 800923, when MN Pollution Control Agency will act on settlement Settlement, if adopted, would result in withdrawal of hearing request SENECHALM E. GLSON, J.F., EPANNAUS, W. Minnesota, Btate of 80/08/28 3cm
- --8009030728 Affidavit stating that proposed settlement will be placed on next MM Pollution Control Agency monthly meeting agenda or considered at special meeting for affirmative majority vote of board members

  GRIEMHURST. L. J. Minnesota, State of 80/08/28 2pp
- 8009190295 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 CLARK.R A Operating Reactors Branch 3 80/08/27 2pg
- --B009190304 Order for mod of Licenses DPR-42 & DPR-60 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by B01101 EISENHUT.D O Division of Licensing E0/08/29 App
- 8009100429 Response in apposition to State of MN 800988 motion to hold spent fuel pool mod proceeding in abeyance pending MN Pollution Control Agency Board 800923 meeting Accepting settlement during meeting very remote H/Certificate of Svc SILBERG.JE. SERNSTEIN.D.C. Northern States Power Co. SILBERG.JE. Ghaw. Pittman. Potts & Trowbridge. 80/09/04. 7pp
- BOO9110023 Response in support of State of MV motion to defer ASLB action until 800923 Settlement if accepted during MN Pollution Control Agency 800923 meeting would obviate proceeding Certificate of Svc encl BARTIS C A Hearing Branch 3 80/09/08 2pp
- 8009230625 Memorandum & order granting MN Pollution Control Agency 800828 motion in which deferral of action was requested pending Agency Board 800923 meeting Petitioner shall file reply to util objections by 801001 if settlement rejected LAZD:R M Atomic Safety and Licensing Board Panel 80/09/18 3pp
- 8009300039 Joint motion to terminate proceeding re CL amend application for spent fuel pool storage expansion Agreement incorporating certain language in OL amend has been reached between parties Contentions withdrawn SILBERO, J E Northern States Power Co OLSON, J F Minnesota, State of BARTH, C Hearing Branch 3 80/09/23 3pp
- P Operating license stage documents & correspondence
- 8009020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 70 days EISENHUT, D Q Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 enci H/o NUREO EISENHUT,D O Division of Licensing 80/08/01 119pp
- 8007230052 Informs that exemption from fee re licensing action associated w/FMI-2 Lessons Learned is unjustified. Previous determination should be disregarded Requested submittal should include proposed class of amend FISENHUT, D Q Division of Licensing 80/08/07 60pp

- 8009190794 Forwards revised Westinghouse STS 3 9 8 2.3 9 10 % Bases 3/4 9 8 % 3/4 7 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NDVAK.T M Assistant Director for Operating Reactors 80/08/15
- --B009190817 Revised Westinghouse BTS 3 9 8 2.3 9 10 & Bases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods

  \* Assistant Director for Operating Reactors 80/06/23 21pp
- 8009190745 Discusses review of util 800611 response to NRC 800507 ltr identifying five new TMI-2 requirements Review based on HR Danton 8000289 ltr re qualifications of reactor operators Item (I) A la does not satisfy criteria CQLLINS,P F Operator Licensing Branch 80/08/25 2pp
- B009170082 Forwards Amends 42 % 36 to Licenses DPR-42 & DPR-60, respectively.EIA & notice of issuance & availability CLARK, R A Operating Reactors Branch 3 80/08/27 3pp
- --8009170089 Amends 42 & 36 to Licenses DPR-42 & DPR-60, respectively, changing Tech Specs, App B, to permit addition of chlorination program for circulating water sys in order to destroy parasitic amoeba in sys CLARK, R A Operating Reactors Branch 3 80/08/27 App
- --8009170087 EIA supporting Amends 42 & 36 to Licenses DPR-42 & DPR-60, respectively # Office of Nuclear Reactor Regulation, Director 80/08/27 4pp
- --8009170092 Notice of issuance & availability of Amends 42 & 36 to Licenses DPR-42 & DPR-60, respectively \* Operating Reactors Branch 3 80/08/27 1p
- 8009290421 Advises that 791109 response acceptable re ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture No further action necessary CLARK, R A Operating Reactors Branch 3 80/09/10 2pp
- 8009170341 Submits further response to NRC 800803 inquiries re proposed fuel surveillance program for refueling outage Fabrication methods used for gadolinia-bearing rods were typical of production-type fuel MAYER.L O Northern States Power Co 80/09/12 3pp.
- B009190481 Notifies of delay until B01114 for submittal of proposed Tach Specs for Lessons Learned Category A requirements, requested by NRC B00902 ltr MAYER, L D Northern States Power Co 80/09/12 2pp
- 8009300334 Forwards JC Lehr 800826 memo documenting EIA re 800826 issuance of Amends 42 & 36 to Licenses DPR-42 & DPR-60, respectively MARTIN.R. Operating Reactors Branch 3 80/09/12 ip
- --8009300340 Forwards compilation of telcons re 800821 license amend request Correspondence w/MN Poliution Control Agency & MN Bept of Matl Resources encl. LEHR, J C Assistant Director for Environmental Technology 80/08/24 7pp
- 8009250244 Submits supplemental info to 800506 request for amend to Licenses DPR-42 & DPR-60 re SI actuation & power distribution limits Lists detailed responses to NRC questions MAYER, L. O. Northern States Power Co. 80/09/19 3pp
- G Inspection reports, IE Bulletins & correspondence
- 8009150074 Advises that response to Item 4 of IE Bulletin 79-17. Revision 1.was satisfactorily completed on Unit 1 in Jul 1980 No corrective actions necessary QLUBERTS.D E Northern States Power Co 80/08/14 ip
- 8009130218 Responds to IE Bulletin 80-19 rs failure of mercury-wetted matrix relays No relays of type described are used in reactor protection sys at facility OllBERTS, DE Northern States Power Co 80/08/14 ip.
- 8009260263 Forwards IE Insp Repts 50-282/80-13 & 50-306/80-13 on 800601-0731 No noncompliance noted HEISHMAN,R F Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 80/08/14 2pp

- --B009260271 IE Insp Repts 50-282/80-13 \$ 50-306/80-13 on 800601-0731 No noncompliance noted Major areas inspected operation, maint surveillance security & radiation protection FEIERABEND. C D. BURGES, B L. LITTLE, W S Region 3. Chicago, Office of the Director 80/08/11 Gpp
- 8009030210 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required REPPLER, J G Region 3, Chicago, Office of the Director 80/08/15 in
- 8309310539 Responds to IE Bulletin 80-18, "Possible Disconnect Mode 4 Automation Industries. Inc Model 200-008 Sealed Source & Pighail Assembly " High injection pumps assured min cacling GILBERTS, D E Northern States Power Co 80/08/15 ip
- 6009090019 Submits addi response to IE Bulletin 80-08. "Exam of Cantainment Liner Penetration Welds " Facility does have containment penetration connections of type described facility was built to ANSI B31 I.1967 Summary rept encl GILBERTS, D.E. Northern States Power Co. 80/08/21 19pp
- 8009170433 Forwards IE Circular 80-18. "10CFRSO 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required, KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/08/22
- KEPPLER, J G. Region 3, Chicago, Office of the Director 80/08/22 1p
- BOG9170405 Responds to IE Bulletin 80~15 re possible loss of emergency notification sys w/loss of offsite power New sys will be installed in Oct 1980 Test will be conducted upon completion of power supply sys Notification made on 800625 GILBERTS, D.E. Northern States Power Co. 80/08/28 2pp
- BOG9230064 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boyeri 480 Volt Type K-600S & K-DDN 600S Circuit Breakers "
  No written response required KEPFLER. J. G. Region 3. Chicago, Office of the Director 80/08/28 18
- 8009100500 Forwards Revision 5 to "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ASME Code Section XI Requirements"

  \*\*KAYERL O Northern States Power Co 80/07/03 2pp
- --8009100505 Revision 5 to "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ABME Code Section XI Requirements " \* Northern States Power Co 80/09/03 10pp
- BC09240i12 Forwards IE Circular 80-21. 'Regulation of Refueling Crews "
  No written response required
  PEPPLER.J 0 Region 3. Chicago. Office of the Director 80/09/10
- A Periodic operating reports & related correspondence
- BO09090277 Forwards "Effluent & Waste Disposal Semiannual Rept for Jan-June 1980 " MAYER: L O Northern States Power Co 80/08/28 ip
- --8009070302 "Effluent & Waste Disposal Semiannual Rept for Jan-June 1920 " \* Northern States Power Co 80/08/28 9pp
- 8009160279 Forwards monthly operating repts for Aug 1780 MAYER.L O Northern States Power Co 80/09/08 ip
- --8009160282 Monthly operating repts for Aug 1980 HUMSTAD A A Northern States Power Co 80/09/01 Spp
- S Reportable occurrences, LERs & related correspondence
- 8009080395 Forwards LER 80-022/03L-0 MAYER, L 0 Northern States Power Co 80/09/02 ip.
- --8009080401 LER 80-022/03L-0 on 800805 during surveillance test, fan-coil unit dome damper 23 could not be positioned properly Caused by leating air supply line to damper actuator Air supply line replaced HUNSTAD. A A Northern States Power Co 80/09/02 ip
- 8009300551 Forwards updated LER 80-025/01T-1
  MAYER: L D Northern States Power Co 80/09/25 19

- --8009390558 Updated LER 80-025/01T-1 on 800904.uitrasonic examination of steam generator support bolts revealed that most had crack indications Preliminary cause suggests environmentally assisted cracking | HNNSTAB. A A Northern States Power CO 80/09/25 10
- 8009300573 Environ Event Rept 80-03 on 800820, during special chlorination program, certain levels of chlorine found outside circulating water sys that exceeded concentration limits in Tech Specs 2 4 1 MARD.P C Northern States Power Co 80/09/25 4pp
- DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT

  F Security, medical, emergency & fire protection plans
- 8009230178 Requests that all personnel be reminded of purpose of emergency notification sys 5 health physics network Sys installed for govt use during emergency ORIER BH Region 1. Philadelphia, Office of the Director 80/08/22 3pp
- 8009170345 Requests assistance of B Grimes &/or T McKenna to meet w/ state nuclear advisory committee re emergency response plan during Oct 1980 BRENKAN.JE Maine, State of 80/09/09 2pp
- O Adjudicatory correspondence
- 8009020417 Order granting extension until 800905 for Commission to review ALAB-602 re spent fuel pool compaction CHILK-S J Office of the Secretary of the Commission 80/08/28 in
- 8009260602 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by B01101 CLARK,R A Operating Reactors Branch 3 80/08/29 2pp
- ---8009260607 Order for mod of License DPR-36 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 80:101

  EISENHUT, D 0 Division of Licensing 80/08/29 opp
- H General correspondence
- 8008120480 Requests info on status of Task A-2. Asymmetric Blowdown Loads on Reactor Primary Coolant Sys Also requests status of problem at ME Yankee
  GARRETTLE Q Affiliation Unknown 80/06/07 lp
- B008:20525 Requests info re status of Task A-17 Also requests info re whether problem has been completely resolved at facility GARREIT.E & Affiliation Unknown 80/06/07 ip
- BOOB120534 Requests info on current status of Task A-40, "Seismic Design Criteria" Also requests knowing if problem at facility has been completely resolved GARRETTIE O Affiliation Unknown 80/06/07 ip
- 800B120549 Requests info on current status of Task A-ii. "Reactor Vessel Hatls Toughness " Also requests to be informed if problem at facility has been completely resolved GARRCITIE G Affiliation Unknown 80/06/07 ip
- 8008120555 Requests info on status of Task A-1. Water Hammer: & resolution of problem at facility.

  GARRETT.E G Affiliation Unknown 80/06/07 1p
- 8008120548 Ack receipt of 800724 teleon advising that task managers responses to inquiry re generic safety issues would be consolidated into single response Lists three questions applicable to plant Requests response prior to 800815 GARRETT, E. G. Affiliation Unknown 80/07/30 ip
- 800922006<sup>7</sup> Responds to 800730 & 800607 ltrs re Task Action Plans A-1, A-2, A-11, A-17 & A-40 which may concern facility NUREO-0649.
  "Task Action Plans for Unresolved Safety Issues Re Nuclear Power Plants," provides details of each task action NDVAK.T M Assistant Director for Operating Reactors 80/08/19 40b
- 8009240137 Responds to 800609 ltr to President Carter expressing concerns re lack of evacuation plan & potential increase in spent fuel storage at facility NRC & FEMA are conducting emergency preparedness plan review EISENHUT, D G Division of Licensing 80/09/02 7pp

- 8009240093 Responds to 800703 ltr requesting lists of required improvements to assure that every reactor is safe Reactors operated b/concept of providing minimal risk to health 5 safety of public NGVAKLT M Assistant Director for Operating Reactors E0/09/04 350
- P Operating license stage documents & correspondence
- 8009020297 Submits interim criteria for shift staffing to all QL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISERHUT, D @ Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 enc! 4/o NUREG EISENHUT, D 0 Division of Licensing 80/08/01 11900
- 8009230052 Informs that exemption from fee re licensing action associated m/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISEKHUT, D G Division of Licensing 80/08/07 60pp
- 8009170264 Forwards Amend 49 to License DPR-36.safety evaluation & notice of issuance & availability
  CLARK.R A Deperating Reactors Branch 3 80/08/14 2pp
- --8009170267 Amend 49 to License DPR-36, revising Tech Spec Figure 3 10-3 which specifies excore monitor symmetric offset alarm band for LOCA limiting conditions
  CLARK,R A Operating Reactors Branch 3 89/08/14 4pp
- ---8009170270 Safety evaluation supporting Amend 49 to License DPR-36
  \* Office of Nuclear Reactor Regulation, Director 80/09/14 2pp
- --8009170273 Notice of issuance & availability of Amend 49 to License DPR-34 ENGLE, B. Operating Reactors Branch 3 80/08/14 2pp
- 8009110696 Advises that 800520 application submitted as Proposed Change 76 requires Class II fee Requests that fee be remitted promptly MILLER.W.O. License Fee Management Granch 80/08/19 1p
- 8009100425 Forwards payment of license amend fees per NRC determination of options expressed in Footnote 2 to 100FR170 22 Fee submitted under protest because proposed change consisted of NRC prescribed clarification GROCE, R H Maine Yankee Atomic Power Co 80/09/03 3pp
- 8009260197 Advises that util response re ECCS evaluation models, dealing w/fuel cladding swelling & incidence of rupture, is acceptable CLARK, R A Operating Reactors Branch 3 80/09/10 2pp.
- 8009170343 Forwards proposed Tech Spec Change 78 to App A of OL.per NRC B00702 ltr to all PHR licensees Also requests amend to implement program to reduce leakage from sys outside containment & to determine airborne rodine concentrations JOHNSON, W.P. Maine Yankee Atomic Power Co. 80/09/11 App
- --8009170347 Proposed Tech Spec Change 78 revising Tech Spec Pages 3 3-1. 3 3-2.3 3-3.3 9-1.3 9-2.4 1-11.4 1-12.4 2-5 & adding new Yable 3 9-3.Page 3 9-5 changes incorporate addl TMI-2 Lessons Learned Category A requirements \* Maine Yankee Atomic Power Co 80/09/11 9pp
- 8009230594 Forwards revised operational QA program reflecting organizational changes Revised QA program supersedes QA program submitted w/800709 ltr
  THUPLOWER W Maine Yankee Atomic Power Co 80/09/17 lp
- ---8009230591 Operational GA program
  LAMFON,R R . FRIZZLE,C D . BANDAZZA,J B Maine Yankee Atomic Power
  Co 80/09/10 68pp
- O Inspection reports, IE Bulletins & correspondence
- 8007080541 Forwards response to IE Bulletin 80-15 re potential misapplication of Rosemount pressure transmitters No corrective action required MOODY. D.E. Maine Yankee Atomic Power Co. 80/07/29 3pp

- 8009120275 Provides further details & justification for components which do not remain in emergency mode upon reset of engineered safety feature signal,per IE Bulletin 80-06 Circuits for Items 18,19 & 20 will not be modified MODDY,D E Maine Yankee Atomic Power Co 80/07/29 4pp
- 8009080528 Responds to IE Bulletin 79-03A Util determined in all cases pipe wall thickness is based on use of 85% of code allowable MoDDY, D E Mains Yankee Atomic Power Co 80/07/30 is
- 8009120207 Responds to IE Bulletin 79-21 re erroneous level indications during accidents due to increase in temp Correction curves for steam generator & pressurizer level instruments developed Application of curves will be completed by 800901 MOODY.D E Maine Yankee Atomic Power Co 80/08/05 2pp
- 8009030095 Forwards Revision 1 to IE Bulletin 80-17, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required ORIER,B H Region 1, Philadelphia, Office of the Director 80/08/15 ip
- 8009180015 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required. GRIER.B H Region 1, Philadelphia, Office of the Director RO/08/22 1p
- 8009120186 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers" No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/08/27. 1p
- 8009090431 Responds to IE Builetin 80~15, "Possible Loss of Emergency Notification Sys W/Loss of Offsite Power " Direct insprevealed that emergency notification sys was powered from non-vital lighting circuit powered from onsite power.

  JDHNSON, W P Maine Yankes Atomic Power Co 80/08/28 2pp
- 8007240030 Forwards IE Circular 80-21, "Regulation of Refueling Craws "
  No written response required
  CRIER.B H Region 1. Philadelphia, Office of the Director
  80/07/10 ip
- 8009240342 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matis " No written response required GRIER, B H Region i, Philadelphia, Office of the Director 80/09/12 ip
- R Periodic operating reports 5 related correspondence
- 8009090468 Forwards "Effluent & Waste Disposal Semiannual Rept.Jan-Jure 1980" GROCE.R H Maine Yankee Atomic Power Co 80/08/29 ip
- --8009090477 "Effluent & Waste Disposal Semiannual Rept.Jan-June 1980" \* Maine Yankee Atomic Power Co 80/08/29 9pp
- 8009160257 Forwards monthly operating rept for Aug 1980 MODDY, D E Maine Yankee Atomic Power Co 80/09/ii 1p
- --8007160257 Monthly operating rept for Aug 1780
  BEERS,F C Maine Yankee Atomic Power Co 80/09/11 5pp
- 8007230455 Forwards util annual rept re average bay temps for Junt-A-; 1780 at miring zone buogs, submitted to ME Dept of Environ Protection Rept provided per util 800307 commitment OARRITY, J H Maine Yankee Atomic Power Co 80/09/12 3pp
- 8009300426 Forwards Aug 1980 discharge monitoring rept submitted to K Dept of Environ Protection GARRITY, J.H. Mains Yankee Atomic Power Co. 80/09/25 1p
- --8009300430 "Discharge Munitoring Rept. Aug 1980 "
  FLANDERS. W L Maine Yankee Atomic Power Co 80/09/25 5pp
- S Reportable occurrences, LERs & related correspondence
- 8007300600 PNC-1-80-127 on 800714.plant was shutdown when one of three seals failed on three reactor coolant pump Shutdown expected to last until 800918 LAZARUS,N J , MARTIN,T T , BRUNNER,E J, Region 1, Philadelphia, Office of the Director 80/07/15 1p

- 8009240637 Ferwards LER 80-017/03L-0 W00D.E C Maine Yankee Atomic Power Co 80/09/19 1p
- --B009260642 LER 80-017/03L-0 on B00822, boron sample taken at completion of addition to RWSY indicated concentration below Tech Spec limit Caused by failure of technician to obtain sufficient sample prior to addition BRINKLER, J E Maine Yankee Atomic Power Co 80/09/19 2pp
- 8009260494 Forwards LER 80-018/03L-0 WGOD, E C Maine Yankee Atomic Power Co 80/09/22 1p
- --8009260503 LER 80-018/OSL-0 on 800826.during steady state power operation, w/diesel generator.D0-18.being operated in surveillance mode.D0-18 auto tripped on overspeed Caused by loose overspeed trip switch actuating arm Arm tightened BRINKLER.JE Mains Yankee Atomic Power Co. 80/09/22 2pp
- DOCKET 50-311 BALEM NUCLEAR GENERATING STATION, UNIT 2 E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8009180170 Forwards Operator Licensing Branch input to SER for full power operation MGGRE.V.A Division of Human Factors Safety 80/09/11 13cc
- F Security, medical, emergency & fire protection plans
- 8008280311 Forwards add1 info re NUREG-0494 fire protection requirements that will not be met.as identified in util 800808 % 19 ltrs Add1 justification in support of implementation schedule & oversized drawings encl MITTL.R L Public Service Electric & Gas Co of New Jersey 80/08/22 12pp
- --8007040374 "Containment Sump Level Transmitter, Installation Detail "
  Drawing Number 237086-8-7637-1R-IEC-0549-C2/0

  \* Public Service Electric & Gas Co of New Jersey 60/06/24 ip
- ---8009040375 "Auxiliary Bldg.Reactor Containment & Fuel Handling Area. Elevation 100 Ft " Bheet 1 of 1 \* Public Service Electric & Oas Co of New Jersey 78/09/01 1p
- -8009040378 "Auxiliary Bldg.Elevation 84 Ft.Reactor Containment 78 Ft & 81 Ft & Fuel Handling Area Elevation 85 Ft & 89 Ft 6 Inches " Sheet I of i # Public Service Electric & Gas Co of New Jersey 78/09/05 ip
- --B009040379 "Auxiliary Bldg & Reactor Containment Elevation 64 Ft "
- Public Bervice Electric & Gas Co of New Jersey 78/08/31 1p
- ---8009040381 "Auxiliary Bldg & Reactor Containment Elevation 45 Ft & 55 Ft " Sheet 1 of 1 
  \* Public Service Electric & Gas Co of New Jersey 78/08/31 1p
- ---8009040384 "Auxiliary Bldg & Reactor Containment Section A-A " Sheet 1
  - \* Public Service Electric & Gas Co of New Jersey 77/01/26 1p
- --8009040385 "Auxiliary Bldg & Reactor Containment. Sections N-D & C-C "
- Sheet 1 of 1 \* Public Service Electric & Gas Co of New Jersey 76/12/29 1p
- ---8009040388 "Reactor Containment Slab at Elevation 78 Ft & Elevation 81 Ft " Sheet 1 of 5

  \* Public Service Electric & Gas Co of New Jersey 75/06/23 1p.
- --8009040392 "Reactor Containment Slab at Elevation 78 Ft & 81 Ft. Sections " Sheet 4 of 5 \* Public Service Electric & Oas Co of New Jersey 70/12/01 ip
- --8009040394 "Reactor Containment Internal Walls & Reactor Foundation Plan Elevation 90 Ft " Sheet 1 of 15 Public Service Electric & Gas Co of New Jersey 71/07/06 19
- ---8039040396 "Reactor Containment Internal Walls & Reactor Foundation Plan Elevation 94 Ft." as-built Sheet 2 of 15 \* Public Service Electric & Gas Co of New Jersey 76/03/23 1p
- ---8009040398 "Reactor Containment Internal Walls & Reactor Foundation Plan Elevation 104 Ft " Sheet 3 of 15 \* Public Service Electric & Gas Co of New Jersey 74/08/08 1p

- --8009040379 "Reactor Containment Internal Walls & Reactor Foundation, Sections," as-built Sheet & of 15 4 Public Service Electric & Gas Co of New Jersey 76/03/23 1p
- --8007040402 "Reactor Containment Internal Walls & Reactor Foundation, Sections " Sheet 5 of 15 \* Public Service Electric & Gas Co. of New Jersey 75/06/24 ip
- --8009040403 "Reactor Containment, Reactor Pit" Sheet 1 of 2

  \* Public Service Electric & Gas Co of New Jersey 76/01/20 1p
- ---8009040405 "Reactor Containment,Reactor Pit," as-built Sheet 2 of 2 \* Public Service Electric δ Gas Co of New Jersey 74/01/29 [
- ---B009040407 "Reactor Containment Internal Walls & Reactor Foundation, Sections " Sheet 7 of 15 \* Public Bervice Electric & Gas Co of New Jersey 71/03/10 ip
- --8007040408 "Reactor Containment Internal Walls & Reactor Foundation, Reinforcement Plans & Sections," as-built Sheet 13 of 15 \* Public Service Electric & Gas Co of New Jorsey 76/03/22 1p
- --8007040410 "Reactor Containment Internal Walls & Reactor Foundation. Reinforcement Plans & Sections " Sheet 14 of 15 \* Public Service Electric & Gas Co or New Jersey 74/03/06 ip
- --8009040411 "Reactor Containment Drain Trench Elevation 81 Ft & 78 Ft Sump Pit Elevation 54 Ft & Inches > 72 Ft 7 Inches " Sheet
  1 of 1
  - \* Public Service Electric & Gas Co. of New Jersey 77/08/08 1p
- 8009230193 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Bys installed for govt use during emergency GRIER, B H Region 1. Philadelphia, Office or the Director 80/08/22 Spp
- 8009190213 Forwards revised implementation schedule for fire protection mods MITTL.R L Public Service Electric & Gas Co of New Jersey 80/09/04 3pp
- J Insurance & indemnity information
- 8009260460 Forwards Endorsement 2 to MAELU Policy XB-72 CORREA, M A Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc Div 80/09/19 3pp
- P Operating license stage documents & correspondence
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria fo Emergency Response Facilities "Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl W/o KUREG EISENHUT, D 0 Division of Licensing 80/08/01 119pp
- 8009110560 Responds to 800527 ltr re withdrawal of 800514 application for Tech Specs changes Controller will refund fee since application review not started MILLER, N O License Fee Hanagement Branch 80/08/12 lpp
- B009110725 Natification of 800819 meeting w/util concerning Tech Spec KERRIGAN, J. Operating Reactors Branch 3 80/08/19 3pp
- 8009150104 Forwards Amend 2 to License DPR-75, safety evaluation & DENION, H R Office of Nuclear Reactor Regulation, Director 80/08/22 3pp
- --- 8009150109 Amend 2 to License DPR-75 permitting special low power test program to be conducted

  DENTON, H R Office of Nuclear Reactor Regulation, Director
  80/08/22 7pp
- --8009150111 Safety evaluation supporting Amend 2 to License DPR-75
  \* Office of Nuclear Reactor Regulation, Director 80/08/22 25pp
- --8009150114 Notice of issuance & availability of Amend 2 to License SCHWENCER, A Licensing Branch 3 80/08/22 2pp

- 8009020237 Commits to installation of seismically & environmentally qualified valve position switches on two pressorizer power apprated relief valves following completion of low power testing program SCHNCIDER, F W Public Service Electric & Oas Co of New Jersey 2000005
- 800912010B Forwards request for add1 info re salt content of long-term auxiliary feeduater source.per full power license review IEDESCO.R L. Assistant Director for Licensing 80/08/26 3pp
- 6009120112 Forwards request for add1 info re post-accident iodine sampling & analysis sys & health physics organization.per full power license raview TEDESCO.R L. Assistant Director for Licensing 80/08/26 3pp
- 8009120501 Forwards request for add1 info re RCS vents.per full power license review TEDE900.R L. Assistant Director for Licensing 80/08/26 3pp
- BOO9190131 Forwards request for additinfoire auxiliary feedwater source to complete evaluation for full power license Util must show discussion presented in 800701 submittel is binding for compositions other than sodium chloride solutions YEDESCO.R L. Assistant Director for Licensing 80/08/26 3pp
- 8007040352 Advises that due to internal communications problems. 800328 ltr responding to TMI-2 Lessons Learned Section 2 ( 3a. erroneously advised that limit switches on power operated relief valves were soismically benvironmentally qualified MITTL, R L Public Service Electric b Cas Co of New Jersey 80/08/28 2pp
- 8007220050 Forwards request for add1 into re upgraded meteorological program turbine discs.containment boundary fracture toughness.cladding swelling & rupture models, relief & safety valve tost requirements & Q-List to TEDESCO.R L. Assistant Director for Licensing 80/08/29 11pp
- 8009050332 Submits response to NRC concerns re effects of dissolved solids other than sodium chloride on steam generators as source of auxiliary feedwater
  HITTLR L. Public Service Electric & Gas Co. of New Jersey
  80/09/03 4pp
- 9009090312 Forwards listing of each regulation in 10CFR20,50 & 100 & description of compliance in license application MITL,R L. Public Service Electric & Oas Co. of New Jersey 80/09/03 92pp
- 8007180469 Forwards supplemental ECCS calculations in response to NRC 800829 itr re NVREO-0630 MITL.R L. Public Service Clectric & Oas Co. of New Jersey 80/07/09 9pp
- BOOP190192 Provides responses to NAC BOOP29 request re relief & safety valvo test requirements Util will monitor EPRI program to provide assurance that it is applicable to plant design & qualify RCS relief & safety valves MITTL,R L. Public Service Electric & Gas Co. of New Jersey B0/09/05 2pp
- 8009190479 Forwards addl info re RCS vents.par NRC 900826 request MITTL,R L. Public Service Electric & Gas Co. of New Jersey 80/09/05 7pp
- 8009190515 Advises that Restinghouse reviewed facility emergency operating ? gower ascension procedures Util incorporated appropriate comments into procedures MITTLAR L. Public Service Electric & Gas Co. of New Jersey 80/09/05 1p
- BOO9140351 Forwards "Natural Carculation Tests" Detailed rept will be incorporated in startup rept following gover range testing MIDURA, H J. Public Service Electric & Gas Co. of New Jersey 80/09/08 1p
- 8009190527 Forwards updated Q-list in response to verbal request & superseding Q-list submitted by 800825 ltr MITTLR L Public Bervice Electric & Gas Co of New Jersey 90/09/08 59p

- 8009140401 Requests that util response to NRC 800702 ltr be delayed 90 days after formal issuance of Unit 2 Tech Specs Tach Spec amends per TMI Lessons Learned Category A requirements for Unit 1 will be implemented after issuance of Unit 2 OL LIBRIZZI.F P Public Service Electric & Gas Co of New Jersey 80/09/09 ip
- 8009180413 Provides supplemental info re facility compliance w/NRC regulations Facility complies w/regulations Util design & review process. GA program & independent review by NRC & ACRS assures protection of public health & safety MITLR L Public Service Electric & Gas Co of New Jersey BO/09/09 1p
- 8009\$90466 Forwards addl info re TMI Lessons Learnad requirements on primary coolant sources outside containment & noble gas. radioiodine & particulate effluent monitoring Liquid radwaste sys not used to cool core MITTLR L. Public Service Electric & Oas Co. of New Jersey 80/09/09 6pp
- BOO91B045B Advises that util will respond to requirements re MUREQ-0583 specified during NRC 80090B-09 audit by 800919 Info will include classification of use by safety significance of items previously identified in util 800825 submittal MITTLR L. Public Service Electric & Gas Co of New Jersey 80/09/11 2pp
- 8009190536 Forwards supplemental info re fracture toughness for containment bidg Unit 2:in response to NRC request during review of conformance w/General Design Criterion 51 MITTLER L Public Bervice Electric & Oas Co of New Jersey 80/09/11 22pp
- 8007300229 Requests addl info re review of facility for full power license Questions are encl re 800825 updated P-List. Item III D i i of NUREO-O674. "TMI-Related Requirements for New OLs" & 800808 & 22 submittals on affluent monitoring sys TEMESCO,R L. Assistant Director for Licensing 80/07/13 5pp
- 8009220266 Forwards add1 info to 800825 submittal re containment sump performance in response to NRC 800721 request Adequate guidance is provided to operators for monitoring ECCS Detailed insulation survey & drawings will be provided MITCLR L. Public Service Electric & Oas Co. of New Jersey 80/09/17 4pp
- 8009220280 Forwards addl info re equipment qualification, in response to NRC 800908-09 audit request MITTL.R L. Public Service Electric & Gas Co. of New Jersey 80/09/18 86pp
- 8009300513 Notifies that Tech Spec changes recommended by NRC 800815
  Its are being reviewed Changes will be incorporated upon
  issuance of full power OL Application for license amend will
  not be submitted
  LIBRIZZI, F P Public Service Electric & Gas Co of New Jersey
  80/09/22 1p
- 8009290361 Bubmits description of alternative proposal for providing assurance that inadvertent failure of suction valve from auxiliary feedwater storage tank will not result in degraded condition of auxiliary feedwater sys
  MITTLE L. Public Service Electric & Oas Co. of New Jersey
  80/09/23 Rpp
- B009300512 Ack receipt of 800826 ltr requesting add1 info re collection of loggerhead sea turtles & Kemp Ridley sea turtles Responses enci.
  LIBHIZILF P Public Sorvice Electric & Oas Co of New Jersey
  80/09/24 ip
- --8009300518 Forwards list of questions re specimens of Atlantic leggenhead turtle & Kemp Ridley sea turtle Response requested within 30 days of receipt of ltr VAROA:8 A Operating Reactors Branch 1 80/08/26 19pp
- G. Inspection reports. IE Bulletins & correspondence
- 8007080530 Responds to IE Bulletin 80-05 Per 800606 response, subsequent investigation revealed two addl tanks which could be subjected to conditions that might cause inward buckling SCHNEIDER, F. W. Public Service Electric & Gas Co. of New Jersey 80/07/29 10
- 8009090230 Forwards add1 response to IE Bulletin 79-27 re loss on nonclass IE instrumentation Evaluation of feasibility of design mods completed & results entl SCHNEIDER, F N Public Service Electric & Gas Co of New Jersey 80/07/31 9pp

- 8007030091 Forwards Revision 1 to IE Bulletin 80~19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C~E " Written Tasponse required ORIER, B H Region 1, Philadelphia, Office of the Director 80/08/15 1p
- 8009180042 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GRIER.8 H Region 1. Philadelphia, Office of the Director
- 8009120206 Forwards IE Info Notice 80-31. "Malaperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required GRIER, 8 H Region 1. Philadelphia, Office of the Director 80/08/27 ip
- BOG9110357 Forwards proprietary & nonproprietary responses to IE Info Notice 79-37, "Cracking in Low Pressure Turbine Discs " Toughness properties data includes fracture appearance transition temp & upper energy & temp MITTL.R L Public Service Electric & Gas Co of New Jersey BD/09/02 46pp
- 8009190396 Advises that 800702 response to IE Bulletin 80-11. "Masonry Wall Besign," for Unit 1 is applicable to Unit 2 Min 1 5 factor of safety was used in Item 3.based on prudent engineering judgment MITTL.R L Public Service Electric & Gas Co of New Jersey 80/09/05 1p
- 8009240045 Forwards IE Circular 80-21, "Regulation of Refueling Crews "
  No written response required
  Office, B H Region 1, Philadelphia, Office of the Director
  80/09/10 1p
- BOO9180455 Forwards updated response to IE Bulletin 79-07. "Seismic Stress Analysis of Safety-Related Piping "Encl includes summary of analysis & resultant mods Requirements of IE Bulletins 79-07 & 79-14 have been met MRTTL.R L Public Service Electric & Gas Go of New Jersey BO/09/ii 4pp
- BOD9240335 Forwards IE Info Notice 80-32. "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required GRIER, B K Region 1, Philadelphia, Office of the Director 89/09/12 1p
- R Periodic operating reports & related correspondence
- 8009090315 Forwards monthly operating rept for May 1980 MIDURA: H J. Public Service Electric & Gas Co of New Jersey 80/09/29 ip
- --8007090320 Monthly operating rept for May 1780 HILLER,L K. Public Service Electric & Oas Co. of New Jersey 80/08/29 3pp
- 8009180249 Forwards monthly operating rept for Aug 1980 M1DURA.H J. Public Service Electric & Gas Co of New Jersey B0/09/10 1p
- --9009180257 Monthly operating rept for Aug 1980 MILLER, L K Public Service Electric & Oas Co of New Jersey 80/09/10 5pp
- 5 Reportable occurrences, LERs & related correspondence
- BOO9110463 PNO-I-80-110 on 800725.IBEM union went on strike Unit 1 operations are continuing w/licensed supervisory personnel All phone lines at facility have been disabled BRICOSL., KEIMIO,R, BRUNNER,E J Region 1, Philadelphia, Office of the Director 80/07/25 ip
- 8009030585 Forwards LER 80-021/03L-0 LIBRIZZI.F P Public Service Electric & Gas Co. of New Jersey 80/08/28 2pp
- --8007030591 LER 80-021/03L-0 on 800729, during routing containment entry, latch for exterior would not close Caused by broken latch pin Pin repaired & door retested satisfactorily NECHAN,R J Public Service Electric & Gas Co of New Jersey 80/08/28 ip

- 8009030613 Forwards LER 80-020/03L-0 LIBRIZZI.F P Public Service Electric & Oas Co of New Jersey 80/08/28 2pp
- --8009030620 LER 80-020/03L-0 on 800729, during routine operation, pressurizer pressure channel 3 would not respond to pressure changes in sys Caused by shorted wire on power supply Power supply repaired Naturally R J Public Service Electric & Gas Co of New Jersey 80/08/28 ip
- 8009090447 Forwards LER 80-024/03L-0 LIBRIZZI.F P Public Service Electric & Gas Co of New Jersey 80/08/28 2pp
- --B009090455 LER 80-024/03L-0 on 800801, while withdrawing rods in preparation for entering Mode 2, position indicator read 20 steps lower than bank demand position Caused by equipment failure Individual rod position indicator replaced NrHMAN,R J Public Service Electric % Gas Co of New Jersey 80/08/28 1p
- 8009090542 Forwards LER 80-023/03L-0 LIBRIZZI,F P Public Service Electric & Gas Co of New Jorsey 80/08/28 2pp
- --8009090550 LER 80-023/02L-0 on 800731: chemical analysis of refueling water storage tank revealed boron concentration at 1980 ppm Caused by personnel error Action was taken to increase concentration above min of 2,000 ppm NEWMAN,R J Public Service Electric & Qas Co of New Jersey 80/08/28 1p
- 8009090554 Forwards LER 80-022/03L-0 LIBRIZZI.F P Public Service Electric & Gas Co of New Jersey 80/08/28 2pp
- ~-8009090558 LER 80-022/03L-0 on 800731, jacket water heater developed leak which caused jacket water heater for 2A diesel to trip Caused by equipment failure Heater replaced Design change issued for different type heater NHMAN,R J Public Service Electric & Oas Co of New Jersey 80/08/28 1p
- 8009090437 Forwards LER 80-025/01T-0 LIBRIZZI.F P Public Service Electric & Gas Co of New Jersey 80/09/04 2pp
- --B009090441 LER 80-025/01T-0 on B00B22, during review of equipment qualification records, limit switches for power operated relief valves were determined seismically \$ environmentally unqualified Caused by internal communication problem MURPHY. M J Public Service Electric & Oas Co of New Jersey B0/09/04 Ip
- 8009150264 Forwards LER 80-026/03L-0 LIBRIZZI,F P Public Service Electric & Gas Co of New Jersey 80/09/09 Zpp
- --8009150267 LER 80-026/03L-0 on 800811, during review of records, determined that reactor was taken critical w/o performing functional test on source range instruments Caused by personnel error MURTHY, M J Public Service Electric & Gas Co of New Jersey 80/09/09
- 8009140478 Forwards LER 80-027/03L-0 LIBRIZZI.F P Public Service Electric & Oas Co of New Jersey 80/09/11 2pp
- --B0091604B2 LER B0-027/03L-0 on 800B15, during routine operation, auxiliary feedwater storage tank fell below min 200,000 gallon level Caused by throttling inlet valve too far during makeup of steam generators Level restored HURPHYIM J Public Service Electric & Gas Co of New Jersey 80/09/11 1p
- --8009230694 LER 80-028/03L-0 on 800820, during surveillance, level in refueling water storage tank found to be below min level Caused by failed hose on temporary demineralizer Storage tank was refilled to greater than min level RANDQLPH, JM Public Service Electric & Gas Co of New Jersey 80/09/18 1p
- # Duke Power Co #0/09/25 2pp

- 8009120669 Refers to 800801 discussion w/J Zupko & 800804 telcon w/F Schneider re training & qualification for position of shift technical advisor Qualifications for position documented in Suppl 4 to facility SER GRIER.8 H Region 1. Philadelphia. Office of the Director
- 8009180306 Summary of 800805 meeting w/applicant in Bethesda.MD re operator exam results
  KERRIGAN, J Licensing Branch 3 80/08/21 App
- 8009110323 Notifies that all reactor operators & senior reactor operators received low power test program training Lists operators not trained because unet taken to Mode 5 operation on 800805 due to control rod drive mechanism vent leakage ECKERT.R M Public Service Electric & Gas Co of New Jersey 80/09/05 Ip
- 8009160393 Reconfirms intentions to provide degraded core training to all operating personnel LIGERICLE Electric & Gas Co. of New Jersey B0/09/10 ip
- 8009230368 Requests waiver of 6-month experience requirement for three interim shirt technical advisors Waiver will expedite licensed operator steffing plan Personnel info encl available in Central Files only LIBRIZZI.F P Public Service Electric & Gas Co. of New Jersey 80/09710 2pp
- DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION F Security, medical, emergency & fire protection plans
- 8009030318 Notifies of 800819.22 \$ 30 regional workshops re development of guidance for acceptable method for coping w/emergencies at facility Requests that representative be sent Subj areas to be discussed include function of facilities & location ENGELKEN, R H. Region 5. San Francisco, Office of the Director 80/08/12 2pp
- 8009020330 Forwards comments on safeguards contingency plan & requests response within 30 days Encl withheld (ref 10CFR2 790)
  NEVAK.T M Assistant Director for Operating Reactors 80/08/14
- 8009230344 Requests that all personnel be reminded of purpose of energency notification sys & health physics network Bys installed for govt use during emergency ENGELKENIR H Region 5, San Francisco, Office of the Director B0/08/22 3pp
- 8009040400 Advises that guard supervisor position was inadvertently omitted from organizational chart in Attachment 4 of physical security plan 3 Encl 6-3 within security plan implementing procedure 6 MALBRIDGE.N C Sacramento Municipal Utility District 80/08/26
- 800905023B Requests response to encl comments re facility 790816 guard training & qualification plan Encl withheld (ref Operating Reactors Branch 4 80/08/26 3pp
- 8009230765 Notification of 800910 meeting w/util in Silver Spring,MD to discuss security plan related info GARNER,D J Operating Reactors Branch 4 80/09/03 2pp

## G Adjudicatory correspondence

- 8009190316 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of inro by 806101 REID.R (4 Operating Reactors Branch 4 80/08/29 3pp
- --8009190324 Brder for mod of License DPR-54 to add info which fully responds to NRC request for info re environ qualification or safety-related electrical equipment Info should be submitted by 801101 EISCMHUT.D G Division of Licensing 80/08/29 App
- 8009090784 Hemorandom of law in support of encl findings of fact & conclusions of law filed in response to CA Energy Commission 800804 findings Urges issuance of order to show cause if revision of Commission 800507 order warranted BAKTER, TA Sacramento Municipal Utility District BAXTER, TA Shaw, Pittman, Potts & Troubridge 80/09/05

- ---8009090788 Proposed findings of fact & conclusions of law in response to CA Energy Commission 800804 findings Sufficient actions & mods implemented per Commission 790507 order sufficient Certificate of Svc encl Certificate of Svc encl BAXTER.T A . TRAVIESO-DIAZ Bacramento Municipal Utility District BAXTER.T A Shaw, Pittman, Potts & Troubridge 80/09/08 58pp
- 8009180431 Order demying SMUD request that Appeal Court take judicial notice of cortain proceedings Submission for appeal decision deferred until ASLB issues final order Appeal Court retains jurisdiction over Case 79-7311 U.S. Court of Appeals 9th Circuit 80/09/11 ip

#### H General correspondence

- 8009100457 Ack receipt of 800705 itr & forwards Friends of the Earth Class 9 petition & Director's decision on petition W/o encl SCHWENCER.A Licensing Branch 2 80/08/27 2pp
- --8009100463 Requests Director's decision on Friends of the Earth petition to consider Class 9 accidents in supplemental EIS FRIESEMA.H P Northwestern Univ 80/07/05 ip

#### P Operating license stage documents & correspondence

- 8009150070 Responds to 800523 recommendations concerning lessons learned from 800226 transient at Crystal River Submits results of investigations re use of atmospheric dump valve at Ocanee Units 1-3,AR Unit 1.Davis-Besse Unit 1 & TMI-1 DENION.H R Office of Nuclear Reactor Regulation. Director t Ocanee v... ENTON H R O 80/07/21
- 8009020297 Gubmits interim criteria for shift staffing to all GL & CP licensees & applicants, per NRC 600507 ltr Discusses administrative provisions for emergency & overtime work Development & implements for to be reviewed within 90 days EISENHUT.D 0 Division of Licensing 80/07/31 7pp
- 8007020366 "Electrical, Instrumentation & Control Aspects of Low Temp Overpressure Mitigating Sys," informal interim rept WEBER, D. A. EG&G, Inc. FIN A-6256 8007020366 80/07/31 16pp
- BOO90800BO Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities " Comments requested withiπ 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 entl M/ο NUREO EISENHUT.D 0 Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D C Division of Licensing 80/08/07 60pp
- 8007050240 Application for Amend 70 to License DPR-54, changing flux-to-flow ratio within reactor core Info supporting proposed amend re thermal hydraulic design 5 accident & transient analysis encl MATTIMOE, J J Sacramento Municipal Utility District 80/08/11

- B009030344 Forwards request for add1 info re bypass & reset of engineered safety features Development drawings for switches BLPB-1 & BLPB-2 & relays RPIV/OC & RPIV/RC should be provided NOVAK.T M Assistant Director for Operating Reactors 80/08/14
- B0090B0433 Forwards rept to results of analysis concerning addl instrumentation to monitor inadequate core cooling WALBRIDGE.W C Sacramento Municipal Utility District 80/08/28
- ---8007080439 "Evaluation of Instrumentation to Detect Inadequate Core Cooling, Prepared for 177 Owners Group " FROITH, D.J., SOMTRIC, J.R., OANTHNER, R.W. Babcock & Wilcox Co B0/0B/15 21pp
- 8009170243 Forwards NRC regional evaluation & supporting data re 800826 meeting at util ofcs Draws mgt attention to particular areas of concern re functional design mods, GA audits & training CREMS. JL Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/08/28 1p

- \_\_8007170244 Advises of Regional Evaluation Review Board 800606
  evaluation of activities for 770&05-800&05 Urgos special
  insp in functional design mods. GA audits & training
  Recommends decrease in functional surveillance testing
  FAULKENGERRY, B , CANTER, H L , CARNER, D J Region 5, Gan Francisco,
  Office of the Director 80/08/08 8pp
- 6009180176 Requests add1 info re adequacy of station electrical distribution sys voltage REID: R W Operating Reactors Branch 4 80/09/03 4pp
- BO09130540 Forwards response to 800701 request re fuel assembly holddown springs MATTIMOE, J J Sacramento Municipal Utility District 80/09/04 860
- GOOTICO388 Application to amend License DPR-54 Forwards proposed Tech Spec changes limiting outage duration for Inverters A or B not to exceed 48-h MATTIMUE, J J Sacramento Municipal Utility District 80/09/08 1p
- --8009140092 Proposed Tech Spec changes re limiting outage duration for Inverters A or B not to exceed 48-h \* Sacramento Municipal Utility District 80/09/08 2pp
- go092&0538 Informs that response to NRG 791109 ltr re portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture is acceptable Util has adequately confirmed representations made by fuel supplier REID.R W Operating Reactors Branch 4 80/09/09 3pp
- BOO9170339 Act receipt of 800801 itr suggesting that Dept of Conservation provide NRC w/comments on proposed program of study of impact of recent foothills fault sys DAVIS.J F California. State of 80/09/12 ip
- BO09290353 Forwards response to NRC 800903 request for info re adequacy of station ejectrical distribution sys voltage WALBRIDGE, W C Sacramento Municipal Utility District 80/09/22 200
- ---8009270356 "Bafety Evaluation & Statement of Staff Positions Relative to Emergency Power Bys for Operating Reactors " # Sacramento Municipal Utility District 80/09/22 3pp
- G Inspection reports, IE Bulletins & correspondence
- 8009030169 Responds to IE Bulletin 79-02. Suppl 1 & Revision 2, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Sixty-nine supports did not meet required safety factors Mods finished MATTIMOE. J J Sacramento Municipal Utility District 80/06/26 Zon
- BG09070B12 Forwards revised response to 1E Bulletin 80-11, "Masonry Wall Design " Util 800707 ltr lacking proper jurat statement HALBRIDGE.W C Sacramento Municipal Utility District 80/07/16 ip
- --8007090813 Revised ltr forwarding response to IE Bulletin 80-ii.
  "Masonry Wall Design " Ltr is notarized
  MALBRIDGE,W C Sacramento Municipal Utility District 80/07/16
  33pp
- GOO9150528 Confirms 790416 response to IE Bulletin 79-03A, Longitudinal Held Defects in ASME SA-312, Type 304 Stainless Stael Pipe "No SA-312 pipe used or planned for use in safety-related sys at facility MATTINGE, J J Sacramento Municipal Utility District 60/07/30 ip
- 80C9260278 Forwards IE Info Notice 80-27, "Broken Studs on Terry Furbine Steam Inlet Flange" No written response required ENGELKEN.R H. Region 5, San Francisco, Office of the Director 80/08/07 | Ip
- SOO9;20487 Forwards IE Insp Rept 50-312/80-23 on 800701-31 No nancomptionce noted CREWS.J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/08/14 2pp.

- 8007030287 Forwards Revision 1 to LE Bulistin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required ENGELKEN R H Region 5, San Francisco, Office of the Director 80/08/15 1p
- 8009290407 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Styds " ENGELKEN.R H Region 5, San Francisco, Office of the Director BO/08/18 4pp
- 8007150510 Forwards IE Insp Rept 50-312/80-22 on 800727-31 No noncompliance noted Rept withheld (ref 100FR2 790) NORDEPHAVO. L R Region 5. San Francisco, Safeguards Branch 80/08/20 200
- 8009160185 Forwards TE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ENGELKEN.R H Region 5. San Francisco, Office of the Director 80/08/22 1p
- B009120465 Forwards IE Info Notice 80-31, "Malpheration of Gould-Grown Boveri 480 Volt Type K-6005 % K-DDN 6008 Circuit Breakers" No written response required ENDELKEN,R H Region 5, San Francisco, Office of the Director 80/08/27 ip
- 8009240378 Responds to IE Bulletin 80-15 Submits rept re "Possible Loss of Emergency Notification Sys (ENS) w/Loss of Oifsite Power " Sys telephone power supply tested 800715 & ENS functioned properly WALBRIDGE.W C Sacramento Municipal Utility District 80/08/27
- 8009300047 Forwards IE Insp Rept 50-312/80-25 on 800811-15 No noncompliance noted SPENCERG & Region 5, San Francisco. Reactor Construction & Engineering Support Branch 80/08/29 2pp
- --8009300054 IE Insp Rept 50-312/80-25 on 800811-15 No moncompliance moted Major areas inspected activities performed in response to open items from grevious insps & inservice insp data revieu NARBUT.P P Region 5. San Francisco. Office of the Director DDDDS, R T Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/08/26 App
- R Periodic operating reports & related correspondence
- 8009050339 Forwards "Effluent & Waste Disposal Semiannual Environ Rept, Jan-June 1980 " Bummary encl MATTIMOE, J. J. Bacramento Municipal Utility District 80/08/15
- --8009050344 "Effluent & Waste Disposal Semiannual Environ Rept, Jan-June 1980 "
- \* Sacramento Municipal Utility District 80/08/15 35pp
- 8009160295 Forwards monthly operating rept for Aug 1980 RODR(GUEZ.R J Sacramento Municipal Utility District 80/09/03 1p
- --8009160297 Monthly operating rept for Aug 1980 CDLONBO.R W Bacramento Municipal Utility District 80/09/03, 5pp
- 8009230677 Forwards monthly operating rept for Aug 1980
  HOLLINGSWORTH Sacramento Municipal Utility District 80/09/16
  2pp
- S Reportable occurrences, LERs & related correspondence
- 8009150269 Forwards LER 80-039/017-0 MATTIMOE, J Secramento Municipal Utility District 80/09/02 2pp
- --8009150272 LER 80-037/01T-0 on 800813.while proceeding to cold shutdown reactor protection sys was placed in shutdown bipass mode 5 nuclear overpower trip setpoint not reduced to less than 5% of rated power Caused by personnel error COLOMBO.R W Sacramento Municipal Utility District 80/09/02 ip
- 8009260472 Forwards LER 80-040/03L-0 8035ENMAIER,W Sacramento Municipal Utility District 80/09/12 ip

- --8009260476 LER 80-040/03L-D on 800812 reactor protection sys channel D trup signal was received Caused by amplifier failure in electronic portion of transmitter Transmitter replaced, calibr, leak tested & returned to syc COLOMBO, R W Sacramento Municipal Utility District 80/09/11
- T Hearing transcripts on non-antitrust matters
- 8009260313 Submittal of prepared testimony for first hearing session No attempts made to provide complete answers to ASLB 800908 memorandum & order re physical separation of TM1 units Certificate of Svc encl Related correspondence TROWBRIDGE.0 F Metropolitan Edison Co 80/09/15 7pp
- --8009260366 "Small Break Operating Ouidelines " Related correspondence \* Babcock & Wilcox Co 69-1106091-00 79/11/30 48pp
- DOCKET 50-313 ARKANSAS NUCLEAR ONE, UNIT 1
- F Security, medical, emergency & fire protection plans
- B009020130 invites participation in 800822 workshop in Atlanta.6A to solicit comment re proposed functional criteria for emergency response facilities in NURED-0696 Discussion to include location.size & staffing of emergency ctrs SEYFRIT.K V Region 4. Dallas. Office of the Director 80/08/12
- 8009090326 Notifies that security sys will be fully implemented on 801001 Any subsequent equipment failure will be compensated for by compensatory measures outlined in util industrial security plan & implementing procedures
  TRIMBLE.D C Arkansas Power & Light Co 80/08/29 1p
- 8009170322 Forwards security personnel training & qualification plans Revision i Revision withheld (ref 100FR2 790) TRIMBLE.D C Arkansas Power & Light Co 80/09/09 1p
- Q Adjudicatory correspondence
- BOD7190306 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by B01101.

  REID:R N Operating Reactors Branch 4 B0/08/29 2pp
- --8009190310 Order for mod of License DPR-51 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101
  EISENHUT.D 0 Division of Licensing 80/08/29 App
- J Insurance & indemnity information
- 80090J0537 Forwards Endorsements 40.41 & 42 to NELIA Policy NF-210 & Endorsements 36 & 37 to MAELU Policy MF-74 TRIMBLE, D C Artansas Power & Light Co 80/08/29 App
- 8009030550 Forwards Endorsement 3 to ANI Binders EB-48 & EB-68 & MAELU Binders XB-48 & XD-68 TRIMBLE.D C Arkansas Power & Light Co 80/08/29 9pp
- p Operating license stage documents & correspondence
- 8007290040 Responds to memo re fuel adjustment clause provision that would permit passing 90% of cost of replacement power on to ratepayers NRC would present any info at formal hearing Na investigation planned VOEGELIR J Office of the Executive Legal Director 80/07/18
- 8009(50070 Responds to 800923 recommendations concerning lessons learned from 800226 transfent at Crystal River Submits results of investigations re use of atmospheric dump valve at Oconsee Units 1-3, AR Unit 1, Davis-Besse Unit 1 & TMI-1 BENION R Office of Nuclear Reactor Regulation, Director 80/07/21. 2pp
- GOO7020277 Submits interim criteria for shift staffing to all OL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 70 days EISENHUT,D Q. Division of Licensing 80/07/31. 7pp

- BOO9080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/o NUREO EISENHUI
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUTED 9 Division of Licensing 80/08/07 40pp
- 8009080483 Advises that Class III fee is due for B00204 application for proposed Tech Spec change re diverse reactor bldg isolation MILLER,W O License Fee Management Branch 80/09/14 ip
- 8009020042 Responds to 800523 ltr requesting info re interim reliability evaluation program TRIMBLE,D C Arkansas Power & Light Co 80/08/15 3pp
- 8007020322 Submits schedule for first 5 months of interim reliability evaluation program annotated to highlight areas of potential NRC participation Anticipated start date scheduled for 800915 ETSENHUT.D 0 Division of Licensing 80/08/15 App
- 9009030248 Advises of fee determinations for 790424 & 060& applications re PORV setpoint change & 790606 application re anticipatory reactor trip MILLER, W O License Fee Management Branch 80/08/19 ip
- 8009030393 Forwards evaluation of instrumentation for detection of inadequate core cooling to support 800711 ltr stating that no add1 instrumentation is needed to meet NUREO-0578 requirements IRIMBLE, P.C. Arkansas Power & Light Co. 80/08/26 22pp
- BOO7120387 Responds to 800701 ltr ra assembly holddown spring failures Video tapes of core from last refueling have been reviewed & spent furl pool assemblies examined No damage to spring or assembly components noted TRIMBLE, D.C. Arkansas Power & Light Co. 80/08/27 Spp
- 8009090482 Forwards proposed revision to radiological effluent Tech Specs for review & approval Requests that implementation of specs be delayed until 811231 CAVANAUGH.W. Artansas Power & Light Co 80/09/05 3pp
- --8007070491 Proposed revision to radiological effluent Tech Specs, Bections 1.2.3.4 & 6 changing data analysis & reporting requirements \* Ariansas Power & Light Co 80/09/05 50pp
- 8009160228 Forwards response to NRC 800623 request for info on waste gas sys finalization of identified mods to correct problems that allow air in-leakage to sys expected in early 1981 TRIMBLE.D C Arkansas Power & Light Co 80/09/09 App
- BOD9250425 Informs of acceptability of response to NRC 791109 ltr reportions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture
  REID.R W Operating Reactors Branch 4 BO/09/09 2pp.
- 8009300145 Forwards Amends 46 & 15 to Licenses DPR-51 & NPF-6, respectively, safety evaluation & notice of issuance & availability REID.R W Operating Reactors Branch 4 80/09/16 2pp
- --8009300148 Amends 46 & 15 to Licenses DPR-51 & NPF-6, respectively, revising ETS re design objective for radioactive gaseous releases & requirements for quarterly rept on radioactive gaseous releases REID.R W Operating Reactors Branch 4 80/09/16 19pg
- ---8009300153 Bafety evaluation supporting Amends 46 & 15 to Licenses

  DPR-51 & NPF-6. respectively.

  # Office of Nuclear Reactor Regulation, Director 80/09/16 4pp
- ---G009300155 Notice of issuance & availability of Amends 46 & 15 to Licenses DPR-51 & NPF-6.respectively REID.R W Operating Reactors Branch 4 80/09/16 2pp
- BOOFDOOZYB Advises that util will submit changes to 790402 response by 801103 as necessary to meet requirements for reactor bldg purge TRIMBLE.D C Arkansas Power & Light Co 80/09/18, 1p.

- 8009300173 Requests deadline extension until 801201 to rewrite model Tech Specs to accompdate existing AR-1 Tech Specs format, unit design & NUREO-0578 Category A mods TRIMBLE.D C. Arkansas Power & Light Co 80/09/19 ip
- O Inspectson reports, IE Bullatins & correspondence
- 8009020224 Responds to IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds" Units utilize flued head design for containment penetrations flued head penetrations radiographed TRIMBLE,D C Arkansas Power & Light Co 80/06/27 (Ipp
- 8008280022 Submits partial response to IE Bulletin 80-07. "Hydramotur Actuators " Complete response expected by 800718 Six Aydramotor actuators used in safety-related sys All six mfg using proper 5160 steel for spring mati TRIKBLE.D C Arkansas Power & Light Co 80/07/08 ip
- BOO9180145 Forwards IE Bulletin 80~18, "Maint of Adequate Min flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/07/24, Lp
- 8009020538 Forwards supplemental IE Info Notice 80-06, "Notification of Significant Events at Operating Power Reactor Facilities"
  No written response required
  SEYFRITIX V Region 4. Dallas, Office of the Director 80/07/29
  ip
- BOQ9180138 Forwards IE Bulletin 80-20, "Failures of Wastinghouse Type W-2 Spring Return to Neutral Control Switches " Written response required SEYFRIT.K V Region 4, Dallas, Office of the Director, 80/07/31 is
- 8009180160 Forwards IE Bulletin B0-19, "Failure of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required SEYFRIT, K V Ragion 4, Dallas, Office of the Director 80/07/31
- 8009260294 Forwards IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange " No written response required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/08/07
- 8009180470 Forwards IE insp Repts 50-313/80-11 & 50-368/80-11 on 800622-0721 & notices of violation & deviation One notice of violation & Attachment A to repts withheld (ref 100682 790). MADSEN.9 L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/08/08 2pp
- --8009180472 Notice of violation from insp on 800622-0721 • Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/08/07 1p
- ---8009180476 Notice of deviation from insp on 800622-0721 \* Region 4, Dallas: Reactor Operations Nuclear Support Branch 80/08/07 is
- --BOOT180481 IE Insp Repts 50-313/80-11 & 50-368/80-11 on 800622-0721
  Noncompliance noted 2T12 valve gallery in Unit 2 auxiliary
  bldg not posted as radiation area & no positive access
  control on Door 364 Attachment A withheld (ref 10CFR2 790)
  JOHMSON, W D . CALLAN, L J . HUNNICUTT, D M. Region 4, Dallas, Office
  of the Director 80/08/07 13pp
- 8009040039 Ack receipt of 800708 & 11 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/80-05 & 50-368/80-05 MANSEN.9 L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/08/12 ip
- --8009040049 Responds to NRC 800416 ltr re violations noted in JE Insp Rept 50-368/80-05 Corrective actions Tech Spec change request generated to clarify existing spec on diesel generator automatic sequence time delay relays TRIMBLE.D C. Arkansas Power & Light Co 80/07/08 ip
- BO09240705 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Hercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required.
  SEYFRIT.K V Region 4, Dallas, Office of the Director 80/08/15 to.

- 8009170390 Forwards IE Circular 80-18 "10CFR50 59 Safety Evaluations For Changes to Radwaste Treatment Sys " No written response required SEYFRIT.K V Region 4. Pallas, Office of the Director 60/08/22
- 8009120420 Forwards IE Info Notice 80-31. 'Maloperation of Gould-Brown Bover1 480 Volt Type K-600S & K-DON 600S Circuit Breakers "No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/08/27
- 8009170173 Forwards IE Insp Repts 50-313/80-13 & 50-368/80-13 on 800721-25 W/o enci notice of violation KELLY, J.A. Region 4. Dallas, Office of the Director 80/08/29 2pp
- --B009t70176 IE lnsp Repts 50-313/80-13 & 50-368/80-13 on 800721-25 Noncompliance noted vital area door fastened shut w/ inadequate fastener.tamper alarm triggering mechanism taped in manner preventing alarm & intrusion alarms not tested CALDWELL, R A , KELLY, J A Region 4, Dallas, Office of the Director 80/08/27 2pp
- R Pariodic operating reports & related correspondence
- 8009020001 Forwards results of impingement data for Jul 1980 TRIMBLE, D.C. Arkansas Power & Light Co. 80/08/27 12pp
- B009090425 Forwards NPDES rept for Second Quarter 1980 re NPDES Permit AR0001392 Util 1trs to EPA encl TRIMBLE.D C Arkensas Power & Light Co 80/08/29 8pp
- ---8009090432 NPDES rept for Second Quarter 1980 re NPDES Permit ARGO01392 \* Arkansas Power & Light Co 80/08/29 15pp
- B009160251 Forwards semiannual radioactive effluent rept for first & second quarters 1980
  TRIMBLE.D C Arkansas Power & Light Co 80/09/08 1p
- --B009160256 Semiannual radioactive effluent rept for first & second quarters 1980 4 Arkansas Power & Light Co B0/09/08 21pp
- 8009230697 Forwards monthly operating rept for Aug 1980 TRIMBLE, D.C. Arkansas Power & Light Co. 80/09/15 ig
- --8009230700 Monthly operating rept for Aug 1980 BRAMLETT.L S Arkansas Power & Light Co 80/09/15 Spp
- 8 Reportable occurrences, LERs & related correspondence
- BOOTIGO557 PND-IV-80-027A correcting info previously reported in PND-IV-027 dtd BOO822 re loss of all telephone communications Util has plans for installation of new communications sys which includes fiber optics & microwave JOHNSON, W D , HUNNICUTT, D M , MADSEN, O L Region 4. Dallas. Office of the Director 80/08/26 2pp
- 8007240106 Responds to 800818 memo re proposed AO classification re reactor coolant pump seal failure Event did not involve major reduction in degree of public safety & should not be considered AO DEMION.H R Office of Nuclear Reactor Regulation, Director 80/08/29 3pp
- --8009240:34 Forwards draft Commission Paper w/proposed FR notice refailure of reactor coolant pump seal at facility Event is under consideration as AU, since it satisfies one example in AO policy statement Requests comment by 800822 HALLER, N M Office of Management and Program Analysis BO/08/18 Pan
- ---8007240145 Responds to request for input re proposed AB classification of reactor coolant pump seal failure at facility Incident more appropriately meets criterion of "Event of Interest "
  No major breakdown in level of public protection determined RIGGS:R Operating Experience Evaluation Branch 80/08/22 3pp
- --800724015B Operating Reactor Event Memo 80-10 forwarding list of LERs re events which result in containment floor flooding & diagram of RCG Water on containment floor is only significant during major LCGA EIBENHUT, D G Division of Licensing 80/07/11 5pp

- ---8009240179 Repts findings re review of available LER data on reactor contant pump seal failures Typical failure modes include inadequate seal spring pressure design error, thermal shock, personnel error & debris 2UDANS.J Division of Engineering 80/05/02 3pp
- 8009090542 Forwards updated LER 80-011/03L-5 TRIMBLE.D C Artansas Power & Light Co 80/09/03 2pp
- --8009090568 Updated LER BO-011/03L-5 on 800401.IE Bulletin 79-14 review revealed 21 piping hangers inoperable Hangers tepaired or modified within Tech Specs time limit BRAMLETT.L S Arkansas Power & Light CO 80/09/03 1p
- 8009190600 PNO-1V-80-030 on B00905, during full power operation steam generator tube leak occurred Leak was indicated by N-1b detector, offgas monitor & main stack monitor Unit will be shut down approx two wks
  JOHNSOR: N D . HUNNICUTT. D M. MADSEN. G L. Region 4, Dallas, Office of the Director B0/09/05 ip
- 8009230708 Forwards updated LER 80-011/03X-6 TRIMBLE,D C Arkansas Power & Light Co 80/09/15 ip
- --8009230715 Updated LER 80-011/03X-6 on 800401,32 piping hangers were declared insperable Design change prepared to upgrade affected hangers to meet design requirements Review continuing BRANLETTL 8 Arkansas Power & Light Co 80/09/15 2pp

### V Operator Examinations

- 8007050330 Submits info re mods to reactor operator training program in response to NRC 800328 ltr Course summaries for thermodynamics, fluid flow & heat transfer training & for mitigating core damage encl
  O'HAMLON, J.P. Artanses Power & Light Co. 80/08/04 9pp
- 8009170241 Documents 800811 presentation of util position re nuclear training program Presentations re operator training, general employee training, training records, on-the-job training, fire brigade training & sys training encl
  CAVANAUGH, W Arkansas Power & Light Co 80/08/13 14pp
- DOCKET 50-315 DONALD C COOK NUCLEAR POWER PLANT. UNIT 1

  F Security, medical, emergency & fire protection plans
- 8007230284 Requests that all personnel be reminded of purpose of omergoncy notification sys & health physics network Sys installed for govt use during emergency KEPFLER.J G Region 3, Chicago, Office of the Director 80/08/22 3pp

#### O Adjudicatory correspondence

- 8009240509 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 80110; VAROA, B A Operating Reactors Branch 1 80/08/29 2pp
- --8009260613 Order for mod of Licenses DPR-58 & DPR-74 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment info should be submitted by 801101
  EISENKUT, D O Division of Licensing 80/09/29 App
- P Operating license stage documents & correspondence
- 8009050460 Forwards Amend 38 to License DPR~88, safety evaluation & notice of issuance & availability
  VARGA.8 A Operating Reactors Branch 1 80/07/25 2pp
- --8009050464 Amend 38 to License DFR-58, revising Tech Specs to allow operation of unit w/Exxon Nuclear Co power distribution control procedures
  VARGA-5 A Operating Reactors Branch 1 80/07/25 17pp
- --8007050470 Safety evaluation supporting Amend 38 to License DPR-58 \* Office of Nuclear Reactor Regulation, Director 80/07/25 3pp
- --809050471 Notice of issuance & availability of Amend 38 to License PR-58 VARGALS A Operating Reactors Branch | 80/07/25 2pp

- 8009120039 Forwards Amend 39 to License DPR-58, safety evaluation & notice of issuance 5 availability
  VAROA S A Operating Reactors Branch 1 80/07/25 2pp
- --8009120049 Amend 39 to License DPR-58, revising surveillance & manitoring requirements for degraded voltage function & surveillance requirements for onsite power source testing VARGALS A Operating Reactors Branch 1 80/07/25 12pp
- --80091200&i Bafety evaluation supporting Amend 39 to License DPR-58
  Draft technical evaluation rept enci

  → Office of Nuclear Reactor Regulation. Director 80/07/25
  1400
- --8009120065 Notice of issuance & availability of Amend 39 to License DPR-58 VAROA.8 A Operating Reactors Branch 1 80/07/25 2pp
- 8009020183 Forwards correspondence on problems identified at other facilities re-personnel errors per 800702 commitment W/o encl
  HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/07/30 ip
- 800902027 Submits interim criteria for shift staffing to all OL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D Q Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0696. "Functional Criteria for Emergancy Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT,D O Division of Licensing 80/08/01 119pp
- BOO9230052 Informs that exemption from fee re licensing action associated w/TMI~2 Lessons Learned is unjustified Previous datermination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D @ Division of Licensing 80/08/07 60pp
- 8009170228 Forwards review & assessment re control rod guide thimble wear in FWRs Issue resolved for Unit 2 Unit 1 review is in progress VARGA.S A Operating Reactors Branch 1 80/08/14 4pp
- BO09190794 Forwards revised Westinghouse STS 3 9 8 2.3 9 10 & Bases 3/4 9 8 5 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NOVAK,T M Assistant Director for Operating Reactors BO/OB/15 in
- --8009190817 Revised Westinghouse STS 3 9 8 2,3 9 10 % Bases 3/4 9 8 % 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control roofs # Assistant Director for Operating Reactors 80/06/23 21pp
- 8009110579 Informs that review of Tech Specs requirements for rod position indication completed Determined that requirements in complishance w/control rod position indication sys at Westinghouss PWRS forwards safety evaluation VARGA.S A Operating Reactors Branch 1 80/08/18 2pp
- --8007110584 Safety evaluation supporting Tech Specs requirements recontrol rod position indication sys at Westinghouse PMRs
  # Office of Nuclear Reactor Regulation, Director 80/08/18 2pp
- 8009(105)2 Forwards revised Page 3/4 3-26a to Tach Specs in Amend 39 to License DPR-58 Due to administrative error, incorrect page was issued VARGA,8 A Operating Reactors Branch 1 80/08/19 ip
- --8009110516 Revised Page 3/4 3-26a to Tech Specs submitted w/Amend 39 to License DPR--50 re engineered safety feature actuation sys Instrumentation trip setpoints # Operating Reactors Branch 1 80/08/19 2pp
- 8009040464 Forwards mather NRC review of ice condensar containment & hydrogen control measures for Sequoyah Nuclear Power Plant ACRS has scheduled meetings in Washington, DC on 800828, 0902 & 04 to discuss issue.

  TEDESCO
- 8009240078 Forwards Amends 40 & 23 to Licenses DPR-58 & DPR-74 respectively, safety evaluation & notice of issuance & availability VARGA.8 A Operating Reactors Branch 1 80/08/29 3pp

- --8009240084 Amends 40 & 23 to Licenses BPR-58 % DPR-74, respectively, revising Unit 1 Tech Specs re refueling water tank operating temp & discharge scour bed protection & Units 1 & 2 plume measurements of water discharge VARGA,S A Operating Reactors Branch 1 80/08/29 21pp
- --8009240089 Safety evaluation supporting Amends 40 & 23 to Licenses DPR-58 & DPR-74 respectively

   Operating Reactors Branch 1 80/08/29 4pp
- --BOO9240097 Notice of issuance δ availability of Amends 40 & 23 to Licenses DPR-58 & DPR-74 respectively MEIGHBORS, J D Uperating Reactors Branch 1 80/08/29 2pp
- 8009120639 "Technical Evaluation Rept on Degraded Orid Protection for Class IE Power Sys for DC Cook Nuclear Plant Unit 1," technical evaluation rept.Aug 1980 CLEVELAND.C J E000 Idaho, Inc FIN A-6256 8009120639 80/08/31 1300
- 8009260520 "Effect of Containment Temp on Liquid Level Measurements.DC Cook Nuclear Station," informal rept UDY, A C E0%0 Idaho, Inc FIN A-6256 8009260520 80/08/31 10pp
- BOO9260568 "Technical Evaluation Rept on Degraded Grid Protection for Class IE Power Sys for DC Cook Nuclear Plant,Unit 1," Revision 1 CLEVELAND,C J E090 Idaho, Inc FIN A-6254 8009260568 80/08/31
  - CLEVELAND, C.J. EG%G Idaho, Inc. FIN A-6256 8009260568 80/QB/3 13pp
- 8009240369 Requests extension to 801031 for submitting info re auxiliary feedwater sys flow design basis per NRC 791030 request Extension will permit in-house review Addl info re condensate storage tank level indication sys encl HUNIER.R S Indiana & Michigan Electric Co 80/09/18 3pp
- Q Inspection reports. IE Bulletins & correspondence
- 8007020227 Ack receipt of 800708 ltr informing NRC of steps taken to correct violations noted in 800610 ltr DAVIS.A 8 Region 3, Chicago, Fuel Facility & Materials Safety Beanch 80/08/08 (p
- --S009020232 Responds to NRC 800610 ltr re violations noted in insp rept Corrective actions placard procedures now require boxes over 640 cubic ft vol to have placards on each side & end HUNTER,R S Indiana & Michigan Electric Co 80/07/08 ip
- 8009140195 Responds to IE Bulletin 77-03A, "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " No sys utilizing pipe are stressed to more than 85% of max allowable stress HUNIER, R 8 Indiana & Michigan Electric Co 80/08/08 1p
- 8009250365 Ack receipt of 800804 ltr informing NRC of steps taken to correct violation noted in IE insp repts
  MEISHHAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/08/14 ip
- --8009250373 Responds to NRC 800710 ltr re violations noted in IE insp repts Corrective action document reviews will be completed on 800815 HUNTER, R S Indiana & Michigan Power Co 80/08/04 2pp
- 8007030190 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written rasponse required KEPPLER.J G Region 3. Chicago. Office of the Director 80/08/15
- 8009260628 Forwards IE Insp Rept 50-315/80-12 on 800722-25 No noncompliance noted DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/08/21 2pp
- --8009260634 IE Insp Rept 50-315/B0-12 on 800722-25 No noncompliance noted Major areas inspected operational radiation protection during refueling & maint, including organization & staffing, exposure control & matl control FISHER, W. L. HUETER, L. J. Region 3, Chicago, Office of the Director. 80/08/18 12pp
- 8009170407 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required
- KEFPLER, J G Region 3, Chicago, Office of the Director 80/08/22

- B009230063 Forwards (E Info Notice 80-31, 'Maloperation of Gould-Brown Boveri 480 Volt Type K-6005 & K-DDN 6005 Circuit Breakers " No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/08/28
- 8009240094 Forwards response to IE Bulletin 80-15. "Possible Loss of Emergency Notification Sys (ENS) w/Loss or Offsite Power" Test verified operability of all sys MALONEY.O P Indiana & Michigan Electric Co 80/09/04 4pp
- 8009240212 Responds to IE Bulletin 80-20, "Failure of Nestinghouse Type W-2 Spring Return to Neutral Control Switches ' Referenced switches are not used in safety-related sys at facility HUNTER, R S Indiana & Michigan Electric Co 80/09/08 1p
- 8009240107 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/09/10 in
- 8009290440 Ack receipt of 800804 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-315/80-08 & 50-316/80-07 HEISHMAN,R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/09/10 Ip
- ~-8009290444 Responds to NRC 800710 Ltr je violations noted in IE Insp Repts 50-315/80~08 \$ 50-316/80-07 Corrective actions events entered in required logbooks & responsible persons reminded of maintaining accurate logs HUNTER.R S Indiana & Michigan Electric Co 80/08/04 3pp
- 8 Periodic operating reports & related correspondence
- 9007110310 Advises that util will submit semiannual radioactive effluent release rept by 800724 Rept being prepared per Section 5 4 1 B of Tech Specs.App B MALGNEY.G P Indiana & Michigan Electric Co 80/09/04 ip
- 8009160273 Forwards monthly operating rept for Aug 1980 SHALLER,D V Indiana & Michigan Electric Co 80/09/12 1p
- ~-8009160277 Monthly operating rept for Aug 1980 OILLETT, W T Indiana & Michigan Electric Co 80/09/05 10pp
- 8009190422 Forwards summaries of impinged fish for Apr & May 1980 in response to NRC request Also forwards related data & repts to aid in evaluation of ecological significance of event Encis available in Central Files only OAULKE, A E American Electric Power Co , Inc. 80/09/16 3pp
- S Reportable occurrences. LERs & related correspondence
- B009090501 Forwards LER 80-017/03L-0 SHALLER.D V Indiana & Michigan Power Co B0/09/03 ip
- --8009090509 LER 80-017/03L-0 on 800804, during low power physics test after refueling, boron injection tank discovered to have boron concentration below required min Caused by inadequate mixing due to low rectirculation flow CHADVELL, H M Indiana & Michigan Power Co 80/09/03 2pp
- 8009110326 Forwards LER 80-018/03L-0 SMALLER/D V Indiana & Michigan Electric Co 80/09/05 1p
- --8009110348 LER 80-018/03L-0 on 800805.during post-refueling startup.RCS average temp fell below 541 F contrary to Tuch Spec 3 I I 5 Caused by unbalance between turbine load & reactor power Turbine load reduced CHADWELL, H M Indiana & Michigan Electric Co 80/09/05 2pp
- 8009150323 Forwards LER 80-019/03L-0 SHALLER,D V Indiana & Michigan Electric Co 80/09/10 1p
- --8009150328 LER 80-019/03L-0 on 800811, while performing surveillance re Tech Spec 3 8 2 1 requirements for inoperable diesel generator, requirement 4 8 1 1 ia was not performed Caused by inadequate surveillance procedures CHADWELL, H M Indiana & Michigan Electric Co 80/09/10 1p
- 8009190503 Forwards LER 80-021/03L-0 8HALLER,D V Indiana 2 Michigan Power Co 80/09/12 ip

- --8009190509 LER 80-021/03L-0 on 800817 during insp.tuo intermediate deck doors were found frozen shut Caused by water from top deck divider beams Design change submitted to insulate divider beams to prevent condensation WIZNER.D 0 Indiana & Michigan Power Co 80/09/12 1p
- 8009300510 Forwards LER 80-020/03L-0 SHALLER, D.V. Indiana & Michigan Electric Co. 80/09/24 ip
- --8009300517 LER 80-020/031-0 on 800831.during normal operation.unit trip & Train A safety injection & steam line isolation occurred Caused by shorted diode in CRID 4 inverter Ail diodes & discillato; boards replaced, tested & returned to svc DELONG.8 D Indiana & Michigan Electric Co 80/09/24 2pp

- 8009170350 Concurs w/NRC 800328 Itr re qualifications of reactor operators Changes necessary to upgrade operations personnel qualifications program have been adopted Revised program was sent on 800725 to NRC for review & approval HUNIER.R S Indiana & Michigan Electric Co 80/09/11 ip
- DOCKE! 50-316 DOMALD C COOK NUCLEAR POWER PLANT. UNIT 2

  F Security, medical, emergency & fire protection plans
- 8009230284 Requests that all personnel be reminded of purpose of emergency notification sys thealth physics network Sys installed for govt use during emergency
  KEPPLER. J O Region 3. Chicago. Office of the Director 80/08/22

#### G Adjudicatory correspondence

- 8009260609 Forwards order requiring info supporting environ qualification or safety-related electrical equipment Requests submittal of info by 80i101 VAROA. S A Operating Reactors Branch 1 80/08/29 2pp
- --8009260613 Order for mod of Licenses DPR-58 & DPR-74 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101
  EISENHUT D G Division of Licensing 80/08/29 App

# P Operating license stage documents & correspondence

- 8009020183 Forwards correspondence on problems identified at other facilities re-personnel errors per 800702 commitment W/o encl
  HEISHMAN F Region 3. Chicago, Reactor Operations Nuclear Support
  Branch 80/07/30 is
- 8009020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D & Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT. D 0 Davision of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend.

  EISENHUT. D & Division of Licensing 80/08/07 60pp
- 8009170228 Forwards review & assessment re control rod guide thimble wear in PHRs Issue resolved for Unit 2 Unit & review is in progress VARGA.8 A Operating Reactors Branch 1 80/08/14 4pp
- 8009190794 Forwards revised Westinghouse STS 3 9 8 2,3 9 10 % Bases 3/4 9 8 % 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control reds Written response required NUVAK.T M Assistant Director for Operating Reactors 80/08/15 tp

- --8009190817 Revised Westinghouse STS 3 9 8 2,3 9 10 5 Bases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure flange during movement of fuel assemblies or control rods

  \* Assistant Director for Operating Reactors 80/06/23 21pp
- BOO9110579 Informs that review of Tech Specs requirements for rod position indication completed Determined that requirements in compliance w/control rod position indication sys at Westinghouse PRRS Forwards safety evaluation VAROA.S A Operating Reactors Branch 1 80/08/18 2pp
- --8009110584 Safety evaluation supporting Tech Specs requirements re control rod position indication sys at Westinghouse PWRs \* Office of Nuclear Reactor Regulation, Director 80/08/18 2pp
- 8009100106 Forwards corrected Page 1 to Amend 22 to License DPR-74 & corrected Tech Spec Page 3/4 3-25a
  VARGA.S A Deprating Reactors Branch 1 80/08/19 2pp
- ---8009100110 Corrected Page 1 to Amend 22 to License DPR-74 & corrected Tech Spec Page 3/4 3-25a \* Operating Reactors Branch 1 80/08/19 2pp
- 8009040464 Forwards matter NRC review of ice condenser containment & hydrogen control measures for Sequeyah Nuclear Power Plant ACRS has scheduled meetings in Washington, DC on 800828, 0902 & 04 to discuss issue
  TEDESCO
- 8007240078 Forwards Amends 40 & 23 to Licenses DPR-58 & DPR-74 respectively, safety evaluation & notice of issuance & availability VAROA, S.A. Goeratino Reactors Branch ( 80/08/27 3eg
- --8009240084 Amends 40 & 23 to Licenses DPR-58 & DPR-74, respectively, revising Unit 1 Tech Specs re refueling water tank operating temp & discharge scour bed protection & Units 1 & 2 plume measurements of water discharge VARGA, S A Operating Reactors Branch 1 80/08/29 21pp
- ---B009240089 Safety evaluation supporting Amends 40 & 23 to Licenses DPR-58 & DPR-74 respectively \* Operating Reactors Branch 1 80/08/29 4pp
- --809240097 Notice of issuance & availability of Amends 40 & 23 to Licenses DPR-58 & DPR-74 respectively NEIOH9DRS.J D Operating Reactors Branch i 80/08/27 2pp
- BO09260084 "Effect of Containment Temp on Liquid Level Measurements.DC Cook Nuclear Station, Unit 2, " Interim rept UDY, A C E0&G Idaho, Inc FIN A-6256 B009260084 B0/08/31 10pp
- 8009240369 Requests extension to 801031 for submitting inform auxiliary feedwater sys flow design basis per NRC 791030 request Extension will permit in-house review Add1 inform condensate storage tank level indication sys encl HUNIER.R B Indiana & Michigan Electric Co 80/09/18 3pp
- G Inspection reports. IE Bulletins & correspondence
- 9007260304 Forwards IE Insp Rept 50-316/80-10 on 800623-27 No noncompliance noted HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/08/07 2pp
- --8009260303 IE Insp Rept 50-316/80-10 on 800623-27 No noncompliance noted Major areas inspected program & documentation recontrol of centrifugal charging/safety injection pumps FOSTER, L. E., SHAFER, N. D., Region 3, Chicago, Office of the Director 80/08/04 7pp
- GOO9020227 Ack receipt of 800708 ltr informing NRC of steps taken to correct violations noted in 800610 ltr
  DAVIS,A B Region 3, Chicago, Fuel Facility & Materials Safaty
  Branch B0/08/08 ip
- --8009020232 Responds to NRC 800610 ltr re violations noted in insp rept Corrective actions placand procedures now require boxes over ,640 cubic ft vol to have placards on each side & end HUNTER,RS Indiana & Michigan Electric Co 80/07/08 ip
- 8009160195 Responds to IE Bulletin 79-03A. "Longitudinal Weld Dufects in ASME SA-312, Type 304 Stainless Steel Pipe " No sys utilizing pipe are stressed to more than 83% of max allowable stress HUNTER:R S Indiana & Michigan Electric Co 80/08/08 ip

- 8009250365 Act receipt of 800804 ltr informing NRC of steps taken to correct violation noted in IE insp repts HEISHMAN.R F. Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/08/14 ip
- --8097250473 Responds to NRC 800710 ltr re violations noted in IE insp repts Corrective action document reviews will be completed on 800815 HUNTER R S Indiana & Michigan Power Co 80/08/04 2pp
- 8009030190 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Mercury-Hetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Dosigned by C-E " Written response required XEPPLER. J G Region 3. Chicago. Office of the Director 80/08/15
- BO09:70407 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER, J. G. Region 3. Chicago. Office of the Director 80/08/22 is
- E007230063 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Baveri 480 Volt Type K-6005 & K-DON 6008 Circuit Breakers " No written response required MEPPLER.J & Region 3. Chicago, Office of the Director 80/08/28
- 8009260094 Forwards response to IE Bulletin 80-15, "Possible Loss of Eastgency Notification Bys (ENS) w/Loss of Offsite Power " Test verified operablity of all sys HALONEY, Q P Indiana & Michigan Electric Co 80/09/04 4pp
- 8007260212 Responds to IE Bulletin 80-20, "Failure of Westinghouse Type H-2 Spring Return to Neutral Control Switches" Referenced switches are not used in safety-related sys at facility MUNTER-R S Indiana & Michigan Electric Co 80/09/08 ip
- 8009240107 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required VEPPLER.J 0 Region 3. Chicago, Office of the Director 80/09/10 to
- 8009290440 Ack receipt of 800804 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/80-08 & 50-315/80-07 HE[SHANN R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/09/10 ip
- --B009270444 Responds to NRC 800710 ltr re violations noted in IE Insp Repts 50-315/80-08 & 50-316/80-07 Corrective actions events entered in required logbooks & responsible persons reminded of maintaining accurate logs HUNTER.R S Indiana & Michigan Electric Co 80/08/04 3pp
- R Periodic operating reports & related correspondence
- SOCTION Advises that util will submit semiannual radioactive effluent release rept by SOCF24 Rept being prepared per Section 5 4 1 B of Tech Specs, App B MALDNEY, G P Indiana & Michigan Electric Co 80/09/04 kp
- 8009160280 Forwards monthly operating rept for Aug 1980 6HALLER.D V Indiana & Michigan Electric Co 80/09/12 ip
- --8007160283 Monthly operating rept for Aug 1980 G1LLETI.W T. Indiana & Michigan Electric Co 80/09/05 6pp
- 8009190422 Forwards summaries of impinged fish for Apr & May 1980 in response to NRC request Also forwards related data & repts to aid in evaluation of ecological significance of event Enc)s available in Central Files only GAULKE.A E American Electric Power Co . Inc 80/09/16 3pp
- S Reportable occurrences, LERs & related correspondence
- 8009190517 Forwards LER 80-030/03L-0 SMALCER.D V Indiana & Michigan Electric Co 80/09/12 1p
- --8009190522 LER 80-030/03L-0 on 800814, during normal operation, radiation monitor R11 alarmed investigation showed R-11 & R-12 sample pumps seized Caused by wear Pump replaced & monitors returned to svc
  WIZMER, D G Indiana & Michigan Electric Co 80/09/12 ip

- 8009170350 Concurs w/NRC 800328 ltr re qualifications of reactor operators Changes necessary to upgrade operations personnel qualifications program have been adopted Revised program was sent on 800725 to NRC for review & approval HUNTER,R S Indiana & Michigan Electric Co 80/09/11 1p
- DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

  F Security, medical, emergency & fire protection plans
- 8009230165 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency ORIER, 8 H Region 1. Philadelphia, Office of the Director 80
- 8009080350 Forwards "Fire Stup Penetration Test on Fire Protection Sys," final rept re Slab 2 ABH.R F Baltimore Gas & Electric Co 80/09/02 1p
- --8007080352 "Fire Stop Penetration Tests on Fire Protection Sys," final rept re Slab 2 PISH, M D , FOIRIER, L J , SCHRAEDER, A L Southwest Research institute 80/08/15 182pp
- 8009300383 Submits status of fire protection mods & details of certain mods which cannot be completed per original schedule List of items requiring extended schedules encl LUNDVALL.A E Baltimore Gas & Electric Co 80/09/26 App
- O Adjudicatory correspondence
- 8009260528 Forwards order requiring into supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801001 CLARK.R A Operating Reactors Branch 3 80/08/29 2pp
- --8007260532 Order for mod of Licenses DPR-53 & DPR-69 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101
  EISENHUT.D G Division of Licensing 80/08/29 App
- J Insurance & indemnity information
- BO09300438 Forwards Endorsement 29 to MAELU Policy MF-76 & Endorsements 30 & 35 to NELIA Policy NF-216 SHOEMAKER, C L Baltimore Cas & Electric Co 80/09/26 4pp
- P Operating license stage documents & correspondence
- BOO9GRO297 Submits interim criteria for shift staffing to all GL & CP licenses & applicants, per NRC BOO5O7 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D Q Division of Licensing. BO/07/31 7pp
- 8009080080 Forwards draft NUREQ-0496, "Functional Criteria for Emergency Response Facilities' Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0496 encl Mo NUREG EISENHUT, D. Q Division of Licensing 80/08/01 119pp
- 8009230032 Informs that exemption from few re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D C Division of Licensing 80/08/07 60pp
- 8009020327 Submits schedule for first 5 months of interim reliability evaluation program, annotated to highlight areas of potential NRC participation Anticipated start date scheduled for 800915
  EISENHUT.D O Division of Licensing 80/08/19 5pp
- BD09020336 Forwards Corrected Tech Specs 4 5 1 f & 4 5 1 b re sampling locations Forwarded w/Amends 44 b 27 to Licenses DPR-53 & DPR-69.respectively CLARK,R A Operating Reactors Branch 3 B0/08/15 2pp
- --8009020338 Corrected Tach Spacs 3/4 5 re min boron concentration values which were included in Amends 44 & 27 to Licenses DPR-53 & DPR-69, respectively

  \* Operating Reactors Dranch 3 80/08/15 4pp

- 8007150415 Informs that facility does not have too specific Event 5 valve configurations discussed in NRC 800223 ltr re-primary coolant sys pressure isolation valves NRC activities re-valve configurations have been finalized for facility CLARK, R.A. Operating Reactors Branch 3: 80/08/15 2pp
- --8009150426 "Primary Cootant Sys Pressure Isolation Valves, Calvert Cliffs Units 1 & 2." technical evaluation rept NGEL\_P N. STILKELL, T C. Franklin Institute/Franklin Research Center NRC-03-79-118 80/07/21 4pp
- 8009150380 Forwards Amends 45 & 28 to Licenses DPR-53 & DPR-69, respectively & notice of issuance & availability CLARK, R A Operating Reactors Branch 3 80/08/19 2pp
- --B009150356 Amends 45 & 28 to Licenses DPR-53 & DPR-69, respectively, adding requirement to maintain safeguards contingency plan, to be fully implemented within 30 days
  TRAMMELL,C M Operating Reactors Branch 3 80/08/19 4pp
- --B009150361 Notice of issuance & availability of Amends 45 & 28 to Licenses DPR-53 & DPR-49, respectively TRANNELL, C M Operating Reactors Branch 3 80/08/19 2gp
- 8009150034 Summary of 800717 meeting w/C-E & util in Sethesda.MD re 18 month fuel cycles for facilities Main purpose of meeting, to present overview of six documents submitted by util on 800626; was fulfilled Operating Reactors Branch 3 80/08/20 4pp LI.C Y
- 8007090553 Submits general program for calculating RCS leak rates for most reactors from PWR vendors Results indicate periodic independent calculation of RCS leak rates by inspectors is WOODRUFF.R W Division of Reactor Operations Inspections 80/08/21
- 8007020020 Forwards proprietary & nonproprietary versions of data sheets from Mestinghouse low pressure turbine disc insp.to replace corresponding pages in 800218 ltr Proprietary version withheld (ref 10CFR2 790)
  LUNDVALL,A E Baltimore Gas & Electric Co 80/08/25 4pp
- 8007040301 Describes proposed dosign mods per NUREG-0576, Item 2 1 7a which requires implementation of safety-grade autostart of auxiliary feedwater by 810101 Drawing change notices encl. including one oversized drawing LUNDVALL, A E Galtimore Cas & Electric Co 80/08/27 13pp
- 8009150250 Forwards response to NRC 800717 questions re C-E topical repts & review of safety evaluation re Westinghouse methodology for statistically combining uncertainties in state & sys parameters LUNDVALL.A E Baltimo Baltimore Gas & Electric Co 80/09/10 17pp
- 8007300077 Forwards Amends 46 & 27 to Licenses DPR-53 & DPR-49, respectively, safety evaluation & notice of issuance & availability CLAR&R A Operating Reactors Branch 3 80/09/10 3pp
- --8009300080 Amends 46 & 29 to Licenses DPR-53 & DPR-69, respectively, changing App A Tech Specs for safety-related hydraulic snubbers & limiting conditions for operation of fire hose stations, shutdown & onsite power distribution sys CLARK, R A Operating Reactors Branch 3 80/09/10 20pp
- --B0093000B3 Safety evaluation supporting Amends 46 & 29 to Licenses DPR-53 & DPR-69, respectively \* Operating Reactors Branch 3 80/09/10 4pp
- --80093000B5 Notice of issuance & availability of Amends 46 & 29 to Licenses DPR-53 & DPR-69, respectively CLA9K, R A Operating Reactors Branch 3 80/09/10 2pp
- 8009160453 Responds to NRC 800911 request for add1 info re spent fuel pool mods Poison matl is 84C powder in fiberglass matrix Irradiation data submitted to NRC on Haddam Neck & Millstone dockets in form of c80-N-78-297 dtd 781031 ASH,R F Baltimore Gas & Electric Co 80/09/12 2pp
- 8009230634 Requests amend to change Tech Specs for License DPR-53 to allow operation for fifth cycle Proprietary & nonproprietary versions of CEN-138(B) encl Proprietary version withheld (ref 100FR2 790) Baltimore Cas & Electric Co 80/09/22 2pp
  - 3009230640 Application to amend Cycle 5 refueling license Karked-up Tech Specs encl \* Baltimore Gas & Electric Co 80/09/22 200pp

- --8009230646 Nonproprietary version of "Description of PROTOTYPE Test Program in Calvert Cliffs : Cycle 5 " \* Combustion Engineering, Inc. CEN-137(8) 80/08/27 Bpp
- --8009230650 Nonproprietary version of "Description of Modified Assemblies in Calvert Cliffs 1 Cycle 5 " \* Combustion Engineering, Inc. CEN-138(B) 80/09/22 App
- 8009240360 Forwards affidavit supporting proprietary designation, per 100FR2 790, for Apps D % E of Cycle 5 reload license submittal SCHERER, A E C-E Power Systems 80/09/22
- O Inspection reports. IE Bulletins & correspondence
- 8009240259 Forwards 1E Insp Repts 50-317/80-10 & 50-318/80-09 on 800418-20 No noncompliance noted CARLSDUR T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/07/23 2pp
- -8009240265 IE Insp Repts 50-317/80-10 % 50-318/80-09 on 800618-20
  No noncompliance noted Major areas inspected qualification
  data for electrical equipment inside containment as defined
  in licensee response to IE Bulletin 79-018
  EBNETER S D Region 1, Philadelphia, Reactor Construction &
  Engineering Support Branch FINKEL, A E Region 1, Philadelphia,
  Office of the Director 80/07/14 16pp
- 8009160504 Responds to IE Info Notice 80-06, Suppl 1, "Notification of Significant Events at Operating Power Reactor Facilities " Proposed Criteria requires medical judgment be made onsite & should be reconsidered TIERNAN, J A Baltimore Gas & Electric Co 80/08/08 1p
- 8009030109 Forwards Revision i to IE Bulietin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Coperating Nuclear Power Plants Designed by C-E "Britten response requi GRIER, BH Ri BO/08/15 1p required H. Region t, Philadelphia, Office of the Director
- B009180572 Forwards IE Circular 80-18, "100FR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GRIER.B H Region 1. Philadelphia, Office of the Director 08/08/22 Ip
- BOO9120169 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover( 480 Volt Type K-6005 & K-DON 6008 Circuit Breakers " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director BO/08/27 1p
- 8009230776 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required GRIER.B H Region 1. Philadelphia. Dffice of the Director 80/09/10 1p
- 8009240285 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matis "No written response required GRIER.B H Region 1. Phitadelphia, Office of the Director BO/07/12 ip
- 8009250047 Ack receipt of payment of civil penalties in amount of \$21.000 proposed in NRC 800801 ltr  $\delta$  util 800821 ltr readdle corrective actions taken further action will be based on future inspa STELLO.V. Office of Inspection & Enfarcement, Office of the Director 80/09/17 2pp
- R Periodic operating reports & related correspondence
- 8009020034 Forwards "Semiannual Effluent Release Rept for Calvert Cliffs Nuclear Power Plant. Second Half 1979 " Meteorological summary for first half of 1980 will be submitted at later LUNDVALL, A E Baltimore Gas & Electric Co 80/08/20 ip
- --B009020035 "Semiannual Effluent Release Rept for Calvert Cliffs Nuclear Power Plant Second Hal+ 1979 " \* Baltimore Gas & Electric Co 80/08/20 17pp
- 8009290244 Forwards monthly operating repts for Aug 1980 MERSON, S D Baltimore Gas & Electric Co 80/09/15
- -8009290248 Monthly operating rapts for Aug 1980 MERSONS D. Baltimore Gas & Electric Co. 80. 80/09/15 24ep

- S Reportable accurrences. LERs & related correspondence
- 8009190665 RO 80-41 on 800812, instrument air compressor after cooler 1f in svc water sys failed causing air ingress in svc water subsys Restored to normal operation after isolation of instrument 11 Details will follow RUSSELL.L B Baltimore Gas & Electric Co 80/08/13 ip
- S009030520 Forwards LER 80-038/03L-0 RUSSELL, L B Baltimore Gas & Electric Co 80/08/29 ip
- --B009030522 LER 80-038/03L-0 on 800801.during normal operation, control room air conditioning compressor tripped & would not restart Caused by failure of compressor amps to meet nameplate data Load demand adjusted
  LADIEMSKI.W , PENCE.W 8 Baltimore Gas & Electric Co 80/08/27
- 8009120354 Forwards LER 80-042/03L-0 RUSSELL, L B Saltimore Gas & Electric Co 80/09/06 1;
- --8009120378 LER 80-042/03L-0 on 800806 during normal operation, engineered actuation sys channel ZE was de-energized for corrective maint Caused by failure of actuation channel B isolation module within channel ZD ZD module replaced LAGIEWSXI, J S., RIZZO, P. G. Baltimore Gas & Electric Co. 80/09/06 to
- BOO9120447 Forwards LER 80-040/03L-0 RUBSELL, L B Baltimore Gas & Electric Co 80/09/06 ip
- ~-B009120455 LER B0-040/03L-0 on 800B06 during normal test of saltwater valve 1-SN-5210-CV.BN-3T49-CV opened causing 11 SM header to decrease 3 paig Cause not known Solenoid valve 1-8V-5149 tested found openable & rebuilt as preventive measure DAVIS, B M , RIZZO P G Baltimore Gas & Electric Co 80/09/06
- 8009120344 Forwards LER 80-043/03L-0 RUSSELL.L B Baltimore Oas & Electric Co 80/09/08 1p
- --8009120348 LER 80-043/03L-0 on 800819 during normal operation while conducting routine maint on 500 kV BRKR 552-22 disconnect device 89-228 malfunctioned Caused by failure of horseshoe clip Disconnect device repaired & returned to svc WEMDERLICH, R L Baltimere Gas & Electric Co 80/09/08 2pp
- 8009160315 Forwards LCR 80-044/03L-0 RUSSELL, L B Baltimore Cas & Electric Co 80/09/08 1p
- --8007160318 LER 80-044/03L-0 on 800820, containment sump drain valves test open for 55 minutes increases in dose rates were essentially zero Gaused by operator error Upon discovery, valves were closed WENDERLICH,R L Baltimore Gas & Electric Co 80/09/08 Spp
- BOO9250311 RO BO-51 on 800911, during post-maint test, control room air conditioning Unit 11 failed to start Attempt to restart Unit 12 failed Cause not stated Arter corrective maint & repairs Units 11 & 12 returned to svc RUSSELL, B Baitimore Gas & Electric Co GO/09/12 3pp
- 8009230531 Forwards LER 80-039/03L-0 RUSSELL, L B Baltimore Oas & Electric Co 80/09/15 1p
- --8009230536 LER 80-039/03L-0 on 800815 during normal operation, control room 12 air conditioning compressor tripped twice Caused by high discharge pressure Unloader valve adjusted & sys design re-evaluated to increase cepacity & reliability LEADIEWEKI.J S., PENCE.M B. Baltimore Gas & Electric Co. 80/9/15 10
- 9007230542 Forwards LER 80-046/03L-0 RUSSELL, B Baltimore Oas & Electric Co 80/09/16 ip
- | 1009230583 Forwards LER 80-048/017-0 | RUSSELL,L B | Baltimore Gas & Electric Co | 80/09/17 | 1

- --8009230592 LER 80-048/OLT-0 on 800993 during maint for control room (2 air conditioner, unit li compressor was not running & later tripped on overload Faulty reset suitch replaced & procedures revised to require check of air conditioner WEMDERLICH, R L , PENCE, W B Baltimore Gas & Electric Co 80/09/17 1p
- 8009230688 Forwards LER 80-045/03L-0 RUSSELL.L D Baltimore Gas & Electric Co 80/09/20 1p
- --8009230695 i.ER 80-049/O3L-O on 800820.computer indication failed except for control element assembly position indication Caused by ipose wire connectors at several edge connector pins for analog bus segmentation cards Connectors soldered in place DAVIS.S M . RIZZO.P G Baltimore Cas & Electric Co 80/09/20 2pp
- 8009300441 Forwards followup LER 80-022/01(-1 RUSSELL,L B Baltimore Gas & Electric Co 80/09/22 1p
- --8009300450 Followop LER 80-022/01X-1 on 809415, util notified of possible deficiency in FSAR safety analysis Section 14 3 Analysis does not address possibility of RCS being drained to not leg w/1% shutdows possibility of RCS being drained DAVIS.8 M Baltimore Gas % Electric Co 80/09/22 2pp
- 8007300464 Forwards LER 80-049/03L-0 RUSSELL, L B Baltimore Gas & Electric Co 80/09/26 1p
- --8009300470 LER 80-049/03L-0 on 800830, during normal operation, 12 control room air conditioning unit tripped & would not restart Caused by high discharge pressure 8gs being re-evaluated for permanent changes to increase capacity LAGIENSKI.J S . PENCE, W B Baltimore Gas & Electric Co 80/09/26
- POCKET 50-318 GALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2

  F Security, medical, emergency & fire protection plans
- 8007230165 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency GRIER.B H Region I, Philadelphia, Office of the Director BO/08/22 Spp
- 8009080350 Forwards "Fire Stop Penetration Test on Fire Protection Sys," final rept re Slab 2
  ASH.R F Baltimore Gas & Electric Co 80/09/02 ip
- --B009080352 "Fire Stop Penetration Tests on Fire Protection Sys," final rept re Slab 2 PISH.M D : POIRIER.L J , SCHRAEDER.A L Southwest Research Institute B0/08/15 182pp
- 8009300083 Submits status of fire protection mods & details of certain mods which cannot be completed per original schedule List of items requiring extended schedules enci LUNDVALL, A E Baltimore Gas & Electric Co 80/09/26 4pp
- G Adjudicatory correspondence
- 8009260528 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 CLARK, R A Operating Reactors Branch 3 80/08/29 2pp
- --8009260832 Order for mod of Licenses DPR-53 % DPR-69 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101
  EISENHUT,D 0 Division of Licensing 80/08/29 App
- J Insurance & indemnity information
- 8009300438 Forwards Endorsement 29 to MAELU Policy MF-76 & Endorsements 30 & 35 to NELIA Policy NF-216 SHOEMAKER.C L. Baltimore Gas & Clectric Co 80/09/26 4pp
- P Operating license stage documents & correspondence
- 8009020297 Submits interim criteria for shift staffing to all DL & CP licensees & applicants.por NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D 0 Division of Licensing 80/07/31 7pp

- 80070800B0 Forwards draft NUREG-0676, "Functional Criteria for Energency Response Facilities ' Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl W/o NUREG EISENHUT, D.G. Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of anend EISEMMUT.D G Division of Licensing 80/08/07 40pp
- 8007020334 Forwards Corrected Tech Specs 4 5 1 f & 4 5 i b re sampling locations forwarded w/Amends 44 & 27 to Licenses DPR-53 & DPR-69, respectively CLARK.R A Operating Reactors Branch 3 B0/08/15 2pp
- --8009020338 Corrected Tech Speca 3/4 5 re min boron concentration values which were included in Amends 44 & 27 to Licenses DFR-53 & DFR-69 respectively to Operating Reactors Branch 3 80/08/15 4pp
- B009150q15 Informs that facility joes not have two specific Event 5 valve conrigurations discussed in hRC 800223 ftr re-primary coolant sys prossure isolation valves NRC activities re-valve configurations have been finalized for facility CLARK.R A Operating Reactors Branch 3 80/08/15 2pp
- --8009150426 "Primary Coolant Sys Pressure Isolation Valves, Calvert Cliffs Units 1 & 2." technical evaluation rept FOELL, P.N. STILMELL, T.C. Franklin Institute/Franklin Research Center NRC-03-79-118 80/07/21 4pp
- 8009190350 Forwards Amends 45 & 28 to Licenses DPR-53 & DPR-49, respectively & notice of issuance & availability CLARK, R A Operating Reactors Branch 3 80/08/19 2pp
- ---R007150356 Amends 45 & 28 to Licenses DPR-53 & DPR-69, respectively, adding requirement to maintain safeguards contingency plan, to be fully implemented within 30 days TRAMMELL. C M Operating Reactors Branch 3 80/08/19 4pp
- ---B009150361 Notice of issuance & availability of Amends 45 & 28 to Licenses DPR-93 & DPR-49, respectively TRAMMELL.C M Operating Reactors Branch 3 60/08/19 2pp
- 8009150034 Bunmary of 800717 meeting w/C-E & util in Bethusda, MD re 18 month fuel cycles for facilities Main purpose of meeting, to present overview of six documents submitted by util on 800626, was fulfilled LI, C Y Operating Reactors Branch 3 80/08/20 4pp
- 8009090553 Submits general program for calculating RCS leak rates for most reactors from PWR vendors Results indicate periodic independent calculation of RCS leak rates by inspectors is reconnended WOODRUFF,R W Division of Reactor Operations Inspections 80/08/21
- 8009020020 Forwards proprietary & nonproprietary versions of data sheets from Westinghouse low pressure turbine disc insp. to replace corresponding pages in 800318 ltr Proprietary version withheld (ref 10CFR2 790)
  LUNDVALE. A E Baltimere Cas & Electric Co 80/08/25 4pp
- B009040301 Bescribes proposed design mods per NUREO-0578,[tem 2 i 7a which requires implementation of safety-grade autostart of auxiliary feeduater by B10101 Deswing change notices encl. including one oversized drawing LUNDVALL.A E Baltimore Gas & Electric Co 80/08/27 13pp
- 8009190011 Provides instructions omitted from 800819 issuance of Amend 28 to License DPR-69 CLARK,R A Operating Reactors Branch 3 80/08/28 2pp
- BODPISO250 Forwards response to NRC BOD717 questions re C-E topical repts & review of safety evaluation re Westinghouse methodology for statistically combining uncertainties in state & sus parameters LUNDVALLIA E Baltimore Gas & Electric Co 80/09/10 17pp
- BOO930GD77 Forwards Amends 46 & 29 to Licenses DPR-53 & DPR-69, respectively, safety evaluation t notice of issuance & availability CLARK R A Operating Reactors Branch 3 80/09/10 3pp

- --800930080 Amends 46 & 27 to Licenses DPR-53 & DPR-69, respectively, changing App A Tech Specs for safety-related hydraulic snubbers & limiting conditions for aperation of fire hose stations, shutdown & onsite power distribution sys CLARK, R A Operating Reactors Branch 3 80/09/10 20pp
- --8009300083 Safety evaluation supporting Amends 46 & 29 to Licenses DPR-53 & DPR-69, respectively \* Operating Reactors Branch 3 80/09/10 4pp
- --8009300095 Notice of issuance & availability of Amends 46 & 29 to Licenses DPR-53 & DPR-69 respectively CLARM.R A Operating Reactors Branch 3 80/09/10 2pp
- 8009160453 Responds to NRC 800911 request for add1 info re spent fuel pool mods Poison matl is 84C powder in fiberglass matrix irradiation data submitted to NRC on Haddam Neck & Millstone dockets in form of C80-7-79-297 dtd 781031
  ASH.R F Baltimore Gas & Electric Co 80/09/12 2pp
- O Inspection reports, IE Bulletins & correspondence
- 6009240259 Forwards IE Insp Repts 50-317/80-10 & 50-318/80-09 on 800518-20 No noncompliance noted CARLSDM,R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/07/23 2pp
- --B009240269 IE Insp Repts 50-317/80-10 & 50-318/80-09 on 800618-20. No noncompliance noted Major areas inspected qualification data for electrical equipment inside containment as defined in licensee response to IE Bulletin 79-018
  EBHETER.8 D Region 1. Philadelphia, Reactor Construction & Engineering Support Branch FINKEL.A E Region 1. Philadelphia, Office of the Director 80/07/14 16pp
- 8009160504 Responds to IE Info Notice 80~06, Suppl 1, "Notification of Significant Events at Operating Power Reactor Facilities "Proposed criteria requires medical judgment be made onsite & should be reconsidered TIERNAN.J A Saltimore Oas & Electric Co 80/08/08 Ip
- 8009030109 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required QRIER, B H Region 1, Philadelphia, Office of the Director 80/08/15 ip
- 8009180572 Forwards IE Circular 80-18, "10CFR50 59 Bafety Evaluations for Changes to Radwasta Treatment Sys " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 08/08/22 10
- 8009120169 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Voit Type K-6008 & K-DON 6008 Circuit Breakers " No written response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/08/27 1p
- B009230776 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required ORIER, B.H. Region 1, Philadelphia. Office of the Director 80/09/10 ip
- BOD9240285 Forwards IE Info Notice BO-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No critten response required ORIER B H Region 1, Philadelphia, Office of the Director-BO
- 8009250047 Ack receipt of payment of civil penalties in amount of \$21,000 proposed in NRC 800801 ltr & util 800821 ltr read() corrective actions taken Further action will be based on future insps STELLO.V Office of Inspection & Enforcement, Office of the Director 80/09/17 2pp
- R Periodic operating reports & related correspondence
- B009020034 Forwards "Semiannual Effluent Release Rept for Galvert Cliffs Nuclear Power Plant. Second Half 1979 " Meteorological surmary for first half of 1980 will be submitted at later date LUNDVALL. A E Baltimore Gas & Electric Co 80/08/20 ip.
- --8009020035 "Semiannual Effluent Release Rept for Calvert Cliffs Nucleal Power Plant. Second Half 1979 " \* Baltimore Gas & Electric Co 80/08/20 17pp

- 8007270246 Forwards monthly operating repts for Aug 1980 MERSON, 6 D Baltimore Gas & Electric Co 80/07/15 in
- --800929024B Monthly operating rapts for Aug 1980
  MERSON:S D Baltimore Cas & Electric Co 80/09/15 24pp
- S Reportable occurrences, LERs & related correspondence
- 8009030543 Forwards LER 80-036/03L-0 RUSSELL, L 8 Baltimore Qas & Electric Co 80/08/29 1p
- ~-8007030559 LER 80-036/03L-0 on 800729, engineered safety features actuating sys channel ZE de-energized in three instances Channel ZE de-energized while troubleshooting Mater pointers to defective bistables oscillated DAVIS.5 M . RIZZO.P O Baltimore Gas & Electric Co 80/08/29
- B009250311 RO 80-51 on 800911, during post-maint test, control room air conditioning Unit 11 failed to start Attempt to restart Unit 12 failed Cause not states After corrective maint & repairs Units 11 & 12 returned to svc RUSSELL, B Baltimore Gas & Electric Co 80/09/12 3pp
- B009230520 Forwards LER 80-037/03L-0 RUSSELL.L B Baltimore Gas & Electric Co 80/09/18 ip
- --8007230527 LER 80-037/03L-0 on 8008i8 while reducing power due to saltwater leak steam generator blowdown hydrogen ion concentrate fell below Tech Spec limit Caused by failure to notice feed line from ammonia tank to manifold was shut off LAGIEMSKI.J S . SPECIALE.J R Baltimore Oas & Electric Co BO/09/18 2pp
- 8009300454 Forwards LER 80-037/03L-0 RUSSELLL B Saltimore Gas & Electric Co 80/09/26 ip
- --BO07300450 LER B0-037/03L-0 on B00910 during normal operation, tentainment sump drain valves were open for 28 minutes & sump level alarm sys was inoperable Caused by operator error Control switch will be modified to spring shut WENDERLICH.R L Baltimore Oas 5 Electric Co. 80/09/26 2pp
- pocket 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2 F. Security, medical, emergency & fire protection plans
- BOO9230175 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Bys installed for govt use during emergency GRIER, B H Region I, Philadelphia, Office of the Director BO

#### Adjudicatory correspondence

- 8007090337 Add1 response to FOIA request for TMI-2, "Startup Problem Ragt" & intervenor Citizens Committee for Protection of Environ Proposed Findings of Fact & Conclusions of Law re Indian Point 2 Forwards intervenor filing FELTON, J H Division of Rules and Records 80/08/12 1p
- 8009030118 Response stating no opposition to NRC 800812 motion that Tech Specs proposed in Director of Ofc of Nuclear Reactor Regulation 800211 order be amended per 800911 mod Formal amend will await hearing outcome W/Certificate of Svc IRCMERIBOE, 0 F. RIDOMAY, D A Metropolitan Edison Co FRCMERIDGE, 0 F. Shaw, Pittman, Potts & Trowbridge 80/08/27 5p
- 8009050425 Notion for correction of record to include failures of instruments & equipment outside containment that contributed to THI-2 accident Focuses on TMI-2 fuel pool which may endanger TMI-1 operation

  LEMIS.M 1 Affiliation Unknown 80/08/28 3pp
- 8000040239 Memorandum & order accepting WA Lockstet, SC Bholly & Environ Coalition on Nuclear Power as parties in proceeding New parties shall respond to NRC motion to conform proposed Tech Space per 800811 mod of order, by 800917 MDLF, JF Atomic Safety and Licensing Board Panel 80/08/29 2pp.
- 8007:10779 Response in opposition to Environ Coalition on Nuclear Power 800822 request for free 800707 prehearing conference transcript Recommends that ruling on future transcripts be deferred pending consolidation Certificate of Svc encl SINGER.L N Hearing Branch 2 80/09/10 5pp

- 8009160190 Response stating no objection to NRC 800812 motion to conform proposed Tech Specs w/Dfc of Nuclear Reactor Regulation 8008ti mod of order Certificate of Svc encl LOCHSTET.W A Affiliation Unknown 80/09/11 3pp
- 8009230628 Advises that York:PA LPPR will be closed on 800929 York TMI-1 & 2 documents will be available at restart hearing NRC must be informed by 800924 if parties object to course of action SMARTZ/L L Antitrust Division 80/09/16 Sno
- 8009300011 Forwards util 800916 interreft memo organizing ASLB 801014 tour to facilities Svc list encl Related correspondence BLAKE.E L. Shaw, Pittman, Potts & Troubridge 80/09/22 7pp
- H General correspondence
- 8009020174 Informs that venting of krypton gas from TMI constitutes generated for US BOORKLUND, P. P. Affiliation Unknown BO/06/11 to
- 8009300246 Responds to 800415 ltr to President Carter re nuclear power plants Action plan developed to provide plan for actions now judged necessary by NRC to improve nuclear facility regulation & operation based on TMI DENION, HR Office of Nuclear Reactor Regulation. Director 80/06/17 4pp
- 8007260205 Forwards N Ginder 800702 ltr expressing concerns re facility venting t possible traces of krypton found in soil around area WALKER, R S House of Rep 80/07/09 2pp
- 8009110637 Responds to CP Cole B00214 ltr to President Carter expressing concerns re-rate structure NRC has ordered that public hearings be conducted to determine whether facility should be operated REID.R U Operating Reactors Branch 4 80/07/25 4pp
- BOOP150413 Responds to 800730 postcard recommending licensing of nuclear plants that meet NRC stds TMI accident precipitated NRC decision not to license new plants until safety criteria are implemented DENION.HR Office of Nuclear Reactor Regulation, Director 80/07/30 ip
- --8009150416 Recommends licensing of nuclear power plants which comply ω/URC stds
  RULEY,E Affiliation Unknown 80/0//23 2pp
- 8009150240 Responds to 791024 ltr to President Carter re possible future operation of THI NRC will conduct meetings to determine under what conditions restart would take place & public will be given opportunity to raise questions BNYDER. B J TMI Program Office 80/07/31 2pp
- --8009150241 Forwards S Kelley 791024 ltr misdirected to dept for reply RATHKOPF.C L Energy, Dept of 80/01/22 4pp
- 8007240107 Responds to 790829 ltr re facility accident Commission determined that accident does not meet specific criteria for extraordinary nuclear occurrance as defined by Price-Anderson Act
  SNYDER, B J TMI Program Office 80/07/31 2pp
- --8009240121 Opposes NRC determination that facility accident was not extraordinary nuclear occurrence Decision ignores possible long-term hazardous effects on workers subjected to continuous radiation exposure & on people offsite RICCITELLI, J. Affiliation Unknown 79/08/29 to
- B0090B0331 Forwards NRC evaluation of info forwarded in B00616 ltr, order donying motion for reconsideration of CLI-B0-25 & order for temporary mod of license Facility decontamination has been completed safely BENTON, H R Office of Nuclear Reactor Regulation, Director B0/08/05.
- 8007020151 Responds to 800422 ltr re K Weiman opposition to venting krypton from reactor bidg UCS concluded that direct radiation-induced physical health effects from purging would be absent Purging completed 800711 DIRCKS, W J Office of the Executive Director for Operations 80/08/06
- --B009020156 Forwards K Weimann comments on venting krypton from reactor bldg SCHULZE,R T House of Rep , Ways and Means 80/04/22 7pp

- 8009020166 Responds to 800923 ltm re concerns of FR Romano of Air & Water Pollution Patrol about 800423 release of Kr-85 from facility
  DIRCKS W J Orfice or the Esecutive Director for Operations 80/08/06 ip
- --8007020168 Requests response to encl FR Romano 800512 ltr to NRC expressing concern about 800423 release of Kr-85 from facility SCHMEINER, R S Senate 80/05/23 ip
- --8009020171 Comments on 800423 release of Kr-85 aircraft.pilots & passengers utilizing airports in facility area, should have been notified of danger of lethal krypton regardless of amount NRC acted irrosponsibly by withholding info ROMANG.FR Air and Water Pollution Patrol 80/05/12 2pp
- B007020172 Responds to B00221 Itr urging revocation of OL due to util inability to handle cleanup operations NRC will fully implement regulatory process in determining acceptability of cleanup operations
  SNYDER.B J TMI Program Office B0/08/11 2pp
- ---8009020178 Favors revoking util OL due to incompetence & inability to handle cleanup operations CARPENTER,M Affiliation Unknown 80/02/21 2pp
- 8009020315 Responds to 800401 ltr expressing appreciation for NRC efforts to repair damages resulting from accident Expresses gratitude for kind remarks
  SNYBER.B.J. TMI frogram Office 80/08/11 lp.
- --8009020317 Expresses appreciation for NRC efforts to repair damages resulting from accident
  DAILY,L , DAILY,H Affiliation Unknown 80/04/01 19
- 8007020465 Responds to postcards re release of Kr-85 Potential public health impact from using any proposed strategies for removing Kr-85 is negligible Purging method is quickest & safest for workers to accomplish
  SNYDER, B. J. TMI Program Office 80/08/11 2pp
- --8009020472 Expresses concern re release of Kr-85 from facility GL should be revoked Health of local people being damaged PETROSKY. J A Affiliation Uninown 80/08/26 2pp
- 8007030369 Responds to 800326 ltr expressing concerns re nuclear energy in Eight of facility (incident Specific plans have been made for porviding accurate info to public for serious accidents Lists HRC conclusions re disposal of krypton gas SNYDER, B J TMI Program Office 80/08/11 3pp
- --B009030375 Expresses concerns to nuclear emergy in light of facility incident Info to accident made available to public was confusing & inaccurate Alternate methods must be used to eliminate krypton gases from facility KROUTIN Q Affiliation Unknown B0/03/26 App
- 8009030678 Responds to 800215 ltr urging revocation of util DL & permanent shutdown of facility Commission has ordered public hearing to determine if Facility should be operated Forwards order outlining (ssues re-public health & safety M/o encl SNYDER, B J TMI Program Office 80/08/11 ip
- --8009030580 Urges revocation of util QL 9 permanent shubdown of facility due to threat posed to public health & safety ALTHQUSE: V Affiliation Unknown 80/02/15 1p
- 8009030681 Responds to 800215 ltr vrging revocation of util OL & permanent shutdown of facility Commission has ordered public hearing to determine facility operation Forwards order outlining issues re public health & safety ((/o enc) SNYDER, B J IMI Program Office 80/08/til 19
- --S009030683 Urges revocation of util DL ½ permanent shutdown of facility due to threat poses to public health ½ safety SWEENEY.A A Affiliation Unknown 80/02/15 3pp
- 8009050375 Responds to ltr to President Carter re cleanup of contaminated water at facility EPICOR-II water treatment sys authorized for use in processing waste water in auxiliary bidg SNYDER B J TMI Program Office 80/08/11 2pp
- 8009100052 Responds to 791206 ltr re TMI cleanup operations Commission issued order on 800612 for temporary mod of license, authorizing controlled purging of Kr-85 from reactor bldg atnosphere
  SNYDER, 3 J TMI Program Office 80/08/11 2pp

- 8009170170 Responds to 800229 ltr re removal of Kr-85 from reactor bldg Forwards NUREG-0642,800610 order for temporary mod of license authorizing purging of Kr-85 & 800612 memo & order discussing rationale for decision to purge W/o encl SNYDER, B J TMI Program Office 80/08/11 2pp
- 8009170266 Responds to 800313 ltr re release of Kr-85 Potential physical health impact on public of using any proposed strategies for removing gas negligible Purging method is quickest & safest for workers to accomplish SN1DER, B J TMI Program Office 80/08/11 2pp
- --8007170269 Expresses concern re release of Krypton gas into atmosphere b dumping conteminated water into Susquehanna River REINHART.M Affiliation Unknown 80/03/13 ip
- 8009170272 Responds to 800313 ltr re release of Kr-85 Potential physical health impact on public of using any proposed strategies for removing Kr-85 is negligible Purging method is quickes to afest for workers to accomplish SNYDER, B J TMI Program Office 80/08/11 2pp
- ---B009170275 Suggests method for venting Kr-B5 into cryogenic processing or condense out radioactive gases in tank containing liquid helium All vent eys should pass through cyrogenics scrub TUTLEMA'L J S Affiliation Unknown B0/03/13 ip
- BOO9020320 Responds to BOO625 ltr re constituent Flick idea to solve brupton gas problem at facility Krupton purging authorized by NRC on BOO612 Authorization was based on detailed evaluation of alternatives DIRCKS.N J Office of the Executive Director for Operations BO/08/12 1p
- --8009020323 Requests response to encl R Flick ltr suggesting method to solve krypton gas problem at facility ATKINSON,E V House of Rep. 80/06/25 3pp
- 8009240100 Responds to 800630 itr re identity of radionuclides in reactor bldg Kr-BS was dominant radionuclide Concentrations of other isotopes were small BNYDER.B J TMI Program Office 80/08/12 ip
- 8007020118 Responds to 800702 ltr requesting info re BL Kelter inquiry about nuclear safety & energy alternatives Every effort being made to protect public health & safety at all nuclear plants Plants found unsafe are not allowed to operate DIRCKS N J Office of the Executive Director for Operations 80/08/13 25pp
- --9007020124 Requests response to encl BL Kelter inquiry about nuclear safety & energy alternatives WILLIAMS: H A Senate 80/07/02 2pp
- 8009020328 Responds to 800711 itr re constituent contern that radioactive matls released during facility purging would pollute ME rainfail Low solubility of krypton & abundance of stable krypton timits sorption of Kr-35 in rainwater DIRCKS/W J Office of the Executive Director for Operations 80/08/13 3pp
- --8009020332 Requests info re constituent concern that radioactive matls released during facility purging would pollute ME rainfail COHEN, W S Senate 80/07/11 ip
- 8007020293 Responds to 800212 telegram to President Carter requesting action to prevent major disaster at nuclear station Studies have resulted in add1 licensee requirements SNYDER, B.J. TMI Program Office 80/08/14 3pp
- 8009020299 Responds to 800329 ltr expressing concerns re nuclear energy to opposing venting of radioactive gases & release of contaminated water Forwards summary of NUREG-0558.re population dose & health impact. to other math W/o enci SNYDER.D J TMI Program Office 80/08/14 4pp
- --8009020304 Expresses concerns re nuclear energy Opposes venting of radioactive gases & release of contaminated water ROGERS.L. Affiliation Unknown 80/03/29 3pp
- 8007020310 Responds to 800313 ltr re release of Kr-85 Potential public health impact from using any proposed strategies for removing Kr-85 is negligible Purging method is quickest & safest for workers to accomplish SNYDER, B J TMI Pragram Office. 80/08/14 2pp
- --8009020314 Expresses concern re release of Kr-85 from facility & affect on pregnancy. No releases should take place until alternative method found for cleanup BIALER, G. Affiliation Unknown 80/03/13 2pp

- 8009090369 Responds to ltr re release of radioactive matls into atmosphere from facility Based on evaluation of alternative trypton disposal methods 5 on public comment.NRC authorized controlled purging of reactor bidg SNYDER.B J TMI Program Office 80/08/14 4pp
- BO09050386 Responds to ltr re release of radioactive matl & urging permanent facility shutdown Public hearing ordered to determine whether facility should be operated & under what conditions restart would take place
  SNYDER.B J Office of Policy Evaluations BO/08/14 3pp
- --8009050391 Requests that NRC prevent release of radioactive matis & contaminated water from facility HRRY. C. Affiliation Unknown 80/08/19 1p
- 8009050496 Responds to Hillside, NJ Board of Health 800610 ltr re release of radioactive gas from facility & health effects of radiation No significant environ impact would result from use of any disposal methods of krypton gases BNVDER. B J THI Program Office 80/09/14 2pp
- --8007050498 Submits 800610 ltr to Quvernor Thornburg re release of radioactive gas from facility & health effects of radiation Venting of radioactive gas from facility will be dangerous to public health & safety BEYER, J M New Jersey, State of 80/06/10 ip
- 8009070350 Urges that period for comment of EIS be extended for period not less than 70 days
  WALTERS.P W , WALTERS.H B Affiliation Unknown 80/08/14 1p
- 800910006B Responds to 790816 itr to President Carter re release of radioactive matl from facility Only low or nondetectible levels currently permitted to be released Disposal of water processed by EPICOR-II to be discussed in programmatic EIS SNYDER.B J TMI Program Office 80/08/14 3pp
- --8009100074 Forwards C Whitney 790816 ltr & newspaper article for proper handling RATHROPF, C L. Energy, Dept of 79/09/21 4pp
- OCO9170285 Responds to 790816 ltr re release of Kr-85 Potential physical health impact on public of using any proposed strategies for removing gas negligible Purging method is quickest & safest for workers to accomplish SNYDER, B. J. TMI Program Office 80/08/14 2pp
- 8009:70362 Responds to 7908:18 ltr re release of Kr-85 Potential health impact on public of using any proposed strategies for removing gas negligible Purging method is quickest & safest for workers to accomplish
  SNYDER.B J TMI Program Office 80/08/14 2pp
- --8009170365 Expresses concern re irresponsible util activities re selease of radwaste into atmosphere Questions explanations for accidental release of radwaste Forwards newspaper clippings about accident MENEFEE, M B Affiliation Unknown 79/08/18 6pp
- BCD9230740 Responds to 800314 ltr re release of contaminated water from facility Commission has authroized use of EPICOR-II water treatment sys for waste water stored in auxiliary bldg tanks Discharge of EPICOR-II processed water not permitted SNYDER. B J IMI Program Office 80/08/14 ip.
- --8009230764 Expression concern re newspaper article on accidental dumping of radwaste in Chesapeake Bay Dumping totally insecusable & will ruin bay HEST.J B Affiliation Unknown 80/03/16 2pp
- 8009020487 Responds to 800628 mailgram to J Collins re purging of krypton gases at facility Purging method was quickest & safest for workers at facility to accomplish disposal of trypton gases W/o encl orders & NUREG-0662
  SNYDER.B J TMI Program Office 80/08/15 2pp
- ---8009020494 Protests purging of radipactive gases from facility Requests info re levels of radiation to which humans & crops were exposed during purging process
  YOUNO,R Affiliation Unknown 80/06/28 ip

- 800702048B Responds to encl L Oetlys 800321 telegram to President Carter re health effects of radiation from TMI Team of investigators has concluded that health effects from TMI accident represents minimal risk to orfsite population SNYDER.B J TMI Program Office 80/08/15 2pp
- 8009020502 Responds to B00324 ltr re specific ill effects suffered by family farm animals to pets Investigators concluded offsite collective dose from radioactive matl represents minimal health risks B/V encl summary of NUREO-0558 SNYDER.8 J TMI Program Office 80/08/15 2pp
- --8007020515 Piesents bill & claims for damages caused by effects of nuclear radiation & gas releases from +acilities Identifies specific damages & requests payment in full or settlement HDLDWAA, P Affiliation Unknown 80/03/24 4pp
- 8009050366 Responds to 800225 ltr +o First Lady re continuing operation of racilities Public hearing to be held to determine if racilities should be operated & conditions of restart H/o Commission 790809 order SNYDER, B J TMI Program Office 80/08/15 2pp
- 8009220049 Responds to encl 800505 ltr to President Carter urging revocation of facility OLs Public hearing will be held refuture operation of Unit 1 Licenses has not yet submitted proposal ror overall recovery of Unit 2 SNYDER, B J TMI Program Office 80/08/15 4pp
- BO09230233 Responds to mailgram & Itrs re release of radioactive gases & water from facility Alternatives for disposal of krypton considered prior to purging decision Collective offsite dose from 790328 accident represents minimal risks
  SNYDER.B J TMI Program Office 90/08/15 3pp
- --8009230239 Comments on NRC 790814 announcement of possibility of venting radioactive gases into atmosphere over 30-day period venting should not take place DRAZIZ The Tribune Chronicle Marren. OH 79/08/14 ip
- --8009230242 Comments on NRC 790814 announcement of possibility of venting radioactive gases into abmosphere over 30-day period venting should not take place DRAZIZ The Tribune Chronicie Warren DH 79/08/14 Ip
- --8099230245 Comments on NRC 790814 announcement of possibility of venting radioactive gases into atmosphere over 3D-day period venting should not take place/NRC on record stating that no safe dose of radiation exists DRAZIZ The Tribune Chronicle/Warren-DH 79/08/14 lp
- ---8007230247 Comments on NRC announcement of possibility of venting radioactive gases into atmosphere over 30-day period venting is immoral & should be stopped NRC findings state that no safe level of radiation exists DRAZ, Z The Tribune Chronicle, Warren, OH 79/08/14 10
- 8009030187 Responds to 800704 ltr re cleanup activities at TMI Licensee has not submitted proposal for overall plant recovery SNYDER, B J TMI Program Office 80/08/18 2pp
- --8009030194 Supports venting Kr-85 from reactor bldg Federal govt should absorb portion of cleanup costs

  EENIGENBURG, J Affiliation Unknown 80/07/04 2pp
- 8009110268 Forwards response to 800928 ltr forwarding RC Gray questions on condition of reactor core & vulnerability of equipment & instrumentation in facility reactor bidg DIRCKS, W 3 Office of the Executive Director for Operations 80/08/18 Spp
- 8009120736 Responds to 800220 ltr re handling of incident Ensures continued protection of public safety 5 health DENTON.H R Office of Nuclear Reactor Regulation. Director 80/08/19 19
- 8009180548 Responds to 800714 ltr re solution for safe removal of gases in confined areas Gas compression method was considered but to procure, install, check out 5 proof test sys would take 2 to 4 yrs
  DENION.H R Office of Nuclear Reactor Regulation, Director
  80/08/19 4pp
- --8009180560 Forwards F Rongstad 800714 ltr for review re suggestion for safe method for disposal of contaminated gases GLAUGEN, D H House of Rep. 80/08/01 1p
- ---8009180565 Forwards schematic diagram 8 explanation for safe removal of gasses in confined areas RDNGSTAD,F Affiliation Unknown 80/07/14 3pp

- 9009110501 Responds to 900623 ltr re enci 9 Trust concerns about health effects or 790328 accident % purging reactor bldg atmosphere Several of Trust concerns result from misunderstanding & misapplication of info DIRCKS:W J Office of the Executive Director for Operations 80/08/21 700
- 8009110494 Responds to 800529 ltr re CW Eneric' concerns about releases of Kr-85 into atmosphere around facility Purging approved 800612 commenced 800628 % concluded 800711 Discusses studies on thyroid disorders
  DIRCHS.MJ Office of the Executive Director for Operations 80/08/22 dop
- 8009150324 Responds to 790701 ltm to MRC me TMI accident Commission has ordered public hearing to determine whether TMI-1 should be operated Communication difficulties attributed to impairment of info from control soon to offsite groups SMYDER. B J TMI Program Office 80/08/22 App
- --8009150327 Expresses concern re TMI accident Util deliberately deceived public in crucial days following accident & should not be allowed to reopen TMI-1 MODDLEF.SE Affiliation Unknown 79/07/01 4pg
- 8009150330 Responds to 800326 ltr re reopening of TMI Licensee has not submitted proposal for overall recovery of Unit 2 NRC 790702 order directed Unit 1 to remain in cold shutdown, pending outcome of restart hearing SN1DER.8 J TMI Program Office 80/08/22 2pp
- --8007150336 Requests cleanup & reopening of TMI RABUCK.B Affiliation Unknown E9/03/26 4p
- 8009150343 Responds to ltr to NRC re reopening of TMI facilities Public hearing will be held re TMI-1 restart Licensee has not submitted proposal for overall recovery of TMI-2 SNYDER.B.J. TMI Program Office 80/08/22 2pp
- --8007150346 Expresses desire for TMI restart Util followed all notification procedures on 790328 NRC & util should be supported in cleanup operation SMITM.J & Affiliation Unknown 80/08/22 2pp
- 8009150441 Responds to 800609 itr expressing concern re radwaste ventilation 2 cleanup Potential physical health impact on public of using any proposed strategies for removal of Kr-85 is negligible BNYDER.B J TMI Program Office 80/08/22 2pp
- ~~8009150445 Expresses concern re raduaste ventilation & cleanup LOCK,J Affiliation Unknown 80/06/09 19
- 8009180452 Responds to encl People of the Earth ltr to President Carter expressing concern for release or Xr-85 from Unit 2 Potential physical health impact using any proposed strategies re Kr-85 removal is negligible SNYDER.B J TMI Program Office 80/08/22 4pp
- 8007160101 Responds to encl 771031 ltr to President Carter re actions taten at TMI Licensees of all operating plants utilizing PMRs have been instructed to take actions re status of equipment procedures & facility designs
  SNYDER.B J TMI Program Office 80/08/22 App.
- 8009170297 Responds to 800216 Itr urging revocation of util DL NRC has ordered public hearing re TMF-1 restart Util has not submitted proposal for overall recovery of Unit 2 SNYDER B J TMI Program Office 80/08/22 ip
- --8009170263 Urges revocation of util OL for TMI CONHEY,J Affiliation Unknown 80/02/16 2pp
- 8009170271 Responds to encI 800411 ltr to President Carter re safety of TMI vicinity NRC.EPA & HEW investigations have shown offsite dose associated w/radicactive mati released from 790328-0429 represents minimal risk SNYDER.B J TMI Program Office 80/08/22 3pp
- 8009230194 Responds to 1tr urging revocation of util DL.NRC has ordered public hearing to determine Unit 1 operation feasability & possible restart conditions Licensee has not submitted proposal for overall recovery of Unit 2 SNYDER.B J TMI Program Office 80/08/22 ip
- --8009230202 Urges revocation of util CL BRISCOE.G A Affiliation Unknown 80/08/22 1p

- 8009230216 Responds to 790726 ltr re TMI accident & subsequent ventilation of radwaste Potential physical impact on public fram using any proposed method for removing Kr-85 is negligible
  SNYDER,E J TMI Program Office 80/08/22 5pp
- --8009230222 Requests info re TMI accident & subsequent ventilation of radwaste GLANIZ,C Affiliation Unknown 79/07/26 2pp
- 8009100206 Responds to 800421 ltr to President Carter re operator training & public awareness re TMI accident Human errors due to incorrect interpretation of RCS instrumentation Centralized dissemination of NRC info planned SNYDER.8 J YMI Program Office 80/08/25 App
- 8009150321 Responds to postcard re safe decommissioning of nuclear reactors & studies of reactor health effects Specific NRC actions include employment of full-time inspectors at TMI, license on instruction & emergency preparedness planning SNYDER.B J TMI Program Office 80/08/25 2pp
- --8009190325 Requests safe decommissioning of all commercial nuclear reactors & performance of health impact studies to determine effects of nuclear energy XELLYK Affiliation Unknown 80/08/25 2pp
- 8009150351 Responds to 800403 ltr re release of Kr-85 at facility NRC evaluated alternative methods for venting Kr-85 to determine effect on personnel.public health & safety & environ Environ assessment issued for public comment SNYDER, B J TMI Program Office 80/08/25 2pp
- --8009190355 Expresses concern ro venting Kr-85 at facility NRC attitude toward psychological stress may be major factor in venting delay BURGER, A C Affiliation Unknown 80/04/03 2pp
- 8009190750 Responds to encl 800424 ltr to President Carter expressing concern re TMI effects on environ Efforts made to ensure continued welfare of public outlined SNYDER.B J TMI Program Office 80/08/25 9pp
- 8009110280 Responds to 800728 itr requesting info re safety of Midland & Fermi plants All nuclear plants subj to enhanced safety requirements resulting from TMI Lessons Learned Task Force recommendations Supporting documentation encl DIRCKS W J Office of the Executiva Director for Operations 80/08/26
- --8009110288 Requests consideration of encl MC Haight ltr re safety of Midland & Fermi plants
  BROOMFIELD.H S House of Rep : Foreign Affairs 80/07/28 2pp
- B009110314 Responds to 800710 ltr re R Collins concerns about facility decontamination Prior to purging NRC examined several alternatives for decontamination Krypton exists normally as only one constituent of air breathed DIRCKS, N J Office of the Executive Director for Operations.
- ~~8009110319 Forwards R Collins 1tr inadvertently omitted from 800710 tr W/o encl PICPLE.J J House of Rep , Ways and Means 80/07/23 1p.
- --B009110322 Requests comment on encl R Collins ltr questioning NRC decision to vent facility krypton gas
  PICKLE,J J House of Rep , Ways and Means 80/07/10 3pp.
- 8009170004 Responds to 790810 itr re accident at TMI NRC has ordered public hearing to determine whether TMI-1 should be operated & under what conditions restart would take place Licensee has not yet submitted proposal for overall recovery SNYDER, B J TMI Program Office. 80/08/26 Spp
- --8009170011 Urges NRC to restore feeling of normalcy to community around YMI Recommends that NRC wait until all investigations are completed before reopening TMI-1 Any premature opening would suggest that economics come before public safety HEIVLY.B J Affiliation Unknown 79/08/10 3pp
- 80091702B3 Responds to 800216 ltr re release of Kr-B5 Potential physical health impact on public of using any proposed strategies for removing gas negligible Purging method is quickest & safest for workers to accomplish SNYDER.B J TMJ Program Office 80/08/27 2pp

- --9009\$70284 Expresses concern re release of radioactive matis into atmosphere Facility CL, should be revoked because of MetEd lies & incompetence CLAY.R V Affiliation Unknown 80/02/16 2pp
- BOO9110212 Responds to 800709 ltr re N Ginder telcon about radio rept on krypton found in soil following facility purging Krypton is noble gas which is chemically inert & does not concentrate in soil DIRCKS U J Office of the Executive Director for Operations 80/08/28 2pp
- 8009110218 Forwards response to 800728 ltr requesting assistance in amswering constituent questions re nuclear power & effects of radiation DIRCKS, M J Office of the Executive Director for Operations 80/08/28 4pp
- 8009090502 Suppl change request for organization plan.Revision 1.which defines proposed new mgt organization Proposed change does not aiter licensee responsibility for operation MOVEY, 6 K. Metropolitan Edison Co. 80/08/27 ip
- 8009090556 Forwards revised pages to 800812 submittal re organization plan.Pevision 14 MOYEY,O K. Metropolitan Edison Co. 80/08/29 Spp
- 8009160596 "Organization Plan"

  # Netropolitan Edison Co 80/08/29 ip
- SOCTIBOJBI Opposes extension of 45-day period for public comment on NAFEG-CABJ Addl delay would seriously hamper operation of cleanup & cause economic hardship on area residents BOCAB,P A Affiliation Unknown BO/09/04 ip
- 8009090380 Urges NRC to survey sociaeconomic composition of Cumberland County re preliminary DES concerning TMI cleanup MYERS, J A , PUNT, N A Cumberland County, PA 80/09/05 2pp
- 8009090571 Requests extension of public comment period re programmatic £18 NRC treatment of public & opposition ltrs during comment period re krypton venting lacked honesty & decency HOLKER,H M Affiliation Unknown 80/09/05 3pp
- BOO9150546 Requests copyright release for 15 articles re TMI accident published in the NY Times
  SNYDER/B J TMI Program Office BO/09/05 2pp
- BOOT:50547 Requests copyright release for 19 articles published in PMIAdelphia Inquirier re TMI accident SM/DER.B J TMI Program Office 80/09/05 2pp
- 8009300001 Requests that encl copyright release form for listed article be signed & returned to NRC by 800919 Article was śnidwertently printed in Vol 2 of "Final EIA for Decontamination of TMI-2 Reactor Bldg Atmosphere "
- BOOP300610 Requests that encl copyright release form for listed articles be signed & returned to NRC by 800919 Article was inadvertently printed in Vol 2 of "Final EIA for Decontamenation of TMI-2 Reactor Bldg Atmosphere"

  SNYDER. B J TMI Program Office 80/09/05 2pp
- 8009300536 Requests that enci copyright release form for listed article be signed & returned to NRC by 800919 Article was inadvertently printed in Vol 2 of "Final EIA for Decontaination of TMI-2 Reactor 81dg Atmosphere "
- 6009300638 Requests that enci copyright release form for listed articles be signed & returned to NRC by 800919 Articles were inadvertently printed in Vol 2 of "Final EIA for Decontamination of TMI-2 Reactor 81g Atmosphere"

  ENVDER. 8 J IMI Program Office 80/09/09 2pp
- 8009180338 Supports view of nuclear power as unhealthy & counsels patience in search for alternative energy sources Supports 90-day pariod for public comments re EIS KATTENBACHER, F Affiliation Unknown 80/09/11 2pp.
- 8009220215 Requests 90-day extension for comments on EIS EAB-M 8 Affiliation Unknown 80/09/12 ip
- 9009290331 Discusses study re mutant plants as result of TMI accident instruments may be able to detect radiation, but not genetic damage Mauspaper articles re study encl AREHARTIT. Affiliation Unknown 80/09/12 3pp

- 8009230126 Informs that organization plan submitted in 800821 ltr & supplemented in 800829 ltrs re mgt & support of facility in current status has been approved COLLINS.J T TMI Program Office 80/09/15 4pp
- 8009300159 Responds to 1tr re excessive electric bil) NRC does not set rates that utils charge for electricity Accident at Unit 2 also caused Unit 1 to be shut down Excerpt From DOE
- --8009300163 Expresses concern re high util bills People on fixed incomes cannot afford cost of energy FASIG.F Affiliation Unknown 80/09/15 ip
- 8009290148 Adds name.as Township Manager for Springettsbury Township, to distribution list for documents re TMI.as requisted in BOOBS2 1tr SNYDER:B J TMI Program Office BO/09/16 1p
- I Financial information
- --B007070508 "Financial Forecast Reflecting Revised Estimate of TMI-2 Clean-up & Recovery " Util B00808 press release enct \* General Public Utilities -- GPU Service Corp B0/08/14 41pp
- 8009180370 Forwards Citibank.N A 800905 itr notifying General Public Utils Corp of reduction in util credit availability,per 800910 telcon request CARROLL.D General Public Utilities GPU Service Corp 80/09/11
- 8009180359 Forwards matis re Ceneral Public Utils Svc Corp economic measures SN Shanaman (PA Public Utils Commission) 800827 statement to PA Congressional delegation encl HDWSON.T G General Public Utilities GPU Service Corp 80/09/12
- P Operating license stage documents & correspondence
- 8009020493 "Final Environ Assessment for Decontamination of TMI Unit 2 Reactor Bldg Atmosphere," Vol 1 of final NRC staff report # TMI Program Office NUREG/CR-1662 VI 80/05/31 96pp Available at NTIS
- 8008060358 Forwards errata sheets correcting errors in five add1 TMI-2 related requirements submitted by 800507 ltr Hems involved are II K 3 25.11 K 29 b II K 3 44 Svc lists encl EISENHUT,D 6 Division of Licensing 80/04/09 69pp
- 8009110963 Responds to 1E comments re TMI-2 Lessons Learned Tech Specs Proposed addition is covered in currently existing Tech NOVAK, T M Assistant Director for Operating Reactors 80/06/10
- 8007050370 FOIA request for list of all isotopes found in facility containment bldg atmosphere samples for 800301-0612
  BALTER, J. Public Interest Law Center of Philadelphia 80/06/12
- 8007020152 Requests clear copies of util missing documents referenced in Rogavin rept within 30 days of raceipt of ltr Missing list of documents encl SNYDER.B.J. TMI Program Office 80/07/02 5pp
- 8009090592 Forwards draft programmatic EIS re decontamination & disposal of radwastes resulting from 790328 accident at facility Request for public comments is being sent to Ofc of Federal Register Wio encl SNYDER. 8 J TMI Program Office 80/07/30 ip
- --8009090404 Notice of issuance & availability of draft programmatic EIS for decontamination of facility SNYDER:8 J TMI Program Office 80/08/11 2pp
- --8009090611 Forwards FR notice & draft programmatic EIS re decontamination & disposal of raduastes resulting from 790328 facility accident W/o encl SNYDER.B J TMI Program Office 80/08/14 4pp

- E0090B00B0 Forwards draft NUREO-0696. "Functional Criteria for Emergency Response Facilities " Cormonts requested within 30 days Proposed implementation schedule for meeting criteria or NUREO-0696 enci W/o NUREO EISENHUT, D @ Division of Licensing 80/08/01 119pp
- 8007070603 Responds to LE Reynolds 800715 request for proprietary classification of SDS polishing unit description Rept withheld (ref 10CFR2 790)

  CGLLING.J T hRC Three Mile Island Task Force 80/08/06 4pp

B009110676 Responds to G Hovey B00725 ltr re pre-accident spent resin disposal Concurs w/disposal plan for matl generated prior to COLLING, J T NRC Three Mile Island Task Force 80/08/06

- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disreganded Requested submittal should include proposed class of amend EISENHUT, D G Division of Licensing 80/08/07 40pp
- 8009050367 Responds to FOIA request for list of all isotopes found in facility containment bldg atmosphere samples for 800301-0612 Forwards document
- Division of Rules and Records 80/08/08 1p
- --8009050376 Analyses of gaseous isotopes found in facility containment bldg atmosphere for 800301-0412 4 Netropolitan Edison Co 80706/12 2pp
- 8009090783 Informs of NRC actions re NUREO-0683, "Programmatic EI8 on Decontamination & Disposal of Radwaste Resulting from 770328 Accident at IME-2" Lists findings & conclusions re environ impacts of cleanup M/o encl NUREO-0683 DENION, HR Office of Nuclear Reactor Regulation, Director SECY-80-295A 80/08/11 4pp
- 8009190619 Advises that NRC considers TMI-2 reactor bidg atmosphere purge complete as of 800711 Effluent releases should again be conducted in accordance w/original App B Tech Specs SNYDER.B J TMI Program Office 80/08/13 3pp
- 8009090155 Forwards proposed outline for revising document draft, "Psychological Stress & Alternatives for Decontamination of TMI Nuclear Station.Unit 2" Restart or decommissioning of plant beyond scope of document REGAN.W H Siting Analysis Branch 60/08/18 5ρρ
- 8007020037 Responds to MRC 800806 ltr requesting commitment date for submittal of contingency plan for alternate storage of reactor bldg sump water Plan will be completed ut of 801013 & submitted by 801017 ARMOLD.R C Metropolitan Edison Co 80/08/22 1p
- 8009020075 Forwards ORNL Jul 1980 rept "Evaluation of Submerged Demineralizer Sys Flowsheet for Decontamination of High-Activity-Level Mater at THI-2: " per commitment to update 800613 response re column performance test results HOVEY, G K Metropolitan Edison Co 80/08/22 ip
- --8009020080 "Evaluation of Submerged Demineralizer Sys Flowsheet for Decontamination of High-Activity-Level Water at TMI-2" CAMFDELL.D C. COLLINS.E D. KING.L. J. Oak Ridge National Laboratory ORNL/TM-744B 80/07/30 Slpp
- 8009030529 Forwards ORKL final rept "Evaluation of Submerged Demineralizer Sys (SDS) Flowsheet for Decontamination of High-Activity-Level Mater at TMI Unit 2 Muclear Power Station HOVEY, G.K. Metropolitan Edison Co. 80/08/22 2pp
- --8009030534 "Evaluation of Submerged Demineralizer 8gs (SD8) Flowsheet for Decontamination of High-Activity-Level Water at THI Unit 2 Nuclear Power Station " CAMPBELL.D O. COLLINGS.E D. KING.L J. Oak Ridge National Laboratory ORML/IN-7448 80/07/31 84pp
- 6009120677 Forwards review.w/comments & questions.of EPICOR II resin solidification test program COLLINS, J T TMI Program Office 80/08/22 App
- 09t00145 Forwards responses to Ofc of Elecutive Director for Operations comments on NRC overview of TMI-2 radiation protection program
  DENION, H R
  Qffice of Nuclear Reactor Regulation, Director
  BOYOB/25 3pp

- -8009100151 Forwards draft philosophy statement & alternate proposals for TMI Site Ofc.in response to 800228 request Info re radiation protection plan encl CREMS.J L. Region 5. San Francisco. Reactor Operations Nuclear Support Branch 80/02/29 24pp
- 8009030473 Forwards missing documents previously provided by util to NRC/TMI Special Inquiry Group in response to 800718 request Provides listing of documents Documents are cross referenced to Rogovin rept M/o encls
  HOVEY.G X Metropolitan Edison Co 80/08/26 2pp
- 8009i60394 Notifies of reversal of util 800324 plan re relocation of EPICOR-I Bys to Unit 2 side of fence Sys is mostly used to process TMI-I wastowater Relatively small amounts of Unit 2 wastewater treated by sys HOV⊂Y, G K Metropolitan Edison Co 80/08/26 3pp
- 8007030421 Requests 45-day extension to comment period for programmatic £15 re TMI cleanup process Public hearing should be conducted prior to drafting of final version £HCLLY.5 C \_ Three Mile Island Public Interest Resource Center 2pp 80/08/27
- 8009040412 Ack receipt of NUREO-0683 re decontamination & disposal of radwastes at TMI-2 NUREO does not address possibility that zirconium hydridos may be present in reactor core Presence of zirconium may change procedures for removal & disposal GULBRANSEN.E A Pittsburgh, Univ of 80/08/27 2pp
- 8009120582 Responds to FOIA request for two documents concerning ECC8 in B3W reactors Forwards documents FELTON, J M Division of Rules and Records 80/08/28 1p
- --8009120589 Forwards results for TMI-2 severe overcooling transient w/
  upperhead connection includes geometry changes to better fit
  FBAR data, vent valves between upper plenum & downcomer & new
  steam generator secondary pressure table
  WILLCUTT, 0 J F Los Alamos Scientific Laboratory 80/06/25
- 8009030554 Requests extension of public commentary date for EIS beyond 801005 Stresses length.complexity & importance of EIS EPSTEIN.E G Affiliation Unknown 80/08/29 2pp
- 8009090421 Comments on sections of draft programmatic EIS re psychological atress issue Rept implies that residents w/ misgivings about util & regulatory competence are unbalanced Rept lacks objectivity & empathy WALSH.E J Affiliation Unknown 80/09/03 ip
- 8007140382 Responds to 800718 request for comments re evaluation of EPICOR II wastes Evaluation will not be completed until end of Sept 1980 dur to Epicor. Inc proprietary restrictions on release or info Forwards waste staging drawings M/O encl HOVEY, O K Metropolitan Edison Co 80/09/04 Sep
- 8009160395 Forwards Attachments 2 & 5 to util 800904 ltr re evaluation of EPICOR-II wastos Attachments withheld (ref 10CFR2 790) HOVEY, G K Metropolitan Edison Co 80/09/04 lp
- 8009180371 Requests extension period to study TMI DES Public needs more time to understand study MATI.C H Affiliation Unknown 80/09/05 lp
- 8007260050 Requests that encl copyright release form for listed article to signed 5 returned to NRC by 800919 Article was inadvertently printed in Vol 2 of "Final EIA for Decontamination of TMI-2 Reactor Bldg Atmosphere "
- 8007240083 Requests that encl copyright release form for listed article be signed & returned to NRC by 800717 Article was inadvertently printed in Vol 2 of "Final EIA for Decontamination of TMI-2 Reactor Bldg Atmosphere "
  SNYDER.B J TMI Program Office 80707/05 2pp
- 8009240093 Requests that encl copyright release form for listed article be signed & returned to NRC by 800919 Article was inadvartently printed in Vol 2 of "Final EIA for Decontamination of THI-2 Reactor "Bldg Atmosphere."

  SNYDER, B J TMI Program Office 80/09/05 2pp.
- BOO9120494 Discusses "primary method of decay heat removal" interpretation & provides insight re util intended method of docay heat removal Requests that MDHR sys recovery operations plan change request be approved as written HDVEY,O K Metropolitan Edison Co 80/09/08 3pp

- BOOT150432 Submits addl info requested by NRC re 480 volt buses 2-38 & 2-49 per MDNR Tech Spec change request Buses are no longer required, due to supplementary ventilation sys being taken out of svc HGVEY, Q K Hetropolitan Edison Co 80/09/08 ip
- --B009150435 "480 V USS 2-38,2-48 & Distribution Panel PDP-5A,5B Dne Line Diagram "
  Burns & Roe Co 79/08/31 1p
- 8009150554 Responds to NRC concerns re util 800731 request for Tech Spacs & recovery operations plan changes required for MDHR sys Change establishes criteria for selection of lower standby pressure control sodium bank pressure HQVEY.G K Metropolitan Edison Co 80/09/08 1p
- 8009160391 Forwards Attachments 2 & 5 to util 800904 ltr re drawings of waste staging facility per requests for comments on evalvation of EPICOR II wastes Info withheld tref 100FR2 7909
  HOVEY: 0 K Hetropolitan Edison Co 80/09/08 4pp
- BCC9170316 Forwards "Preliminary Sys Description Task Ts=27.Mini Decay Heat Removal Sys," Revision 3 HOVEY.C K Metropolitan Edison Co 80/09/08 ip
- --B009170317 "Preliminary Bys Description Task Ts-27.Mini Decay Heat Removal Bys." Revision 3 BROWNEWELL, R P Burns & Roe Co 80/08/19 62pp
- 8009170377 Requests approval for shipment of several EPICOR II resin liners which have been expended during course of processing auxiliary bldg waters Dates of proposed shipments not established HOVEY.O K Metropolitan Edison Co 80/09/OB ip
- BOD7180359 Requests extension of 45-day comment period for facility EIS to 90 days
  SCHAUDEL,S L Affiliation Unknown B0/09/08 ip
- E009290235 Ack acceptance of invitation to study health & safety consequences associated w/disposition of decontaminated accident generated waste water Draft preliminary EIS & radionuclide distribution tables encl DEMTON: If R Office of Nuclear Reactor Regulation, Director 20/09/08 5pp.
- BO09110328 Forwards "TMI-2 Recovery Program Estimate "
  CMIN.W Y General Public Utilities GPU Service Corp BO/09/09
  19
- --8009(10330 "TMI-2 Recovery Program Estimate " \* General Public Utilities - GPU Service Corp 80/08/01 69pp
- 8009120416 Forwards draft Tech Spec 3 3 1 1 re neutron monitoring instrumentation in response to 800822 ltr Radiation level 44ta for containment entries will be provided by licensee FSSR & other mat1 available in LPDR GDLDBERG.8 C Hearing Branch 2 80/09/10 4pp
- 8009180391 Requests extension of period for comment on EIS,NUREG-0683, to 90 days KNOUFF.Q Affiliation Unknown 80/09/10 1p
- 800922027 Forwards color photo negatives from second entry into containment bldg W/o enc! HOVEY.G K. Metropolitan Edison Co. 80/09/11 1p
- BO09220342 Urges NRC to extend deadline from 45 days to 60, for study & comment on EIB
  PETERSON, J M Affiliation Unknown BO/09/11 1p
- 8009160359 Forwards matts re General Public Utils Syc Corp economic measures 8M Shanaman (PA Public Utils Commission) 800827 statement to PA Congressional delegation encl HOWSON, T G General Public Utilities GPU Service Corp 80/09/12 279p
- --B009160961 Biscusses actions taken by owners re TMI-2 cleanup plans DIECKAMP.H General Public Utilities - GPU Service Corp B0/09/12 3pp
- 8009170265 Advises that util will not rely on regulatory guidance or definition of criteria or approval to proceed w/major cleanup activities until completion of final programmatic EIS
  DIECKAMP. H Owneral Public Utilities GPU Service Corp 80/09/12.

- 8009220346 Requests extension of 45-day period for public comment on EIB to 90 days Cites public concern that NRC favors util stockholder interest over public safety BI(LER.E Affiliation Unknown 80/09/12 ip
- 8009220129 Submits info re personnel training for submerged demineralizer sys Multiphased approach includes classroom training re sys operation, theory & practical factors training NRC participation welcomed HOVEY.G K. Metropolitan Edison Co. 80/09/15 ip
- B009250440 Ack receipt of B00826 ltr re operation & location of EPICOR-I Requests indication of what measures are available to assure that sys will not be operated by Unit 1 Procedure 1104-29% COLLINS.J T TMI Program Office B0/09/15 2pp
- 8009240541 Forwards tritium monitoring results from TMI groundwater & soil samples Tritium level analysis in Observation Wells OW-138. GN-14 & DW-17 encl RIETHLE, W.E. General Public Utilities GPU Service Corp. 80/09/16 26pp
- 8007220276 Responds to NRC 900805 ltr submitting recommendations re TMI worker registry for use in potential studies of radiation effects Proposed definition of worker would be impractical, due to number of visitors receiving little or no radiation HGVEY, G K Metropolitan Edison Co 80/09/30 2pp
- 8009300389 Submits clarification of 2 interpretation re definition of primary method of decay heat removal 2 intended method of decay heat removal HGVEY, G K Metropolitan Edison Co 80/09/30 App
- Q Inspection reports. IE Bulletins & correspondence
- 8009030044 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Retted Matrix Relays in Reactor Protective Sys of Operating Muclear Power Plants Designed by C-E " Uritten response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/08/15 1p
- B009020241 Responds to IE Bulletin 79-23 Review of emergency diesel generators revealed that no connection exists between generator neutrals & primary winding of exciter jower transformer Operational tests failed to show subj. condition HOVEY, O. K. Metropolitan Edican Co. 80/08/22 2pp
- 8009030372 Responds to IE Bulletin 80-05 Review indicates that 28 of 30 tanks are adequately protocted from Nacuum condition resulting in tank buckling Supporting documentation encl HOVE, G K Metropolitam Edison Co 80/08/22 App
- 8009180013 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/08/22 1p
- 8009120184 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers" No written response required ORIER 8 H Region I, Philadelphia, Office of the Director 80/08/27 ip
- 8009170334 Notifies that response to findings of NRC special inspidentified in Stello 800807 ltr to Arnold, will be submitted by 800909 HDVEY, 0 K Metropolitan Edison Co 80/09/05 lp
- 8009300014 Responds to NRC 800807 ltr re violations noted in IE Insp Repts 50-320/80-10 & 50-320/80-14 Containers for liquid radwaste now meet code requirements Containment vessels proven leak resistant Payment for civil penalties encl ARNOLD, R C Metropolitan Edison Co 80/09/08 4pp
- 8007230790 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required ORIER,8 H Region 1, Philadelphia, Office of the Director BD/09710 Ip
- 8009240316 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required GRIER.B H Region i, Philadelphia, Office of the Director 80/09/12 lp

- R Periodic operating reports & related correspondence
- 8009020135 Forwards weekly status lept for 800803-09 CCLLINS,J T THI Program Office 80/08/11 App
- 8009070796 Forwards status rept for w/ of 800810-16 COLLINS.J T TM! Program Office 80/08/18 App
- 8009100375 Forwards TMI Program Ofc status rept for wk of 800817-23 COLLINS, J T TM1 Program Office 80/08/25 5pp
- 8009190539 Forwards weekly status rept for wk ending 800823 COLLINS. J T TMI Program Office 80/08/25 5pp
- 8009150532 Forwards weekly status rept for wk ending 800829 COLLING.J T TMI Program Office 80/08/29 4pp
- 8009110316 Forwards supplemental info to "Effluent & Haste Disposal Semiannual Rept, Jan-June 1980." for TMI-! 1 2 & EPICOR-II & supplemental info to "Effluent & Waste Semiannual Rept, 791015-1231." for EPICOR-II
  HERBEIN
- --8007110333 Supplemental info to "Effluent & Waste Disposal Semiannual Rept. Jan-June 1980 " # Metropolitan Edison Co 80/09/05 24pp
- --8009110340 Supplemental info to "Effluent & Waste Disposal Semiannual Rept.Jan-June 1780." for EPICOR-II \* Metropolitan Edison Co 80/09/05 8pp
- ~-809110344 Supplemental info to "Effluent & Waste Disposal Semiannual Rept.for 791015-1231" re EPICOR-II 4 Metropolitan Edison Co 80/09/05 Spp
- 8007180204 TMI Program Ofc weekly status rept for wk of 800830-0906 COLLINS, J T TMI Program Office 80/09/08 App
- 8009190490 Forwards info re 1979 annual rept of aquatic ecological studies of TMI in response to NRC 800805 request HOVEY,O K Metropolitan Edison Co 60/09/12 9pp
- 8009270481 Forwards weekly status rept for wk of 800907-13 COLLINS, J T TMI Program Office 80/09/15 4pp
- 8009300550 Forwards trutium results from TMI groundwater & soil samples obtained on 800530,0707,18 & 25 Results of analyses performed on soil samples from OM-138,0M-14 & OM-17 RIETHLE, IF E General Public Utilities - GPU Service Corp 80/09/16 2700
- 8009300399 Forwards "Executive Summary, TMT Units 1 & 2 Liquid & Gaseous Releases for Jul 1980. addl data for biquid discharges to Susquehanna River for 1980 % explanation of TM1 efficent & Busquenanna Kiver for 1760 - expension of the Constitution of the
- --0009300401 "Executive Summary, TMI Units 1 & 2 Liquid & Caseous Releases for Jul 1980 " Tables providing add1 data for liquid discharge to Susquehanna River enc! 4 Porter-Gert: Consultants, Inc. 80/09/19 13pp
- S Reportable occurrences. LERs & related correspondence
- 8009020378 Forwards LER 80-030/01L-0 Metropolitan Edison Co 80/08/20 is
- --8009920387 LER 80-030/01L-0 on 800717, following first reactor bldg 0090-2038/ Lek bu-030701L-0 on a00717.1010ming first reactor entry since Mar 1979 accident.600r seal leakage detected in excess of Tech Spec limit Apparently caused by some foreign mati remaining on seal after cleaning CHAPLIN-S D Ketropolitan Edison Co 80/08/18 2pp
- 8009030349 Forwards LER 80-034/03L-0 H0VEY.0 K Metropolitan Edison Co 80/08/25 1p
- ---8009030361 LER 80--034/03L-0 on 800725 during recovery mode, use of hot cater hydrolasing set off fire alarm in fuel handling bldg Ventilation automatically shut down & was not returned to see for 5-h Caused by operator response to fire alarm CHAPLIN.S D Metropolitan Edison Co 60/08/25 3pp

- 8009050243 Informs that LERs 79-013.79-019.80-017 & 80-021 have been PERKINS,M A Office of Inspection & Enforcement, Office of the
- Director 80708702
- --8007050245 LER 80-017 has been cancelled \* Metropolitan Edison Co 80/09/02
- -8009050246 LER 79-013 has been cancelled
- --8009050247 LER 79-019 has been cancelled \* Metropolitan Edison Co 80/09/02
- --8009050249 LER 80-021 has been cancelled \* Metropolatan Edison Co 80/09/02
- 8009180415 Engwards LER 80-036/011-0 HOVEY, D. K. Metropolitan Edison Co 80/09/05 1p
- --8009180426 LER 80-036/01L-0 on 800808, failed to perform RCS coolant dissolved baron & hydrogen analyses Cause by contamination of B&N R&D facility Util in process of establishing onsite capabilities for performing RCS coolant analyses CHAPLIM:S D Metropolitan Edison Co 80/09/05 3pp
- 8009120402 Forwards LER 80-035/03L-0 HOVEY, G K Metropolitan Edison Co 80/09/08 1p
- ---8009120406 LER 80-035/03L-0 on 800731 during recovery mode operation trouble alarm received in control room Caused by Failed flame detectors within balance of plant diesel generator Detector replaced Diesel generators removed from specs. CHAPLIM.8 D Metropolitan Edison Co 80/09/05 3pp
- 8009120450 Forwards LER 80-033/01L-0 HOVEY.G K Metropolitan Edison Co 80/09/08 1p
- --8007120452 LER 80-033/01L-0 on 800730.Gould-ITE reported possible failure of relay pneumatic timing device. Model J2013 Caused by age & deterioration.coupled w/kwo failures of timers & erressive need for recalibr Failed timers replaced CHAPCIN.8 D Metropolitan Edison Co 80/09/09 Spp
- 8009180404 Forwards LER 80-037/01L-0 HGVEY, G K | Metropolitan Edison Co | 80/09/09 | 1p
- --8009180408 LER 80-037/01L-0 on 800808, leak rate testing of reactor bldg personnel air lock door 2 showed excessive leakaga Caused by failure to equalize pressure inside & outside airlock resulting in door suddenly opening & striking wall CHAPLIN.8 D Metropolitan Edison Co 80/09/08 3pp
- T Hearing transcripts on non-antitrust matters
- 8009260313 Submittal of prepared testimony for first hearing session No attempts made to provide complete answers to ASLB 800908 memorandom & older re physical separation of TMI units Certificate of Svc ent. Related correspondence TROWBRIDGE.OF Metropolitan Edison Co 80/09/15 7pp
- ---8009260366 "Small Break Operating Guidelines " Related correspondence \* Babcock & Wilcox Co 69-1106001-00 79/11/30 48pp
- U Congressional/Executive Coirespondence
- B007020476 Provides Subcommittee on Nuclear Regulation w/NRC rept.
  "NRC Plan for Cleanup Operations at TM1-2" Portions of plan
  subj to change as cleanup work & related investigations
  continue H/o encl
  DIRCKS.N J Office of the Executive Director for Operations
  80/08/15 ip
- 8009020482 Provides Subcommittee on Energy & Power w/NRC rept. "NRC Plan for Cleanup Operations at TMI-2 " Portions of plan subj to change as cleanup work & related investigations continue W/o encl DIRCKS.N J Office of the Executive Director for Operations 80/08/15 ip
- 8009020489 Provides Subcommittee on Environ.Energy & Natural Resources W/MRC rept, "NRC Plan for Cleanup Operations at TMI-2" Partions of rept subj to change as cleanup work & related investigations continue W/o encl DIRCKG, W J Office of the Executive Director for Operations 80/08/15 1p

- 8009020496 Provides Subcommittee on Energy & Environ w/NRC rept. "NRC Plan for Cleanup Operations at TMI-2" Portions of plan subject or change as cleanup work & related investigations continue M/o enci DIRCKS, N J Office of the Executive Director for Operations 80/08/N J 0
- BO09110486 Responds to 800703 ltr requesting comments on P Montague statement to Editor of NY Times on cessum content of spent resins from EPICOR-II processing sys Wastes are considered suitable for burial at commercial low level disposal site DIRCKSH J Office of the Executive Director for Operations 80/08/25 2pp
- --B009110491 Requests comments on encl statement by P Montague of Nati Campaign for Radwaste Bafety, to Editor of NY Times on cesium content of spent resins from EPICOR-II processing sys GTTINDER.R L House of Rep 80/07/03 2pp
- BOO7070570 Opposes any decision to dispose of facility radwaste at any DDE facility & specifically at Savannah River facility Waste should be disposed w/other commercial waste rather than w/defense waste DERRICK-B House of Rep 80/08/28 ip
- V Operator Examinations
- 8009030464 Forwards Administrative Procedure 1006.operator requalification program & status of requalification program for Unit II operators Replacement operator training program will be submitted upon completion HERBEIN.J O Metropolitan Edison Co 80/08/08 2pp
- --8009030469 "Administrative Procedure 1006, Revision 3," operator requalification program Status of requalification program for Unit II operators encl

  \* Hetropolitan Edison Co 80/07/31 42pp
- 8009080240 Forwards operator requalification program per 800328 1tr HERBEIN.J G Metropolitan Edison Co 80/08/08 2pp
- F Security, medical, emergency & fire protection plans
- BO09236245 Requests that all personnal be reminded of purpose of emergency notification sys & health physics network Bys installed for govt use during emergency O'REELLY, J.P. Region 2, Atlanta, Office of the Director BO/OB/22 lp
- 8009030484 Notifies that final version of upgraded emergency plan will be submitted by 810102 WIDNER,H A Georgia Power Co 80/08/28 ip
- 8009140448 Informs of util concept of physical means for alerting & providing clear instructions to populace within plume exposure emergency planning some Design concept is to provide tone alert receivers for all establishments in zone HIDNER, N A Georgia Power Co 80/09/12 3pp
- G Adjudicatory correspondence
- 8009240597 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 REJD.R W Operating Reactors Branch 4 80/08/29 2pp
- ---8009240603 Order for mod of Licenses DPR-57 & NPF-5 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101

  EESENGUT, D © Division of Licensing 80/08/29 App.
- P. Operating license stage documents & correspondence
- 8009110954 Supple NRC 800707 request for proposed Tech Specs changes re scream discharge vol vent & drain valves. & reactor protection sys & control rad block limit switch surveillance requirements Class III license fee to be submitted w/change EISEMBUT D O Division of Licensing 80/07/22 22pp
- BOO9020297 Bubmits interim criteria for shift staffing to all OL & CP licensess & applicants, per NRC 800507 ltm Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENMUT, D O Division of Licensing 80/07/31 7pp

- 8009080080 Forwards draft NUREC-0696, "Functional Criteria for Emergency Response Facilibles" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREC-0696 encl W/o (NUREC EISENHUT, D C Division of Licensina 80/08/01 119co
- BOO7230052 Informs that exemption From fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D G Division of Licensing 80/08/07 60pp
- 8009230763 Forwards "Mark 1 Containment Long-Term Program SER, Resolution of Generic Technical Activity A-7," NUREO-0661 W/a encl REID,R N Operating Reactors Branch 4 80/08/20 2pp
- 8009180549 Advises that reply has not been received for 770405 request for addl info re 750303 application for Tech Spec change Application considered withdrawn NDVAK.T M Assistant Director for Operating Reactors 80/08/25
- 8007250421 Informs of acceptability of response to NRC 791109 ltr re portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture REID.R W Operating Reactors Branch 4 80/09/09 2pp
- 8009190423 Application for amend to Licenses DPR-57 & NPF-5 consisting of changes to Tech Specs WIDNER,W A Georgia Power Go 80/09/15 4pp
- --8009170428 Proposed changes to Tech Specs Tables 3 2-11,4 2-11 & 6 2 2-1 & Tech Specs 6 3 for unit staff qualifications,6 4 for training & 6 5 for review & audit \* Georgia Power Co 80/09/15 4pp
- --8009170432 Proposed changes to Tech Specs Tables 3 3 6 4-1,4 3 6 4-1 & 6 2 2-1 & Tech Specs 6 3 for unit staff qualifications,6 4 for training & 6 5 for review & audit 4 Georgia Power Co 80/09/15 5pp
- Q Inspection reports, IE Bulletins & correspondence
- 8009090007 Forwards IE Bulletin 80-07. Suppl 1, "BUR Jet Pump Assembly Failure " No response required O'REILLY. J P Region 2, Atlanta, Office of the Director 80/05/13
- 8009150332 Forwards IE Insp Repts 50-321/80-26 \$ 50-366/80-26 on 800625-26 No noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch \$0/07/23 2pp
- --B009150370 IE Insp Repts 50-321/B0-26 & 50-366/B0-26 on 800425-26
  No noncompliance noted Major areas inspected sattling of
  structural backfill around RHR & plant svc water intake
  structure & piping
  HARRIS, J R Region 2. Atlanta, Office of the Director
  CCNLON, T E. Region 2. Atlanta, Reactor Construction & Engineering
  Support Branch 80/07/22 3pp
- 8009220265 Forwards IE Insp Repts 50-321/80-24 & 50-366/80-24 on 800513-0609 & motice of violation LEMIS-R C Region 2. Attanta. Reactor Operations Nuclear Support Branch 80/07/25 Spp
- --8009220337 Notice of violation from insp on 800513-0609 LEWIS.R C Region 2, Atlanta. Reactor Operations Nuclear Support Branch 80/07/25 19
- --8009220341 IE Insp Repts 50-321/80-24 & 50-366/89-24 on 800513-0609 Noncompliance noted motor bearing cooling water inlet valves were found improperly shut on RHR svc water pumps DANCE.H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch RODERS.R F Region 2, Atlanta, Office of the Director 80/07/25 9pp
- 8009050076 Forwards partial response to IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Seven welds failed nondestructive examination Unit 1 containment & Unit 2 torus penetration info forthcoming WIDNER.W A Georgia Power Co 80/08/05 8pp
- 8007020287 Submits response to IE Bulletin 80-17.Suppl 1 Procedures have been established to assure operability of scram discharge vol WIDNER.WA Georgia Power Co BO/08/07 2pp

- 8009030154 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Unitten response required O'REILLY, J P Res Region 2. Atlanta, Office of the Director 80/08/15
- 8009020180 Responds to Suppl 1 of IE Bulletin 80-17 re failure of control rods to insert during scram at BWR Existing design of facility meets requirement for continuous monitoring of water level in scram discharge vols WIDNER.U A Georgia Power Co 80/08/19 2pp
- 8009020393 Submits status of recent util efforts towards compliance of IE Bulletin 79-018. "Environ Gualification of Class IE Equipment" Util has joined BMR owners group effort on Equipment hollstin WIDNER, W.A. Georgia Power Co. 80/98/19 2pp
- 8009160039 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE DWR Facilities " No specific action or response requested O'REILLY, J P. Region 2, Atlanta, Office of the Director 80/08/19
- 8009230:105 Submits response to IE Bulietim 79-018 Expects to complete qualification test program & component replacement by 820x39
- WIDNER, W.A. Georgia Power Co. 80/09/19 2pp
- 8009110671 Responds to IE Bulletin 79-01B Forwards 90-day repts re environ qualification of Class IE equipment w/less than 40-up aging qualification by commany of equipment w/less than 40-up aging qualification W/o encis
  HIDNER.U A Georgia Power Co 60/08/22 2pp
- 8009120077 Forwards Suppl 3 to IE Bulletin 80-17. "Failure of Control Rods to Insert During Stram at BMR " Written response required. O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/22 1 p
- 8009160147 Forwards IE Circular 80-18, "100FR90 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required
  O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/22
- 8009110824 Ack receipt of 800731 itr informing NRC of steps taken to correct deviations noted in IE Insp Repts 50-321/80-02 & 50-366/80-02 HMRPHYC E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/08/25 ip
- --B009110B28 Responds to NRC B00208 ltr re violations noted in IE Insp Repts 50-321/80-02 \$ 50-366/80-02 Corrective actions relocation of fire pump controller & installation of tamper alarms for fire valves to be completed Aug 1780 HIDHER. II A Georgia Power Co 80/07/31 bp
- 9009120311 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Bovert 480 Volt Type K-6008 & K-DON 4008 Circuit Breakers "No written response required O'REILLY.J P Region 2. Atlanta, Defice of the Director 80/08/27.
- 8009110576 Responds to IE Bulletin 80-15 Emergency notification sys powered by telephone company To ensure sys extensions operate independently of plant phones: testing was conducted on 800815 All extensions operable during power trip HIDNER.U A Georgia Power Co 80/08/29 1p
- 8009150162 Responds to 1E Bulletin 80-19, Revision & Mercury-wetted matrix relays are not used in reactor protection sys WIDNER, W A Georgia Power Co 80/08/27 ip
- 8009230204 Forwards IE Insp Repts 50-321/80-34 & 50-366/80-34 on 800313-14 No noncompliance noted KENNA, W B Region 2, Atlanta, Safeguards Branch 80/08/29 ip
- --8009230210 IE Insp Repts 50-321/80-34 \$ 50-366/80-34 on 800813-14 No noncompliance noted Major areas inspected licensee implementation of contingency strike plan Details withheld (ref 10CFR2 770) MCGUIRE, D R Re trer lucraz 740; McCOURE,D R. Region 2. Atlanta, Bafeguards Branch, TOBIN.W J Region 2. Atlanta, Office of the Director. 80/08/29 ip

- 8009230525 Forwards Revision 1 to IE Bulletin 79-26. "Boron Loss From BWR Control Blades " Written response required O'REJLLY.J P Region 2. Atlanta. Office of the Director 80/08/29
- B009240367 Responds to IE Bulletin B0-17, Suppl 3 Gutlines procedures in effect re loss of instrument air, loss of control rod driveline, rod drift 2 undrained scram discharge vol Function test of switches required prior to startup WIDNER, W A Georgia Power Co 80/08/29 2pp
- 8009290282 Forwards IE Circular 80-21, "Regulation of Refueling Craws" No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/09/10
- 8009300104 Submits response to IE Bulletin 80-20 No Westinghouse Type W-2 control switches used in safety-related applications WIDNER,W A Georgia Power Co 80/09/12 ip
- R Periodic operating reports & related correspondence
- 8009030415 Forwards "Bemiannual Radioactive Effluent Release Rept,"
  Jan-June 1980
  MANRYM Georgia Power Co 80/08/30 1p Georgia Power Co 80/08/30 1p
- --8007030419 "Semiannual Radioactive Effluent Release Rept." Jan-June \* Georgia Power Co 80/08/30 44pp
- 8009180199 Forwards monthly operating rept for Aug 1980 MANRY.M Georgia Power Co 80/09/10 1p
- --8009180208 Monthly operating rept for Aug 1980 UNDERWOOD, P. R. Georgia Power Co. 80/09/10
- S Reportable occurrences, LERs & related correspondence
- 8009020436 Forwards LER 80-084/03L-0 MANRY,M Georgia Power Co 80/08/26 1p
- --8009020446 LER BO-084/O3L-O on 800807, while performing HNP-1-3167.RHR svc water flow indication for RHR svc water loop B observed swinging excessively Caused by faulty amplifier Amplifier replaced 5 transmitter recalibr
  NIX.R T Georgia Power Co 80/08/26 2pp
- 8007020437 Forwards LER 80-095/03L-0 MAPRY, M Georgia Power Co 80/08, 80/08/26 1p
- -8007020444 LER 80-095/03L-0 on 800808, w/reactor at steady state of power.during RHR valve operability surveillance on RHR A loop w/B loop out of svc.inboard injection valve iEII-F015A failed to open Caused by burned motor windings & rotor. NIX.R T Deorgia Power Co 80/08/26 2pp
- 8009020461 Forwards LER 80-099/03L-0 MANRY,N Georgia Power Co 80/08/28 is
- --8009020469 LER 80-099/03L-0 on 800817, while performing normal operation of unit radwaste, door to empty drum conveyor room discovered unlocked Caused by evening shift personnel not locking door when eriting Lock changed to self locking type. BAKLEY, S X Georgia Power Co 80/08/28 2pp
- 8009020404 Forwards LER 80-092/03L-0. MANRY, M Georgia Power Co 80/08/ 80/08/29 1p
- ---8009020414 LER 80-092/03L-O on 800731.while at steady state power, cooling water to LPCI inverter room cooler was isolated resulting in high ambient temp in inverter room Caused by high ambient temp causing 8 loop of RHR to be inoperable C000IN.C L Georgia Power Co 80/08/29, 2pp
- 8009090469 Forwards LER 60-098/03L-0 MANRY, M Georgia Power Co 80/09/02 1p
- --8009090480 LER 80-098/03L-0: on 800816, during HNP-1-3957, torus to drywell vacuum brasker operability test closed indication lights on valve ITAB-F323H failed to extinguish w/valve in full open position Causs not known RIX.R T Georgia Power Co 80/07/02 2pp
- BOD9090443 Forwards LER BO-097/03L-0 MANRY, M Georgia Power Co 90/09. 80/09/04 tp

~-BOD9090460 LER 80-097/03L-0 on 800Bi5.during reactor operations at 2370 MAt.bldg vent radiation monitor sample pump failed Caused by moisture swelling pump carbon vanes Pumps rotated daily to prevent recurrence ROGERS.H H Georgia Power Co 80/09/04 2pp

8009150295 Forwards LER 80-100/01T-0 HANRY, M Georgia Power Co 80/09/05 1p

--B009150298 LER B0-100/01T-0 on 800822.vtil notified by Bechtel that seismic piping support was not installed Apparently caused by goor communication w/designer re addition of support to original analysis Support installed COGGIN.C L Georgia Power Co 80/09/05 2pp

8909150281 Forwards LER 80-101/03L-0 MANRY,M Georgia Power Co 80/09/09 1p

8009180291 Forwards LER 80-102/031-0 MANRY.M Georgia Power Co 80/09/09 1p

--9009150294 LER 80--102/03L-0 on 800921.while at steady state power. II LPCI inverter tripped making B loop of RHR inoperable Caused by high ambient temp Temporary cooling is being used until installation of permanent chillers is complete COGOTN.C L Georgia Power Co 80/09/09 2pp

B009180392 Forwards LER B0-103/03L-0 MANRY, M Georgia Power Go B0/07/09 1p

--8009150385 LER 80-103/03L-0 on 800822 during operation at 99% power, plant svc water flow was restricted Caused by tripped drive mechanism & coupling failure of strainers 1P41-D103A & 1P41-D103B Breaker reset & coupling repaired MIX.R T Georgia Power Co 80/09/09 2pp

8009150384 Forwards LER 80-104/03L-0 MANRY,M Georgia Fower Ca 80/09/09 1p

--8009150386 LER 80-104/03L-0 on 800826 during annual surveillance & operability testing five snubbers did not meet acceptance criteria Caused by seal leakage as snubbers were low on fluid Two snubbers were reconditioned & others replaced NIX.R Y Georgia Power Co 80/09/09 2pp

8009300497 Forwards LER 80-096/03L-0 MANRY, M Ocorgia Power Co 80/09/23 1p

--8009300502 LER 80-096/03L-0 on 800902.all points of IT47-R612 Drywell & Torus temp recorder read 17 degrees F higher than redundant recorder 1T47-R611 Caused by calibr drift Instrument recalibr & returned to syc NIX.R T Georgia Power Co 80/09/23 2pp

### V Operator Examinations

8009050291 Forwards excerpt from new training outline re criteria for operator training & licensing Current policy requires instructors attend annual simulator training & retraining lectures as part of approved requalification program MAMRY.M Georgia Power Co. 80/08/12 7pp

## DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION

A Application/construction stage documents & correspondence

8007080080 Forwards draft NUREG-0676, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl W/o NUREG EISENHUT, D G Division of Licensing 80/08/01 119pp

#007070631 Notification of cancellation of 800827 meeting w/DWR licensing review group to discuse concensus positions on TMI issues (NUREQ-0674) NIL9DN.J N Assistant Director for Licensing 80/08/04 10pp

8009070631 Notification of cancellation of 800827 meeting w/BWR licensing review group to discuss concensus positions on TMI issues (NUREG-0674) MILSDN, J N Assistant Director for Licensing 80/08/04 10pp

8009020425 Responds to NRC 800711 request for util confirmation of const completion date 2 fuel load schedule Fuel load forecast is 820601-0901 Station will be physically ready to load fuel before conclusion of CL proceeding NOVAPRO, J P Long Island Lighting Co 80/08/21 3pp

BOO9030437 Forwards commitments to meet requirements outlined in NUREG-0578 "TMI-2 Lessons Learned Task Force Status Rept & Short-Term Recommendations." per NRC 790927 & 1109 ltrs Requests concurrence & comments on submittal NOVARRG.JP Long Island Lighting Co 80/08/29 80pp

8009110742 Notification of 800904-05 meeting w/Mark II owners group to discuss plants chugging C/O & lateral load specs ANDERSON.C Containment Systems Branch 80/08/29 14pp

8007120375 Forwards missing page to be inserted in section entitled "Containment Hydrogen Concentration," contained in "Shoreham Nuclear Power Station Responses to NUREG-0578, Short-Term Leasons Learned Requirements"

GUAGUIL, L. Long Island Lighting Co. 80/07/05 2pp

8009260091 Notifies of B01007 proposed date to review whether OBE & SRV responses should be considered separately or combined during ABME code fatigue calculations GE selected samples to emphasize highly fatigued components
WILSON. J N Assistant Director for Licensing 80/09/15 7pp

8009230590 Comments on NUREG-0696 in relation to "Design Criteria & Description, Technical Support Ctr for Shoreham Nuclear Power Station." SNRC-486 Emphasizes Importance of receiving evaluation of design criteria as early as Sept 1980 NOVARRD. J P Commonwealth Edison Co 80/09/16 3pp

### F Security, modical, emergency & fire protection plans

8008280053 Notification of 800819.20 & 22 workshops in Valley Forge.PA. Chicago. IL & Atlanta. GA. respectively, to solicit public comment re NVRGD-0696, "Functional Criteria for Emergency Response Facilities" GRIER. B H. Region 1. Philadelphia, Office of the Director 80/08/11 200

# G Adjudicatory correspondence

8009120550 Forwards NRC insp repts of fabrication of facility reactor pressure vessel per request during 800519 health committee public hearing W/o and ORIER, B H Region 1, Philadelphia, Office of the Director 80/08/04 2pp

800902041k Responds to 800822 itr Documents will be sent to Shoreham Opponents Coalition & MHB Technical Associates if spare copies are available Other Intervenors or consultants must be contacted if spare copies are not located BORDENICK.B M Hearing Branch 4 80/08/28 ip

8009040248 Forwards recently promulgated amends to amergency planning regulations W/o encis BORDENICK-B M Hearing Branch 4 80/09/02 1p

BO09170231 Forwards contractor repts NUREO/CR-0742, NUREO/CR-0743 & NUREO/CR-0744, in response to B00B21 request delivered at B00927 meeting M/o enci B0R0EHICK, B M Hearing Branch 4 80/07/08 2pp

BOO9300001 Forwards DD Vassallo 790927 & 1009 ltrs re TM1-2 followup actions & discussions of Lessons Learned Short-Term Requirements Remaining documents will be provided whon available
BORDENICK, B M Hearing Branch 4 80/09/26 2pp

# M Antitrust correspondence

8009190415 Re-requests update of Jan 1976 submission of antitrust info in accordance w/AEC Reg Guide 9 3 SALTZMAN.J Utility Finance Branch 80/09/16 1p

O Inspection reports, IE Bulletins & correspondence

8009090085 Forwards IE Bulletin 80-07, Suppl 1. "BWR Jet Pump Assembly Failure" No response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/05/13 19

- 8009190159 Forwards IE Insp Rept 50-322/80-11 on 800401-0704 No noncompliance noted BRU-M'ER.E J Region I, Philadelphia. Peactor Operations Nuclear Support Branch 80/07/24 2pp
- --8009150161 IE Insp Rept 50-322/80-11 on 800601-0706 No noncompliance noted Pajor areas inspected tours of facilities, test witnessing, review of fire protection measures & QA review HIGGINS, C , LINVILLE, J C Region 1, Philadelphia, Office of the Director KISTER, H B Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/07/21 7pp
- 8009120234 Responds to IE Bulletin 79-03A re longitudinal weld defects in 8A-312 type 304 stainless steel pipe 8A-312 piping used at facility satisfies criteria Sys pressure-temp values louer than reduced allowable code NGVARRO.JP Long Island Lighting Co 80/08/04 2pp
- 8009030009 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/08/15 1p
- 8009030493 Forwards empty binder for increased vol of preservice insp plan inserts to cover usli be sent at later date Suggests Saction G be placed in second binder due to size Requests that NRC ack receipt of binder NOVARRO, J P Long Island Lighting Co 80/08/15 ip
- 8009120088 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at DMR " No written response required ORIER.8 M Region I, Philadelphia, Office of the Director 80/08/22 1p
- 8009180009 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/08/22 1p
- 8009120180 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Voit Type K-6008 & K-DON 6008 Circuit Breakers " No written response required ORIER B H Region I, Philadelphia, Office of the Director 80/08/27 ip
- 8009230786 Forwards IE Circular 80-21, 'Regulation of Refueling Crews " No written response required GRIER BH Region I. Philadelphia. Office of the Director 80/09/10 ip
- 009240315 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive fatls " No written response required RRIER, B If Region 1, Philadelphia, Office of the Director 10/09/12 19
- )9250003 Forwards relevant portions of IE insp Repts 50-322/78-01. i0-322/78-17 & 50-322/79-12 in response to 800731 itr iQRBENICK.B M Hearing Branch 4 80/09/23 5pp
- Reportable occurrences, LERs & related correspondence
- 009120120 Ack receipt of 800724 Interim deficiency rept re power supply failure CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/01 1p
- --8009120123 Interim deficiency rept re 24-volt do power supplies w/ Bailey Controls Co electronic analog instrumentation Fallowup rept will be submitted within 90 days MAVARRO.J P Long Island Lighting Co 80/07/24 2pp
  - KET 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2
    Application/construction stage documents & correspondence
  - POBOSE Forwards draft NUREG-0276, "Functional Criteria for ergency Response Facilities" Comments requested within 30 is Proposed implementation schedule for meeting criteria NUREG-0676 ent I 470 NUREG SCHUT. D G Division of Licensing 80/08/61 117pp

- B009020263 Forwards response to questions re Category I concrete masonry walls, sample calculation 2 pertinent location drawings, in response to NRC 800421 ltr CRANE.P A Pacific Gas & Electric Co 80/08/27 32pp
- --8009020265 "Plan Area A Elevation 107 Ft "
  \* Pacific Gas & Electric Co 79/12/11 1
- --8009020268 "Plan Area H Elevation 100 Ft "

  \* Pacific Gas & Electric Co 78/02/24 ip
- --8007020269 "Plan Area A Elevation 119 Ft "
  \* Pacific Gas & Electric Co 80/07/15 1
- --8009020270 "Plan Area H Elevation 115 Ft "
  \* Pacific Gas & Electric Co 79/09/22 in
- --8007020272 "Plan Area H Elevation 128 Ft "
  + Pacific Oas & Electric Co 78/10/30 1
- ---8007020274 "Pian Area K Elevation 185 Ft "

  # Pacific Gas 8 Electric Co 78/11/01 ip
- --8009020275 "Finish Schedule & Interior Details "
  \* Pacific Gas & Electric Co 79/12/12 ip
- --8009020277 "Miscellaneous Concrete Block Details "
  # Facific Gas & Electric Co 78/09/27 ip
- 8009110707 Forwards request for add1 info to continue review & evaluation for full power OL Info should be provided to low power turbine discs & rotors & evaluation of turbine missiles
  SCHWENCER, A Licensing Branch 3 80/08/27 7pp
- 8007070544 Advises that habitability aspects of facility control room comply w/requirements of Reg Guides i 78 & 1 75 & SRP.

  Sections 2 2 1-3 & 6 4 as specified in NUREG-0660.per NRC 800507 request Conclusion confirmed in Suppl 9 to 8ER GRANE.P A Pacific Gas & Electric Co 80/09/03 ip
- B009180486 Forwards Revision 4 to "Description of Sys Interaction Program for Seismically-Induced Events" Requests that receipt of rept be ack GRANE.P A Pacific Gas & Electric Co 80/09/16 ip
- --8009180493 "Description of Sys Interaction Program for Seismically-Induced Events: " Revision 4 \* Pacific Gas & Electric Co 80/08/29 92pp
- 8009250288 Forwards response to NRC 800606 itr requesting addl info re shielding review, containment monitors & iodine sampling at facilities Monitors are mutually redundant using separate power supplies from separate vital instrument busses CRANE.P A Pacific Oas & Electric Co 80/09/22 App
- E NRC Safety Evaluation Report (SER), supple & correspondence
- BOO9090195 Forwards Suppl 10 to facility SER covering TMI-2-related matters M/o encl
  BCHWENCER, A Licensing Branch 3 80/08/15 5pp
- F Security, medical, emergency & fire protection plans
- 8009030337 Notifies of 800819,22 & 30 regional workshops re development of guidance for acceptable method for coping w/emergencies at facility Requests that representative be sent Subj areas to be discussed include function of facilities & location ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/08/12 2pp
- 8009230337 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network. Bys installed for govt use during emergency ERVELMENTR H Region 5. San Francisco, Office of the Director 80/09/22 3pp
- 8009150565 Requests add1 info & commitments re NRC evaluation of emergency preparedness program for conformance w/NURE0-0654 TEDESCO.R L Assistant Director for Licensing 80/08/26 9pp.
- 8007070612 Requests clarification of apparent omission of 1tr of agreement between util & Field Ranch on Page 5-6 of Feb 1780 Emergency Plan, Revision 2, App 7 SCHWENCER, A Licensing Branch 3 80/08/30 3pp

- 8009290049 Forwards & Schwencer 800910 memo to HR Denton re alleged inaccuracios in emergency plan text Requests assistance in determination of substantiation of alleged inaccuracies TEDESCO, R L Division of Licensing 80/09/11 ip
- BOO922020 Forwards lighting maps of protected area of facility in response to NRC request Maps withheld (ref 10cFR2 790) ROSED 0 Los Alamos Scientific Laboratory BO/09/17 ip

### Q Adjudicatory correspondence

- 8009220213 Confirms 800702 teleon re arrangements for mailing & delivery of security matls per ALAB-600 order Advises that mailing arrangements re sensitive info between intervenor San Luis Dbispo Mothers for Peace & util are necessary NORTON. B Bruce Norton 80/07/17 2pp
- 8009030157 Executed amended affidavit of nondisclosure protecting licensee physical security plan Certificate of Svc encl LEWIS.W L Affiliation Unknown 80/08/20 6pp
- BCO9030489 Response in opposition to Governor of CA motion for revision of mandisclosure affidavit re security plan Takes exception to governor of CA BOOB14 & 19 ltrs submitted in response to ASLAB order Certificate of Svc encl ACRAION.B., GEHR.A C., FURBUSH.M H. Pacific Gas & Electric Co RO/08/21 7pp
- 8009020071 Motion for JE Luco & MD Trifunac to provide testimony by 800905 instead of 800902 Secretarial help unavailable MORDLINGER.M & Office of the General Counsel 80/08/27 ip
- 8009030112 Order scheduling Sopt-Nov 1980 security plan hearings Parties may move for supplemental evidence re issues reopened in seismic ALAB-998 by 800919 State of CA motion to ravise nondisclosure affidavit denied B16HQP.C J Atomic Safety and Licensing Appeal Panel 80/08/28 16mp
- BOOTO30597 Response to ASLB 800814 order re util motion to load fuel & for low power tests Covernor of CA & joint intervenors' replies should be stricken as failures to make substantive responses Certificate of Syc encl CRANE, F A , OEHR, A C , NORTON, B Pacific Gas & Electric Co BO/08/28 7pp
- BOOGLIGOIP Request for BOO925 sits insp visit Security plan w/maps, diagrams & safeguards contingency plan must be available for review by HH Brown.LC Lampher.LO Gluffrida.RE White & DR Bievers who will undertake visit BROWN,R H . GEORGIOU,B S . LAMPHER.L C California, State of 80/09/08. 2pp
- BOO9150404 Response to ASLB BOOB14 order re util BOOB04 motion for low power tests Urges summary dismissal of motion Security & seismic issues not yet resolved & are needed for low power testing BROWN, H H, LANPHER, L C, California, State of BROWN, H H Hill Christopher & Phillips BO/09/11 4pp
- 8009160234 Response to ASLB 800814 order re util motion for low power testing. Urges dismissal of motion due to reopening of record on security plan & seismic design Late discovery of Hosgri fault warrants consideration of Class 9 accidents FLEISCHAKER, D San Luis Obispo Mothers for Peace FLEISCHAKER, D Fleischaker, D S 80/09/11 5pp
- 8009160360 Forwards JF Devine & RF Yerkes combined testimony w/latter prof qualifications.ger ASLB 800819 memorandum & order Explains svc process re repts mentioned in testimony METCHEN.E. O Hearing Branch 4 80/09/12 2pp
- ~-8009160363 Combined testimony in response to ASLB 800819 memorandum & order on Question 9 re geology & seismology repts New data & conclusions re LNG repts have no impact on USOS position RF Yerkes prof qualifications encl DEVINE, J F, YERKES, R F Interior, Dept of, Geological Survey 80/09/12 App
- 8009190036 Forwards 800819 FR notice re upgraded emergency plan regulations RAVIS.L D Hearing Branch 4 80/09/15 19pp
- 8009220406 Response in opposition to util & NRC objections re State of CA 800902 statement of security plan issues upon which participation is requested challenged subject are responsive to ASLB 800808 fourth prehearing conference order BROWN.H.H. LANPHER.L. C., GEORGIOU, B. G. California, State of 80/09/15 4pp

- 8009220362 Forwards plaintiff, San Luis Obispo Mothers for Peace, complaint for declaratory judgement injunctive relief & mandamus, disqualifying JM Mendrie from further participation in OL proceedings
  FLEISCHAKER, D Fielschaker, D S FLEISCHAKER, D San Luis Obispo Mothers for Peace 80/09/16 20pp
- 8009230616 Correction to State of CA 800908 interrogatories directed to NRC re security plan proceeding Certificate of Svc encl Related correspondence BRGUN.H H . LANPHER.L C . GEORGIOU.B S California, State of 80/09/14 4pp
- 8009240544 Forwards RB Hubbard affidavit re need for Class 9 accident analysis to accompany joint intervenois' reply to ASL® 800814 order Related correspondence FLEISCHAKER D Fleischaker, D S 80/09/19 ip
- --8009240546 Affidavit re need for Class 9 accident & sys reliability analyses of facility by util Analysis needed due to effect of reactor contamination on economic cost & health risks CEO 800320 ltr encl Related correspondence HUBBARD.R B MHB Technical Associates 80/09/17 18pp
- --8009240550 Submits conclusion of study on NRC regulations & policy re environ analysis of possible nuclear accidents under NEPA Typical EIB does not consider or analyse possibility of major accident in Class 9 category SPETH, G Council on Environmental Quality 80/03/20 4pp
- 8009260469 Notice of 801020 evidentiary hearings in San Luis Obispo.CA re ASLAB 800624 decision.ALAB-598.which reopened soismic issues BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/09/23

#### H General correspondence

- 8009090534 Urges use of influence for speedy & successful approval of facility Industrial & agricultural production could be jeopardized.

  SLOTT, N. Affiliation Unknown 80/07/23 ip
- 8009110382 Urges opening of facility as necessary enterprise in area Newspaper articles entl BRADBURY.V A Affiliation Unknown 80/08/05 4pp
- 8009170200 Responds to 800326 ltr to President Carter re delays in licensing process Delays attributed to seismic re-evalvation of facility, lessons learned from TMI accident & public hearings re safety & security SCHWENCER. A Licensing Branch 3 80/08/22 5pp
- BD09030581 Requests that facilities be certified for startup operations & plans for RY81-82 be devloped w/o delay.CA could face serious pawer shortages Electronics industry & economy could be adversely affected QARGIA.H California. State of 80/08/25 lp
- 8009050342 Urges donial of licensing Diable Nuclear power plant & any other plants
  SCHUMACHER.J Affiliation Unknown 80/08/27 ip
- 8009100457 Ack receipt of 800705 ltr & forwards Friends of the Earth Class 9 petition & Director's decision on petition W/o encl SCHWENCER.A Licensing Branch 2 80/08/27 2pp
- --8009100463 Requests Director's decision on Friends of the Earth petition to consider Class 9 accidents in supplemental EI8 FRIESEMA: HP Northwestern Univ 80/07/05 1p
- 8009220042 Responds to 800319 ltr opposing licensing of facilities NRC has reacted positively in light of TMI accident to improve safety at all nuclear plants in operation & under const SCHMENCER.A Licensing Branch 3 80/09/03 ip
- 8009180248 Responds to 800422 ltr to President Cater re potential radiological risks at facility NRC has re-examined plant for conformance to fuel loading & low power testing requirements 8CHNEWER, A Licensing Branch 3 80/09/09 3pp
- 8009290054 Forwards 800830 ltr to util requested by C Neiburger of Telegram Tribune on 800909 re alleged inaccuracies in emergency plan text Matter must be resolved prior to issuance of full power OL.
  EISENHUT, D. O Division of Licensing 80/09/10 ipp

- 8009300295 Responds to 790920 ltr to President Carter re concern over offect of low level radiation storage & transportation of high level radwaste & ability of plant to withstand seismic acitivity Fact sheets addressing concerns encl HIRAOLIA,F Licensing Branch 3 80/09/19 6pp
- --8009300306 Forwards misdirected T Game: 790920 lti to President Carter re effects of low level radiation Requests response RATHKOPF,C L. Energy, Dept of 80/01/22 3pp
- K Utility Final Bafety Analysis Report (FSAR) & amende
- 8009090514 Forwards Amend B5 to OL application, including matl for Chapters 4,13,14 & 17 of FSAR CRANE.P A Pacific Gas & Electric Co 80/09/03 2pp
- --8009090520 Amend 85 to OL application, including matl for FSAR Chapters 4.13.14 & 17 SCHUYLER, J O Pacific Qas & Electric Co 80/08/28 7pp
- ---8009090526 Revision to FSAR, including matl re QA & conduct of operations for Chapters 4, 13, 14 & 17 \* Pacific Gas & Electric Co 80/08/31 403pp
- 9 Inspection reports, IE Bulletins & correspondence
- 8009260299 Forwards IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlet Flange " No written response required ENOELKEN,R H Region 5, San Francisco, Défice of the Director 80/88/07 Ip
- 8007030278 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required EMSELKEW, R X Region 5. San Francisco, Office of the Director 80/08/15 ip
- 8007290305 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No written response required ENGELKELY, R H Region 5. San Francisco. Office of the Director 80/08/18 4pp
- 8009140191 Forwards [E Circular 80-18, "100FR50 59 Gafety Evaluations for Changes to Radwaste Treatment Bys " No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/08/22 ip
- 8009120458 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Bovert 480 Volt Type K-600S & K-80N 600S Circuit Breakers " No written response required ENGELKELIAR H Region S. San Francisco. Office of the Director 80/08/27 ip
- T Hearing transcripts on non-antitrust matters
- 8009070779 Testimony in response to ASLAS 800807 order.ALAB-604 LUCO.E . NORDLINGER.M S Luco.J E 80/09/04 7ipp
- 8009090552 Testimony in response to ASLAB 800807 order, ALAB-604 TRIFURAC, M. Bouthern California: Univ. of NORDLINGER, M.S. Office of the General Counsel. 80/09/05 182pp
- 8009160360 Forwards JF Devine & RF Yertes combined testimony w/latter prof qualifications.per ASLB 800BL9 memorandum & order Explains svc process re repts mentioned in testimony, KETCHEN.E 9 Hearing Branch 4 80/09/12 2pp
- ---8009i60363 Combined testimony in response to ASL9 8008i9 memorandum & order on Question 9 re geoloty & seismology repts New data & conclusions re LNG repts have no impact on USOS position RF Yerkes prof qualifications encl
  DEVINE, J F Interior Dept of Geological Survey 80/09/12 App
- U Congressional/Executive Correspondence
- 8009:10514 Responds to 800530 ltr re facility licensing status Major const completion delays result of seismic re-evaluation & of TMI-2 Lessons Learned Task Force recommendations Facility will not be authorized to load fuel until approx 1981 DIRCKS.U J Office of the Executive Director for Operations 80/08/21 2pp

- --8009110520 Urges prompt campletion of necessary requirements for granting facility license Delays result in increase in constituent util bills Requests licensing status SHUKWAY,N D House of Rep 80/05/30 ip
- 8009220255 Provides status of NRC efforts re final licensing of facility Further actions will be required by ASLAB, ASLB & Commission
  DIRCKS.M J Office of the Executive Director for Operations 80/09/17 2pp
- DOCKET 50-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

  F Security, medical, emergency & fire protection plans
- SOO9230252 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency O'REILLY, J P Region 2. Atlanta, Office of the Director BO/08/22
- 8009090402 Submits revised schedule for submittal of revised emergency plan as specified by 800819 final rule revising 10CFR50 & 70 UTLEY,E E Carolina Power & Light Co 80/09/02 ig
- G Adjudicatory correspondence
- 8009220120 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittat of info by 801101 IFPGLITG, T.A. Operating Reactors Branch 2 80/08/29 2pp
- --8009220122 Order for mod of Licenses DPR-62 & DPR-71 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment. Info should be submitted by 801101

  EISENHUT, D G Division of Licensing 80/08/29 App
- H General correspondence
- BOO9120437 Advises of BWR owners group organizational changes & that future correspondence be forwarded to DB Waters Future requests for util action should be addressed to individual licensees & applicants
  WATERS.D B Carolina Power & Light Co 80/09/09 2pp
- P Operating license stage documents & correspondence
- 8009110554 Suppls NRC 800707 request for proposed Tech Specs changes re scram discharge vol vent & drain valves. & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISEIHUT.D © Division of Licensing 80/07/22 22pp
- B009020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants.per NRC B00507 ltr Discusses administrative provisions for energency & overtime work Development & implementation to be reviewed within 90 days EISENHUT.D O Division of Licensing B0/07/31 7pp
- 8009080080 Forwards draft NUREC-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREC-0696 encl M/o NUREC EISENHUT.
- 8007230092 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISERMUF, D. G. Division of Licensing 80/08/07 60pp
- 8009040309 Advises that two specific Event 5 valve configurations do not exist at facility per review of response to 800223 ltr "Primary Coolant Sys Pressure Isolation Valves," technical evaluation rept encl
  IPPOLITO, T A Operating Reactors Branch 2 80/08/08 App
- --8009040315 "Primary Coolant Sys Pressure Isolation Valves," technical evaluation rept NOELL,P N. STILWELL,T C Franklin Institute/Franklin Research Center NRC-03-79-118 80/07/21 5pp

- 8009190678 Forwards NUREC-0661, "Mark I Containment Long-Term Program SER Resolution of Generic Technical Activity A-7" Rept discusses generic suppression pool hydrodynamic load derinition W/o encl IPPDLITO,T A Operating Reactors Branch 2 80/08/20 2pp
- 8009230772 Notification of 800905 meeting w/util in Bethesda.MD to discuss procedure for amending OLs to add addl owners WILSON, J.N. Licensing Branch 1 83/08/27 4pp
- 8007070448 Forwards updated outage schedule re Mark I containment program mode Containment mode to conclude in May 1782 Plant unique analysis scheduled to be completed in June 1781 UTLEY,EE Carolina Power & Light Co 80/07/02 2pp
- BD09190047 Advises of acceptability of 791227 response to NRC 791109 let re ECCS evaluation models dealing w/fuel cladding swelling L incidence of rupture 1PPOLITO.T A Decrating Reactors Branch 2 80/09/03 2pp
- 8009170186 Forwards "Recovery of Radioactive Hatl from Brunswick County Landfill near Southport.NC," final rept FURR.B J Carolina Power & Light Co 80/09/05 1p
- --8009170191 "Recovery of Radioactive Matl from Brunswick County Landfill Near Southport.NC." final rept + Carolina Power & Light Co 80/09/05 38pp
- --8009170197 "Radiation Control & Test Procedure 3280, Radioactive Mat1 Recovery Procedure " \* Carolina Power & Light Co 80/05/01 8pp
- 8009160376 Forwards results of review of ECCS equipment availability w/dc power supply failure
  UTLEY.E E Carolina Power & Light Co 80/09/11 4pp
- 8009170400 Summary of 800905 meeting w/CP&L & NC Municipal Power Agency 3 in Bethesda,MD re procedure for OL & CP amends WILBON,J N Licensing Branch i 80/09/12 7pp
- 800923043B Forwards proposed revisions to Tech Specs, implementing changes requested by NRC 800702 ltr re TMI Lessons Learned requirements Proposed license conditions encl
  WTLEY, E E Carolina Power & Light Co 80/09/16 4pp
- ~~8009230439 Proposed revisions to Tech Specs,Pages 3/4 3-51 & 52, B 3/4 3-3,6-5.6-6 re post-accident monitoring instrumentation & min shift crew composition \* Carolina Power & Light Co 80/09/16 10pp
- 9 Inspection reports: IE Bulletins & correspondence
- 800909055 Forwards IE Bulletin 80-07, Suppl 1, "BWR Jet Pump Assembly Failure "No response required O'REILLY.JP Region 2. Atlanta. Office of the Director 80/05/13
- 8009150329 Forwards IE Insp Repts 50-324/80-26 & 50-325/80-29 on Branch 80/07/24 2pp
- ---9009150375 IE Insp Repts 50-324/80-26 & 50-325/80-29 on 800601-30 JUVISUS/S IE INSP Nepts 50-324/80-26 & 50-325/80-27 on 900601-30

  No noncompliance noted Major areas inspected control room
  observations. Unit 1 refueling operations, review of plant
  logs, tour of vital areas & physical security
  OUZTS-JE Region 2, Atlanta. Diffice of the Director
  KELLOGO.P J Region 2, Atlanta. Reactor Operations Nuclear Support
  Branch 80/07/23 3pp
- 8007240273 Forwards IE Insp Repts 90-324/80-23 & 50-325/80-26 on 800602-06 No noncompliance noted LONG.F J Region 2, Atlanta, Office of the Director 80/08/04.
- --8009240284 IE Insp Repts 50-324/80-23 & 50-325/80-26 on 800602-06 No noncompliance noted Major areas inspected site environ monitoring & circumstances surrounding 800222 radioactive mati release from auxiliary boiler sys LONO, FJ : MARSH, RJ Region 2: Atlanta, Office of the Director HARDIN:A K Region 2: Atlanta, Reactor Construction & Engineering Support Branch 80/08/04 13pp
- 8009020199 Submits response to IE Bulletin 80-17. Suppl 1 No design deficiencies have been noted which would preclude scram discharge vol from performing required functions FURR. 8 J Carolina Power & Light Co 80/08/07 200

- B009030163 Forwards Revision 1 to IE Bulletin 80-19, 'Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sus of Operating Nuclear Power Plants Designed by C-E ' Written response required O'REILLY J P Rec Region 2, Atlanta, Office of the Director BO/08/13
- 8009160040 Forwards IE Into Notice 80-30. 'Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Am at Certain GE BWR Lacilities " No specific action or response requested O'REILLY, J.P. Region 2. Atlanta, Orfice of the Director 80/08/19
- 8009230059 Submits response to IE Bulletin 80-20 Westinghouse Type W-2 control switches not used in safety-related applications FURR:B J Carolina Power & Light Co 80/08/19 Ip
- 8009230080 Submits response to IE Sulletin 80-19 Hercury-wetted relays are not used in reactor protection sys FURR.B J Carolina Power % Light Co 60/08/19 to
- 8009230085 Submits add) info to ltem 3 of IE Bulletin 80-02 Feedwater spargers were evaluated & do not require essential equipment classification Carolina Power & Light Co 80/08/19 2pp
- B00909063B Ack receipt of BJ Furr 800703 ltr identifying corrective measures for noncompliance noted in 800611 ltr & payment of proposed civil penalties
  STELLO, V Office of Inspection & Enforcement, Office of the Director 80/08/20 ip
- B009120072 Forwards Suppl 3 to IE Bulletin 89-17. "Failure of Control Rods to Insert During Scram at BUR " Written response required required O'REILLY, J.P. Region 2 Atlanta, Office of the Director 80/00/22
- 8009140124 Forwards IE Circular 80-18, "10CFR50 59 Bafety Evaluations for Changes to Radwaste Troatment Sys " No written response required
- O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/22
- B009020321 Responds to B00801 notice of proposed imposition of civil penalty re improper disposal of radioactive matl Corrective action taken new procedure implemented to remove radioactive matl Penalty for encl
  JDNES.J A Carolina Power & Light Co 00/09/27 7pp
- 8009110027 Responds to NRC 800801 lir re violations noted in If insp repts Corrective actions radiation protection program improved & offsite disposal of potentially contaminated matl terminated JOI FB J A Carolina Power & Light Co 80/08/2/ 17pp
- 8009120290 Forwards IE info Notice 80-31. "Maloperation of Oculd-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required O'REILLY, J P Region 2. Atlanta, Orfice of the Director 80/08/27
- 8009240370 Responds to IC Nulletin 80-15 Emergency notification sysponered from Generator 2 during loss of offsite power powered from Generator 2 during loss of Offsite power Dissel generator actual load test is scheduled for Fall of FURR. B J Carolina Power & Light Co 80/08/27
- 8009110662 Responds to IE Bulletin 80-17, Suppl Dire failure of 76 of 185 control rods to fully insert during stram at BUR Item ( not applicable Periodic Test 1 i 2P rovisod FURR B U Carolina Power & Light Co BO/08/20 ip
- 8009230526 Forwards Revision 1 to 1E Bulletin 79-26. "Boron Loss From BUR Control Blades " Written response required O'REILLY, J.P. Rogion 2. Atlanta. Office of the Director 80/08/29
- 8009240329 Ack receipt of 800711 % 0811 ltrs informing NRC or steps taken to correct violations noted in IE Insp Repts
  50-324/40-20 & 50-325/80-23.
  MURPHY:C E Region 2, Atlanta, Reactor Construction & Engineering
  Bupport Branch 80/07/03 ip
- --8009240340 Responds to NRC 800617 Itr re violations noted in If Insp Repts 30-324/80-20 & 50-325/80-23 Corrective actions procedures established re site engineering, QA/QC acceptance of surveillance data & inservice insp TOLLISON, A C Carolina Power & Light Co 80/08/11 2pp

- --8009240356 Responds to NRC 800611 ltr re violations noted in IE Insp Repts 50-324/80-20 & 50-325/80-23 Corrective actions reorganization of inservice insp will make future submittals more complete YOLLIBON A C Carolina Power & Light Co 80/07/11 App
- --8009240363 Forwards IE Insp Repts 90-924/80-20 & 50-325/60-23 on 800527-30 & notice of violation MJRPHY.C E. Region 2. Atlants, Reactor Construction & Engineering Support Branch 80/05/17 2pp
- --8009240368 Notice of violation from the on 800527-30 a Region 2, Atlanta, Office of the Director 80/06/16 ip
- --8009240374 IE Insp Repts 50-324/80-20 & 50-325/80-23 on 800527-30 Noncompliance noted inservice frap program incomplete & surveillance activity procedures not established or implemented HERDT, A.R. Region 2. Atlanta, Reactor Construction & Engineering Support Branch BLAKE, J.J. Region 2. Atlanta, Office of the Director 80/05/16 5pp
- 8009290287 Forwards IE Circular 80-2t, "Regulation of Refueling Crews" No written response required O'REILLY, J.P. Region 2. Atlanta, Orfice of the Director 80/09/t0 Sep
- 8007180365 Responds to 800827 Itr re notice of violation concerning improper disposal of radioactively contaminated matt & problems in implementation & mot of radiation protection program Related currespondence
  JONES, J A Carolina Power & Light Co 80/09/12 1p
- BOO9300042 Ack receipt of payment of civil penalties & util BOO827 ltr re measures taken to correct items of nancompliance Measures will be reviewed during subsequent insps to determine effectiveness in preventing addl noncompliance STELLO.V Office of Inspection & Enforcement, Office of the Director BO/09/12 lp
- 8009230693 Forwards 90-day response to IE Bulletin 79-018,re environ qualification of electrical equipment Add1 qualification data will be submitted upon availability Response available in Central Files only
  UTLEY.E £ Carolina Power & Light Co 80/09/19 ip
- R Periodic operating reports & related correspondence
- 8009160260 Forwards monthly operating repts for Aug 1900 TOLLISON, A.C. Carolina Power & Light Co. 80/09/09 ip
- --8009160263 Monthly operating ropts for Aug 1980 Wittis,E Carolina Power & Light Co 80/09/03 10pp
- S Reportable occurrences. LERs & related correspondence
- 8009020380 Forwards LER 80-057/031-0
  TOLLISON, A C Carolina Power & Light Co 80/08/26 ip
- --8009020391 LER 80-057/03L-0 on 800728 during calibr & functional check performance, low level switch 2-821-LIS-NB31C-3. Yarway Model 4418c, actuated at IS3 90 inches water applied Caused by instrument duriff Switch recalibr & returned to svc TOLLISON, A.C. Carolina Power & Light Co. 80/08/R6 1p
- 8009150168 Part 21 rept re leats in heat exchanger tubes of calandria type radicaste evaporator at facility Cause attributed to corrosive attack Evaporator unit out of svc pending repair of leats in tubes & sholl
  BENNETT
- B009100433 Submits special rept re 800808 total loss of power to Emergency Dus E-3 Caused by improperly grounded welding machine Welding cables rerouted TOLLISONAA C Caroline Power & Light Co 80/09/04 2pp
- 8009180570 RD 80-062 on 800907, during reactor core isolation cooling flow rate test at 150 psig pressure.RCIC turbine tripped on high exhaust pressure Caused by manually operated stop check in exhaust to torus found in locked closed position TOLLISON.A C Carolina Power & Light Co 80/09/08 3pp
- 8009230719 Forwards LER 80-050/03L-0 TOLLISON, A C Carolina Power & Light Co 80/09/10 ip

- --8009230727 LER 80-050/03L-0 on 800821, switch 2 of 2-821-F15-N02|B Barton Model 288 found out of calibr Probably caused by accidental bumping by personnel during refueling outage Switch & instrument recalibr & returned to svc TOLLISON.A C Carolina Power & Light Co 80/09/10 2pp
- 8009230459 RD on 800819, fire support group tripped fire protection deluge valve on 50-ft elevation of diesel generator bidg in ventilation intake fan room Valve actuator arm facing seal found cracked & actuator solenoid relay misadjusted TOLLISON. A C Carolina Power & Light Co 80/09/15 ig
- 8009250265 Special rept while performing insp to determine fire dc.r operability, dotermined that three doors inoperative Caused by door closers in need of adjustment Closers readjusted & returned to operability

  TOLLISON. A C Carolina Power & Light Co 80/09/16 ip
- 6009260635 Forwards LER 80-066/01T-0 FURR.B J Carolina Power & Light Co 80/09/19 ip
- --8009260638 LER 80-066/01T-0 on 800907, reactor core isolation coding turbine tripped on high turbine enhants pressure Caused by improper valve positioning apparently due to personnel error
  TOLLISON, A C Carolina Power & Light Co 80/09/19 6pp
- 8009290288 Forwards updated LCR 80-033/03L-1 TOLLIBON, A C Carolina Power & Light Co 80/09/19 ip
- --8009290309 Updated LER 80-033/03L-1 on 800215, while attempting to 11; in 2A RIMR room cooler, cooler blower motor tripped on magnetics Caused by low breaker magnetics setting Breaker magnetics reset 3 breaker satisfacturily tested TOLLESON, A C Carolina Power & Light Co 80/09/19 1p
- --8009300479 Updated LER 80-062/01T-1 on 800907 during unit 2 reacter core isolation cooling flow rate testimeactor core isolation cooling turbine tripped on high turbine exhaust pressure Caused by personnel error TULLIBON.A C Carolina Power & Light Co 80/09/24 App
- DOCKET 50-329 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1

  F. Sacurity, medical, emergency & fire protection plans
- BOOY230252 Requests that all personnel be reminded of purpose of emergency notification sys 5 health physics network Sys installed for govt use during emergency D'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/22
- E009090402 Bubmits revised schedule for submittal of revised exerging plan, as specified by 800819 final rule revising 10CFR50 & 70
  UTLEY, E E Carolina Power & Light Co 80/09/02 ip
- 6 Adjudicatory correspondence
- BOO9220120 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 IPPOLITO.T A Operating Reactors Branch 2 80/08/29 2pp
- ---B009220122 Order for mod of Licenses DPR-62 & DPR-71 to add infest fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by B01101 EIBENHUT, D & Division of Licensing 80/08/27 App
- H General correspondence
- 8009120437 Advises of BWR owners group organizational changes & that future correspondence be forwarded to DB Waters Future requests for util action should be addressed to individual licenses & applicants
  WATERS, D H Carolina Power & Light Co 80/09/09 2pp

- P Operating license stage documents 5 correspondence
- 8009110554 Suppls NRC 800707 request for proposed Tech Specs changes re scram discharge vol vent A drain valves. 9 reactor protection sys 6 control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT, D 0 Division of Licensing 80/07/22 22pp
- 8009020297 Submits interim criteria for shift staffing to all DL & CP licensees & applicants per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISSNHUT.D G Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities 'Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 enci W/o NUREG EISENHUT, D G Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lossons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D G Division of Licensing 80/08/07 aOpp
- 8009040309 Advises that two specific Event 5 valve configurations do not grist at facility per review of response to 800223 ltr "Primary Coolant Sys Pressure Isolation Valves." technical evaluation rept encl
  IPPDL1TO: T A Operating Reactors Branch 2 80/08/08 3pp
- --5009040315 "Primary Coolant Eys Pressure Isolation Valves," technical evaluation rept NGELL,P N . STILWELL,T C Franklin Institute/Franklin Research Center NRC-03-79-118 80/07/21 5pp
- 8009190678 Forwards NUREO-0661, "Mark I Containment Long-Term Program SER Resolution of Generic Technical Activity A-7" Rept discusses generic suppression pool hydrodynamic load definition M/o encl IPPOLITO,T A Operating Reactors Branch 2 80/08/20 2pp
- 8009230772 Notification of 800905 meeting w/util in Bethesda,MD to discuss procedure for amending OLs to add addl owners HILBGN. J N Licensing Branch 1 80/08/29 4pp
- 8009090448 Forwards updated outage schedule re Mark I containment program mode Containment mode to conclude in May 1992 Plant unique analysis scheduled to be comploted in June 1981 UTLEY,E E Carolina Power & Light Co 80/09/02 2pp
- E009190047 Advises of acceptability of 791227 response to NRC 791109 lfr re ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture IPPOLITE TA Operating Reactors Branch 2 80/09/03 2pp
- 8009170186 Forwards "Recovery of Radioactive Matl from Brunswick County Landfill near Southport,NC," final rept FURR,B J Carolina Power & Light Co 80/09/05 1p
- --8009170197 "Radiation Control & Test Procedure 3280, Radioactive Matl Recovery Procedure " # Carolina Power & Light Co 80/05/01 8pp
- 8009160374 Forwards results of review of ECCS equipment availability w/dc power supply failure
  UTLEY.E E Carolina Power 1 Light Co 80/09/11 4pp
- 8009170400 Summary of 800905 meeting w/CP&L & NC Municipal Power Agency 3 in BethesdarMD re procedure for OL & CP amends WILSON.J N Licensing Branch 1 80/09/12 7pp
- BOD9190425 Application to amend License DPR-71 to revise Tech Specs by changing temporary spec issued W/Amend 29 re safety roller valve settings Effective and date of spec will be extended until completion of T-quencher mod VTLEY.E E Carolina Power & Light Co 80/09/15 2pp

- 8009230438 Forwards proposed revisions to Tech Specs, implementing changes requested by NRC 800702 ltr re TMI Lessons Learned requirements Proposed license conditions encl
  UTLEY.E E Carolina Power & Light Co 80/09/16 4pp
- --8009230437 Proposed revisions to Tech Specs.Pages 3/4 3-51 & 92. B 3/4 3-3.6-5.6-6 re post-accident monitoring instrumentation & min shift crew composition & Carolina Power & Light Co 80/09/14 [Opp
- Q Inspection reports. IF Bulletins & correspondence
- 8009090095 Forwards IE Bulletin 80-07, Suppl 1, "BMR Jet Pump Assembly Failure" No response required O'REILLY, J.P. Region 2, Atlanta, Ortice of the Director 80/05/13 lp
- 8009190329 Forwards IE Insp Repts 50-324/80-26 & 50-325/80-29 on 800601-30 No noncompliance noted LEWIS:8 C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/07/24 2pp
- --8009190379 IE Insp Repts 50-324/80-26 % 90-328/80-29 on 800601-30
  No noncompliance noted Major areas inspected control room
  observations.Unit 1 refueling operations review of plant
  logs, tour of vital areas & physical security
  OUZTS.JE Region 2. Atlanta, Office of the Director
  KELLOGG.P J Region 2. Atlanta, Reactor Operations Nuclear Support
  Branch 80/07/23 3pp
- 8009240273 Forwards IE lnsp Repts 50-324/80-23 & 50-325/80-26 on 800402-04 No noncompliance nated LDNG, F J Region 2, Atlanta, Office of the Director 80/08/04
- --8007240284 JE Insp Repts 50-324/80-23 & 50-325/80-26 on 800602-06 No noncompliance noted Major areas inspected site environ monitoring & circumstances surrounding B00222 radioactive matl release from auxiliary boiler sys LONO, F. J. MARSH.R. J. Region 2. Atlanta, Office of the Director HARDIN,A K. Region 2. Atlanta, Construction & Engineering Support Branch 80/08/04 15pp
- 8009020199 Submits response to IE Bulletin 80-17, Suppl 1 No design defictencies have been noted which would preclude scram discharge vol from performing required functions FURR:B J Carolina Power & Light Co 80/08/07 2pp
- 8007030163 Forwards Revision 1 to IE Bulletin 80-17, "Failures of Mercury-Hetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Uritten response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/15
- 8009160040 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessantial Control Air at Certain GE BNR Facilities " No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/19 to
- B009230059 Submits response to 1E Bulletin 80-20 Nestinghouse Type W-2 control switches not used in safety-rolated applications FURR.B J Carolina Power & Light Ca B0/08/19 1p
- 8009230080 Submits response to IF Bulletin 80-19 Mercury-wetted relays are not used in reactor protection sys FURR,B J Carolina Power & Light Co 80/08/19 1p
- BO04230085 Submits add1 info re Item 3 of IE Bulletin 60-02 Feedwater spargers were evaluated & do not require essential equipment classification FURR.B J Carolina Power & Light Co B0/08/19 2pp
- 8007070638 Ack receipt of BJ Furr 800703 ltm identifying corrective measures for noncompliance noted in 8006ii ltm & payment of proposed civil penalties STELLO, Unifice of Inspection & Enforcement, Office of the Director 80/08/20 lp
- 8009120072 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR" Written response required 0'REILLY.JP Region 2, Atlanta, Office of the Director 80/08/22

- 8009160124 Forwards IR Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required CrRFILLY.J P. Region 2. Atlanta, Orfice of the Director 80/08/22
  - O'REILLY, J P Region 2. Atlanta, Orfice of the Director 80/08/22 tp
- 8009020321 Responds to 800801 notice of proposed imposition of civil penalty re improper disposal of radioactive matl Corrective action taken new procedure implemented to remove radioactive matl Penalty fee end.

  JONES, J.A. Carolina Power & Light Co. 80/08/27 7pp
- 8009110027 Responds to NRC 800801 ltr re violations noted in 1E insp repts Corrective actions radiation protection program improved & offsite disposal of potentially contaminated mat1 terminated JQP-S.J.A. Carolina Power & Light Ca. 80/08/27 17pp
- 8009120290 Forwards IE Info Notice 80-31. "Haloperation of Gould-Brown Bovers 483 Voit Type K-6005 & K-DON 6005 Circuit Breakers " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/27
- E009240370 Responds to IE Bulletin 80-15 Emergency notification syspowered from Generator 2 during loss of offsite power Diesel generator actual load test is scheduled for Fall of 1980 FURR.B J Carolina Power & Light Co 80/08/27 2pp
- 8009110662 Responds to IE Bulletin 80-17. Suppl 3. re failure of 76 of 185 control rods to fully insert during scram at BNR Item 1 not applicable Persodic Test 1 1 2P revised FURR. B J Carolina Power & Light Co 80/09/28 1p
- 8007230526 Forwards Revision 1 to IE Bulletin 79-26. "Boron Loss From BHR Control Blades" Written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/29 is
- 8007240329 Ack receipt of 800711 & 0811 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/80-20 & 50-325/80-23 MURPHY.CE Region 2. Atlanta Reactor Construction & Engineering Support Branch 80/09/03 ip
- --8009240340 Responds to NRC 800617 ltr re violations noted in IE Insp Repts 50-324/80-20 & 50-325/80-23 Corrective actions procedures established re site engineering 0A/GC acceptance of surveillance data & inservice insp TOLE ISON, A C Carolina Power & Light Co 80/08/11 2pp
- -- #8009240356 Responds to NRC 800a11 ltr re violations noted in IE Insp Repts 50-224/80-20 & 50-325/80-23 Corrective actions reorganization of inservice insp will make future submittals more complete TOLLISONA C Carolina Power & Light Co 80/07/11 4pp
- --8007240363 Forwards IE Insp Repts 50-324/80-20 & 50-325/60-23 on 800527-30 & notice of violation MJRPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/86/17 2pp
- --8009240368 Natice of violation from insp on 800527-30
  \* Region 2. Atlanta, Office of the Director 80/06/16 is
- --8009240374 [E Insp Repts 50-324/80-20 & 50-325/80-23 on 800527-30 Noncompliance noted inservice insp program incomplete & surveillance activity procedures not established or implemented HERDI.A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch BLAKE J Region 2, Atlanta, Office of the Director 80/06/16 Spp
- 8009290287 Forwards IE Circular 80-21, "Regulation of Refueling Craws " No written response required O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/09/10 500
- B009180355 Responds to B00827 Itr re notice of violation concerning improper disposal of radioactively contaminated matl & problems in implementation // mgt or radiation protection program Related correspondence

  J0095.J A Carolina Power & Light Co 80/09/12 1p
- BOO9300042 Act receipt of payment of civil penalties & util 800827 ltr re measures taken to correct items of noncompliance Measures will be reviewed during subsequent insps to determine effectiveness in preventing addl noncompliance STELLO.Y Office of Inspection & Enforcement, Office of the Director 80/09/12 ip

- 8009230693 Forwards 90-day response to IE Bulletin 79-016, re environ qualification of electrical equipment Addl qualification data will be submitted upon availability Response available in Central Files only
  UTLEY.S E Carolina Power & Light Co 80/09/19 1p
- R Pariodic operating reports & related correspondence
- 8009160260 Forwards monthly operating repts for Aug 1980 TOLLISON,A C Carolina Power & Light Co 80/09/09 ip
- --8009160263 Monthly aperating repts for Aug 1980 HILLIS.E Carolina Power & Light Co 80/09/03 10pp
- S Reportable occurrences. LERs & related correspondence
- 8009150168 Part 21 rept re leaks in heat exchanger tubes of calandria type radwaste evaporator at facility Cause attributed to corrosive attack Evaporator unit out of svc pending repair of leaks in tubes & shell BENNETT.R C Whiting Corp 80/09/09 3pp
- 8009100433 Submits special rept re 800808 total loss of power to Emergency Bus E-3 Causes by improperly grounded welding machine Nelding cables rerouted TOLLISON, A C Garolina Power & Light Co 80/09/04 2pp
- 8009120346 Ferwards LER 80-055/03L-0 FURR. B J Carolina Power & Light Co 80/09/05 1p
- --8009120371 LER 80-055/03L-0 on 800812 during startup preparations, reactor vessel conductivity measured excessively high Caused by organics breakdown in reactor vessel Series of condensate makeup & reject operations performed using charcoal filters TOLLISON, A C Carolina Power & Light Co 80/9/04 1p
- 8009180570 RO 80-062 on 800907, during reactor core isolation cooling flow rate test at 180 psig pressure, RCIC turbine tripped on high exhaust pressure Caused by manually operated stop check in exhaust to torus found in locked closed position TOLLISOM, A C Carolina Power & Light Co 80/09/08 3pp
- 8009230624 Forwards updated LER 80-012/03L-i TOLLISON, A C Carolina Power & Light Co 80/09/10 1p
- --8007230635 Updated LER 80-012/03L-1 on 800224 during normal surveillance,RIF valves X206D-C, variable leg isolation for torus level transmitter GAC-LT-2606 & switch E41-LSH-N019B, shut & failed to reoper Gaused by leaking switch diaphragm TOLLISON.A C Carolina Power & Light Co 80/09/10 2pp
- 8009230725 Forwards updated LER 80-024/03L-1 TGLLISCH.A C Carolina Power & Light Co 80/09/10 1p
- --8009230735 Updated LER 80-024/03L-1 on 800405, drywell equipment drain integrator observed indicating flow w/both pumps secured & common isolation valve shut Caused by accumulation of rust & corrosion around valve seat of vacuum breaker TOLLISON,A C Carolina Power & Light Co 80/09/10 2pp
- B009230736 Forwards LER 80-066/03L-0 TCLLISON, A C Carolina Power & Light Co 80/09/12 ip
- --8009230740 LER 80-066/03L-O on 800824, during normal surveillance, containment atmospheric menitor oxygen analyzer, I-CAC-ATIN-1257-2: was observed indicating upscale Caused by loss of sample flow due to condensate in analyzer air dryer TOLLISON, A C Carolina Power & Light Co 80/09/12 2pp
- 8007230457 RO on 800819, fire support group tripped fire protection deluge valve on 50-ft elevation of diesel generator bldg in ventilation intake fan room Valve actuator arm facing seal found cracked & actuator solenoid relay misadjusted TOLLISON, A C Carolina Power & Light Co 80/09/15 ip
- 8009230470 Forwards LER 80-045/03L-0 TOLLISON-A C Carolina Power & Light Co 80/09/16 1p
- 8007230709 Forwards LER 80-067/03L-0 TOLLISON A C Carolina Power & Light Co 80/09/16 1p

- --gg09230717 LER 80-047/03L-0 on 800822, while withdrawing control rods during startup, erroneous rod blocks were received from rod worth minimizer Also plant process computer printed notch errors thile none existed Cause not determined TOLLISONAC Carolina Power 5 Light Co 80/09/16 2pp
- ED39230718 Forwards LER 80-063/03L-0 TO:\_LISON.A C Carolina Power 3 Light Co 80/09/16 1p
- --8009230745 LER 80-063/03L-0 on 800826, during testing of reactor flow bias, three average power range monitors were actuating out of spec Caused by instrument drift Monitor4 recalibr % returned to svc
  TOLLISCHAC Carolina Power % Light Co 80/09/16 1p
- EC09250265 Special rept while performing insp to determine fire door operability.determined that three doors inoperative Caused by dear closers in need of adjustment Closers readjusted & returned to operability TOLLISOW.
- 8009270286 Forwards LER 80-058/03L-0 TOLLISOM, A C Carolina Power & Light Co 80/09/19 1p
- --B009290311 LER 80-058/03L-0 on 800822, during normal surveillance, drywell flow integrator failed to change while sump pump was running Caused by blown fuse in drywell floor drain flow transaitter power supply Fuse replaced FOLEISON.A C Carolina Power & Light Co 80/09/19 2pp
- 3309303489 Forwards LER 80-069/03L-0
  TOLLISON A C Carolina Power & Light Co 80/09/23 [p
- --8009300509 LER 80-069/03L-0 on 800827, during normal surveillance, RHR flow indicator on remote shutdown panel demonstrated erratic indications w/sys shutdown Caused by mechanical failure of meter movement Movement callbr & returned to suc TOLLISON.A C Carolina Power & Light Co 80/09/23 2pp
- 8009300559 Forwards LER 80-070/03L-0 TGLLISON A C Carolina Power 3 Light Co 80/09/24 1p
- --8007300569 LER 80-070/03L-0 on 800828, during normal operation, several alarms received from Diesel Generator 1 Cause not determined Alarm relays reset, generator tested & returned to svc Update rept to be submitted upon discovery of cause TOLLISOV.A C Carolina Power & Light Co 80/09/24 ip
- ECCEPT 50-326 UNIV OF CALIFORNIA AT INVINE RES REACTOR
- G Inspection reports, IE Bulletins & correspondence
- 80.09120459 Ack receipt of 800821 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-326/80-01 CREWS.J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/09/04 ip
- --8039120466 Responds to NRC 800812 ltr re violations noted in IE Imap Rept 50-326/80-01 Corrective actions operating procedure revised to include annual review of reactor operational records MCGAUGH, J L California, Univ of, Irvine 80/08/21 3pp
- --8009120470 Ack receipt of 800724 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-326/80-01 NRC concluded that licensee actions are not sufficient to avoid further violations

  CREWS.J L Region 5, San Francisco: Reactor Operations Nuclear Support Branch 80/08/12 ip
- -8009(2047) Responds to NRC 800703 ltr re violations noted in IE lnsp Rept 50-326/80-01 Corrective actions reactor operations committee will establish regular schedule for review of facility operations & schedule quarterly committee meetings MCCAUCH.JL California, Univ or, Irving 80/07/24 2pp
- -8009120474 Forwards IE Insp Rept 50-326/80-01 on 800519-21 & notice of violation CREMS.J L Region 5, San Francisco, Reactor Operations Muclear Support Branch 80/07/03 2pp
- -8009120476 Notice of violation from insp on 800519-21 \* Region 5, San Francisco, Office of the Director 80/07/03 ip

- --8007120478 IE Insp Rept 50-326/80-01 on 800517-21 Noncompliance noted failure of reactor operations committee to meet & conduct quartorly reviews at required frequency FAULKENGERRY, B. Region 5. San Francisco, Reactor Operations Nuclear Support Branch ZMETZIO, Q.B., CMAFFEE, A.E. Region 5. Gan Francisco, Office of the Director 80/07/03 Spp
- DOCKET 50-327 SEGUDYAH NUCLEAR PLANT, UNIT 1
- E NRC Safety Evaluation Report (SFR), suppls & correspondence
- BO07080419 Forwards Suppl 2 to SER (NUREG-0011)
  SCHNENGER, A Licensing Branch 2 B0/09/04 2p
- --8009080423 SER for facility

  \* Office of Nuclear Reactor Regulation, Director NUREO-0011 82
  80/08/31 175pp Available at NTIS \$5.50
- 8009260254 Forwards Buppl 3 to SER for facility SCHWENCER, A Licensing Branch 2 80/09/16 2pp
- --8009260258 SER for facility, Suppl 3 \* Office of Nuclear Reactor Regulation, Dijector NUREO-0011 83 60/09/30 82pp Available at NTIS \$4 00
- F Security, medical, emergency & fire protection plans
- BOO9230267 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Bys installed for govt use during emergency O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/08/22.
- 8009030536 Notifies of 800822 final implementation of radiological emergency plan as revised by 800/21 & 0815 ltrs MILLS.L M Tennossee Valley Authority 80/08/29 ip
- 8009230333 Forwards physical security plan.Revision 6A Revision withheld (ref 10CFR2 790)
  MILLS.L M Tennassee Valley Authority 80/09/17 1p
- Q Adjudicatory correspondence
- 8009220427 Order authorizing issuance of OL DRR-77 CHILK.S J Office of the Secretary of the Commission 80/09/10 ip
- H General correspondence
- BOO7110387 Commends Commissioners for denying facility full-power license until hydrogen buildup issue has been resolved beyond any doubt No compromise too expensive for prevention of another near-devastating event such as TMI CALDNELLM A Affiliation Unknown RO/09/00 10
- 8009120301 Responds to 800/03 ltr requesting NRC comment on & Bpallons 800619 ltr re-potential impact of dan failure of Pand Hill Reservoir which util is considering for future const FEG scheduled for completion in Dec 1980 DIRCKS. W. J. Office of the Executive Director for Operations 80/09/08 | 1p
- --8009120317 Requests NRC response to encl K Spallone 800619 ltr re potential impacts of Pond Hill Reservoir const & operation within 2 wks of receipt of request SCHWEIKER, R B Benete 80/07/03 2pp
- I Financial information
- B009090543 Forwards Annual Financial Rept 1979. CROSS.J L Tennessee Valley Authority 60/09/04 ip
- --8009070563 Annual Financial Rept 1979 \* Tennessee Valley Authority 80/09/04 4App
- J Insurance & indemnity information
- 8009030374 Forwards Endorsement 1 to NELIA Binder EB-66 FIELPER, J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/08/25 2pp

- K. Utility Final Sarety Analysis Report (FSAR) & amends
- 8009030560 Forwards atfidavit certifying that Amends 66 & 67 to FSAR were mailed to D Moore. JE Hagan & BA Osborne en 800826 MILLS.L M Tennessee Velley Authority 80/08/26 28p
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8009120528 Notice of ACRS 800710-12 meeting in Washington DC to discuss rept on N9C screty research budget for FN82 & operation of Sequeyah Unit 1
  HOYLE, J. C. Assistant Director for Export/Import & International Safeguards 80/06/19 App
- 9009190766 Distusses 2431d ACRS meeting on 800710-12 to Sequoyah review & research program Fr82 budget
  PLESSET.M S ACRS Advisory Committee on Reactor Safeguards
  80/07/18 358
- 8009160083 Notice of ACRS Subcommittee on Structural Engineering 800902 meeting in Pashington, DC to establish max internal pressure Sequeyah containment can withstand HOYLE J C Office of the Secretary of the Commission 80/08/13 2ao
- 8009050394 Transcript of ACRS Subcommittee on Structural Engineering 800902 hearing in Washington.DZ re establishing max external pressure temp that Sequoyah containment structure can withstand ACRS Advisory Committee on Reactor Safeguards 80/09/02 182pp
- 8009180172 Forwards agendas for ACRS 800902 subcommittee meeting & 800904 full committee meeting re facilities
  TEDESCO.R L Assistant Director for Licensing 80/09/02 4pp
- 800915023B Responds to request for comments on questions contained in V Gilinsky 800807 ltr re factility ice condenser containments Factility is capable of sustaining pressure of at least 45 psig w/o structural failure PLESSCT. M S ACRS Advisory Committee on Reactor Safeguards 80/09/08 3pp
- 8009300329 Forwards ACRS 600908 ltr to J Ahearne re ice condenser containments CONTAINMENTS SCHEENCER, A Licensing Branch 2 80/09/18 2pp .
- P Operating license stage documents & correspondence
- 8009110604 Requests review of R&D Associates rept, "Sequoyah Containment Analysis" Comments due by 800801 TEOESCO.R L. Assistant Director for Licensing 80/07/29 2pp
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl N/o NUREG EISENHUT, D O Division of Licensing 80/08/01 119pp
- 8008210618 Discusses preliminary assessment of use of igniters as method of hydrogen control at facilities Assessment based on present understanding of util-proposed igniter scheme Exclusive use of igniters may not be grudent BARI.R A Brookheven National Laboratory 80/08/08 3pp
- 8009120578 Responds to request for comments re Sequoyah containment Forwards info re stringer & skin interaction Concludes NRC calculations overestimated beneficial effect of stringers HUBBARD.H W R & D Associates 80/08/18 Bpp
- 8009110332 Forwards full-power OL, stide presentation entitled, "NRC Staff Review of Sequoyah for Full Power Operation Commission Brisfing, 800821," transcript of NRC 800821 public meeting & draft Suppl 2 to SER, NUREO-0011 DENION, IR Office of Nuclear Reactor Regulation, Director, 80/08/20 14pp
- --8007110341 Transcript of Commission 800821 public meeting in Mashington, DC to discuss facility full-power license Pp 1-87 \* Cormission 80/08/21 91pp
- ---8009110343 Braft Suppl 2 to SER \* Office of Nuclear Reactor Regulation, Director NURE9-0011 92 80/09/15 150pp

- 8009040434 Forwards matl re NRC review of ice condenser containment to hydrogen control measures for Sequoyah Nuclear Power Plant ACRS has scheduled meetings in Washington. DC on 800828.0702 to 40 discuss issue TEDESCO.R L. Assistant Director for Licensing 80/08/22 50b
- ---8009040443 "Hydrogen Control for Sequoyah Nuclear Plant, Units | 1,2 +
  4 Office of Nuclear Reactor Regulation, Director 80/08/13
  81pp
- --8009040450 Transcript of 800821 discussion of Sequoyah full power license in Washington, DC Pp 48-89 + Connission 80/08/21 47pp
- 8009150527 Forwards requests for addl info in response to util 800814 1tr re-safety analysis of interim distributed ignition sys SCHMENCER.A Licensing Branch 2 80/08/28 3pp
- 8009030436 Forwards Procedure IP-18. "Plant Release Rate Calculations" & graphs of containment activity as function of monitor reading. in fulfillment of 800811 commitment to provide correlation procedure MILLS.t M Tennessee Valley Authority 80/08/29 3pp
- --8009630435 "Plant Release Rate Calculations "
  ZOBEL.W , KITTS,R J , DILL.J Tennessee Valley Authority
  80/08/21 48pp
- 8009240560 Forwards preliminary staff assessment re use of halon as hydrogen combustion control measure Items addressed include selection 8 design of halon delivery sys, chemical stability requirements, reactivity 5 consequences of halon injection DENTON, H R Defice of Nuclear Reactor Regulation, Director 80/08/29 9pp
- --8009240564 Staff requirements memo re Commission 800814 meetjng CHILK, S J Office of the Secretary of the Commission 80/08/18
- 8009030662 Forwards "Core Degradation Program.Vol 1 Hydrogen Study\* t "Core Degradation Program Vol 2 Rept on Safety Evaluation of Interim Distributed Ignition Sys." in response to NRC 800828 itr Cross ref of NRC Questions & util answers encl MILLS.L M Tennessee Valley Authority 80/09/02 3pp
- --8009030664 "Core Degradation Program, Vol 1 Hydrogen Study = # Tennessee Valley Authority 80/09/02 100pp
- 8009050257 Forwards status rept on licensing items requiring completion defore exceeding 5% power operation identified in 800820 draft full power license Procedures required as resolution to IE Bulletin 79-27 will be approved by 800905 CROSS.J.L. Tennessee Valley Authority 80/09/03 2pp
- 6009110349 Farwards proposed full-power OL. Supple 2 & 3 to SER & "Discussion of Environ Effects of U Fuel Cycle " Tests & safety review of proposal for distributed ignition sys expected to be completed by Jan 1981 DENICH H R Office of Nuclear Reactor Regulation, Director 80/09/03 18pp
- --8009110355 Draft Suppl 3 to SER

  \* Office of Nuclear Reactor Regulation, Director NUREG-001153
  80/09/30 75pp
- --8009110398 "Discussion of Environ Effects of U Fuel Cycle" \* Office of Nuclear Reactor Regulation, Director 80/09/30 92pp
- --80091100A0 Suppl 2 to SER

  \* Office of Nuclear Reactor Regulation, Director NURE9-001157
  H0/08/31 180pp Available at OPO %5 50
- 8009250243 Forwards consultant ltr on possible fire risk in its condensors w/foam insulation Response requested by 900704 for discussion at ACRS meeting TEDESCO.R L. Assistant Director for Licensing 80/09/03 2pp
- --8009250247 Expresses concern re possible fire risk in ice condenset
  W/foam insulation
  MACDDUGALL-E A Brockhaven National Laboratory 80/08/18 IP

- 8007080299 Forwards description of facility ice condenser insulation maths & containment wall insulation structural design & insulation flammability review results CROSS.J L Tennessee Valley Authority 80/09/04 lipp
- B009090370 Forwards addl info on temp control for main steam valve rooms in response to NRC request Info revises util 800729 ltr
  - CROSS.J L. Tennessee Valley Authority 80/09/04 2pp
- 8009120389 Provides info re polyurethane foam insulation in ite condenser Auto ignition temp is 1,000 F & ignition temp is 400 to 500 F Decomposition starts at 300 F CRESS.J L Tennessee Valley Authority 80/09/05 ip
- 8009300294 Forward Chilk 800818 memo to Dircks re briefing on hydrogen control in Sequoyah containment DENTON.H R Office of Nuclear Reactor Regulation, Director B0/99/10 1p
- 8009190476 Forwards info re matl test repts for critical section of containment steel Mill test rept on critical section will be submitted by 800919
  MILLS.L M Tennessee Valley Authority 80/09/12 4pp
- 8009170297 Forwards mill test rept re critical section of containment steel in facility Matl suppls 800912 submittal which summarizes assessments of containment to withstand internal pressures Diversize drawings available in Central Files only, MILLS, L M Tennessee Valley Authority 80/09/15 10pp
- 8009230549 Proposes alternate replacement schedule for turbocharger drive gear assemblies mfg by General Motors Util will limit turbocharger operation to less than 200-h MiLLS.L M Tennessee Valley Authority 80/09/17 2pp
- 8009290333 Forwards Revision 3 of response to NUREO-0578, TMI-2 Leasons Learned Task Force status rept & short-term recommendations, Items 2 1 & Revision 3 changes procedures description for reducing & quantifying leakage from liquid sys MILLS, L M Tennessee Valley Authority 80/09/22 ip
- 8009300226 Requests changes to facility Tech Specs to permit plant startup Includes revisions to surveillance requirements.
  Leakage limit for valves FCV-74-1 & FCV-74-2 & leakage testing on valves after automatic or manual action MILLS.L K Tennessee Valley Authority 80/09/23 2pp
- 8007300400 Forwards technical questions re implementation of interim policy on 10CR450 & 51
  MILLS.L.M Tennesses Valley Authority 80/09/23 3pp
- 8009290262 Application for amend of License DPR-77, changing Tech Specs 3 4 6 2,4,4 6 1 % 3 4-1 to permit leak testing of valves in Mode 3 MILLS, L M Tennessee Valley Authority 80/09/24 ip
- --8009290280 Proposed Tech Specs 3 4 6 2,4 4 6 1 & 3 4-1, permitting leak testing of valves in Mode 3 & allowing util 30 days to accumulate data at rated sys pressure to establish baseline leakage limits for RHR sys supply line valves # Tennessee Valley Authority 80/09/24 Spp
- G Inspection reports, IE Bulletins & correspondence
- E009040317 Forwards IE Insp Rept 50-327/80-23 on 800616 No noncompliance noted BTGHR.J.P. Region 2. Atlanta. Fuel Facility & Materials Safsty Branch 80/07/14 2pp
- --8009040330 IE Insp Rept 50-327/80-23 on 800616 No noncompliance noted Major areas inspected emergency exercise between TVA & offsite support organizations

  JENKINS, 0 R Region 2, Atlanta, Fuel Facility & Materials Safety Branch 01880N,0 T , COTILE,W Region 2, Atlanta, Office of the Director 80/07/15 App
- 8007100051 Forwards IE Bullstin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Written response required d'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/07/24
- 8009020214 Forwards response to IE Bulletin 79-03A No 5A-312 & A-312, Type 300 series fusion wolded pipe used or planned for use in safety-related sys at greater than 85% design stress except Watts Bar Mati under investigation at Watts Bar Milles-L M Tennessee Valley Authority 80/08/05 2pp

- 8009090802 Responds to IE Bulletin 79-03A "Longitudinal Weid Defects in ASNE SA-312. Type 301 Stainless Steel Pipe " Use of matis still under investigation for sys supplied by MBSS vendor MILLS. L II Tennessee Valley Authority 80/08/05 2pp
- 8009020303 Forwards IE Insp Repts 50-327/80-24,50-328/80-15, 50-390/80-20,50-391/80-14,50-438/80-13 50-439/80-13, 50-518/80-11,50-518/80-11,50-518/80-11,50-554/80-10,50-520/80-11,50-521/80-11, 50-554/80-10,50-566/80-10 & 50-567/80-10 O'REILLY, J P Region 2, Atlanta, Orfice of the Director 80/08/04
- --8009020312 Notice of violation from insp on 800707-11 \* Region 2, Atlanta, Office of the Director 80/08/06 4pp
- --8009020337 IE Insp Repts 50-327/80-24,50-328/80-15,50-390/80-20,50-391/80-14,50-438/80-13,50-439/80-13,50-518/80-11,50-519/80-11,50-526/80-11,50-521/80-11,50-553/80-11,50-554/80-10,50-554/80-10,50-554/80-10,50-554/80-10,50-554/80-10,800-70-11
  BROWNLEE, V L , MODERNOW, L Region 2, Atlanta, Office of the Director CONLON-TE Region 2, Atlanta, Reactor Construction & Engineering Support Brench 80/09/06 24pp
- 8007030146 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mencury-Hetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Hritten response required O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/08/15 to
- 8009020104 Forwards table listing all components identified by drawing review which do not remain in emergency mode after reset of an engineered safety features signal No items require mod to comply wilnteent of IG Bulletin 80-06 MILCS.L M Tennessee Valley Authority 80/08/18 App
- 8009160153 Ferwards IE Circular BO-18, "IOCFR90 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 60/08/22 ip
- 8009110118 Ack receipt of 800820 ltr informing NRC of steps taken to correct violations noted in IE Imag Rept 50-327/80-26 KEMNA.W 8 Region 2: Atlanta. Safeguards Branch 80/08/27 ip
- --8009110181 Responds to NRC 800728 ltr re violations noted in IE lasp Rept 50-327/80-26 Corrective actions withheld (ref 10CFR2 790) MILLS: L M Tennesses Valley Authority 80/08/20 ip
- --8009110168 Forwards IE Insp Rept 50-327/80-26 on 800708-09 & notice of violation Notice of violation withheld (ref 100FR2 790) KENNA.W B Region 2, Atlanta, Safeguards Branch 80/07/28 2pp
- --8009110191 IF Insp Rept 50-327/80-24 on 800708-09 Nancompliance noted testing alarms ence every seven days Details withheld (ref 10cFR2 790)
  TOBIN, If J. Region 2. Atlanta, Office of the Director Offices of the Director
- 8009120340 Forwards IE Info Notice 80-31, 'Maleperation of Gould-Brown Boveri 480 Volt Type K-6008 5 K-DON 6008 Circuit Breakers "
  No written response required
  O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/27
  to
- 8009120679 Responds to IF Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Relays identified are not used in facility Forty manhours expended for review MILLS-L M Tennessee Valley Authority 80/09/04 ip
- 8009250480 Forwards response to 18 Bulletan 80-15, "Possible Loss of Emergency Notification Sys (EUS) w/Loss of Offsite Power "ENS at facility is supplied power from onsite power source Mod to EMS power supply will be implemented CROSS, J. L. Tennessee Valley Authority 80/09/05 2pp
- 8009260375 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/10 5pg
- GOD9300195 Submits response to IE Bulletin BO-05 re engineered safety features reset controls Pressurizer backup heater bank has been found to return to normal status Operating instructions & operator training will provide guidance MILLG.L II Tennessee Valley Authority GO/09/15 2pp

# R Periodic operating reports & related correspondence

- E009030397 Discharge monitoring mept for 800501-0601 EL-ASHRY, M 1 , STEINER.G R Tonnessee Valley Authority 80/08/08
- 8007070414 Forwards "Radiological Impact Assessment Sequoyah Nuclear Plant Jan-June 1780 " MILLS.L.H. Tennessee Valley Authority 80/08/27 1p
- --8009090418 "Radiological Impact Assessment, Sequoyah Nuclear Plant, Jan-June 1980" 3 Tennessee Valley Authority RH-80-6-801 80/08/29 23pp
- 8007170261 Forwards monthly operating rept for Aug 1980 BALLENTINE, J M Tennessee Valley Authority 80/09/09 1p
- --8009170262 Monthly operating rept for Aug 1980
  BALLENTINE J M , HUBER, J M Tennassee Valley Authority 80/09/02
- S. Reportable occurrences. LERs & related Lucrespondence
- 8009100537 Final deficiency rept re control rod drop events Operating procedures to be revised per Nestinghouse instructions. Procedural change will be made prior to greater than 90% power level ascension t will prevent power overshoot. MILLS, L. M. Fennessee Valley Authority 80/08/05 2pp
- 8009020201 Final deficiency rept re sarety injection pump breaker lockout Seal-in contact of IX relays to be removed from circuit breakers in 6,900-volt shutdown boards by 801103 MILLS:L N Tennessee Valley Authority 80/08/25 2pp
- 8009030367 Forwards RD 80-3 CALHOUN.J R Tennessee Valley Authority 80/08/27 1s
- --8007030373 RO 80-3 with reactor on Mode 4, both centrifugal charging pumps automatically started injecting 535 gallons of 20,000 ppm borated water at 193 F into RCS Caused by incorrect suitch manipulation during test performance

  4 Tennessee Valley Authority 80/08/27 lp
- 8009030517 Forwards LER 80-094/03L-0 CALHOUN.J R Tennessee Valley Authority 80/08/27 1p
- --8009030523 LER 80-094/03L-0 on 800620, w/unit in Modes 3,4 or 5, May 1980 evaluation for tritium was not performed Caused by inadequate description in procedure SI-415 for taking monthly samples while unit is in different modes GRIP EY, C.F. Tennessee Valley Authority 80/08/27 1p
- 8009090547 Forwards LER 80-060/03L-0 CALHOUN, J R Tennessee Valley Authority 80/08/28 1p
- --8009070590 LER 80-060/03L-0 on 800521, ERCW liquid effluent radiation monitors were declared inoperable due to continuous, sporadic spiking Caused by contactor chattering on 8-8 emergency gas treatment sys room cooler fan motor HEREFORD, J B. Tennessee Valley Authority 80/08/28 ip
- 8009080354 Forwards EER 80-138/03L-0 CALHOUN, J. R. Tennessee Valley Authority 80/08/29 1p
- --8009090355 LCR 80-138/OGL-0 on 800801, during heavy thunderstorm, cooling tower blowdown line effluent monitor declared inoperable Caused by nearby lightning strike or power line surge Danagad parts being repaired & backup channel installed EMITHSON. J D. Tennessee Valley Authority 80/08/29 ip
- 8009080360 Forwards LCR 80-142/03L-0 CALHOUN, J R Tennessee Valley Authority 80/08/29 1p
- --8007080367 LER 80-142/03L-0 on 800/18, during testing w/unit in Mode 3, ice bod temp exceeded Tach Spec limit of 27 F Caused by insufficient recovery time between personnel entries & exits Work halted & temp reduced to 27 F.19 5-h later KIRK, 0 B Tennessee Valley Authority 80/09/02 ip
- 8009080373 Forwards LER 80-140/03L-0 CALHOUM, J.R. Tennessee Valley Authority 80/08/29 in

- --8009080380 LER 80-140/03L-O on 800809, during preoperational test.dieseJ generator 86LOR relay coils burned out following blackout initiation Caused by 86LOR relay being reset before blackout relays Coils replaced t relays reset ROMINE, D Tennessee Valley Authority 80/08/29 2pp
- 8009080382 Forwards LER 80-129/03L-0 CALHOUN, J. R. Tennessee Valley Authority 80/09/02 ip
- --B009080391 LER 80-129/03L-O on 800808, while operating in Mode 2 at 3 5% power, diesel generator 1A-A failed to start during simulated loss of power to 2A-A 6 9-kV shutdown board Caused by 43T (L) switch being left in test position from previous test RECORD, D J Tennessee Valley Authority 80/09/02 2pp
- 8009090527 Forwards LER 80~064/03X~1 CALHOUN,J R Tennessee Valley Authority 80/09/02 1p
- --8009090583 LER 80-064/03X-1 on 80050B.w/reactor in Mode 4, all zones on ice condense engaged open door alarms Caused primarily by ineffective design of control rod missile shield seals Seals were redesigned febricated & installed KIRK.G B Tennessee Valley Authority 80/09/02 3pp
- 8009090531 Forwards LER 80-143/03L-0 CALHOUN, J.R. Tennessee Valley Authority 80/09/03 ip
- ~-8009090589 LER 80-143/03L-0 on 800731, during preoperational test TVA 56, relay K609 was manually picked up & diesel operators 18-3, 2A-A & 2B-B failed to start Cause unknown Generators were ratested & subsequently started on 800801 RMMINE Tennessee Valley Authority 80/09/03 ip
- 8009120411 Forwards LER 80-149/03L-0 CALHOUN, J R Tennessee Valley Authority 80/09/04 ip
- 8009120412 Forwards LER 80-139/03L-0 CALHOUN, J R Tennessee Valley Authority 80/09/04 tp
- ---8009120440 LER B0-139/03L on B00807, during operation in Mode 2.B train transfer switch for component cooling water pump supply tripped on three occasions Caused by thermal overload assembly Switches modified by defeating overload features KIRK. 3 B Tonnessee Valley Authority 80/09/04 2pp
- B009160325 Forwards LER 80-147/03L-0 CALHOUN, J R Tennessee Valley Authority B0/09/04 ip
- ~-8009160327 LER 80~147/O3L~O on 800807, during support & hanger insp.addl hanger not required by design analysis was found installed on containment spray piping Hanger was temporary & inadvertently left in place Hanger was removed SUEARINGEN, J D Tennessee Valley Authority 80/09/04 1p
- 8009160375 Forwards LER 80-145/03L-0 CALHOUN, J R Tennessee Valley Authority 80/09/04 Ip
- --8009160380 LER 80-145/03L-0 on 800807, in mode 2 operation, cell 5t in diesel generator battery 18-8 shorted & failed, w/three addl cells already strapped out Cause not stated Diesel generator cells restored w/cells from diesel generator 28-8 RUMINE.D Tennessee Valley Authority 80/09/04 1p
- 8009160372 Second revised final deficiency rept re possible structural failure of spent fuel pool gate during seismic event Problem to be corrected by administratively requiring gate to remain in storage location during normal plant operations
  MILLS.L M Tennessee Valley Authority 80/09/08 Spp
- 8009160421 Forwards LER 80-146/03L-0 CALHOUN, J R Tennessee Valley Authority 80/09/08 1;
- ---8009160425 LER 80-146/03L-0 on 800617. following post-maint testing of safety injection pump 18-8, one step of venting instructions not signed Caused by lack of immediate followup action to determine cause before entering mode 3 HILSON. O Tennessee Valley Authority 80/09/08 2pp
- 8009160370 Forwards LER 60-151/03L-0 CALHOWA, J R Tennessee Valley Authority 80/09/10 1p

- --B009160398 LER B0-151/03L-0 on B00Bil, turbine driven auxiliary feedwater pump failed to start after loss of both main feedwater pumps Caused by torque switch failure causing yaive FCV-1-51 motor operator to short GELSTON. A H Tennessee Valley Authority 80/09/10 3pp
- 6009160406 Forwards LER 80-155/03L-0 GALHOUNJ R Tennessee Valley Authority 80/09/11 1p
- --8007160412 LER 80-155/03L-0 on 800813, w/unit in mode 3, remote shutdown monitoring channel L-68-312c was found inoperable Caused by flaw in plant operating procedures 8 unscaled transmitter leg was drained KIRK, 0 B Tennessee Valley Authority 80/07/11 1p
- EQ09160463 Forwards LER 80-152/03L-0 CALMOUN, J. R. Temmesson Valley Authority 80/09/11 ip
- ---9009160468 LER 80-152/03L-0 on 800812 dieset generator battery IB-B cellt 49-51 were found in discharged condition Caused by inadequate procedure Procedure has been changed & personnel reinstructed GEL670N.A H Tennessee Valley Authority 80/09/11 3pp
- 8009190471 Forwards LER 80-141/01T-0 CALKDUN, J R Tennessee Valley Authority 80/09/11 1p
- --80091905ti LER BO-141/01T-O on 800829, while in Mode 5, pinhote leak was discovered in rod travel-housing latch housing interface seal weld on control rod drive mechanism C-11 Cause not stated Fault to be ground out & weld repaired WILLIAMS, W O Tennessee Valley Authority 80/09/11 ip
- 8009190540 Forwards LER 80-154/03L-0 CALHOUM R Tennessee Vallay Authority 80/09/12 ip
- --E009190547 LER 80-154/03L-0 on 800815, auxiliary bldg vent radiation monitor B-RM-90-1018 did not respond to check source Caused by short in 24-volt power supply & detactor preamplifier HEREFORD, J M Tennessee Valley Authority 80/09712 1p
- 8009230524 Special Rept 80-4 on 800623 unit received safety injection signal from high steam flow & lo-to Tave signal or lo steam generator pressure Approx 540 gallons borated water injected into RCS at 190 F Originally reported as 5,400 gallons \* Tonnessee Valley Authority 80/09/17 4pp
- BOO9230587 Forwards LER 80-084/01X-1 CALHOUN,J R Tennessee Valley Authority 80/09/18 ip
- --8009230394 LER 80-084/01X-1 on 800623 control room integrity breached Caused by removal of door C-49 & removal of tape used from door C-37 & C-50 in control room Door reinstalled Personnel reinstructed to insure doors are not removed KIRK.0 B Tennessee Valley Authority 80/09/18 2pp
- 8009230730 Forwards LER 80-077/03X-1 CALHOUR, J.P. Tennessee Valley Authority 80/09/19 ip
- --8009230734 LER 80-077/03X-1 on 800525 during Mode 4.RHR containment sump recirculation valve FCV-63-73 would not open due to failure of FCV-74-21 to actuate limit switch Maint request made to adjust limit switch KIRK, 0 B Tennessee Valley Authority 80/09/19 2pp
- 8009300451 Special Rept 80-5 on 800804, fire detector XS-13-29F found to have thermal detector in place of ionization detector Caused by installation of wrong type of detector Correct detector installed Sys declared operable on 800805 CALHOUN, J R Tennessee Valley Authority 80/09/25 2pp
- T Hearing transcripts on non-antitrust matters
- 8009110332 Forwards full-power OL, slide presentation entitled, "NRC Staff Review of Sequoyah for Full Power Operation -- Commission Briefing, 800821, " transcript of NRC 800821 public matting & draft Suppl 2 to SER, NUREO-0011 DENION, H R Office of Nuclear Reactor Regulation, Director 80/08/20 14pp
- --9009110341 Transcript of Commission 800821 public meeting in Harbington,DC to discuss facility full-power license Pp 1-89 \* Commission 80/08/21 91pp

- 8009290021 Transcript of 800916 public meeting in Washington, DC rediscussion & vote on Commission program to review OL applications, AM session Pp 1-62
  AHEARNE, J.F., GILINSKY, V. BRADFORD, P.A. Commission 80/09/16
- --8009270023 Forwards proposed modified license condition re hydrogen control measures
  AMEARNEL J. F. Commission 80/09/11 200
- --8009290026 Forwards proposed modified license condition re hydrogen control measures, as alternative to H Deaton 800903 proposal Hatter should be reviewed in early 1982 AUSTIU, J H Commission 80/09/09 2pp
- --B009250030 Forwards TVA summary sheets is mill certification data portaining to containment DENTON, H R Office of Nuclear Reactor Regulation, Director 80/09/15 20pp

- 8009120261 Submits info on degraded core training for operating employees, per NRC request Training completed for licensed reactor & senior reactor operators Presently conducting training for shift technical advisors CRCSS.J L Tennessee Valley Authority 80/09/05 1p
- DOCKET 50-328 SEQUOYAH NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8009ii0604 Requests review of R&D Associates rept. "Sequoyah Containment Analysis " Comments due by 80080i TEDESCO.R L Assistant Director for Licensing 80/07/29 2pp
- 8007080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl W/o NUREO EISENHUT.D G DIVISION of Licensing 80/08/01 119pp
- 80082(0618 Discusses preliminary assessment of use of igniters as method of hydrogen control at facilities Assessment based on present understanding of util-proposed igniter scheme Exclusive use of igniters may not be prudent BARI, R A Brookhaven National Laboratory 80/08/08 3pp
- 8007120578 Responds to request for comments re Sequoyah containment Forwards info re stringer & skin interaction Concludes NRC calculations overestimated beneficial effect of stringers HUBBARD, H W R & D Associates 80/09/18 Opp
- B009040434 Forwards mati re NRC review of ice condenser containment & hydrogen control measures for Sequoyah Nuclear Power Plant ACRS has scheduled meetings in Washington, DC on B00828, 0902 & 04 to discuss issue TEDESCO,R L. Assistant Director for Licensing 80/08/22 5pp
- --8009040443 "Hydrogen Control for Sequoyah Nuclear Plant, Units 1 & 2 "

  4 Office of Nuclear Reactor Regulation, Director 80/08/13
- --8007040450 Transcript of 800821 discussion of Sequoyah full power license in Washington DC Pp 48-89 \* Carmission 80/08/01 47pp
- 8009150527 Forwards requests for addition in response to util 800814 1tr re safety analysis of interim distributed ignition sys SCHWENCER, A Licensing Branch 2 60/08/28 3pp
- 8009030436 Forwards Procedure IP-18. 'Plant Release Rate Calculations' & graphs of containment activity as function of monitor reading.in fulfillment of 800811 commitment to provide correlation procedure
  MILLS.L. M Tennessee Valley Authority 80/08/29 3pp
- --8009030438 "Plant Release Rate Calculations " ZOBEL,N , KITTS,R J , DILL,J Tennessee Valley Authority 80/08/21 48pp
- 8009240960 Forwards preliminary staff assessment re use of halon as hydrogen combustion control measure Items addressed include selection & design of halon delivery systemical stability requirements reactivity & consequences of halon injection DENIGN.H R Office of Nuclear Reactor Regulation, Director 80/08/29 496

- --8009240564 Staff requtrements memo re Commission 800814 meeting CHILK:S J Office of the Secretary of the Commission 80/08/16 1p
- 8009110349 Forwards proposed full-power OL. Supple 2 % 3 to SER & "Discussion of Environ Effects of U Fuel Cycle " Tosts & safety review of proposal for distributed ignition sys espected to be completed by Jan 1981
  DENION R Offsice of Nuclear Reactor Regulation, Director 60/09/03 18pp
- ---B009110355 Draft Suppl 3 to SER
  \* Office of Nuclear Reactor Pegulation, Director NURE0-0011 63
  B0/09/30 79p
- --8009110358 "Discussion of Environ Effects of U Fuel Cycle" • Office of Nuclear Reactor Regulation, Director 80/09/30 9200
- --8009110360 Suppl 2 to SER + Dffice of Nuclear Reactor Regulation, Director NUREG-0011 S2 80/08/31 180pp Available at 0PD 75 50
- 8009080259 Forwards description of facility ice condenser insulation matter & containment wall insulation structural design & insulation flammability review results
  CROSS.J L. Tennessee Valley Authority 80/09/04 11pp
- 8009090370 Forwards additinfo on temp control for main steam valve rooms in response to NRC request Info revises util 800729 ltr
- CROSS.J L Tennessee Valley Authority BD/09/04 2pp
- 8009300294 Forward Chilk 800818 memo to Dircks re briefing on hydrogen control in Sequoyah containment DENTON H R Office of Nuclear Reactor Regulation, Director 80/09/10 1p
- B009190476 Forwards info re matl test repts for critical section of containment steel Mill test rept on critical section will be submitted by B00915
  MILLS.L M Tennessee Valley Authority B0/09/12 4pp
- 8009170297 Forwards mill test rept re critical section of containment steel in facility Matl suppls 800912 submittal which summarizes assessments of containment to withstand internal pressures Oversize frauings available in Central Files only MILLS, L. M. Tannessee Valley Authority 80/09/15 10pp
- 8009290333 Forwards Revision 3 of response to NUREO-0578,TMI-2 Lessons Learned Task Force status rept & short-term recommendations, Items 2 1 & Revision 3 changes procedures description for reducing & quantifying leakage from liquid sys MILLS.L M Fannessee Valley Authority 80/09/22 1p
- 8009300400 Forwards technical questions re implementation of interim policy on 10CFR50 & 51 MILLS.L M Fennessee Valley Authority 80/09/23 3pp
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 80090804(9 Forwards Suppl 2 to SER (NUREC-0011) SCHWENCER.A Licensing Branch 2 80/09/04 2p;
- --8009080423 SER for facility \* Office of Nuclear Reactor Regulation, Director NUREO-0011 S2 80/08/31 175pp Available at NTIS 49 50
- 8009260254 Forwards Suppl 3 to SER for facility SCHWENCER, A Licensing Branch 2 83/09/16 2pp
- --8009260258 SER for facility.Suppl 3
  \* Office of Nuclear Reactor Regulation. Director NURE9-0011 83
  80/09/30 82pp Available at NTJS \$4 00
- F Security, medical, emergency & fire protection plans
- 8009230267 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Bys installed for govt use during emergency O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/22 in
- 8009230333 Forwards physical security plan.Revision 6A Revision withheld (ref 100FR2 790)
  MILLS.L. M Tennessee Valley Authority 80/09/17 1p

- H General correspondence
- 8009ii0387 Commends Commissioners for denying facility full-power license until hydrogen buildup issue has been resolved beyond any doubt No compromise too expensive for prevention of another near-devastating event such as TMI CALDWELL,M A Affiliation Unknown 80/09/08 ip
- 8009120301 Responds to 800703 ltr requesting NRC comment on K Spallene 800619 ltr re-potential impact of dam failure of Pond Hill Reservoir, which util is considering for future const FES scheduled for completion in Dec 1980 DIRCKS:N J Office of the Executive Director for Operations 80/09/08 lp
- --8009120317 Requests NRC response to encl K Spallone 800619 ltr re potential impacts of Pond Hill Reservoir const & operation within 2 wks of receipt of request SCHNEIKER:R S Senate 80/07/03 2pp
- I Financial information
- 8009090543 Forwards Annual Financial Rept 1979 CROSS.J L. Tannessee Valley Authority 80/09/04 1p
- --8009090563 Annual Financial Rept 1979
  \* Tennessee Valley Authority 80/09/04 44pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8007030560 Forwards affidavit certifying that Amends 66 & 67 to FSAR were mailed to D Moore, JE Hagan & BA Osborne on 800826 MILLS, L M Tennessee Valley Authority 80/08/26 2pp
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8009190766 Discusses 243rd ACRS meeting on 800710-12 re Sequevah review & research program FY82 budget PLESSET.M S ACRS - Advisory Committee on Reactor Sefeguards 80/07/18 3pp
- 8009140083 Notice of ACRS Subcommittee on Structural Engineering 800902 meeting in Washington,DC to establish max internal pressure Sequevah containment can withstand HOYLE,J C Office of the Secretary of the Commission 80/08/13
- 8007050394 Transcript of ACRS Subcommittee on Structural Engineering 800902 hearing in Washington.DC re establishing max external pressure temp that Sequoyah containment structure can withstand

  \* ACRS Advisory Committee on Reactor Safeguards 80/09/02 18200
- BOOP180172 Forwards agendas for ACRS 800902 subcommittee meeting & 800904 full committee meeting re facilities TEDESCO.R t. Assistant Director for Licensing 80/09/02 4pp
- BOO915023B Responds to request for comments on questions contained in V 911insty 800B07 Itr re facility ice condenser containments Facility is capable of sustaining pressure of at least 45 psig w/o structural failure PLEBSET.H B ACRS Advisory Committee on Reactor Safeguards 80/09/08 3pp
- 8009300329 Forwards ACRS 800908 ltr to J Ahearne re ice condenser contailments BGHHEROER: A Licensing Branch 2 80/09/18 2pp
- P Operating license stage documents & correspondence
- 8009230549 Proposes alternate replacement schedule for turbocharger drive gear assemblies mfg by General Motors Util util limit turbocharger operation to less than 200-h MILLS,L H Tennessee Valley Authority 80/09/17 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 8009100063 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Escondary Side High Energy Line Rupture " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/07/24

- 8009020214 Forwards response to IE Bulletin 79-03A No SA-312 & A-312. Type 300 series fusion welded pipe used or planned for a in safety-related sys at greater than 85% design stress except Matts Bar Matl under investigation at Matts Dar NHLUS-L M Tennesser Valley Authority 80/08/05 2pp
- 8009090802 Responds to IE Bulletin 79-03A, "Longitudinal Weld Defects in ASKE 8A-312.Type 304 Stainless Steel Pipe" Use of matts still under investigation for sys supplied by NSSS vendor MILLS.L. if Tennessee Valley Authority 80/08/05 2pp
- 8009020303 Forwards IE Insp Repts 50-327/80-24,50-328/80-15, 50-390/80-20,50-391/80-14,50-438/80-13,50-439/80-13, 50-\$18/80-11,50-519/80-11,50-520/80-11,50-521/80-11, 50-553/80-11,80-554/80-10,50-564/80-10 & 50-567/80-10 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/06 200
- ---B009020312 Notice of violation from insp on 800707-11 \* Region 2. Atlanta: Office of the Director 80/0 80/80/08
- --8007020337 IE Insp Repts 50-327/80-24,50-328/80-15,50-390/80-20,50-371/80-14,50-438/80-13,50-439/80-13,50-518/80-11,50-519/80-11,50-521/80-11,50-553/80-11, 50-554/80-10,50-566/80-10 & 50-567/80-10 on 800707-11
  BRGWNLEE,V L , MODENOS,L Region 2, Atlanta, Office of the
  Director CONLON.T E Region 2, Atlanta, Reactor Construction &
  Engineering Support Branch 80/08/06 24pp
- 8009170161 Forwards IE Insp Rept 50-328/80-14 on 800708-11 No NORTH TOTAL NAME OF THE PROPERTY OF THE PROPER
- --8009170163 IE insp Rept 50-328/80-14 on 800708-11 No moncompliance noted Major areas inspected preservice & inservice insp BO/08/04 4pp Region 2, Atlanta, Office of the Director
- 8009030146 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Res Region 2, Atlanta, Office of the Director 80/08/15
- 8009660153 Forwards IE Circular 80-18, "100FR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/22

- BOO9120340 Forwards IE Info Notice BO-31, "Maloperation of Gould-Brown Bovert 480 Volt Type K-6005 % K-DON 6005 Circuit Breakers " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 60/08/27
- 8009240454 Forwards response to IE Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters No corrective action required due to results of evaluation that indicated impossibility of anomalous output MILLG.L M Tennessee Valley Authority 80/08/27 2pp
- 8009120479 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Relays identified are not used in facility Forty manhours expended for review MILLS.L M Tennesses Valley Authority 80/09/04 ip
- 8009260375 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required
  O'REILLY, J P Region 2. Atlanta, Office of the Director 80/09/10
- R Periodic operating reports & related correspondence
- 8009030397 Discharge monitoring rept for 800501-0601 EL-ASHRY, M T , STEINER, G R Tennessee Valley Authority 80/08/08 87-pp
- S Reportable occurrences. LERs & related correspondence
- B009040426 Becond interim deficiency rept re defective reactor vessel upper internals guide tube support pins TVA & Westinghouse replacing pins. Next rept will be submitted by B009fi HILLS, L M Tennassee Valley Authority 80/07/24 ip.

- 8009100537 Final deficiency rept re control rod drop events Operating procedures to be revised per Westinghouse instructions Procedural change will be made prior to greater than 90% power level ascension & will prevent power overshoot MILLS.L M Tennessee Valley Authority 80/08/05 2pp
- 8007100236 First interim deficiency rept re evaluation of sensing line connections to process piping Reanalysis of process piping will be completed by end of Sept Next rept will be submitted by 801017 MILLS, L M Tennessee Valley Authority 80/08/07 2pp
- 8007100284 Final interim deficiency rept re spray header attachment lug re-evaluation Lug attachments for containment spray b RMM sys headers not properly evaluated when supports reanalysed for steel containment vessel dynamic movements MILLS,L B Tennessee Valley Authority 80/08/07 2pp
- 8008190463 Final deficiency rept re hydrogen detection sys integrity Util has ordered mod kits & anticipates that installation will be completed by 801205 MILLS,L K Tennessee Valley Authority 80/08/13 2pp
- 8007100576 Final deficiency rept re hydrogen detection sys integrity Pump diaphragm rupture could result in sys integrity breach, affecting plant safety Sample pump field mod kit being provided by Comsip, Inc Installation anticipated by 801205 MILLS,L M Tennessee Valley Authority 80/08/13 2pp
- 8009100496 Revised final deficiency rept re incorrect valve weights in upper head injection sys Addi valves w/erroneous weights listed Piping sys load analyses were rerun using correct MILLS, L M Tennessee Valley Authority 80/09/02 3pp
- 8009100459 Final rept re deficiencies in installed pipe hangers & discharge piping in essential raw cooling water pumping station Caused by errors in design drawings & embedded pipes extending past location requirements
  MILLS.L M Tennessee Valley Authority 80/07/04 2pp
- 8009110320 Second interim deficiency rept re design criteria for secondary side pipe breaks Util completed analysis of pipe rupture interaction Protective devices will be added or piping will be rerouted Will submit next rept by 801028 MILLS.L M Tennessee Valley Authority 80/09/04 1p
- 8009160372 Second revised final deficiency rept re possible structural failure of spent fuel pool gate during seismic event Problem to be corrected by administratively requiring gate to remain in storage location during normal plant operations
  MILLB.L M Tennessee Valley Authority 80/09/08 3pp
- 8009160326 Third interim deficiency rept re defective reactor vessel upper internals guide tube support pins Westinghouse evaluation of guide tube pins being reviewed Replacement of pins underway Next rept will be submitted by 801215 MILLS-L M Tennessee Valley Authority 80/09/10 ip
- 8009160328 Third interim deficiency rept re unviron qualification of Class IC instruments in valve room Six steam generator pressure transmitters replaced Pressure suitches for flow to auxiiiary feed pump repaired MILLS.L M Tennessee Valley Authority 80/09/12 ip
- 8009290332 Third interim deficiency rept re environ qualification of Class IE equipment Status of NCRs encl Environmentally qualified switches were installed Soleroid valves will be replaced Next rept will be submitted by 801121 KILLS.L M. Tennessee Valley Authority 80/09/19 2pp
- B009290350 First interim deficiency rept re safety injection sys train B flow defect Flow tests continuing Similar defect reported at Watts Bar i Watts Bar flow test rescheduled for B01031 Next rept will be submitted by 801023 MILLS, L M Tennessee Valley Authority B0/09/22 2pp
- 8009300395 Fourth interim deficiency rept re upper head injection hydraulic isolation valve accomplator weighing sys Util will delay design changes proposed by Westinghouse until further testing completed MILLS, L M Tennessee Valley Authority 80/09/25 ip
- 8007300467 Final deficiency rept re seismic qualification of auxiliary feedwater pump recirculation line Caused by use of Improper design category Line to be reclassified & required seismic supports added prior to Unit 2 fuel load MILLS.L M Tennessee Valley Authority 80/09/25 2pp

# T Hearing transcripts on non-antitrust matters

- GOOGRGOOP1 Transcript of GOOP16 public meeting in Washington, DC rediscussion & vote on Commission program to review OL applications, AM session Pp 1-62
  AMEARNE, J.F., GILINSKY, V., BRADFORD, P.A., Commission 60/09/16
  65pp
- --8009290023 Forwards proposed modified license condition re hydrogen control measures
  AMEARME, J. F. Commission 80/09/11 2pp
- --8009290024 Forwards proposed modified license condition re hydrogen control measures, as altornative to H Denton 800903 proposal Hatter should be revigwed in early 1982 AUSFIRD J H Commission 80/09/09 2pp

### V Operator Examinations

B007120261 Submits info on degraded core training for operating employeas.por NRC request Training completed for licensed reactor & senior reactor operators Presently conducting training for shift technical advisors
CROSS.J L Tannessee Valley Authority B0/09/05 1p

#### DOCKET 50-329 MIDLAND PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 8007080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities ' Corments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT.D G Division of Licensing 80/08/01 119pp
- 8009020173 Provides satisfactory review of encl Army Corps of Engineers Itr rept to geotechnical engineering review Requests rept be submitted to util for response LEAR, G. Hydrologic & Geotechnical Engineering Branch 80/08/05 2pp
- 9009020179 Gobmits ltr rept re completion of Subtask 1 re geotechnical engineering review Identifies unresolved 1stues & suggests course of action Guppl encl MCCALLIGEER, P. Army, Dept of, Office of Surgeon General 80/07/07 17pp
- 8007020165 Ack receipt of 800724 ltr from JH Cook transmitting rept on reactor pressure vessel support mod FIORCLLIO Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/08/11 ip
- 8009100005 Notification to 800822 meeting w/util in Bethesda, MD to clarify % suppl info to const completion schedule HOOD, D Operating Reactors Branch 3 80/08/21 Spp
- 8009120199 Requests add1 info re permanent dewatering sys proposed for site per Hydrologic & Geotechnical Engineering Branch review TEDESCO.R L Assistant Director for Licensing 80/08/27 lipp
- 8009090397 Forwards response to NRC 800421 info request to Category E masonry ualls Oversize drawings available in Central Files only CGGK.J W Consumers Power Co 80/09/03 lipp
- BOO7090500 Forwards description of nuclear operations & facility mgt organizational changes Revisions will be submitted to incorporate changes to OA program policies
  HOFFMAN.O P Consumers Power Co BO/09/05 4pp
- ---80070705|| "Nuclear Svcs Dept," & "OA Nuclear Operations " \* Consumers Power Co 80/09/05 2pp
- 8007:70257 Amend 8: to application for CPs & DLs.including discussion of applicants position on need for add1 borings, sottlement update & Revision 9 to response to NRC requests re plant fill.originally referenced by Amend 72 COOK, J W Consumers Power Co 80/09/82 230pp
  - 0727036B Forwards B&W Rept 86-1120838-00, "Evaluation of Instrumentation to Detect Inadequate Core Cooling Prepared For 17/ Dwners Group " 'OSK,J W Consumers Power Co 80/07/12 ip

- --8009290373 "Evaluation of Instrumentation to Detect Inadequate Core Cooling Prepared For 177 Owners Group " FROTHIN J Babcock Wilcox Co 86-1120838-00 80/08/15 22pp
- 8009220238 Forwards response to NRC 781011 & 1222 ltrs requesting addl info for review of application for DLs CODK, J W Consumers Power Ca 80/09/15 ip
- --8009220242 "Rept of Archaeological Mitigation & Avoidance on CPC Right-of-Kay in Saginaw & Midland Counties, MI " OZKER.D., TAGGART.D.H. Michigan, Univ. of 80/02/18 200pp
- --8009220247 "Terrestrial Ecological Survey for Midland Nuclear Plant Tittabauassee Substation to Gary Road Substation 345 kV Transmission Right-of-Way." final rept # Aptock Engineering Services 79/11/30 200pp
- 8009230550 Forwards Amend 82 to CP & OL application & Revision 11 to environ rept COOK.J W Consumers Power Co 80/09/15 ip
- --8009230562 Revision 11 to environ rept \* Consumers Power Co 80/09/30 100pp
- 8009230707 Submits corrections to 800711 ltr re cracked steam generator manuay studs at Oconee 3
  TAYLOR, J.H. Babcock & Wilcox Co. 80/09/15 lp
- 8009300332 Summary of 800825 meeting w/util in Bethesda,MD re potential timing & methods for resuming formal docket review of DL application HODD: D S Licensing Branch 3 80/07/16 App
- 8009300309 Requests addl info re reactor pressure vessel support mods FEDESCO.R L Assistant Director for Licensing 80/09/19 3pp
- 8009300507 Forwards affidavit acknowledging distribution of Amend 82 to CP & CL application.Revision 11 to environ rept COOK.J W Consumers Power Co 80/09/22 4pp
- C Utility Environmental Report (ER), amends & correspondence
- 8007230550 Forwards Amend 82 to CP & QL application & Revision il to environ rept CCOK.J W Consumers Power Co 80/09/15 ip
- ---8009230562 Revision 11 to environ rept \* Cansumers Power Co 80/09/30 100pp
- 8009300507 Forwards affidavit acknowledging distribution of Amend 82 to CP & OL application. Revision 11 to environ rept CDGK. J W Consumers Power Co 80/09/22 App
- F Security, medical, emergency & fire protection plans
- 8008080⊃97 Forwards "Evacuation Clear—Time Estimates for Areas Near Ridland.MI Nuclear Power Plant." in response to NRC 791226 & 800702 ltrs CGDW.J W Consumers Power Co 80/07/31 2pp
- --8008080302 "Evacuation Clear-Time Estimates for Areas Near Midland.Ml Nuclear Power Plant" Oversize drawings encl \* HMM Associates.Inc 80-059 80/07/31 112pp
- 8009100924 Transmits emergency planning info to be made available to public at LPDR in Midland.MI W/o encl SQUOER.J L Public Document Branch 80/08/27 ip
- G Adjudicatory correspondence
- 8009050354 Advises of withdrawal as atty for WH Marshall Requests that firm name be removed from roster % that all parties be notified MERRITT.G J Thompson, Nielson, KlaverKamp & James 80/08/13 2pp
- 8009050423 Contention alleging that Class 9 accident will cause massive flow of radioactive matls into Saginaw Bay river which-provides drinking water to area Urges full disclosure per NEPA MARSHALL. W H Mapleton Intervenors 80/08/27 2pp

- 8009020429 Response in support of B Stamiris amended petition to intrivene re Contention 4 on OA Urges amend of Contentions 1.2.3 & 6 Contentions 5 re differential soil settlement must not be accepted w/o amend W/Certificate of Svc PATON.W D Hearing Branch 4 80/08/29 11pp
- 8007020440 Response in support of SK Warren 800814 amended petition to intervene re Contentions 1 & 3 on fill soil composition & dswatering procedures Contentions 2 & 4 re seepage & preloading should be amended Certificate of Svc encl JOXES.B W Hearing Branch 2 80/08/29 9pp
- 8009030718 Response to SK Warren 800814 suppl & B Stamiris amend to petitions to intervene Opposes Warren Contentions 2 & Stamiris Contentions 1.2.3 & 5 Urges rephrasing of Stamiris Contention 4 re GA Certificate of Svc encl FARNELL.A S Consumers Pawer Co FARNELL.A S Isham, Lincoln & Seale 80/08/30 11pp
- BOOP220001 Suppl to SK Warren patition to intervene & amended suppl to B Stammis petition to intervene Alleges inadequacy of permanent dewatering procedures & CPC financial pressures adversely affecting resolution of soil settlement issues WARREN, S X, STAMIRIS, B Affiliation Unknown 80/09/09 8pp
- --8009260002 Statement asserting NRC & CPC positions of SK Warren & B Stamaris revised contentions No objections stated by NRC Partial objections stated by CPC of circulating water lines & other irrelevant issues Certificate of Svc encl MILLER.M I Consumers Power Co MILLER.M I Isham, Lincoln & M I Consumers Power Co 80/09/18 4pg
- 8009(80397 Forwards util answer to notice of hearing W/o encl FARNELL, A S Isham, Lincoln & Beale 80/09/11 ip
- 8009190420 Notice of appearance in proceeding Certificate of Svc sncl BRUNNER, J E Consumers Power Co 80/09/11 3pp
- 8009250034 Notice of reconstitution of ASLB due to IW Smith schedule conflict C Beckhoefer appointed chairman LAZO.R M Atomic Safety and Licensing Board Panel 80/09/19 ip
- S009300023 Notice of 801007-09 depositions of D Hood, L Heller & J Kame of NRC & 801013.15 & 16 depositions of JW Simpson, W Lawhead & R Erickson of Corps of Engineers re Stamiris & Warren contentions Certificate of Svc encl
  FARMELL, A S Consumers Power Co FARNELL, A S Isham, Lincoin & Beale 80/09722 7pp
- £009250004 Advises that, in response to 800920 mailgram, future transcripts will be mailed to 8 Gadlar PATON, R D Hearing Branch 4 80/09/23 ip
- 8009290039 Responds to GA Linenberger 800910 inquiry re NRC conclusion on Page 3 of 790906 order modifying CPs Safety issues in question are associated w/remedial action correcting soil # ficienties Hearing Branch 4 80/09/24 3pm PATON, U. D.
- H General correspondence
- 8007110280 Responds to 800728 Itr requesting info re safety of Midland & Fermi plants All nuclear plants subj to enhanced safety requirements resulting from TMI Lessons Learned Task Force recommendations Supporting documentation encl DIRCKS,N J Office of the Executive Director for Operations DIRCKS, W J Of 80/08/26 24pp
- --8007110288 Requests consideration of encl MC Haight ltr re safety of Hidland & Fermi plants BRDOMFIELD,WS House of Rep , Foreign Affairs 80/07/28 2pp
- BOOTO90040 Responds to 800507 itr to President Cartor re safety, cost & need for facilities NRC issued order on 791206 prohibiting soil const activities pending CP amend Study shows two-unit plant will provide electric power at lowest cost EISENHUT, D & Division of Licensing 80/08/27 10pp.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- SOOTITO218 Forwards portion of Amend 81 to FSAR. "Discussion of Applicant Position on Need for Addl Borings for Kidland Plant Units 1 & 2 " Discussion attempts to document presentations & new mat! introduced at 800827 meeting w/NRC GOOK, J N Consumers Power Co 80/09/16 Spp

- --8009190221 Portion of Amend 81 to FSAR entitled. "Discussion of Applicant Position on Need for Addl Borings for Midland Plant Units 1 & 2 "

   Consumers Power Co 80/09/14 41pp
- Q Inspection reports, IE Bulletins & correspondence
- 8009150194 Forwards IE Insp Repts 50-329/80-20 & 50-330/80-21 on ROY100194 Forwards to Into Repts 30-327780-20 & 30-33780 & 18880 & 880708-10 & notice of violation FIGRELLI.9 Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/07/18 2pp
- --8009150197 Notice of violation from insp on 800708-10 \* Region 3, Chicago, Office of the Director 80/0 80/07/18
- --9009150203 IE Insp Ropts 50-329/80-20 & 50-330/80-21 on 800708-10 Noncompliance noted failure to specify applicable code in purchase order

  purchase order

  BANIELSON, D H Region 3. Chicago, Reactor Construction to Engineering Support Branch LEE.E H K Region 3. Chicago, Office of the Director 80/07/18 App
- 8009180231 Forwards IE Insp Repts 50-329/80-22 & 50-330/80-23 on 800701-31 No noncompliance noted FIORELLI,9 Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/08/07 2pp
- --8009180240 IE insp Repts 50-329/80-22 & 50-330/80-23 on 800/01 31 No noncompliance noted Major areas inspected detensioning of reactor hold down bolts, const activities of Zack Co & reactor note nown costs.const Activities of Zack Co & caseload forecasting KNDP.R C . COCK.R J Region 3. Chicago, Office of the Director 80/08/09 5pp
- 8009230110 Responds to IF Bulletin 80-00, "Exam of Containment Liner Penetration Welds " Circumstances addressed not considered problematical because NDE performed required by applicable COOK, J W Consumers Power Co 80/08/14 lipp
- 8007030226 Forwards Revision 1 to 1E Builetin 80-17. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER, J Q Region 3. Chicago, Office of the Director 80/08/15
- 8009260410 Forward\* IE Insp Repts 50-329/80-13 & 50-330/80-14 on 800227-29,0305-06,0312-13 & 20,0418 & 0502 & notice of WEPPLER: J O Region 3, Chicago, Office of the Director (10/08/1)
- --8009260413 Notice of violation from insp on 800227-29,0305-06,0312-13 5 20.0418 5 0502 \* Region 3, Chicago, Office of the Director (10/08/14) 3pp
- --8009260415 IE Insp Repts 50-327/80-13 & 50-330/80-14 on 800227-29. 007260415 IE Insp Repts 30-337/80-13 & 30-330/80-14 on 800227-20, 0305-06, 0312-13 & 20,0418 & 0302 Noncompliance noted inadequate procurement document control special processes control & purchase math-equipment & svc control FFOSTER, J E. ERBLC M. NORELLUS, C E. Region 3, Chicago, Office of the Director 80/08/13 23pp
- 8007170418 Forwards IE Circular 80-10, "100FR50 97 Safety Evaluations for Changes to Radwaste Treatment Bys " No written response required

  KEPPLER. J C Region 3. Chicago, Office of the Director (10/08/22
- B00916024B Forwards IE Insp Repts 50-329/80-17 & 80-330/80-18 on B00617-18 & 0722 & 0812-13 No noncompliance noted FIORELLIO Region 3. Chicago. Reactor Construction & Engineering Bupport Branch B0/08/27 2pp
- --B009160249 IE Insp Repts 50-329/80-17 & 50-330/80-18 on B00617-18,0/22 & 0B12-13 No noncompliance noted Major areas inspected preservice inspected preservice inspectors work activities, nondestructive examination, personnel certification & data WARD, K D Region 3, Chicago, Office of the Director DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Dranch 80/08/25, App
- 8009230071 Forwards IE Info Notice 80-31, "Malaperation of Gould-Brown Boveri 480 Volt Type K-6005 & K-DON 6008 Circuit Breakers " No written response required KEPPLER, J. Q. Region 3, Chicago, Office of the Director 80/08/20

- 8009170227 Forwards NRC positions & requests for add1 info to IE Bulletins 79-21 & 80-06 re temp effects on level measurements & engineered safety feature reset controls Info needed for NRC review of QL applications TEDESCO,R L Assistant Director for Licensing 80/09/04 12pp
- 8009240129 Forwards IE Circular 80-21. "Regulation of Refueling Crews " Na written response required KEPPLER, J & Region 3, Chicago, Office of the Director 80/09/10
- 8009290472 Ack receipt of 800825 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/80-20 & 50-330/80-21 FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/10 ip
- --8009290475 Responds to NRC 800710 ltr re violations noted in IE Insp Repts 50-329/80-20 & 50-330/80-21 Corrrective actions audit of weld filler malls procurement initiated & fabrication conditions qualified CODK, J N Consumers Power Co 80/08/25 App
- R Periodic operating reports & related correspondence
- 8009040295 Forwards Becktel nonconformance repts & log sheets.Becktel NOVOLUMB FORWARDS SECRET NONCONFORMANCE PEPES & 100 SHE quality action requests B&W nonconformity repts B&W inservice insp nonconformance repts util nonconformance, audit finding & corrective action repts COOK.J W Consumers Power Co 80/09/21 300pp
- S Reportable occurrences, LERs & related correspondence
- 800B190605 Interim deficiency rept re inconsistent cross-referencing between B&W & Bechtel numbering sys affecting instrument sys Instrument index & electrical schemes under revision for application of appropriate cross-refs CDOK.J W Consumers Power Co 807/08/13 3pp
- 8009030654 Ack receipt of 800731 interim deficiency rept re safe shutdown boration capability FIBRELLI, G Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/08/14 ip
- 8007030657 Ack receipt of 800801 interim deficiency rept re reactor vessel broken anchor bolt FIDRELLI, O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/08/14 ip
- 8009100&64 Ack receipt of 800813 interim rept re NSSS component norable of the Articles of Boulli interim rept re NESS component identification identification.
  FIORELLI, C. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/28 ip
- 8009230275 Interim rept re containment internal structures coating deficiency Substantial progress made in isolating factors contributing to delamination condition k in formulating corrective action progrem Next rept by 801103 COOK.J W Consumers Power Co 80/09/09 ip.
- 800925026B Interim Deficiency Rept 9 re component quelification test documentation Nonconformance Repts 1789,1795,1796,2659 & 2664 have been dispositioned & quality test review for matl requisition has been closed Next rept issued by 801205 CBGK, J W Consumers Pawer Co ED/09/19 64pp
- 8009250284 Deficiency rept re HELBA restraint design Steady state rather than peak thrust forces were used in design of G-listed pipe whip restraints investigation & identification of root cause recommended Another rept due by 801201 COOK. J. N Consumers Power Co 80/09/19 App
- 8009290360 Deficiency rept re high energy line break analysis of pipe whip restraint designs Caused by misinterpretation of BN-TDP-2 Affected restraints re-evaluated Next rept by COOK, J W Consumers Power Co 80/09/19, App.
- T Hearing transcripts on non-antitrust matters
- 8009160499 Transcript of 800910 prehearing conference in Midland.MI Pp 234-408

  A Atomic Safety and Licensing Board Panel ISSUANCES OL 80/09/10

- DOCKET 50-330 MIDLAND PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8009080780 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria JS Proposed implementation schedule for macring civil NUREG-04046 enci N/O NUREG SENHUT,D 0 Division of Licensing 80/08/01 119pp EISENHUT, D G
- B009020173 Provides satisfactory review of encl Army Corps of Engineers ltr rept re geotechnical engineering review Requests rept be submitted to util for response LEAR.0 Hydrologic & Geotechnical Engineering Branch B0/08/05
- 8009020179 Submits ltr rept re completion of Subtask 1 re geotechnical engineering review Identifies unresolved issues & suggests course of action Suppl enc!
  MCGALLISTER.P Army, Dept of, Office of Surgeon General 80/07/07
- 8007020165 Ack receipt of 800724 ltr from JW Cook transmitting rept on reactor pressure vessel support mod FIGREULI.0 Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/08/11 ip
- 8009100005 Notification fo 800822 meeting w/util in Bethesda.MD to clarify & suppl info re const completion schedule HDDD,D Operating Reactors Branch 3 80/08/21 5pp
- 8009120199 Requests addl info re permanent dewatering sys proposed for site per Hydrologic & Geotechnical Engineering Branch TEDESCO.R L Assistant Director for Licensing 80/08/27 11pp
- B007090397 Forwards response to NRC 800421 info request re Category I masonry walls Oversize drawings available in Central Files only COOK,J W Consumers Pawer Co 80/09/03 11pp
- 8009090500 Forwards description of nuclear operations & facility mgt organizational changes Revisions will be submitted to incorporate changes to QA program policies HOFFKAN.O F Consumers Power Co 80/09/05 App
- --8007070511 "Nuclear Svcs Dept," & "GA Nuclear Operations "
  \* Consumers Power Co 80/09/05 2pp
- 8009170259 Amend 81 to application for CPs & OLs.including discussion of applicants position on need for add1 borings, settlement update & Revision 9 to response to NRC requests re plant fill.originally referenced by Amend 72 COOK.J W Consumers Power Co 80/09/12 230pp
- B00727036B Forwards B&W Rept B6-1120B3B-00, "Evaluation of Instrumentation to Detect Inadequate Core Gooling Prepared For 177 Guners Oroup " COOKJ W Consumers Power Co 80/07/12 1p
- ---8009290373 "Evaluation of Instrumentation to Detact Inadequate Core Cooling Prepared For 177 Owners Group " FROTH.D J Babcock & Wilcox Co 86-1120838-00 80/08/15 22pp
- 8009220238 Forwards response to NRC 781011 & 1222 ltrs requesting add1 into for review of application for OLS CODK.J W Consumers Pawer Co 80/09/15 ip
- --8009220242 "Rept of Archaeological Mitigation & Avoidance on CFC Right-of-Way in Saginaw & Midland Counties,MI " OZKER,D , TAGGART,D W Michigan, Univ of 80/02/18 200pp.
- --8007220247 "Terrestrial Ecological Survey for Midland Nuclear Plant Tittabawassee Substation to Gary Road Substation 345 kV Transmission Right-of-Way." final rept \* Aptach Engineering Services 79/ii/30 200pp
- 8009230550 Forwards Amend 82 to CP & OL application & Revision 11 to environ rept GBOK, J W Consumers Power Co 80/09/15 ip
- --8009230559 Amend 82 to application for OLs & CPs + Consumers Power Co 80/09/15 ip
- 8009230707 Submits corrections to 800711 ltr re cracked steam generator manuay studs at Occure 3 TAYLOR, J H Babcock & Wilcox Co 80/09/15 1p

- googgogge Summary of 800825 meeting w/util in Bethesda,MD re potential timing & methods for resuming formal docket review of OL application MOOD,D S Licensing Branch 3 80/09/16 App
- 8009300307 Requests addl info re reactor pressure vessel support mods TEDESCO.R L. Assistant Director for Licensing 80/09/17 3pp
- 8009300507 Forwards affidavit acknowledging distribution of Amend 82 to CP & OL application, Revision 11 to environ rept COOK. J H Consumers Power Co 80/09/22 4pp
- C Utility Environmental Report (ER), amends & correspondence
- B009230550 Forwards Amend 82 to CP & CL application & Revision 11 to environ rept CDGK, J H Consumers Power Co 80/09/15 1p
- F Security, medical, emergency & fire protection plans
- BOOROB0297 Forwards "Evacuation Clear-Time Estimates for Areas Near Kidland, MI Nuclear Power Plant." in response to NRC 791226 & BOO702 ltrs CODK.J N Consumers Power Co 80/07/31 2pp
- --8008080302 "Evacuation Clear-Time Estimates for Areas Near Midland, MI Nuclear Power Plant " Oversize drawings encl # HMM Associates, Inc 80-059 80/07/31 112pp
- 6009100924 Transmits emergency planning info to be made available to public at LPDR in Midland,MI W/o encl SOUDER,J L Public Document Branch 80/08/27 ip
- 9. Adjudicatory correspondence
- BOO7050354 Advises of withdrawal as atty for NH Marshall Requests that firm name be removed from roster & that all parties be notified
  MERRITERO J Thompson, Nielson, KlaverKamp & James BO/08/13 2pp
- 8007050423 Contention alleging that Class 9 accident will cause massive flow of radioactive matls into Saginaw Bay river which provides drinking water to area Urges full disclosure per NEPA MARSHALL, U H Mapleton Intervenors 80/08/27 2pp
- 6009020429 Response in support of B Stamiria amended petition to intervene re Contention 4 on GA Urges amend of Contentions 1.2.3 & 6 Contentions 5 re differential soil settlement aust not be accepted w/o amend W/Certificate of Svc FATON.W D Rearing Branch 4 60/08/29 11pp.
- BO09020440 Response in support of SK Marren B00814 amended patition to intervane re Contentions 1 & 3 on fill soil composition & dawatering procedures Contentions 2 & 4 re seepage & preloading should be amended Certificate of Svc encl.

  JUNES B W Hearing Branch 2 80/08/27 7pp
- SOC9030718 Response to SK Warren 800814 suppl & 8 Stamiris amend to petitions to intervene Opposes Warren Contentions 2 & Stamiris Contentions 1,2,3 & 5 Urges rephrasing of Stamiris Contention 4 re QA Certificate of Svc encl FARNELL.A S Consumers Power Co FARNELL.A S Isham, Lincoln & Seale 80/08/30 11pp
- BOO9260001 Suppl to SK Warren petition to intervene & amended suppl to S Stamiris petition to intervens Alleges inadequacy of permanent dewatering procedures & CPC financial pressures adversely affecting resolution of soll settlement issues MARREN.S K . STAMIRIS.B Affiliation Unknown 80/09/09 Bpp
- --8009260002 Statement asserting NRC & CPC positions re SK Warren & B Stamaris revised contentions No objections stated by NRC Partial objections stated by CPC re circulating water lines & other irrelevant issues Certificate of Svc encl MILLER, M I. Consumers Power Co. MILLER, M I. Isham. Lincoln & Beals 60/09/18 4pp
- 8009160397 Forwards util answer to notice of hearing W/o encl FARNELL, A S Isham, Lincoln & Seale 80/09/11 ip
- BOC9190420 Notice of appearance in proceeding Certificate of Syc encl BRUNNER, J E Consumers Power Co 80/09/11 3pp

- 8009250034 Notice of reconstitution of ASLB due to IW 5mith schedule conflict C Beckhoefer appointed chairman LAZO.R M Atomic Safety and Licensing Board Panel 80/09/19 ip
- BO09300023 Notice of B01007-09 depositions of D Hood.L Heller & J Kane of NRC & B01013.15 & 16 depositions of JR Simpson.H Lawkead & R Erickson of Corps of Engineers.re Stamiris & Warren contentions Certificate of Svc encl FARNELL.A S Consumers Power Co FARNELL.A S Isham, Lincoln & Beale B0/09/22 9pp
- 8009250004 Advises that, in response to 800920 mailgram, future transcripts will be mailed to 5 Oadler PATON.W D Hearing Branch 4 80/09/23 ip
- 8009290039 Responds to GA Linenberger 800910 inquiry re NRC conclusion on Page 3 of 790906 order modifying CPs Safety issues in question are associated whomedial action correcting soil deficiencies PATON.W P Hearing Branch 4 80/09/24 3pp
- H General correspondence
- 8009110280 Responds to 800728 ltr requesting info re safety of Midland & Fermi plants All nuclear plants subj to enhanced safety requirements resulting from TMI Lessons Learned Task Force recommendations Supporting documentation and DIRCKS.W J Office of the Executive Director for Operations 800/08/26 2499
- --B00911028B Requests consideration of encl MC Haight ltr re safety of Midland & Fermi plants BROOMFIELD.W S House of Rep , Foreign Affairs 80/07/28 2pp
- GOOPO90040 Responds to BOO507 ltr to President Carter re safety, cost & need for facilities NRC issued order on 791206 prohibiting soil const activities pending CP amend Study shows two-unit plant will provide electric power at lowest cost EISEKHUT, D & Division of Licensing 80/08/27 (Opp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8009190218 Forwards portion of Amend 81 to FSAR, "Discussion of Applicant Position on Need for Addl Borings for Midland Plant Units [ & 2 " Discussion attempts to document presentations & new mat] introduced at 800929 meeting w/NRC COOK, J W Consumers Power Co 80/09/16 3pp
- --8009170221 Portion of Amend 81 to FBAR entitled, "Discussion of Applicant Position on Need for Addi Borings for Midland Plant Units 1 3 2 " \* Consumers Power Co 80/09/14 41pp
- G Inspection reports, IC Bulleting & correspondence
- 8009190194 Forwards 1E Insp Repts 50-329/80-20 % 50-330/80-21 on 800708-10 & notice of violation FIGRELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/07/18 2pp
- --8009150197 Notice of violation from imag on 800708-10
  \* Region 3, Chicago, Office of the Director 80/07/18 ip
- --8009180203 IE Insp Repts 50-329/80-20 A 50-330/80-21 on 800708-10
  Noncompliance noted failure to specify applicable code in
  purchase order
  DANIELSON. D H Region 3. Chicago, Reactor Construction &
  Engineering Support Branch LEG.E W K Region 3. Chicago. Office
  of the Director 80/07/18 App
- B009180231 Forwards IE Insp Repts 50-329/80-22 & 50-330/80-23 on B00701-31 No noncompliance noted FIURELLI,O Region 3, Chicago, Reactor Construction & Engineering Support Branch B0/09/07 2pp
- --8007180240 IE insp Repts 50-327/80-22 % 50-330/80-23 on 800701-31
  No noncompliance noted Major areas inspected detensioning of reactor hold down bolts.const activities of Zack Co & caseload forecasting KNOP.R C . COOK.R J Region G. Chicago, Office of the Director 80/08/05 Spp
- 8009230110 Responds to IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Circumstances addressed not considered problematical because NDE performed required by applicable codes CODA, J W Consumers Power Co 80/08/14 11pp

- 8009030226 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER.J G Region 3. Chicago, Office or the Director 80/08. Region 3. Chicago, Office of the Director 80/08/15
- 8009260410 Forwards IE Insp Repts 50-029780-13 & 50-030780-14 on 800227-29,0305-04,0312-13 & 20,0418 & 0502 & notice of Violation
  KEPPLER, J G Region 3. Chicago, Office of the Director 80/08/18
- .--8009260413 Notice of violation from insp on 800227-29,0305-06.0312-13 & 20.0418 & 0502 + Region 3, Chicago. Office of the Director 80/08/13 3pp
- --8009260415 IE Insp Repts 50-329/80-13 > 50-330/80-14 on 800227-29, 0305-06, 0312-13 & 20.0418 & 0502 Noncompliance noted inadequate procurement document control special processes control & purchase math.equipment % svc control
  FOSTER.J E . ERR.C H . NORELIUS.C E Region 3. Chicago. Office of
  the Director 80/06/13 23pp
- 800917041B Forwards IE Circular 80-18, "10CFR50 57 Safety Evaluations for Changes to Radwasto Treatment Sys " No written response KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/22
- 8009160248 Forwards IE lnsp Repts 50-329/80-17 & 50-330/80-18 on 800617-18 & 0722 & 0812-13 No noncompliance noted FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/27 2pp
- -8009160249 IE Insp Repts 50-329/80-17 t 50-330/80-18 on 800617-18,0722 DUVIOURY IE INSPORTS 30-32-70-17 A 30-32-70-18 On DOUBLE SO ORDER 19 No noncompliance noted Major areas inspected preservice insports of the statistics, nondestructive examination, personnel certification & data HARD K D Region G. Chicago. Dffice of the Director DANIELSON, D H Region G. Chicago. Reactor Construction & Engineering Support Branch 80/08/25 6pp
- 8009230071 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Bover: 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required KEPPLER.J G Region 3. Chicago, Orfice of the Director 80/08/28
- 8009170227 Forwards NRC positions & requests for add1 info to IE Bulletins 79-21 & 80-06 re temp effects on level measurements & engineered safety feature reset controls Info needed for NRC review of OL applications TEDESCO,R L Assistant Director for Licensing 80/09/04 12pp
- 8009240129 Forwards IE Circular 80-21, "Regulation of Refueling Crews " No written response required
  KEFPLER, J. G. Region 3. Chicago, Office of the Director 80/09/10
- 8009290472 Ack receipt of 800825 ltr informing NRC of steps taken to correct violations noted in IE lasp Repts 50-329/80-20 & 50-330/80-21 FIGRELI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/10 ip
- --8009290475 Responds to NRC 800710 ltr re violations noted in IE Insp Repts 50-329780-20 \$ 50-330780-21 Corrective actions audit of weld filler matls procurement initiated & fabrication conditions qualified CODK.J W Consumers Power Co 80708725 App
- R Periodic operating reports & related correspondence
- 8007040295 Forwards Bechtel nonconformance repts & log sheets.Bechtel quality action requests,85W nonconformity repts.B5W inservice insp nonconformance repts.util nonconformance, audit finding & corrective action repts CO
- S Reportable occurrences. LERs & related correspondence
- 8009030654 Ack receipt of 800731 interim deficiency rept re safe shutdown boration capability
  FIORELLI.O Region 3, Chicago, Reactor Construction & Engineering
  Support Branch 80/08/14 ip

- 8009030657 Ack receipt of 800801 interim deficiency rept re reactor vessel broken anchor bolt FIORELLI, G. Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/08/14 ip
- 8009100664 Ack receipt of 800813 interim rept re NSSS component identification FIORELLI, G. Region 3. Chicago, Reactor Construction & Engineering 80/08/28
- 8009230275 Interim rept re containment internal structures coating deficiency Substantial progress made in isolating factors contributing to delamination condition & in formulating corrective action program Next rept by 801103 COOK, J W Consumers Power Co 80/09/09 ip
- 8009250268 Interim Deficiency Rept 9 re companent qualification test documentation Nonconformance Repts 1789,1795,1796,2659 & 2664 have been dispositioned & quality test review for matl requisition has been closed Next rept issued by 801205 CDGk, J (\* Consumers Power Co 80/09/19 44pp
- 8009250284 Deficiency rept re HELBA restraint design Steady state rather than peak thrust forces were used in design of G-listed pipe whip restraints Investigation & identification of root cause recommended Another rept due by 801201 COOK, J N Consumers Power Co 80/09/19 App
- 8009270360 Deficiency rept re high energy line break analysis of pipe whip restraint designs Caused by misinterpretation of BN-TQR-2 Affected restraints re-evaluated Next rept by 801121 COCK, J W Consumers Power Co 80/09/19 6pp
- T Hearing transcripts on non-antitrust matters
- 8009160499 Transcript of 800910 prehearing conference in Midland, MI \* Atomic Bafety and Licensing Board Panel ISSUANCES DL B0/09/10
- DOCKET 50-331 DUANE ARNOLD ENERGY CENTER F Security, medical, emergency & fire protection plans
- 8007230302 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency KEPPLER.J & Region 3. Chicago. Office of the Director 80/08/22
- 8009180389 Forwards revised safeguards contingency plan to modified amended security plan Revision withheld (ref 10CFR2 790) ROOT.L D Iowa Electric Light & Power Co 80/09/15 ip
- G Adjudicatory correspondence
- 8009220109 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 IPPOLITO T A Operating Reactors Branch 2 80/08/29 Rpp.
- --8009220112 Order for mod of License DPR-49 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101 EISENHUT, D G Division of Licensing 80/08/29 App
- P Operating license stage documents & correspondence
- 8009110554 Suppls NRC 800707 request for proposed Tech Specs changes for scram discharge vol vent & drain valves, & reactor protection sys & control rod block limit switch surveillance requirements Class III iconse fee to be submitted w/change EISENHUT, D 0 Division of Licensing. 80/07/22 22pp
- 8009020297 Submits interim criteria for shift staffing to all QL & CP licenseas & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT. D G Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities "Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl W/o NUREG.
  EISENHUT, DG Division of Licensing 80/08/01 119pp

- 8009230052 Informs that exemption from fee re licensing action associated u/TMI-2 Lessons Learned is unjustified Previous determination should be disnegarded Requested submittal should include propased class of amend EISENHUT, D O Division of Licensing 80/08/07 60pp
- 8069020144 Confirms that two specific Event 5 valve configurations do not exist at facility NRC activities re valve configurations finalized for facility Franklin Research Ctr-Primary Coolant Sys Pressure Isolation Valves." encl IPPOLITO, T.A. Operating Reactors Branch 2 80/08/08 3pp
- --8009020148 "Primary Coolant Sys Pressure Isolation Valves," technica) evaluation rept NOELL.? N . STILWELL.T C Franklin Institute/Franklin Research Canter 80/07/21 Spp
- 8009180204 Forwards NUREO-0461, "Mark I Containment Long-Term Program SER Resolution of Generic Technical Activity A-7 " Rept describes NRC requirements re generic suppression pool hydrodynamic load W/o encl IFPOLITO.T A Operating Reactors Branch 2 80/08/20 2pp
- 8009090777 Advises that util response to NRC 791109 ltr re portions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture is acceptable No further action necessary 1890LITO.TA Operating Reactors Branch 2 80/08/22 2pp
- BOO9020289 Forwards facility Mark I project schedule re long-term program plant mods Bchedule offered as add1 clarification & update of initial schedule previously submitted Util plans to install ail major torus-related mods prior to Dec 1980 ROOT.L D I awa Electric Light & Power Co 80/08/25 2pp
- BOG9190001 Advises that commitments to NRC 791023 "Interim Position on Containment Purging & Venting Pending Resolution of Isolation Valve Operability," are acceptable & remain in effect pending completion of NRC long-term review IPPOLITO, T A Operating Reactors Branch 2 80/09/03 2pp
- BOO9170333 Advises that comments on NUREG-0696, "Functional Criteria for Emergency Response Facilities," will be incorporated into AIF comments Applauds NRC shift of philosophy re location of emergency operations facility ROOTL D lows Electric Light & Power Co 80/09/05 ip
- 8009190533 Application to amend License DPR-49 modifying Tech Specs to reflect TMI-2 Lessons Learned Category III amend fee encl RODT,L D IDWA Electric Light & Power Co 80/09/10 ip
- E009230286 Forwards fee payment for application to amend App A Tech Sgec\* RDDT, L D Iowa Electric Light & Power Co 80/09/12 2pp
- BCOO190541 Proposed Tech Spec changes supporting amend to License DPR-49 by changing Tables 3 2-A,3 2-H,4 2-H,Sections 6 2, 6.3 & 6 B & deleting Note 8 on Page 3 2-7 to reflect TMI-2 Lessons Learned 4 lows Electric Light & Power Co 80/09/10 16pp
- 9 Inspection reports. IE Bulletins & correspondence
- BOOGO90042 Forwards IE Bulletin 80-07, Suppl 1, "BWR Jet Pump Assembly Failure" No response required MEPPLER, J.O. Region 3, Chicago, Office of the Director 80/05/14
- BO09100154 Forwards IE Insp Rept 50-331/80-10 on 800402-30 & notice of violation MEISHVANN R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/07/24 2pp
- --8009100156 Notice of violation from insp on 800602-30

  Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/07/23 p
- --8007100161 IE Insp Rept 50-331/80-10 on 800602-30 Noncompliance noted failure to lock closed valve in standby liquid control sys LITILE.M S. (HRISTIANSON,F., CLARDY,L. Region 3, Chicago, Office of the Director 80/07/23 4pp
- 8009020170 Responds to IE Bulletin 80-16 re Rosemount, Inc transmitter misapplication Rosemount pressure transmitters not installed mor primmed to be installed at facility RDOT, L D Iowa Electric Light & Power Ca 80/07/28 lp

- 8009170961 Responds to NRC request for add1 info re control rod driveline sys Response includes info reviewed per IE Bulletins 79-02 & 79-14 No resnalysis of safety-related piping sys performed ROOTL D Towa Electric Light & Power Co 80/08/11 3pp
- 8007030202 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Mercury-Retted Matrix Relays in Reactor Protective Sys of Operating Nuclear Fower Plants Designed by C-E " Written response required KEPPLER, J G Region 3. Chicago. Office of the Director 80/08/15
- 8009090026 Responds to Item B of IE Bulletin BO-17, Suppl 1, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BMR "
  Operating procedures will be revised to require surveillance testing of switches
  ROOT, L D Iowa Electric Light & Power Co 80/08/15 4pp
- 8009150459 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE BWR Facilities "No specific action or response requested KEPPLER.J G Region 3, Chicago, Office of the Director 80/08/20 to
- 8009120050 Forwards Suppl 3 to IE Bulletin 80-17. "Failure of Control Rods to Insert During Scram at BNR" Written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/08/22 to
- 8009170428 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER, J & Region 3. Chicago, Office of the Director 80/08/22
- 8009040424 Responds to IE Bulletin 80-17. Suppl 3 Action Item 1 does not apply since scram discharge vol headers connect directly to instrument vol rather than through 2-inch pipe Revised procedures available at site for review ROOT.L D Town Electric Light & Power Co 80/08/27 2pp
- 8009230082 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers" No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/08/28
- 8009120555 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Relays are not used in facility Twenty-four manhours expended for review ROOT.L D lower Electric Light & Power Co 80/08/29 ip
- 8009170409 Responds to IE Bulletin 80-20 re failures of Westinghouse Type W-2 spring return to normal control switches Identified switches are not used in safety-related areas Twenty-four manhours expended on review ROOT.L D lows Electric Light & Power Gø 80/08/29 ip
- 8009170427 Suppls 800505 response to IE Bulletin 79-01B re environ qualification of Class IE equipment Vendor contact established re outstanding items Reviews underway Final response will be submitted by 801101 RCGT.L D Jowa Electric Light & Power Co 80/08/29 ip
- B009230484 Forwards Revision 1 to IE Bulletin 79-26, "Boron Loss From BUR Control Blades " Written response required KEPPLER.J G Region 3. Chicago, Office of the Director B0/08/29 1p
- 8009240103 Forwards IE Circular 80-21. "Regulation of Refueling Crews" No written response required KEPPLER, J.G. Region 3. Chicago. Office or the Director 80/09/10 1p
- R Periodic operating reports & related correspondence
- 8009190499 Forwards monthly operating rept for Aug 1980 MINECK.D L lowe Electric Light & Power Co 80/09/12 ip
- -~8009190504 Monthly operating rept for Aug 1980 VAN SICKEL.J Fowa Electric Light & Power Co 80/09/15 8pp

- S Reportable occurrences, LERs & related correspondence
- 8009030466 Forwards LER 80-038/03L-0 MINFCK.D L lowa Electric Light & Power Co 80/08/29 ip
- -9009030471 LER 80-038/03L-0 on 800801/during normal power operation, both drywell particulate recorders found downscals Caused by high moisture content on particulate radiation detectors due to MSIV pacting leak Leak repaired RAGER, M I Gua Electric Light & Power Co 80/08/29 sp
- 8009170315 Forwards LER 80-039/03L-0 MINFCK.D L Ioua Electric Light & Power Co 80/09/10 lp
- --BO09170320 LER BO-039/03L-O on B00820, during surveillance test, high differential pressure switch PDIS 2139 tripped at 2 75 psid contrary to Tech Specs Gaused by instrument drift Switch callor, tested & returned to svc RAGER, M loua Electric Light & Power Co B0/09/10 lp
- B009170324 Forwards LER 80-040/03L-0 MINFCK.D L Towa Electric Light & Power Co 80/09/10 1p
- --8009170328 LER 80-040/03L-0 on 800812, river water supply loop A removed to facilitate interchange of pump motors 1P-117A & 1P-117C as IP-117A replaced IP-117C on 79131 to maintain operation iP-117C returned to svc after original motor installed RAGER, M Towa Electric Light & Power Co 80/09/10 ip
- B009170348 Forwards LER 80-041/03L-0 MINECK, D L Iowa Electric Light & Power Co B0/09/10 1p.
- --8009170392 LER 80-041/03L-0 on 800820, control bldg isolation damper fV-AD-31A would not close, compromising operability of A control bldg standby filter unit Caused by shaft-operated connector bolt falling out of linkage RAGER. H Towa Electric Light & Power Co 80/09/10 1p
- 8009170355 Forwards LER 80~042/03L-0 MINECK.D L Ioua Electric Light & Power Co 80/09/10 ip
- ---B009170360 LER 80-042/03L-0 on 800813 during surveillance testing, containment spray permissive P3 43110 tripped at 2 3 psig. above max allowable Caused by instrument drift Instrument recalibr RAGER, M Ioua Electric Light & Power Co 80/09/10 ip
- 8009170363 Forwards LER 80-043/03L-Q HINECK.B L lowa Electric Light & Power Co 80/09/10 ip
- --8009170367 LER 80-043/031-0 on 800813, reactor core isolation cooling turbine trip throttle valve would not open during surveillance testing resulting in limiting condition for operation Cavsed by improperly positioned latching pin RAGER, M.S. Iowa Electric Light & Power Co. 80/09/10 ip
- BO09300493 Forwards LER 80~044/03L~0 RINECK D L | Iowa Electric Light & Power Co | 80/09/23 | 19
- --B009300501 LER B0-044/03L-0 on B00B24, during power ascension Rod Block

  Manitar B indicated downscale for any rod selected resulting
  in continuous rod withdrawal block Caused by improperly set
  pin connector Pin seated, panel tested & returned to svc

  RAGER, M S lowe Electric Light & Power Co B0/09/23 ip
- DOCKET 50-332 BARNWELL REPROCESSING PLANT
- Q Adjudicatory correspondence
- 8009170366 Comments on rulemaking 50-5 re mixed oxide fuel 0ESMO & other recycle-related licensing proceedings should continue Positive affirmative action to approve licenses recommended KIRK, W.F. Milliam F. Kirs. 80/08/28 4pp.
- 8009160224 Requests GESMO re fuels be completed Info as needed for future decisions re reprocessing of spent nuclear fuel VILLEMY, G. R. Affiliation Unknown 80/09/08 1p
- 8009160420 Comments on rulemaking 50-5 GESMG proceedings should be reopened to provide early procedural framework for subsequent licensing RICHARDS.R.B General Electric Co 80/09/08 2pp

- 8009300525 Forwards Comments in response to Commission 800807 order reterminated GERMO proceedings Reopening would be inimical to natt security & defense & at odds w/nonproliferation objectives
  BIALIK.E I New York, State of 80/09/23 7pp
- 8009300514 Expresses concern re-respening of GESMO & other related licensing proceedings for reprocessing sites FEIG.D Affiliation Unknown 80/09/13 ip
- 8009220226 Comments on rulemaking 50-5 QESMO proceedings should be reopened Technical economic & safety issues must be addressed in order for decisions to be made no use of mixed~ oxide fuels WEITZBERG, A Affiliation Unknown 80/09/15
- 8009260641 Urges resumption of GESMO hearings BOLONA & Affiliation Unknown 80/09/16 1p
- ~~4007260646 Opposes reopening of QESMO hearings BURRELLA Affiliation Unknown 80/09/13 1p
- ~-8009260652 Urges reopening GESMO & recycle-related proceedings & consideration of expanding scope to include recycle of LWR fuel in breeder reactors MCCORMACK.M House of Rep. 80/09/22 2pp
- 8009300540 Comments on reopening of GESMO proceedings Addl use of nuclear generated electricity should be paced to preserve significant quantities of hydrocambon reserves for use as raw malls in future chemical mfg BURRIS,L American Institute of Chemical Engineers 60/09/23 2pp
- 8009300549 Request extension of time for comment on Commission 800807 order re reopening GESMO proceeding HOLDEN:R 8 Allied General Nuclear Services 80/09/23 1p
- 8009300541 Supports reopening of GESMO & other recycling license proceedings PRICE.JE Affiliation Unknown 80/09/23 ip
- Q Inspection reports, IE Bulletins & correspondence
- 8009080231 Ack receipt of IE Insp Rept 50-332/80-02 an 800708-11 No proprietary info HGLDEN,R 9 Allied General Nuclear Services BO/08/08 ip
- ~-8009080233 Forwards IE Insp Rept 50-332/80-02 on 800708-11 No noncompliance noted KEN/IA:N B Region 2: Atlanta. Safeguards Branch 80/07/28. 19
- --8009080838 I& Insp Rept 50-332/80-02 on 800708-ii No noncompliance noted Major areas inspected safety committee, internal review & audits: IOCFR21 implementation & IE info notices CORYELL.0 P Region 2, Atlanta. Office of the Director KAHLE.J B Region 2, Atlanta. Safeguards Branch 80/07/08 4ps 80/07/09 4pp
- 8009230400 Forwards IE Circular 80-20, "Changes in Safe-Slab Tank Dimensions" No written response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/08/21
- DOCKET 50-333 JAMES A FITZPATRICK NUCLEAR POWER PLANT F Security, medical, emergency & fire protection plans
- 800923018B Requests that all personnel be reminded of purpose of emergency notification sys & health physics natwork, Mys installed for govt use during emergency GRIER, B H Region 1. Philadelphia. Office of the Director 80/08/22 3pp
- Adjudicatory correspondence
- 8009220104 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 IPPOLITORT A Operating Reactors Branch 2 80/08/29 2pp
- --8009220107 Order for mod of License DPR-59 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment info should be submitted by 801101
  EISENHUT,D Q Division of Licensing. 80/08/29 6pp

#### I Financial information

- 8007120376 Forwards estimated cash flow & audited financial statements for 1977

  BERRY, G T Power Authority of the State of New York 80/09/03
- P Operating license stage documents & correspondence
- 8009110554 Suppls NRC 800707 request for proposed Tech Specs changes re scram discharge vol vent & drain valves, & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENRUT.D O Division of Licensing 80/07/22 22pp
- 8009020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUI.D G Division of Licensing 80/07/31 7pp
- BOO90800BO Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 enci W/o NUREO EISENHUT.B O Division of Licensing 80/08/01 119pp
- 8007230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D 0 Division of Licensing 80/08/07 60pp
- 8009170255 Advises that two specific Event 5 valve configurations do not exist at facility per review of response to NRC 800223 ltr "Primary Coolant Sys Pressure Isolation Valves," technical evaluation rept encl JPPOLITO.T A Operating Reactors Branch 2 80/08/08 Spp
- --8009170260 "Primary Coolant Sys Pressure Isolation Valves," technical evaluation rept NOELL.P N . STILMELL, T C Franklin Institute/Franklin Research Center NRC-03-79-118 80/07/21 5pp
- 8009230237 Forwards NUREG-0661, "Mark I Containment Long-Term Program SER.Resolution of Generic Technical Activity A-7 " Rept dascribes NRC review results regeneric suppression pool hydrodynamic load definition W/o encl
- 8009030505 Forwards OE comments re facility reload SER ODYN use for rapid pressurization transient analyses re future reloads appropriate Transition to ODYN should not unduly perturb reload licensing cycle or penalize plant operation SHERNOOD, 6 G Deneral Electric Co , Nuclear Energy Products Div 80/08/22 5pp
- 8009070778 Informs that no relief will be granted for 20-month inservice insp/inservice testing test cycle due to three major differences of position NRC position on issues encl IPPBLITU.T A Operating Reactors Branch 2 80/08/27 4pp
- 8009180554 Advises that response to NRC 791109 ltr re ECCS evaluation models dealing w/fuel cladding swelling ½ incidence of rupture is acceptable No further action necessary IPPOLITO T A Operating Reactors Branch 2 80/09/03 2pp
- 8007270437 Fdrwards Amends 32 & 50 to Licenses DPR-64 & DPR-57, respectively, safety evaluation & notice of issuance & availability VARQA, 8 A Operating Reactors Branch 1 80/09/05 3pp
- --8009270446 Amends 32 & 50 to Licenses DPR-64 & DPR-59, respectively, changing organization chants & position titles & increasing manbership of safety review committee for both units VAROA, S.A. Operating Reactors Branch 1 80/09/05 26pp
- --8009270451 Safety evaluation supporting Amends 32 & 50 to Licenses

  DPR-64 & DPR-59, respectively

  # Office of Nuclear Reactor Regulation, Director 80/09/05 3pp
- --8009290454 Notice of issuance & availability of Amends 32 & 50 to Licenses DPR-64 & DPR-59, respectively VARGA, S A Operating Reactors Branch 1 80/09/05 3pp

- 8009(20362 Provides update of Mark I containment program mod schedule previously submitted on 790469 to 0921 Installation of vent header deflectors & saddle supports under torus complete. Other mods planned for completion during Fall 1981 BAYNE, J.P. Power Authority of the State of New York 80/09/09 Zpp
- 8009260446 Requests extension until 80(010 for submitting Tech Spec changes re TMI-2 Lessons Learned Category A items, due to completion of refueling outage restant of plant, fire protection / TMI related mods BANNE, J P Power Authority of the State of New York 80/09/23 ip
- O Inspectson reports. IE Bulletins & correspondence
- 8009090106 Forwards IE Bulletin 80-07. Suppl 1, "BWR Jet Pump Assembly Failure" Response required GRIER, DH Region 1, Philadelphia, Office of the Director 80/05/13 Ip
- 8009190936 Advises that response to IE Bulletin 80-14 will be consolidated w/reply to IE Bulletin 80-17 due to similarity of action items

  PASTERNAM.R J Power Authority of the State of New York 80/07/28
- 8007020115 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312 Type 304 Statinless Steel Pipes" No SA-312 or A-312. Type 300 seites fusion welded pipe in use or planned for use in safety-related sys PASTERNAN, R J Power Authority of the State of New York GO/07/27 Ip
- 8009110257 Ack receipt of 800607 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-333/80-05 GRIER.8 H Region 1. Philadelphia. Office of the Director 80/08/07 2pp
- --8009110278 Responds to NRC 800516 itr re violations nated in IE Insp. Rept 50-233/80-05 Corrective actions personnel training session to be conducted b instrument maint procedure revised PASTERNAK, R. J. Power Authority of the State of New York 80/06/07 7pg
- --8009110301 Forwards IE Insp Rept 50-333/80-05 on 800407-11 & notice of violation BRUNNER,E J Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/05/14 2pp
- --8009110393 Notice of violation from insp on 800407-11 \* Region 1, Philadelphia, Office of the Director 80/05/09 3pp
- --B009110306 IE Insp Rept 50-333/80-05 on 800407-11 Noncompliance noted failure to perform periodic procedure review & failure to implement calibr program for safety-related instruments GREEN/AN. E. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch BLUMBERO, N J Region 1. Philadelphia, Office of the Director 80/05/09 15pp
- 8007070014 Responds to IE Bulletin 80-19. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E "Mercury-wetted relays not used in sys at facility PASTERNAK.R J Power Authority of the State of New York 80/08/12 to
- 8009100117 Responds to IE Bulletin 80-20. "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches " No Type W-2 switches used in safety-related sys PASTERNAK.R J Power Authority of the State of New York 80/08/12 to
- 8009030074 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Mercury-Hetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER. B H Region i. Philadelphia. Office of the Director 80/08/15 1p
- 8009080266 Discusses IE insp on 800414-10 % 23-25 b forwards proprietary version of notice of violation & notice of proposed imposition of civil penalty Proprietary notice withheld (ref 10CFR2 790)
  STELLO, V Office of Inspection & Enforcement, Office of the Director, 80/08/18 2pp

- --8009080270 Notice of proposed imposition of civil penalty in amount of \$18,000 for item of nancompliance noted in IE inspion or \$18 000 for item or noncompliance noted in IE insp on 80044448 & 23-25 + Ornice of Inspection & Enforcement, Office of the Director
  - 80/08/18 Ιp
- 8009120100 Forwards Suppl 3 to IE Bulletin 80-(7. "Failure of Control Rods to Insert During Scram at BUR' Written response required
  - GRIER, B H Region 1. Philadelphia. Office of the Director
- 8009180028 Forwards IE Circular 80-18, "10CFR50 99 Safety Evaluations for Changes to Radwaste Treatment Sys ' No written response
- Region i, Philadelphia, Office of the Director 80/08/22 1 в
- 009120233 Forwards IE Info Notice 80-31 "Malaperation of Gould-Brown Bover: 480 Volt Type K-600S & K-DON 600S Circuit Breakers" No written response required GRIER, B H Region I. Philadelphia, Office of the Director 8009120233 Forwards IE Info Notice 80-31
- No written GRIER, BH R
- 8009230499 Forwards Revision 1 to IE Bulletin 79-26. "Boron Loss From BNR Control Blades " Written response required GRIER.B K Region 1. Philadelphia. Office or the Director 80/98/29 1p
- 8009240035 Forwards (E Circular 80-21, 'Regulation of Refueling Crews " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/09710 1p
- 8009240324 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Ma+1s ' No written response required ORIER, B H Region I, Philadelphia, Office or the Director 80/09/12 tp
- R Periodic operating reports & related correspondence
- 8009100268 Forwards "Effluent & Waste Disposal Semiannual Rept. Jan-June PASTERNAM, R J Power Authority of the State of New York 80/08/26
- --8009100275 "Effluent & Waste Disposal Semiannual Rept.Jan-June 1980 "

  4 Power Authority of the State or New York 80/08/26 84pp
- 8009090303 Forwards monthly operating rept for Aug 1980 PASTERNAK, R. J. Power Authority of the State of New York 80/09/05
- -8009090308 Monthly operating rept for Aug 1980 \* Power Authority of the State of New York 80/09/05 16pp
- 9 Reportable occurrences, LERs 3 related correspondence
- 8009040591 EN-80-037 on 800818, notice of violation & notice of Devotors the Burector of civil penalties of \$48,000 to be issued Action is based on items of noncompliance associated wimplementation of physical security plan BROCYETITY W. THOMPSON, D. Orfice of Inspection & Enforcement. Office of the Director BO/03/14 ip
- 8007030405 Forwards LER 80-065/03T-0 PASTERNAX,R J Power Authority of the State of New York 80/08/27
- --B009030314 LER 80-065/03T-0 on 800B14, during normal operations, while inerting primary containment standby gas treatment sys AFB round inoperable Caused by blocked drain line allowing water to accumulate in line until fairs could not discharge CHILDS N V Powel Authority of the State of New York 80/08/27 200
- 8007030418 Forwards LER 80-066/03L-0 PASTERNAGE J Power Authority of the State of New York
- -8009030423 LER 80-066/03L-0 on 800805 during normal shutdown conducting surveillance procedure F-ISP-8, cors spray sys pipe break detection switches IA-DPIS-43A & 43B found set greater than limit Caused by Instrument drift Instruments recaller CHILDS.W V Power Authority of the State of New York 80/08/28

- 8009020354 Forwards LER 60-067/03L-0 PASTERNAK, R J Power Authority of the State of New York 80/08/29
- --8009020359 LER 80-067/03L-0 on 800805.while conducting instrument surveillance check, steam line low pressure switches found set higher than 100 psig limit Caused by instrument drift instruments calible k returned to svc CHILDS, W V Power Authority of the State of New York 80/08/25 60/08/29
- 8009020394 Forwards LER 80-048/03L-0 PASTERNAK,R J Power Authority of the State of New York 80/08/29
- --8009020403 LER 80-068/03L-0 on 800806, during normal cold shutdown, conducting instrument surveillance F-ISP-15, drywell drain sump pump flow transmitter found out of talerance Caused by instrument drift Instrument recellibr CHILDS.W V Power Authority of the State of New York 80/08/29
- 8009020409 Forwards LER 80-069/03L-0
  PASTERNAK, R J Power Authority of the State of New York 80/08/29
- -8009220422 LER 80-069/03L-0 on 800807.during normal shutdown,while conducting surveillance test F-ST-22A, auto depressurization sys timer found set below limit Caused by setpoint drift Timer adjusted 3 returned to syc CHILDS.W V Power Authority of the State of New York 80/08/27
- 8009090359 Forwards LER 80-037/03X-1 PASTERNAK,R J Power Authority of the State of New York 80/09/03
- --B009090361 LER 80-037/03X-1 on 800418 during normal operation & surveillance testing feedwater control sys level transmitter O6-17-52A found out of calibr Caused by seat leak on instrument bypass (equaliting) valve Instrument recalibr CHILDS,W V Power Authority of the State of New York 80/09. 80/09/03
- 8009120410 Forwards LER 80-070/03L-0
  PASTERNAK.R J Power Authority of the State of New York 80/09/08
- --8009120415 LER 80-070/03L-0 on 800809-15, intermediate range monitor sys problems encountered during plant shutdown, startup & normal operations Cause under speculation Followup rept to be submitted Power Authority of the State of New York 80/09/08
- 8009120359 Forwards LER 80-071/03L-0 PASTERNAK, R J Power Authority of the State of New York 80/09/09
- --8009120365 LER 80-071/03L-0 on 800810, during plant startup at less than 150 sig. reactor core isolation cooling turbine speed would not control in manual during surveillance test Sys flow also did not control in automatic Cause not determined CHILDS. W Power Authority of the State of New York 80/09/09
- 8009140445 Forwards LER 80-072/03L-0 PASTERNAK, R J Power Authority of the State of New York 80/09/11
- --8909160447 LER 80-072/03L-0 on 800812.during plant startup & operation, low pressure coolant injection inverter tripped Caused by electronic control failure Following repair, inverter became CHILDS.W V Power Authority of the State of New York 80/09/11
- B009160458 Forwards LER 80-066/03X-1
  PASTERNAM, R J Power Authority of the State of New York B0/09/11
- --8009160476 LER 80-066/03x-1 on 800805, during instrument surveillance procedure F-ISP-8, core agray sys pipe break detection switches 14-DPIS-A9A 3. A38 found set above max allowable Caused by instrument drift Switch recallibr CHILDS, W.V. Power Authority of the State of New York 80/09/ll

- 8009190499 Forwards LER 80-073/03L-0 PASTERNAA,R J Power Authority of the State of New York 80/09/12 1e
- --8009190496 LER 80-073/03L-0 on 800815 during surveillance, offgas radiation monitor B found out of calibr Caused by instrument drift & detector aging Adjusted & restored monitor to operable status 3 days after discovery Power Authority of the State of New York 80/09/12 ip
- DOCKET 90-334 BEAVER VALLEY POWER STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- E009230172 Requests that all personnel be reminded of purpose of energency notification sys & health physics network Sys installed for govt use during emergency GRIER, B H Region 1. Philadelphia, Office of the Director BD/08/22 3pp
- 3 Adjudicatory correspondence
- 8009220093 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 VAROA.S A Operating Reactors Branch 1 80/08/29 3pp
- --8009220096 Order for mod of License DPR-66 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101
  EISENHUT, D G Division of Licensing 80/08/27 &pp
- P Operating license stage documents & correspondence
- 8009020297 Submits interim criteria for shift staffing to all QL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D O Division of Licensing 80/07/31 7pp
- 8009030167 Requests written justification of long-term operability of long head safety injection pumps on basis of mods made as results of tests run at facility & elsewhere VAROA.5 A Operating Reactors Branch 1 80/07/31 2pp
- BOC9080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/o NUREO EISENHUT.D O Division of Licensing 80/08/01 119pp
- BCG9230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend ETSENHUT.P O Division of Licensing 80/08/07 60pp
- 8009190794 Forwards revised Westinghouse STS 3 9 8 2,3 9 10 & Bases 3/4 9 8 & 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NOVAK.T M Assistant Director for Operating Reactors 80/08/15 to
- --8009190817 Revised Wastinghouse STS 3 9 8 2,3 9 10 % Bases 3/4 9 8 & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods

  \* Assistant Director for Operating Reactors 80/06/23 21pp
- 8009180525 Ack receipt of 800514 application for amend of license re Tach Spec changes Review determined to require Class II fee DIGOS.R M License Fee Management Branch 80/08/21 ip
- 8009190589 Forwards Amend 28 to License DPR-66, safety evaluation & notice of issuance & availability EIBENHUT, D G Division of Licensing B0/08/27 2pp
- --8009190596 Amend 28 to License DPR-66, revising Tech Specs to reflect mods made to alleviate NPSH problems w/low head safety injection & recirculation spray pumps VAROA, S A Operating Reactors Branch 1 80/08/27 12pp
- --8007170602 Safety evaluation supporting Amend 28 to License DPR-66

  d Office of Nuclear Reactor Regulation. Director G0/08/27
  18pp

- --8009190607 Notice of issuance & availability of Amend 28 to License PR-66 GROTE:MUIS, M. Operating Reactors Branch 1 80/08/27 2pp
- 8009150219 Forwards Amend 29 to License DPR-66. safety evaluation \$
- notice of issuance & availability
  VAROA.S A Operating Reactors Branch 1 80/08/29 3pp
- --8009150244 Amend 29 to License DPR-66, revising Tech Specs to eliminate use of reactor coolant pump position trip above setpoint P-8 VARGA, S.A. Operating Reactors Branch 1 80/08/29 4pp
- --8009150246 Safety evaluation supporting Amend 29 to License DPR-66
  \* Office of Nuclear Reactor Regulation, Director 80/08/29 2pp
- --8009150248 Notice of Issuance & availability of Amend 29 to License DPR-66 NEIOHBORS, J D Operating Reactors Branch 1 80/08/29 2pp
- B009090405 Forwards "Low Head Safety Injection Pumps Presently Installed at Beaver Valley Power Station.Unit 1." in response to NRC B00731 | Itr Rept describes mode 5 testing conducted to assure long-term operability of pumps DUNN.C (I Duquesne Light Co B0/09/04 ip
- ---8009090412 "Low Head Safety Injection Pumps Presently Installed at Beaver Power Station. Unit 1" IRELAND.R N , SIEBER. J D , CAREY. J Duquesne Light Co B0/09/04 4pp
- B007100609 Forwards Class II fee to suppl Class IV fee submitted in B00514 application for amend of License DPR~66 MODRE.G W Duquesne Light Co 80/09/04 1p
- --8009100617 Forwards check for Class II fee DIGOS.R M License Fee Management Branch 80/09/08 ip
- 8007240166 Forwards Amend 30 to License DPR-66, safety evaluation & notice of issuance 5 availability
  VARQA:8 A Operating Reactors Branch 1 80/09/10 3pp
- --8009260181 Amend 30 to Liconse DPR-65 revising radiological Tech Specs to reflect new streamline break protection sys VARBA, 5 A Operating Reactors Branch 1 80/09/10 30pp
- ---8007260186 Safety evaluation supporting Amend 30 to License PPR-66
  \* Operating Reactors Branch 1 80/07/10 28pp
- --8009260192 Notice of issuance & availability of Amend 30 to License DPR-66 VARRALS A Operating Reactors Branch t 80/09/10 29p
- 8009230601 Confirms 800915 teleon re qualification of chlorine detection sys per Reg Guide I 95 Detection sys qualified for all expected environs t severe environs that could lead to chlorine release SIEBER, J D Duquesne Light Co 80/09/16 3pp
- BOO9230711 Confirms BOO909 teleon re basis for selecting assential sys regarding clarification of NUREG-D576 Item 2 i 4 SIEDER, J D Duquesne Light Co 80/09/16 ip
- BO09230263 Application to amend License DPR-66, changing Tech Specs Bections 3 3,3 4,3 11,4 3,4 4 & 4 11 to add auxiliary feedwater to engineered safety feature sys instrumentation & revising accident monitoring instrumentation requirements DUNN.C N Duquesne Light Co 80/09/17 2pp
- ---B009230269 Proposed Tech Specs 3 3.3 4.3 11.4 3.4 4 & 4 11 re engineered safety feature instrumentation, accident maniforing instrumentation, surveillance requirements, RCS pressuriter & min shift crew composition \* Duquesne Light Co B0/09/17 31pp
- 8009230454 Confirms 800704 telcon re compliance w/NUREO-0578, Item 2 1 3 b concerning wide range pressure imputs & resistance temp detector uncertainty Util will upgrade nonsafety-grade input to safety grade during second refueling BIEGER, J D Duquesne Light Co 80/09/17 lp
- 8009230593 Confirms 800919 telcon re clarification of util position w/respect to NRC questions concerning 800628 submittal on TMI Short-Term Lessons learned requirements SIEBER, J. D. Duquesne Light Co. 80/09/17 8pp

- BQQ9300359 Responds to NRC B00813 ltr re revisions to Tech Specs Revisions will be provided in Oct 1980 Tech Spec changes are not immediately necessary fun of 23 ft or water over top of reactor vessel flange during movement of fuel assemblies DUNN,C N Duquesne Light Co 80709726 2pp
- O Inspection reports. IE Bulletins & correspondence
- 8009180001 Forwards IE Insp Rept 50-334/80-14 on 890519-23 No noncompliance noted BRUNNER.E J Region 1, Philadelphia. Reactor Operations Nuclear Support Branch 80/07/18 2pp
- --8009180005 IE Insp Rept 50-334/80-14 on 800519-23 No moncompliance noted Major areas inspected design change mod control, QA/QC surveillance, audits 2 followup on previously identified items
  GREENIMALE Region 1, Philadelphia, Reactor Operations Nuclear Support Branch NAPUDA.G , SIMONETTI.G Region 1, Philadelphia, Office of the Director 80/07/16 Spp
- B009160244 Forwards IE Insp Rept 50-334/80-19 on 800627-28 No noncompliance noted MARTIN.N G Region 1. Philadelphia. Safeguards Branch B0/07/24 20p
- --B009160246 IE insp Rept 50-334/80-19 on B00627-28 No noncompliance noted Major areas inspected licenses actions taken in response to possible intrusion into protected area Details withheld (ref 100FR2 790)
  SMITH 0 C Region i, Philadelphia, Safeguards Branch DELVIN, J Region 1, Philadelphia, Office of the Director 80/07/24 ip
- 8009;10047 Forwards IE Insp Rept 50-334/80-12 on 800420-0531 No noncompliance noted BRUNNER,E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/07/25 2pp
- --8009110050 IE Insp Rept 50-334/80-12 on 800420-0531 No noncompliance noted Major areas inspected plant operations, apparent gaseous waste tank release & potential recirculation spray heat exchange integrity problem BECKMMAN.D A , HEGNER.J D Region i, Philadelphia, Office of the Director MCAME,E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/07/23 20pp
- 8009100384 Ack receipt of 800417 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-334/80-05 BRU/RIER,E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/08/11 2pp
- --8009100389 Responds to NRC 800329 itr re violations noted in IE Insp Rept 50-334/80-05 Corrective actions refueling water storage tank level indicators rearranged & meteorological calibr procedures altered DUNN.C N Duquesne Light Co 80/04/17 App
- ---B009100392 Forwards IE Insp Rept 50-334/80-05 on B00205-0B & 12-13 & notice of violation BRUHHER,E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch B0/03/25 2pp
- --8009100395 Natice of violation from insp on 800205-08 & 12-13 \* Region I. Philadelphia, Office of the Director 60/03/24 3pp
- --8009100397 IE Insp Rept 50-334/60-05 on 800205-08 & 12-13 Noncompliance noted failure to post temporary changes & revisions, failure to use approved procedure to perform Tech Spec calibr & failure to document calibr BAUNACK. W. Region I. Philadelphia. Reactor Operations Nuclear Support Branch 8LUMBERO. N. Region I. Philadelphia. Office of the Director 80/03/24 [5pp
- 6009150430 Forwards Performance Appraisal Branch insp planning data to facilitate 600818-22 insp Insp will examine problems identified w/Pacific Pumps RRUNKER.E J. Region J. Philadelphia, Reactor Operations Nuclear Support Branch 60/08/11 5pp
- 8009090116 Forwards responses to IE Bulletin 79-14 & Suppls 1 & 2.
  "Seismic Analysis for As-Built Safety-Related Piping Sys "
  W/completion of mods-all piping sys will be able to perform
  required safety functions during seismic event
  WOOLEVER.E J . SENCHYSKYN.J B Duquesne Light Co 80/08/14 8pp
- --8009070117 "Response to IE Bulletin 79-14 " Util schedule for completion of response and a state of 80/08/14 10pp # Stone & Webster Engineering Corp # 80/08/14 10pp

- 8007030070 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required ORIER. B H Region 1. Philadelphia. Office of the Director 80/08/15 1p
- 8009180478 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ORIER B H Region 1, Philadelphia. Office of the Director 80/08/22 19
- 80090907Bi Forwards evaluation of util 790430,0514,17 & 0712 responses to IE Bullstin 79-06A Appropriate actions taken to meet bullstin requirements Further actions may be required VARGA.S A Operating Reactors Branch I 80/08/27 14pp
- 8009120176 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 3 K-DON 6008 Circuit Breakers" No written response required GRIER.B H Region 1. Philadelphia. Office of the Director 80/08/27 1p
- 8007080307 Forwards response to NRC 800801 notice of violation in IE Insp Rept 50-334/80-15 Corrective action calibr procedures will be revised by 801031 DUNN.C N Duquesne Light Co 80/09/02 3pp
- 8009090374 Responds to NRC 800B18 ltr re violations noted in IE Insp Rept 50-334/80-22 Corrective action personnel responsible for preparing Radcon form 4 5 instructed to promptly update form upon receipt of required info DUNN.C N Duquesne Light Co 80/09/03 3pp
- B009230780 Forward's IE Circular 80-21, "Regulation of Refueling Crews"
  No written response required
  GRIER.B H Region 1, Philadelphia, Office of the Director
  80/09/10 ip
- BO09160374 Responds to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Long-term evaluation of any as-built discrepancies will be based on appropriate loading combination for design 8 operation DUNN.C N Commonwealth Edison Co B0/09/11 2pp
- B009240309 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matis " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director B0/09/12 1p
- R Periodic operating reports & related correspondence
- 8007030390 Forwards NPDES discharge monitoring repts for Jul 1980 MDDRE, G W Duquesne Light Co 80/08/29 2pp
- --8009030395 NPDES discharge monitoring repts for Jul 1980 MODRE, Q W Duquesne Light Co 80/08/29 13pp
- 8009180188 Forwards monthly operating rept for Aug 1980 DUNN.C N Duquesne Light Co 80/09/15 ip
- --8009180194 Monthly operating rept for Aug 1980 TIMAG.D R Duquesne Light Co 80/09/03 4pp
- 8009190446 Notifies that add1 time is needed to complete semiannual effluent rept for first six months of 1980 Rept will be submitted by 800930 Dose estimation data will be forwarded by 801030 DUNN.C N Duquesne Light Co 80/09/15 2pp
- S Reportable occurrences, LERs & related correspondence
- 8009050250 Forwards LER 80-060/03L-0 WERLING, J A Duquesne Light Co 80/08/28 2pp
- --8007050254 LER 80-060/03L-0 on 800827, discovered that damage to ECCS charging pumps may occur following secondary side high energy line break Caused by excessive back pressure preventing sufficient flow to prevent damage to pumps LACEY.W B Duquesne Light Co 80/08/28 2pp
- 8009120377 Forwards LER 80-047/03L-0 WERLING J A Duquesne Light Co 80/09/04 2pp

- --B009120384 LER 80-047/03L-0 on 800805 during exercise mode emergency diesel generator output circuit breaker failed to close Caused by relay latch inoperability due to dirty contacts After replacing contact block, diesel tested satisfactorily LACEY.W 8 Duquesne Light Co 80/09/04 2pp
- BOO9150393 RO evaluation & reanalysis required by IE Bulletin 79-14 revealed that certain piping & supports have less conservatism than assumed for safety analysis Cause unstated Pipe support will be added prior to startup HERLING. J A Duquesme Light Co 80/09/08 2pp
- 8009250251 RGs 80-062/01P & 80-063/01P on 800908 during evaluation & ranalysis required by IE Bulletin 79-14 overstrassed conditions found on boron injection tank & charging pump 10 discharge lines REPULING. J A Duquesna Light Co 80/09/08 1p
- 8009160309 Forwards LERs 80-062/01T-0 & 80-063/01T-0 WERLING.J A Duquesne Light Co 80/09/09 3pp
- --B009160311 LER B0-062/01T-O on 800908, overstress condition found to exist on boron injection tank discharge line during seismic event Cause unknown Pipe support mods will be completed before startup LACEY, W S. Duquesne Light Co. B0/09/09, 2pp
- --8009140313 LER 80-063/01T-0 on 800908, overstress condition found to erist on IC charging pump discharge line during seismic event. Cause unknown Pipe support mods will be completed before startup

  LACEY.N S Duquesne Light Co 80/09/09 2pp
- 8009160444 Forwards LER 80-059/01T-0 WERLING.J A Duquesna Light Co 80/09/09 2pp
- --800916045: LER 80-059/01T-0 on 800823.during dieset restart on low pressure following shutdown from surveillance run, starter motor burned up Caused by open field winding Starter was replaced £ACEY.N 8 Duquesne Light Cp 80/09/09 2pp
- 8009160470 Forwards LER 80-064/03L-0 MERLING, J.A. Duquesne Light Co. 80/09/10 2pp
- 8009180409 Forwards LER 80-008/01T-1 MERLING. J A Dequesne Light Co 80/09/11 2pp
- --B009160411 LER 80-00B/01T-1 on B00225, during in-plant insp. potential overstress condition of cable spreading room floor indicated due to postulated seismic loading Caused by utilizing underside of floor to higher degree than original design LACEY.W S Duquesne Light Co. 80/09/11 3pp
- BOO9190500 RO evaluation & analysis required by IE Bulletin 79-14 revealed piping & supports have less conservatism during satismic events Mods will be made prior to startup WERLING, J A Duquesne Light Co 80/09/15 2pp
- BO07240450 Forwards LERs 80-065/01T-0,80-066/01T-0 & 80-067/01T-0 WERLING, J A Duquesne Light Co 80/09/17 2pp
- --8009240456 LER 80-045/01T-0 on 800912, determined that both river water supply lines will be subj to overstress during seismic event Caused by dead weight & DBE loading factors Corrective actions underway LACEY.N 8 Duquesne Light Co 80/09/17 2pp
- --8009240458 LER 80-056/017-0 on 800912 determined that "A" steam generator steam outlet pips hangers will be subj to overstress during seismic event Gused by dead weight & DBE logding factors Hanger mod Gused by dead weight & LACEY, W S Dreguesne Light Co 80/09/17 2pp
- HO09290251 Forwards LER 80-052/017-0 WERLING.J. A Duquesne Light Co 80/09/19 2pp

- ---B009290257 LER 80-052/01T-0 an B00726, diesel fire pump was running helow rated RPM & pressure Caused by clogged fuel oil filter Filter replaced LACEY, W S Duquesne Light Co 80/09/19 2pp
- 8009300412 RO 80-070/01P on 800922.born dilution discovered during RCS initial fill & vent, causing unplanned reactivity insertion to exceed Tech Specs limits Caused by procedural deficiency Boric acid blender total flow setpoint changed WERLING, J A Duquesne Light Co 80/09/23 2pp
- 8009300543 LER 80-021 has been cancelled \* Duke Power Co 80/09/25 1p
- DOCKET 50-335 ST LUCIE PLANT, UNIT 1

  F Security, medical, emergency & fire protection plans
- 8007270624 Forwards proposed revision to emergency plan Apps will be forwarded under separate cover Complete amplementation will depend on availability of essential resources

  UHRIO.R E Florida Fower & Light Co 80/07/23 ip
- ~-8007290625 Draft emergency plan 4 Florida Power & Light Co 80/07/15 140pp
- 8009230261 Requests that all personnel be remanded of purpose of amergency notification sys & health physics network Bys installed for govt use during emergency O'REILLY, J.P. Region 2: Atlanta, Office of the Director 80/08/22 to
- 8007100922 Transmits emergency planning info to be made available to public at LPDR.Fort Pierce.FL W/o encl SOUDER.J L. Public Document Branch 80/08/27 (p
- O Adjudicatory correspondence
- 8009190297 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 CLARK,R A Operating Reactors Branch 3 80/08/29 2pp
- M Antitrust correspondence
- 8009190091 Matton before US Court of Appeals for BC Circuit, for expedited consideration of petition for review re consolidation of Civil Action 80-1099 w/administrative proceeding W/Certificate of Svc Related correspondence JABLON,R A . LANDSMAN,R M Florida Cities JABLON,R A Spiegel & McDiarmid 80/09/19 5pp
- 8009300476 Response before US Court of Appeals for DC Circuit, in opposition to petitioners' motion for expedited consideration of Civil Action 80-1099 Certificate of Sycencl Related correspondence DYM, H, BOUKNIOHT, JA Florida Power & Light Co DYM, H Covington & Burling 80/09/23 Spp
- P Operating license stage documents & correspondence
- 800702027 Bubmits interim criteria for shift staffing to all GL & CP licensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D Ø Division of Licensing 80/07/31 7pp
- 8007080080 Forwards draft NUREC-0676. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREC-0676 entl M/o NUREC EISENHUT.D © Division of Licensing 80/08/01 119pp
- 8007230082 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EIBENHUT,D 0 Division of Licensing 80/08/07 40pp

- B009040490 Responds to NRC B00728 ltr requesting opinion & advice re potential void cormation in vessel head Phenomena is unaffected by relatively small differences in fuel design Company would not analyze event unless asked by customer CHSLEY,OF Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) B0/08/26 ip
- 8009110325 Informs that util has contracted C-E for technical support to consultation in order to respond to questions re aspects of 800611 natural circulation cooldown at facility Responds to MRC 800812 ltr requesting technical opinion & advice SCHERER, A E Combustion Engineering, Inc. 80/09/05 2pp
- 8009150251 Forwards info re auxiliary feedwater sys in response to NRC 800502 request includes info re emergency operating procedure re alternate sources of auxiliary feedwater, pump area cormunizations & redundant condensate tank UHRIG.R E Florida Power & Light Co 80/09/10 3pp
- 8009160200 Forwards revised plans for monitoring noble gases which might be released from steam plant, per TMI Lessons Learned Task Force short-term requirements UHRIO.R E Florida Power & Light Co 80/09/11 2pp
- 8007140378 Responds to NRC 800702 ltr re TMI-related Tech Specs Proposed specs have been drafted & forwanded to onsite & offsite review committees for review & approval UHRIO, R E Florida Power & Light Co 80/07/12 ip
- 8009180444 Forwards response to NRC 800721 request for add1 info re adequacy of station electric distribution sys voltages UHRIG.R E Florida Power & Light Co 80/09/12 4pp
- 8009230306 Forwards updated response re natural circulation cooldown Emergency Operating Procedure 0120040 revised to address recognition of potential for upper head steam formation & cooldown rate necessary to provent void formation UHRIG.R E Florida Power & Light Co 80/09/16 3pp
- Q Inspection reports. IE Bulletins & correspondence
- 8009220182 Forwards IE Insp Rept 50-335/80-19 on 800609-10.No noncompliance noted STOHR.J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/06/26 2pp
- ---8009220184 IE Insp Rept 50-335/80-19 on 800609-10 No noncompliante noted Major areas inspected previous insp findings & IE Bulletin 79-18 JENKINS 0 R Region 2. Atlanta, Fuel Facility & Materials Safety Branch PERROTTI, D J Region 2. Atlanta, Office of the Director 80/06/26 3pp
- 8009100049 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Changing Pumps Following Secondary Side High Energy Line Rupture "Written response required O'REILLY. J P Region 2, Atlanta, Office of the Director 80/07/24
- 8009030320 Suppls response to IE Bulletin 80~04, "Analysis of PNR Main Stream Line Break w/continued Feedwater Addition " Complete analysis of automatic auxiliary feedwater initiation, supports installation of automatic sys UHR1G,R E Carolina Power & Light Co 80/08/04 ip
- 8007240066 Forwards IE Insp Repts 50-335/80-23 & 50-389/80-09 on 800715-18 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/08/05 2pp
- ---8009240071 IE Insp Repts 50-335/80-23 & 50-389/80-09 on 800715-18
  No honcompliance noted Major areas inspected records
  associated w/work performance during outage in areas of
  installation welding, weld rod control & core drilling
  VANDOURN.P K Region 2, Atlanta, Office of the Director
  HERDIA R Region 2, Atlanta, Reactor Construction & Engineering
  Support Branch 80/08/04 6pp
- 8009020192 Submits response to IE Bulletin 79-03A Facility has no fusion welded SA-312 Type 304 stainless steel pipe in use or planned for use in safety-related sys

  UHR10,R E Florida Power & Light Co 80/08/06 1p
- 8009020306 Informs of visual & ultrasonic examinations on representative samples of circumferential welds in syscontaining stagnant oxygenated & borated water.per IE Bullatin 79-17 No stress corrosion in welds UHRIG.R E Florida Power & Light Co 80/08/14. 1p

- 8009030158 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/15
- 8009170374 Forwards corrected page for licensee 800804 response to tE Bulletin 80-05 re engineered safety feature reset controls UHRIO.R E Florida Power & Light Co 80/08/19 2pp
- 8009160143 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/22 ip
- 8007120308 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Bovers 480 Volt Type K-6008 t K-DON 6008 Circuit Breakers " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 60/08/27
- 8009190137 Responds to IE Bulletin 80-15 Fourteen manhours expended preparing rept & 434 manhours expended on corrective action UHRIG,R E Fiorida Power & Light Co 80/09/02 3pp
- B009290277 Forwards IE Circular B0-21, "Regulation of Refueling Crews \* No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/10 5no
- 8009300152 Submits response to IE Bulletin 80-20 Westinghouse Type N-2 switches are used in safety-related 4160-volt switchgear Switches used do not use neutral function which caused problem referenced in bulletin
  UKRIO.R E Florida Power & Light Co 80/09/12 1p
- 8009300372 Forwards response to IE Bulletin 79-14, "Beismic Analysis for As-Built Safety-Related Piping Sys " UHRIQ.R E Florida Power & Light Co 80/09/19 609pp
- A Periodic operating reports & related correspondence
- 8009170279 Forwards monthly operating ropts for Aug 1980 SCHMIDT, AD Florida Power & Light Co 80/09/06 ip
- --8009170281 Monthly operating repts for Aug 1980 CHILBON V T Florida Power & Light Co 80/09/06 15pp
- S Reportable occurrences, LERs & related correspondence
- 8009020365 Forwards LER 80-033/03L-0 SCHMIDT.A D Florida Power & Light Co 80/08/25 ip
- --8009020372 LER 80-033/03L-0 on 800724,while at 100% power, control element assembly 63 dropped to fully inserted position Caused by technician accidently shorting output of 15-volt power supply while taking routine voltage measurements PACE, P L Florida Power & Light Co 80/08/25 ip
- --8009120316 LER 80-034/03L-0 on 800818 during full power operation. control element assembly (CEA) 41 dropped to full insertion Caused by failure of CEA 41 core power programmer 15-volt power supply Power supply replaced PACE, P L Florida Power & Light Co 80/09/02 1p
- 8009120307 Forwards LER 80-035/03L-0 SCHMIDT.A D Florida Power & Light Co 80/09/03 1p
- ~-8009120318 LER 80~035/03L-0 on 800804 during full power operation control element assembly (CEA) 16 dropped to full insertion Caused by failure of CEA 16 core power programmer 15-volt power supply replaced PACE.P L Florida Power & Light Co 80/09/03 1p
- 8009150288 Forwards LER 80-036/03L-0 8CHMIDT.A D Florida Power & Light Co 80/09/03 ip
- ~-8009150290 LER 80-036/03L-0 on 800805, during full power operation control element assembly 23 dropped to full insertion Caused by failure in core element assembly core power programmer 15-volt power supply Power supply replaced PACE, P L Florida Power & Light Co 80/09/03 1p

- 8099300482 Forwards LER 80-040/03L-0 SCRMIDT, A D Florida Power & Light Co 80/09/15 ip
- --8009390485 LER 80-040/03L-0 on 800815, during startup node, control alement assembly 30 dropped into fully inserted position Cause undetermined No corrective action necessary PACE,PL Florida Power & Light Co 80/09/15 1p
- DOCKET 50-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2

  F. Security, medical, emergency & fire protection plans
- 8009230180 Requests that all personnel be reminded of purpose of twergency notification sys & health physics network Sys installed for govt use during emergency GRIER. BH Region 1. Philadelphia. Office of the Director 80/08/22 3pp
- Q. Adjudicatory correspondence
- BO07190322 forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by B01101 CLARK-R A Operating Reactors Branch 3 80/08/29 2pp
- --8009190328 Order for mod of License DPR-65 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be subsitted by 801101
  EISENHUT,D 0 Division of Licensing 80/08/29 App
- P Operating license stage documents & correspondence
- BOOP020297 Submits interim criteria for shift staffing to all QL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Divelopment & implementation to be revisued within 90 days EISENBUT, D Q Division of Licensing 80/07/31 7pp
- 8009180309 "Safety Evaluation of Inservice Testing Program for Pumps & Valves:" Interim rept 790426-801025 FEMRINGER, J M , ROCKHOLD, H C E000 Idaho, Inc FIN A-6258 8007180309 80707/31 32pp
- BOO7080080 Forwards draft NUREG-0696, "Functional Criteria for Energency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT.D 0 Division of Licensing 80/08/01 119pp
- BO09120709 Forwards agenda of 800821 meeting at util ofcs to discuss assessment of regulatory performance GRIER, B It Region 1. Philadelphia, Office of the Director 80/08/04 2pp
- BOO7i10553 forwards add1 info requests re thermal hydravlics & accident & transient analysis sections of basic safety rept, & Cycle 4 relead safety analysis Requests add1 inforrequested on 800710.18 & 27, by 800815 to meet review schedule MOVAK.1.K Assistant Director for Operating Reactors 80/08/06 Ann
- BOO9230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISEMMUT.D © Division of Licensing 80/08/07 60pp
- <009180213 Confirms that two specific Event 5 valve configurations do not exist at facility Franklin Research Ctr Technical Evaluation Rept. "Primary Coolant Sys Pressure Isolation Valves." encl CLARK.R A Operating Reactors Branch 3 80/08/15 2pp</p>
- -B009190219 "Primary Coolant Sys Pressure Isolation Valves," technical evaluation rept NOCLL.P N : STILWELL,Y G Franklin Institute/Franklin Research Center. NRC-03-79-118 80/07/21 4pp
- OC903004B Forwards Amend 60 to License DPR-65, safety evaluation & notice of issuance & availability
  CLARK.R A Operating Reactors Branch 3 80/08/19 2pp
- -8009030054 Amend 60 to License DPR-65, changing Tech Specs to allow containment electrical penetrations module replacement concurrent w/fuel movement TRAKKELL, C Operating Reactors Branch 3 80/08/19 7pp

- --B009630062 Notice of issuance A availability of Amend 60 to License DPR-65 TRACMELL.C M Operating Reactors Branch 3 80/08/19 2pp
- 8009100454 Advises that mgt meeting w/NRC in Berlin.CT has been rescheduled for 800911 Agenda encl GRIER.B H Region 1, Philadelphia, Dffice of the Director 80/08/20 Zpp
- B009050195 Forwards addl info on Cycle 4 reload re thermal-hydraulics, transient \$\psi \text{accident analyses, \$\psi \text{reactor physics \$\psi \text{fuols,in} response to NRC 800806 ltr CDUNSILL \$\psi \text{ODUNSILL \$\psi \text{ODUNSILL \$\psi \text{ONOSILL \$\psi
- B009150247 Forwards addl info requosted by NRC re design mod to Cycle 4 fuel assemblies \$ GA program in offect during design of Cycle 4 reload fuel COUNSILN G. FEE.W F Northeast Nuclear Energy Co (qubs of Northeast Utilities) 80/08/27 App
- B007030378 Advises that util will not meet deadline for implementation of NUPEG-0578 requirements re emergency procedures & retraining for accidents & transients NRC feedback needed COUNSIL,# 9 Connecticut Yankee Atomic Power Co COUNSIL,# 9 Connecticut Yankee Atomic Power Co COUNSIL,# 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/08/20 2pp
- B009050103 Application for amend to License DPR-65, incorporating proposed revisions to Tech Specs required to support plant operation Suring Cycle 4 reload CGU/811,U G Northeast Nuclear Energy Co (subs of Northeast Utilities) B0/08/29 3pp
- --B009050105 Proposed revisions to Tech Specs required to support plant operation during Cycle 4 reload

  \* Northeast Nuclear Energy Co (subs of Northeast Utilities)
  B0/08/29 28pp
- 8009190662 Requests Class III fee for review of 800920 application for proposed Tech Spec changes re automatic initiation of auxillary feedwater sys Application involves consideration of single safety issue
  MILLER.W O License for Management Branch 80/09/02 ip
- B009110371 Requests that encl supporting document be docketed under Millstone KAPO.P S 80/09/09 1p
- 8009180445 Advises that C-E owners group 800215.0430 & 0731 ltrs re asymmetric LOCA loads are applicable to Millstone Unit 2 & should be reparded as util response to NRC 780125 request COUNSIL.N G Northoast Nuclear Energy Co (subs of Northeast Utilities) 80/09/10 2ρρ
- BOO9180357 Forwards implementation status of Category B TMI-2 lessons Learned requirements for each facility Echedules specificalty identify Items where requirement connot be met or schedule is not feasible GOUNSIL. If G Connecticut Yankee Atomic Power Co COUNGIL, If G Northeast Nuclear Energy Co (subs of Northeast Utilities) BO/09/15 43pp
- BOO7290351 Application for amend to Licenses DPR-61.DPR-21 & DPR-65. incorporating revisions to Tech Specs for RCS per TMI-related requirements Fee encl COUNSIL.U G Connecticut Vankee Atomic Power Co CDUNSIL.U G Northeast Utilities BO/07/16 App
- --8009290372 Proposed revisions to Tech Specs 3/4 4 3 for limiting condition for operation of RCS relief sys \* Connecticut Yankee Atomic Power Co 78/12/00 3pp
- --8007270377 Proposed revisions to Tech Spect 3/4 4-3a re limiting conditions for operation of RCS relief valves-operating \* Connecticut Yankee Atomic Power Co 80/07/30 ip
- --8009290381 Proposed revisions to Tech Specs 3/4 4 4 for limiting canditions for operation of RCS pressurizer \* Connecticut Yankee Atomic Power Co 80/09/30 2pp
- --8009290384 Proposed revisions to Tech Space 3/4 4 5 for RCS steam generators
  \* Connecticut Yankee Atomic Power Co 80/09/30 ip

- --8009250397 Proposed revisions to Tech Specs 6 0 for administrative controls
  - Connecticut Yankes Atomic Power Co 80/09/30 3pp
- 8009300179 Forwards nonproprietary & proprietary repts, "Guide Thimble Inset Design " Withholding application & affidavit encl Proprietary version withheld (ref 10CFR2 790) COUNSIL W G Northeast Utilities 80/09/18 16pp
- --8007300183 "Guide Thimble Inset Design," nonproprietary version
  # Northeast Utilities 80/09/30 15pp
- BOO9300291 Corrects typographical error in Tech Spec Table 3 9-1 of Amend 60 to License BPR-65 Doors 292 & 297, listed as servicing solidification sys area, should be 292 & 207 COUNSIGN 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/09/22 ip
- G. Inspection reports. IE Bulletins & correspondence
- 8009150082 Forwards IE Insp Repts 50-245/80-10 & 50-336/80-07 on 802501-0705 No noncompliance noted BRUNNERE J Region 1, Philadelphia. Reactor Operations Nuclear Support Branch 80/07/14 2pp
- --B009150028 IE Insp Repts 50-245/80-10 & 50-336/80-07 on 800601-0705
  No noncompliance noted Major areas inspected control room,
  accessible portions of Unit 1 reactor & intate bldgs.Unit 2
  encl & condensate polishing facility
  KEIMIO.R R Region 1. Philadelphia, Reactor Operations Nuclear
  Support Branch SMEDLOSKY.J T , ZIMMERMAN.R P Region 1.
  Philadelphia, Office of the Director 80/07/11 7pp
- 8009;10482 Responds to IE Bulletin 80-16 re Rusemount.Inc pressure transmitters Model 1151 or 1152 Util does not plan to install sub; transmitters at facility CCUNSIL.N G Northeast Utilities 80/07/31 lp
- 8009150465 Discusses 800805 meeting u/util re physical protection program insp findings & forwards outline of corrective actions Encl withheld (ref 10CF82 790) ORIER B H Region 1. Philadelphia, Office of the Director 80/08/07 lp
- 8009100109 Updates 800714 response to IE Bulletin 79-02. Revision 2. JUNIOUS Updates BUD/16 response to IE Bulletin 79-02-Revision "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts," by forwarding revised list of seismic Category I supports on block walls using subj bolts COUNSIL U. V. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) BO/08/11 6pp
- 8007030031 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required ORIER B H Region I, Philadelphia, Office of the Director BO/08/15 ip
- 8009182017 Forwards IE Circular 80-18, "1007850 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GRIER,B H Region 1, Philadelphia, Office of the Director 80/08/22 1o
- 8009120190 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Bover: 480 Volt Type K-6005 & K-DON 6008 Circuit Breakers " No written response required CRIER.8 H Region i. Philadelphia. Dffice of the Director 80/03/27 ip
- 8009230791 Forwards IE Circular 80-21, 'Regulation of Refueling Crews " No written response required GO-21. Regulation of Refuel No written response required GRIER.B H Region 1. Philadelphia, Office or the Director 80/09/10 ip
- 8009240319 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Euclusive-Use Shipments of Radioactive Habls "No written response required GRIER.8 H Region 1. Philadelphia, Office of the Director 80/09/12 ip
- A Periodic operating reports & related correspondence
- 8009020283 "Semiannual Radioactive Effluents Release Rept. Jan-June. Northeast Murlear Energy Co (subs of Northeast Utilities) 80/08/29 100pp

- 8009230345 Forwards monthly operating rept for Aug 1980 MROCZKA, E. J. Northeast Utilities 80/09/18 ip
- --8009230347 Monthly operating rept for Aug 1980 HOWLETT, G H Northeast Utilities 80/09/03
- S Reportable occurrences, LERs & related correspondence
- B009020284 Forwards LER B0-027/03L-0 MRGCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Utilities) B0/08/25 1p
- --8009020285 LER 80-027/03L-0 on 800729, during steady state power operation, leak from failed socket weld found on fitting in i-inch safety injection tank recirculation line Caused by crack due to long-term fatigue attributed to vibration. HARRIS.J S Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/08/25 2pp
- B009160457 Forwards LERS 80-028/03L-0.80-029/03L-0 & 80-030/03L-0 MR0CZKA.E J Northeast Utilities 80/09/08 ip
- --8009160461 LER 80-028/03L-0 on 800811.at 100% power, control element assembly 41 dropped from 180 to zero steps Caused by faulty jumper cable from refuel disconnect panel to reactor head Power reduced & assembly realigned Replacement planned MARRIS.J S Northeast Utilities 80/09/08 1p
- ---B009160464 LER 80-029/03L-0 on 800812, during surveillance test on 12 U diesel,125 VDC ground alarm received Caused by frayed insulation on wire in Bondix connector allowing contact between bare wire & connector shell bire recovered HARRIS,J S Northeast Utilities 80/09/08 Ip
- --B007i60467 LER 80-030/03L-0 on B00812.during routine operation, containment air temp exceeded 120 F Caused by svc water temp control valve to reactor bldg closed cooling water heat exchangers being set too high Valve readjusted HARRIS.J S Northeast Utilities 80/07/08 1p
- 8009190460 Forwards LERs 80-028/03L-0,80-029/03L-0 & 80-030/03L-0 MRDCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Ut(lities) 80/09/08 ip
- --8009190531 LER 80-028/03L-0 on 800811, during steady state 100% power operation, control element assembly 41 dropped to zero steps from 180 steps Apparently caused by faulty jumper cable from refuel disconnect panel to reactor head HARRIS, J & Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/09/08 ip
- --B009190537 LER 80-029/03L-0 on 800B12, during 12U diesel surveillance testing, 125 VDC (Bus 201A) ground alarm was received Caused by frayed insulation on one wire in Bendix connector Frayed insulation replaced HARRIS.J S Northeast Nuclear Energy Co (subs of Northeast Ustlittles) 80/09/08 1p
- -B009190543 LER 60-030/03L-0 on 800B12 during routine power operation, containment air temp found in excess of 120 F limit Caused by svc water temp control valve to reactor hidg closed cooling water heat exchangers set too high Valve readjusted HARRIS.J S Northeast Nuclear Energy Co (subs of Northeast Ut(lities) 80/09/08 1p
- B009260649 Forwards LER B0-031/03L-0 MRDCZKA,E J Northeast Utilities 80/09/12 1p
- --B009260654 LER 80-031/03L-0 on B00817.one of two min channels of wide range neutron flux instrumentation required for Mode 5 failed Caused by defective preamplifier Component replaced HARRIS.J S Northeast Utilities 80/09/12 1p
- DOCKET 50-338 NORTH ANNA POWER STATION, UNIT 1
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 80D9150523 FES for facility # Office of Nuclear Reactor Regulation, Director NUREG-0134 ADD 2 80/08/31 53pp Available at NTIS \$3 25

- F Security, modical, emergency & fire protection plans
- 8009230273 Requests that all personnel be reminded of purpose of emergency matification sys & health physics network Sys installed for govt use during emergency D'REILLY, J.P. Region 2. Atlanta, Orrice of the Director 80/08/22 19
- 8009230320 Forwards revised nuclear security personnel training & qualification program Program withheld (ref 100FR2 790)
  SYLVIA.B R Virginia Electric & Power Co 80/09/19 1p
- 8009260182 Requests extension of 30 days to respond to 800804 request that emergency plan be revised Request is based on scope of revision \$ internal review required SYLVIA.B R Varginia Electric \$ Power Co 80/09/22 ip

### Q Adjudicatory correspondence

- 8009260615 Forwards order requiring inro supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 CLARK.R A Operating Realtors Branch 3 80/08/29 2pp
- 8009230529 Advises of changes to Station Settlement Procedure 1-PT-Ji1 per ALAB-578 Settlement monitoring Points 11,12,13 & 14 & all reference to Units 3 & 4 svc water pump house have been deleted SYLVIA,8 R Virginia Electric & Power Co 80/09/19 1p

#### H General correspondence

- 8007070436 Responds to enci Botetourt County Chamber of Commerce 800626 request to FERC for info re when facilities will be operational Lists status of plant operating schedules DENTON: H R Office of Nuclear Reactor Regulation, Director 80/09/05 3pp
- J Insurance & indemnity information
- 8009090384 Forwards Endorsement 1 to NELIA Binder EB-70 ANDREWS,C L Marsh & McLennan Inc . M & M Nuclear Consultants, Inc Din 80/09/03 2pp
- P Operating license stage documents & correspondence
- G009110610 Forwards request for add1 info re bypass & roset of engineered safety features per review of 790113 & 1220 submittals Requests response within 30 days CLARKER A Operating Reactors Branch 3 80/07/10 4pp
- BO09020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D & Division of Licensing 80/07/31 7pp
- BOO9050000 Forwards draft NUREC-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISEMHUT.D O Division of Licensing 80/08/01 119pp
- BOO9230052 Informs that exemption from fee re licensing action associated #/IMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D & Division of Licensing 80/09/07 60pp
- EQ09190794 Forwards revised Westinghouse STS 3 9 B 2,3 9 10 & Bases 374 9 B & 374 9 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NOVAK.T M Assistant Director for Operating Reactors 80/08/15 to
- --8067190817 Revised Westinghouse STS 3 9 8 2.3 9 10 b Bases 3/4 9 8 \$ 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods \* Assistant Director for Operating Reactors 80/06/23 21pp

- 8007070881 Advises that Class II fee is required for review associated w/issuance of Amend 18 on 800517 MILLER,W D License Fee Management Brench 80/08/22 ip
- BO09030426 Requests amend to OLs consisting of changes to Tech Specs & to ETS Proposed changes encl FERGUSON, J H Virginia Electric & Power Co 80/08/28 4pp
- ---8009030428 Proposed Tech Spec & ETS changes transferring independent review responsibility from existing Sys Nuclear Safety Operating Committee to Safety Evaluation & Control staff \* Virginia Electric & Power Co 80/08/28 44pp
- BOO9096344 Application to amend Licenses NPF-4 & NPF-7, transferring independent review responsibility from sys nuclear safety b operating committee to safety evaluation b control staff t audit responsibility to 9A dept Received w/o encl check FERGUSON. J H Virginia Electric b Power Co 80/08/28 4pp
- --R009070347 Proposed Tech Spec changes to Section 6 transferring independent review responsibility from sys safety & aperating committee to safety evaluation & control staff & audit responsibility to GA dept

  4 Virginia Electric & Power Co 80/08/28 35pp
- --8009070352 Proposed ETS change to Section 5 transferring independent review responsibility from sys safety & operating committee to safety evaluation & control staff % audit responsibility to GA dept
  - # Virginia Electric & Power Co 80/08/28 9pp
- BOOPIIO431 Forwards FPRI repts on resin intrusions into boilers & steam generators per NRC request Concurs w/EPRI conclusions, which are applicable, in part, to facility
  SYLVIA.B R Virginia Clectric & Power Co 80/09/08 ip
- --8009110433 EPRI Repts RP-623-3, first % second progress repts.Apr & Jun.
  1979, respectively.RP-623-1, fourth progress rept.Jul 1979 &
  RP-1563-2, first progress rept.June 1980 Repts concern resin
  intrusions into boilers & steam generators
   Electric Power Research Institute 80/09/08 600pp
- 8009160429 Forwards fee in response to NRC 800822 request for payment re issuance of Amend 18 to License NPF-4 BAUM.E A Virginia Electric & Power Co 80/09/11 1p
- --8007160433 Submits info re util 800711 fee payment DIGGS.R M. License Fee Management Branch 80/09/15 ip
- 8009260529 Requests analysis of precision obtainable from direct measurement sys for svc water pipe expansion joints as compared wexisting indirect sys & cost estimate for implementation NDVAK.T M Assistant Director for Operating Reactors 80/09/12
- 8009190525 Bubmits info re maintaining min of 23 ft of water over reactor vessel flange during fuel movement, in response to NRC 800815 ltr Changes to Tech Specs to include RHR sys requirements identified in NRC 800011 ltr being reviewed SYLVIA, B R Virginia Electric & Power Co 80/09/16 2pp
- 8009230287 Submits update re secondary chemistry program Facility maintains secondary chemistry in compliance w/Westinghouse all volatile treatment guidelines Until evaluation is completed, Unit i Powder units will operate in bypass mode SYLVIA, B R Virginia Electric & Power Co 80/09/17 ip
- 8009220134 Forwards comments on NUREQ-0696 in response to NRC 800801 request Implementation of requirements according to time schedula not considered feasible Requests meeting to discuss preliminary plan re effective emergency response facilities FERGUSDN. J H Virginia Electric & Power Co 80/09/18 16pp
- 8007230292 Notifies of delay until Oct 1980 of responses to NRC 800710 & 25 requests for addl info re bypass & reset engineered safety feature actuation signals
  SYLVIA.B R Virginia Electric & Power Co 80/09/18 1p
- 8009290349 Provides add1 info re electrical distribution sys voltages Designs encl SYLVIA.B R Virginia Electric & Power Co 80/09/24 23pp.
- 8009309249 Forwards add1 into re multiple structure amplified response spectra evaluation of piping sys design, per NRC 800725 request Table 1, identifying status of each problem & basis for acceptability under Phase I effort encl SYLVIA.B R Virginia Electric & Power Co 90/09/24 9pp

- @ Inspection reports, IE Bulletins & correspondence
- 8009100055 Forwards (E Builetin 80-18, "Maint of Adequate Min Flow Through Centrirugal Charging Pumps Following Secondary Side High Energy Line Rupture " Written response required O'REILLT, J.P. Region 2, Atlanta, Orrice of the Director 80/07/24
- 8009020242 Submits response to IE Bulletin 79-03A For North Anna, no SA-312 or A-312. Type 300 series fusion welded pipe in Use at greater than 85% design stress For Surry, eight fittings determined in excess of 85% design stress SYLVIA.B R Virginia Electric & Power Co 80%08/08 2pp
- 8007030141 Forwards Revision I to IE Bulletin 80-17, "Failures of Mercury-Retted Matrix Relays in Reactor Protective Sys of Operating Ruclear Power Plants Designed by C-E " Written response required O'REILLY. J.P. Region 2. Atlanta. Office of the Director 80/08/15
- 8005230077 Submits supplemental response to IE Bulletin 79-18 Design change to provide visual evacuation signal in diesel generator rooms will be completed by 800930 SYLVIA.B R Virginia Electric & Power Co 80/08/21 ip
- 8009160172 Forwards IE Circular 80~18. "10CFRSO 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required D'REILLY.J P Region 2 Atlanta. Office of the Director 80/08/22
- 8009120031 Responds to TE Bulletin 80-19 Surry Units 1 & 2 do not use mercury-wetted relays in reactor protection sys No response for North Anna Units 1 & 2 SYLVIA.B R Virginia Electric & Power Co 80/08/27 2pp
- B009;20314 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-2005 1 X-DON 6005 Circuit Breakers "
  No written response required
  O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/27 is
- 8009240399 Forwards response to IE Bulletin 80-15 re possible loss of emergency notification sys w/loss of offsite power Design change initiated to change power supply to vital bus Administrative Procedure 29 & revised Affidavit encl SYLVIA.B R Virginia Electric & Power Co 80/09/05 3pp
- B009260517 Forwards IE Circular 80-21, 'Regualtion of Refueling Craws "
  No written response required
  O'REILLY, J P Region 2, Atlanta, Office of the Director BD/09/10
  Spp
- 8009150237 Forwards response to NRC 800820 ltr re violations noted in IE insp Repts 50-338/80-29 & 50-339/80-28 Corrective actions specific instructions given to control room operators re when to place channel in tripped condition SYLVIA.B R Virginis Electric & Power Co 80/09/12 4pp
- 8007300116 Forwards response to IE Bulletin 80-20 Hestinghouse Fype W-2 control switch applications found Sub; switches have been tested satisfactorily SYLVIA:B R Virginia Electric & Power Co 80/09/15 App
- 8009300255 Summarizes results of extensive steam generator insp performed during refueling outage Intention to install steam generator insp ports should be reconsidered until after more insps are performed SYLVIA.B R Virginia Electric & Power Co 80/09/26 4pp
- R Periodic operating reports & related correspondence
- 8009050329 Forwards "Radioactive Effluent Release Rept for North Anna Power Station," Jan - June 1980 SYLVIA.B R Virginia Electric & Power Co 80/09/02 12p
- --8009050335 "Radioactive Effluent Release Rept for North Anna Power Station." Jan-June 1980 OILBERT, J D. HOPPER, D K., CARTHRIGHT, W.R. Virginia Electric & Power Co. 80/09/02 229pp
- 8007270317 Forwards monthly operating repts for Aug 1980 SYLVIA.B R Virginia Electric 5 Power Co 80/09/15 1;
- --8009290321 Monthly operating repts for Aug 1980 WOODSMALL.W A . NEUFER.A 0 Virginia Electric & Power Co 80/09/09 9pp

- 8007230356 Forwards corrections to monthly operating repts for Aug 1980 SYLVIA.8 R Virginia Electric & Power Co 80/09/17 to
- --8009230360 Corrected operating repts for Aug 1980
  NEUFER, A G Virginia Electric & Power Co 80/09/09 2pp
- S Reportable occurrences, LERs & related correspondence
- 8009050026 Disagrees w/util plan to shut off recirculation flow as interim fix re low flow from auxiliary feed pump 1-FW-P-3B discussed in LER 80-061/01T-0 Recirculation flow path should be retained to protect pump CHECK, P & Assistant Director for Plant Systems 80/08/04 lp
- 8009120702 Part 21 rept re potential nonconservatism in indicated feedwater flow due to fouling of feedwater ventur:
  Detailed engineering evaluation is being performed SYLVIA.8 R Virginia Electric & Power Co 80/08/15 3pp
- 8009030555 Forwards LER 80-068/03L-0 CARTWRIGHT, W R Virginia Electric & Power Co 80/08/27 1p
- --8009030561 LER B0-068/03L-0 on 800801.during full power.electrical load discovered as having been added to 1H emergency bus w/o approved jumper Caused by improper administrative controls Load isolated from emergency bus & personnel reinstructed CARTWRIGHT.W R Virginia Electric & Power Co 80/08/27 2pp
- 8009030606 Forwards LER 80-061/01X-1 CARTWRIGHT, W R Virginia Electric & Power Co 80/08/27 ip
- --B009030614 LER 80-061/01X-1 on B0070B.S&W review indicated that under accident conditions, auxiliary feedwater pump 1-FW-P-3B may not be able to function as designed Cause unknown Testing on pump us11 be conducted to determine pump flow capacity CARTWR1GHT.W R Virginia Electric & Power Co 80/08/27 2pp
- B009030629 Forwards LER 80-069/03L-0 CARTWRIGHT, W R. Virginia Electric & Power Co B0/08/27 ip
- --8009030&32 LER 80-069/03L-0 on 800801.while operating in Mode 1 at 100X power, sample analysis indicated boron concentrations in stress of Tech Spec limit Caused by stratification of boric actd in either accumulator or makeup source (RNST)

  CARTHRIGHT.W R Virginia Electric & Power Co 80/08/27 2pp
- 8009030442 Forwards LER 80-072/03L-0 CARTWRIGHT, W R Virginia Electric & Power Co 80/08/27 ip
- --8009030649 LER 80-072/03L-0 on 800808.containment bulk average temp exceeded Tech Spec limit Caused by operation during period of high outside temp Temp returned to 105 F within 4-h No corrective action necessary CARTHRIGHT,W R Virginia Electric & Power Co 80/08/27 2pp
- 8009030653 Forwards LER 80-070/03L-0 CARTWRIGHT, W R Virginia Electric & Power Co 80/08/27 ip.
- ---B007030458 LER B0-070/03L-0 on B00814, containment air particulete high flow alarm was actuated Caused by dislocated high flow relay suitch Suitch replaced & loose relay socket tightened CARTHRIGHT, W R Virginia Electric & Power Co 80/08/27 2pp
- 8009030612 Forward's LER 80-071/017-0 CARTHRIGHT.W R Virginia Electric & Power Co 80/08/29, Ip
- --8009030623 LER 80-071/01T-0 on 800818, review per IE 8ulletin 79-018 indicated info inadequate to demonstrate environ qualification of signal processors Operators alerted to possible erroneous indication from processors CARTWRIGHT, W R Virginia Electric & Power Co 80/08/29 29p
- 8009090499 Forwards LER 80-074/03L-0 CARTWRIGHT.W R Virginia Electric & Power Co 80/09/03 ip
- --8009090512 LER 80-074/03L-0 on B00810, w/unit in Mode 1. axial flux difference deviated greater than 5% from target & quadrant power tilt ratio exceeded 1 02 Caused by xenon transient during & after load reduction CARTWRIGHT, W R Virginia Electric & Power Co 80/09/03 2pp
- 8009090541 Forwards LER 80-065/03L-0
  GARTHRIGHT:W R Virginia Electric & Power Co 80/09/05 lp.

- 8009220243 Forwards LER 80-067/03X-1 CARTWRIGHT,W R Virginia Electric & Power Co 80/09/16 1p
- --8009220324 LER 80-067/03X-1 on 800724 mitigation sys leak theck was not performed within 92-day surveillance interval Caused by lack of proper maint repts issued to operations dept Logging process altered to allow timely notice to applicable dept CARTHRIGHT, W.R. Virginia Electric & Power Co. 80/09/16 2pp
- E009220251 Forwards LER 80-073/03L-0 CARTWRIGHT.W R Virginia Electric & Power Co 80/09/16 ip
- --8009220306 LER 80-073/03L-0 on 800818, operability of one low head mafety injection sys was compromised when MOV-1863A valve was de-energized Caused by need to rework weld on leaking drain valve Weld reworked & tested satisfactorily CARTWRIGHT.W R Virginia Electric & Power Co 80/09/16 2pp
- 8009220369 Forwards LER 80-076/03L-0 CARTW919HT,W R Virginia Electric & Power Co 80/09/16 ip
- ---8009220373 LER 80-076/03L-0 on 800820 w/unit in Mode 1, discovered that casing cooling pump 1~R8-P-3A test had not met acceptance criteria Caused by personnel failure to notice that differential pressure was above acceptable limits CARTHRIGHT, W R Virginia Electric & Power Co 80/09/16 2pp
- 8009230505 Forwards LER 80~075/03L-0 CARTHRIGHT, H R Virginia Electric & Power Co 80/09/18 1p
- ---9009230613 LER 80-075/03L-0 on 800904, in Mode I at 100% power, sample analysis of SI accumulator 1B revealed excessive boron concentration Caused by stratification of stagnant solution in accumulator Concentration diluted CARTWRIGHT, W R Virginia Electric & Power Co 80/09/18 2pp
- 8009230622 Forwards LER 80-077/03L-0 CARTWRIGHT,W R. Virginia Electric & Power Co 80/09/18 1p
- --8007230636 LER 80-077/03L-0 on 800821, performing ECCS valve position verification, incorrect valve alignment affecting both LHSI pump min flow recirculation paths discovered Cause relates to change in RWAT flow path alignment to reduce temp CARTHRIGHT, W R Virginia Electric & Power Co 80/09/18 2pp
- TINU , WDITATE STUDY ANNA HTROM FEE-OZ TENDO
- D #RC Draft/Final Environmental Statements, supple & correspondence
- 8009150923 FES for facility + Office of Nuclear Reactor Regulation, Director NUREG-0134 ADD 2 80/08/31 53pp Available at NTIS \$3.25
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- B009110505 BER for facility, Suppl 12 # Office of Nuclear Reactor Regulation, Director NUREG-0053 B12, B0/08/31 9pp Available at NTIS \$1 75
- 8009240636 Forwards Suppl 12 to SER, addressing issue of emergency preparedness W/o encl YOUNOBLOOD, B J Licensing Branch 1 80/09/08 3pp
- F Security, medical, emergency & fire protection plans
- BO09230273 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency O'REILLY, J P Region 2. Atlanta, Office of the Director BO/08/22 to
- 8009300056 Summary of 800812 meeting w/util.State of VA & FEMA in Bethesda.MD re discussion of joint emergency plan exercise at plant site DROMERICK, A W Licensing Branch 1 80/09/12 4pp
- 8009230320 Forwards revised nuclear security personnel training & qualification program Program withheld (ref 10CFR2 790)
  BYLVIA.B R. Virginia Electric & Power Co 80/09/19 1p

- 8009260182 Requests extension of 30 days to respond to 800804 request that emergency plan be revised Request is based on scope of revision & internal review required SYLVIA, B R Virginia Electric & Power Co 80/09/22 ip
- G Adjudicatory correspondence
- 8007£30629 Advises of changes to Station Settlement Procedure 1-PT-111 per ALAB-578 Settlement monitoring Points 11, 12, 13 % 14 % all reference to Units 3 % 4 svc water pump house have been deleted SYLVIA, N R Virginia Electric & Power Co 80/07/19 1p
- H General correspondence
- 8009220033 Responds to 800805 request to reconsider decision to delay startup of facility NRC has not decided to delay issuance of full power OL License will be issued upon completion & FEMA approval of emergency preparedness exercise
  INGRAM, F Office of Public Affairs 80/08/13 1p
- --8009220037 Urges reconsideration of decision to delay facility startup Danger of nuclear accident extremely small Alternatives present greater risk BANDORTH.C S Affiliation Unknown 80/08/05 ip
- 8009090436 Responds to encl Hotetourt County Chamber of Commerce 800626 request to FERC for info re when facilities will be operational Lists status of plant operating schedules DEMION, H R Office of Nuclear Reactor Regulation, Director 80/09/05 3pp
- J Insurance & indomnity information
- 8009090384 Forwards Endorsement 1 to NeLIA Binder E8-70 ANDREMS.C L Marsh 8 McLennan.Inc , M & M Nuclear Consultants,Inc Div 80/09/03 2pp
- P Operating license stage documents & correspondence
- 800908008D Forwards draft NUREG-0676, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl W/o NUREG EISENHUT, D Q Division of Licensing 60/08/01 119pp
- 8009090330 Responds to 800802 telcon re Commission decision to defer issuance of full power license Review of SER found emergency preparedness matters not completed License & Tech Specs were still being madified for review AHEARNE.J F Commission 80/08/08 2pp
- --8009090333 Requests that Commission reconsider NRC staff recommendation that util be permitted to operate facility Test of emergency evacuation procedures scheduled for 800816
  DALTON-JN Virginia, State of 80/08/02 2pp
- 8009090346 Responds to 800801 telcon re Commission decision to defer issuance of full power license Review of SER found emergency preparedness matter not completed License & Tech Specs were still being modified for review AHEARKE, J. F. Commission 89/08/08 2pp
- --8009090347 Requests that Commission reconsider 800731 action denying util permission to begin commercial operation of facility NALSKE, C. Atomic Industrial Forum. 80/08/01 1p
- 8009050192 Forwards Amend 2 to License NPF-7, safety evaluation & notice of issuance & availability YOUNGBLOOD, B J Licensing Branch 1 80/08/18 3pp
- --8009050196 Amend 2 to License NPF-7 permitting conduct of water hammer domainstration test YOUNGBLOOM, 8 J Licensing Branch 1 80/08/18 2pp
- --8009050201 Bafety evaluation supporting Amend 2 to License NPF-7

  # Office of Nuclear Reactor Regulation, Director 80/08/18 3pp
- --B009050204 Notice of issuance & availability of Amend 2 to License RMF-7 YOUNGELOOD, B J Licensing Branch 1 80/08/18 Rpp
- 8009140454 Forwards License NPF-7 w/App A to Tech Specs,FR notice & NUREO-064 EISENBUT, D 0 Division of Licensing 80/08/21 3pp

- --8009160657 License NPF-7 for facility authorizing operation at 1007 gauer DENTON,H R Office of Nuclear Reactor Regulation, Director 80/08/21 13pp
- --8009160859 Notice of issuance of License NPF-7 for operation at 100% power YOW/GSLOOD, B. J. Licensing Branch 1 80/08/21 2pp
- --8009160661 Revision 1 to facility Tech Specs.App A to License NPF-7 Assistant Director for Operating Reactors NUREO-0664 R1 80/08/31 420pp Available at 6PD 49 00
- --8007160663 ETS (radiological & nonradiological).App A to License NPF-7 \* Assistant Director for Operating Reactors NUREG-0664 RI 80/08/31 59pp
- 8009090863 Advises that util met NRC requirements by completion of Condition 2 C (5) to License NPF-7, dtd 800921 Matter EISENHUT, D.G. Division of Licensing 80/08/22 3pp
- 8009030426 Requests amend to OLs consisting of changes to Tech Specs & to ETS Proposed changes encl FERGUSON, J H Verginia Electric & Power Co 80/08/28 4pp
- --8009030428 Proposed Tech Spac & ETS changes transferring independent review responsibility from existing Sys Nuclear Safety Operating Committee to Safety Evaluation & Control staff & Virginia Electric & Power Co 80/08/28 44pp
- 8007070344 Application to amend Licenses NPF-4 & NPF-7, transferring independent review responsibility from sys nuclear safety & operating committee to safety evaluation & control staff & audit responsibility to 6A dept Received w/o encl check FERGUSGN, J H Virginia Electric & Power Co 60/08/28 4pp
- ~~8009070347 Proposed Tech Spec changes to Section 6 transferring independent review responsibility from sys safety & operating committee to safety evaluation & control staff & audit responsibility to GA dept

  \* Virginia Electric & Power Co 80/08/28 35pp
- --8009090352 Proposed ETS change to Section 5, transferring independent review responsibility from sys safety & operating committee to safety evaluation & control staff & audit responsibility to QA dept

  4 Virginia Electric & Power Co 60/08/28 9pp
- 8009190658 Notification of rescheduled 800909-10 meeting w/util at site to discuss pump & valve inservice testing Meeting originally scheduled 800826-27 DROMERICK, A W Licensing Branch 1 80/08/20 4pp
- 8009110868 "North Anna Power Station Unit 2 Tech Specs.App A to # Commission NUREO-0664 R1 80/08/31 250ss
- 8009080394 Forwards 38 detailed support drawings for pipe supports installed on low head safety injection discharge piping shown on 12090-MSK-104B-5, for use in performing independent verification of SXW pipe stress analysis SYLVIA, B R Virginia Electric & Power Co 80/09/02 39pp
- 8009090640 Forwards questions & comments re pumps & valves inservice testing program to be used as basis for 800909-10 meeting agenda
  Agenda
  TEDESCO, R L Assistant Director for Licensing 80/09/05
- 8009150319 Notifies that facility is operating at 30% power Neutron shield test completed b levels are lower than expected Plant will be operating at 50% power by 800911 YOUNGBLOOD, B. J. Licensing Branch i 80709711 ip
- 8009260529 Requests analysis of precision obtainable from direct measurement sys for syc water pape expansion joints as compared w/existing indirect sys & cost estimate for implementation NOVAK.T M Assistant Director for Operating Reactors 80/09/1 Assistant Director for Operating Reactors 80/09/12
- 8009190525 Submits info re maintaining min of 23 ft of water over reactor vessel flange during fuel movement, in response to NRC 800815 ltr Changes to Tech Specs to include RHR sqs requirements identified in NRC 800611 ltr being reviewed. SYLVIA, B R Virginia Electric & Power Co 80/09/16 2pp

- 8009223134 Forwards comments on NUREG-0696 in response to NRC 800801 request Emplementation of requirements according to time schedule not considered feasible Requests meeting to discuss preliminary plan re effective emergency response facilities FERGUSON. J H Virginia Electric & Power Co 80/09/18 1app
- 8009270490 Forwards Pages 3/4 4-4 & 3/4 4-5 of Tech Specs to substitute sections incorrectly numbered YOUNG.B J Licensing Brench 1 80/09/19 2pp
- --8009290496 Corrected pages incorporting corrected Sections
  3 4 1 4.4 4 1 3 1-4.3 4 1 5.3 4 2 % 4 4 2 of Tech Specs reboren concentrations

  \* Licensing Branch 1 80/09/19 4pp
- G Inspection reports, 1E Bulletins & correspondence
- 8009100056 Forwards IE Bulletin 80-18. "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Written response required O'REILLY. J F Region 2. Atlanta, Office of the Director 80/07/24
- 8009020242 Submits response to IE Bulletin 79-03A For North Anna.no EA-312 of A-312. Type 300 series fusion welded pipe in use at greater than 857 design stress For Surry, eight fittings determined in excess of 85% design stress SYLVIA.B R Virginia Electric & Power Co 80/08/08 2pp
- 8009030141 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Morcury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Rec Region 2, Atlanta, Office of the Director 80/08/15
- 8009160172 Forwards IE Circular 80-18, "10CFRSO 59 Bafety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22
- B009120031 Responds to IE Builetin 80-19 Surry Units 1 & 2 do not use mercury-wested relays in reactor protection sys No response for North Anna Units 1 & 2 SYLVIA, B R. Virginia Electric & Power Co. 80/08/27 2pp
- 8009120314 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DUN 6008 Circuit Breakers " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/27
- 8009240399 Forwards response to IE Bulletin 80-19 re possible loss of emergency notification sys w/loss of offsite power Design change initiated to change power supply to vital bus administrative Procedure 29.6 revised Affidavit encl SYLVIA, B R Virginia Electric & Power Co 80/09/09 3pp
- 8009240517 Forwards IE Circular 80-21. "Regualtion of Refueling Crews " No written response required G'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/10
- 8009150257 Forwards response to NRC 800820 ltr re violations noted in IE Insp Repts 50-338/80-29 & 50-339/80-28 Corrective actions specific instructions given to control room operators re when to place channel in tripped condition SYLVIA.B R Virginia Electric & Power Co 80/09/12
- BC09300114 Forwards response to IE Bulletin 80-20 Westinghouse Type W-2 control switch applications found Subj switches have been tested satisfactorily BYLVIA.B R Virginia Electric & Power Co 80/09/15 3pp
- R Periodic operating reports & related correspondence
- 8007050327 Forwards "Radioactive Effluent Release Rept for North Anna Power Station:" Jan June 1980 SYLVIA:8 R Virginia Electric & Power Co 80/09/02 12p
- ---B009050333 "Radioactive Effluent Release Rept for North Anna Power Station: "Jan-June 1980 GILBERT.J D. HOPPER.D M., CARTHRIGHT.W R Virginia Electric & Power Co 80/09/02 225pp
- BO09290317 Forwards monthly operating repts for Aug 1780 BYLVIA:B R Virginia Electric & Power Co 80/09/15

- --BOO9290321 Monthly operating repts for Aug 1980
  WBODSMALL, W A . NEUFER, A G Virginia Electric & Power Co
  80/09/09 9pp
- 8009230356 Forwards corrections to monthly operating repts for Aug 1980 SYLVIA, B.R. Virginia Electric & Power Co. 80/09/17 ip
- --8009230360 Corrected operating repts for Aug 1980 NEUFER/A 9 Virginia Electric & Power Co 80/09/09 2pp
- S Reportable occurrences. LERs & related correspondence
- BO09030567 Forwards LER 80-043/03L-0
  CARTHRIGHT & Virginia Electric & Power Co 80/08/27 ip
- --800903057; LER 80-043/03L-0 on 800814, during Mode 5 operation, pressurizer power relief valve declared inoperable when nitrogen gas supply required for overpressure protection dropped below 1,775 psig Caused by low nitrogen pressure CARTWRIGHT,W R Virginia Electric 3 Power Ca 80/08/27 2pp
- E009030576 Forwards LER 80-044/03L-0 CARTH9[0H], W R Virginia Electric & Power Co 80/08/27 1p
- --BOO9030586 LER BO-D44/031-0 on BO0730 during Mode 2 generation at 3% power bypass feedwater regulator valve failed open causing high water level in steam generator A Caused by valve operator failure possibly caused by water in air line CARTHRIOHT.W R Virginia Electric & Power Co BO/08/27 2pp
- 8009030593 Forwards LER 80-046/03L-0 CARTHRIGHT, W R Virginia Electric & Power Co 80/08/27 1p
- --8009030408 LER 80-046/03L-0 on 800818, while heating in Mode 3 operation, position indication for control rod 0-9 greater than 12 steps from demand position Caused by voltage drift in signal conditioning card Recalibr & functional test done CARTWRIGHT, W R Virginia Electric & Power Co 80/08/27 App
- 8009030615 Forwards LER 80-045/03L-0 CARTURIGHT, UR Virginia Electric & Power Co 80/08/27. 1p
- --8009030419 LER 80-045/03L-0 on 800803 during RCS cooldown control room operator observed greater than 12 step deviation between rod indicator & demand indicator Caused by instrument drift Rad position indicator recalibr CARTHRIGHT.W R Virginia Electric & Power Co 80/08/27 2pp
- 8009090538 Forwards LER 80-037/03L-0 CARTHRIGHT, W R Virginia Electric & Power Co 80/09/05 ip
- --8009090584 LER 80-037/03L-0 on 800807, during Mode 3 operation, sample analysis indicated high boron concentration in SI accumulators A & C Caused by stratification of boric acid in makeup source or accumulators
  CARTHROOHT, W R Virginia Electric & Power Co 80/09/05 2pp
- SCOP180412 Forwards LER 80-052/03L-0 CARTWRIGHT, W R Vinginia Electric & Power Co 80/09/12 1p
- --8009180417 LER 80-052/03L-0 on 800823, w/unit at 4% power, C main steam trip valve would not fully close using train A close pushbutton Caused by solenoid operated valve in instrument air line to trip valve stuck in open position CARTWRIGHT, W R Virginia Electric & Power Co 80/09/12 3pp
- EOO9220239 Forwards LER 80-049/03L-0 CARTWRIGHT, W R Virginia Electric & Power Co. 80/09/16 1p
- --BO09220319 LER 80-049/03L-0 on 800822, operating in Mode 2 at 3% power, loops A & C channel tour steam/flow bistables were tripped to allow mod to condensate pots Upon return to svc, A failed high Caused by instrument drift & improper valve lineup CARTWRIOHT, W R Virginia Electric & Power Co 80/09/16 2pp.
- BOO9220241 Forwards LER 60-051/03L-0 CARTWRIGHT,W R Virginia Electric & Power Co 80/09/16 ip
- --8009220315 LER 80-051/03L-0 on 800821. W/unit in Mode 2.C feedline containment isolation check valve 2-FW-126 did not meet post maint valve cycling test requirements Caused by failure of valve to shut completely due to burr on pivot pin bushing \* Virginia Electric 1 Power Co 80/09/16 3pp

- 8009220395 Forwards LER 80-053/03L-0 CARTWRIGHT, W R Virginia Electric & Power Co 80/09/16 1p
- --B009220360 LER 80-053/03L-0 on B00625 during Mode 1 operation. C steam time flow Channel 4 indicated low & channel placed in trip condition Caused by instrument drift Channel recallor & returned to syc Capswallor N R Virolnia Flectric & Power Co. 80/09/16 2pp
- 8009230589 Forwards LER 80 048/03L-0 CARTWR16HF, W R Virginia Electric & Power Co 80/09/16 1p
- --8009230600 LER 80-048/03L-0 on 800828, performing inspitechnicians discovered feed flow square root comparator card out of calibr Cause undetermined Card recalible testurned to svo CARTHRIGHT, W.R. Virginia Electric & Pawor Co. 80/09/16 2pp
- BOOY230594 Forwards LER 80-047/03L-0 CARTWR1GHT, W R Virginia Electric & Power Co BO/09/18 1p
- ---9009230577 LER 80-04//03L-0 on 800819; in Mode 2 at 3% power, steam flow indications on loops A.B & C gave erroneous readings Caused by design deficiency in pressure sensing sys of ventur) in main steam line Engineering study & design mod carried out CARTWRIGHT.W R Virginia Electric & Power Co 80/09/18 2pp
- T Hearing transcripts on non-antitrust matters
- 800910018 Transcript of 800820 meeting in Washington DC to discuss full power license Pp 1-90 M/supporting documentation # Commission 80/08/20 57pp
- U Congressional/Executive Correspondence
- 800909033B Responds to 800809 ltr re Commission decision to defer issuance of full power license Review of SER found emergency preparedness matters not completed License & Tech Specs were still being modified for review AMEARNE, J F Commission 80/08/11 2pp
- DOCKET 50-340 BEABROOK NUCLEAR STATION. UNIT 1
- A Application/construction stage documents & correspondence
- 80070B00B0 Forwards draft NUREO-0676, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NURCO-0676 encl W.a. NUREO EISENHUT.D O Division of Licensing 80/08/01 119pp
- POCKET 90-341 ENRICO FERMI ATOMIC POHER PLANT, UNIT 2

  A Application/construction stage documents? correspondence
- 8007080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl N/A NUREO EISENHUT, D & Division of Licensing 80/08/01 119pp
- 8009120690 Forwards "Mark I Containment Long-Term Program BCH, Resolution of Generic Technical Activity A-7." HUREO-0661 M/o encl SCHMENCER, A Licensing Branch 2 B0/08/20 2pp
- 8007030602 Submits response to 800711 ltr requesting estimate for const completion date Util currently estimates latest fuel load date for plant to be Nov 1982 Roview of plant 1974 CL application should resume w/publishing of SFR by Har 1981 TAUSER.H Detroit Edison Co 80/08/26 Zpp
- 8007260991 Notifies of 801007 proposed date to review whether OBC & BRV responses should be considered separately or combined during ASME code fatigue calculations GC selected samples to emphasize highly fatigued components WILSON, J.N. Assistant Director for Licensing 80/09/15 9pp
- 8009240502 Forwards Amend 30 to application for licenses & Amend 30 to FBAR, including drawings & calculations requested by NRC THOMAS, E.B. LeBosuf, Lamb, Leiby & MacRae 80/09/22 ip

- --8009240507 Amend 30 to application for license for purpose of transmitting addl info requested by NRC Hilbel. C K Detroit Edison Co 80/09/18 2pp
- --8009240509 Amend 30 to FSAR
  \* Detroit Edison Co 80/09/30 50pp
- --8009240513 Drawings & calculations requested by NRC. submitted in conjunction w/Amend 30 to FSAR

  \* Detroit Edison Ca 80/09/22 275pp
- H Congrat correspondence
- BO07110280 Responds to 800728 itr requesting info re safety of Midland b Fermi plants All nuclear plants subj to enhanced safety requirements resulting from TM Lessons Learned Task Force recommendations Supporting documentation encil DIRCKS U.V. Office of the Elecutive Director for Operations 24pp
- ~-8009110288 Requests consideration of encl MC Haight ltr re mafety of Midland & Ferms plants

  RRGMMFFFLD,WS House of Rep , Foreign Affairs 80/07/28 2pp
- ) Financial information
- 8009220013 Discusses impact of licensing re-merging of two cooperatives that together own 20% of facility Action will have no significant impact on licensing procedure KININERAL Licensing Branch 2 80/08/25 1p
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8009240502 Forwards Amend 30 to application for licenses & Amend 30 to FSAR, including drawings & calculations requested by NRC THOMAS, E. 3 LeBoeuf, Lamb. Leiby & MacRae 80/09/22 ip
- --8009240509 Amend 30 to FSAR \* Detroit Edison Co BO/09/30 50pp
- --8007240513 Drawings & calculations requested by NRC, submitted in conjunction w/Amend 30 to FSAR

  \* Detroit Edison Co 80/09/22 275pp
- M Antitrust correspondence
- 8009260058 Forwards notice of receipt of OL application & request for antitrust info
  SCHWENGER, A Licensing Branch 2 80/08/27 2pp
- --8009260063 Notice of receipt of OL application & request for antitrust SCHWENCER, A Licensing Branch 2 80/08/27 2pp
- Q Inspection reports, IE Bulletins 5 correspondence
- 8009090029 Forwards IE Sulletin 80-07. Suppl 1. "BWR Jet Pump Assembly KEPPLER, J G Region B. Chicago, Office of the Director 80/05/14
- 8009030198 Forwards Revision I to IE Bulletin 80-19. "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sigs of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/08/15
- 8009150477 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain QE BMR Facilities " No specific action or response requested
  KEPPLER, J G Region 3. Chicago, Office of the Director 80/08/20
- 8009120046 Forwards Suppl 3 to IE Sulletin 80-17. "Failure of Control Rods to Insert During Scram at BNR " No written response ROBER OF RESIDENCE OF THE DIRECTOR OF THE DIRE
- 3009170426 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response EPPLER, J G Region 3, Chicago, Office of the Director 80/08/22

- E009180016 Responds to IE Bulletin 79-03A re longitudinal weld defects in ASME SA-312 Type 304 stainless steel pipe apools Manufacturer review, util results & description of corrective action will be submitted by 800915
- 800918002? Requests extension until 801001 to respond to IE Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters Required analysis complex bestensive HINES.E Detroit Edison Co 80/08/26 ip
- 8009230072 Forwards IE Info Notice 80-31, 'Maloperation of Gould-Brown Bover: 460 Volt Type K-600S & K-DON 600S Circuit Breakers " No written response required KEPPLER.J G Region 3, Chicago Office of the Director 80/08/28
- 8009090417 Submits revision to 800513 ltr which responded to IE Bulletin 80-02. "Inadequate QA for Nuclear Supplied Equipment "Provides reasons for accepting statements re GA/GC program as basis for judging equipment integrity HINES,E Detroit Edison Ca 80/09/04 3pp
- 8009250446 Revises 800513 response to 1E Bulletin 80-02, "Inadequate QA for Nuclear Supplied Equipment" Thermal feedwater steeves were fabricated under properly controlled QA program HINFS,E Detroit Edison Co 80/09/04
- 8009240101 Forwards IE Circular 80-21, "Regulation of Refueling Crews" NOVEMBER 1 PERSONSE required

  KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/10
- S Reportable occurrences, LERs & related correspondence
- 8009040455 Interim deficiency rept re Agastat relay bases Different model relay mounting base has been ordered Evaluation of QE proposal to modify relay bases is continuing Final rept will be submitted by 801006 FAHRNER.
- 8009140417 Folkowup to final deficiency rept re design inadequacy of QA relief valves w/insufficient capacity to limit pressure in event of reducing valve failure & discharge blockage Cause not stated Design mods underway to replace valves FAHRNER, II J Detroit Edison Ca 80/09/05 3pp
- 8007270055 Ack receipt of 800805 interim deficiency rept re Agastat relay base problem Final rept awaited for review FIORELLI, Q Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/10 ip
- DOCKET 50-344 TROJAN NUCLEAR PLANT, PORTLAND GENERAL ELECTRIC
- F Security, medical, emergency & fire protection plans
- 8009110616 Requests participation in study of people-related problems in nuclear safeguards Study involves collection of data on licensee security forces & practices EISENHUT, D G Division of Licensing 80/07/25 2pp
- 8007030327 Notifies of 800819,22 & 30 regional workshops re development of guidance for acceptable method for coping w/amergencies Requests that representative be sent Discussion will include function of facilities & location ENGELMEUR H Region 5. San Francisco. Office of the Director 80/08/12 2pp
- 8009230339 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network. Sys installed for govt use during emergency ENSELKEN.R H Region 5. San Francisco, Office of the Director. 80/08/22 3pp
- 8009100509 Forwards safeguards info re security plan Info withheld (ref 100FR2 790)

  ©UODWIN,C Portland General Electric Co 80/09/04 ip
- Q Adjudicatory correspondence
- B007020054 Order charifying ABLB B00711 initial decision re control bldg mods Provisions of PGE-1020 through Revision 4 & PG&E Exhibit 27 will be solely imposed as license conditions All other matt will become part of amended FBAR MILLER.ME Atomic Bafety and Licensing Board Fanel 80/08/27

- 8009040263 Order granting extension until 800909 for Commission to raview Director's decision under 100FR2 206 CHILK-S J Office of the Secretary of the Commission 80/08/29
- B009190308 Forwards order requiring into supporting environ qualification of safety-related electrical equipment Requests submittal of info B01101 CLARK.R A Operating Reactors Branch 3 80/08/29 2pp
- --800919031: Order for mod of License NPF-1 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101
  EISENHUT, D. G. Division of Licensing 80/08/29 App
- B009180010 Order adhering to ASLB 800711 initial decision which rejected State of OR proposed license conditions reaccelerated reporting MILLER.M E Atomic Bafety and Licensing Board Panel 80/09/04
- 8009090252 Advises that NRC will not file exceptions to ASLB 800711 initial decision, per ASLB 800827 clarifying order ORAY, J R Hearing Branch 1 80/09/05 1p
- 8009110011 Certifies svc of LER 80-017/03L-0 w/related correspondence, upon parties in proceeding on 800905 MCCARREL 8 F Portland General Electric Co 80/09/05 2pp
- 8007120244 Order granting extension until 800730 for Commission to review Director's decision under 10CFR2 206, DD-80-26 CHILK, S. J. Office of the Secretary of the Commission 80/09/07
- 8009190189 Order extending until 800929 time for State of DR to either withdraw exceptions to ASLB 800711 decision, amend exceptions in light of ruling or notify ABLAB of intent to proceed w/appeal on basis of exceptions as now formulated BISHOP, C J Atomic Safety and Licensing Appeal Panel 80/09/15 2pp
- 8009290452 Informs Commission of Director's denial resuspension of plant operations in light of volcanic activity at Mount 8t Helens Recommends effects of activity on evacuation be considered in conjunction w/required emergency planning MALSCH.M 9 Office of the General Counsel SECY-A-80-130 80/09/15 44pp
- 9009300566 Amended exceptions to initial decision re license conditions & to ASLB order re State of OR motion for reconsideration Accelerated reporting of design changes & completion of seismic evaluation must be imposed Certificate of Svc encl OSTRANDER, F W Oregon, State of 80/09/23 5pp

### H General correspondence

- BOO9110389 Requests that facility be closed & defueled Eruptions from Mount Baint Helens would make moving out of area impossible if nuclear accident should occur SNOW.C A Affiliation Unknown BO/07/29 ip
- J Insurance ₺ indemnity information
- 8009190501 Forwards Endorsements 41 & 34 to ANI & MAELU Policies NF-225 b MF-86 respectively HILBON F R Portland General Electric Co 80/08/04 3pp
- P Operating license stage documents & correspondence
- 8G09020297 Submits interim criteria for shift staffing to all OL & CP licenses & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work. Development & implementation to be reviewed within 90 days EISENHUT.D G. Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREQ-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISEMHUT.D O Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Pravious determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D G Division of Licensing 80/08/07 60pp

- 8009190794 Forwards revised Westinghouse STS 3 9 8 2,3 9 10 & Bases 3/4 9 8 & 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Whitten response required NDVAK.T M Assistant Director for Operating Reactors 80/08/[5]
- --8009190B17 Revised Westinghouse STS 3 9 8 2.3 9 10 & Bases 3/4 9 B & 3/4 9 10 requiring 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods
  - \* Assistant Director for Operating Reactors 80/06/23 21pp
- 8009020039 Advises that finite element analyses performed by Bechtel have been completed Refined displacement multiplication factors are at or below 800628 criteria Summary of results encl
  BROEHL.D J Portland General Electric Co 80/08/20 3pp
- 8009090823 Summary of 800825 meeting u/util in Portland.OR re effect of volcanic activity at Mount St Helens on plant TRAMMELL.C M Operating Reactors Branch 3 80/08/25 34pp
- 8009150385 Responds to NRC 800815 ltr re making revisions to Tech Specs assuring water level requirements during Mode 6 Current procedures require min of 10 ft of water above fuel assembly during transfer GOODMIN.C Portland General Electric Co 80/09/10 1p
- 8007260032 Advises that util response re ECCS evaluation models, dealing w/fuel cladding swelling & incidence of rupture, is acceptable CLARK,R A Operating Reactors Branch 3 80/07/10 2pp
- 8009180468 Advises that license change application re implementation of TMI-2 Lessons Learned requirements uill be submitted by
- GOODWIN.C Portland General Electric Co 80/09/12 1p
- 8009220363 Provides addl info in response to NRC 800723 ltr re relationship of recent volcanic activity at Mount St Helens to facility Info addresses NRC Questions 361 t.2 % 3 Encl maps available in Central Files unly GODDWIN.C Portland General Electric Co 80/09/15 13pp
- 8009290117 Notification of 800925 meeting w/util & Westinghouse in Bathesda, MD to discuss hab examination results of steam generator U-bend samples TRAMMSLL, C M Operating Reactors Branch 3 80/09/16 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 8009020244 Forwards IE Insp Rept 50-344/80-14 on 800602-30 No noncompliance noted CREMB, J.L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/07/22 2pp
- --8009020251 IE Insp Rept 50-344/B0-14 on 800502-30 No noncompliance noted Major areas inspected plant operations, maint, surveillance testing, physical security, procurement, emergency preparedness & LER followup MALMROS, M H, JOHNSTON, G W, Region 5, San Francisco, Office of the Director STERNBERO, D M, Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/07/22 5pp
- BO09260300 Forwards IE Info Notice 80-27, "Broken Studs on Terry Turbine Steam Inlet Flange " No written response required ENBELKEN.R H Region 5, San Francisco. Difice of the Director BO089707 10
- 8009140620 Responds to IE Bulleton 79-00A. "Longitudinal Neld Defects in ABM& SA-312. Type 304 Stainless Steel Pipe" No subj pipe at faculity subjected to design stress greater than 85% of code allowable stress COUDMIN.C Portland Ceneral Electric Co 80/08/09 2pp
- 8009150009 Updates 800603 response to IE Bulletin 80-08 re containment penetration welds Still unable to locate documentation for 11 welds Independent checks indicate groper radiography procedures followed Welds to be resealing papied 8 pring 1981 GOODWIN.C Portland Ceneral Electric Co 80/08/14 1p
- 8000150059 Supple response to IE Sulletin 80-05 re vacuum protection measures for all sys that contain primary water Licensee 800609 ltr outlined commitment to provide locking & warning on valves w/o redundant sys fanks have redundant protection 60000WIN.C Portland General Electric Co 80/08/14 2pp

- 8009250337 Responds to IE Bulletin 80-15 re possible loss of emergency notification sys(ENB) w/loss of offsite power Sys powered from telephone company Emergency power supplies consist of set of battories 5 dc diesel generator SOUDWIN.C Portland General Electric Co 80/08/14 Spp
- 8009030290 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/09/15 1p
- 8007270404 Forwards IE Info Notice 80-27, 'Degradation of Reactor Coolant Pump Stude " ENGELKEN,R H Region S, San Francisco, Office of the Director 80/08/18 4pp
- 8009160183 Forwards IE Circular BO-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ENGELKEILR H Region 5, San Francisco, Office of the Director
- 8009240375 Updates 800702 response to IE Bulletin 80-08, re containment liner penetration wolds Documentation found for welds identified in Table 1 as Items 1.51 & 74 Unable to tocate documentation for 11 welds GOUDWIN.C Portland General Electric Co 80/08/25 ip
- 8009120460 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6005 Circuit Broakers " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/08/27 lp
- 8009110308 Forwards, "Environ Qualification of Electrical Equipment, Master List," Revision K per 800114 IE Bulletin 77-01B réquirements & 800827 order for license mod Encl available in Contral Files only GOODWIN.C Portland General Electric Co 80/09/05 2pp
- 8007300312 Ack receipt of 800822 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-344/80-17 BOSK:H & Region 5. Ban Francisco, Fuel Facility & Materials Safety Branch 80/07/12 ip
- --8009300314 Responds to NRC 800806 ltr re violations noted in IE Insp Rept 50-344/80-17 Corrective actions procedure implemented requiring checklist be used during insp of drums prior to shipment to verify proper labeling 6000MIN, C Portland General Electric Co 80/08/22 3pp
- --B009300318 Forwards IE Insp Rept S0-344/80-17 on 800619 & notice of violation B00K,H E Region 5. San Francisco. Fuel Facility & Materials Safety Branch 80/08/06 2pp
- --8009300319 Notice of violation from insp on 800619 \* Region 5. Sam Francisco. Office of the Director 80/08/05 28a
- --8009300324 IE Insp Rept 50-344/80-17 on 800619 Noncompliance noted failure to mark two drums "Radioactive-LSA" & one container appeared to fail requirement of strong tight package FONO.T. WENSLAMSKI.F.A. Region 5. San Francisco. Office of the Director StOK.H.E. Region 5. San Francisco. Fuel Facility & Materials Safety Branch 80/08/05 7pp
- R Periodic operating reports & related correspondence
- 8009030575 Forwards "Effluent & Maste Disposal Semiannual Rept.Jan-June 1980 " QGODMIN.C Portland General Electric Co 80/08/28 1p
- --8009030579 "Effluent & Waste Disposal Semiannual Rept. Jan-June 1980 " \* Portland General Electric Co 80/08/28 & 6pp
- 8009100239 Forwards monthly operating rept for Aug 1980, YUNDI. C.P., Portland General Electric Co. 80/09/02 1p
- --B009100242 Monthly operating rept for Aug 1980 BAIR-0 6 Portland General Electric Co. 80/09/02 Spp

- S Reportable occurrences, LERs & related correspondence
- 8009090410 RO on 800721, during Mode 1 monthly functional testing, found seismic monitoring sensor ST 6336 in cable apreading room not responding acceptably Caused by malfunction of seismic triaxial accelerometer ST 6336 Channel repaired YUNDT, C P Portland General Electric Co 80/08/28 2pp
- 8009190471 Forwards RD re seismic monitoring instrument being inoperable for period exceeding 30 days
  YUNOT,C P Portiand General Electric Co 80/08/28 ip
- --8009150475 RO on 800731, during monthly functional testing, seismic monitoring sensor ST 6336 did not respond acceptably Caused by seismic triaxial accelerometer in cable spreading room failure to functionally test Channel was repaired \* Portland General Electric Co 80/08/28 ip
- 8009260506 Forwards updated LER 80-005/01T-1 YUNDT, C.P. Portland General Electric Co. 80/08/29 ip
- --8007260510 Updated LER 80-005/01T-1 on 800411, main steam isolation valves did not fully close as required Caused by component failure Immediately freed up stems 5 cycle valves Permanent corrective action is under investigation PERRY, J C Portland General Electric Co 80/08/29 3pp
- E009170309 RO during 800910-1201, cable spreading room sprinkler fire suppression sys L will be inoperable during mod to three zoned deluge sys 20.21 & 22 Backup fire protection measures will be employed YURIOT, GP Portland General Electric Co 80/09/04 lp
- 8009100449 Forwards LER 80-017/03L-0
  BROEHL, D J Portland General Electric Co 80/09/05 ip
- --8009100453 Forwards RO-17 re inoperable containment spray pump room fan YUNDT.C P Portland General Electric Co 80/08/29 2pp
- ~~8009100461 RD 80-17 on 800803, one-inch conduit AB-4596, supplying power to MV252A fan for west containment spray pump room, damaged by concrete core drilling Drilling procedure changed to include voice communication between driller & observer \* Portland general Electric Co 80/08/29 ip
- --B009100467 LER 80-017/03L-O on B00803.during concrete core drilling, conduit damaged which supplied power to west containment spray power poom fan Fan rendered inoperable Caused by core drilling crew error Certificate of Svc encl
  PERRY.J C Portland General Electric Co 80/08/29 4pp.
- B007180379 Describes evaluations & followup actions re LERs

   80-005/017-0,80-009/03L-0 & 80-010/03L-0,in response to

   800728 ltr

   COCODMIN.C
   Portland General Electric Co
   80/09/05
   6pp
- 8009300471 RO followup to CP Yundt 800924 rept to M Malmros re high steam flow bistable trip setpoints incorrectly set but within limits of Tech Specs Occurrence will be reported to NRC as LER YUNDT, C P Portland General Electric Co 80/09/25 ip
- DOCKET 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1

  F Security, medical, smergency & fire protection plans
- B009230309 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency KEPPLER, J Q Region 3, Chicago, Office of the Director 90/08/22 3pp
- 8009120430 Forwards update re current status of fire protection upgrades at facility CROUSE.R P Toledo Edison Co 80/09/05 Spp
- O Adjudicatory correspondence
- 8009190572 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 REID.R W Operating Reactors Branch 4 80/08/29 2pp

- --BOO9190581 Order for mod of License NPF-3 to add info which fully responds to NRC request for info re environ qualification of safety-related plectrical aquipment Info should be submitted by 80:101 EISENHUI, DO Division of Licensing 80/08/29 App
- P Operating license stage documents & correspondence
- 8009150070 Responds to 800523 recommendations concerning lessons learned from 800226 transient at Crystal River Submits results of investigations ie use of atmospheric dump valve at Goonee Units 1-3.8 Unit 1, Davis-Besse Unit 1 & TMI-1 DENTON-H R Office of Nuclear Reactor Regulation. Director
- 8007020297 Submits interim criteria for shift staffing to all GL & CP litensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 70 days EISENHUT, D Q Division of Licensing 80/07/31 7pp
- 8009080090 Forwards draft NUREQ-0696. "Functional Criteria for Energency Response Facilities " Comments requested within 30 Jays Proposed implementation schedule for meeting criteria of NUREG-0696 enci Wo NUREG EISENBUT.D 0 Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action DOVERDODE Informs that exemption from few reliability activities associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D 0 Division of Cicensing 80/08/07 40pp
- BOO9030577 Informs of Class 3 fee requirement for review of fish tepingement study HILLER.H O License Fee Management Branch 80/08/14 Ip
- 8007070445 Requests Class III fee for Ofc of Nuclear Reactor Regulation review of util 800721 & 0804 submittals re RCS flow indication DIGOSIR M License Fee Management Branch 80/08/25 ip
- 8009300046 Forwards Amend 30 to License NPF-3, safety evaluation & notice of issuance & availability REID,R W Operating Reactors Branch 4 60/08/27 2pp
- --8009300052 Amend 30 to License NPF-3, deleting License Condition 2 C (3)(r) re-submittal of seismic reanalysis REID:R W Operating Reactors Branch 4 80/08/27 2pp
- --8009300033 Safety evaluation supporting Amend 30 to License NPF-3

   Office of Nuclear Reactor Regulation, Director 80/08/27
- --8007300057 Notice of issuance & availability of Amend 30 to License REID,R W Operating Reactors Branch 4 80/08/27 2pp
- 8009170145 Forwards corrected Tech Spec Page 3/4 5-4 issued on 800725 w/Amend 28 to DL RELO.R W Operating Reactors Branch 4 80/09/04 2pp
- --800919014B Corrected Tech Spec Page 3/4 5-4, originally issued 800725 # Operating Reactors Branch 4 80/09/04 2pp
- 8009100172 Forwards Well rept. "Evaluation of Instrumentation to Detect Inadequate Core Cooling Prepared for 177 Dwners Group" CROUSE:R P Toledo Edison Co 80/09/08 ip
- --B009100176 "Evaluation of Instrumentation to Detect Inadequate Core Cooling Prepared for 177 Owners Oroup " FROTH D J Babcock & Wilcox Co 80-1120838-00 80/08/15 2ipp
- 8009240346 Forwards Amend 31 to License NPF-3, safety evaluation & notice of (savance & availability REID. R H Operating Reactors Branch 4 80/09/08 2pp
- --8009260353 Amend 31 to License NPF-3/modifying containment purge & erhaust isolation valves & allowing plant in cold shutdown to heat up & operate at power w/valves inoperable REID.R W Operating Reactors Branch 4 80/09/08 7pp
- --8009260358 Safety evaluation supporting Amond 31 to License NPF-3.

  \*\* Operating Reactors Branch 4 60/09/08 2pp

- --8009260364 Notice of issuance & availability of Amend 31 to License REID:R W Operating Reactors Branch 4 80/09/08 2pp
- 8009250491 Informs of acceptability or response to NRC 791109 ltr reportions of ECCS evaluation models dealing w/fuel cladding swelling & incidence of rupture REID.R W Operating Reactors Branch 4 80/09/07 2pp
- 8007220297 Forwards application for amend of Licanse NPF-3, consisting of proposed Tech Spec Changes, in response to NRC 800702 ltr re TMI Lessons Learned Category A requirements CROJBE, R P Toledo Edison Co 80/09/16 ip
- --G009220301 Application for amend of License NPF-3 consisting of proposed Tech Spec changes supporting actions to satisfy TMI Lessons Learned Category A requirements CROUSE, R P Toledo Edison Cp 60/09/16 1p
- --8009220313 Proposed Tech Specs 1 2.3 3-3.3 3-11.4 3-2.3 3-10.4 3-10. 3 4 11.6 3 6 5.6 2-1.3/4 4 4.3/4 4 5.3/4 4 10 % 3 4 4 11 re safety features actuation sys instrumentation Made in response to TMI Lessons Learned Category A requirements 4 Toledo Edison Co 80/09/14 14pp
- G Inspection reports, IE Sulletins & correspondence
- 8009290019 Forwards IE Insp Rept 50-346/80-17 on 800604 No REPPLER J G Region 3, Chicago, Office of the Director 80/07/10
- --8009290020 IE Insp Rept 50-346/80-17 on 800604 No noncompliance soted Major areas inspected assessments of security (nsp findings & enforcement actions re 800430 personnel averexposure TAMBLINO T N Region 3. Chicago. Office of the Director REISHMAN.R F Region 3. Chicago. Reactor Operations Nuclear Support Brench 80/07/09 12pp
- 8009150504 Forward: IE Insp Rept 50-346/80-21 on 800708-09 No nancompliance noted FIGRELLIO Region 3, Chicago, Reactor Construction & Engineering Support Branch 90/07/28 Spp
- --8009150508 IE Insp Rept 50-346/80-21 on 800708-09 No nuncompliance noted Major areas inspected GA/GC program implementing procedures, work activities & IE Bulletin 77-17 & IE Bulletin 80-09 activities WARD, K D Region 3, Chicago, Office of the Director DANIELSON, D M Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/25 4pp
- 8007300238 Forwards IE Insp Rept 50-346/80-19 on 800616-20,23-27 & 30 & 0701-03 & 07-11 & notice of violation HEIGHMAN, R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/08/12 2pp
- ---8009300240 Notice of violation from insp on 800620.23-27 & 30 & 0701-03 & 07-11 \* Region 3, Chicago, Office of the Director 80/08/11 2pp
- --8009300243 IF Inso Rest 50-346/80-19 on 800420,23-27 & 30 & 0701-03 & 07-11 Noncompliance noted failure to keep log of events & to properly log locked valve position REYES,L A, WARNICK,R F Region 3, Chicago, Office of the Director BO/OB/11 lipp
- 8009150067 Forwards Revision i to 800403 response to IE Bulletin 79-018 Revision I supercodes initial response & provides addl evaluation work sheets re components subj to increased radiation from recirculating fluid following LOCA M/o encl CROUSE.R P Toledo Edison Co 80/08/14 3pp
- 8009030214 Forwards Revision ! to IE Bulletin 80~19, "Failures of Mercury-Welted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Hritten response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/08. Region 3, Chicago, Office of the Director 80/08/15
- 8009220176 Bubmits add1 info re IE Bulletin 79-14, "Seismic Analysis for As-Built Sefety-Related Piping Sys " Stress calculation on main steam line outside containment was calculated using proposed mod support sys instead of as-built configuration CROUSE.R P Toledo Edison Co 80/08/18 2pp
- 8009290097 Forwards 1E Insp Rept 50-346/80-22 on 800722-24 No noncompliance noted
  FIORELLI, Q Region 3, Chicago, Reactor Construction & Engineering
  Support Branch 80/08/19 2pp

- --8009270101 IE insp Rept 50-346/80-22 on 800722-24 No noncompliance noted Major areas inspected pipe whip restraint mod at hot leg risers, snubber installations, accessible area piping & procedure review YIM.1 T. BRICKLY, R H. DANIELSON, D H. Region G. Chicago, Office of the Director 80/08/18 7pp
- 8009260659 Forwards IE Insp Rept 50-346/80-24 on 800721-25 & notice of violation DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/08/20 2pp
- --8007260451 Notice of violation from insp on 800721-25 \* Region 3. Chicago. Office of the Director 80/08/18 1p
- --8009260665 IE insp Rept 50-346/80-24 on 800721-25 Noncompliance noted failure to report exceeding Tech Spec limiting operating condition & to perform sulfate monitoring at required interval PHILLIPS.M P., OESTHANN.M J. ESSIG.T H. Region 3, Chicago, Office of the Director 80/08/18 10pp
- 8009110504 Forwards response to IE Bulletin 80-15. "Possible Loss of Emergency Notification Sys (ENS) w/Loss of Offsite Power" Adequacy of emergency notification sys verified in 800625 util insp w/appropriate telephone company representative CRGUSE.R P Toledo Edison Co 80/08/22 3pp
- 8009170437 Forwards IE Circular 80-18, "10CFRSO 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/22
- 8009260097 Forwards 30-day response to Item 1 of IE Bulletin B0-17. Revision 1. "Failures of Mercury-Metted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E "No subj relays used CROUSE.R P Toledo Edison Co 80/08/26 2pp
- 8009230058 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover: 480 Volt Type K-6005 & K-DON 6005 Circuit Breakers" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/28
- 8009240|18 Forwards IE Circular 80-21, "Regulation of Refueling Crews " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/10
- R Periodic operating reports & related correspondence
- 8009080317 Furwards "Semiannual Radioactive Liquid & Gaseous Release Rept. Jan-June 1980 " MURRAY: T D Toledo Edison Co 80/08/21 1p
- ~-8007080317 "Semiannual Radioactive Liquid & Gaseous Release Rept Jan~ June 1980 " \* Toledo Edison Co 80/08/21 87pp
- )09150276 Forwards monthly operating rept for Aug 1980 MURRAY, T D  $\,$  Toledo Edison Co  $\,$  80/09/09  $\,$  1p  $\,$
- -8007150277 Monthly operating rept for Aug 1980-SARSOUR, B Toledo Edison Co 80/09/09 IApp
- Reportable occurrences, LERs & related correspondence
- 3009020333 Forwards LERs 80-055/03L-0,80-056/03L-0,80-057/03L-0 & 80-058/01T-0 MURRAY.T D Toledo Edison Co 80/08/22 19
- ---8009020376 LER 80-038/03L-0 on 800724, loss of decay heat flow caused by DH12 going shut was observed DH11 closed while attempting to restore SFAS CH4 cabinet to normal DH11 closed on 800803 while removing bistable BA413 Caused by personnel error FROHNE-R Toledo Edison Co 80/09/07 ip
- 8009020057 Forwards LER 80-060/01T-0 HURRAY,T D Toledo Edison Ca B0/08/26 ip
- ~-800902006( LER 90-060/01T-0 on 800813 during resetting of trip point, decay heat isolation valve DH il began closing Caused by personnel error DH il reopened. DH pump 1-2 started & flow re-established Tech Specs amended ISLEY, T Toledo Edison Co 80/08/26 3pp

- 8009160391 Forwards LER 80-012/03L-1 MURRAY, T D Toledo Edison Co 80/09/09 1m
- --8007160379 LER 80-012/03L-1 on 800201, reactor operator noticed control room position indication was lost for letdown cooler isolation valve MUZA Caused by const personnel bumping into disconnect switch breaker Switch repositioned STDTZ, J C Toledo Edison Co 80/02/28 3pp
- 8009120351 Forwards LER 80-061/03L-0 MURRAY, F D Toledo Edison Co 80/09/10 1p
- --8009120356 LER 80-061/03L-0 on B00812 during calibr & maint records check personnel found valve 8V5005 installed 760826 for temporary use was not replaced Caused by inadequate administrative control Replacement for SV5005 requested ISLEY.T Toledo Edison Co 80/09/10 3pp
- 8009230682 Forwards LER 80-062/03L-0 MURRAY, T D Tolado Edison Co 80/09/18 1p
- ----8009230686 LER 80-062/03L-O on 800903.while performing walkdown per IE Bulletin 80-11.discovered that protective curbs had not been provided around one of pipe chases in mechanical room 3 & 4 Caused by AE error Curbs will be added MURRAY.T D Toledo Edison Co 80/09/18 3pp
- 8009230690 Forwards LER 80-063/03L-0 MURRAY: T D Toledo Edison Co 80/09/18 in
- --8007230692 LER 80-063/03L-0 on 800823 control room operator discovered that indicating lights on safety features actuation sys indication panel for damper CV5442 were out Caused by random failure of fuse in control circuit Fuse replaced THOMPSON, T Toledo Edison Co 80/09/18 2pp
- 8009230671 Forwards LER 80-064/03L-0 MURRAY,T D Toledo Edison Co 80/09/19 1p
- --8007230680 LER 80-064/03L-O on 800822, station experienced loss of exsential instrument ac panel Y2 Caused by failure of YV-2 inverter output fuse No cause determined for fuse failure Failed fuse replaced ISLEY, T Toledo Edison Co 80/09/18 3pp
- 8009290363 Forwards LER 80-065/03L-0 MURRAY, T D Toledo Edison Co 80/09/23 1p
- --8009290370 LER 80-065/03L-O on 800826,loss of position indication light caused loss of control power to breakers rendering emergency diesel generator 1-1 inoperable Caused by human error Switch reclosed & breaker position indication returned MATHENY,D Toledo Edison Co 80/09/23 3pp
- DOCKET 50-348 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 1

  F Security, medical, emergency & fire protection plans
- 8009230249 Requests that all personnel be reminded of purpose of emorgancy notification sys & health physics network Sys installed for govt use during emergency O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/22 1p
- 8009090585 Forwards summary of 800821 working session re installation of fire barriers for cable trays 5 conduits Util concludes that all commitments & requirements have been fulfilled CLAYTON.F.L. Alabama Power Co. 80/09/02 2pp
- O Adjudicatory correspondence
- 8007230115 Forwards order requiring info supporting environ qualification of safety-related electrical equipment. Requests submittal of info by 801101 VAR9A,8 A Operating Reactors Branch 1 80/08/27 2pp
- --8007230117 Order for mod of License NFP-2 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment Info should be submitted by 801101
  EISENHUT, D G Division of Licensing 80/08/29 App

- 8009300407 Informs of M Farrar resignation from full-time ASLAP position Name should be deleted from svc list for all but Farley antitrust proceeding Svc list for all other dockets need contain only two ASLAB members RØSENTHAL, A S Atomic Safety and Licensing Appeal Panel 80/09/25
- M General correspondence
- B009300435 Requests that distribution list be revised to reflect recent mgt-level reorganization WD Whitt has assumed responsibilities formerly assigned to AR Barton CLAYION.F L Alabama Power Co 80/09/23 ip
- J Insurance & Indomnity information
- 8009020278 Forwards ANI Secondary Financial Protection Binder EB-73 • Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div 80/08/26 6pp
- N Utility Final Safety Analysis Report (FSAR) & amends
- ECO9150259 Forwards Amend 74 to FSAR for Unit 1 & to application for OL for Unit 2 Certificate of Svc encl CLAYTON:F. I. Alabama Power Co. 80/09/12 2pp
- ---BOD9150260 Amend 74 to application for OL for Unit 2 & to FSAR for Unit 1 CLAYTON,F L Alabama Power Co 80/09/12 ip
- --8009150263 Amend 74 to FSAR # Alabama Power Co 80/09/12 9pp
- H Antitrust correspondence
- 8009090339 Motion for issuance of decision at earliest convenience Proceeding pending since 790308 Certificate of Svc encl Granted by ASLAB on 800908 BLUME.H & Antitrust Division 80/09/05 3pp
- 80092&0&62 Response in support of NRC 800905 motion for issuance of dacision issues, if resolved, will affect future power supply & development of supply planning Injury may occur if delayed Certificate of Svc encl
  HJELMFELT, D C Hunicipal Electric Utility Association, Alabama
  HJELMFELT, D C Hjelmfelt, D C 80/09/23 3pp
- P Operating license stage documents & correspondence
- 8009080274 Forwards "Setpoint Study for Farley 1 & 2," proprietary (MCAF-B313) & nonproprietary (MCAP-9758) versions.
  Application & affidevit for withholding encl
  ANDEREGN.T M Westinghouse Electric Corp 80/07/25 13pp
- --8009080299 "Setpoint Study for Farloy 1 & 2," nonproprietary version KD,M Westinghouse Electric Corp ORTCNBERG,L I : ROSSI,C E Westinghouse Electric Corp : Nuclear Energy Systems WCAP-9768 74/05/31 216pp
- 8009020297 Bubmits interim criteria for shift staffing to all OL & CP licensess & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D O Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/o NUREO EISENHUT.D © Division of Licensing 80/08/01 119pp
- 8009230052 Informs that exemption from fee re licensing action associated G/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUF, D.O. Division of Licensing 60/08/07 60pp
- 8009110030 Forwards Amend 15 to License NPF-2, safety evaluation & notice of issuance & availability VARGA.8 A Operating Reactors Branch 1, 80/08/14 2pp
- ---8009110031 Amend 15 to License NPF-2, revising low-low steam generator water level reactor trip setpoint to compensate for high containment pressure following postulated high energy line break VAROA, S.A. Operating Reactors Branch 1 80/08/14 6pp

- --8009/10033 Safety evaluation supporting Amend 15 to License (NPF-2 \* Office of Nuclear Reactor Regulation, Director 80/08/14 3pg
- --8009110035 Notice of issuance & availability of Amend 15 to License NAF-2 VARGALS A. Operating Reactors Branch 1 80/08/14 2pp
- 8009190794 Forwards revised Westinghouse STS 3 9 8 2.3 9 10 & Bases 3/4 9 8 % 3/4 9 10 to require 23 ft of water over top of reactor pressure vessel flange during movement of fuel assemblies or control rods Written response required NOVAK.T M Assistant Director for Operating Reactors 80/08/15 is
- --8009190817 Revised Westinghouse STS 3 9 8 2.3 9 10 % Bases 3/4 9 8 % 3/4 9 10 requiring 23 ft of water over top of reactor pressure flange during movement of fuel assemblies or control rods \*\*Assistant Director for Operating Reactors 80/06/23 21pp
- 8009080387 Forwards summary & results of 800819 working session w/NRC re hot shutdown panel, per 800814 tolcon w/NRC CLAYTON,F L. Alabama Power Co. 80/08/28 2pp
- 8009090566 Requests that radiological ETS for Unit 2.NRC approved during wt of 800825.be implemented for Unit 1 on 810101 to assure consistent implementation for both units CLAYTON.F. L. Alabama Power Co. 80/09/02 ip
- 8009120425 Requests that Tech Specs re exposure of fuel assemblies & control rods remain unchanged until after receipt of Unit 2 full power OL.
  CLAYTON-F L. Alabama Power Co. 80/09/03 lp
- 8009110371 Requests that encl supporting document be docketed under Millstone KAPD.PS Assistant Director for Core & Containment Systems 80/09/09 ip
- 8007160358 Requests that RHR Tech Specs, as agreed for Unit 2, be implemented for Unit 1 after receipt of Unit 2 full power OL to assure consistent implementation for both units CLAYTON FL Alabama Power Ca 80/07/10 ip
- 8009300381 Forwards summary of results achieved at 800918 meeting re isolation of hot shutdown panel & main control board instrumentation mods, resulting from NRC 800915 request for addI info CLAYTON-F L Alabama Power Co 80/09/22 2pp
- 8009300424 Supports EPRI & Westinghouse comments on NUREG-0577, re alternate approach for demonstrating nuclear support structure adequacy.per 800702 commitment CLAYTON,F L Alabama Power Co. 80/09/26 ip
- G Inspection reports, JE Bulletins & correspondence
- 8009:10258 Forwards response to IE Bulletin 79-018. Items 1.2 & 3 re environ qualification of electrical equipment Includes master list for each sys or subsystem w/electrical equipment items within scope of bulletin CLAYTONIF L. Alabama Power Co. 80/04/29 350pp
- 8009020466 Forwards IE Insp Rept# 50-348/80-18 \$ 50-364/80-18 on 800623-26 No noncompliance noted STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/07/14 2pp
- ---8009020477 IE Insp Repts 50-348/80-15 % 50-344/80-18 on 800623-26 No noncompliance noted Major areas inspected radwaste mgt GIBSDNA F Region 2. Atlanta. Fuel Facility & Materials Safety Branch WRAY, J R Region 2. Atlanta. Office of the Director 89/07/11 6pp
- 8009100040 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/07/24
- 8009110102 Forwards IE Insp Repts 50-348/80-19 \$ 50-344/80-23 on 800602 -30 No noncompliance nated LEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/07/29 2pp

- ---R009110202 IE Insp Repts 50-348/80-19 & 50-364/80-23 on 800602-30 No noncompliance noted Hajor areas inspected sys integrity outside containment monitoring instrumentation, radiation controls, fluid leats, piping vibration & rire hazards BRADFORD, W H. MARTIN.R D Region 2. Atlanta, Office of the Director 80/07/28 7pp
- 8009050052 Responds to IE Builetin 79-03A. "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " No 300 series fusion welded pipe used in safety-related sys subj to stresses greater than 85% of max allowable stresses CLAYTOUFF L Alabama Power Co 80/08/01 2pp
- BO07020271 Forwards response to IE Bulletin BO-15 Emergency notification sys verified as powered offsite w/backup battery packs CLAYTO:LF L. Alabama Power Co. BO/08/06 5pp
- 8009120045 Forwards IE Insp Repts 50-349/80-14 & 50-364/80-16 on 800609-13 & 16-20 & notice of violation LENIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/09/08 2pp
- --8009120052 Notice of violation from insp on 800609-13 & 16-20 \* Region 2, Atlanta, Office of the Director 80/08/06 2pp
- --B03912007: IE Insp Repts 50-348/80-14 & 50-364/80-16 on 800609-13 & 16-20 Moncompliance noted failure to provide definitive corrective action for identified matl storage inadequacies & failure to control consumables in safety-related sys BELISLE.G A . FORD,E J Region 2. Atlanta, Office of the Director UPRIGHT.C M Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/08/06 35pp
- 8007030123 Forwards Revision I to IE Builetin 80-19, "Failures of Marcurg-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY. J P Region 2, Atlanta, Office of the Director 80/08/15 to
- 3009160110 Forwards IE Circular 80-18, "100FRSD 59 Bafety Evaluations for Changes to Radwaste Treatment Sys " No written response required 0'REJLLY, J P Region 2. Atlanta, Office of the Director 80/08/22
- 8009120251 Forwards IC Info Notice 80-31, "Maloperation of Gould-Brown Bover: 480 Volt Tupe K-6008 & K-DON 6008 Circuit Breakers " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/27 to
- 8009160587 Responds to IE Bulletin 80-17 Mercurg-wetted relays not utilized in reactor protection sys in either facility CLAYTON,F.L. Alabama Power Cn. 80/08/29 1p
- 8009190576 Ack receipt of 800812 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/80-16 & 50-364/80-19 MURPHY-C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 60/09/03 2pp
- --8009190583 Responds to NRC 800723 ltr re violations noted in IE lnsp Repts 50-348/80-16 & 50-364/80-19 Corrective actions testing & analysis initiated to determine probable error introduced through improper use of torque multipliers CLAYTON.F L Alabama Power Co 80/08/12 5pp
- --B009190588 Forwards IE Insp Repts 50-348/B0-16 \$ 50-364/B0-19 on B00617-20 & notice of violation PURPHY.C E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch B0/07/23 2pp
- --8039190593 Notice of violation from insp on 800517-20
  \* Region 2. Atlanta, Reactor Construction & Engineering Support
  Branch 80/07/21 2pg
- -8009190609 IE Insp Repts 50-348/80-16 & 50-364/80-19 on 800617-20 Noncompliance noted torque wrench multiplier used for IE Bulletin 79-02 testing not controlled or calibr & inadequate instruction for mod & insp of support AMG.N P Region 2. Atlanta. Office of the Director HERDT, A Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/07/21 499
- 19290276 Forwards IE Circular 80-21, "Regulation of Refueling Crews" o written response required
  "REFLLY, J.P. Region 2. Atlanta, Office of the Director 80/07/10

- 8009303534 Responds to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment " Responses submitted on 800429 & 0730 completely addressed bulletin requirements No further action required CLAYTON.F L Alabama Power Co 80/09/22 1p
- R Periodic operating reports & rolated correspondence
- 8009030491 Forwards "Semiannual Radioactive Effluent Release Rept. Jan-June 1980 " CLAYTON.F L. Alabama Power Co. 80/08/28 ip
- --8007030475 "Semiannual Radioactive Effluent Release Rept. Jan-June 1980 " \* Alabama Power Co. 80/08/28 55cp
- 8009160268 Forwards monthly operating rept for Aug 1980 CLAYTON: F L. Alabama Power Co. 80/09/11 2pp
- --8009160270 Monthly operating rept for Aug 1980 HAIRSTON,W G Alabama Power Co 80/09/01 Spp
- 8009230566 Forwards corrections to printout Pages 1.3, 4 & 7 of draft summary of effluent & waste disposal semiannual rept for 1978 in response to NRC 800825 ltr Corrected pages available in Central Files only CLAYTON.F L Alabama Power Co 80/09/15 lpp
- S Reportable occurrences, LERs & related correspondence
- 8009020062 Forwards LER 80-044/03L-0 CLAYTON F L Alabama Power Co 80/08/22 1p
- --8009020068 LER 80-044/03L-0 on 800723, during surveillance test diasel generator IC failed to reach rated speed & voltage & was declared inoperable Cause under continued investigation HAIRSTON.W O Alabama Power Co 80/08/22 2pp
- 8009030427 Forwards LER 80-045/03L-0 CLAYTOR:F L Alabama Power Co 80/08/26 1p
- --8009/330429 LER 80-045/03L-0 on 800727, vacuum pump tripped on low flow causing containment atmosphere radioactivity monitoring sys RIE & RIE to be declared inoperable Caused by fouled filter paper in vacuum pump Paper replaced HAIRSTON W O Alabama Power Co 80/08/26 1p
- 8009160320 Forwards LER 80-046/03L-0 CLAYTON F L Alabama Power Co 80/09/08 1p
- --8009160323 LER 80-046/03L-0 on 800813, steam flow channel associated w/ flow transmitte: 475 failed low Caused by defective loop power supply cord Cord replaced & channel returned to syc HAIRSTON, N O Alabama Power Co 80/09/09 ip
- 8009160307 Forwards LER 80-047/03L-0 CLAYTON:F L Alabama Power Co 80/09/11 1p
- --8009160308 LER 80-047/O3L-0 on 800812, svc water bldg 8 train battery sys declared inoperable due to low specific gravity of battery cell No cause found Battery placed on equalize & gravity returned to normal HAIRSTON, W G Alabama Power Co 80/09/11 1p
- 8009230722 Forwards LER 80-040/03L-0 CLAYTON,F L Alabama Power Co 80/09/16 1p
- --8009230729 LER 80-048/03L-0 on 800817, containment atmoshpere gaseous & particulate radioactivity monitoring sys were declared incperable due to pump failure & pump trip on low flow Caused by pump burnout & sys flow maladjustment H4IRSTON, W G Alabama Power Co 80/07/16 ip
- 8009230710 Forwards LER 80-049/03L-0 CLAYTON, F L Alabama Power Co 80/09/18 1p
- --8009230737 LER 80-049/03L-0 on 800820, reactor trip instrumentation channel associated w/RCS loop flow transmitter 434 inoperable due to loss of flow indication Caused by defective transistors on card C1-242
  HAIRSTON.H O Alabama Power Co 80/09/18 ip
- 8009300572 Forwards LER 80-050/03L-0 CLAYTOM F L Alabama Power Co 80/09/24 1p

- \_g009300577 LER 80-050/03L-0 on 800825, svc water train B dc distribution mys declared inoperable when no output indication from battery charger 4 was observed Caused by actuation of high wolfage shutdown relay Reset & returned to svc HAIRSTON.W G Alabama Power Co 80/09/24 1p
- OPG00523 Forward: LER 80~051/03L~0
  CLAYTON F L Alabama Power Co 80/09/25 tp
- @OO9300527 LER 80-051/03L-0 on 80082a.diesel generator iC failed to reach spaced within specified limits Apparent cause was leaking check valve in fuel oil sys Valve replaced & diesel generator returned to svc
  HAIRSTON.W & Alabama Power Co 80/09/25 2pp
- 09300511 Forwards LER 80-052/03L-0 CLAYTON:F L Alabama Power Co 80/09/26 tp
- 3009300515 LER 80-052/03L-0 on 800B27 electronic switching sys BiH sequencer failed to meet time requirement for steps 2 & 3 Caused by setpoint drift Agastat timers satisfactorily reset

  MAIRSTON. # O Alabama Power Co B0/09/26 ip
- Operator Examinations
- :9100318 Forwards revised operating shift manning & training schedule er 800804 exam results & 800904 verbal request LAYTON:F L. Alabama Power Go 80/09/08 6pp
- KET 50-352 LIMERICK GENERATING STATION, UNIT 1
  Application/construction stage documents & correspondence
- POBOOBO Forwards draft NUREO-0696, "Functional Criteria for margency Response Facilities " Comments requested within 30 ays Proposed implementation schedule for meeting criteria # NUREO-0696 encl W/O NUREO BEN代17,D Q Division of Licensing 80/08/01 119pp
- P110742 Notification of 800904-05 meeting w/Mark II owners group to Lscuss plants chugging C/O & lateral load specs
  4DERSON.C Containment Systems Branch 80/08/29 14pp
- P290370 Forwards Amend 24 to application for CL & revised Pages to PAR. Summary description of amend revision encl PADLEYJE J Philadelphia Electric Co 80/09/24 4pp
- OP290380 Amend 24 to application for OL Revises PBAR Pages 5 12-13 & 5.2-16 Certificate of Syc encl
  BOYER.V S Philadelphia Electric Co 80/09/24 4pp
- OF290382 Amend 24 to PBAR, revising Pages 5 2-13 & 5 2-16 Philadelphia Electric Co 80/07/24 3pp
- tility Preliminary Safety Analysis Report, amends
- R90378 Forwards Amend 24 to application for OL & revised Pages to NR. Summary description of amend revision encl
  NDLEY, E. J. Philadelphia Electric Co. 80/09/24 4pp
- 19290380 Amend 24 to application for OL Revises PSAR Pages 5 12-13 & 3.2-16 Certificate of Svc and IOVER.V.S Philadelphia Electric Co 80/09/24 4pp
- '9290392 Amend 24 to PSAR, revising Pages 5 2-13 t 5 2-16 Philadelphia Electric Co 80/09/24 3pp
- curity, medical, emergency & fire protection plans
- 70332 Forwards "Limerick Nuclear Generating Station Preliminary Countion Time Estimates" Rept withheld (ref 10CFR2 790) KLEY.J NUS Corp 80/08/22 1p
- Brat correspondence
- 30448 Responds to 800317 ltr requesting public debate re issues repriate to avacuation of large population ctrs near 1ts.
  TON.H R. Office of Nuclear Reactor Regulation, Director 14/21 Spp

- ~~8009180462 Requests public debate re issues appropriate to evacuation of large population ctrs near plants Expresses Confidence in attempts by Commissioners to represent public concerns EMOR\*, A Affiliation Unitrol 60/03/19 ip
- 8009220078 Responds to 800237 ltr expressing opposition to cirst of factilities Util application for Gis will be subjected to detailed safety & environ relieus by 1,72 % may be subj of public hearing if application is contested 1NGRAM, F. Office of Public Arfairs 50/08/13 1p
- ---B0092E0031 Expresses concern re const of racilities Forwards newspaper article re dangers of nuclear plants MAYER, P Affiliation Uninc. 1 80/03/07 2pp
- B009150316 Responds to E60718 Itr to President Carter transmitting Borough of Phoenix: Ille: PA resolution opposing const of nuclear reactors Facility is not undergoing review Util studies be exacuation time estimates have been submitted DENTON H R Office of Auclear Reactor Regulation. Director B0/08/25
- --8009150318 Forwards Borough of Phoenii.ills.PA 830718 its to Fresident Carter: transmitting Resolution 80-10 opposing const of nuclear reactors Requests response SEAL.M H President of US & Executive Offices 83/07/25 App
- O Inspection reports, IE Bulletins & correspondence
- 8009090089 Forwards IR Bulletin 80-07. Suppl 1. "BWR Jet Pump Assembly Failure" No response required GRIER. B H Region 1. Philadelphia, Office of the Director 8D/03/13 1p
- BOOP1005B1 Forwards IE Insp Repts 50-352/60-13 & 50-353/80-11 on BOO402-13 No noncompliance noted CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch BO/07/21 2pp
- ~~8009100884 IE Insp Repts 50-352/80-13 & 50-353/80-11 on 800602-13 No noncompliance noted Major areas inspected Unit 1. installation & welding of safety-related piping & supports, Unit 2, tour of facility conducted MATTIA. J C Region 1. Philadelphia. Office of the Director MCGAUGHY. R R Region 1 Philadelphia. Restor Construction & Engineering Support Branch 60/07/16 App
- 8009090222 Ack receipt of 800710 ltr informing NRC of steps taten to correct violations noted in IE Insp Repts 50-352/80-04 & 50-333/80-04 CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/08/05 ip
- --RG09090224 Responds to NRC B00ol0 ltr re violations noted in IE linsp Repts 50~352/80-04 & 50-353/80-04 Corrective actions concrete strength will be based on 90-day compressive strength tests KEMPER.J S Philadelphia Electric Co 80/07/10 4pp
- --8009070227 Forwards IE Insp Repts 50-352/80-04 & 50-353/80-04 on 800319-21 & 0402-04 No noncompliance mated GARLSOM, R T. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/10 2pp
- --BOOY090232 IE Insp Repts 50-352/80-04 & 50-353/80-04 on 800319-21 O402-04 No noncompliance noted One deviation noted failure to meet FSAR commitment for concrete strength in 28-day compression tests
  ERNETER, S D Region 1, Philadelphia, Reactor Construction & Engineering Support Branch CHAUDHARY. S K Region 1, Philadelphia, Office of the Director 80/06/06 7pp
- 8009100022 Ack receipt of 800717 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-352/80-05 & 50-353/80-05 CARLSOWR T Region i. Philadelphia, Reactor Construction & Engineering Support Branch 90/08/05 ip
- --8009100026 Responds to NRC 800619 ltr re violations noted in IE Rapts 50-352/80-05 & 50-353/80-05 Corrective actions weld cavity repaired for pipe restraint KEMPER.J S Philadelphia Electric Co 80/07/17 Jpp
- --8009108025 Forwards IE insp Repts 50-352/80-05 & 50-353/80-05 or -0430 & notice of violation CARLSON T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/19 2pp
- --8009100028 Notice of violation from insp on 800326-0430 \* Region 1, Philadelphia, Office of the Director 80/06/13

- --8009100030 IE Insp Repts 90-352/80-05 & 50-333/80-05 on 800326-0430 Moncompliance noted failure to repair weld cavity properly for pipe restraint MCGAUGHY,R W Region 1. Philadelphia. Reactor Construction & Engineering Support Branch MATTIA.J C Region 1. Philadelphia, Office of the Director 80/06/13 19pp
- 8009190044 Act receipt of 800804 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-352/80-09 & 50-353/80-08

SMITH & H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/08/14 ip

- --8009190048 Respands to MRC B00714 ltr re violations noted in IE Insp Repts 50-352/80-09 & 50-353/80-08 Corrective actions sewage pumped on continuous batch basis from holding tanks to treatrent plant KEMPER. V S Philadelphia Electric Co B0/09/04 3pp
- --8009190049 Forwards IE (nsp Repts 50-352/80-09 & 50-353/80-08 on 800522-27 % notice of violation SMITH/S H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 80/07/14 2pp
- --8009190053 Netice of violation from insp on 800522-27

  \* Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 80/07/07

  1p
- ---8009190056 IE Insp Repts S0-352/80-09 & 50-353/80-08 on 800522-27 Noncompliance noted failure to control untreated wastewater & discharge from site BORES, R J Region I, Philadelphia, Fuel Facility & Materials Safety Branch JACKSON, T J Region 1, Philadelphia, Office of the Director 80/07/07 9pp
- 8009030083 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Marcury-Metted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER, B M. Region 1, Philadelphia, Office of the Director 80/08/15 19
- 8009120106 Forwards Suppl 3 to IE Bulletin BO-17, "Failure of Control Rods to Insert During Scram at BWR" No written response required GRIER.B H Region 1, Philadelphia, Office of the Director BO/08/22 1p
- 8009180035 Forwards IE Carcular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GRIER, B M Region 1, Philadelphia, Office of the Director 80/08/22 | 1p
  - 8009120200 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover: 480 Volt Type K-600S & K-DON 6008 Circuit Breakers " No written response required ORIER. B H Region 1, Philadelphia, Office of the Director 80/08/27 lp
  - B009230794 Forwards IE Carcular B0-21, "Regulation of Refueling Crews"
    No written response required
    ORIER BH Region I, Philadelphia, Office of the Director
    B0/09/10 ip
- 800f240353 Forwards IE Info Notice 80-32. "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matis " No written response required ORIER Of H Region i. Philadelphia, Office of the Director 80/09/12 ip
- S Reportable occurrences, LERs & related correspondence
- 8009040425 Advises of completion of investigation of engineering documents re-Fairbanks Morse Model 381D8-1/8 powered generator sets u/stacked heat exchangers Potential for situation similar to Limerick does not exist MORIARTY. J M Colt Industrias, Inc., Fairbanks Morse Engine Div 80/08/27 ip
- U Congressional/Executive Correspondence
- B009100073 Discusses 800527 testimony by V Boyer, util senior vice president, releasely planning NRC met w/Boyer on B00630 Boyer has committed to assuring that all util mgt levels have sincere commitment to effective per

- ---8009100078 Discusses 800527 testimony by V Boyer, util senior vice president, re-emergency planning NRC met w/Boyer on 800630 Boyer has committed to assuring that all util mgt levels have sincere commitment to affective emergency measures AMEARNE, JF Commission 80/08/20 ip
- DUCKET 50-353 LIMERICK GENERATING STATION, UNIT 2

  A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/o NUREO EISENHUT, D & Division of Licensing 80/08/01 119pp
- 8009110742 Notification of 800904-05 meeting w/Mark II owners group to discuss plants chugging C/D & Jateral Load specs ANDERSON.C Containment Systems Branch 80/08/29 14pp
- B. Utility Preliminary Bafety Analysis Report, amends
- 8009270378 Forwards Amend 24 to application for OL & revised Pages to PSAR Summary description of amend revision enci BRADLEY, C J Philadelphia Electric Co 80/09/24 4pp
- --8009290380 Amend 24 to application for QL Revises PSAR Pages 5 12-13 to 5 2-16, Certificate of Svc encl BOYER.V S Philadelphia Electric Co 80/09/24 4pp
- --8007290382 Amend 24 to PSAR, revising Pages 5 2-13 & 5 2-16.
  \* Philadelphia Electric Co 80/09/24 3pp
- F Security, medical, emergency & fire protection plans
- 8009170332 Forwards "Limerick Muclear Generating Station Preliminary Evacuation Time Estimates " Rept withheld (ref 10CFR2 790) BERKLEY, J NUS Corp 80/08/22 1p
- H General correspondence
- 8009180448 Responds to 800319 ltr requesting public debate re issues appropriate to evacuation of large population ctrs near plants
  DENION.H R Office of Nuclear Reactor Regulation, Director 80/04/21 3pp
- --8009:80462 Requests public debate re issues appropriate to evacuation of large population ctrs near plants Expresses confidence in attempts by Commissioners to represent public concerns EMORY, K. Affiliation Unknown 80/03/19 Ip
- 8009220078 Responds to 800809 ltr expressing opposition to const of facilities Util application for OLs will be subjected to detailed safety & environ reviews by NRC & may be subj of public haaring if application is contested INORAM.F. Office of Public Affairs 80/08/13 lp
- --8009220081 Expresses concern re const of facilities Forward\* newspaper article re dangers of nuclear plants MYER.P Affiliation Unknown 80/08/09 2pp
- 8009150316 Responds to 800718 ltr to President Carter transmitting Borough of Phoenizville.PA resolution opposing const of nuclear reactors Facility is not undergoing review Util studies re evacuation time estimates have been submitted DENTON.H R Office of Nuclear Reactor Regulation, Director 80/08/25 2pp
- --8009150318 Forwards Borough of Phoenixville,PA 800718 ltr to President Carter, transmitting Resolution 80-10 opposing const of nuclear reactors Requests response SEAL,M M President of US 3 Executive Offices 80/07/25 App
- 0 Inspection reports, IE Bulletins & correspondence
- 8007070087 Forwards IE Bulletin 80-07. Suppl 1, "BWR Jet Pump Assembly Failure" No response required GRIER.B H Region 1, Philadelphia. Office of the Director 80/05/19 1p
- 8007100881 Forwards IE Insp Repts 50-352/80-13 & 50-353/80-11 on 800&02-13 No noncompliance noted CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/07/21 2pp

- --BOOT100BB4 IE Insp Repts SO-352/80-13 & 50-353/80-11 on BOOG02-13 No noncompliance noted Major areas inspected Unit 1, installation & welding of sarety-related piping & supports; Unit 2, tour of facility conducted MATIA, J C. Region 1, Philadelphia, Office of the Director MCOAUCHY, R W. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/16 App
- 8009070222 Ack receipt of 800710 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-352/80-04 ½ \$0-353/80-04 ½ CARLEGURR T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/08/05 1p
- --8009090226 Responds to NRC 800610 itr re violations noted in IE Insp Repts 50-352/80-04 & 50-353/80-04 Corrective actions concrete strength will be based on 90-day compressive strength tests KEMPER.U S Philadelphia Electric Co 80/07/10 4pp
- --8009090229 Forwards IE Insp Repts 50-352/80-04 & 50-353/80-04 on 800219-21 & 0402-04 No noncompliance noted CARLSOM,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/10 2pp
- --8009090232 IE Insp Repts 50-352/80-04 & 50-353/80-04 on 800319-21 & 0402-04 No noncompliance noted One deviation noted failure to meet PSAR commitment for concrete strength in 20-day compression tests
  EBNETER, S D Region 1, Philadelphia, Reactor Construction & Engineering Support Branch CHAUDHARY, S K Region 1.
  Philadelphia, Office of the Director 80/06/06 7pp
- BOD9103022 Ack receipt of B00717 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-352/80-05 & 50-353/80-05 CARLEGNER T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/05 1p
- --8009100026 Responds to NRC 800619 ltr re violations noted in IE lusp Repts 30-352/80-05 & 50-333/80-05 Corrective actions weld cavity repaired for pipe restraint KEMPERIJ 5 Philadelphia Electric Co 80/07/17 3pg
- --8007100025 Forwards IE Insp Repts 50-392/80-05 & 50-393/80-05 on 800326 -0430 & notice of violation CARLSON,R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/06/19 2pp
- --8009100028 Notice of violation from insp on 800326-0430
  \* Region 1. Philadelphia. Office of the Director 80/04/13 1;
- 8009170044 Ack receipt of 800804 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-352/80-09 & 50-353/80-08 SMITH, 0 H Region i, Philadelphia, Fuel Facility & Materials Safety Branch 80/08/14
- --600919004B Responds to NRC 800714 ltr re violations noted in IE Insp Repts 80-352/80-09 & 50-383/80-08 Corrective actions sewage gumped on continuous batch basis from holding tanks to treatment plant KFMPER.J B Philadelphia Electric Co 80/08/04 3pp
- --B009190049 Forwards IE Insp Repts 50-392/80-09 & 50-393/80-08 on 800522-27 & notice of violation SMITH,0 H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/07/14 2pp
- ---8007190053 Notice of violation from insp on 800522-27.

   Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/07/07 ip
- ---BOO9190056 IE Insp Repts 50-352/80-09 & 50-353/80-08 on 800522-27
  Noncompliance noted failure to control Untreated wastewater
  & discharge from site
  BORES, R. J. Region 1. Philadelphia, Fuel Facility & Meterials
  Safety Branch JACKSON, T J. Region 1. Philadelphia, Office of the
  Director 80/07/07 9gp

- B009030083 Forwards Revision 1 to 1E Builetin 80-19, "Failures of Mercury-Mettod Matrix Relays in Reactor Fratective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/08/15 | p
- 8009120106 Forwards Supp) 3 to 1E Bulletin 80-17. "Fa()ure of Control Rads to Insert During Scram at BWR 'No written response required GRIER.B H Region 1, Philadelphia, Office of the Director BO/08/22 1p
- 8009180035 Forwards IE Circular 80-18, "10CFRSO 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/08/22 1p
- 8009120200 Forwards IE Info Notice 80-31, "Meloperation of Gould-Brown Boveri 480 Volt Type K-6005 & K-DON 6005 Circuit Breakers " No written response required ORIER B H Region 1, Philadelphia, Office of the Director 80/08/27 ip
- 8009230794 Forwards IE Circular 80-21, "Regulation of Refueling Crews " No written response required GRIER, B M Region I. Philadelphia. Office of the Director 80/09710 ip
- 8009240353 Forwards IE info Notice 80-32 "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required ORIER B M Region 1. Philadelphia. Office of the Director 80/09/12 1p
- S Reportable occurrences, LERs & related correspondence
- 8009040425 Advises of completion of investigation of engineering documents re Fairbanks Morse Model 38TDB-1/8 powered generator sets wistacked heat exchangers Potential for situation similar to Limerick does not exist MDRIARTY, J M Colt Industries, Inc., Fairbanks Morse Engine Div 80/08/27 ip
- U Congressional/Erecutive Correspondence
- 8009100073 Discusses 800527 testimony by V Bayer util senior vice president, re emergency planning NRC met w/Bayer on 800530 Boyer has committed to assuring that all util mgt levels have sincere commitment to affective emergency measures AHEARNE, J F Commission 80/08/20 lp
- --8009190078 Discusses 800527 testimony by V Boyer, util senior vice president, re emergency planning NRC met w/Boyer on 800630 Boyer has committed to assuring that all util mgt levels have sincere commitment to effective emergency measures AMEARNE, J F Commission 80/08/20 ip
- DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8007080080 Forwards draft NUREG-0676, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 ent NO NUREG EISENHUT.D @ Division of Licensing 80/09/01 119pp
- E00918016B Forwards NUREG-046f. "Mark I Containment Long-Term Program SER Resolution of Generic Tachnical Activity A-7 " Rept describes requirements regeneric suppression good hydrodynamic load M/o enc! SCHHENGER, A Licensing Branch 3 80/08/20 2pp
- @ Inspection reports, IE Bulletins & correspondence
- 8009090096 Forwards IE Bulletin 80-07.Suppl [, "BWR Jet Pump Assembly Failure " No response required GRIER.B H Region I, Philadelphia, Office of the Director 80/05/13 | p
- BO09190187 Forwards IE Insp Repts 50-354/80-09 & 50-355/80-09 on 800602-27 No noncompliance nated CARLSDVR T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/07/25 2pp

- ---8039190190 IE Insp Repts 50-354/80-07 & 50-355/80-09 on 800602-27 No noncompliance noted Major areas inspected PDM vent line bellows repair, backfilling 3; compaction testing, structural steel installation 3; welding activities inside containment BATEMAN, N H, MCGAUGHY, N H Region 1, Philadelphia, Office of the Director 80/07/24 8pp
- 8009110472 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pige " No ASME SA-312 or ASTM A-312 Type 300 series fusion-welded piping products use greater than B5% of allowable stresses MARTINI J Public Service Electric & Gas Co of New Jersey 80/07/30 2pp
- 8009190203 Ack receipt of 800721 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-354/80-04 & 50-355/80-04 CARLSON,R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/08/06 ip
- --8009190210 Responds to NRC 800318 ltr re violations noted in IE Insp. Respts 50-354/80-04 & 50-355/80-04 Corrective actions review of concrete specs & procedures & training for all civil GC examiners increased MARTIN.T J. Public Service Electric & Gas Co. of New Jersey 80/07/21 3pp
- --8009190214 Forwards IE Insp Repts 50-354/80-04 & 50-355/80-04 on 800331 -0430 & notice of violation CARLSOLL R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/18 2ap
- --8009190216 Notice of violation from insp on 800331-0430 \* Region 1, Philadelphia, Office of the Director 80/06/17 ip
- --8009190223 IE Insp Repts 50-354/80-04 & 50-355/80-04 on 800331-0430 Noncompliance noted failure to follow procedures designed to prevent segregation of concrete during placement & failure of GC to take action to stop improper placement MCGAUGHY.R W. BATEMAN.W H. Regson 1. Philadelphia, Office of the Director 80/06/17 i3pp
- 8009030060 Forwards Revision 1 to IE Bulletin BO-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER.B H Region I, Philadelphia, Office of the Director 80/08/15 ip
- 8009120110 Forwards Suppl 3 to 1E Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/08/22 1p
- B0091B0044 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ORIER.B H Region 1, Philadelphia, Office of the Director 80/08/22 1p
- 8007070557 Responds to IE Sullatin 80-16 re potential misapplication of Rosemount Models 1151 & 1152. Investigation should be completed by 801110 Awaiting response from Bechtel & AE MARTINIT J Public Service Electric & Gas Co of New Jersey
- 8009120239 Forwards IE Info Notice 80-31, "Maloperation of Qould-Brown Boveri ABO Volt Type K-6008 & K-DON 6008 Circuit Breakers" No written response required ORIER, B R Region 1, Philadelphia, Office of the Director BO/08/27 1p
- -8009230795 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required GRIER.8 H Region 1, Philadelphia, Office of the Director 80/09/10 1p
- 8009240330 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Erclusive-Use Shipments of Radioactive Matls " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/09/12 1p

- S Reportable occurrences, LERs & related correspondence
- B009120218 Part 21 rept re epoxy surface sys whose qualification is indeterminable due to conflicting data in qualification test repts 5 data not supported by actual test results Investigation is continuing MARTINI J Public Service Electric & Gas Co of New Jersey B0/08/12 2pp
- 8009190037 Ack receipt of interim rept re potential significant deficiency of biological shield supplied by PX Engineering Co CARLSON, A T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/08/20
- --8009150043 Interim rept re potential significant deficiency of biological shield supplied by PX Engineering Co Bechtel currently conducting investigation of documentation & effecting re-examination where appropriate MARTIN.T J Public Bervice Electric & Gas Co of New Jersey 80/08/07 19
- B009160650 Part 21 rept re Con/Chem spoxy surfacer sys Euppls B00B12 ltr re sub; item reported by Bechtel Power Corp Will advise of schedule dates of completion when Bechtel engineering studies finalized MARTIN.T J Public Service Electric & Gas Co of New Jersey 80/09/02 2pp
- DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8007080080 Forwards draft NUREG-0676, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days.Proposed implementation schedule for meeting criteria of NUREG-0676 encl W/o NUREG EISENNUT,D G Division of Licensing 80/08/01 117pp
- 8009180168 Forwards NUREO-0661. "Mark I Containment Long-Term Program SER Resolution of Generic Technical Activity A-7 " Rept describes requirements re generic suppression pool hydrodynamic load M/a encl SCHMENCER, A Licensing Branch 3 80/08/20 2pp
- @ Inspection reports, IE Bulletins & correspondence
- 8009090694 Forwards IE Bulletin 80-07. Suppl 1, "BNR Jet Pump Assembly Failurs" No response required ORIER. B H Region 1, Philadelphia, Office of the Director 80/05/13 1p
- 8009190187 Forwards IE Insp Repts 50-354/80-09 & 50-355/80-09 on 800&02-27 No noncompliance noted CARLSON.R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/25 2pp
- --8009150190 IE Insp Repts 50-354/80-09 & 50-355/80-09 on 800602-27 No noncompliance noted Major areas inspected PDM vent line bellows repair backfilling & compaction testing, structural steel installation & welding activities inside containment BATEMAN.W H . MCGAUGHY, R W Region 1, Philadelphia, Office of the Director 80/07/24 Spp
- 8009110472 Responds to IE Bulletin 79-03A, "Longitudinal Weld Defects in ABME SA-312.Type 304 Stainless Steel Pipe " No ABME SA-312 or ASTM A-312 Type 300 series fusion-welded piping products use greater than 85% of allowable stresses MARTIN.T J Public Service Electric & Gas Co of New Jarsey E0/07/30 2pp
- 6007170203 Ack receipt of 800721 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-354/80-04 & 50-355/80-04 CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/06 1p
- --8009190210 Responds to NRC 800618 ltr re violations noted in IE Insp. Repts 50-334/80-04 & 50-355/80-04 Corrective actions review of concrets specs & procedures & training for all civil QC staminars increased MARTIN.T U Public Service Electric & Gas Co of New Jersey 80/07/21 gpp
- --8007190214 Forwards IE Insp Repts 50-354/80-04 & 50-355/80-04 on 800331 -0430 & notice of violation. GARLESULA T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/06/18 2pp

- --B009190223 IE Insp Repts 50-354/80-04 & 50-355/80-04 on B00331-0430 Noncompliance noted failure to follow procedures designed to prevent segregation of concrete during placement & failure of GC to take action to stop improper placement MCGAUOHY, R W. BATEMAN.W H. Region 1. Philadelphia, Office of the Director 80/06/17 13pp
- BOC7030060 Forwards Revision 1 to 1E Sulletin 80-17, "Failures of Hercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER, B M. Region 1. Philadelphia. Office of the Director 80/08/15 1p
- 8009[20]10 Forwards Suppl 3 to 1E Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR" No written response required QRIER, B H Region 1, Philadelphia, Office of the Director 80/08/22 1p
- B0091B0044 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GRIER.B H Region 1. Philadelphia, Office of the Director 80/08/22 1p
- 8009090559 Responds to IE Bulletin 80-16 re potential misapplication of Rosemount Models 1151 & 1152 Investigation should be completed by 801110 Awaiting response from Bechtel & AE HARTIN,T J Public Service Electric & Oas Co of New Jersey 80/08/27 1p
- 8009120239 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-600S & K-DQN 600S Circuit Breakers " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/08/27 ip
- 8009230795 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required CRIER.B H Region 1. Philadelphia, Office of the Director 80/09/10 1p
- 8DC9240330 Forwards IE Info Notice 8D-32. "Clarification of Certain Regultements for Exclusive-Use Shipments of Radioactive Hatls " No written response required ORIER, B.H. Region I. Philadelphia. Office of the Director 80/09/12 ip
- DOCKET SO-356 UNIV OF ILLINOIS LOPRA RESEARCH REACTOR

  \*\*Referring reports & related correspondence\*\*
- BOO9130496 Forwards "Annual Rept, Aug 1979-Aug 1980, IL LOPRA Reactor " BECK. 6 P . CHILTON, A B Illinois, Univ of Urbana-Champaign BO/09/05 1p
- --8009150461 "Annual Rept. Aug 1979-Aug 1980, IL LOPRA Reactor "
  1111nois, Univ of Urbana-Champaign 80/09/05 ip
- DOCKET 50-358 WILLIAM H ZIMMER NUCLEAR STATION, UNIT 1

  A Application/construction stage documents & correspondence
- 8009020i17 Confirms 800724 telcon arranging NRC 800730 & 31 meeting \*\*Makeveral BHR license Forwards sample ltr w/meeting \*\*schedule\*\*
  \*\*HEISHMAN.R F Region 3, Chicago, Reactor Operations Nuclear Support \*\*Branch 80/07/24 1p'
- BCOGGBOOBO Forwards draft NUREC-0676, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl W/o NUREG EISENHUT, D O Division of Licensing 80/08/01 119pp
- 8009070631 Notification of cancellation of 800827 meeting w/BWR licensing review group to discuss concensus positions on TMI issues (NUREO-0694) Wilson J N Assistant Director for Licensing 80/08/04 10pp
- 8009110255 Requests that util advise NRC on number of lines exempted on main steam.nuclear boiler, residual heat removal, coolant injection, reactor recirculation & standby liquid control sys re permitted exemptions under ASME Code. Section XI, iHB-1220 BCHMENCER. A Licensing Branch 2 80/08/21. 4pp

- B009110742 Notification of 600904-05 meeting w/Mark II owners group to discuss plants chugging C/O & lateral load specs ANDERSON. C Containment Systems Branch 80/08/29 14pp
- 800926067: Forwards request for add1 info re Category I masonry wall design TEDESCO.R L Assistant Director for Licensing 80/09/10 5pp
- 8009290086 Forwards positions re degraded grid voltage & protection of reactor containment electrical penetrations, developed during review of FSAR Requests date or response TEDEBCO.R L. Assistant Director for Licensing 80/09/12 8pp
- 8009260091 Notifies of #01007 proposed date to review whether OBE & SRV responses should be considered separately or combined during ASNE code fatigue calculations GE selected samples to emphasize highly fatigued components WILSON.J N Assistant Director for Licensing 80/09/15 9pp
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8007250267 Requests add1 info re containment pressure boundary fracture toughness for final SER completion
  TEDESCO.R L Assistant Director for Licensing 80/09/10 3pp
- f Security, medical, emergency & fire protection plans
- 8009030588 Forwards Revision 16 to "Fire Protection Evaluation Rept "
  BORGMANN, E A Cincinnati Gas & Electric Co 80/08/29 1p
- --8009030590 Revision 16 to "Fire Protection Evaluation Rept"

  \* Cincinnati Cas & Electric Co BO/08/31 2pp
- 8009050333 Comments on util 800818 preliminary evacuation time study & requests NRC insure that City of Mentor has integral role in facility emergency planning Study has serious flaws that must be examined & corrected REDER, M. Mentor, KY. 80/09/02 2pp
- B0072B0470 Immediate action itr re potentially deficient fire stop math mfg by Tech-Bil, inc Lists products found to be in nonconformance w/project & NRC requirements & actions to be completed before leaded elastomer installation is continued KEPPLER. J. O Region 3. Chicago. Office of the Director 80/07/04 2pp
- O Adjudicatory correspondence
- 8007030693 Response to parties' comments on Contention 5 per ASLB 300714 order re-potential hazards of irradiated fuel transportation Urges same degree of protection for residents of nonurban areas Certificate of Svc 2 address change enci FANKHAUSER, D Frankhauser, D D WOLIVER, J Woliver, J D 80/08/26
- 8009020445 Forwards Commission 800819 amend to emergency planning rules N/o encl BARTH,C A Hearing Branch 3 80/08/29 1p
- 8007050272 Responds to ASLB 800804 memorandum on behalf of util, reutil % NRC plans for analyzing t evaluating safety significance of 800727 earthquake Util has concluded that event had no safety significance for facility CONNER, T B Conner, Moore & Corber CONNER, T B Cincinnati Gas & Electric Co 80/07/02 2pp
- 8009100595 Response in apposition to applicants' motion for summary disposition of Contention 5.per ABLB 800714 order inviting comments in light of physical protection final rule Burden of proof not sustained Certificate of Svc encl MARTIN.D K , BESHEAR.S L Kentucky, State of 80/09/04 10pp
- 8009220413 Memorandum advising NRC to provide ASLB w/best estimate for issuance of BER suppl re unresolved generic issues Urgas NRC to evaluate applicants financial ability re items mandated by TRI accident & various contingencies BECHHDEFER, C Atomic Safety and Licensing Board Panel 80/09/17 4on
- 8009300016 Response in opposition to State of KY 800904 objection to summary disposition of Contention 5 Concurs w/ASLB 800714 momorandum & order Challenge to spent fuel casks design is barred as matter of law Certificate of Svc encl CONNER, T B . NETTERHAHN, M J Cincinnati Gas & Electric Co CONNER, J B Conner, Moore & Corber 80/09/23 7pp

## d inspection reports. IE Bulletins & correspondence

- 8009040531 Forwards IE Bulletin 80-07, Supp) 1. "BWR Jet Pump Assembly Failure" Response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/14 to
- 8009110655 Forwards IE Insp Rept 50-358/80-15 on 800623-27 & notice of violation FIORELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Brench 80/07/25 2pp
- andbout nieucu Anio/152 Sbb
- --8009110656 Notice of violation from insp on 800623-27

  \* Region 3. Chicago, Office of the Director 80/07/25 ip
- --8009110661 JE Insp. Rept S0-358/80-15 on B00623-27 Noncompliance noted failure to establish controls to assure that structural design changes are implemented in field & verified by GC KNOP, R C . BARRETT.P A Region 3. Chicago, Office of the Director B0/07/25 4pp
- 8009160509 Forwards IE Insp Rept 50-359/80-14 on 800602-06,09-10,16-20 & 23-26 & notice of violation
  HEISHMAN, R F Region 3, Chicago. Reactor Operations Nuclear Support Branch 80/07/31 2pp
- --8009160512 Notice of violation from insp on 800602-06.09-10.16-20 t 23-26
  - \* Region 3, Chicago, Office of the Director 80/07/30 200
- --8009160514 IE Insp Rept 50-358/80-14 on 800602-06,09-10,16-20 & 23-26 Noncompliance noted inadequate corrective action to control weld rod & inadequate corrective action taken on audit findings WARNICK, R F , DANIELS, F T Region 3: Chicago, Office of the Director 80/07/30 7pp
- 8007030192 Forwards Revision 1 to IE Bulletin 90-19. "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E "Written response required KEPPLER.J Q Region 3. Chicago, Office of the Director 80/08/15
- 8009150473 Forwards IE Info Notice 80-30. "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE BNR Facilities " No specific action or response requested REPPLER.J G Region 3. Chicago, Office of the Director 80/08/20 is
- 8009120032 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scræm at INR " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/22 to
- 8009170408 Forwards IE Circular 80-18, "10CFR50 59 Safe.y Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER.J Q Region 3, Chicago, Office of the Director 80/08/22 to
- 8009230081 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6005 & X-DON 6005 Circuit Breakers " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/08/28
- 8009250223 Ack receipt of 800804 ltr informing NRC of steps taken to correct violations noted in 15 Insp Rept 50-358/80-09 KEPPLER, J Q Region 3, Chicago, Office of the Director 80/08/30 ip
- --8009250227 Responds to NRC 800702 ltr re violations noted in IE Insp Rept 50-388/80-09 Corrective actions HJ Kaiser procedure re central of nonconforming matls will be revised BURGMANNIE A Cincinnati Gas & Electric Co 80/08/04 2pp
- 709170422 Responds to IE Bulletin 80-19 & Revision 1 re failures of sercury-wetted matrix relays in reactor protective sys dentified relays are not used in facility Four manhours spended for investigation OROMANN/E A Cincinnati Oas & Electric Co 80/09/02 ip
  - 9170429 Responds to 1E Bulletin 80-20 re failures of Westinghouse pe W-2 spring return to neutral control switches antified switches are not used in safety-related areas mandays expended for investigation MANN.E A Cincinnati Gas & Electric Co 80/09/02 1p

- 8009250137 Responds to IE Bulletin 80-17 & Revision 1. "Failures of Mercury-Notted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Relays not utilized in reactor protective sys of facility BOROMANN.E A Cincinnati Gas & Electric Co 80/09/03 1p
- 8009240090 Forwards IE Circular 80-21, "Regulation of Refueling Creus" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/10 %
- 8009250146 Forwards request for info re turbine disc for NRC review of inservice insp program
  TEDESCO.R L Assistant Director for Licensing 80/09/10 4pp
- 800929044B Ack receipt of 800821 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/80-15 FIORELLI, O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/09/10 ip
- --B009290460 Responds to NRC ltr re violations noted in IE Insp Rept 50-358/80-15 Corrective actions procedure establishing method to verify field activities will be issued BGR9MANN.E A Cincinnati Gas & Electric Co B0/08/21 2pp
- S Reportable occurrences, LERs & related correspondence
- 8009150062 Part 21 rept re power plant noncomplying valves Reanalysis 90% complete Corrective action involves design changes & review by customer engineering & field personnel High priority on valves which must meet increased loading.
  NIEHAUS; P W William Powell Co 80/08/03 2pp
- 8009100620 Ack receipt of 800804 ltr informing NRC of actions taken to correct deficiency re Ruskin fire dampers FIORELLI.G Region 3, Chicago. Reactor Construction & Engineering Support Branch 80/08/25 lp
- 8009250490 Immediate action ltr re potentially deficient fire stop matl mfg by Tech-Sii, Inc Lists products found to be in nonconformance w/project & NRC requirements & actions to be completed before leaded elastomer installation is continued KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/04
- DGCKET 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2

  A Application/construction stage documents & correspondence
- 8009120505 Notification of contract execution, Mod 5 to "Bimulation of Earthquake Ground Motions for San Onofre " Contractor K Aki MCNULTY, A Administrative Contracts Branch FIN B-4531 80/04/01
- ~-8009120514 Mod 5, extending period of performance & adding add1 funds to "Simulation of Ground Motions for Ban Gnofre" AKI.K Massachusetts Institute of Technology PERLMAN.J Administrative Contracts Branch FIN B-6531 80/04/01 1p
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT, D & Division of Licensing 80/08/01 119pp
- 8009020006 Forwards addendum to June 1980 response to Guestion 361 63, rs origin of folds & faults, offshore & south of facility, per NRC request during 800814 geosciences meeting Addendum will be included in Amend 21 to FSAR, to be submitted in Oct 1980 DASKIN, X P Southern California Edison Co 80/08/22 2pp
- --9007020007 Addendum to June 1780 response to Question 361 63 re origin of folds & faults.offshore & south of facility Four composite geologic cross-sections encl \* Southern California Edison Co 80/08/22 23pp
- ~~8009020010 "Offshore Geologic Structure," Plate 2. Sheet 12 \* Southern California Edison Co 80/08/31 ip.
- 8009100417 Bummary of 800724 meeting w/applicants to discuss analysis of Imperial Valley earthquake of Oct 1979 ROOD,H Licensing Branch 3 80/08/27 16pp
- 8009150420 Notification of contract execution "Followon to Simulation of Earthquake Oround Motions for San Onofre Nuclear Generating Station," awarded to E Luco LITLE, M Administrative Contracts Branch FIN 8-6898-0 80/08/27

- --9009150424 Contract "Followon to Simulation of Earthquake Ground Mations for San Onofre Nuclear Generating Station," awarded to E Luco LUCD.J E Luco,J E PERLMAN,J Administrative Contracts Branch FIN B-6898-0 80/08/27 5pp
- 8009160227 Notification of 800909-10 meeting w/util to conduct caseload forecast panel site visit ROOD.K Licensing Branch 3 80/08/27 4pp
- BOO9140252 Summary of BOO812-15 meeting w/Southern CA Edison Co.C-E. Becktel & San Diego Gas & Electric Co in Bethesda,MD to discuss non-TMI related open items BDGD.H Licensing Branch 3 80/08/27 11pp
- 8009240622 Notification of 800909-11 meeting w/util in San Clemente.CA to conduct electrical site visit ROCD.H Licensing Branch 3 80/08/27 3pp
- 8005240052 Notification of contract execution "Followon to Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station " Contractor R Hermann LITLE, K Administrative Contracts Branch FIN 8-6878-0 80/08/28
- --8009240057 Contract "Followon to Simulation of Earthquake Ground Hotions for San Onofre Nuclear Generating Station," awarded to R Hermann HERMANN, R 5t Louis Univ PERLMAN, J Administrative Contracts Branch FIN 8-6898-0 80/08/28 Spp
- BOOPO50302 Forwards responses to NRC BO0523 & 0616 ltrs.proprietary & nonproprietary versions of CEN-135(s). "CPC/CEAC Boftware Mods for San Onofre Unit 2." in response to NRC question 221 IB Hithholding affidavit encl
  BASKIN.K.P. Southern California Edison Co 80/09/03 77pp
- --8009050308 "CPC/CEAC Software Mods for San Onofre Unit 2 " Proprietary version withheld (ref 10CFR2 790) + Combustion Engineering, Inc. CEN-135(S)-NP 80/08/31 79pp
- BOOTS10547 Notification of 800910 meeting w/util & C-E in Bethesda, MD to discuss NRC questions re CENPD-178
  RBOD.H Licensing Branch 3 80/09/04 3pp
- 8009120273 Notification of 800909 meeting u/util & C-E in Windsor.CT to discuss audit of CENPD-17B analysis methods
  ROOD.H Licensing Branch 3 80/09/04 3pp
- 8009380330 Forwards questions to Executive Order 11988 Flood Plain Mgt Response requested by 800912 TEDEBCO.R L. Assistant Director for Licensing 80/09/04 App
- 8009290143 Notification of 800926 meeting w/utils & Kerr-McGee Chemical Carp in Bethesda,MD to discuss review & recommendations for site specific ground response spectra & program plans for seismic functional qualification of Class IE equipment ALLISON,D.P Systematic Evaluation Program Branch 80/09/08 3pp
- 8009170913 Notification of 800923 meeting w/util, USOS & CDMO in Menlo Park: CA to discuss seismology & geology re facilities.
  RDOD, H Licensing Branch 3 80/09/09 3pp
- BOOP(8042) Forwards response to hydraulic engineering questions reflood plain mgt, per NRC 800704 request Site does not fall within floodplain as defined by Executive Order 11988
  BASKIN.K P Southern California Edison Co 80/09/10 4pp
- --8009i80429 "Preconst Floodplains.Units 2 & 3 "
  # Southern California Edison Co 80/09/10 1p
- --8009;80433 "Post-Const Floodplains. Units 2 & 3 "
  # Southern California Edison Co 80/09/10 ip
- 8009250150 Approves of util 800115 plans to terminate preoperational Aonitoring program SCHMENCER: A Licensing Branch 3, 80/09/11 3pp
- 3009250451 Forwards proposed memorandum of agreement for San Onofre transmission lines & two ltrs from State of CA, Dept of Parks & Recreation.per 800909 telcon Formal request for concurrence will follow shortly SCALETTI.D.
- ~8009250456 informs of assuming H Bass responsibilities Requests informal meeting w/NRC to discuss directions of mutual interests in preserving cultural resources BELL.D A. California, State of BO/04/18 ip

- f Security, medical, emergency & fire protection plans
- 8009030358 Notifies of 800819,22 % 30 regional workshops re development of guidance for acceptable method for coping w/emergencies at facility Requests that representative be sent Subj areas to be discussed include function of facilities & location EXGELKEN, R H Region 5, San Francisco. Office of the Director 80/08/12 2pp
- 8008270278 Forwards Jul 1980 revised emergency plantin response to NRC 791031 request for addl info Licensee is assisting local govt in devising emergency response procedures BASKIN.K P Southern California Edison Co 80/08/18 2pp
- ~~8008270280 Emergency plan ★ Southern California Edison Co → San Diego Gas & Electric Co 80/07/31 225pp
- 8009030387 Forwards revised safeguards contingency plan per NRC 791211 & 800324 requests Plan withheld (ref 100FR2 790)
  BASKIN-K & Southern California Edison Co 80/08/28 2pp
- 8009050286 Forwards Revision 1 to security force training 5 qualification plan Plan withheld (ref 10CFR2 790) BASKIN.K P Southern California Edison Co 80/09/03 ip
- 8009240347 Forwards emergency planning info for placement in local PDR SQUOER, J L Division of Rules and Records 80/09/04 ip
- G Adjudicatory correspondence
- 8009020057 Order establishing discovery schedule Discovery re geology, seismology & emergency planning shall end 30 days following NRC safety evaluation & svc of emergency plan Depositions shall be completed 40 days after such svcs SMITH, I W Atomic Safety and Licensing Hoard Panel 80/08/27 5pp
- 8009160339 Forwards NUREG-75/111, NUREG-0654 & NUREG-0696 in response to 800811 tolcon re emergency planning into U/o encls DAVIS, L. D. Hearing Branch 4 80/08/27 1p
- 8009110396 Forwards stipulation to extend time within which Southern CA Edison Co will answer intervenor Friends of The Earth 800811 interrogatories PIGOTT.D R Chickering & Gregory 80/09/03 (p
- --8009110399 Stipulation between parties allowing Southern CA Edison Co extension until 800915 to respond to intervenor Friends of The Earth 800811 Interrogatories Approved by ASLB on 800908 PIGOTT, D.R. Southern California Edison Co. PIGOTT, D.R. San Diego Gas & Electric Co. PIGOTT, D.R. Chickering & Gregory. 80/08/27 200
- B009100404 Interrogatories directed to NRC re Cristianitos fault, Newport-Inglewood-Rose Canyon-San Miguel fault ione & other seismic-related issues Certificate of Svc enct WHARTON,R J. POGALIES, JK Friends of the Eurth WHARTON,R J Wharton & Pogalies 80/09/04 17pp
- B009190299 Responds to FDIA request for 15 documents listed in bibliography of NUREO-0625, "Rept of Biting Policy Task Force" Documents 6-8 & 13 are available in PDR Forwards remaining documents FELTON, J M Division of Rules and Records B0/09/04 1p
- ~-BO09190587 Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants, for determination of site acceptability & adequacy of engineered safety features MINGOUE, R II Office of Standards Development, Director SECY-79-362 79/06/04 7pp
- --8009190630 Requests that enci. "Differences in Procedures for Estimating Atmospheric Dispersion Conditions at Inland & Coastal Sites," be sent to appropriate Boards SCINTO.JF Hearings Division 79/04/04 16pp
- 8009090774 Forwards 800B19 FR notice re final rules upgrading emergency planning regulations effective 801103 CHANDLER.L. J. Hearing Branch 1 80/09/05 19ap
- 8009160341 Advises that NUREC-75/111.NUREC-0654 & NUREC-0696 were mailed on 800827 per 800828 inquiry about emergency planning info Discovery requests should be made through counsel Wharton DAVIS.L D Hearing Branch 4 80/09/11 1p

- 8009190083 Response to Intervenor Friends of The Earth 800811 fourth set of interrogatories Objects to portions requesting production of documents Certificate of Svc encl PIGOITIO R . CASEY, S B . MOCHER, C R . Southern California Edison Co 80/09/15 46pp
- H General correspondence
- 8009050339 Urges NRC not to issue low power fuel loading license for Unit 2 LITFIN.K Affiliation Unknown 80/09/28 1p
- 8009120448 Opposes licensing of facility for low level fuel loading due to undue risks posed to public health & safety Requests to be informed of NRC actions & future public hearings HARRIS, J.F. Affiliation Unknown 80/08/28 ip
- 8009110399 Opposes licensing of facility KLEIN:S Affiliation Unknown 80/08/29 ip
- 8009110398 Opposes low level testing & licensing of facility/since no evacuation plan possible MARTINEZ P R Affiliation Unknown 60/08/29 ip
- 8009120183 Opposes licensing of facility for low power testing allowing bypass of new TML mods & evacuation laws Requests notification of public hearings on issue & any procedural change COHFN.E Affiliation Uninown 80/03/29 is
- 8009120444 Opposes licensing of facility for low level testing due to undus risks posed to health & safety of public & environ BROWN,P Affiliation Unknown 80/09/29 ip
- 8009050350 Expresses apposition to nuclear energy & licensing of Unit 2 COMEN.P Affiliation Unknown 80/09/03 lp
- B009110430 Oppuses granting low power loading license to avoid evacuation plan requirements PULIDO. M Affiliation Unknown 80/09/03 ip
- 8009100448 Forwards updated 10CFR2.50.51 % 100 W/o encl CHANDLER.L J Hearing Branch 1 80/09/05 1p
- 8009120188 Opposes granting low-power fuel loading license, or any license, to Unit 2 Requests any info re new developments concerning facility operation PAULSEN.K Affiliation Unknown 80/09/05 ip
- BOO9120435 Opposes licensing of facility Human needs should be placed before monetary gains POLLACK.S Affiliation Unknown 80/09/05 ip
- 800912043B Expresses concern re law power fuel loading license for plant & requests info re-public hearings SIGUR.S R Affiliation Unknown 80/09/05 ip
- B009120439 Opposes licensing of facility due to undue risks posed to public & future health & safety BEPECOUR.C Affiliation Unknown 80/69/05 ip
- 8009120442 Opposes licensing of facility for low level testing due to undue risks posed to public & environ health & safety Nuclear gower is unnecessary POLLEIT,R Affiliation Unknown 80/09/05 ip
- 8009230637 Protests plant licensing even in authorization is only for operation at 5% capacity Expresses concern that conversion to safe nonnuclear fuels will consequently be more difficult MARTIN. Affiliation Unknown 80/09/14 10
- 8009230633 Forwards transcript of 800814 public meeting in Bethesda, MD re-seismic issues Similar documents usually available at LPDR M/o encl
  DAVIS.L D Hearing Branch 4 80/09/18 ip
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8009190338 Forwards Amend 20 to FSAR Amend contains responses to NUREO-0560 & NUREO-0594, "TMI-Related Requirements for New OLs " DIETCH.R Southern California Edison Co 80/09/12 ig

- --8007190344 Application for amend to facility license applications, incorporating Amend 20 to FEAR Amend consists of responses to NUREG-0694 \$ NUREG-0660, "TMI-Related Requirements for New Ols "

  \* Southern California Edison Co GILLMAN, D W San Diego Gas & Electric Co 80/09/12 3on
- --8009190351 Amend 20 to FSAR, including responses to NUREG-0694 & NUREG-0660. "TMI-Related Requirements for New OLs " \* Southern California Edison Co \* San Diego Gas & Electric Co 80/08/31 225pp
- P Operating license stage documents & correspondence
- 8009260022 Notification of second rescheduling until 801003 for meeting w/SEP owners group & KMC. Inc +o discuss NRC initial review of site-specific ground response spectra & util program for seismic functional qualification of Class IE equipment ALLISON.D P Systematic Evaluation Program Branch 80/09/10 3pp
- G Inspection reports, IE Bulletins & correspondence
- 8009020258 Forwards IE Insp Repts 50-361/80-09 & 50-362/80-06 on BO0428-0301 No noncompliance noted SPENCER,O S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/07/10 2pp
- --B009020267 IE Insp Repts 50-361/80-07 & 50-362/80-06 on B00428-050; No noncompliance noted Major areas inspected const activities including previous open items & equipment storage & maint ECKMARDT, J H. ELIN, J O Region 5, Ban Francisco. Office of the Director HAYNES, R C Region 5, San Francisco. Reactor Construction & Engineering Support Branch 80/07/10 6pp
- 8009160626 Responds to 1E Bulletin 79-03A. "Longitudinal Weld Defects in ASKE SA-312. Type 304 Stainless Steal Pipe " Unly piping components subjected to design stresses greater than 85% of allowable stresses listed in encl
  BASKIW. K P Southern California Edison Co 80/08/01 7pp
- 8009260297 Forwards IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inlat Flange" No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/08/07 lp
- B009120475 Forwards IE Insp Rept 50-361/80-11 on 800615-0717 No noncompliance noted CREWS, J. L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/08/12 2pp
- --B009120479 IE Insp Rept 50-361/80-11 on 800615-0717 No noncompliance noted Major areas inspected preoperational test program & procedures & independent insp program FAULKENBERRY, B Region 5, San Francisco, Reactor Operations Nuclear Support Branch JOHNSON, A D , PATE, R J Region 5, San Francisco, Office of the Director 80/08/11 4pp
- 8009030280 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E " Written response required ENGELKEUR H Region 5, San Francisco, Office of the Director 80/08/15 ip
- 8009290497 Forwards IE Info Notice 80~27, "Degradation of Reactor Coolant Pump Studs " ENOELKEN,R H Region 5, San Francisco, Office of the Director 80/08/18 4pp
- 8009160184 Forwards IE Circular 80-18, "10CFRSO 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/08/22 1p
- BO09300017 Submits response to IE Bulletin BO-16 Rosemount Models 1151 % 1152 pressure transmitters are not planned for use in safety-related applications
  BASKIN.K P Southern California Edison Co 80/08/26 2pp.
- 8009120463 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DDN 6008 Circuit Breakers" No written response required ENSELKFINR H Region 9, San Francisco, Office of the Director 80/08/27 Ip

- S Reportable occurrences, LERs > related correspondence
- 800909047D Final deficiency rept re lubricated armature bumpers on some NEMA Size 3 starters & contactors mfg by Square D Co All 30 suspect starters will be inspected during Sept 1980 Starter bumpers containing lubricant will be replaced PAPAY, L T Southern California Edison Co 80/09/03 3pp
- 8009300431 Final deficiency rept re excessive bypass flow for high pressure safety injection pumps Orifice assembly design has been modified by manufacturer & will be installed by 801015 PAPAY.L T Southern California Edison Co 80/09/25 3pp
- T Hearing transcripts on non-antitrust matters
- 8007100021 Summary of 800814 meeting w/util & USGS in Bethesda.MD reoffshore exploration results Transcript encl ROOD.H Licensing Branch 3 80/08/21 4pp
- --8009100024 Transcript of 800814 public meeting w/util & USGS in Bethesda.HD re offshore exploration results Pp 1-76 \* Licensing Branch 3 80/08/14 85pp
- DOCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3
- A Application/construction stage documents t correspondence
- 8009120505 Notification of contract execution, Mod S to "Simulation of Earthquake Ground Motions for San Onofre " Contractor K Aki KCRULTY, A Administrative Contracts Branch FIN B-6531 80/04/01
- --8009120514 Mod 5, extending period of performance & adding add1 funds to \*Simulation of Ground Motions for San Onofre "

  AKI.K Massachusetts Institute of Technology FIN B-6531
  8870470E 19
- BOOY0800BO Forwards draft NUREC-0676, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl W/o NUREG EJSENMUT, D O Division of Licensing 80/08/01 119pp
- B007020005 Forwards addendum to June 1980 response to Question 361 63, re origin of folds & faults.offshore & south of facility, per NRC request during 800814 geosciences meeting Addendum will be included in Amend 21 to FBAR, to be submitted in Oct 1980 BASKIN, K P Southern California Edison Co 80/08/22 2pp
- --B009020007 Addendum to June 1980 response to Question 361 63 re origin of folds & faults:offshore & south of facility Four composite geologic cross-sections encl
  # Bouthern California Edison Co 80/08/22 23pp
- --8007020010 "Offshore Geologic Structure," Plate 2, Sheet 12 \* Southern California Edison Co 80/08/31 1p
- \$009100417 Summary of 800724 meeting w/applicants to discuss analysis of Imperial Valley earthquake of Oct 1979 ROOD: H Licensing Branch 3 80/08/27 16pp
- 8009150420 Notification of contract execution "Followen to Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station." awarded to E Luco
  LITLE.M Administrative Contracts Branch FIN B-6898-0 80/08/27
- --8009150424 Contract "Followon to Simulation of Earthquake Ground Hotions for San Onofre Nuclear Generating Station," awarded to E Luco LUCO, J E Luco, J E FIN 8-6898-0 80/08/27 5pp
- 8009(60227 Notification of 800909-10 meeting w/util to conduct caseload forecast panel site visit RDOD:H Licensing Branch 3 80/08/27 4pp
- SCO9160252 Summary of S00812-15 meeting w/Southern CA Edison Co.C-E. Bachtel & San Diego Gas & Electric Co in Bethesda.MD to discuss non-TMI related open items RDDD-H Licensing Branch S 80/08/27 lipp
- 9009240622 Natification of 800909-11 meeting w/util in Ban Clemente,CA to conduct electrical site visit ROOD,H Licensing Branch 3 80/08/27 3pp

- 8009240052 Notification of contract execution "Followon to Simulation of Earthquake Ground Motions for San Chofre Nuclear Generating Station "Contractor R Hermann LITYLE.M Administrative Contracts Branch FIN B-6898-0 80/08/28
- ~~8009240057 Contract "Followon to Simulation of Earthquake Ground Motions for San Chofre Nuclear Generating Station," awarded to R Hermann HERMANN, R St Louis Univ FIN 8-6898-0 80/08/28 5pp
- 8009050302 Forwards responses to NRC 800923 & 0616 ltrs.proprietary & nonproprietary versions of CEN-135(s), "CPC/CEAC Software Mods for San Onofre Unit 2." in response to NRC question 221 18 Withholding affidavit encl
  BASKIN.K P Southern California Edison Co 80/09/03 77pp
- ~-8009050308 "CPC/CEAC Software Mods for San Onofre Unit 2 " Proprietary version withheld (ref 100FR2 790) \* Combustion Engineering, Inc. CEN~[35(5)-NP 80/08/31 79pp
- 8009110547 Notification of 800910 meeting w/util & C-E in Bethesda.MD to discuss NRC questions re CENPD-178
  ROOD,H Licensing Branch 3 80/09/04 3pp
- 8009120273 Notification of 800909 maeting w/util & C-E in Windsor,CT to discuss audit of GENND-178 analysis methods RODD,H &icensing Branch 3 80/09/04 3pp
- 8009180330 Forwards questions re Exacutive Order 11988 Flood Plain Mgt Response requested by 800912 TEDESCO.R L Assistant Director for Licensing 80/09/04 App
- 8009290143 Notification of 800926 meeting w/utils & Kerr-McGee Chemical Corp in Bothesda, MD to discuss review & recommendations for site specific ground response spectra & program plans for seismic functional qualification of Class IE equipment ALLISON, D.P. Systematic Evaluation Program Branch 80/09/08 3pp
- B009190913 Notification of B00923 meeting w/util.USOS & CDMO in Menlo Park,CA to discuss seismology & geology re facilities ROOD,H Licensing Branch 3 80/09/09 3pp
- BOOPIB0421 Forwards response to hydraulic engineering questions re flood plain mgt. per NRC 800904 request Site does not fall within floodplain as defined by Executive Order 11988 BASKIN.K P Southern California Edison Co 80/09/10 4pp
- --8009180429 "Preconst Floodplains.Units 2 & 3 "
  \* Southern California Edison Co 80/09/10 tp
- --8009180433 "Post-Const Floodplains, Units 2 & 3 "
  \* Southern California Edison Co 80/09/10 ip
- 8009250150 Approves of util 800115 plans to terminate preoperational monitoring program
  SCHWENCER, A Licensing Branch 3 80/09/11 3pp
- 8009250451 Forwards proposed memorandum of agreement for San Unofre transmission lines & two ltrs from State of CA.Dept of Parks & Recreation.per 800909 telcon Formal request for concurrence will follow shortly SCALEITI.D C Licensing Branch 3 80/09/13 9pp
- --8009290456 Informs of assuming H Bass responsibilities Requests informal meeting w/MRC to discuss directions of mutual interests in preserving cultural resources BELL,D A California, State of 80/04/18 tp
- F. Security, medical, emergency  $\lambda$  fire protection plans
- 8007030338 Notifies of 800817.22 & 30 regional workshops re development of guidance for acceptable method for coping w/emergencies at facility Requests that representative be sent Subj areas to be discussed include function of facilities & location ENGELKEN,R H Region 5. San Francisco. Office of the Director 80/08/12 2pp
- B00B270278 Forwards Jul 1980 revised emergency plan, in response to NRC 791031 request for addl info Licensee is assisting local govt in devising emergency response procedures
  BASKIN,K P Bouthern California Edison Co 80/08/18 2pg
- --8008270289 Emergency plan \* Southern California Edison Co \* San Diego Gas & Electric Co 80/07/31 223pp

- 80090303B7 Forwards revised safeguards contingency plan per NRC 791211 & 800324 requests Plan withheld (ref 10CFR2 790) BASKIN.K P Southern California Edison Co 80/08/28 2pp
- 8009050286 Forwards Revision 1 to security force training \$
  qualification plan Plan withheld (ret 100FR2 790)
  BASKIN, K.P. Southern California Edison Co. 80/09/03 ip
- 8007240347 Forwards emergency planning into for placement in local PDR SOUDER, J t Division of Rules and Records 80/09/04 ip
- G Adjudicatory correspondence
- BOO9020059 Order establishing discovery schedule Discovery re geology, sessmology & emergency planning shall end 30 days following NRC safety evaluation & svc of emergency plan Depositions shall be completed 40 days after such svcs BMITH. I W Atomic Safety and Licensing Board Panel BO/08/27 5pp
- 80091A0339 Forwards NUREG-75/111.NUREG-0654 & NUREG-0696 in response to 800811 telcon re emergency planning info W/o encls DAVIS.L D Hearing Branch 4 80/05/27 ip
- 8009110376 Forwards stipulation to extend time within which Southern CA Edison Co will answer intervenor Friends of The Earth B00811 interrogatories PIGOTT, D.R. Chickering & Gregory 80/09/03 1p
- --8007110377 Stipulation between parties, allowing Southern CA Edison Co extension until 800715 to respond to intervenor Friends of The Earth 800911 interrogatories Approved by ASLB on 800708 PTOUTT, D.R. Southern California Edison Co. P10077-D.R. San Diego Cas & Electric Co. P10077-D.R. Chickering & Gregory 80/08/27 200
- 8009100406 Interrogatories directed to NRC re Cristianitos fault, Newport-Inglewood-Rose Canyon-San Miguel fault ione & other seismic-related issues Certificate of Svc encl MHARTON, R J . POGALIES, J K Friends of the Earth WHARTON, R J Wharton & Pogalies 80/09/04 17pp
- BOO9170299 Responds to FOIA request for 19 documents listed in bibliography fo NUREG-0625, "Rept of Siting Policy Task Force " Documents &-8 % 13 are available in PDR Forwards remaining documents FELTURAL M Division of Rules and Records 80/09/04 1p
- ---BOD9190587 Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants, for determination of site acceptability & adequacy of engineered safety features
  MINOQUE.R B Office of Standards Development, Director
  SECY-79-362 79706/04 7pp
- --B009190630 Requests that encl. "Differences in Procedures for Estimating Atmospheric Dispersion Conditions at Inland & Coastal Sites." be sent to appropriate Boards SCINTD. J F Hearings Division 79/04/04 Lépp
- 8007090774 Forwards 800819 FR notice re final rules upgrading emergency planning regulations, effective 801103 CHANDLER, L. J. Hearing Branch 1 80/09/05 19pp
- 8009160341 Advises that NUREG-75/111.NUREG-0654 & NUREO-0696 were mailed on 800927 per 800828 inquiry about emergency planning info Discovery requests should be made through counsel Wharton DAVIS, D Hearing Branch 4 80/09/11 1p
- 8009190083 Response to intervenor Friends of The Earth 800811 fourth sot of interrogatories Objects to portions requesting production of documents Certificate of Svc encl PIODITIO R. CASEYIS B. KOCHER. C. R. Southern California Edison Co 80/09/15 46pp
- H General correspondence
- 8009050357 Urgss NRC not to issue low power fuel loading license for Unit 2 LITFIN.K Affiliation Unknown 80/09/28 1p
- 8009:10398 Opposes low level testing / licensing of facility, since no evacuation plan possible MARTINEZ, P. R. Affiliation Unknown 80/08/29 1p
- 8009120444 Opposes licensing of facility for low level testing due to undue risks posed to health % safety of public % environ BRONN-P Affiliation Unknown 80/08/27 ip

- 8009050390 Expresses opposition to nuclear energy & licensing of Unit 2 COHEN, P Affiliation Unknown 80/09/03 in
- 8009110430 Opposes granting low power loading license to avoid avacuation plan requirements
  PULIDG:M Affiliation Unknown 80/09/03 1p
- 8009100448 Forwards updated 10CFR2.50.51 & 100 W/o encl CHANDLER.L J Hearing Branch 1 80/07/05 1p
- 800912018B Upposes granting low-power fuel loading license, or any license, to Unit 2 Requests any info re new developments concerning facility operation PAULSON K Affiliation Unknown 80/09/05 Ip
- B009230537 Protests plant licensing even if authorization is only for operation at 5% capacity Expresses concern that conversion to safe nonnuclear fuels will consequently be more difficult
  MARTIN. # Affiliation Unknown B0/09/14 ip
- 8007230633 Forwards transcript of 800814 public meeting in Bethesda. KD re seismic issues Similar documents usually available at LPDR N/o encl DAVIS. L D Hearing Branch 4 80/07/18 ip
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8009190338 Forwards Amend 20 to FSAR Amend contains responses to NUREG-0660 & NUREG-0694, "TMI-Related Requirements for New OLs" DIEICH, R Southern California Edison Co 80/09/12 19
- ---8009190344 Application for amend to facility license applications, incorporating Amend 20 to FSAR Amend consists of responses to NUREO-0694 & NUREO-0660. "TMI-Related Requirements for New OLs"

  \* Southern California Edison Co GILLMAN,D W San Diego Gas & Electric Co 80/09/12 3pp
- --8009190391 Amend 20 to FSAR. including responses to NUREQ-0640. "TMI-Related Requirements for New ULs"

  \* Southern California Edison Co \* San Diego Gas & Electric Co
  80/08/31 225pp
- Q Inspection reports, IE Bulletins & correspondence
- B007020258 Forwards IE Insp Repts 50-361/80-07 & 50-362/80-06 on B00428-0501 No noncompliance noted SPENCER, G & Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/07/10 2pp
- ---8009020267 IE Insp Repts 50-361/80-07 & 50-362/80-06 on 800428-0501
  No noncompliance noted Major areas inspected const
  activities including previous open items & equipment storage
  & maint
  ECKHARDTJ H , ELIN, J O Region 5, San Francisco, Office of the
  Director HAYNES.R C Region 5, San Francisco, Reactor
  Construction & Engineering Support Branch 80/07/10 App
- 8009160626 Responds to IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME 8A-312, Type 304 Stainless Steel Pipe " Only piping components subjected to design stresses greater than 85% of allowable stresses listed in encl
  BASKIN,K P Southern California Edison Co 80/08/01 7pp
- SOO9260297 Forwards IE Info Notice BO-29, "Broken Studs on Terry Turbine Steam inlet Flange" No written response required ENOELKEN,R H Region S. San Francisco, Office of the Director BO/88/07 ip
- BOO9030280 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Watted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required, ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/08/15 1p
- 8009290457 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " ENOELKEN.R H Region 5, San Francisco, Office of the Director 80/08/18 4pp
- 8009160184 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required EMOEKENIAR H Region 5, San Francisco, Office of the Director 80/08/22 1p

- BOORGOOD!7 Submits response to IE Bulletin 80-16 Rosemount Models 1151 1152 pressure transmitters are not planned for use in safety-related applications BASKIN.R P Southern Callfornia Edison Co 80/08/26 2pp
- BOOP:20463 Forwards IE Info Notice BO-31. "Maloperation of Gould-Brown Boxeci 480 Volt Type K-600S & K-DDN 600B Circuit Breakers " No written response required ENGELKENR H Region 5. San Francisco, Office of the Director 80/08/27 1p
- S Reportable occurrences, LERs & related correspondence
- 8009090470 Final deficiency rept re lubricated armature bumpers on some NEMA Bize 3 starters & contactors mfg by Square D Co All 30 suspect starters will be inspected during Sept 1980 Starter bumpers containing lubricant will be replaced PAPAY, L T Southern California Edison Co 80/09/03 3pp
- B009300431 Final deficiency rept re excessive bypass flow for high pressure safety injection pumps Orifice assembly design has been modified by manufacturer & will be installed by B01015 PAPAY.L T Bouthern Galifornia Edison Co 80/09/25 3pp
- T Hearing transcripts on non-antitrust matters
- 8009100021 Summary of 800814 meeting w/util & USGS in Bethesda,MD re offshore exploration results Transcript encl RCCD,H Licensing Branch 3 80/08/21 4pp
- --8009100024 Transcript of 800814 public meeting w/util & USGS in Bethesda: MD re offshore exploration results Pp 1-76 Licensing Branch 3 80/08/14 85pp
- DOCKET 50-363 FORKED RIVER NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8000080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREO EISENHUT.D G Division of Licensing 80/08/01 119pp
- G Inspection reports, IE Bulletins & correspondence
- 80090300042 Forwards Revision i to 1E Bulletin 80-19, "Failures of Hercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER,B H Region i, Philadelphia, Office of the Director BO/08/15 ip
- 8007180004 Forwards IE Circular 80-18, "100FRS0 57 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response requered GRIER.B K Region i. Philadelphia. Office of the Director
- 8009120177 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 t K-DON 6008 Circuit Broakers " Wo written response required GRIER, B H Region 1, Philadelphia. Office of the Director 80/08/27 1p
- 8009240032 Forwards IE Circular 80-21. "Regulation of Refueling Crews " ORIER. B H Region i, Philadelphia, Office of the Director 80/09/10 ip
- 8009240311 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required ORIER.B H Region I, Philadelphia, Office of the Director 80/09/12 1p
- DOCKET 50-364 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- B009080294 Forwards "Betpoint Study for Farley 1 ½ 2." proprietary (WCAP-B313) & monproprietary (WCAP-9768) versions Application & affidavit for withholding encl ANDERSON T M Westinghouse Electric Corp 80/07/25 13pp

- --8009080299 "Setpoint Study for Farley 1 & 2," nonproprietary version KG.M Westinghouse Electric Corp ORTENBERG,L I . ROSSI.C E Westinghouse Electric Corp , Nuclear Energy Systems WCAP-9768 74/05/31 216pp
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities 'Comments requested within 30 days Proposed implementation schedule for meeting criteria or NUREG-0696 encl M/o NUREG EISENHUT. D G Division of Licensing 80/08/01 1:9pp
- 8007020030 Forwards util position on licensing issues re-shift manning, low power test procedures, high range radiation detection, fire protection & security plan CLAYTON, F. L. Alabama Power Co. 80/08/19 4pp
- 8009020045 Forwards info ra TMI-2 action plan per 800716 request CLAYTON F L Alabama Power Co 80/08/20 3pp
- 8007020038 Provides addl info re shirt supervisor functions in response to NRC 800819 request One of two shirt supervisors will be designated as supervisor in charge & will hold Unit 1 & Unit 2 license CLAYTON F L Alabama Power Co 80/08/22 1p
- 8009090128 Forwards request for add1 info re RCS vents RHR sys & bypass, override & reset circuits of engineered safety features TEDESCO.R L. Assistant Director for Licensing 80/08/25 18pp
- 8009170174 Informs that facility will be ready for fuel loading to low power testing license by 800919 Submits info to assist in obtaining proper fee for license SCHWENCER.A Licensing Branch 2 80/08/27 2pp
- 8009030492 Submits add1 info requested by NRC 800124 ltr re qualification of Barton Lot 2 transmitters Review of differential pressure transmitters proved acceptable for respective functions CLAYTON,F L Alabama Power Co 80/08/28 Ip
- 8009080387 Forwards summary t results of 800819 working session w/NRC re hot shutdown panel.per 800814 telcon w/NRC CLAYTON.F L Alabama Power Co 80/08/28 2pp
- 8009110541 Notification of 800905 meeting w/util & Westinghouse in Bethesda.MD to discuss Westinghouse proposed response to staff questions re WCAP-7292 KINTNER.L L. Licensing Branch 2 80/08/29 3pp
- B009190409 Informs of 800903 meeting w/Commission re DL for facility Draft SER Suppl 4, license & Tech Specs, addendum to FES & licensee B00925 ltr demonstrating compliance w/Commission regulations encl W/o encls DENION.HR Office of Nuclear Reactor Regulation, Director 80/08/27 ip
- 8009230767 Notification of 800902-03 meeting w/util in Zion.IL to run selected transients & accidents on simulator & to evaluate emergency operating procedures KINTHER.L L Licensing Branch 2 80/09/29 2pp
- 8007040246 Submits response to NRC request resulting from 800821-28 10740240 Submits response to NRC request resulting from the meeting re App A Tech Specs 3 3 3 8. 'Accident Monitoring Instrumentation' 8 3 7 9. "Snubbers " Info should be considered in development of final App A Tech Specs CLAYTON,F L. Alabama Power Co. 80/09/02 5pp
- --8009040251 Proposed Tech Specs 3 3 3 8 % 4 3 3 8 re accident monitoring instrumentation limiting condition for operation & surveillance requirements, respectively # Alabama Power Co 80/09/02 3pp
- 8009040386 Forwards "Special Low Power Tests Safety Evaluation." & draft startup test procedures. "Cooldown Capability of Charging & Letdown Sys,' "Natural Circulation." & "Forced Circulation Cooldown" CLAYTON, F L Alabama Power Co 80/09/02 7pp
- --8009040387 "Special Low Power Tests Safety Evaluation " \* Alabama Power Co 80/08/31 47pp
- --8009040389 Draft Phase III Test Procedure 501-7-001. "Cooldown Capability of Charging & Latdown Sys " \* Alabama Power Co 80/07/24 14pp
- --8009040390 Draft Phase III Test Procedure 501-7-002, "Natural Circulation " \* Alabama Power Co 80/07/24 49pp

- ---8009040391 Draft Phase III Test Procedure 501-7-003, "Forced Circulation Cooldown "

  \* Alabama Power Co 80/08/10 41pp
- --8007040373 Braft Phase III Test Procedure 501-7-003, "Natural Circulation W/Simulated Loss of Power Conditions" \* Alabama Power Co 80/07/28 41pp
- --8009040395 Draft Phase III Test Procedure 501-7-004. "Effect of S/Q Secondary Bide Isolation on Natural Corculation " Alabama Power Co 80/07/29 42pp
- 8007080293 Forwards info re Category I masonry walls, per NRC 800421 request Oversize Grawings available in Central Files only CLAYTON, F.L. Alabama Power Co. 80/09/02 4pp
- 8009070566 Requests that radiological ETS for Unit 2,NRC approved during wk of 800825, be implemented for Unit 1 on 810101 to assure consistent implementation for both units CLAYTON, F. L. Alabama Power Co. 80/09/02 1p
- 8009120425 Requests that Tech Specs re exposure of fuel assemblies & control rods remain unchanged until after receipt of Unit 2 full power Ci.

  CLAYTON.F L Alabama Power Co 80/09/03 tp
- 8007150484 Forwards proposed mod to auxiliary feedwater flow control solengid valves per NRC license requirement for fuel loading t lower pawer testing CLAYYON.F.L. Alabama Power Co. 80/09/08 4pp
- 8009160415 Forwards response to NRC request for add1 info re Reactor Sys Branch Question 210 1.Item 3 re cavitation & air CLAYTON F L Alabama Power Co 80/09/08 3pp
- 8009240551 Forwards request for add] into & Power Sys & Mechanical Engineering Branch positions re overload protection design & RCPB safety 148 respectively TEDESCG.R L Assistant Director for Licensing 80/09/10 9pp
- 8009170353 Forwards Phase III Test Procedure 501-7-003, "Natural Circulation W/Bimulated Loss of Offsite AC Power," & Phase III Test Procedure 501-7-006, "Conling W/Simulated Loss of Power Conditions"

  CLAYION,F 4. Alabama Power Co. 80/09/11 4pp
- --8009170356 Phase [[[ Test Procedure 501-7-006, "Cooling W/Simulated Loss of Power Conditions" \* Alabama Power Co 80/09/08 25pp
- 8009300051 Notification of 800918 meeting w/util in Bethesda.MD to discuss review of license application KINTNER.L. Licensing Branch 2 80/09/11 Jpp
- 800930028B Natification of 80091B meeting w/ut:1 in Bethesda.MD to review containment purge requirements.RCS vents & leakage tosts for RCS valves KINNMER.L Licensing Branch 2 80/09/11 2pp
- 8009190259 Forwards Amend 74 to FSAR for Unit 1 & to application for *OL* for Unit 2 Certificate of Svc enci CLAYTON F L Alabama Power Co 80/09/12 2pp
- --8009150260 Amend 74 to application for OL for Unit 2 % to FSAR for Unit CLAYTON, F.L. Alabama Power Co. 80/09/12 1p
- --8009150263 Amend 74 to FSAR \* Alabama Power Co 80/0 80/09/12 900
- 8007170214 Forwards "Environ Qualification of Class IE Equipment," response to NURES-0388 Response withheld (ref 100FR2 790) CLAYTON,F L Alabama Power Co 80/09/12 9pp
- 8009230465 Forwards add1 info re potential design deficiencies in hypacs.override L reset circuits of engineered safety features, in response to NRC 800825 itr CLAYTOM F L Alabama Power Co 80/09/12 App
- 8009230448 Forwards add1 into re turbine trip w/o reactor trip below 50% power in response to Item C 3 10 of II K 3 in NUREG-0694 CLAYTON:F L Alabama Power Go 80/09/16 14pp

- 8009290329 Notifies of incorporation of add1 documents into license application NPF-B. Item 2 C 6, per App 0 100FR50 Westinghouse Topical Rept. HCAP-992 & responses to NRC 790725 request for info filed w/NRC CLAYTON: F L Alabama Power Co 80/09/22 2pp
- 8009300391 Forwards summary of results achieved at 800919 meeting re isolation of hot shutdown panel & main control board instrumentation mods.resulting from NRC 800915 request for addl info CLAYTON F L. Alabama Power Co. 80/09/22 2pp
- 9009290391 Forwards response to NRC Power Sys Branch Questions 040 1-040 14 rs diesel generators CLAYTON:F L Alabama Power Co 80/09/24 24pp
- F Security, medical, emergency & fire protection plans
- 8009160324 Summarizes 800812 meeting & 800815 telcon re completion of fire protection sys & equipment installation Mods are scheduled for completion in late Oct 1980 CLAYTON-F L. Alabama Power Co. 80708/18 2pp
- 8009020030 Forwards util position on licensing issues to shift manning, low power test procedures, high range radiation detection, fire protection, t security plan CLAYTON, F L Alabama Power Co 80/08/19 App
- 8007230249 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency O'REILLY, J P Region 2, Atlanta. Office of the Director 80/08/22
- Q Adjudicatory correspondence
- B009090415 Authorizes Director of Ofc of Nuclear Reactor Regulation to issue License NPF-8 for fuel loading \$ low power testing HOYLE.J C Office of the Secretary of the Commission 80/09/05
- 8009220226 Comments on rulemaking 50-5 GEBMO proceedings should be reopened Tachnical.economic & safety issues must be addressed in order for decisions to be made re use of mised-oxide fuels
  WEITZBERG.A Affiliation Unknown 80/09/15 1p
- 8009300407 Informs of M Farrer resignation from full-time ASLAP position Name should be deleted from svc list for all but Farley antitrust proceeding Svc list for all other dockets need contain only two ASLAB members
  ROSENTHAL.A 8 Atomic Safety and Licensing Appeal Panel 80/09/25
- H General correspondence
- 8007300435 Requests that distribution list be revised to reflect recent agt-level reorganization WO Whitt has assumed responsibilities formerly assigned to AR Barton CLAYTON.F L. Alabama Power CO 80/07/23 ip
- M Antitrust correspondence
- 8007070337 Motion for issuance of decision at earliest convenience Proceeding pending since 770308 Certificate of Svc encl Granted by AELAS on 800708 BLUME: M B Antitrust Division 80/07/05 3pp
- 8009260662 Response in support of NRC 800905 motion for issuance of decision issues; if resolved, will affect future power supply b devalopment of supply planning Injury may occur if delayed Certificate of Svc encl HJECHFELT,D C Municipal Electric Utility Association, Alabama HJELHFELT,D C Hjelmfelt,D C 80/09/23 3pp
- Q Inspection reports, IE Bulletins & correspondence
- 8009020466 Forwards IE insp Repts 50-348/80-15 & 50-364/80-18 on 800823-24 No nencompliance noted STOMR.J P Region 2. Atlanta. Fuel Facility & Materials Safety Branch 80707/14 2pp
- --8009020477 IE Insp Repts 50-348/80-15 & 50-364/80-18 on 800423-26 No noncompliance noted Major areas inspected radwaste mgt 018503,A F Region 2, Atlanta, Fuel Facility & Materials Safety Branch WRAY,J R Region 2, Atlanta, Office of the Director 80/07/11 App

- 8009103040 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Written response required D'REELLY, J.P. Region 2, Atlanta, Office of the Director B0/07/24
- 8009090415 Forwards IE Insp Rept 50-364/80-20 on 800630-0702 No noncompliance noted MARPHY.C E Region 2. Atlanta Reactor Construction & Engineering Support Branch 80/07/25 2pp
- --8009050421 IE Insp Rept 50-364/80-20 on 800630-0702 No nuncompliance noted Major areas inspected preservice insp activities CROWLEY.B R Region 2, Atlanta, Office of the Director HERDI, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/25 Spp
- B009110102 Forwards IE Insp Repts 50-348/80-19 & 50-364/80-23 on 800602 -30 No noncompliance noted LEMIS, R C Region 2 Atlanta, Reactor Operations Nuclear Support Branch B0/07/29 2pp
- --B009110202 IE insp Repts 50-348/80-19 % 50-364/80-23 on 800602-30 No noncompliance noted Major areas inspected sys integrity outside containment, monitoring instrumentation, radiation controls fluid leaks, piping vibration & fire hazards BRADFORD W H , MARTIN, R D Region 2. Atlanta, Office of the Director 80/07/28 7pp
- 8009050032 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " No 300 series Fusion welded pipe used in safety-related sys subj to stresses greater than 85% of max allowable stresses CLAYTOM.F. L. Alabama Power Co. 80/08/01 2pp
- 8009120045 Forwards IE Insp Repts 50-348/80-14 & 50-364/80-16 on 800509-13 & 16-20 t notice of violation LENIG.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/08/08 2pp
- --8009120052 Notice of violation from insp on 800609-13 & 16-20 + Region 2. Atlanta, Office of the Director 80/08/06 2p
- --8009120071 IE Insp Repts 50-348/80-14 & S0-364/80-16 on 800609-13 & 16-20 Noncompliance noted failure to provide definitive corrective action for identified matl storage inadequacies & failure to control consumables in safety-related sys BELISLE, G A , FORD, E J Region 2, Atlanta, Office of the Director UPRIONT, C M Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/08/06 35pp
- BOO9020301 Forwards revisions to 800107 response re IE Bulletin 79-02.

  "Pipe Support Base Plate Designs Using Concrete Expansion
  Anchor Bolts." Revision 2.1tem 7 & 800115 response to IE
  Bulletin 79-14 re as-built safety-related piping sys
  CLAYJON.F L Alabama Power Co 80/08/15 7pp
- 8009830123 forwards Revision I to IE Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/08/15
- 8009100237 Ack receipt of IE Insp Rept 50-364/80-24 on 800708-11 No proprietary info CLAYTON,F L Alabama Power Co 80/08/22 ip
- --8009100330 Forwards 1E Insp Rept 50-364/80-24 on 800708-11 No noncompliance noted MURTHY,CE Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/01 2pp
- 8009160110 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22

- 9009120251 Forwards IE Info Notice 80-31, 'Ifaloperation of Gould-Brown Bovert 480 Volt Type K-6008 ? K-DON 6008 Circuit Breakers " No written response required O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/08/27
- 8009110687 Responds to IE Bulletin 80-19 Mercury-wetted relays not utilized in reactor protection sys in either facility CLAYTON.F L. Alabama Powei Co. 80/08/29 ip
- 8009190576 Ack receipt of 800812 Itr informing NRC of steps taken to correct violations noted in IE Insp. Repts 50-348/80-16 t 50-364/80-19 MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/09/03 2pp
- --8009190383 Responds to NRC 800723 ltr re violations noted in IE Insp Repts 50-348/80-16 % 50-344/80-19 Corrective actions testing & analysis initiated to determine probable error introduced through improper use of torque multipliers CLAYTON, F.L. Alabama Power Co. 83/08/12 5pp
- --8009190588 Forwards IE Insp Repts 50-348/80-16 & 50-364/80-19 on 830617-20 & notice of violation MURPHY, C.C. Region 2. Atlanta, Roactor Construction & Engineering Support Branch 80/07/23 2pp
- --B009190593 Notice of violation from insp on 800517-20
  \* Region 2. Atlanta. Reactor Construction & Engineering Support
  Branch 80/07/21 2pp
- --8009170609 [E Insp Repts 50-348/80-16 5 50-364/80-19 on 800617-20 Noncompliance noted torque wrench multiplier used for IE Bulletin 79-02 testing not controlled or calibr & inadequate instruction for mod & insp of support ANO, W P Region 2. Atlanta. Office of the Director HERDT, A Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/21 4pp
- 8007290276 Forwards IE Circular 80-21. "Regulation of Refueling Crews"
  No written response required
  O'REILLY, J P Region 2, Atlanta, Orrice of the Director 80/09/10
  Son
- S Reportable occurrences, LERs & related correspondence
- B009100363 Deficiency evaluation rept re Westinghouse centrifugal charging pump operation following secondary side high energy line rupture Design change implemented to remove safety injection initiation closure signal from isolation valves CLAYTON.F L Alabama Power Co 80/08/20 4pp
- T Hearing transcripts on non-antitrust matters
- 800-9180222 Transcript of 800-904 meeting in Washington, DC re low power UL Pp 1-9  $\times$  Commission 80/09/04 12pp
- V Operator Examinations
- 8009100318 Forwards revised operating shift manning & training schedule per 800804 exam results & 800904 verbal request CLAYTON,F L Alabama Power Co 80/09/08 App
- 6009300498 Advises that training program for mitigating core damage is scheduled to commence on 800929 & to be completed by mid Nov 1980 Training program will become part of requellification program CLAYID.F. L. Alabama Power Co. 80/09/24 ip
- 8009300463 Revises commitments submitted 800924 re training for mitigating core damage Selected personnel will receive pertinent training in areas where assistance would be expected in event of severe core damage CLAYTON
- DOCKET 50-366 EDMIN I MATCH NUCLEAR PLANT, UNIT 2

  F Security, medical, emergency & fire protection plans
- 8009230265 Requests that all personnel be reminded of purpose of emergancy notification sys & health physics network Sys installed for govt use during emergency D'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/22 to

- 8009030484 Nutrifies that final version of upgraded emergency plan will be submitted by B10102 WIDNER,U A Goorgia Power Co 80/08/28 lp
- 8009160448 Informs of util concept of physical means for alerting & providing clear instructions to populate within plume exposure emergency planning zone Design concept is to provide tone alert receivers for all establishments in zone WIDNER, N.A. Georgia Power Co. 80/09/12 3pp

### G Adjudicatory correspondence

- 8007240577 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 REID.R W Operating Reactors Branch 4 80/08/27 2pp
- --8009240603 Order for mod of Licenses DPR-57 & NPF-5 to add info which fully responds to NRC request for into re environ qualification of safety-related electrical equipment Info should be submitted by 801101 EISENBUT.D & Division of Licensing 80/08/29 App

# P Operating license stage documents & correspondence

- 8009110554 Suppls NRC 800707 request for proposed Tech Specs changes re scram discharge vol vent & drain valves. & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT.D G Division of Licensing 80/07/22 22pp
- BOO9020297 Submits interim criteria for shift staffing to all OL & CP livensees & applicants, per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D C Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o RUREG EISENHUT, D G Division of Licensing 80/08/01 119pp
- 8007230052 Informs that exemption from fee relicensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D.Q. Division of Licensing 80/08/07 60pp
- 8009230763 Forwards "Mark 1 Containment Long-Term Program SER, Resolution of Generic Technical Activity A-7," NUREG-0661 W/o encl REID, R V Operating Reactors Branch 4 80/08/20 2op
- 8009180163 Lists issues to be addressed re restart of unit Items identified should be resolved prior to Eycle 2 operation & do not include anticipated submittals of Fech Spec changes Requests response advising of submittal date for each item VERRELLI,D M Operating Reactors Branch 4 80/08/26 3pp
- 8009190423 Application for amend to Licenses DPR-57 & NPF-5 consisting of changes to Tech Specs WIDNER, N.A. Georgia Power Co. 80/09/15 App
- --8009190432 Proposed changes to Tech Specs Tables 3 3 6 4-1.4 3 6 4-1 & 6 2 2-1 & Tech Specs 6 3 for unit staff qualifications.6 4 for training & 6 5 for review & audit + Georgia Power Co 80/09/15 Spp

# Q Inspection reports, IE Bulletins & correspondence

- 8009090057 Forwards IE Bulletin 80-07. Suppl 1. "BWR Jet Pump Assembly Failure" No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/13 to
- 8009150332 Forwards IE Insp Repts 50~321/80-26 & 50~366/80-26 or 800625-26 No noncompliance nated MURPHY:C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/23 2pp
- --8009150370 IE Insp Repts 50-321/80-26 & 50-366/80-26 on 800625-26
  No noncompliance noted Major areas inspected settling of structural backfill around RHR & plant svc water intake structure & piping HARRIS.JR Region 2. Atlanta. Office of the Director CONLOUIT E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/07/22 3pp

- 8009220265 Forwards IE Insp Repts 50-321/80-24 & 90-366/80-24 on 800513-0609 / notice of violation LEWIS.R C Region 2. Atlanta Reactor Operations Nuclear Support Branch 80/07/25 2pp
- ~~8009220337 Notice of violation from insp on 800513~0607 LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/07/25 1p
- --8009229341 IE Insp Repts 50-321/80-24 & 50-366/80-24 on 800513-0609 Noncompliance noted motor bearing cooling water inlet valves were found improperly shut on RMR svc water pumps DANCE.H C Region 2. Atlanta. Reactor Operations Nuclear Support Branch ROCERS.R F Region 2. Atlanta, Office of the Director 80/07/25 9pp
- 8009050076 Forwards partial response to IE Bulletin 80~08, "Exam of Containment Liner Penetration Nelds " Seven welds failed hondestructive examination Unit 1 containment & Unit 2 torus penetration info forthcoming WIDNER.N A Georgia Power Co 80/08/05 8pp
- 8009020287 Submits response to IE Bulletin 80-17.Suppl 1 Procedures have been established to assure operability of scram discharge vol WIDNER.W A Occupia Power Co 80/08/07 2pp
- 8009030194 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Marcury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/15 ip
- 8009020180 Responds to Suppl 1 of IE Bulletin 80-17 re failure of control rods to insert during scram at BNR Existing design of facility meets requirement for continuous monitoring of water level in Scram discharge vols WIDNER, WA Occordia Power Co 80/08/19 2pp
- 8009020393 Submits status of recent util efforts towards compliance w/ IE Bulletin 79-010, "Environ Qualification of Class IE Equipment " Util has joined BMR owners group effort on bulletin WIDNER, H A Georgia Power Co 80/09/19 2pp
- 8009160039 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain OE BWR Facilities "No specific action or response requested O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/19 is
- 8009230105 Submits response to IE Bulletin 79-018 Expects to complete qualification test program & component replacement by 820430 WIDNER, N.A. Georgia Power Co. 80/08/17 2pp
- 8009:1067: Responds to IE Bulletin 79-01B Forwards 90-day repts re environ qualification of Class IE equipment, summary of outstanding items & summary of equipment w/iess than 40-yr aging qualification W/o encis WIDNER, W A Georgia Power Co 80/08/22 2pp
- 8009120077 Forwards Suppl 3 to IE Bulletin 80-17, "Failurs of Control Rods to Insert During Scram at BWR " Written response required O'REILLY,J P Region 2, Atlanta, Office of the Director 80/08/22
- 8009160147 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/22
- 8007110824 Ack receipt of 800731 ltr informing NRC of steps taken to carrect deviations noted in 16 Insp Repts 50-321/80-02 & 50-366/80-02 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/08/25 ip
- --8009110828 Responds to NRC 800208 ltr re violations noted in JE Insp Repts 30-321/80-02 & 50-366/80-02 Corrective actions relocation of fire pump controller & installation of tamper alarms for fire valves to be completed Aug 1980 WIDNER, W.A. Georgia Power Co. 80/07/31 ip

8009030442 Forwards LER 80-106/03L-0 MA'RY, M Georgia Power Co 80/08,

```
8009120311 Forwards IE Into Notice 80-31, "Maloperation of Gould-Brown
Bovers 480 Volt Type K-600S & K-DON 600S Circuit Breakers "
Ro written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/27
9009110676 Responds to 1E Bulletin 80-15 Emergency natification sys
powered by telephone company To ensure sys extensions
operate independently of plant phones, testing was conducted
on 800815 All extensions operable during power trip
NIDMER, W.A. Georgia Power Co. 80/08/29 ip
 8009230204 Forwards IE Insp Repts 50-321/80-34 & 50-366/80-34 on
     800813-14 No noncompliance noted
KENNA, W B Region 2, Atlanta Safeguards Branch 80/08/29 ip
 --8009230210 1E Insp Repts 50-321/80-34 & 50-366/80-34 on 800813-14 No
          oncompliance noted Major areas inspected licenses implementation of contingency strike plan Details withheld (ref 10CFR2 790)
MCGUIRE D R Region 2. Atlanta, Safeguards Branch TOBIN.
          REGUIRE,D R Region 2. Atlanta, Safeguards Branch
Region 2. Atlanta, Office of the Director 80/08/27
                                                                                                                        L MINIBOT
 8009230525 Forwards Revision 1 to IE Bulletin 79-26, "Boron Loss From BMR Control Blades" Written response required O'REFLLY, J.P. Region 2, Atlanta, Office of the Director 80/08/29
 8009240367 Responds to IE Bulletin 80-17. Suppl 3 Outlines procedures in effect re loss of instrument air.loss of control rod driveline. rod drift b undrained scram discharge vol Function test of switches required prior to startup MIDHER. If A Georgia Power Co 80/08/29 2pp
 8009290282 Forwards IE Circular 80-21, "Regulation of Refueling Crews"
     No written response required
D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/10
 8007300104 Submits response to IF Bulletin 80-20 No Westinghouse Type
H-2 control switches used in safety-related applications
HIDNSR,W A Georgia Power Co 80/07/12 1p
 R Periodic operating reports & related correspondence
 80070304[5 Forwards "Semiannual Radioactive Effluent Release Rept."
      Jan-June 1980
MANNY M One
                           Qeorgia Power Co 80/08/30 1p
 --- 8009030419 "Semiannual Radioactive Effluent Release Rept." Jan-June
                Qeorgia Power Co 80/08/30 44pp
 8009180496 Forwards monthly operating rept for Aug 1980
MAXAY.M Georgia Power Co 80/09/10 ip
---8009180235 Montbly operating rept for Aug 1980
UNDERWOOD, P. R. Georgia Power Co. 80/09/10 9pp
& Reportable occurrences, LERs & related correspondence
8007030451 Forwards LER 60-113/03L-0
MARRY.M Georgia Power Co 80/08
                                                                  B0/08/25 1o
--BC09030461 LER 80-113/03L-0 on 800726, w/reactor in shutdown mode following performance of manual scram per IE Bulletin 80-17, scram discharge vol hi level switches 2011-N013A & D found inoperable Caused by crushed floats Rept update to follow CQGOIN.C L Georgia Power Co 80/08/25 2pp
8007020369 Forwards LER 80-109/03L-0
MANRY,M Georgia Power Co 80/08/26 ip
--8009020374 LER 80-109/03L-0 on 800809, while performing HPC1 valve operability, HPC1 suppression chamber suction valve 2E41-F041 failed when cycled to check for battery ground Caused by meter winding failure due to high temp Motor repaired UIX.R T Georgia Power Co 80/08/26 2pp
8009020400 Forwards LER 80-122/03L-0
MARRY.M Georgia Power Co 80/08/26 1p
---8009020405 LER 80-122/03L-0 on 800811.during steady state operation at full power.while performing HNP-2-3001, reactor high pressure instrument test: switch 2821-1023C actuated at 1,068 psig Caused by setpoint drift Switch recallibr NIX.R T Georgia Power Co. 80/08/26 ip
```

```
--8009030447 LER 80-106/03L-O on 800728.w/reac+or in cold shutdown, potassium sylfate, matural ascanite & potassium hydrogen sulfite deposits discovered around spems on sacrificial shield Cause undotermined Update rept uill be submitted CDGGIN,C L Georgia Power Co 80/08/26 2pp
8009020352 Forwards LER 80-119/02L-0
MAPRY,M Georgia Power Co 80/08/27 ip
 --8009020347 LER 80-119/02L-0 on 800805, during QA audit surveillance, fire
          barrier penetration seal through ricor of control room was
found breached Caused by failure to reseal following cable
removal Seal repaired 800820 Fire watch established
CDGGIN.C L Georgia Power Co 80/08/29 2pp
8009020419 Forwards LER 80-123/03L-0
MANKY, M Georgia Power Co 80/08
                                                                                    80/08/29 to
~-8009020433 LER 80~123/03L-0 on 800812.during normal operation, while performing reactor core isolation cooling steam line pressure instrument functional test outboard isolation valve failed to fully close Caused by derective torque switch NIX.R T Georgia Power Co 80/08/29 2pp
6009090428 Forwards updated LER 80-032/01%-1
MANRY,M Georgia Power Co 80/09/04 ip
--8009070438 Updated LER 80-032/01X-1 on 800327.during simulated loss of sus pressure surveillance test.2D plant svc water sump sequenced improperly Cause not found Sys tested & pump tied to bus within required limits Test continued w/no problems COGOIN.C L Georgia Power Co 80/09/04 2pp
8009090486 Forwards LER 80-124/03L-0
MANRY, M Georgia Power Co 80/09/04 lp
  --8009090495 tER 80-124/03L-0 on 800813, during surveillance of torus drywell vacuum breakers, 2748-F323J valve failed to give proper light indication on 800827, 2748-F323I failed in similar manner Cause not known NIK, R T Georgia Power Co 80/09/04 2pp
8009150331 Forwards LER 80-126/03L+0
MANRY,M Georgia Power Co 80/09/
                                                                                   B0/09/09 1a
--8009190335 LER 80-126/03L-0 on 800824, during steady state operation at 1540 MW 2P33-P001A, primary containment hydrogen & oxygen analyzer became inoperable Caused by faulty design of regent gas flowmeter Design change requested NIX.R T Georgia Power Co 80/09/09 2pp
8009160285 Forwards LER 80-125/03L-0
MANRY,M Georgia Power Co 80/09/11 1p
---8009160306 LER 80-125/03L-O on 800824 during control room panel check.
2832-F001B valve found to have no indicating lights Gaused
by open fuse in valve control circuit Circuit integrity
verified t control fuse replaced
NIX.R T Georgia Power Co 80/09/11 2pp
8009230316 RO on 800908, following reactor scram. HPCI auto initiated beinjected due to low reactor water leve! Caused by MSIV closure, which caused reactor scram. loss of RFPI & increased reactor pressure HPCI returned water level to normal MANRY, M Georgia Power Co. 80/09/15 2pp
8009290278 Forwards LER 80-105/03L-0
MANNY.M Georgia Power Co 80/09/18 1p
--8009290281 LER 80-105/03L-0 on 800821, nitrogen pressure was lost to
both standby liquid control sys accumulators Caused by
"A" test valve leak 3 "B" test valve being broken while
installing test gauge Test valves replaced
NIX,R T Georgia Power Co 80/09/18 2pp
8009300519 Forwards LER 80-128/03L-0
MAKRY, M Georgia Power Co B0/09.
                                                                                     B0/09/23 Lp
 ---B009300524 LER B0-12B/03L-0 on 800705, reactor high pressure instruments
            2B21-HO23C & D actuated above Tech Bpecs Caused by setpoint
drift Emitches recalibr & tested successfully
NIX.R T Georgia Power Co 80/09/23 2pp
```

#### V Operator Examinations

800905029; Forwards excerpt from new training outline re-criteria for operator training & licensing Current policy requires instructors attend annual simulator training & retraining lectures as part of approved requalification program MANRY. M Georgia Power Co 60/08/12 7pp

#### DOCKET 50-967 BAILLY GENERATING STATION

- A Application/construction stage documents & correspondence
- 8007080080 Forwards draft NUREO-0696. "Functional Criteria for Emergency Response Facilities." Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 enci. N/O NUREG EISENHUT, D.G. Division of Licensing. 80/08/01. 119pp
- 8009110742 Notification of 800904-05 meeting w/Mark II owners group to discuss plants chugging C/O & lateral load specs ANDERSON.C Containment Systems Branch 80/08/29 14pp
- 8009300419 Forwards "Pretiminary Review Soil Parameters Used in USOS Rept 78-138 Efrects of Seepage From FlyrAsh Settling Fonds & Const Dewatering on Groundwater Levels in Cowles Unit IN Dunes Natl Labeshore IN," in response to 800131 meeting BOHM R J Northern Indiana Public Service Co 80/09/26 ip
- --8009300421 "Preliminary Review Soil Parameters Used in USOS Rept 78-138, Effects of Seepage From Fly-Ash Settling Ponds & Const Dewatering on Groundwater Levels in Cowles Unit, IN Dunes Hati Lakeshore, IN "

  4 Northern Indiana Public Service Co 8D/05/31 34pp

## O Adjudicatory correspondence

- 8009030552 Forwards appeal re denial of appropriateness of contentions in hearings on CP renewal Workable evacuation plan should be formalized & made operable before &L stage SCHULTZ, 0 Affiliation Unknown 80/08/26 ip
- 8009020048 Response to ASLB 800807 special prehearing conference order re short pilings as issue in proceeding Issue should not be deferred due to new method of installation & serious safety questions that may arise Certificate of Svc encl EEKULER, S N , FAHNER, T C , MURRAY, M J Illinois, State of 80/08/25 9pp
- 8009090621 Ack receipt of 800605 request to join State of IL petition for suspension or revocation of CP Consideration of request delayed pending outcome of risk assessment study DENTON HR Office of Nuclear Reactor Regulation, Director 80/09/25 ip
- --8009090627 Requests under 10CFR2 206. submitted on behalf of intervenors City of Cary. IN. United Steelworkers of America Local 6787. Bailly Altiance. Save the Dunes Council & Critical Mass Energy Project to join State of 1L petition to suspend CP CONN. D B Gary. IN CONN. D B Public Citizen Litigation Group B0/06/05 7ρρ
- --8009090633 Petition to intervene & request for hearing submitted on behalf of City of Gary,IN.United Steelworkers of America Local 6787.Bailly Alliance,Save the Dunes Council & Critical Mass Energy Project COMM.D B . SCHULTY, W D Gary,IN CGMM.D B Public Citizen Litigation Group B0706/05 7pp
- --8007070635 Response, submitted on behalf of City of Gary, IN.United Steelworkers of America Local 6787, Bailly Alliance, Save the Dunes Council % Critical Mass Energy Project to NRC & util opposition to petition to intervene Draft affidavits encl CONN, D B . SCHULTZ, W B Oary, IN CONN, D B Public Citizen Littgation Group 80/02/26 20pp
- 8009020084 Motion to compel NRC to determine whether to issue supplemental or new EIS per NEPA due to changes in circumstances occurring since EIS was issued Cartificate of Svc & supporting documentation encl MURRAY. M J. FAHNER. T. C., SEXULER. S. N. Illinois, State of 80/08/26 15pp
  - 09090372 Requests limited appearance at forthcoming ASLB hearing re CP amend for facility  $_{\rm JOHNSON,\,L}$  Affiliation Unknown 80/08/27 ip

- 8009020402 Order granting extension until 800911 for State of IL to respond to ASLB 800807 order re contentions incorporated by ref Repties to IL response will be extended accordingly GROSSMAN, H Atomic Safety and Licensing Board Panel 80/08/28 ip
- 8009030703 Natice for R Bohn B00930 deposition in Chicago, IL re late const completion & joint intervenors' contentions admitted per ASLB B00807 order Certificate of Bvc encl Related correspondence VOLLEN, R J. 08ANN, E W. Isaak Walton League of America, Porter County Chapter VOLLEN, R J. 80/08/28 4pp
- 8009030710 Arguments in support of intervenors' 800630 reworded contentions filed in response to ASLB special prehearing conference provisional order Discusses Class 9 accident & spent fuel storage W/Certificate of Svc VOLLEN.R J . OSANN.E W Izaak Walton League of America. Porter County Chapter VOLLEN.R J Vollen. R J 80/08/28 9pp
- 8007040281 Response in opposition to State of IL & Porter County Chapter 1977-80 contentions to health & safety issues Contentions do not relate to couse of delay in const Does nat address environ contentions Certificate of Svc encl SHEA. K H , EICHORN, M H Northern Indiana Public Service Co SHEA. K H Lowenstein. Newman. Reis. Azelrad & Toll 80/08/28 15pp
- B007030[49 Natice of appeal from ASLB 800808 order denying intervention COM, D.B., SCHULTI, W.B., Gary, IN COM, D.B., Cohn, D.B., 80/09/29 1a
- --8007030152 Brief in form of pleading supporting 800827 natice of appeal from ASLB 800808 order denying intervention Asserts interest & restates relevancy Urges application of 1973 ALAB-129 test Documentation & Certificate of Svc encl COHN.D M , SCHULTZ.W B Gary.IN COHN.D B Cohn, D B 80/08/29 26cc
- 8009050432 Memorandum advising parties that oral argument will be heard on 801002 of decided Date must be reserved BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/09/02 ip
- 8009080509 Notion for extension until 800915 to respond to City of Oary. IN notice of appeal t supporting brief Counsel contemporaneously involved in other pleadings Certificate of 8vc encl
  SHEA.K H . EICHHORN.W H Northern Indiana Public Service Co SHEA.K H . Lowenstein.Newman.Reis.Axelrad & Toll 80/09/03 5pp
- 8009080511 Mution for consolidation of responses to Porter County Chapter 800826 & State of IL arguments re admission of Porter County new contentions Requests extension until 10 days after svc of State of IL filing W/Certificate of Svc SHEA.K H . EICHHORN.W H Northern Indiana Public Service Co SHEA.K H Lowenstein.Newman.Reis, Arelrad & Toll 80/09/03 4pp
- 8009100515 Advisos of limited appearance at ASLB hearing. TAIT.L Affiliation Unknown 80/09/03 1p
- 8009090420 Order granting extension until 801010 for parties to respond to submittals filed in response to revised contentions GROSSMAN.H Atomic Safety and Licensing Board Panel 80/09/03 ip
- 8009090791 Forwards util memorandum of law in response to State of IL motion to compel NRC determination re need for EIS
  SHEA.K H Lowenstein, Newman, Reis, Axeirad & Toll 80/09/05 2pp
- ---8009090798 Ack positive response in 800320 ltr re accident analyses in nuclear reactor EIS Conveys CEQ specific views on interim policy under NEPA Policy purpose is public disclosure of new developments W/internal memo & Certificate of Svc SPETH, G Council on Environmental Quality 80/08/14 Spp
- 8009110783 Response in opposition to ASLE BOOB25 order denying State of IL Contentions 7D & B Issues presented reflect compelling matters of public interest & are within acope of proceeding Centificate of Svc arcl FAHNER, T C , SEKULER, S N Illinois, State of 80/09/05 3pp

- 8009;1080B Response in opposition to Porter County Chapter & State of IL 800825 & 26 motions to compet NRC determination re need for EIS NRC should inform ASLB & parties of schedule for completion of evaluation of util extension request SHEA.K H EICHHORN.W H Northern Indiana Public Service Co SHEA.K H Lowenstein, Neuman, Reis, Azelrad & Toll 80/09/05 3pp
- 8009120372 Response by Porter County Chapter Intervenors stating no objection to util 800903 request for reply consolidation Conditions position upon grant of extension until 800926 for intervenor to reply to util re revised contentions VOLLEN.R J Izaak Walton League of America, Porter County Chapter VOLLEN.R J Vollen.R J 80/09/08 10
- ---B007120445 Response by Porter County Chapter Intervenors in opposition to NRC 800822 position re new contentions & motion to consolidate Urges admission & consolidate to environ issues arising after CP issuance Certificate of Bvc encl VOLLEN.R J Itaak Walton League of America. Porter County Chapter VOLLEN.R J Vollen. R J 80/09/08 App
- 8009150400 Response in apposition to NRC 800822 motion to consolidate contentions Consolidation premature Undistinguishable interests are impossible to be defined prior to progress of discovery Certificate of Syc encl SEMULER.S N. FAHNER.T C Illinois, State of 80/09/08 3pp
- 8009110018 Response to Porter County Chapter & State of IL 800825 & 26 motions, respectively NRC will determine whether EIS is required in Oct 1780 Due consideration will be given to CEQ 800812 lyr Certificate of Svc enci
- 8009190463 Forwards revised Pages 21.22 & 24 of memorandum of law on need to prepare EIS rs CP extension, attached to 800905 ltr Section 9 103 of NRC regulations was overlooked Memorandum submitted w/800905 ltr SHEARS H Lowenstein, Newman, Reis, Axelrad & Toll 80/09/10 App
- 8007160247 Memorandum in support of Porter County Chapter Contentiions R-I I R-I 15 previously adopted by State of IL Contentions fit within 1973 ALB-129 definition in DC cook proceeding rescope of hearing Certificate of Svc encl VAN VRANKEN.J., FAHNER.I C Illinois, State of 80/09/11 App
- 8007250057 Notice of change of address W/Cortificate of Svc LAUDIG.S Laudig. S 80/09/13 2pp
- 8009170147 Brief in opposition to City of Cary et al & O Schultz appeal from ASLB 900807 special prehearing conference order Urges that denial of intervention & contention re emergency evacuation be upheld Certificate of Svc encl QBLDBERQ,8 C Hearing Branch 2 80/07/15 21pp
- 8009190039 Brief in opposition to City of Gary, IN, et al & G Schultr appeal from ASLB 800807 special prehearing conference order Urges that denial of intervention re emergency evacuation be affirmed & appeal dismissed Certificate of Svc encl SHEA, K H , FRANTZ, B P , EICHHORN, W H Northern Indiana Public Service Co 80/09/15 36pp
- 8009220177 Brief in form of pleading supporting City of Gary, IN, et al & O Schultz Appeal from ASLB 800808 special prehearing conference order Urges reversal of portion danying admissibility of evacuation issues Certificate of Svc encl SEKULER.S N , FAHNER.T C , MURRAY.M J Illinois, State of 800/09/15 8pp
- 8009230008 Brief in form of pleading in support of City of Gary, IN et al & O Schultz appeal from ASLB 800806 special prehearing order denying intervention Urges reversal of order re evacuability as opposed to suitability W/Certificate of Svc VDLLEN:R J . OSANN.E W Isaak Walton League of America. Porter County Chapter VOLLEN:R J Vollen, R J 80/09/15 14pp
- 8009230035 Brief in form of pleading in opposition to City of Gary.IN et al & 0 Schultz appeal from ASLD 800807 special prohearing conference order denying intervention Contention does not relate to cause of delay Certificate of Svc enci SHEA.K H., FRANTZ.8 P. ETCHHORN.W H. Northern Indiana Public Service Co. 80/09/15 29pp
- 8009180259 Forwards portions of Northern IN Public Svc Co 800915 brief in opposition to appeals Cover sheet, table of contents, table of authorities & Certificate of Svc only encl BHEA.K H. Lowerstein, Neuman, Reis, Axeirad & Toll 80/09/14 iOpp.

- 8009190419 Memorandum & order consulidating City of Gary, IN.et al & G Schult: appeals from ASLB 800807 special prehearing conference order Appeal arguments will be heard on 801002 at NRC in Bethesda: MD Names must be submitted by 800928 BISHOP, C. J. Atomic Safety and Licensing Appeal Panel 80/09/17 3ab
- 8009230382 First request for designation of NRC witnesses for 801019 deposition in Chicago. Il re Contentions 1, 3, 4, 5, 7 & B admitted per ASLS 800807 special prehearing conference order Certificate of Svc enc1 VDLLEN.R J . 05ANM,E W | Izaak Walton League of America. Porter County Chapter VDLLEN.R J Volien, R J 80/09/17 4pp
- 8009230399 Notice for EA Schroer & HP Lyle B01021 & 28 deposition taking respectively in Chicago, IL re Contentions 1.3.4,5.7 & B admitted per ASLB 800807 special prehearing conference order Certificate of Svc encl Related correspondence VOLLEN.R J . DSANN.E W Traak Walton Leegue of America, Porter County Chapter VOLLEN.R J Vollen. R J 80/09/17 4pp
- 8009260011 First request for production of documents directed to NRC Addresses delay in const. remobilization of contractors, installation of slurry wall & environ significance of amend Insp & copying will take place on 801014 in Chicago IL VOLLEN.R J , OSANN,E W Iraak Walton League of America, Porter County Chapter VOLLEN.R J Vollen, R J 80/09/18 8pp
- 8009220173 Submission of Exhibit B erroneously omitted from State of IL 800915 brief filed in form of pleading in support of City of Gary, IN. et al ½ B Schultr appeal MURRAY, II J Illinois, State of 80/09/19 4pp
- 8009230041 Advises that 86 Goldberg will present RRC oral argument in proceeding per ASLAB 800917 memorandum & order GDLDBERG.S C Hearing Branch 2 80/09/19 ip
- 800930000A Response in opposition to util application for extension of CP which would constitute major federal action affecting environ if granted Urges issuance of revised E18 Extension cannot be based on 1973 FEB KIMBALL, T L National Wildlife Federation SHELDON, K P Sierra Club COCHRAN, T B Natural Resources Defense Council 80/09/24
- 8009300025 Advises that WH Eichhorn will present 800917 oral argument on behalf of util per ASLAB 800917 memorandum & order Related correspondence EICHHORN W M Eichhorn, Eichhorn & Link 80/09/24 1p
- 8009300005 Advises that contrary to 800818 pleading, NRC safety evaluation of applicant pile installation proposal will be issued on 801015
- OGLDBERG.S C Hearing Branch 2 80/09/26 1p

  8009300331 Order denying State of It, motion to compel NRC determing State of It, motion to compel NRC determine to compel NRC dete
- 800930033; Order denying State of It, motion to compel NRC determination whether EIS will be assued per NEPA NRC will decide need for EIS by early Oct 1980 Time frame reasonable GROSSMAN. H Atomic Safety and Licensing Board Panel 80/09/26 2pp
- 8009300576 Response in apposition to State of IL 800911 memorandum & to Porter County Chapter arguments filed in support of County new contentions on safety matters issues held to be outside scope of proceeding Certificate of Svc encl SMEA.K H . FRANTZ.B P . EICH-GRN.W H Northern Indiana Public Service Co 80/09/26 lipp
- H General correspondence
- 8909100511 Opposes const of facility \* Affiliation Unknown B0/09/01 Spp
- 8009;80556 Responds to 800421 ltr expressing concerns re facility & NRC response to 800416 question re why plant should be completed before deciding whether or not it should operate Safety evaluation concluded plant may be safely built > operated YOUNGBLOOD, B J Licensing Branch 1 80/09/10 2pp
- G Inspection reports, IE Bulletins & correspondence
- 8009090047 Forwards IE Gulletin 80-07, Suppl 1, "BWR Jet Pump Assembly Failure," No response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/05/14
- 8009100165 Responds to IE Sulletin 77~03A, "Longitudinal Weld Defects in ASKE SA~312.Type 304 Stainless Steel Pipe " No piping as yet installed at facility SHORD, E M Northern Indiana Public Service Co 80/08/14 1p

- 8007110556 Responds to IE Bulletin 80-08, "Exam of Containment Liner Penetration Nelds" Due to delays in NRC completion of pile foundation reviews.const % engineering on plant halted for three yes Will submit response by 820104 SHORBLE K Northern Indiana Public Service Co 80/08/14 lp
- 8007(10567 Responds to IE Bulletin 80-16. "Potential Misapplication of Rosemount, Inc Models 1951 & 1952 Pressure Transmitters W/Either A or D Output Codes ' Will respond, following resymption of engineering & const, by 820104
  SEGREEM Northern Indiana Public Service Co 80/08/14 1p
- 8009030207 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written respinse required KEPPLER, J G Region 3, Chicago. Office of the Director 80/08/15 in
- 6007190485 Forwards [E Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE BUM Facilities" No specific action or response requested KEPPLER, J G Region 3, Chicago, Office of the Director 60/08/20 to
- 8009120055 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scien at BUR" No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/08/22 in
- 8009170432 Forwards IE Circular 80-18, "10CFR90 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/08/22
- 8009230259 Responds to NRC BOOROS request for supplemental info re IE Bulletin 80-07, "BWR Jet Pump Assembly Failure" No jet pumps have been installed at facility Util will adopt plan to prevent cracking in BWR jet pump hold down beams SHORB.E M Northern Indiana Public Bervice Co 80/08/27 2pp
- 8007230074 Forwards IE info Notice 80-31. "Maloperation of Gould-Brown Bover! 480 Volt Type K-600S & K-DON 600S Circuit Breakers " No written response required KEPPLER. J O Region 3. Chicago. Office of the Director 80/08/28
- 6009240110 Forwards IE Circular 80-21, "Regulation of Refueling Crows" No written response required KEPPLER, J.O. Region 3. Chicago, Office of the Director 80/09/10
- 8009300565 Forwards IE Insp Meeting Rept 50-367/80-02 on 800724 FIORELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/09/19 ip
- --8009300571 IE insp Meeting Rept 50-267/80-02 on 800724 No nancompliance noted Areas discussed coast status & general IE policies re coast FIGRELLI, G Region 3, Chicago, Reactor Coastruction & Engineering Support Branch 80/06/18 2pp
- R Periodic operating reports & related correspondence
- 8009020005 Forwards well charts for 800730-0804. Bailly wells u/o recorders 5 pond levels for 800806, pneumatic pressure transducers & water meter readings for 800804, USOS wells for 800727-0803 b new USOS wells for 800727-0803 BOHN, R J Northern Indiana Public Service Cp 80/08/22 35pp
- 8009030434 Forwards "Guarterly Rept.Bailly Nuclear-1 Sits." Apr-June 1980 PURCELL.J Northern Indiana Public Service Co 80/08/22 1s
- --8009030435 "Quarterly Rept.Bailly Nuclear-1 Site." Apr-Jun 1980 \* Texas Instruments, Inc. 80/08/30 175pp
- 8009020091 Forwards well charts for 800804-12.pond levels for 800813 & Bailly walls w/o recorders pneumatic pressure transducers, water meter readings & USOS wells for 800812 BOHNR U Northern Indiana Public Service Co. 80/08/25 33pp
- 8007090427 Forwards well charts for B00812-20.Bailly walls w/o recorders, pond lovels, pneumatic prossure transducers & water meter readings for 800820 t U833 wells for 800817 BOHN.R J Northern Indiana Public Service Co 80/08/27 33pp

- 8009090489 Forwards well charts for 800820-27 & Bailly wells w/o recorders, pond levels, pneumatic pressure transducers, water meter readings & USGS wells for 800827 BDM4, R J Northern Indiana Public Service Co 80/09/05 35pp
- 8009150474 Forwards well charts for 800827-0903.Bailly Wells w/o recorders.pond levels.pneumatic pressure transducers.water meter readings & USOS wells for 800903.rainfall data for 800901-0831 & Lake MI levels for 800515.0601 & 15 BOHN,R J Northern Indiana Public Service Co 80/09/11 36pp
- 8009250297 Forwards well charts for 800903-10, Bailly wells w/o recorders, pand levels, pnowmatic pressure transducers, water moter readings & USOS wells 800910 BDHN,R J Northern Indiana Public Service Co 80/09/19 34pp
- 8009300446 Forwards well charts for 800910-17.8ailly walls w/o recorders, pond levels, pneuamtic pressure transducers, water meter readings 2 USOS wells for 800917 USOS has installed new Well 9-4A next to Well 0-4 Water level included BGIN,R J Northern Indiana Public Service Co 80/09/24, 33pp
- DOCKET 50-368 ARXANSAS NUCLEAR ONE, UNIT 2
- F Security, medical, emergency & fire protection plans
- BOOGOZOIGO Invites participation in BOOB22 workshop in Atlanta, GA to solicit comment re proposed functional criteria for emergency response facilities in NUREG-0696 Discussion to include location, size & staffing of emergency ctrs
  SEYFRIT, K V Region 4, Dallas, Office of the Director 80/08/12
- B009090326 Notifies that security sys will be fully implemented on B01001 Any subsequent equipment failure will be compensated for by compensatory measures butlined in Util industrial security plan b implementing procedures
  TRIMBLE.D C Arkansas Power & Light Co 80/08/29 1p
- 8009170322 Forwards security personnel training & qualification plan-Revision 1 Revision withheld (ref 100FR2 790) TRIMBLE D C Arkansas Power & Light Co 80/09/09 ip
- G Adjudicatory correspondence
- 8007260535 Forwards order requiring info supporting environ qualification of safety-related electrical equipment Requests submittal of info by 801101 CLARK.R A Operating Reactors Branch 3 80/08/27 2pp
- --8009260540 Order for mod of License NPF-6 to add info which fully responds to NRC request for info re environ qualification of safety-related electrical equipment info should be submitted by 801101
  EISENHUT, D 0 Division of Licensing 80/08/27 6pp
- J Insurance & indemnity information
- 8007030537 Forwards Endorsements 40,41 & 42 to NELIA Policy NF-210 & Endorsements 36 & 37 to MAELU Policy MF-74, TRIMDLE,D C Artansas Power & Light Co 80/08/29 6pp
- 8009030550 Forwards Endorsement 3 to ANI Binders EB-48 & EB-68 & MAELU Binders YB-48 & XB-68 TRIMBLE,D C Arkansas Power & Light Co 80/08/29 9pp
- P Operating license stage documents & correspondence
- BOO9020297 Submits interim criteria for shift staffing to all OL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for amergency & evertime work Development & implementation to be reviewed within 90 days EISENHUT, D & Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 entl W/o NUREG EISENHUT, D 0 Division of Licensing 80/08/01 119pp
- 8007230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Pravious determination should be disregarded Requested submittal should include proposed class of amend EISENHUT, D O Division of Licensing 80/08/07 60pp

- GOO9:50287 Application to amend License NPF-6.changing Tech Spec 3 4 35 re pressurizer code relief valves Class III fee encl CAVANAUOH.W Arkanses Power & Light Co 80/08/29 3pp
- --B009150292 Proposed Tech Spec 3 4 3 b re time extension for setting pressuriser code safety valves under ambient (hot) conditions

  \* Arkanses Power & Light Co 80/08/29 ip
- BOO9110371 Requests that encl supporting document be docketed under Milistone MAPO.P S Assistant Director for Core & Containment Systems BO/09/09 1p
- BOO9180424 Application for amend to License NPF-6 mafifying surveillance requirements of Tech Spec 4 6 2 3 to assure operability of containment sys Class III amend fee & supporting documentation encl CAVANAUGH, W Arkansas Power & Light Co 80/09/11 6pp
- --8009180427 Proposed mods to surveillance requirements of Tech Spec 4 & 2 3 to assure operability of containment sys \* Arkansas Power & Light Co 80/09/11 1p
- 9009250126 Forwards Amend 14 to License NPF-6, safety evaluation & notice of issuance & availability CLARK.R A Operating Reactors Branch 3 80/09/12 2pp
- ---8009250130 Amend 14 to License NPF-6 revising App A Tech Specs to identify water flow rate requirements for operation mode allowed by Tech Spec 3 6 2 3 CLARK.R A Operating Reactors Branch 3 80/09/12 5pp
- ---B007250133 Safety evaluation supporting Amend 14 to License NPF-6

  \* Operating Reactors Branch 3 80/09/12 2pp
- --9009230137 Notice of issuance & availability of Amend 14 to License NFF-5 CLARK.R A Operating Reactors Branch 4 80/09/12 2pp
- 8009260453 Application for amend of License NPR-6, changing Tech Specs 3 6 2 3,4 6 2 3,3/4 6 3 & 3/4 6 4 Fee encl CAVANAUGH. H. Arkansas Power & Light Co. 80/09/16 9pp
- --8009260456 Proposed Tech Specs 3 6 2 3,3/4 6 3 & 3/4 6 4, permitting operation w/min of one containment cooling unit operable in each group & surveillance flow requirement of 1,250 gpm to each group # Arkansas Power & Light Co 80/09/16 3pp
- 8009300145 Forwards Amends 46 % 15 to Licenses DPR-51 & NPF-6, respectively, safety evaluation & notice of issuance & availability REID,R W Operating Reactors Branch 4 80/09/16 2pp
- --8007300148 Amends 46 & 15 to Licenses DPR-51 & NPF-6, respectively, revising ETS re design objective for radioactive gaseous releases & requirements for quarterly rept on radioactive gaseous releases
  REID.R W Operating Reactors Branch 4 80/09/16 19pp
- --BO09200153 Safety evaluation supporting Amends 46 & 15 to Licenses DPR-51 & MPF-6, respectively \* Office of Nuclear Reactor Regulation, Director B0/09/16 4pp
- --8007300155 Notice of issuance & availability of Amends 44 \$ 15 to Licenses DPR-51 & NPF-6.respectively RE\$D.R W Operating Reactors Branch 4 80/09/16 2pp
- BOO9300173 Requests deadline extension until 801201 to rewrite model Tech Specs to accommodate existing AR-1 Tech Specs format, unit design & NUREG-0578 Category A mods TRIMBLE.D C Artansas Fower 3 Light Co 80/09/19 ip
- 80G9300242 Confirms tolcon commitments re removal of accumulation of Asian clams from containment cooling units In addition to physical cleaning, efforts include flushing w/high temp water to kill any live clams remaining CAVANAUGH.W Arkansas Power & Light Co 80/09/22 2pp
- O Inspection reports, IE Bulletins & correspondence
- GOO9020224 Responds to IE Bulletin 80-08, "Exam of Containment Liner Penatration Welds " Units utilize flued head design for containment penetrations flued head penetrations radiographed TRINBLE.D C Arkansas Power & Light Co 80/06/27 lipp

- 8009180145 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrirugal Charging Pumps Following Secondary Side High Energy Line Rupture " Written response required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/07/24
- 8009020538 Forwards supplemental IE Info Notice 80-06. "Notification of Significant Events at Operating Power Reactor Facilities " No written response required SEYFRIT, K V Region 4. Dallas. Office of the Director 80/07/29 to
- 8009180138 Forwards IE Bulletin 80-20. "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches" Written response required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/07/31
- 8009180160 Forwards IE Bulletin 80-19, "Failure of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E" Written response required SEYFRIT. & V Region 4. Dallas. Office of the Director 80/07/31
- 8009260294 Forwards IE Info Notice 80-29, "Broken Studs on Terry Turbing Steam Inlet Flange " No written response required SEYFRIT.K V Region 4. Dalias: Office of the Director 80/08/07 in
- 8009180470 Forwards IE Insp Repts 50-313/80-11 \$ 50-368/80-11 on 800522-0721 & notices of violation & deviation One notice of violation & Attachment A to repts withheld (ref 10CFR2 770) MADSEN,O L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/08/08 2pp
- --8009180472 Notice of violation from insp on 800622-0721 \* Region 4, Dallas, Reactor Operations Notlear Support Branch 80/08/07 ip
- --8009180476 Notice of deviation from insp on 800622-0721 \* Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/08/07 lp
- --8009180481 IE Insp Repts 50-313/80-i1 & 50-368/80-i1 on 800622-0721 Noncompliance noted 2712 valve gallery in Unit 2 auxiliary bldg not posted as radiation area & no positive access control on Door 364 Attachment A withheld (ref 10CFR2 790) JOHKSOA, W D. CALLAN, L J. HUNNICUIT, D M. Region 4, Dallas, Office of the Director 80/08/07 13pp
- 8009040039 Ack receipt of 800708 % 11 ltrs informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-313/80-05 & 50-368/80-05 MADSEN.C L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/08/12 ip
- --8007040047 Responds to NRC 800416 ltr re violations nated in IE Insp Rept 50-368/80-05 Corrective actions Tech Spec change request generated to clarify existing spec on diesel generator automatic sequence time delay relays TRIMBLE, D.C. Arkansas Power & Light Co. 80/07/08 ip
- 8007240735 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Morcury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required SEYERIT.X V Region 4. Dallas, Office of the Director 80/08/15 19
- 8009170390 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/08/22
- 8009120420 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers "No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/08/27 ip
- 8009170173 Forwards IE lnsp Repts 50-313/80-13 \$ 50-348/80-13 on 800721-25 W/o encl notice of violation KELLY, J A Region 4. Dallas, Office of the Director 80/08/29 208

- --B009170176 IE Insp Rapts 50-313/80~13 & 50-368/80-13 on 800721-25 Noncompliance noted vital area door fastened shut w/ inadequate fastener, tamper alarm triggering mechanism taped in manner preventing alarm & intrusion alarms not tested CALDMELL, R A , KELLY, J A Region 4. Dallas, Office of the Director 80/08/27 2pp
- R Periodic operating reports & related correspondence
- 8009090425 Forwards NPDES rept for Second Quarter 1980 re NPDES Permit ARO901392 Ut;1 ltrs to EPA enc! TRIMBLE:D C Arkansas Power & Light Co 80/08/29 8pp
- --8009090432 NPDES rept for Second Guarter 1980 re MPDES Permit
- Arkansas Power & Light Co 80/08/29 15pp
- 8009160251 Forwards semiannual radioactive effluent rept for first & second quarters 1980 TRIMBLE.D C Arkansas Power & Light Co 80/09/08 1p
- --8009160256 Samiannual radioactive effluent rept for first & second quarters 1980 4 Arkansas Power & Light Co 80/09/08 21pp
- 6009230407 Forwards monthly operating rept for Aug 1980 TRIMBLE, D.C. Arkansas Power & Light Co. 80/09/15
- --8009230410 Monthly operating rept for Aug 1980 PENDERGRAFT, R Artenses Power & Light Co P0/09/15 600
- S Reportable occurrences, LERs & related correspondence
- 8009020449 Forwards LER 80-059/03L-0
  TRIMBLE,D C Artanses Power & Light Co 80/08/26 2pp
- --8009020458 LER 80-059/03L-0 on 800727, during Mode 1 operation, core operating limits supervisory sys plant computer program indicated power margin of "80% rather than expected 0% at rated power Probable cause intermittent hardware failure SHIVELY, C N . O"MANLON, J P Arkansas Power & Light Ca 80/08/24
- 8009140557 PNO-IV-80-027A correcting info previously reported in PNO-IV-027 dtd 800822 re loss of all telephone communications Util has plans for instellation of new communications sys which includes fiber optics & microwave JOHNSON N D. HUNNICUTY D M. MADSEN, G L. Region 4, Dailas, Office of the Director 80/08/26 2pp
- 8009030422 Forwards updated LER 80-037/01%-; TRIMBLE/D C Arkansas Power % Light Co 80/08/27 ip
- --8009030425 Updated LER 80-037/01X-1 on 800503 (uring Mode 1 operation, safety injection tanks (SIT) C & D were found to have boron concentrations of 1711 ppm & 1620 ppm Probably caused by dilytion of SIT makeup path by reactor coolant SHIVELY.C N Arkansas Power & Light Co 80/08/27 4pp
- 8009030539 Forwards LER 80-061/03L-0 TRIMBLE,D C Arkansas Power & Light Co 80/08/27 ip
- --8009030546 LER 80-061/03L-0 on 800728, leakage discovered on C charging pump at elbow weld during Mode 1 operation Caused by vibration Defective pipe spool piece replaced 5 hanger installed to reduce vibration Pump operable after repairs PENDERGRAFT. R Arkansas Power & Light Co 80/08/27 ip
- 8009030622 Forwards LER 80-060/03L-0 TRIMBLE.D C Arkansas Power & Light Co 80/08/28 ip
- --8009030428 LER 80-040/03L-0 on 800730.D core protection calculator failed during Mode 1 operation Cause unknown DNBR/LPD trips bypassed 0 sys reinitialized & failure indications returned to normal Bypasses removed Unit remained operable TRIMBLE.D C Arkansas Power & Light Co 80/08/20 2pp
- 8009030410 Forwards updated LER 80-050/03X-1 TRIMBLE.D C Arkansas Power & Light Co 80/08/29 ip
- ---B009030417 Updated LER 80-050/03X-1 on 800804 during Mode I operation, uhile testing emergency faedwatar pump (2P7A), overspeed trip occurred rendering 2P7A inoperable Cause not specified, but hydraulic control oil sys is suspected Vendor contacted PENDERGRAFT,R Arkansas Power & Light Co 80/08/29 ip

- 800909037B Forwards LER 80-057/03L-0
  TRIMBLE, D C Arkansas Power & Light Co 80/09/03 1p
- --8009090385 LER 80-057/03L-0 on 800805 during Mode 1 operation.all control element assembly calculator 1 inputs to core protection calculators were placed on inoperable status as precautionary measure SHIVELY, C N Arkansas Power & Light Co 80/09/03 ip
- 8009180149 PNO-IV-80-028 on 800903, svc water flow to containment cooling coils failed to meet min flow rate required by Tech Specs Khen compliance w/Tech Specs could not be demonstrated unit was shut down Licensee is investigating JOHNSON, W D , HUNNICUTT, D M , MADSEN, O L Region 4, Dallas, Office of the Director 80/09/04 2pp
- 8009190590 PNO-IV-80-031 on 800904, containment bldg purge was started w/o licensed operator in charge knowing when purge started Caused by operator in charge being involved in other work JUHNSON, W D. HUNNICUTT.D M , MADSEN, G L. Region 4. Dallas, Office of the Director 80/09/05 2pp
- 8009150293 Forwards LER 80-044/03L-0 TRIMBLE, D C Arkansas Power & Light Co 80/09/08 ip
- --8009150296 LER 80-064/03L-0 on 800810, during Mode 1 operation, plant protective sys channels A & D malfunctioned Caused by power supply failure Channels repaired & declared operable per Tech Specs SHIVELY.C N Arkansas Power & Light Co 80/09/08 1p
- BOO9150258 Forwards LER 80-062/03L-0
  TRIMBLE, D C Arkansas Power & Light Co BO/09/09 ip
- -8009150261 LER 80-062/03L-O on 800801 during startup test procedures review for RCS calorimetric flow rate test, power uncertainty bias terms in core protection calculators revealed calibratelerance less constant than Tech Spec requirements EHIVELY.C N Arkansas Power & Light Co 80/09/09 1p
- 8009150268 Forwards LER 80-066/03L-0
  TRIMBLE, D C Arkansas Power & Light Co 80/09/09, ip
- --8009130271 LER 80-064/03L-O on 800811. during Mode 1 operation, hi-hi containment pressure trip was received on plant protective sys channel D Other channels reported normal pressures Caused by power supply failure on bistable card PENDERGRAFT.R Arkansas Power & Light Co 80/09/09 1p
- 8009150273 Forwards LER 80-065/03L-0 TRIMBLE, D C Arkansas Power & Light Co 80/09/09 1p
- --8009150275 LER 80-065/03L-0 on 800812, while performing surveillance testing on containment spray & sump valves, containment sump recirculation valve failed Caused by valve operator overload breaker tripping due to foreign matl in switch contacts PENDERGRAFT.R Arkansas Power & Light Co 80/09/09 ip
- 8009230705 Forwards LER 80-068/03L-0
  TRIMBLE, D.C. Arkansas Power & Light Co. 80/09/16 ip
- --B009230712 LER 80-068/03L-0 on 800823 during Mode 1, leak was discovered on 8 charging pump, 2P368, discharge header at discharge relief valve pipe Apparent cause is vibration induced from positive displacement pumps Mods made to all three pumps SHIVELY, C N Arkansas Power & Light Co 80/09/16 1p
- 8009230744 Forwards LER 80-067/03L-0 TRIMBLE,D C Arkansas Power & Light Co 80/09/16 ip
- --8009230748 LER 80-067/03L-0 on 800B23.during Mode 1 operation I-13i dose equivalent value of 3 & uCi was observed Caused by "CRUD" Surst RCS letdown flow was increased \$\mu\$ I-13i decreased to 0 26 uCi PENDERGRAFT,R Arkansas Power \$\mathcal{E}\$ Light Co 80/09/16 5pp
- 8009240496 Forwards LER 80-072/01T-0 TRIMBLE.D C Arkansas Power & Light Co 80/09/17 1p
- -8009240504 LER 80-072/01T-0 on 800903, during Mode 1 operation, discovered 800820 surveillance indicated inadequate evc water flow through containment bldg coolers Caused by buildup of Asian clams in svc water side of coolers SHIVELY, C H Arkansas Power & Light Co 80/09/17 4pp
- 8009300538 Forwards LER 80-063/03L-0 TRIMBLE, D C Arkansas Power & Light Co 80/09/18 19

- --8009300546 LER 80-063/03L-0 on 800822, after unit trip at 90%, power A condensate storage tank level feel below Tech Spec min Caused by emergency feedwater sys Suction taken from tank after unit trip Procedures revised to prevent reoccurrence SHIVELY, C N Arkansas Power & Light Co 80/09/18 ip
- y Operator Examinations
- 8009050330 Submits info re mods to reactor operator training program in response to NRC 800328 ltr Course summaries for thermodynamics, fluid flow & heat transfer training & for mitigating core damage encl m-HAMLON.J P Arkansas Power & Light Co 80/08/04 900
- BOG9170241 Documents 800811 presentation of util position re nuclear training program Presentations re operator training.general employee training, training records, on—the—job training, fire brigade training 8 ys training encl
  CAVANAUOH.W Artansas Power & Light Co BO/08/13 16pp
- DOCKET 50-369 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 1

  A Application/construction stage documents & correspondence
- B009110636 Forwards requests for add1 info re radwaste mgt sys.per review of FBAR Revision 39 Comments on radiological ETB & offsite dose calculation manual encl TEDESCO.R L Assistant Director for Licensing 8D/07/29 8pp
- 8009080080 Forwards draft NUREG-0676, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl W/o NUREG EISENHUI,D 0 Division of Licensing 80/08/01 119pp
- 8009020122 Forwards request for addl info re floodplain mgt per Esscutive Order 11988 Response requested by 800808 YEDESCO.R L Division of Licensing 80/08/06 5pp
- 8009030069 Notification of 800904 meeting w/util in Buthesda,MD to dlacess standby shutdown facility BIRKEL.R A Licensing Branch 1 80/08/14 4pp
- BOO9040434 Forwards matl re NRC review of ice condenser containment & hydrogen control measures for Sequoyah Nuclear Power Plant.

  ACRS has scheduled meetings in Washington.DC on BOOB2B,0902
  & 04 to discuss issue
  TEDESCO.R L Assistant Director for Licensing BO/08/22 Spp
- --8009040443 "Hydrogen Control for Sequoyah Nuclear Plant.Units 1 % 2 "

  \* Office of Nuclear Reactor Regulation, Director 80/08/13
  Blue
- --8009040450 Transcript of 800921 discussion of Sequoyah full power license in Washington, DC Pp 48-89 \* Commission B0/08/21 47pp
- BOOP120114 Requests add1 info re containment pressure boundary fracture toughness by 800903
  TEDESCO.R L Assistant Director for Licensing 80/08/22 3pp
- 8009090877 Forwards request for addl info re radiation protection Complete response should be provided by 800902 TEDESCO.R L Assistant Director for Licensing 80/08/25 4pp
- 8009180489 Requires submittal of ATWB emergency operating procedure for ARC review by 800919 Generic analysis should confirm ATWB mitigation capability described in Vol 3 of NUREO-0460 Commission will determine required mods & schedules TEDESCO.R L Assistant Director for Licensing 80/08/25 4pp
- 8009120623 Forwards request for addl info re containment emergency sump performance under post-LOCA conditions Requests info by 800903
  TEDESCO,R L Assistant Director for Licensing 80/08/26 App
- 8009020371 Provides documentation of activities & current work status re hydrogen control in ice condenser containments Facility will have ECCS Bys will not generate substantial amounts of hydrogen ECCS will prevent hydrogen problem PARKER, H O Duke Power Co 80/08/27 3pp
- B009160649 Requests info needed by 800908, for review of application re low pressure turbine discs TEDESCO.R.L. Assistant Director for Licensing 80/08/27 3pp

- 8009]50333 Forwards request for add1 (nfo re Category I masonry wall design Requires response by 800919 TEDESCO.R L Assistant Director for Licensing 80/08/29 5pp
- 8009100152 Requests info by 800919 to complete final Tech Spocs Required info includes proposed changes requiring technical justification & identification of FSAR revisions subsequent to issuance of SER requiring Tech Spec changes YOUNGBLGOD, D. J. Licensing Branch ( 80/09/02 Spp.
- 8009190236 Forwards FR notice re-rolocation of local PDR to Atkins Library, Univ. of NC, Charlotte, NC FELTON, J.M. Division of Rules and Records 80/09/02 2pp
- --8009190242 Notice of relocation of local PDR to Atkins Library.Univ of NC.Charlotte.NC FELTON.J M Division of Rules and Records 80/09/02 2pp
- 800916026t Forwards proprietary & nonproprietary versions of Westinghouse computer printout data entitled "Low Pressure Turbine Disc Info," in response to NRC 800827 request Proprietary version withheld (ref 100FR2 790) PARKER-N O Duke Power Ca 80/09/04 2pp
- 8009110345 Forwards updated responses to "Duke Power Co. McQuire Nuclear Station Response to TMI Concerns " Fuel loading for Unit 1 scheduled for Oct 1980 PARKER.W O Duke Power Co 80/09/08 34pp
- 8009150439 Notifies that util 800925 ltr re ATMS requirements responds to NRC 790817 & 800825 requests Ltr reflects current util intentions re interim ATMS procedures prior to OL issuance PARKER, W O Duke Power Co 80/09/09 lp
- 8009150548 Requests exemption from mechanical snubber requirements until startup following first refueling outage Testing equipment necessary to comply w/NRC surveillance requirements is unavailable PARKER, N O Duke Power Co 80/09/08 1p
- 8009300644 Summary of 800904 meeting woutil in Bethosda,MD re final standby facility Connection w/station will occur subsequent to NRC review & approval Site visit considered for 800925-26
  BIRKEL,R A Licensing Branch 1 80/09/09 2pp
- 8009140600 Forwards response to RL Tadesco 800822 ltr requesting info re containment pressure boundary fracture toughness Matis test data in storage at facility Oversize drawings available in Central Files only PARKER.W O Duke Power Co 80/09/10 3gp
- 8009290001 Forwards request for add) info concorning reactor sys re Branch Technical Position RSB 5-1 TEDESCO.R L Assistant Director for Licensing 80/09/11 Spp
- 8009180376 Forwards add1 info re ECCS evaluations in response to RL. Tedesco 800805 ltr Provides results of supplemental calculations to demonstrate potential impact of using fuel rod models: per draft NUREG-0630; on LOCA analysis for Unit 1 PARKER. M O Duke Power Co 80/09/15 Spp
- 8009180322 Forwards draft emergency procedures for review including immediate actions & diagnostics for safety injection. LUCA & steam generator tube rupture Secondary line rupture & loss of feedwater will be provided by 800919 PARKER.W O Duke Power Co 80/09/16 ip
- --B009180327 Draft emergency procedures, including immediate actions & diagnostics for safety injection.LGCA & steam generator tube rupture # Duke Power Co B0/09/16 50pp
- 8007170397 Responds to NRC 800520 ltr re NUREC-0577. "Potential for Low Fracture Toughness & Lameliar Tearing on PNR Steam Congrator & Reactor Coclant Pump Supports " No response needed, pending add1 NRC guidance PARKER, W D Duke Power Co 80/09/16 1p
- 8009190506 Forwards Revision 1 to util 800702 response re info request on Category I masonry walls
  PARKER, W O Duke Power Co 80/09/16 4pp
- BOO9240409 Responds to NRC 800731 ltr stating position re incore thermocouples Thermocouple readout has capability for printout within 5-6 minutes Thermocouples are capable of measuring in 2,000 F range PARKER, W O Duke Power Co 80/09/17 2pp

- 6005290169 Advises that auxiliary feedwater sys automatic initiation meets safety grade requirements re FMI Item II E 1 2.NUREG-0578. Section 2 1 7 a Requests compliance demonstration.by 800529.re automatic removal of manual bypass VOUNG91,000.B J Licensing Branch ( 80/09/17 Gpp
- 8009240489 Forwards response to Bulletins & Orders Task Force recommendations re auxiliary reedwater sys Response supplements info transmitted in 800813 ltr PARKER, N G Duke Power Co 80/09/18 7pp
- 8009290371 Advises that response to NAC 800827 request for info re draft Tech Specs has been sent PARKER, M O Duke Power Co 80/09/19 1p
- 8009290303 Forwards addl info re Category I masonry wall design per NRC 800829 request Also forwards revised Page 3 of 800916 response PARAKR.N D Dute Power Co 80/09/23 12pp
- 8005300434 Responds to NRC 800826 request for info re containment emergency sump debris PARKER, N O Dube Power Co 80/09/24 App
- F Security, medical, emergency & fire protection plans
- 8009260527 Forwards comments re storage & in-transit security plan for SNM of low strategic significance Response requested within 30 days Comments withheld (ref 100FR2 790) MCCORKLE, 0 W Physical Security Licensing Branch 80/08/08 1p
- 8009/20029 Forwards facility emergency plan & related info PARKER, & O. Dute Power Co. 80/08/25 13pp
- --8009020033 Emergency plan for facility \* Duke Power Co 80/08/25 200pp
- B009120592 Forwards emergency preparedness evaluation Current plan provides acceptable state of emergency preparedness for fuel load & low power testing GRIMES/& K Emergency Preparedness Program Office B0/09/04 4pp
- 8009290175 Advises that health physicist should report directly to station manager per Reg Guide 8 B & NUREO-0660 & NUREG-0694 re radiation protection organization Requests commitment to comply or explanation of alternate compliance w/criteria BIRKEL, R Licensing Branch I 80/09/17 3pp
- O Adjudicatory correspondence
- 8009050086 Response in opposition to Carotina Environ Study Group 800509 & D815 motions requesting reopening of hearing record Neu contentions relamengency planning & comparative containment design are impermissible attact on regulations MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman 80/09/03 230s
- ---B0090500B7 Affidavit ra hydrogen generation & control following postulated TMI-type accident Util action effectively procludes excess hydrogen generation Certificate of Svc encl CAMADY.K S Duke Power Co 79/07/09 7pp
- 8009090241 Response urging deferrel of ruling on Carolina Environ Study Group 800815 mattan to reapen record re hydrogen generation issue arising from TMI accident Suggests 15 days for parties to file simultaneous reply W/Certificate of Svc KETCHEN, E. G. Hearing Branch 4 80/09/04 11pp
- 8009120252 Forwards 800819 FR notice amending emergency planning regulations KETCHEN.E G Hearing Dranch 3 80/09/08 19pp
- 8009140343 Forwards FR notice of relocation of LPDR KETCHEN, E 0 Hearing Branch 4 80/09/12 1p
- --8009160347 Forwards notice of relocation of LPDR CHILK.S J. Office of the Secretary of the Commission 80/09/05
- --8009160352 Notice of relocation of LPDR to Atlins Library, Univ of NC, Charlotte, UNCC Station, NC FELTON, J. M. Division of Rules and Records 80/09/02 1p
- 8009220425 Notice of appearance in proceeding Certificate of Svc enci CHATISS.J R Regulations Division 80/09/18 2pp

- 6009260D10 Submittal updating applicant 800903 response in opposition to Carolina Environ Study Group motion to reopen CL record re hydrogen generation control issue arising from TMI accident Certificate of Svc encl PORTER, W.L., MCGARRY, J.M. Duke Power Co. MCGARRY, J.M. Debevoise & Liberman 80/09/19 App
- BO09260266 Response in opposition to N Kiefer 800911 ltr seeking intervention if OL record reopened Petition deficient but limited appearance statement may be granted Cortificate of Svc encl MCOARRY, J M , PORTER, W L Consumers Power Co MCGARRY, J M Debevoise & Liberman 80/09/23 4pp
- 8009240273 Response in opposition to JJ Scott 800911 ltr seaking intervention if OL record respond Petition deficient but limited appearance statement may be granted Certificate of Svc enci MCGARRY, J M. PORTER, W.L. Consumers Power Co. MCGARRY, J M. Debevoise & Liberman. 80/09/23 4pp
- H General correspondence
- 8009100103 Responds to 800729 request for public hearing re effects of TMI-2 type accident on facility containment bldg Motions by util to terminate stay of ASLB 770418 decision 7 by intervenor to reopen proceedings are pending KETCHENLE G Hearing Branch 4 80/08/20 2pp
- 8009180385 Expresses concern re proximity of facilities to Charlotte. NC All safety factors should be considered prior to granting of OLs
  CDNVEY.N H Affiliation Unknown 80/09/11 2pp
- --BOO91804BO Expresses concern re proximity of facilities to Charlotte.
  NC Licensing hearings should be reopened due to problems
  w/low pressure containment bidg & danger of hydrogen
  explosion
  BCOTT.J J Affiliation Unknown 80/09/11 is
- 8009230746 Requests licensing hearings be reopened to consider low gressure containment bldg inability to withstand more than 15 psi Believes that TMI-2 pressure reached 28 psi KIEFER.N Affitiation Unknown 80/09/11 ip
- Q Inspection reports. IE Bulletins & correspondence
- 8009100058 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " Written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/07/24 is
- 8009030175 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Morcury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/15
- BD09030183 Ack receipt of IE Insp Rept 50-359/80-13 on 800610-19 No proprietary info PARKER, U Dute Power Co 80/08/15 ip
- ---8009030168 Forwards IE Insp Rept 50-369/80-13 on 800610-19 No noncompliance noted LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/07/28 2pp
- --8007030199 IE Insp Rept 50-369/80-13 on 800610-19 No noncompliance noted Major areas inspected preoperational testing, IE Bulletin 80-50 % previous insp findings UPRIGHT.C M Region 2. Atlanta, Reactor Operations Nuclear Support Branch JOHNSON, A H Region 2, Atlanta, Office of the Director 80/07/28 2pp
- 8009050545 Ack receipt of IE Insp Rept 50-369/80-15 on 800609,10,17 & 18 No proprietary info PARKER, W O Duke Power Co 80/08/15 ip
- ---8009050547 Forwards IE Insp Rept 50-369/80-15 on 800609.10.17 & 18 Mc noncompliance noted LEMIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/07/28 2pp

- --8009050550 IE Insp Rept 50-369/80-15 on 800609, 10.17 & 18 No noncompliance noted Major areas inspected hot functional testing preparation, preoperational test witnessing & responses to bulletins & circulans MARTIN, R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch DDNAT, T J Region 2, Atlanta, Office of the Director 80/07/28 5pp
- 8009140833 Respands to IE Bulletin 80-20 re failures of Westinghouse M-2 spring return to neutral control switches Identified switches are not used or planned to be used in safety-related areas Thirteen manhours expended for review PARKER, W O Duke Power Co 80/08/20 1p
- 8009160137 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required g'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/22
- 8009120343 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover( 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/27
- 8009250191 Ack receipt of IE Insp Rept 50-369/80-21 on 800714-18 No proprietary info PARKER, O Dute Power Co 80/08/27 lp
- --8009250196 Forwards IE Insp Rept 50-369/80-21 on 800714-18 No moncompliance noted STOHR, J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/08/07 2pp
- 8009120598 Responds to IE Bulletin 80-19 Mercury-wetted matrix relays are not used or planned for use in reactor protection sys PARKER,W O Duke Power Co 80/08/28 1p
- BOO9240201 Ack receipt of BO0605,30 & 0718 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-369/80-04 MURPHY.C & Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch BO/08/29 1p
- --3009240206 Responds to NRC IE Insp Rept 50-369/80-04 Corrective actions completion of evaluation of add1 hangers per 800630 ltr PARKER, N D Duke Power Ca 80/07/18 2pp
- --8009240212 Responds to IE Insp Rept 50-369/80-04 Corrective actions performed reinsp of hangers PARKER, N O Dute Power Co 80/06/30 2pp
- --8009240220 Responds to NRC 800512 ltr re violations noted in IE Insp Rept 50-349/80-04 Corrective actions rept issued to record items of noncompliance & evaluation performed to determine proper actions necessary to resolve problems PARKER, W D Duke Power Ca 80/04/05 3pp
- --8009240228 Forwards IE Insp Rept 50-369/80-04 on 800416-18 & notice of violation MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/12 2pp
- --8009240232 Notice of violation from insp on 800416-18 \* Region 2, Atlanta, Office of the Director 80/05/08 ip
- --B007240241 IE Insp Rept 50-369/80-04 on 800416-18 Noncompliance noted insp data for support 1-MCA-ND-H265 not available Three of five selfdrill expansion anchor bolts of support 1-MCA-ND-H76 determined to be torqued less than CP-308 requirements ANG.W P Region 2. Atlanta, Office of the Director HERDT, A R Region 2. Atlanta, Cactor Construction & Engineering Support Branch 80/05/08 4pp
- 8009290297 Forwards IE Circular 80-21, "Regulation of Refueling Crows" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/10 500

- B009300157 Submits response to IE Bulletin 79-13.Revision 2 During radiograph testing indication was found in auxiliary feedwater notile on steam generator A Indication is considered acceptable PARKER.W O Duke Power Co 80/09/11 1p
- S Reportable occurrences. LERs & related correspondence
- 8007040383 Significant deficiency rept re loose impoller cap & jam nuts on RHR Pump IA Caused by inadequacy of IR recommendation re IE Circular 77-19 Util has informed I-8 that recommendation util not resolve problem PARKER.H O Duke Power Co 80/08/28 2pp
- B007240481 Significant Deficiency Rept 5D 369/80-15 on B00917, pressurizer cavity exceeded design temp Caused by insufficient ventilation cooling flow 5 higher than design heat loads Permanent temp monitoring sys will be installed DONAT.T Duke Power Co 80/09/18 4pp

#### V Operator Examinations

- 8009240087 Requests detailed discussion & description of proposed licensed operator staffing plan projected through Dec 1983 by 800912 TEDESCO.R i. Assistant Director for Licensing 80/09/03 Jac
- 8009240448 Discusses proposed licensed operator staffing plan Marked-up Tech Specs Table & 2-1 re shift creu composition & breakdown of total licenses, individuals in training & available min requirements for Sept 1980-Jul 1981 encl PARKER.W O Duke Power Co 80/09/18 6pp
- DUCKET 50-370 WILLIAM B MCGUIRE NUCLEAR STATION. UNIT 2

  A Application/construction stage documents & correspondence
- 8007110636 Forwards requests for addl info re radwaste mgt sys.per review of FSAR Revision 39 Comments on radiological ETS & offsite dose calculation manual encl TEDESCO.R L Assistant Director for Licensing 80/07/29 8pp
- 80090800BO Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities ' Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl M/o NUREG EISENHUT, D G Division of Licensing 80/08/01 119pp
- 8009020122 Forwards request for addl info re floodplain mgt per Executive Order 11988 Response requested by 800808 TEDESCO,R L Division of Licensing 80/08/06 5pp
- 8009030069 Notification of 800904 meeting w/util in Bethesda.MD to discuss standby shutdown facility BIRKEL.R A Licensing Branch i 80/08/14 4pp
- 8009040434 Forwards mather NRC review of ice condenser containment & hydrogen control measures for Sequoyah Nuclear Power Plant ACRB has scheduled meetings in Washington, DC on 800828, 0902 & 04 to discuss issue TEDESCO, R L. Assistant Director for Licensing 80/08/22 5pp
- 8009120116 Requests add1 info re containment pressure boundary fracture toughness by 800903 TEDESCO, R L. Assistant Director for Licensing 80/08/22 3pp
- 8007070B77 Forwards request for add1 tofo re radiation protection Complete response should be provided by 800702 TEDESCO.R L Assistant Director for Licensing 80/08/25 4pp
- 8009180489 Requires submittal of ATMS emergency operating procedure for NRC review by 800919 Generic analysis should confirm ATMS mitigation capability described in Vol 3 of NUREO-0460 Commission will deformine required mods & schedules TEDESCO, R L Assistant Director for Licensing 80/08/25 4pp
- 8007120623 Forwards request for addl info re containment emergency sump performance under post-LOGA conditions Requests info by 800703
  TEDESCO.R L Assistant Director for Licensing 80/08/26 App
- 8009020371 Provides documentation of activities & current work status re hydrogen control in ice condenser containments Facility will have ECCS Bys will not generate substantial amounts of hydrogen ECCS will prevent hydrogen problem PARKER, W Q Duke Power Co 80708/27 3pp

- 9009160649 Requests info needed by 800908 for review of application re low pressure furbing discs TEDESCOR L Assistant Director for Licensing 80/08/27 3pp
- 8009150333 Forwards request for additinfo re Category I masonry wall design Requires response by 800919
  TEDESCO.R L Assistant Director for Licensing 80/08/29 5pp
- 8009100152 Requests info by 800919 to complete final Tech Specs Required info includes proposed changes requiring technical justification & identification of FSAR revisions subsequent to issuance of SER requiring Tech Spec changes YOU.KGRLOOD. B J Licensing Branch & 80/09/02 3pp
- 8009190236 Forwards FR notice re relocation of local PDR to Atkins Library, Unsv of NC. Charlotte, IJC FELTCH, J M Division of Rules and Records 80/09/02 2pp
- --8009190242 Notice of relocation of local PDR to Atkins Library,Univ of NC.Charlotte.NC FELTON.J M Division of Rules and Records 80/09/02 2pp
- 8009110345 Forwards updated responses to "Duke Power Co,McGuire Nuclear Station Response to TMI Concerns " Fuel loading for Unit 1 scheduled for Oct 1980 PARMER: N D Duke Power Co 80/09/03 34pp
- 8009150439 Notifies that util 800925 ltr re ATMS requirements responds to NRC 790817 & 800825 requests Ltr reflects current util intentions re interim ATMS procedures prior to DL issuance PARKER, N O Duke Power Co 80/09/09 ip
- 8009300644 Summary of 800904 meeting w/util in Bethesda.MD re final standby facility Connection w/station will occur subsequent to NRC review & approval Site visit considered for 800925-26
  BIRKEL.R A Licensing Branch 1 80/09/09 2pp
- 8009140600 Forwards response to RL Tedesco B00822 ltr requesting info re containment pressure boundary fracture toughness Matls test data in storage at facility Oversize drawings available in Central Files only PARKER.N O Dute Power Co 80/09/10 3pp
- 8007270001 Forwards request for add1 info concerning reactor sys re Branch Technical Position RSB 5-1 TEDESCO.R L Assistant Director for Licensing 80/09/11 5pp
- BOO9180375 Forwards add1 info re ECCS evaluations in response to RL Tedesco 800805 ltr Provides results of supplemental calculations to demonstrate potential impact of using fuel rod models.psr draft RUREG-0530. on LCCA analysis for Unit 1 PARKER, W O Duke Power Co 80/09/15 5pp
- BO09180322 Forwards draft emergency procedures for review, including immediate actions & diagnostics for safety injection.LQCA & steam generator tube rupture Secondary line rupture & loss of feedwater will be provided by BO0919 PARKER, W O Duke Power Co 80/09/16 1g
- ---8009180327 Draft emergency procedures, including immediate actions & diagnostics for safety injection, LOCA & steam generator tube rupture

  \* Duke Power Co 80/09/16 50pp
- BOO9190399 Responds to NRC 800520 Itr re NUREO-0577, "Potential for Low Fracture Taughness & Lamellar Tearing on PMR Steam Generation & Reactor Coolant Pump Supports " No response needed, pending add1 NRC guidance PARKER, W D Duke Power Co BO/09/14 ip
- G009190506 Forwards Revision 1 to util 800702 response re info request on Category 1 masonry walls PARKER.W 0 Duke Power Co 80/09/16 4pp
- 8009240409 Responds to NRC 800731 1tr stating position re incore thermocouples Thermocouple readout has capability for printout within 3-6 minutes Thermocouples are capable of measuring in 2,000 F range PARKER, N O Duke Power Co 80/09/17 2pp
- BOO9270169 Advises that auxiliary feedwater sys automatic initiation meets safety grade requirements re TMI Item II E 1 2,NUREO-0578,Saction 2 1 7 a Requests compliance demonstration.by 800929,re automatic removal of manual bypass YOUNG9LOUD.B J Licensing Branch 1 80/09/17 3pp

- 8009240489 Forwards response to Bulletins & Orders Task Force recommendations re auxiliary feedwater sys Response supplements info transmitted in 800819 ltr PARKER, NO Duke Power Co 60/09/18 7pp
- 8009290371 Advises that response to NRC 800827 request for info re draft Tech Specs has been sent PARKER, W O Duke Power Co 80/09/19 Ip
- 8009290303 Forwards addl info re Category I masonry wall design per NRC 800829 request Also forwards revised Page 3 of 800916 response PARKER:N O Duke Power Co 80/09/23 12pp
- 8009300434 Responds to NRC 800824 request for info re containment energency sump debris
  PARKER, W D Duke Power Co 80/09/24 4pp
- F Security, medical, emergency & fire protection plans
- 8009020029 Forwards facility emergency plan & related info PARKER, N D Duke Power Co 80/08/25 13pp
- --8009020033 Emergency plan for facility \* Duke Power Co 80/08/25 200pp
- 8007120572 Forwards emergency preparedness evaluation Current plan provides acceptable state of emergency preparedness for fuel load & low power testing GRIMES, B K Emergency Preparedness Program Office 80/09/04 App
- 9007270175 Advises that health physicist should report directly to station manager per Reg Guide 8 & & NUREG-0660 & NUREG-0674 re radiation protection organization Requests commitment to comply or explanation of alternate compliance w/criteria BIRKEL.R Licensing Branch 1 90/09/17 3pp
- G Adjudicatory correspondence
- 8009050086 Response in opposition to Carolina Environ Study Group 800607 & 0815 motions requesting recopening of hearing record New contentions re emergency planning & comparative containment design are impermissible attack on regulations MCGARRY, J M Dube Power Co MCGARRY, J M Debevoise & Liberman 80/09/03 23pp
- --8009050087 Affidavit re hydrogen generation & control following postulated TMI-type accident Util action effectively precludes excess hydrogen generation Certificate of Byc enc!
  CANADY, K S Duke Power Co 79/07/09 7pp
- 8009090241 Response urging deferral of ruling on Carolina Environ Study Group 800815 motion to reopen record re hydrogen generation issue anising from TMI accident Suggests 15 days for parties to file simultaneous reply W/Certificate of Svc KETCHEN.E 0 Hearing Branch 4 80/09/04 11pp
- 8009120282 Forwards 800819 FR notice amending emergency planning regulations
  KETCHEN.E G Hearing Branch 3 80/09/08 17pp
- 8009160343 Forwards FR notice of relocation of LPDR KETCHEN, E G Hearing Branch 4 80/09/12 1p
- --B009160347 Forwards notice of relocation of LPDR
  CHILK.S J Office of the Secretary of the Commission 80/09/05
- --8009160952 Notice of relocation of LPDR to Atkins Library, Univ of NC, Charlotte, UNCC Station, NC FELTON, J M Division of Rules and Records 80/09/02 ip
- 8009220425 Notice of appearance in proceeding Certificate of Svc encl CURTISS, J.R. Regulations Division 80/09/18 2pp
- 8009260010 Bubmittal updating applicant 800903 response in opposition to Carolina Environ Study Group motion to reopen GL record re hydrogen generation control issue arising from TMI accident Certificate of Syc encl PORTER, W L , MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman 80/09/19 6pp

- 8009260266 Response in opposition to N Kiefer 800931 ltr seeking intervention if GL record reopened Petition deficient, but limited appearance statement may be granted Certificate of Svc encl MCGARRY, J M . PORTER, W L Consumers Power Co MCGARRY, J M . Pohamies & Litherman . 8009/23 4nn
- 8069260273 Response in opposition to JJ Scott 800911 ltr seeking intervention if OL record reopened Petition deficient, but I imited appearance statement may be granted Certificate of Svc enci MCGARRY, J M , PORTER, W L Consumers Power Co MCGARRY, J M Dehaunisa & Liberman 80/09/23 4pp

### H General correspondence

- 8009100103 Responds to 800729 request for public hearing re effects of TMI-2 type accident on facility containment bidg Motions by util to terminate stay of ABLS 790418 decision & by intervenor to reopen proceedings are pending XETCHENLE O Hearing Branch 4 80/08/20 2pp
- 8009180385 Expresses concern re proximity of facilities to Charlotte, NC All safety factors should be considered prior to granting of CLs CCNVEY, W H Affiliation Unknown B0/09/ii 2pp
- 3007230746 Requests licensing hearings be reopened to consider low pressure containment bidg (nability to withstand more than 15 psi Beliaves that TMI-2 pressure reached 28 psi KIEFER.N Affiliation Unknown 80/09/11 ip
- G Inspection reports, IE Bullatins & correspondence
- 8009030175 Forwards Revision 1 to 1E Bulletin 80~19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY. J.P. Region 2, Atlanta, Office of the Director 80/08/15
- 8009160633 Responds to IE Bulletin 80-20 re failures of Westinghouse W-2 spring return to neutral control switches Identified switches are not used or planned to be used in safety—related areas Thirteen manhours expended for review PARKER, W O Duke Power Co 80/08/20 ip
- 8009150366 Ack receipt of 800807 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-370/80-08 MDRPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/08/22 ip
- --BD09150369 Forwards response to NRC 800718 ltr re violation noted in IE Insp Rept 50-370/80-08 Corrective actions procedures reviewed & all refs to unapproved procedures deleted PARKER/U O Duke Power Co 80/08/07 2pp
- --- 2007150372 Forwards IE Insp Rept 50-370/80-08 on 800616-19 & notice of violation MJRPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 80/07/18 2pp
- --8009150374 Notice of violation from insp on 800416-19 • Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/07/18. ip:
- --8009150377 IE Insp Rept 50-370/80-08 on 800616-19 Noncompliance noted failure of ultrasonic procedures to complete instructions for performing & recording exams YAJAC, L. D. Region 2, Atlanta, Office of the Director HERDT, A.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/18 ip
- 8009160137 Forwards IE Circular 80-18, "100FR80 59 Safety Evaluations for Changes to Radwaste Treatment 8ys " No written response required D'REILLY.J P. Region 2, Atlanta. Office of the Director 80/08/22
- 3009120262 Ack receipt of IE Insp Rept 50-370/80-11 on 800707-09 No proprietary info PARKER, M.J. Duke Power Co. 80/08/27 ip

- 8009120343 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover: 480 Vott Type K-6005 & K-DON 6005 Circuit Breakers" No written response required GREILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/27
- 8009120598 Responds to IE Sulletin 80-19 Mercury-wetted matrix relays are not used or planned for use in reactor protection sys PARKER.N D Duke Power Co 80/08/28 Ip
- 8009240256 Ack receipt of 800822 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-270/80-09 MURPHY.C E Region 2. Atlanta Reactor Construction & Engineering Support Branch 80/09/29 ip
- --8009240262 Responds to NRC 800725 ltr re-violations noted in IE Insp Rept 50-370/80-09 Corrective actions loose termination in referenced mater aperated valves corrected & inspected/new installation specs issued PARKER
- --8009240265 Forwards IE Insp Rept 50-370/80-09 on 800624-27 & notice of violation «WRPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 60/07/25 2pp
- --8009240270 Notice of violation from insp on 800624-27 \* Region 2, Atlanta, Office of the Director 80/07/25 2pp
- --B009240276 IE Insp Rept 50-370/80-09 on 800624-27 Noncompliance moted inadequate procedures for insp of safety-related cable terminations GIBEOUS, T.D. Region 2. Atlanta. Reactor Construction & Engineering Support Branch MERRIWEATHER, N., CONLON, T.E. Region 2. Atlanta. Office of the Director 80/07/25 4pp
- 8009270297 Forwards IE Circular 80-21, 'Regulation of Refueling Grews' No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/10
- 8 Reportable occurrences. LERs & related correspondence
- 8007040383 Bignificant deficiency rept re toose impeller cap & jam nuts on RHR Pump 1A Caused by inadequacy of IR recommendation re IE Circular 79-19 Util has informed I-R that recommendation will not resolve problem PARKER, U D byke Power Co 80/08/28 2pp

#### V Operator Examinations

- 8009240087 Requests detailed discussion & description of proposed licensed operator staffing plan projected through Dec 1983 by 800912 TEDESCO,R L. Assistant Director for Licensing 80/09/03 3pp
- 8009240448 Discusses proposed licensed operator staffing plan Marked-up Yech Specs Table 6 2-1 re shift crew composition 8 breakfown of total licensees, individuals in training & available min requirements for Sept 1980-Jul 1981 encl PARKER.W O Duke Power Co 80/09/18 6pp

#### DOCKET 50-373 LASALLE COUNTY STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 8007080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl N/o NUREG EIBENHUT, D & Division of Licensing 80/08/01 117pp
- 8009020126 Forwards request for add1 info re floodplain mgt per Executive Order 11988 Requests response completion schedule TEDESCO:R L. Division of Licensing 80/08/05 4pp
- B009090631 Notification of cancellation of B00827 meeting w/BWR licensing review group to discuss concensus positions on TMI issues (NUREO-0694) WILBOIL J N Assistant Director for Licensing 80/08/04 10pp

- 8009110420 Notification of 800915-19 meeting u/util at site to review control room design & operation BOURRIA:A Licensing Branch 1 80/08/25 3pp
- 8009110742 Notification of 800904-05 meeting w/Mark II owners group to discuss plants chugging C/O & lateral load specs ANDERSON.C Containment Systems Branch 80/08/29 14pp
- 8009110715 Notification of 800923 meeting w/util in Bethesda, MD to discuss soil properties utilized in soil interaction analyses
  - BOU-NIA.A Licensing Branch 1 80/09/03 3pp
- 8007180540 Notification of 800924 meeting w/util in Bethesda.MD to provide status of facilities requalification program for seismic qualification review tear BDURMAA Licensing Branch 1 80/09/08 3pp
- 8009180815 Forwards request for add1 into to complete evaluation of FSAR TEDESCO.R L Assistant Director for Licensing 80/09/10 7pp
- 8009140885 Informs of revised facility position on NUREO-0494. Task [1 D 3 3 re portable (odine instrumentation One SAM & five Ping-Eberline rodine monitor sys will be available at site Equipment meets NRC requirements DEL GEORGE.L D Commonwealth Edison Co 80/09/11 19
- 8009180404 Forwards "Chugging Loads for Assessment of 4TCO Data." Re.ision I.suppl to containment design assessment rept Revision withheld (ref IOCFR2 790) DELGEORGE, LO Commonwealth Edison Co 80/09/12 2pp
- 8009260091 Notifies of 801007 proposed date to review whether DBE & SRV responses should be considered separately or combined during ASMF code facings calculations GE selected samples to emphasize highly fatigued components
  WILSON, J.N. Assistant Director for Licensing 80/09/15 9pp
- 8007240511 Forwards errata to suppl to "Chugging Loads for Assessment of 4TCO Data." Revision 1 Revision withheld (ref 10CFR2 790)
  DELOEDROE, L O Commonwealth Edison Co 80/09/23 Rpp
- F Security, medical, emergency & fire protection plans
- 8007100378 Forwards review of util generating station amergency plan & draft ltr requesting addl info & commitments from util PAOAMO.F G Emergency Praparedness Licensing Branch 80/08/28
- 8009110400 Advises of acceptance of safeguards contingency plan submitted by 800324 ltr YOUNOBLOOD,B J Licensing Branch 1 80/09/02 2pp
- 8009250489 Immediate action ltr re potentially deficient fire stop matl mfg by Tech-Sil.Inc Lists products round to be in nonconformance w/project & NRC requirements & actions to be completed before leaded elastomer installation is continued KEPPLER, J G Region 3. Chicago, Office of the Director 80/09/04
- G. Inspection reports: JE Bulletins & correspondence
- 8009040517 Forwards IE Bulletin 80-07, Suppl 1, "BWR Jet Pump Assembly Failure " Response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/14
- B009:50022 Forwards JE Insp Rept 50-373/80-25 on B00520-23,27-30,0403-06 & 10-13 % notice of violation HEISHMAILR F Region 3. Chicago. Reactor Operations Nuclear Support Branch B0/07/24 Zpp
- --8009150024 Notice of violation from insp on 800520-23,27-30,0403-06 & 10-13 \* Region 3. Chicago, Office of the Director 80/07/23 3pp
- --8009150025 IE Insp Rept 50-373/80-25 on 800520-23.27-30.0603-06 & 10-13 Nancompliance noted failure to complete procedure changes required to ensure that drywell pneumatic air on nitrogen bottles manifold vented during ILRT STREETER.J Region 3. Chicago, Reactor Operations Nuclear Support Branch MANA.F. MCGREOGR.L Region 3. Chicago, Office of the Director 80/07/23 12pp

- 8009180266 Forwards IE Insp Repts 50-373/80-29 & 50-374/80-18 on B00708-10 No noncompliance noted FIORELLI.G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/07/28 2pp
- --BO09180280 IE Insp Repts 50-373/80-29 & 50-374/80-18 on 800708-10 Na noncompliance noted Major areas inspected observation of work inside Unit 2 reactor pressure vessel, licensee actions re 10CFR50 55s (tems & IE bulletins NILLIAMS, C C , ERB.C M , NEISLER, J H Region 3, Chicago, Office of the Director 80/07/25 App
- 8009020109 Responds to IE Bulletin 79-03A, "Longitudinal Weld Dyferts in ASME SA-312, Type 304 Stainless Steel Pipe " SA-312 pipe not present in operating plants Final confirmation from suppliers anticipated by 800915 re const plant piping sys NAUOHTON, W F Commonwealth Edison Co 80/08/07 2pp
- 8009290462 Forwards IE Insp Rept 50-373/80-31 on 800729-30 No noncompliance noted FIGRELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/08/14 2pp
- --8009270465 IE Insp Rept 50-373/80-31 on 800727-30 No moncompliance noted Major areas inspected suppression pool modifollowup insp on deficiency unresolved items & observation of instrumentation installation records
  NEISLER, J H , WILLIAMS, C C Region 3, Chicago, Office of the Director 80/08/13 4pp
- 8009030231 Forwards Revision 1 to IE Bulletin 80-17, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E "Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/15 to
- 8009110545 Responds to IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds," supplementing 800709 response Corrects Zion response re rings used for field circumferential butt weld Reviews accuracy of other statements ABEL,JS Commonwealth Edison Co 80/08/15 4pp
- 8009160681 Submits supplementary response to IE Bulletin 80-08.
  "Examination of Containment Liner Penetration Welds."
  correcting statement made in DL Peoples 800709 ltr Further
  review not necessary
  ABEL, J S Commonwealth Edison Cg 80/08/15 4pp
- 800912003B Forwards Suppl 3 to [E Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BHR " No written response required KEPPLER: J Q Region 3, Chicago, Office of the Director 80/08/22
- 8009180551 Forwards IE Circular 80-18. "IOCFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER.J O Region 3. Chicago, Office of the Director 80/08/22
- 8009120558 Advises that insp exemptions were probably made on 27 pipelines under ASME Code. Secitor XI. 1W8-1120 Method of analysis for exemptions was correct, but input assumptions were in error Values based on assumptions encl YOUNOBLOOD, B J Licensing Branch i 80/08/25 5pp
- 8009180040 Forwards IE Insp Repts 50-373/80-32 & 50-374/80-20 on 800806-08 & notice of violation KEPPLER,J G Region 3, Chicago, Office of the Director 80/08/27
- --8009180047 Notice of violation from insp on 800804-08 \* Region 3. Chicago. Office of the Director 80/08/25 3pp
- --8009180094 IE Insp Repts 80-373/80-32 % 50-374/80-20 on 800806-08
  Noncompliance noted inadequate document control inadequate
  GA audits & surveillance lack of approved work procedures &
  lack of training program for contract personnel
  DANIELSON.D H. Region 3. Chicago, Reactor Construction &
  Engineering Support Branch YIN, I T. Region 3. Chicago, Diffice of
  the Director 80/08/25 6pp
- 8009230094 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/08/28

- B009180466 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Identified relays are not used in facility No action required Twenty-four manhours expended on review RAUSCH. T J Commonwealth Edison Co 80/08/29 1p
- 8009190007 Responds to IE Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters Identified transmitters are not used in Byron & Braidwood safety-related areas LaBalle will comply w/requirements by defining mods by 801001 RAVSCH.T J Commonwealth Edison Co 80/08/29 2pp
- 8009250468 Supplemental response to IE Bulletin 80-09. "Hydramotor Actuator Deficiencies " Deficient springs in actuators w/ Masonerlian valves for safety-related applications will be replaced prior to shipment to site RAUSCH.T J Commonwealth Edison Co 80/08/29 3pp
- 8009240133 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required XEPPLER, J.G. Region 3, Chicago, Office of the Director 80/09/10 in
- B009300200 Forwards response to IE Bulletin 80-20 No Westinghouse Type W-2 control switches are used in safety-related sys at Dresdan Quad Cities & LaBalle County Responses for Zion & Byron are encl RAUSCH.T J Commonwealth Edison Co B0/09/15 App.
- S Reportable occurrences, LERs & related correspondence
- 8007040599 PNO-III-80-153 on 800814.Region 3 to issue immediate action ltr confirming util cessation of onsite design & installation activities involving small bore pipe hangars Action result of deficiencies identified in 800807-08 insp. WEISLER, J H , WILLIAMS.C C Region 3, Chicago, Office of the Director FIORELLI.G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/14 1p
- 8009250489 Immediate action ltr re potentially deficient fire stop math add by Tech-8il. Inc Lists products found to be in nonconformance w/project & NRC requirements & actions to be completed before leaded elastomer installation is continued KEPPLER. J G Region 3, Chicago. Office of the Director 80/09/04 20p
- 8009270379 Final interim deficiency rept re MSIV leakage control sys E32 being installed E23 equipment cannot meet functional requirements to relieve steamline pressure Mods being implemented & will be completed prior to fuel lead BELGEORGE, L O Commonwealth Edison Co 80/09/19 2pp
- V Operator Examinations
- 8009300287 Forwards preliminary topical outlines of proposed modules on thermal hydraulics & core damage mitigation to be included in revised reactor operator training program per 800328 request NAVOHTON. U F Commonwealth Edison Co 80/09/15 7pp
- DOCKET 50-374 LABALLE COUNTY STATION, UNIT 2
- A Application/construction stage documents & correspondence
- BOOTOBOORO Forwards draft NUREG-0676, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl W/o NUREG EISENHUT. D 0 Division of Licensing 80/08/01 117pp,
- 8009020126 Forwards request for add1 info re floodplain mgt per Executive Order 11988 Requests response completion schedule TEDESCO.R. L. Division of Licensing 80/08/05 4pp
- 8007110420 Notification of 800715-19 meeting w/util at site to review control room design & operation
  ECURNIA, A Licensing Branch 1 80/08/25 3pp
- 8009110715 Notification of 800923 meeting w/util in Bethesda,MD to discuss soil properties utilized in soil interaction analyses
  8008NIA:A Licensing Branch 1 80/09/03 3pp
- 8009180540 Notification of 800924 meeting w/util in Bethquada, MD to provide status of facilities requalification program for seismic qualification review team BDURNIA.A Licensing Branch 1 80/09/08 3pp

- 8009180515 Forwards request for addition to complete evaluation of FSAR
  TEDESCO.R L Assistant Director for Licensing 80/09/10 7pp
- 8009:60585 Informs of revised facility position on NUREG-0694. Task II D 3 3 re portable iodine instrumentation One SAM & five Ping-Eberline rodine monitor sys will be available at site Equipment meets NRC requirements

  DEL GEORGE.L O Commonwealth Edison Co #0/09/11 1p
- BOO9180406 Forwards "Chugging Loads for Assessment of 4TCD Data," Revision 1, suppl to containment design assessment rept Revision withheld (ref IOCFR2 790) DELGEDROE: LO Commonwealth Edison Co 80/09/12 2pp
- 80092605)1 Forwards errata to suppl to "Chugging Loads for Assessment of 4TCO Data." Revision 1 Revision Cithheld (ref 100FR2 790)
  DELGEORGE, LO Commonwealth Edison Co 80/09/23 2pp
- F Security, medical, emergency & fire protection plans
- BO09250489 Immediate action ltr re potentially deficient fire stop math meg by Tech-Sil. Inc Lists products found to be in nonconformance w/project % NRC requirements % actions to be completed before leaded elastomer (installation is continued KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/04
- 6009100378 Forwards review of util generating station emergency plan & draft ltr requesting addl info & commitments from util PAGAKO.F G Emergency Preparedness Licensing Branch 80/08/28 550
- 8009110400 Advises of acceptance of safeguards contingency plan submitted by 800324 ltr YOUNGBLDOD.B J Licensing Branch 1 80/09/02 2pp
- Of Inspection reports, IE Bulletins & correspondence
- 8007040517 Forwards IE Builetin 80-07. Suppl i. "BNR Jet Pump Assembly Failure " Response required KEPPLER, J G Region 3. Chicago. Office of the Director 80/05/14
- 8007180266 Forwards IE losp Repts 50-373/80-29 & 50-374/80-18 on B00708-10 No noncompliance noted FIGRELLIG Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/07/28 2pp
- ---B009180280 IE Insp Repts 50-3/3/80-29 % 50-374/80-18 on 800708-10 No noncompliance noted Major areas inspected observation of work inside Unit 2 reactor pressure vessel, licensee actions re 10CFRS0 55e items & IE bulletins WILLIAMS, C C, ERB. C M, NEISLER, J H Region 3, Chicago, Office of the Director 80/07/25 App
- 8009020109 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME 8A-312. Type 304 Stainless Steel Pipe " SA-312 pipe not present in operating plants final confirmation from suppliers anticipated by 800915 re
- 8009030231 Forwards Revision i to IE Builetin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/15 1p
- 8009110945 Responds to IE Bulletin 80-08. "Exam of Containment Liner Penetration Wolds," supplementing 800709 response Corrects Zion response re rings used for field circumferential butt weld Reviews accuracy of other statements ABEL.US Commonwealth Edison Co 80/08/15 App
- 8009160681 Submits supplementary response to TE Bulletin 80-08, "Examination of Containment Liner Penetration Welds." correcting statement made in DL Peoples 800709 Itr Further review not necessary ABEL.J S Commonwealth Edison Co 00/08/15 4pp
- 8009120038 Forwards Suppl 3 to 1E Builetin 80-17, "Failure of Control Rods to Insert During Scram at BNR" No written response required KEPPLER, J Q Region 3, Chicago, Defice of the Director 80/08/22 ip

- 8009180551 Forwards IE Ciicular 80-18, "IOCFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/22
- 8009120558 Advises that inspleremptions were probably made on 27 pipelines under ASME Code. Seciton VI. 1MB-1120 Method of analysis for exemptions was correct, but input assumptions were in error Values based on assumptions encl. YOUNGBLOOD, B. J. Licensing Branch 1 80/08/25 5pp
- 8009180040 Forwards lE Insp Repts 50-373/80-32 & 50-374/80-20 on 800806-08 & notice of violation KEPPLER.J G Region 3. Chicago. Office of the Director 80/08/27
- ---8099180047 Notice of violation from insp on 800806-08 \* Region 3, Chicago, Office of the Director 80/08 B0/08/25 3on
- --B009180054 IE Insp Repts 50-373/80-32 % 50-374/80-20 on B00806-08
  Noncompliance noted inadequate document control inadequate
  GA audits % surveillance lack of approved work procedures &
  lack of training program for contract personnel
  BAMSELSUN.D H Region 3. Chicago, Reactor Construction &
  Engineering Support Branch YIN.I T Region 3. Chicago, Office of
  the Director 80/08/25 6pp
- 8009230094 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Bovers 480 Volt Type K-6005 & K-DON 6005 Gircuit Breakers" Na written response required KEPFLER.J G Region 3. Chicago, Office of the Director 80/08/28
- 8009180456 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrir relays in reactor protective sys identified relays are not used in tacility No action required Twenty-four manhours expended on review
  RAUSCH.T J Commonwealth Edison Co 80/09/29 1p
- 8009190907 Responds to JE Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters Identified transmitters are not used in Byron & Braidwood safety-related areas LaSalle will comply w/requirements by defining mods by 801001 RAUSCH.T.J. Commonwealth Edison Co. 80/08/29 2pp
- 8009250468 Supplemental response to IE Bulletin 80-09. "Hydramotor Actuator Deficiencies " Deficient springs in actuators w/ Masoneilian valves for safety-related applications will be replaced prior to shipment to site RAUSCH.T J Commonwealth Edison Co 90/08/29 3pp
- 8009240133 Forwards IE Circular 80-21, "Regulation of Refueling Crews " No written response required KEPPLER, J.G. Region 3, Chicago, Office of the Director 80/09/10
- 8009300200 Forwards response to IE Bulletin 80-20 No Westinghouse Type 4-2 control switches are used in safety-related sys at Dresden. Guad Citles & LaSalle County Responses for Zion & Commonwealth Edison Co 80/09/15 App
- S Reportable occurrences. LERs & related correspondence
- 8009290497 Immediate action itr re-potentially deficient fire stop matl mfg by Tech-Sil, Inc Lists products round to be in nonconformance w/project & NRC requirements & actions to be completed before leaded elastomer installation is continued KEPPLER, J G Region 3. Chicago, Office of the Director 80/09/04
- 8009290399 Final interim deficiency rept re MSIV leakage control sys E32 being installed E23 equipment cannot meet functional requirements to relieve steamline pressure Mods being implemented & will be completed prior to fuel load DELGEORGE.L O Commonwealth Edison Co 80/09/19 2pp
- V Operator Examinations
- 8009300287 Forwards preliminary topical outlines of proposed modules on thermal hydraulics & core damage mitigation to be included in revised reactor operator training program per 800326 request NAUGHTON, H F Communuealth Edison Co 80/09/15 7pp

- DOCKET 50-376 NORTH COAST NUC PLANT G Adjudicatory correspondence
- 8009040225 Motion for clarification of scope of single issue to be tried in ASLB 800817 order re intervenor 800430 petition on lack of intention to build Praws attention to util inaction & contradictory actions W/Certificate of Svc FERNOS.0 Citizens for the Conservation of Natural Resources, Inc 80/08/27 3pp
- 8009040233 Motion for ruling on intervenor 800718 submission seeking legal assistance during hearings plus round trip travel & lodging expenses for counsel Certificate of Svc encl FERNOS.0 Citizens for the Conservation of Natural Resources.Inc 80/08/27 3pp
- B009110010 Motion advising of temporary substitution of author Requests incorporation of T Morales on svc list in absence W/Certificate of Svc FERNOS, G Citizens for the Conservation of Natural Resources, Inc B0/09/03 2pp
- 8009110055 Interrogatories & request for production of documents directed to applicant Questions applicant financial statement re past & future total investment in project Certificate of Svc encl FERNOS, © Citizens for the Conservation of Natural Resources, Inc 80/09/03 5pp
- 8087090411 Order granting extension until 800919 for Commission to review ALAB-605
  MOYLE.J C Office of the Secretary of the Commission 80/09/05
- 8009110065 Order denying part of Citizens for Conservation of Natural Resources 800827 motion for legal assistance from FY80 appropriations Funds may or may not be appropriated in FY81 Intervence 800827 motion re intention to build denied WGLFE.S J Atomic Bafety and Licensing Board Panel 80/09/08 2pp 90/09/09 2nm
- 8009110021 Interrugatories & requests for production of documents directed to Puerto Rico Water Resources Authority Requests info re Islote site development & latest long-range forecast for energy & peak load demands W/Certificate of 8vc HCGURREN, H J Hearing Branch 1 80/09/07 8pp
- 800914014B Motion for withdrawal of application for CP AXELRAD.M Puerto Rico Electric Power Authority AXELRAD.M Lowenstein.Newman.Reis.Axelrad & Toll B0/09/11 fp ,
- --8009150151 Motion for termination of proceeding due to encl withdrawal of application Certificate of Svc encl AXELRAD, M Puerto Rico Electric Power Authority AXELRAD, M Lowenstein, Newman, Reis, Axelred & Yoll 80/09/ii 3pp
- 8009180554 Requests Commission take no action re ALAB-605 Intervenor must present case to ABLB before Commission acts to review ALAR-605 Intervenor counsel in hose until after Commission action deadline of 800919 Certificate of Svc encl CARDONA.T M Citizens for the Conservation of Natural Resources.Inc 80/09/13 2pp
- 8009240470 Motion for direct certification requesting that CP application be dismissed w/prejudice rather than accepting applicant withdrawal terminating proceeding Certificate o Svc encl FERNOS, G 80/09/17 Citizens for the Conservation of Natural Resources, Inc.
- --8009280681 Addendum to 800917 motion for direct certification which requested that CP application be dismissed w/prejudice Applicant withdrawal evading direct confrontation w/issues raised & litigated for 5 yrs is unfair W/Certificate of Svc FERNOS, 0 Citizens for the Conservation of Natural Resources, Inc 80/09/18 2pp
- --8007260684 Motion for stay of proceeding until Commission rules upon direct certification seeking dismissal of application w/ prejudice Certificate of Svc enci FERNOS. Q Citizens for the Conservation of Natural Resources, Inc 80/09/18 2pp
- 8009230049 Response stating no opposition to util 800912 motion for bermination of proceeding & withdrawal of application Certificate of Svc encl MCOURREN.H J Hearing Branch 1 80/09/19 3pp

- BOO9250007 Advises that NRC does not intend to respond to Citizens for Conservation of Natural Resources BOO903 motion of temporary thange of address unless advised to contrary by ASLB MCOURRENH J Hearing Branch 1 B0/09/23 1p
- 8009250022 Forwards NRC Rules of Practice in response to 800903 ltr Arrangements will be made for temporary availability of NRC Issuances in LPDR N/o enc1 MCQURREN.H J Hearing Branch 1 80/09/23 ip
- 8009230439 Advises that intervenor answer to 800911 withdrawal of application & motion for termination of proceeding, on behalf of PR Electric Power Authority, has not been received Certificate of Svc encl HOLFE, S. J., COLE, R.F. Lowenstein, Newman, Reis, Axelrad & Toll 80/07/25 4pp
- 8009300462 Advises that util will not respond to discovery requests due to 800918 withdrawal of application Reserves right to file objections or motion for protective order if attempts are made to pursue proceeding Certificate of Svc encl AXELRAD, M Lowenstein, Newman, Reis, Axelrad & Toll 80/09/25 4pp

#### DOCKET 50-378 CAORSD NUCLEAR STATION

- A Application/construction stage documents & correspondence
- 8009110742 Notification of 800904-05 meeting w/Mark II owners group to discoss plants chugging C/D & lateral load specs ANDERBON.C Containment Systems Branch 80/08/29 14pp

## DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3

- A Application/construction stage documents & correspondence
- BOOT110565 Notification of 800813 meeting ω/util in Bethesda. MD to discuss facility review status
  KANE,W Licensing Branch 2 80/07/22 2pp
- 8009080080 Forwards draft NUREG-D696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 enci W/o NUREG EISENHUT, D O Division of Licensing 80/08/01 119pp
- 8009190010 Summary of 800813 meeting w/util in Bethesda,MD to discuss status of application for OL & potential problem areas
  KANE,W F Licensing Branch 2 80/08/26 5pp
- BO09240968 Forwards Mechanical Engineering Branch & ORNL status review re FSAR through Amend 8 & request for add1 info Util should prepare meeting agenda re resolution of open issues
  TEDESCO.R L. Assistant Director for Licensing 80/09/04 33pp
- BOO9230437 Forwards 800901 revised PWR const milestone & activities itst Const is 83% complete MAURIN,L V Louisiana Power & Light Co 80/09/19 8pp

#### H General correspondence

- 8009190491 Notifies of organizational changes in util LV Maurin has been named facility project director Forwards organization chart Press release encl ASHELL,D L. Louisiana Power & Light Co 80/09/16 2pp
- --8009190494 Util organization chart
  \* Arkansas Power & Light Co 80/09/16 1p
- O Inspection reports, IE Bulletins & correspondence
- 8009170368 Completes response to IE Bulletin 80-05 re spont resin tank Vent valve to vent gas collection header locked open except during resin transfer to prevent excessive vacuum conditions
  ASMELL.D L Louisiana Power & Light Co 80/07/11 ip
- BOC9170168 Forwards IE Insp Rept 50-382/80-12 on 800623-27.No noncompliance noted. HADSEN/G L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/07/31 2pp
- --8009170172 IE Insp Rept 50-382/80-12 on 800623-27 No noncompliance noted Major areas inspected operational staffing & overall preoperational test program CONSTABLE.9 L. WESTERMAN.1 F Region 4, Dailas. Office of the Director 80/07/31 3pp

- 8004190158 Submits response to IE Bulletin 79-03A Two pieces Type 300 series fusion welded pipe installed in containment spray sys Both pieces removed Subj pipe in storage will be removed from site
  ASWELL-D L Louisiana Power & Light Co 80/08/06 2pp
- 8009190153 Submits response to IE Bulletin 80-19 Reactor protective sys does not use mercury-wetted relays ASMELL.D L Louisiana Power & Light Co 80/08/08 1p
- 8009190333 Forwards IE Insp Rept S0-382/80-18 on 800728-31 No noncompliance noted SEIDLE N C Region 4. Dallas. Reactor Construction & Engineering Support Branch 80/08/13 3pp
- --8007190340 IE Insp Rept 50-382/80-18 on 800720-31 No noncompliance noted Major areas inspected welding activities on RCPB & other safety-related piping & installation of electrical of electrical cable CROSSMANW A Region 4, Dallas, Reactor Construction & Engineering Support Branch HALLAR E. GLOBERT, L. D. Region 4, Dallas, Office of the Director 80/08/12 App
- 8009300089 Forwards IE Insp Rept 50-382/80-16 on 800722-25 No noncompliance noted SEIDLE.W C Region 4. Dailas. Reactor Construction & Engineering Support Branch 80/08/14 2pp
- ---8009300096 IE Insp Rept 50-382/80-16 on 800722-25 No noncompliance noted Major areas inspected follow-on review of immediate action Itr & previously identified unresolved items STEMART.R C. CROSSMAN W A Region 4. Dallas, Office of the Director 80/08/13 4pp
- 8007030266 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Marcury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E "Unitten response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/08/15
- 8009170397 Forwards IE Circular 80~18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/08/22
- B009120427 Forwards IE Info Notice B0-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-600S & K-DON 600S Circuit Breakers "
  No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/08/27
- B009300092 Submits response to 1E Bulletin 80-16 Investigation of subjudiletin is still in progress Expects to submit final rept by B01020
  ABHELL, D L Louisiana Power & Light Co 80/08/27 ip
- B009170180 Forwards IE Insp Rept 50-382/80-19 on 800611 No noncompliance noted KELLY.J ∧ Region 4, Dallas, Office of the Director 80/08/27 ip
- --8009170183 IE Insp Rept 50-382/80-19 on 800611 No nancompliance noted Major areas inspected plans for security & independent insp effort CALDWELL, R. A. KELLYJ A. Region 4, Dallas, Office of the Director 80/08/27, in
- B009300212 Submits response to 1E Builetin 80-09 ITT General Controls Series AH-90 & NH-90 hydramotor actuators will be used in safety-related sys Problems are being investigated & corrective actions are being taken ASWELL,D L Louisiana Fower & Light Co 80/08/29 2pp
- 8009300100 Submits response to IE Bulletin 80-20 re failures of Westinghouse Type W-2 switches Investigation of subjbulletin is still in progress Expects to submit final reptby 801005
  MAURIN.L V Louisiana Power & Light Co 80/09/09 1p
- 8 Reportable occurrences. LERs & related correspondence
- 8009300342 Notifies that util response to Potential Const Deficienty 27 re ITT General Control actuators will be addressed in response to IE Bulletin 80-09, "Hydramator Actuator Deficiencies " Response will be completed by 800829 ASHELL,D L. Louisiana Pawer & Light Co. 80/08/15 ip

- B009300338 Final rept re Significant Const Deficiency 10 re defective emergency generator roller pins Roller pin diameter redesigned to provide interference fit at assembly between pin 2 crosshead 2 reduce clearance between pin 2 coller ORNICH J. MILHISER, R. J. HART, J. Louisiana Power & Light Co. 80/09/18 3pp
- 8009290094 Forwards final repts of Significant Const Deficiency & re emergency diesel generator sharts & springs & Significant Const Deficiency 10 re defective emergency diesel generator roller pins W/o Rept of Const Deficiency 10 ASNaLL.D L Louisiana Power & Light Co 80/09/23 1p
- --8009290396 Final rept of Const Deficiency 6 re defective shafts & springs for Cooper-Bessemer emergency diesel generators Caused by additemath on splines and of shafts & cracks in spring base metal New shaft fabricated & spring reworked HARTINETI.R A . CRNICH.J . MILMISER.R J Louisiana Power & Light Co 80/09/18 3pp
- --8009290398 Part 21 rept re shaft defects in two emergency diesel generator sets supplied to Ebasco Svcs, Inc for util Caused by addl length in splined driven end of shafts Replacement will be completed by 780930 BENDER, B Cooper Industries, Inc., Cooper - Bessemer Co Div 78/07/25
- ---8009290401 Part 21 rept re spring defect in six emergency diesel generator sets supplied by Cooper Energy Svcs to nuclear facilities Caused by cracks in base metal resulting from electrolytic plating Spring will be replaced by 780930 BENDER, B Cooper Industries, inc. Cooper Energy Services Div 78/07/25 2pp
- DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

  A Application/construction stage documents \$ correspondence
- 9007030285 Responds to 800417 request for info re NRC involvement in archeological data recovery activities for FY79 Completed questionnaire encl
  DENION, HR Office of Nuclear Reactor Regulation, Director
  80/06/11 7pp
- --8009030314 Requests info re NRC involvement in archeological data recovery activities for FY79 & forwards questionnaire DELAPORTE.C T Interior.Dept of 80/04/17 4pp
- B0090B0080 Forwards draft NUREC-0596. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREC-0596 Encl W/o NUREC EISENHUT.D C Division of Licensing 80/08/01 119pp
- G009090831 Notification of cancellation of B00827 maeting w/BWR licensing review group to discuss concensus positions on TMI issues (MUREC-0694) WILSON JN Assistant Director for Licensing 80/08/04 10p
- 8009150498 Summary of 80082; meetings w/Brchtel,util.0E & Savannah River Plant in Bethesda.MD re FSAR open review items STARK.R M Licensing Branch | 80/08/26 App
- BO09080364 Documents agreements reached 1 actions to result from 800714-16 meeting w/NRC re draft B00421 SER & open items in FSAR Sections 3 6 through 3 10 CURTIS-N W Pennsylvania Power & Light Co 80/08/28 105pp
- 8009110742 Notification of 800904-05 meeting w/Mark II owners group to discuss plants chugging C/O & lateral load specs ANDERSON, C Containment Systems Branch 80/08/29 14pp
- 8009120651 Notification of 800926 meeting ω/util in Bethesda MD to discuss fuel load date STARK.R M. Licensing Branch I. 80/09/04 1p
- ---B009120640 Responds to NRC 80071; itr re request for estimate of fuel load dates Primary sys fill & flush or Unit 1 completed & hydro & reactor internal vibration test near completion H/ 594 of plant sys in startup.completion by 810601 is likely CURTIS.N W Pennsylvania Power & Light Co 80/08/19 App
- 8009100484 Forwards request for add1 info re accident evaluation, needed for review of OL applications RM Start principal contact TEDESCO,R L Assistant Birector for Licensing 80/09/05 4pp
- 6009180464 Summary of 800821 meeting φ/uts1 in Bethesda.MD re forecasted fuel load date STARX.R M. Licensing Branch 1 80/09/05 3pp

- B009150470 Forwards complete response to SA Varga B00421 request for info on Category I masenry walls employed by plants under CP & GL review CURTIS.N W Pennsylvania Power & Light Co 80/09/08 Bpp
- 8009160310 Forwards document used to establish recommended instrument nominal trip setpoints & Tech Specs limits per 800821 request
- requast CUQTIS.N N Pennsylvania Power & Light Co 80/09/10 19pp
- 8009170290 Forwards ASME Boiler & Pressure Vessel Code, Section 3 overpressure rept per FSAR Question 211 204 CURTIS, N.W. Pennsylvania Power & Light Co. 80/09/12 25pp
- 8009240091 Notifies of 801007 proposed date to review whether OBE & SRV responses should be considered separately or combined during ASMF code fatigue calculations GE selected samples to emphasize highly fatigued components

  HELSON.J N Assistant Director for Licensing 80/09/15 9pp
- D NRC Braft/Final Environmental Statements, supple & correspondence
- 8007100082 Responds to 800626 itr requesting comments on anci K Spailone itr re potential impact of Pond Hill Reservair dam failure Dam safety not under NRC review KRC is reviewing potential environ impact of dam const & operation DIRCKS.N J Office of the Executive Director for Operations 80/08/18 3pg
- F Security, medical, emergency & fire protection plans
- 8009300669 Notification of 801027 meeting w/util in Berwick,PA to view status & configuration of electrical sys w/respect to electrical separation & fire protection STARK,R M Licensing Branch | 80/09/10 4pp
- Q Adjudicatory correspondence
- 8009120295 Requests time to make limited appearance statement at licensing hearings Requests to be informed when & where hearings will be held GAWAYCH M A Affiliation Unknown 80/09/Q2 is
- 8009110787 Advises that NRC will not respond to applicants' 800822 motion for partial summary disposition of Contention 17 records (issue Commission regulations allow only opposing replies

  CUTCHIN.J M Hearing Branch 3 80/09/08 ip
- 8009110016 Response in opposition to Environ Coalition on Nuclear Power 800822 request for free prohearing conferences transcripts prior to 800729 Does not oppose grant of transcripts of future sessions Certificate of Svc encl CUTCHIN. J M. Hearing Branch 3 80/09/09 Spp
- 8009180394 Motion in apposition to applicant request for summary disposition of Contention 17 re ozone Issue is of public interest I requires hearing Motion grant would prevent full litigation of Contention 17 M/Certificate of Svc HALLIGAN,T J Citizens Against Nuclear Dangers 80/09/10 2pp
- 8007160414 Requests to make limited appearance statement at licensing hearing for facility GOROONE: A Affiliation Unknown 80/09/12 ip
- 8007270043 Decision, ALAB-613, denying Environ Coalition on Nuclear Power 800315 petition referred to ASLAB on 800516, re alleged ASLAB refusal to stop applicants discovery harassments Supporting documentation encl BISHOP, C. J. Atomic Safety and Licensing Appeal Panel 80/09/23 127ab
- Q inspection reports, IE Audietins & correspondence
- 8007070094 Forwards IE Bulletin 80-07, Suppl 1, "BWR Jet Pump Assembly Failure " No response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/05/13 1p
- 8009250299 Forwards IE Insp Repts 50-387/80-13 \$ 50-388/80-09 on 800602-05 No noncompliance noted CARLSGIRT T Region 1. Pailadelphia, Reactor Construction & Engineering Support Branch 80/07/11 2pp

- ---BD09250302 IE Insp Repts 50-387/80-13 % 50-388/80-09 on 800602-05 No noncompliance noted Major areas inspected installation of water supply & distribution sys.water & gaseous suppression sys.specs & drawings & GA program EBMETER.S D Region 1. Philadelphia. Reactor Construction & Engineering Support Branch KOLTAY.P S Region 1. Philadelphia. Office of the Director 80/07/08 7pp
- B00917023i Forwards IE Insp Repts 50-387/80-10 & 50-388/80-06 on B00421-0516 & 27-30 No noncompliance noted CARLSON,R T Region I. Philadelphia, Reactor Construction & Engineering Support Brench 80/07/15 2pp
- --8009190241 IE Insp Repts 50-387/80-10 & 50-388/80-06 on 800421-0516 & 27-30 No noncompliance noted Major areas inspected installation & welding of RCPB & other piping & installation of safety-related components HCGAUGHY, R W Region 1. Philadelphia. Reactor Construction & Engineering Support Branch GALLO, R M , RHOADS, O G Region 1. Philadelphia, Office of the Director 80/06/30 17pp
- POO9100889 Forwards IE Insp Repts 50-387/80-15 % 50-388/80-10 on BOO623-27 No noncompliance noted CARLSON.R T Region 1, Philadelphia. Reactor Construction & Engineering Support Branch 80/07/21 2pp
- --8009100873 IE Insp Repts 80-387/80-15 & 50-388/80-10 on 600623-27 No noncompliance noted Major areas inspected licensee corrective action on previous insp results/GC.equipment starage & work in progress

  DURR.J P Region 1, Philadelphia, Office of the Director MCGAUGHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/16 Spp
- 8009120142 Responds to IE Bulletin 80-03 Insps will be performed & results reported when charcoal adsorber cells are returned from manufacturer CURTIS.N W Pennsylvania Power & Light Co 80/07/30 1p
- BOO9190956 Respands to IE Bulletin 80-02 No equipment supplied by Marvin Engineering Co CURTIGN W Pennsylvania Power & Light Co 80/07/30 Ip
- E009190247 Ack receipt of 800721 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-387/80-09 CARLEON R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/08/01 lp
- --9007170250 Responds to NRC 800607 itr re violations noted in IE Insp Rept 50-387/80-07 Corrective actions more detailed instructions provided to weld examiners SABDL.A R Pennsylvania Power & Light Co 80/07/21 2pp
- --8007170294 Forwards IE Insp Rept 50-387/80-09 on 800422 & 0508-09 & notice of violation CARLSON,R T Region 1, Philadelphia. Reactor Construction & Engineering Support Branch 80/06/09 2pp
- --8099190257 Notice of violation from insp on 800422 & 0508-09 \* Region I, Philadelphia, Office of the Director 80/06/02 ip
- --BO09190259 IE Insp Rept 50-387/80-09 on 800422 & 0508-09 Noncompliance noted failure to follow approved procedure during ultrasonic examination of piping welds TRIPP.LE Region 1. Philadelphia, Reactor Construction & Engineering Support Branch MCDREARTY, R A Region 1. Philadelphia, Office of the Director 80/06/02 Spp
- 80C9090516 Responds to IE Bullatin BO-OB, "Examination of Containment Liner Penetration Welds " Flued head design utilized for piping penetrations illustrated in Figure NE-1120-1 Electrical penetration design is illustrated in encl CURTIS.N W Pennsylvania Power & Light Co. BO/OB/O7 24pp
- 8009190264 Ack receipt of 800728 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-387/80-04 & 50-388/80-02 CARLS0N:R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/11 ip
- --8009190271 Responds to NRC 800529 ltr re violations noted in 1E insp Repts 50-387/80-04 & 50-388/80-02 Corrective actions all weld filler math certifications to be reviewed in accordance w/86AM BABDU.A R Pennsylvania Power & Light Co 80/07/28 3pp
- --8009190277 Forwards IE Insp Repts 50-387/80-04 & 50-388/80-02 on B00303-0312 & 0320-0418 & notice of violation CARLSGN.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/29 2pp

- --8009190282 Natice of violation from insp on 800303-0312 % 0320-0418 # Region i, Philadelphia. Office of the Director 80/05/28 1p
- ~~8009190288 IE Insp Repts 50-387/60-04 & 50-388/80-02 on 800303-0312 & 0320-0418 Noncompliance noted failure to document chemical analysis of weld filler mat:

  \* Region 1, Philadelphia. Reactor Construction & Engineering Support Branch 80/05/28 14pp
- 8009030086 Forwards Revision 1 to IE Bulletin 80-17, "Failures of Morcury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E "Written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/08/15 1p
- 8009090036 Responds to [E Bulletin 79-03A, "Longitudinal Neld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Pipe is not used in safety-related sys subjected to design stress greater than 854 CURTIS.N W Pennsylvania Power & Light Co 80/08/15 1p
- 8009120109 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BIR" No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/08/22
- 8009180037 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ORIER B H Region 1. Philadelphia. Office of the Director 80/08/22 1p
- 8009120204 Farwards IE Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-600S & K-DON 600S Circuit Breakers " No written response required GRIER B H Region 1. Philadelphia, Office of the Director 80/08/27 1p
- 8009240115 Forwards IE Circular 80~21. "Regulation of Refueling Crews " No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/09/10 1o
- 8009240328 Forwards IE Info Notice 80-32. "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " Us written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/09/12 ip
- S Reportable occurrences, LERs & related correspondence
- 8009090630 Ack receipt of 800703 interim rept re deficiency on Pacific chack valves CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/08/01 Ip
- ---8009090454 Interim rept re deficiency on Pacific check valves Problems w/valve operation in Unit I core spray pump discharge vertical pipe run necessitate bonnet stops rework Final rept expected by Sept 1980 CURTIS.N W Pennsylvania Power & Light Co 80/07/03 2pp
- 8009i1040i Ack receipt of 800721 final deficiency rept re improper sloping of GE piping & tubing CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/08/01 lp
- ---B007i104i4 Final deficiency rept re improper sloping of GE piping & tubing As-built drawings will be revised to include actual steps of installed pipe CURTIS.N W Pennsylvania Power & Light Co B0/07/21 4pp
- 8009120128 Ack receipt of 800722 interim rept re deficiency in pipe support design drawing released for fabrication & installation CARLSON,R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/08/01 ip
- 8009120711 Ack receipt of 800723 interim deficiency rept re improper safety classification for solenoid valve CARLBON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/01 ip
- 8007120704 Ack receipt of 800707 interim deficiency rept re cracks in Anchor-Darling valve yokes CARLSON,R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/04 ip

- 8009090472 Final deficiency rept re nonconforming ICO-Rally, Type SLV-1200 braided riberglass sizeving used as barrier natl for electrical separation Caused by Inadequacy of Bechtel recommendation authorizing field purchase CURTIS.N H Pennsylvania Power & Light Co 80/09/05 4pp
- DOCKET 50-388 SUSGUCHANNA STEAM ELECTRIC STATION, UNIT 2

  A Application/construction stage documents & correspondence
- 6009030985 Responds to 800417 request for info re NRC involvement in archeological data recovery activities for FY79 Completed questionnairs and DENIONH R Office of Nuclear Reactor Regulation, Director 80/06/11 70s
- 8007080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 entl N/o NUREG EISENMUT, D G Division of Licensing 80/08/01 119ap
- 8009150498 Summary of 800821 meetings w/Bechtel,util,0E & Savannah River Plant in Bethesda.MD re FSAR open heview items STARK.R M Licensing Branch i 60/08/26 App
- 8007080354 Documents agreements reached & actions to result from 800714-16 meeting w/NRC re draft 800421 8ER & open items in FSAR Sections 3 & through 3 10 CURTIS:N W Pennsylvania Power & Light Co 80/08/28 105pp
- 8009110742 Notification of 800904-05 meeting u/Mark II cumars group to discuss plants chugging C/O & lateral load specs ANDERSON.C Containment Systems Branch 80/08/29 14pp
- 8009120651 Notification of 800926 meeting w/util in Bethesda MD to discuss fuel load date STARK,R M Licensing Branch 1 80/09/04 1p
- --B009120660 Responds to MRC B00711 ltr re request for estimate of fuel load dates Primary sys fill & flush of Unit 1 completed & hydro & reactor internal vibration test near completion U/65% of plant sys in startup.completion by B10601 is likely CURTIS.N W Pennsylvania Power & Light Co 80/08/19 4pp
- 8009100484 Forwards request for add1 info be accident evaluation, needed for review of OL applications RM Stark principal contact TEDESCO.R ( Assistant Director for Licensing 80/09/05 4pp
- 8007180464 Summary of 800821 meeting w/util in Bethesda: MD re forecasted fuel load date STARK R M Litensing Branch 1 80/09/05 3pp
- 8009150470 Forwards complete response to SA Varga 800421 request for info on Category I masonry walls employed by plants under CP & OL revieu

  CURTIS-N W Fennsylvania Power & Light Co 80/09/08 Bpp
- 8009160310 Forwards document used to establish recommended instrument nominal trip setpoints? Forh Specs limits per 800821 request CURTIS.N W Pennsylvania Power & Light Co 80/09/10 19pp
- 8009170290 Forwards ASME Boiler & Pressure Vessel Code, Section 3 overpressure rapt per FSAR Question 211 204 CURTIS.N W Pennsylvania Power & Light Co 80/09/12 25pp
- F Security, medical, emergency & fire protection plans
- 8009300669 Notification of 801027 meeting w/util in Berwick,PA to View status & configuration of electrical sys w/respect to electrical separation & fire protection
  STARK,R B Licensing Branch | 80/09/10 | App
- G Adjudicatory correspondence
- 8009120275 Requests time to make limited appearance statement at licensing hearings Requests to be informed when & where hearings will be held GARRYCH, N.A. Affiliation Unknown 80/09/02 1p
- 8009110787 Advises that NRC will not respond to applicants' 800822 motion for partial summary disposition of Contention 17 recorded issue Commission regulations allow only opposing replies CUTCHIN, J.K. Hearing Branch 3 80/09/08 [p

- B009110016 Response in opposition to Environ Coalition on Nuclear Power B00922 request for free prehearing conferences transcripts prior to B00725 Does not oppose grant of transcripts of future sessions Certificate of Svc encl CUTCHIN.J M. Hearing Branch 3. 80/09/09. Spp
- 8009180394 Motion in opposition to applicant request for summary disposition of Contention 17 re ozone Issue is of public interest & requires hearing Motion grant would prevent full litigation of Contention 17 W/Certificate of Svc HALLIGAN: T J Citizens Against Nuclear Dangers 80/09/10 2pp
- BCO9160414 Requests to make limited appearance statement at licensing hearing for facility GURGONE. A Affiliation Unknown 80/09/12 ip
- BO09290043 Decision, ALAB-613, denying Environ Coalition on Nuclear Power B00315 petition referred to ASLAB on B00916, re alleged ABLAB refusal to stop applicants discovery harassments Supporting documentation encl
  BISHOP, C.J. Atomic Safety and Licensing Appeal Panel 80/09/23
- Q Inspectson reports, IE Bulletins & correspondence
- 8009090094 Forwards IE Bulletin 80-07, Suppl 1, "BUR Jet Pump Assembly Failure" No response required GRIER.B H. Region 1, Philadelphia, Office of the Director 80/09/13 1p
- 8009250299 Forwards IE Insp Repts 50-387/80-13 % 50-388/80-09 on 800602-05 No nancompliance noted CARLSDIR T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/07/11 2pp
- --8009250302 IE Insp Repts 50-387/80-13 & 50-388/80-09 on 800602-05 No noncompliance noted Major areas inspected installation of water supply & distribution sys, water & gaseous suppression sys, specs & drawings & GA program
  EBMETER. B D Region 1, Philadelphia, Reactor Construction & Engineering Support Branch KOLTAY, P B Region 1, Philadelphia, Office of the Director 80/07/08 7pp
- 8007170231 Forwards IE Insp Repts 90-387/80-10 & 50-388/80-06 on 800421-0516 & 27-30 No noncompliance noted CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/15 2pp
- --R009190241 IE Insp Repts 50-387/80-10 % 50-388/80-06 on 800421-0516 & 27-30 No noncompliance noted Major areas inspected installation & welding of RCPB & other piping & installation of safety-related components MCGAUGHY.R W Region 1. Philadelphia. Reactor Construction & Engineering Support Branch CALLO,R M., RHOADS.O G Region 1. Philadelphia. Office of the Director 80/06/30 17pp
- 8009100889 Forwards IE Insp Repts 50-387/80-15 & 50-388/80-10 on BOO&23-27 No noncompliance noted CARLSON-R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/21 2pp
- --8009100893 IE Insp Repts So-387/80-15 & 50-388/80-10 on 800623-27 No noncompilance noted Mayor areas inspected licensee corrective action on previous insp results.OC. equipment storage & work in progress DURR.JP Region I. Philadelphia. Office of the Director MCGAUGHY:RW Region I. Philadelphia. Reactor Construction & Engineering Support Branch 80/07/16 Spp
- 8009120142 Responds to IE Bulletin 80.03 Insps will be performed & results reported when charcoal adsorber cells are returned from manufacturer CURTIS.N W Pennsylvania Power & Light Co 80/07/30 ip
- 8009190956 Responds to IE Bulletin 80-02 No equipment supplied by Marvin Engangering Co CURTIS:N W Pennsylvania Power & Light Co 80/07/30 Ip
- B009090616 Responds to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds "Flued head design utilized for piping genetrations illustrated in Figure NE-1120-1 Electrical penetration design is illustrated in encl CURTIS.N H Pennsylvania Power & Light Co 80/08/07 24pp
- 8009190264 Ack receipt of 800728 ltr informing NRC of steps taken to correct violations noted in IE lnep Repts 50-387/80-04 & SO-388/80-02 CARLSON,R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/08/11 1p

- --8009190271 Responds to NRC 800529 ltr re violations noted in IE Insp Repts 50-387/80-04 & 50-388/80-02 Corrective actions all weld filler matl certifications to be reviewed in accordance w/80AM SABOL.A R Pennsylvania Power & Light Co 80/07/28 3pp
- --8009190277 Forwards IE Insp Repts 50-387/80-04 & 50-388/80-02 on 800303-0312 & 0320-0418 & notice of violation CARLEON.R T Region J. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/29 2pp
- --8009190282 Notice of violation from insp on 800303-0312 & 0320-0418
   Region 1, Philadelphia, Office of the Director 80/05/28 1p
- --800919028B IE Insp Repts 50-387/80-04 & 50-388/80-02 on B00303-0312 & 0320-0418 Noncompliance noted failure to document chemical analysis of weld filler matl + Region 1. Philadelphia. Reactor Construction & Engineering Support Branch B0/05/28 14pp
- 8009030086 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Hercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER.E H. Region I, Philadelphia. Office of the Director 80/08/15 ip
- 8009070035 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ABKE BA-312. Type 304 Stainless Steel Pipe " Pipe is not used in safety-related sys subjected to design stress greater than 85% CURTIS-N W Pennsylvania Power & Light Co 80/08/15 1p
- 8009120109 Forwards Suppl 3 to 1E Bulletin BO-17. "Failure of Control Rods to Insert During Scram at BWR " No written response required. GRIER, B H Region 1, Philadelphia, Office of the Director 80/09/22 1p
- 8009180037 Forwards IE Circular 80-19. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required PRIER, B H Region 1. Philadelphia. Office of the Director 80/08/22. 1p
- 6007120204 Forwards IE Info Notice 80-31. "Maloperation of Qould-Brown Boveri 480 Volt Type K-6008 & K-DQN 4008 Circuit Breakers "
  No written response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/08/27.
- 8009240115 Forwards IE Circular 80-21, "Regulation of Refueling Craws " No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/09/10
- S Reportable occurrences, LERs & related correspondence
- 6009090450 Ack receipt of 800703 interim rept re deficiency on Pacific check valves CARLESUIR.T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/01 ip
- --8009090454 Interim rept re deficiency on Pacific check valves Problems
  w/valve operation in Unit 1 core spray pump discharge
  vertical pipe run necessitate bonnet stops rework Final rept
  expected by Sept 1980
  CURFIS.N W Pennsylvania Power & Light Co 80/07/03 2pp
- 009110401 Ack receipt of 800721 final deficiency rept re laproper stoping of GE piping & tubing CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/01 1p
- -BOO9:10414 Final deficiency rept re improper sloping of GE piping & tubing As-built drawings will be revised to include actual slope of installed pipe CURTIS,N W Pennsylvania Power & Light Co 80/07/21 4pp
- 009120128 Ack receipt of 800722 interim rept re deficiency in pipe support design drawing released for fabrication & installation CARLSON.R T. Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/01 ip

- 8009120711 Ack receipt of 800723 interim deficiency rept re improper safety classification for solenoid valve CARLSON. A T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/01 1p
- 8007120704 Ack receipt of 800707 interim deficiency rept re cracks in Anchor-Darling valve yokes CARLSON,R T Region I. Philadelphia, Reactor Construction & Engineering Support Branch 80/08/04 10
- 8009090472 Final deficiency rept re nonconforming ICO-Raily, Type SLV-1200 braided fiberglass sleeving used as barrier matl for electrical separation Gaused by inadequacy of Bechtel recommendation authorizing field purchase CURTIS.N W Pennsylvania Power & Light Co 80/09/05 4pp
- DUCKET 50-389 ST LUCIE PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREG-0494, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUPEG-0496 encl 4/0 NUREG EISENHUT, D G Division of Licensing 80/08/01 119pp
- B009090842 Requires submittal of ATMS emergency operating procedure for NRC review by B01019 Generic analysis should confirm ATMS mitigation capability described in NUREO-0460, Vol 3 Commission will determine required mode & schedules TEDESCO.R L Assistant Director for Licensing B0/08/25 3pp
- 8009090851 Requests that info on chemical formulation & quantity of NUKEM 750 to be used as expansive joint filler inside containment be provided by 800910
  TEDESCO.R L Assistant Director for Licensing 80/08/25 2pp
- 8009030633 Submits info requested in NRC 800711 ltr re up-to-date const completion schedules Facility will be ready for fuel loading in Nov 1982 Three oversize photographs & supporting documentation encl UHRIG.R E Florida Power & Light Co 80/08/26 15pp
- 8007300043 Notification of time change for 800718 meeting w/util in Bethesda MD to discuss schedule & staff review of application Meeting will be held at 11 00 AM BIRKEL R A Licensing Branch 1 80/07/09 3pp
- B009300667 Notification of B00918 meeting w/util in Bethesda.MD to discuss schedule & NRC review of application BIRKEL,R A Licensing Branch 1 B0/09/09 3pp
- 8009150262 Responds to NRC 800825 ltr re use of NUKEM 750 as expansion joint filler inside containment includes chemical formulation of NUKEM 750 & quantity used inside containment UHRIG.R E Florida Power & Light Co 80/09/10 tp
- 8009300105 Forwards Amend 1 to CPPR-144, incorporating conditions to alleviate loss of ac power in event of station blactout Notice of issuance & availability of decision encl YOUN08L00p.B J Licensing Branch 1 80/09/18 2pp
- --8009300108 Amend 1 to CPPR-144, incorporating conditions to alloviate loss of ac power in event of station blackout YGUNOBLDOD, B J Licensing Branch 1 80/09/18 1p
- F Security, medical, emergency & fire protection plans
- 8009230261 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network, Sys installed for got use during emergency O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/22
- G Adjudicatory correspondence
- 8009040355 Order granting extension until 800915 for Commission to review ALAB-603 CHILK-S J Office of the Secretary of the Commission 80/09/29
- BOO9190279 Responds to FOIA request for 15 documents listed in bibliography fo NUREG-0625, "Rept of Siting Policy Task Force" Documents 6-8 t 13 are available in PDR Forwards remaining documents FELTON, J K Division of Rules and Records 80/09/04 ip

- --8009190537 Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants, for determination or site acceptability & adequaty of engineered safery features HIMOSUE R B Office of Standards Development, Director SEC:-77-342 79/06/04 7pp
- --8009190633 Requests that encl "Differences in Procedures for Estimating Atmospheric Dispersion Conditions at Inland & Coastal Sites," be sent to appropriate Boards SCINTO.J F Hearings Division 79704704 16pp
- BCO9(B0546 Order extending time until B00929 in which Commission may act to review ALAB-603 CHILK-S J Orrice of the Secretary of the Commission B0/09/15 4p
- 8009260459 Memorahdum to counsels disclosing past involvement as AEC Deputy Director of Fechnical Review Previous involvement w/ St Lucie Units 1 & 2 has not prejudiced objectivity Objections will be considered if filed by 801002 HERWRIE. J M Commission 80/09/19 2pp
- 8009260009 Forwards Amend I to CPPR-144 & notice of issuance & availability.in reaponse to ALAB-603
  PATON.W D Hearing Branch 4 E0/09/23 1p
- --8007260012 Amend 1 to CPPR-144 incorporating Paragraph 3 H, re consideration of total loss of ac power as DBE YOUR.SECOOD B J Licensing Branch 1 60/09/18 1p
- --B009260013 Notice of issuance & availability of Amend I to CPPR-144 YOUNGSECOOD B J Licensing Stanch I 80/09/18 Zpp
- 8009260463 Order granting extension until 801006 for Commission to elect whether to review ALAB-603 CHILK.S J. Office of the Secretary of the Commission 80/09/24

# M Antitrust correspondence

- B009020131 Advises that Cormission has received addl antitrust advice from Atty General re CP application No antitrust hearing necessary for proposed amend to CP SALTZMAN J Utility Finance Branch 80/08/05 2pp
- 8009110013 Ack rereipt of FL Cities 800822 ltr re draft settlement reached by utilipoj & NRC Final settlement addresses intervenor concerns SHAPAR.H K Diffice of the Executive Legal Director 80/09/08 ip
- 8007220221 Forwards Fit Cities comments be advice ltr concerning util Orlando settlement JABLDWR A Spiegel & McDiarrid 80/07/10 1p
- --B007220222 Comments concerning util Orlando settlement FL Cities prepared to show by argument i evidence that grant of unconditioned license to util would create or maintain situation inconsistent w/antitrus\* laws

  JASLON.R A , ROTH.A J Florida Cities JABLON.R A Spiegel & McDiarrid B0/09/10 3pp
- --8009220223 Comments concerning notice of withdraual of intervention by Oriando utils As procedural matter, motion would be necessary for Orlando to withdraw Certificate of Svc encl JABLON.R A Florida Cities JABLON.R A Spingel & McDiarmid 80/07/07 5pp
- 8009160033 Joint motion for approval & authorization to implement encl stipulation re license conditions Urgas immediate effect w/o prejudice to different or addl conditions that day be imposed after hearing FL Cities must specify objections URBAN.JR Justice.Dept of DEHEY, L. S. Antitrust Division DYM. H Florida Power L. Light Co. 80/09/12 Jpp
- --BCG7160041 Stipulation reflecting util consent to incorporate encl license conditions w/o prejudice to addi or different conditions that may be imposed after hearing Stipulation does not constitute admission of guilt M/Certificate of Svc URBAN.J R Justice.Dept of DEMEY.L S Antitrust Division DYM,H Florida Power & Light Co 80/07/12 35pp
- BOO9:70162 Motion supported by DOJ & NRC. for suspension of responses to interrogatories DOJ.NRC & util settlement may affect procedures Certificate of Svc encl JABLON:R A . DYM, Florida Cities JABLON:R A Spiegel & McDiarmid BO/09/15 2pp

- 8009190091 Motion before US Court of Appeals for DC Circuit, for especiated consideration of petition for review reconsolidation of Civil Action 80-1099 W/administrative proceeding W/Certificate of Svc Related correspondence JABLON, R A , LANDEMAN, R M Florida Cities JARLON, R A Spiegel & McDiarmid 80/09/15 5pp
- 8009260653 Order granting FL Cities & Dthl 800915 joint motion to suspend interrogatory responses Request unopposed by remaining parties
  SMITH. [ W Abomic Safety and Licensing Board Panel 80/09/22 1p
- B009300476 Response before US Court of Appeals for DC Circuit, in apposition to petitioners' motion for expedited cansideration of Civil Action 80-1099 Certificate of Svc encl Related correspondence DYM.# Florida Power & Light Co BDUKNIOHT, J A Lowenstein, Newman, Reis, Akelrad & Toll 80/09/25 5pp

#### P Operating license stage documents & correspondence

- 8009040490 Responds to NRC 800728 ltr requesting opinion & advice repotential void formation in vessel head Phenomena is unaffected by relatively small differences in fuel design Company would not analyze event unless asked by customer OHSLEY.0 F Exxon Nuclear Co , Inc (subs of Exxon Corp ) 80/08/26 ip
- Q Inspection reports, IE Bulletins & correspondence
- 8009100130 Forwards IE Insp Rept 50-389/80-08 on 800604-06 & notice of violation MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/06/23 2pp
- --8007100146 Notice of violation from insp on 800604-06 • Region 2, Atlanta, Office of the Director 80/06/20 1p
- ---B097100149 IE Insp Rept 50-3B9/80-0B on 800604-06. Noncompliance noted inadequate procedural controls on sand-cement fill CONLON.T E Region 2. Atlanta, Reactor Construction & Engineering Support Branch HARRIS, J R Region 2. Atlanta, Office of the Director 80/06/20 4pp
- 8009240066 Forwards IE Insp Repts 50-339/80-23 & 50-389/80-09 on 800715-18 No noncompliance noted MXRPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/05 2pp
- --8009240071 IE Insp Repts 80-335/80-23 & 50-389/80-09 on 800715-10 No noncompliance noted Major areas inspected records associated w/work performance during outage in areas of installation welding, weld rod control & core drilling VANDOORN.P & Region 2. Atlanta, Office of the Director HERDT.A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/04 App
- 8009030158 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Hetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/1
- 8009160143 Forwards IE Circular 80-18, "IOCFR50 59 Safety Evaluations for Changes to Radwasto Treatment Sys " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/22
- 8009240174 Responds to IE Bulletin 80-16, "Potential Misapplication of Rosemount, Inc Models 1151 & 1152 Pressure Transmitters w/ Either A or D Output Codes " Transmitters are not installed in any safety-related applications
  UHRIG.R E Florida Power & Light Co 80/08/26 ip
- BOOP12030B Forwards IE Info Natice BO-31, "Maloperation of Qould-Brown Boveri 480 Volt Type K-600S & K-DON 600S Circuit Breakers " No written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/08/27
- 8009110693 Responds to IE Bulletin 80-19 Mercury-webted relays not used in logic matrix of reactor protective sys UHRIGIR E Florida Power & Light Co 80/08/29 ip
- 8009290277 Forwards IE Circular 80-21. "Regulation of Refueling Creus" No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/09/10 5pp

- BOO9300040 Submits response to IE Bulletin 80-30 re Westinghouse W-2 control switches investigation is still in progress & complete response is expected by 801014

  URRIG.R E Florida Power & Light Co 80/09/15 ip
- S Reportable occurrences. LERs & related correspondence
- 8009100585 Final deficienty rept re cracked & broken electrical penetration connections Caused by poor assembly techniques Supplier will develop repair procedures & repair & replace fractured ring tongue connectors

  UHRIG.R E Florida Power & Light Co 80/08/06 4pp
- BOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1

  A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Pacilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/O NUREO EISENHUT, D © Division of Licensing 80/08/01 119pp
- 8009040437 Forwards matl re NRC review of ice condenser containment & hydrogen control measures for Sequoyah Nuclear Power Plant ACRS has scheduled meetings in Washington, DC on 800828, 0902 & 04 to discuss issue
  TEDESCO,R L Assistant Director for Licensing 80/08/22 2pp
- 8009300400 Forwards technical questions re implementation of interim policy on 100FR50 & 51
  MILLS.L d Tennessee Valley Authority 80/09/23 3pp
- F Becurity, medical, emergency & fire protection plans
- B009120488 Forwards "Watts Bar Nuclear Plant Units 1 & 2 Fire Protection Submittal," in response to NRC 790108 request for add1 info MILLS.L M Tennessee Valley Authority 80/09/09 400pp
- J Financial information
- E009090543 Forwards Annual Financial Rept 1979 CROSS.J L Tennessee Valley Authority 80/09/04 1p
- --8009090563 Annual Financial Rept 1979 \* Tennessee Valley Authority 80/09/04 44pp
- M. Utility Final Safety Analysis Report (FSAR) & amends
- 8009020094 Forwards Amend 41 addendum to FSAR Encl matl imadvertently onitted from 800430 submittal MILLS,L M Temnesses Valley Authority 80/08/26 ip
- --- 2009020097 Addendum to Amend 41 to FSAR # Tannessee Valley Authority 80/08/26 100pp
- BOO9D30574 Forwards affidavit cartifying that Amend 41 addendum to FSAR was mailed to BA Osborne,D Wair & JC Hagan on B00826 MILLS,L M Tennessee Valley Authority, 80/08/26 2pp
- a inspection reports, IE Bulletins & correspondence
- 8009030032 Forwards IE Insp Repts 50-370/80-18 & 50-371/80-11 on 800625-27 No noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/17 2pp
- --BOO9030040 IE Insp Repts 50-390/80-18 & 50-391/80-11 on 800625-27 No noncompliance noted Major areas inspected const activities, deficiency repts, handling & storage of piping & GA audits CANTRELL, F S Region 2, Atlanta, Reactor Construction & Engineering Support Branch THOMAS, M Region 2, Atlanta, Office of the Director 80/07/16 4pp
- 8009100063 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/07/24 ip
- 8004030257 Ack receipt of 800723 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-390/80-08 LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/08/04 ip

- --8009030260 Responds to NRC 800626 lfr re violation noted in IE Insp. Rept 50-370/80-08 Corrective actions craft supervision re-emphasized 5 add1 craftsmen assigned to check work areas daily MILLS.L M. Tonnessee Valley Authority 80/07/23 2pp
- ---8009030264 Ack receipt of 8006(0 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-390/80-08 Requests add1 info re piping sys cleanliness LEWIS: R C Region 2: Atlanta: Reactor Operations Nuclear Support Branch 80/06/26 lp
- --8009030270 Forwards IE Insp Rept 50-390/80-08 on 800324-26 & notice of violation LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/05/02 2pp
- --8009030274 Notice of violation from insp on 800324-25 # Region 2, Atlanta, Office of the Director 80/05/02 2pp
- --8007030281 IE Insp Rept 50-390/80-08 on 800324-26 Noncompliance noted failure to maintain adequate lubrication procedure to ensure valve lubrication procedure in initial valve operation ASHENDER, M.C. Region 2. Atlanta, Office of the Director DANCE, H.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/05/02 App
- 8009020214 Forwards response to IC Bulletin 79-03A No SA-312 & A-312, Typo 300 series fusion welded pipe used or planned for use in safety-related sys at greater than 85% design stress except Watts Bar Matl under investigation at Watts Bar MILLS, L M Tennessee Valley Authority 80/08/05 2pp
- 8009090802 Responds to IF Sulletin 79-03A. "Longitudinal Weld Defects in ASME 8A-312. Type 304 Stainless Steel Pipe "Use of matls still under investigation for sys supplied by NSSS vendor MILLS.L II Tennessee Valley Authority 80/08/05 2pp
- 8009020303 Forwards IE Insp Repts 50-327/80-24.50-328/80-15, 50-390/80-20, 50-391/80-14, 50-438/80-13, 50-439/80-13, 50-518/80-11, 50-518/80-11, 50-518/80-11, 50-526/80-11, 50-523/80-11, 80-554/80-10, 50-566/80-10, 50-567/80-10, 60-667/80-1
- ~-8007020312 Notice of violation from insp on 800707-11 \* Region 2: Atlanta, Office of the Director 80/08/06 4pp
- --8007020337 IC Insp Repts 30-327/80-24,50-328/80-15,50-390/80-20, 50-391/80-14,50-438/80-13,50-439/80-13,50-518/80-11, 50-519/80-11,50-521/80-11,50-553/80-11, 50-554/80-10,50-564/80-10 & 50-567/80-10 an 800707-11 SROUNLEE, V L, MODENOSL Region 2, Atlanta, Diffice of the Director CUNLON,T C Region 2, Atlanta, Reactor Construction & Engineering Support Blanch 80/08/06 24pp
- 8009030146 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Morsury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required D'REJLLY, J.P. Region 2. Atlanta, Diffice of the Director 80/08/15 is
- 8009140153 Forwards IE Circular 80-18, "LOCFR50 59 Safety Evaluations for Changes to Radwaste Troatment Sys 'No written response required O'REILLY, J.P. Region 2, Atlanta, Office or the Director 60/08/22 in
- 8009120340 Forwards IC Info Notice 80-31, "Malaperation of Gould-Brown Bovers 480 Voit Type K-6005 & K-DON 6008 Circuit Breakers" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/27
- 8009180087 Forwards response to IE Bulletin 80-16 Research Models 1151 & 1152 pressure transmitters are not used or planned for use except at Bellefonte Nuclear Plant where use will be evaluated MILLSIL M. Tennessee Valley Authority 80/08/29 2pp
- 8009240454 Forwards response to 1E Bulletin 80-16 re potential misapplication of Resembnit pressure transmitters No corrective action required due to results of evaluation that indicated impossibility of anomalous output MILLS-L M Tennessee Valley Authority 80/08/29 2pp
- 8009120679 Responds to 1F Bulletin 80-19 re failures of mercury-wetted matrix relays in leactol protective sys Relays identified are not used in facility Forty manhours expended for review MILLS.L M Tennessee Valley Authority 80/09/04 ip

- 8009260375 Forwards IE Circular 80-21, "Regulation of Refueling Creus " No written response required O'REILLY, J.P. Region 2 Atlanta, Office of the Director 80/09/10
- 8009160418 Forwards response to items of noncompliance cited in IE Insp. Repts 50-390/80-21 & 50-391/80-15 Corrective actions incomplete work items have been completed or placed on list Six high point vents have been routed to closed drain sys. MILLS.L.M. Tennessee Valley Authority 80/09/11 8pp
- 8009160423 Forwards response to deficiencies noted in IE Insp Repts 50-390/80-19 2 50-391/80-13 Corrective actions GC procedure to be revised to include requirement to inspect one inch on either side or weld MILLS: (1 Tennessee Valley Authority 80/09/11 Spp
- S Reportable occurrences, LERs & related correspondence
- 8009040486 Second interim deficiency rept re defective reactor vessel upper internals guide tube support pins TVA & Hestinghouse replacing pins Next rept will be submitted by 800911 MILLS.L.M. Tennessee Valley Authority 80/07/24 [p
- 8009100537 Final deficiency rept re control rod drop events Operating procedures to be revised per Westinghouse instructions Procedural change will be made prior to greater than 90% power level accession & will prevent power overshoot MILLS.L M Tennessee Valley Authority 80/08/05 2pp
- 8009040436 Notifies of inability to correct deficiency re qualification of cold foaming procedures in accordance w/800603 deadline Anticipated completion scheduled for 800908 diffLS,L it Tennessee Valley Authority 80/08/07 ip
- 8008150212 Third interim deficiency rept to faulty fillet welds & GC breakdown Reinsp of fillet welds begun Addl affected areas include cable tray supports; conduit supports & steel Addl info will be provided by 801031 MILLS.L K Tennessee Valley Authority 80/08/08 ip
- 8009040401 Third interim deficiency rept re excessive output fluctuations of Foxboro instrumentation TVA & Westinghouse have not yet arrived at permanent solution Addl into to be submitted by 810209 MILLS.L M Tennassee Valley Authority 80/08/08 1p
- 8008130476 Submits third interim deficiency rept re UHI hydraulic isolation valve accumulator weighing sys Add1 info to be transmitted by 800919 MILLS,L B Tennessee Valley Authority 80/08/08 1p
- 8009040430 Bubmits third interim deficiency rept re UHI hydraulic isolation valve accumulator weighing sys Addl info to be transmitted by 800919
  MILLS.L H Tennessee Valley Authority 80/08/08 ip
- 8008170458 Fourth interim deficiency rept re Penn Ventilator QA program Util still evaluating drawings & documents supplied by Penn Ventilator Will submit next rept by 80110 MILLS.L M Tennessee Valley Authority 80/08/13 ip
- 8009100576 Final deficiency rept re hydrogen detection sys integrity Pump diaphragm rupture could result in sys integrity breach, affecting plant safety Sample pump field mod kit being provided by Consip. Inc Installation anticipated by 801205 MILLS.L M Tennessee Valley Authority 80/08/13 2pp
- 8009020046 Fourth interim deficiency rept re steam generator water level raf column error Util working w/Wastinghouse to evaluate interfacing problems in installing instrumentation for temp compensation of level transmitter output signal MILLS.L M Tennessee Valley Authority 80/08/22 ip
- BOO9020056 Final deficiency rept re seismic supports for auxiliary feedwater control vaives Support struts cannot be installed due to interference wiother equipment Interferences will be removed or new strut will be field fabricated MILLS,L M Tennessee Valley Authority BO/08/22 2pp
- 8009100293 Final deficiency rept re documentation tag & conduit support tag removal Support Tag CS-AB-15, 589 & conduit support Tag CB-AB-15, 190 located & attached to proper support. & removal documented Craft employees will be retrained MILLS.(L M Tennessee Valley Authority 80/09/03 2pp
- 8009:100443 Second interim deficiency rept re insufficient analysis of 3-inch fire protection lines Analysis has been deleted Next rept will be a feet.

- BOO9100283 Final deficiency rept re cutting of conduit supports w/o cutting release Cutting of conduit supports documented as required by Procedure WBNP-GCP-1 7 Craft personnel will be retrained in documentation procedures
  MILLS.L.M Tennessee Valley Authority BO/09/04 2pp
- 8009150537 Final deficiency rept re pressurizing fans w/o automatic blads pitch control Util purchased inlet vane dampers which will control air flow into control bldg similar to manner provided by automatic pitch control blades MILLS.L M Tennessee Valley Authority 80/09/05 2pp
- 8009160319 Fifth interim deficiency rept re surface cracks in loop one steam generator Surface indications removed by grinding to max depth of 0 190 inches Necessity of nondestructive exams not decided Addl info will be submitted by 801028

  MILLS.L II Tennessee Valley Authority 80/09/09 ip
- 8009160326 Third interim deficiency rept re defective reactor vessel upper internals guide tube support pins Mestinghouse evaluation of guide tube pins being reviewed Replacement of pins underway Next rept will be submitted by 801215 MILLS.L K Tennessee Vailey Authority 80/09/10 ip
- 8009230468 First interim deficiency rept re damage to upper head injection giping hanger which is located on underside of reactor cavity shield plug Caused by plug being lifted for gastot fitup w/o hangers being disconnected Insp underway MILLS.L M Tennessee Valley Authority 80/09/12 2pp
- 8009230611 First interim deficiency rept re discrepancy in two MK-71 embedded plates Existing dimension for MK-71 plate at 156 degrees discovered w/less than required anchor bolts Plates fabricated w/only one stud Addl info by 801121 MILLS.L M Tennessee Valley Authority 80/09/16 2pp
- 8009250273 Final deficiency rept re emergency gas treatment sys open head spray nozzles Open head spray nozzles will be replaced by closed head water spray nozzles to provent water from spraying charcoal bees in event of inadvertent initiation MILLS.L M Tennessee Valley Authority 80/09/17 2pp
- 8007230540 First interim deficiency rept re deterioration of unused Kerotest Y-type globe valves discovered during disassembly & insp Maeting scheduled w/Kerotest to discuss short & longterm currective actions MILLS.L. M Tennessee Valley Authority 80/09/18 3pp
- 8009230510 Final deficiency rept re incorrect analysis of siping \$45 over operating temp range Cause not stated Piping sys reanalyzed w/no major changes required MILLS-L M Tennessee Valley Authority 80/09/18 2pp
- 8009290324 Third interim deficiency rept re radiation dose inside containment exceeding cable qualification Computer codes suitable for analyses of beta radiation dose to cables inside containment obtained Completion will require months. HILLS: L M Tennessee Valley Authority 80/09/19 ip
- 8009290327 Fourth interim deficiency rept re upper head injection isolation valve accumulator weighing sys Proposed Westinghouse design changes will be delayed until further testing completed Addl info will be provided by 801005 MILLS.L M Tennessee Valley Authority 80/09/19 ip
- B009290344 Final deficiency rept re 6.700 volt shutdown board breaker lockout Seal-in contact of IX relay will be removed from control circuits prior to fuel loading MILLS.L M Tennessee Valley Authority 80/09/19 2pp
- DOCKET 50-391 WATTS DAR NUCLEAR PLANT, UNIT R

  A Application/construction stage documents & correspondence
- 8009160547 Forwards Westinghouse 800222 & 0604 ltrs stating vendor will provide for in-transit physical protection for nuclear fuel MILLS:L M Tennessee Valley Authority 80/06/13 3pp
- 8009090080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl Wo NUREG EISENMUT.D C Division of Licensing 80/08/01 119pp
- 8009040467 Forwards matl re NRC review of ice condenser containment & hydrogen control measures for Sequoyah Nuclear Power Plant ACRS has scheduled meetings in Washington, DC on 800828, 0902 & 04 to discuss issue TEDESCO, R L. Assistant Director for Licensing 80/08/22 2pp

- 8009300400 Forwards technical questions re implementation of interim policy on 100FR50 t 51 MILLS.L # Tennessee Valley Authority 80/09/23 3pp
- F Security, medical, emergency & fire protection plans
- 8005150206 Forwards addl comments re transportation portion of fuel storage physical security plan dtd 800516 Requests that response be consolidated w/responses to NRC 800716 ltm & be submitted within 30 days of receipt of ltm MCCORKLE, 0 W Physical Security Licensing Branch 80/08/11 ip
- 8009030548 Forwards amend to fuel storage physical security plan Plan withheld (ref 10CFR2 790) MILLS.L K Tennessee Valley Authority 80/08/27 1p
- 8009120488 Forwards "Hatts Bar Nuclear Plant Units 1 & 2 Fire Protection Submittal." in response to NRC 790108 request for add1 info MILLS,L M Tennessee Vailey Authority 80/09/09 400pp
- I Financial information
- B009090543 Forwards Annual Financial Rept 1979
  CROSS, J L. Tennessee Valley Authority 80/09/04 1p
- --80090909053 Annual Financial Rept 1979
  \* Tennessee Valley Authority 80/09/04 44pp
- 🔾 Utility Final Safety Analysis Report (FSAR) & amends
- 8009020094 Forwards Amend 41 addendum to FSAR Encl matl inadvertently amitted from 800430 submittal MILLS.L M Tennessee Valley Authority 80/08/26 ip
- ---8009020097 Addendum to Amond 41 to FSAR
  Tennessee Valley Authority 80/08/26 100pp
- 8009030574 Forwards affidavit certifying that Amend 41 addendum to FBAR was mailed to DA Osborne, D Wade & JE Hagan on 800826.
  KILLS.L M Tennessee Valley Authority 80/08/26 2pp
- Q Inspection reports. IE Bulletins & correspondence
- B009030032 Forwards IE Insp Repts 50-390/80-18 & 50-391/80-11 on B00629-27 No noncompliance noted HURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch B0/07/17 2pp
- --B009030040 IE Insp Repts 50-390/80-18 & 50-391/80-11 on 800625-27 No noncompliance noted Major areas inspected const activities. deficiency repts, handling & storage of piping & QA audits CANTRELL.F S Region 2. Atlanta. Reactor Construction & Engineering Support Branch THOMAS, M Region 2. Atlanta. Office of the Director 80/07/16 4ρρ
- 8009100063 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Bide High Energy Line Rupture "No written response required O'REILLY.U P Region 2. Atlanta. Office of the Director 80/07/24
- 8009020214 Forwards response to IE Bulletin 79-03A No 8A-312 & A-312, Type 300 series fusion welded pipe used or planned for use in safety-related sys at greater than 85% design stress except Natts 8ar Mabl under investigation at Natts Bar MILLS.L K Tennessee Valley Authority 80/08/05 2pp
- BO09090802 Responds to IE Bulletin 79-03A: "Longitudinal Weld Defects in ABHE BA-312. Type 304 Stainless Steel Pipe" Use of matls still under investigation for sys supplied by NBSB vendor HILLS.L M Tennessee Valley Authority B0/08/05 2pp
- BO09020303 Forwards IE Inup Repts 50-327/80-24, 50-328/80-15, 50-390/80-20, 50-391/80-14, 50-438/80-13, 50-439/80-11, 50-518/80-11, 50-518/80-11, 50-520/80-11, 50-520/80-11, 50-536/80-11, 50-536/80-10, 50-367/80-10

  O'REILLY, J P Region 2, Atlanta, Office of the Director BO/08/06 208

- --8009020337 IE Insp Repts 50-327/80-24,50-328/80-15.50-390/80-20,50-391/80-14.50-438/80-13.50-439/80-13.50-518/80-11,50-50-519/80-11.50-520/80-11.50-520/80-11.50-553/80-11,50-554/80-10.50-566/80-10 & 50-567/80-10 on 800707-11 BROWNLEE, V L Region 2, Ablanta, Office of the Director 80/08/06 24pp
- 8007030146 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Merculy-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Flower Plants Designed by C-E 'Written response required 0'REILLY, J P. Region 2, Atlanta. Office of the Director 80/08/15
- 8009160153 Forwards IE Circular 80-18, "10CFRSD 59 Safety Evaluations for Changes to Raduaste Treatment Sys " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/22
- 8009120340 Forwards IF Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Voit Type K-6005 & K-DON 6005 Circuit Breakers " No written response required O'REELLY, J P Region 2, Atlanta Office of the Director 80/08/27
- 8009120679 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Relays identified are not used in facility Forty menhours expended for review MILLS, L M Tennessee Valley Authority 80/09/04 ip
- 8007260375 Forwards IE Circular 80-21, "Regulation of Refueling Crews"
  No written response required
  D'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/10
  Soo
- 8009160418 Forwards response to items of noncompliance cited in IE Insp Repts 50-390/80-21 & 50-391/80-15 Corrective actions incomplete work items have been completed or placed on list Six high point vents have been routed to closed drain sys MILLS.L M Tennessee Valley Authority 80/09/11 Bpp
- 8009160423 Forwards response to deficiencies noted in IE Insp Repts 50-390/80-19 & 50-391/80-13 Corrective actions QC procedure to be revised to include requirement to inspect one inch on either side af weld MIU.S.L M Tennessee Valley Authority 80/09/11 Spp
- S Reportable occurrences, LERs & related correspondence
- 8009040486 Becond interim deficiency rept re defective reactor vessel upper internals guide tube support pins TVA & Westinghouse replacing pins Next rept will be submitted by 800911 MILLS.L M Tennessee Valley Authority 80/07/24 ip
- 8009100837 Final deficiency rept re control rad drop events Operating procedures to be revised per Westinghouse instructions Procedural change will be made prior to greater than 90% power level ascension 8 will prevent power overshoot MILLB.L M Tennessee Valley Authority 80/08/05 2pp
- B007040436 Notifies of inability to correct deficiency re qualification of cold foaming procedures in accordance w/B00603 deadline Anticipated completion scheduled for 800708 MILLS, L M Tennessee Valley Authority 80/08/07 ip
- 8007040401 Third interim deficiency rept ro excessive output fluctuations of Foxboro instrumentation TVA & Westinghouse have not yet arrived at permanent solution Add1 info to be submitted by 810207
  MILLS.L M Tennessee Valley Authority 80/08/08 ip
- 8009040430 Submits third interim deficiency rept re UHI hydraulic isolation valve accumulator weighing sys Addl info to be transmitted by 800919 MILLS, L. M. Tennessee Valley Authority 80/08/08 ip
- 8009100576 Final deficiency rept re hydrogan detection sys integrity Pump diaphragm rupture could result in sys integrity breach, affecting plant safety Sample pump field mod kit being provided by Comsip. Inc Installation anticipated by 801205 MILLS, t. M Tennesses Valley Authority 80/08/13 2pp
- 8009020046 Fourth interim deficiency rept re-steam generator water level raf column error Util working u/Westinghouse to svaluate interfacing problems in installing instrumentation for temp compensation of level transmitter output signal MILLS.L M Tennessee Valley Authority 80/08/22 ip

- 8009020056 Final deficiency mept me seismic supports for auxiliary feaduater control valves Support struts cannot be installed due to interference wiather equipment interferences will be removed on new strut will be field rabricated MILLS,L M. Tennessee Valley Authority 80/09/22 2pp
- 8009100293 Final deficiency rept re documentation tag & conduit support tag removal Support Tag CS-AB-15,589 & conduit support Tag CS-AB-15,190 located & attached to proper support, & removal documented Craft employees will be retrained MILLS.L K Tennassee Valley Authority 80/09/03 2pp
- 8009100443 Second interin deficiency rept re insufficient analysis of 3-inch fire protection lines Analysis has been delayed Next rept will be submitted by 801125 MILLS, L M Tennessee Valley Authority 80/09/03 ip
- 8009100283 Final deficiency rept re cutting of conduit supports ω/ο cutting release Cutting of conduit supports documented as required by Procedure WBMP-60P-1 7 Craft personnel will be retrained in documentation procedures
  MILLS.L M Tennessee Valley Authority 90/09/04 2pp
- 8009150537 Final deficiency mept re pressurizing fans u/o automatic blade patch control Util purchased inlet vane dampers which will control air rlow into control bldg similar to manner provided by automatic pitch control blades MILLS.L.M. Tennessee Valley Authority 80/09/05 2pp
- 8009160326 Third interim deficiency rept to defective reactor vessel upper internals guide tube support pins Mestinghouse evaluation of guide tube pins being reviewed Replacement of pins underway Next rept will be submitted by 801215 MFLLS.C M Tennessee Vailay Authority 80/09/10 Ip
- 8007230468 First interim deficiency rept re damage to upper head injection piping hanger which is located on underside of reactor cavity shield plug Caused by plug being lifted for gasket fitup w/o hangers being disconnected Insp underway MILLS,L K Tennessee Valley Authority 80/09/12 2pp
- 8009230611 First interim deficiency rept re discrepancy in two MK-71 ambedded plates Existing dimension for MK-71 plate at 196 degrees discovered w/less than required anchor bolts Plates fabricated w/only one stud Add info by 80(12) MILLS.L M Tennessee Valley Authority 80/09/16 2pp
- 8009250273 Final deficiency rept re emergency gas treatment sys upen head spray noisles Open head spray noisles will be replaced by closed head water spray noisles to prevent water from spraying charcoal beds in event of inadvertent initiation MILLS, L M Fennessee Valley Authority 80/09/17 2pp
- 8009230560 First interim deficiency rept re deterioration of Unused Kerotest Y-type globe valves discovered during disassembly & Insp Meeting scheduled w/Kerotest to discuss short & longtern corrective actions MILLS.C
- 8009230610 Final deficiency rept re incorrect analysis of piping sys over operating temp range Cause not stated Piping sys reanalyted w/no major changes required MILLS.L K Tennessee Valley Authority 80/09/18 2pp
- 8009290324 Third interim deficiency rept re radiation dose inside containment exceeding cable qualification Computer codes suitable for analyses of beta radiation dose to cables inside containment obtained Completion will require months MILLS.L M Tennessee Valley Authority 80/09/19 1p
  - 09290327 Fourth interim deficiency rept re upper head injection isolation valve accumulator weighing sys Proposed Westinghouse design changes will be delayed until further testing completed Addl info will be provided by 801005 MILLS.L M Tennessee Valley Authority 80/09/19 ip
  - 09290344 Final deficiency rept re 6,900 volt shutdown board breaker lockout Seal-in contact of LX relay uill be removed from antrol circuits prior to fuel loading 'LLS.& M Tennessee Vallay Authority 80/09/19 2pp
    - IT 50-395 VIRGIL C SUMMER NUCLEAR STATION, UNIT 1

      \*\*plication/construction stage documents & correspondence
  - 1080080 Forwards draft NUREO-0696. "Functional Criteria for iergency Response Facilities " Comments requested within 30 us Proposed implementation schedule for meeting criteria NUREO-0696 enc. Wo KUREO SERMUT, D G Division of Licensing 80/08/01 119pp

- 8009050418 "Seismic Activity Near VC Summer Nuclear Station." Oct-Dec 1978 TALMANI,P South Carolina, Univ of 79-4 80/08/07 32pp
- 8009030332 Forwards requests for addlinfo concerning qualification of electrical equipment in order to complete review of ten plant electrical items Response should be provided by 800912
  TEDESCO.R L Assistant Director for Licensing 80/08/12 App
- 8009090789 Forwards request for addl info re TMI-2 action plan concerns Clarification that steam dump/safety & containment hydrogen purge exhausts will be monitored by high range noble gas efficient monitors should be provided TEDESCO,R L Assistant Director for Licensing 80/08/15 3pp
- 8007090875 Forwards NRC position re application of cladding swelling & rupture LOCA models Requests supplemental calculations
  TEDESCO.R.L Assistant Director for Licensing 80/08/26 3pp
- 8009030493 Forwards responses to NRC 800807 questions re shielding of personnel after accident Responses are in FSAR change form 5 will be included in next FSAR amend NICHOLS:T C South Carolina Electric & Gas Co 80/08/27 16pp
- 8007190776 Forwards request for addl info re floodplain mgt Requests responses no later than 800926 TEDESCO.R L Assistant Director for Licensing 80/08/28 4pp
- 8009180549 Forwards Geotechnical Review Branch requests for additinfor releffects of settlement of pumphouse & svc water intake structure TEDESCO.R L. Assistant Director for Licensing 80/09/02 12pp
- 8009180341 Requests attendance by representative at 800910 meeting in Bethes4a,MD to discuss schedule for resolution of remaining issues re licensing application TEDESCO.R L Assistant Director for Licensing 80/09/04 App.
- 8009100320 Forwards responses to RE Jackson 800620 seismology questions Responses will be incorporated in FSAR by amend Requests meeting w/NRC re seismology NICHQLS.T C South Carolina Electric & Gas Co 80/09/05 103ps
- 8009110211 Forwards response to mgt review concerns identified at 800708-10 meeting w/NRC Point-by-point comparison w/dozument entitled "Criteria For Util Mgt & Technical Competence" will be submitted at later date NICHOLS
- 8009120347 Submits response pro se & on behalf of SC Public Svc Authority, to NRC 900908 questions re TMI mods described in NUREO-0660 Anticipatory reactor trip upon turbine trip is interjocked w/P-7 setpoint NICHOLS:TC South Carolina Electric & Gas Co 80/09/09 2pp
- 8009170294 Forwards responses to questions from GA Branch Matl will be incorporated in next FSAR amend First three pages correct numbering problem w/NRC questions Last four pages provide info inadvertently omitted from last amend NICHOLS:T C South Carolina Electric & Gas Co 80/09/12 8pp
- 8009290159 Forwards request for addl info re plant shielding & design & high range containment monitors contained in NUREO-0578 TEDESCO.R L Division of Licensing 80/09/16 Spp
- 8009230296 Responds to questions re preoperational test program for facility Test sequence error will be revised to have core loading instrumentation procedure performed as initial Phase III test Air operated valves will be checked NICHOLS, T.C. South Carolina Electric & Gas Co. 80/09/17 2pp
- 8009290337 Forwards responses to generic requests for add1 info re Executive Order [1988 on floodplain mgt requested in RL Tedesco 800828 ltr Structures & topographic changes do not effect Monticello Reservoir flood hydrology NICHOLS:TC South Carolina Electric & Gas Co 80/09/23 4pp
- 8009300168 Responds to NRC request re underclad cracking in reactor vessel nozzles Related mati encl NICHOLS:T C. South Carolina Electric & Gas Co 80/09/23 22pp
- 8009260516 Forwards nonproprietary & proprietary versions of "Environ Gualification, Safety-Related Electrical Equipment/NUREO-OSB8." in response to DF Ross 800221 ltr Proprietary version withheld (ref 10CFR2 790) Affidavit encl NICHQL.5.T C South Carolina Electric & Gas Co 80/09/24 9pp

- ~-B009260518 Nonproprietary version of "Environ Qualification, Safety-Related Electrical Equipment/NUREO-0588 " ± South Carolina Electric & Gas Co B0/09/24 100pp
- E 1980 Safety Evaluation Report (SER), suppls & correspondence
- 8007160592 Forwards SER input & requests add1 info re containment pressure boundary fracture toughness PAMLICXI.S S Materials Engineering Branch 80/08/22 2pp
- F Security, medical, emergency & fire protection plans
- 8009120119 Forwards request for add1 info radiation emergency plan Requests response by B00926 TEOESCO.R L. Assistant Director for Licensing 80/09/02 19pp
- BOOP1605BB Informs of actions initiated to assist BC & local govt in dsvelopment of radiological emergency response plans consistent W/NRC-FEMA criteria MCCONNELL.JW Federal Emergency Management Agency 80/09/10 ip
- 8009230282 Forwards physical security plan, Amend 2 Plan withheld traf 100FR2 790) MICHOLS, T C Bouth Carolina Electric & Gas Co 80/09/17 ip
- Q Adjudicatory correspondence
- 8009140337 Response before US District Court for Middle District of NC. Greensboro Div.in apposition to Util motion for protective ander red Civil Action C-77-3949 Affidavit & Certificate of Swc anci BRAND, WE Brand & Hall 80/09/04 20pp
- 8009170282 Forwards 800819 FR notice re final rule upgrading Commission emergency planning regulations
  GDLD8ERG/S C Hearing Branch 2 80/09/15 13pp
- BOOT230027 Notice of withdrawal from proceeding re Commission 800430 memorandum & order,CLI-80-28, on development of new info Certificate of Byc encl CCMMER,T B . COMMER,T B . WEITERHARD M Conner. Moore & Corber 80/09/17 4pp
- BOOP300007 Notice of appearance in proceeding Certificate of Bvc encl MNOTTS.JB South Carolina Electric & Cas Co KNOTTS.JB South Carolina Public Service Authority KNOTTS.JB Debevoise & Liberman BO/O9/24 2pp
- \* Utility Final Safety Analysis Report (FBAR) & amends
- BOO9150314 Forwards changes to FBAR Section 2 5.for subsequent incorporation into FBAR by Amend 21 Requests prompt scheduling of meeting to discuss any remaining concerns MICHOLS.T C Southern California Edison Co 80/09/12 1p
- --8009150315 Amend 21 to FSAR
  \* Southern California Edison Co 80/10/31 29pp
- M Antitrust correspondence
- 8007020065 Responds to Commission 800630 memorandum & order Updates info re changes in util proposed operations & competitive status Supersedes util 800728 ltr directed to F Chanania Supporting documentation encl
  MICHOLS
- BOO9020459 Response to request for comments on Commission B00630 memorandum & order Central Electric Power Cooperative is being availed increased power supply options from SC Electric & Gas & Santee Cooper Certificate of Svc encl CHANANIA,F D Antitrust Division B0/08/29 10pp
- --8009020462 Forwards SC Public Svc Authority info in response to 800708 Itr MGRRISCN, H. P. Cahill, Oordon & Reindel 80/07/28 ip
- --BOO9020468 Responds to 800708 ltr directed to PT Allen by outlining status of negotiations between Central Electric Power Cooperative & applicants 88AND.W E Brand & Hall 80/08/05 7pg
- 8009180366 Requests meeting w/Central Electric Power Cooperative, Inc & REA to discuss REA proposed agreement changes Changes under evaluation Some changes would cause difficulty if adopted.
  MESCHER, V.C. South Carolina Public Service Authority 80/09/10 to

- 8009190307 Advises Commission & parties that DDJ attorneys have returned to counsel For petitioner documents obtained by MC Electric Membership Corp through discovery in antitrust proceeding re-racility Motion encl
  BRAND.WE Brand & Hail 80/09/1t 15pp
- --8009150312 Affidavit re SC Electric & Gas Co filing for protective order or documents sought by NC Electric Membership Corp concerning antitrust proceeding Plaintiff argues protective order would unduly burden litigation proceedings BRAND. II E Brand & Hall 80/09/03 5pp
- 8009300002 Notice of appearance in proceeding Certificate of Svc enct KNDTTS, J B South Carolina Flectric & Gas Co 80/09/24 4pp
- 8009300021 Requests extension until 801010 to respond to Commission 800630 memorandum & order Carerul analysis & evaluation of issues required KAPLAN.D A. Justice,Dept of 80/09/24 ip
- 8007300560 Order granting extension until 801010 for BOJ to comment on Commission 800630 memorandum & order CHILK.S.J. Office of the Secretary of the Commission 80/09/29 to
- P Operating license stage documents 3 correspondence
- 8007050383 Responds to FOIA request for documents re seismic activity at facility from 1978 to present Forwards Technical Rept 79-4. "Seismic Activity Near VC Bunner Nuclear Station: " Oct-Dec 1979 8 std order for DOC wor's FELTON, J M Division of Rules and Records 80/08/07 ip
- 4 Inspection reports, IF Bulletins & correspondence
- 8007030138 Forwards IE Insp Rept 50-395/80-17 on 800624-27 No noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/17 2pp
- --8009030140 IE Insp Rept 50-395/80-17 on 800424-27 No noncompliance noted Major areas inspected previous insp rindings.licensee identified atoms & preservice insp program HERDT. A Region 2. Atlanta, Reactor Construction & Engineering Support Dranch GIRARD. E H Region 2. Atlanta, Office of the Director 80/07/17 5pp
- 8009110107 Forwards 1E Insp Ropt 50-3/5/60-19 on 800716-18 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/07/29 2pp
- --8009110198 IE Insp Rept 50-395/80-19 on 800714-18 No noncompliance noted Major areas inspected pipe support baseplate designs using concrete expansion anchor halts & selsmic analysis for as-built safety-related piping sys

  ANO.N P Region 2. Attanta Office of the Director HERDT, A R
  Region 2. Attanta, Reactor Construction & Engineering Support Branch 60/07/28 4pp
- 8009030129 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Mercury-Hetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P. Region 2, Atlanta. Office of the Director 00/08/15
- 8009030130 Forwards Revision ( to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/15 ip
- 8009180511 Advises that NRC Audit Rept 50-395/80-17 dtd 800717 contains no proprietary info NICHOLS:T C South Carolina Electric 9 Gas Co 80/08/18 1p
- 8009160118 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 60/08/22 tp
- B009160120 Forwards IE Circular 60-18, "100FR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director B0/08/22 Ip

- 8009020031 Final rept, per 100FR21 & 1E Bulletin 80-16, re Rosemount Model 1152 pressure transmitter safety hazards Tuelve transmitters could have false instrument outputs caused by everyange condition instruments to be modified or replace NICHOLS.T C Southern California Edison Ca 80/08/25
- 8005250072 Responds to IE Bulletin 80-16 Review of safety-related applications or Rosenbunk Model 1152 pressure transmitters w/output codes A or D indicates none can be exposed to input pressures which could result in anoralous output signals NICHOLS, T C South Carolina Electric & Cas Co 80/08/25
- 8009030460 Pesponds to 1E Bulletin 80-19. "Failures of Hercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E Mercury-wetted relays in 7300 series are not used in matrix logic applications NECHOLS,T C South Carolina Electric & Gas Co 80/08/27 1p
- 8009110719 Ack receipt of 18 Insp Rept 50-395/80-19 on 800729 No proprietary info NICHOLS, T.C. South Carolina Electric t Gas Co. 80/08/27 ip
- 8009120265 Forwards IF Info Notice 80-31. "Maloperation of Gould-Brown Bovers 480 Volt Type K-6008 E K-EDN 6008 Circuit Breakers " No written response required O'REILLY, J P Region 2. Atlanta, Orfice of the Director 80/08/27
- 8009120286 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover: 480 Volt Type K-6005 S K-DON 6005 Circuit Breakers " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/27
- 8009160631 Ack receipt of 800728 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-395/80-15 LEWIS,R C Region 2 Atlanta Reactor Operations Nuclear Support Branch 80/09/04 ip
- -8009160634 Responds to ARC ltr re violations noted IE Insp Rept 50-395/80-15 Corrective actions Hydrostatic Test Procedure 80-15-Hi revised to include appropriate tolerances for relief setting Shubber inspected 2 protective wrappings installed NICHOLS: T C South Carolina Electric & Gas Co 80/07/28 5pp
- --8009160537 Forwards IE Insp Rept 50-395/80-15 on 800501-31 & notice of violation LEMIS.RC Region 2. Atlanta, Reactor Operations Nuclear Support Branch 60/07/07 2pp
- --8009160638 Notice of violation from insp on 800501-31
  \* Region 2. Atlanta. Office of the Director 80/0 B0/07/03 1p
- --8007160640 IE lnsp Rept 50-395/80-15 on 800501-31 Noncompliance noted failure to establish procurement document change program & failure to follow preoperational test procedures SKOLDS.JL Region 2. Atlanta, Office of the Director KELLGGG.R J Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/07/03 App
- 8009180129 Submits response to IE Bulletin 80-19. Revision 1 CP Clare Model HG2X-1011 mercury-vetted relays are not used in reactor protective sys
- 8009240510 Forwards requests for addl info re preliminary preservice
- insp program TEDESCO.R L Assistant Rirector for Licensing 80/09/10 4pp
- 8009240397 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/10
- 8009300590 Submits response to 1E Sulletin 80-20 No indications of use of Westinghouse Type W-2 control switches NICHOLS, T.C. South Carolina Electric & Gas Co. 80/09/11 1p
  - /9,240552 Forwards preservice insp #lan Plan includes programs for reld insps.hydrostatic tests.pump & valve insps & component .upport insps
    HICHGLS, T G South Carolina Electric & Cas Co 80/09/17 1p
- 8007240557 Preservice into plan MDMROE, J D. SMITH, S J. COLLIER, L B. South Carolina Electric & Gas Co. 80/09/15 300pp

- S Reportable occurrences. LERs & related correspondence
- 8009100427 Interim deficiency rept re Class 1 pipe installed w/o having required 4-way ultrasonic exam Piping not properly examined presented for shipment Caused by failure to perform & comply w/procedures to verify matl acceptability NICHOLS.Y C South Carolina Electric & Gas Co 80/07/30 Opp
- 8009020031 Final rept,per 10CFR21 & IE Bulletin 80-16,re Rossmount Model 1152 pressure transmitter safety hazards Twelve transmitters could have false instrument outputs caused by overrange condition Instruments to be modified or replaced NICHOLS.T C Southern California Edison Co 80/08/25 2pp
- 8009030621 Interim deficiency rept re lack of full penetration welds for attachments to Class I pipe Attachment welds will be reworked providing full penetration Class II & III attachments will be evaluated & rept furnished NICMGLS.T C South Carolina Electric & Oas Co 80/08/28 2pp.
- 8007080337 Final deficiency rept re potential stress corrosion cracking problem of control rod guide tube support pins supplied by Mestinghouse Util will replace pins which have been solution heat treated in range of 1,750 to 2,000 F NIGHOLS.T C Southern California Edison Co 80/07/03 3pp
- DOCKET 50-397 WPPSS NUCLEAR PROJECT, UNIT 2
- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREG-0496, "Functional Criteria for Emergency Response Facilities "Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl M/o NUREG EISENHUT. D C Division of Licensing 80/08/01 119pp
- 8007030521 Forwards "SRV Loads Improved Definition & Application Methodology for Mark II Containments," prepared by Burns & Roe. Inc. Rept withhold (ref 10CFRZ 790)
  RENBERGER: D. L. Washington Public Power Supply System. 80/08/08
- B009070631 Notification of cancellation of B00827 meeting w/BWR licensing review group to discuss concensus positions on TMI issues (NUREQ-0694) WILSON J N Assistant Director for Licensing 80/08/04 10pp
- BOD9030121 Notification of BOOB15 meeting w/util in Betheads, MD to discuss proposed structural replacement of plug welds in sacrificial shield LYNCH.M D Licensing Branch I 80/08/14 3pp.
- 8009110056 Add1 response to FOIA request for 36 categories of documents re facility Region 5 documents are available in PDR Forwards documents listed in App A
  FELTOH, J M Division of Rules and Records 60/08/26, 3pp
- --8009110061 Discusses transfer of lead responsibility for repair to facility sacrificial shield wall Signatures of HD Thornburg & RH Vollmer represent concurrence w/listed proposed actions THORNBURG, H D Division of Reactor Construction Inspection 80/05/19
- --8007110066 Transcript of 800206 brisfing in Bethesda, MD re review & evaluation of sacrificial shield wall, pipe whip restraints & related structures Pp 1-126 & Cormission 80/02/06, 126pp
- B009030403 Forwards proprietary version of "Safety Relief Valve Loads Improved Definition & Application Methodology for Mark II Containments," technical rept Rept withheld (ref 100FR2 790) VERDERBER, J J Burns & Ros Co 80/08/27 2pp
- BOO9080321 Requests meeting on 800918 w/Instrumentation & Controls Sys Branch & Reactor Sys Branch to discuss concerns before contract expiration on 800930 RENBERGER, D. L. Washington Public Power Supply System 80/08/29
- 8009090103 Lists steps to be taken prior to OL issuance to further reduce risk from ATMS events during interim period before plant mods determined by Commission are completed ATMS emergency operating procedure must be submitted for review TEDESCUR L Assistant Director for Licensing 80/08/27 Upp

- 8009090496 Forwards addl geologic into re time of latest movements of earth faults on Gable Mountain near ctr of reservation. No conclusions re significance have been reached & info is not considered reportable under IOCFR21 RENBERGER.D L. Washington Public Power Supply System. 80/09/02
- 8009260091 Notifies of 801007 proposed date to review whether OBE & SRV responses should be considered separately or combined during ASME code fatigue calculations GE selected samples to emphasize highly fatigued components
  WILSON, J N Assistant Director for Licensing 80/09/15 9pp
- 8009230392 Forwards "IEEE Reliability Qualification Rept." Revision A, "Machanical Design Rept." Revision A, "Dynamic Testing Rept." & "Thermal Cycle Test Performance" Repts available Central Files only RENBERGER, D L. Washington Public Power Supply System 80/09/14
- 8009230696 Forwards oath of affirmation inadvertently omitted from DL Renberger 800916 ltr to BJ Youngblood RENBERGER, D L Washington Public Power Supply System 80/09/17
- 8009300352 Confirms 800930 & 1001 meeting schedules w/Reactor Sys Branch & Structural Engineering Branch, respectively, re sacrificial shield wall at facility RENBERGER, D.L. Washington Public Power Supply System 80/09/22
- F Security, medical, emergency & fire protection plans
- 9009030267 Notifies of 800819,22 & 30 regional workshops re development NOTUSED NOTIFIES OF BOOB19, 22 & 30 regional workshops re deve of guidance for acceptable method for coping w/emergencies at facility Requests that representative be sent Bubj areas to be discussed include function of facilities & location ENGELERN, R H Region 5. San Francisco. Office of the Director 80/08/12 2pp
- K Utility Final Bafety Analysis Report (FSAR) & amends
- 6007D20043 Forwards revisions to electrical instrumentation & control drawings listed in Section 1 7 of FSAR Amend 12 will reflect revisions W/o encl REMBERGER, D. L. Washington Public Power Supply System 80/07/31
- 6009090680 Forwards Amend 10 to FSAR Affidavit of distribution will be furnished within 10 days of filing Affidavit & Burns & Ros arrata sheet encl RENBERGER, D. L. Washington Public Power Supply System 80/08/08
- --8009090319 Amend 10 to FBAR Seventy-three drawings encl \* Washington Public Power Supply System 80/07/31
- ~-8009090322 Package of 73 drawings to be recalled at later date for microfilming Addl documentation included ◀ Mashington Public Power Supply Bystem 80/07/31 400pp
- 8009160312 Forwards util 800910 transmittal ltr & Certificate of Svc for Amend 10 to F5AR RENBERGER, D. L. Washington Public Power Supply System 80/09/10
- O Inspection reports. IE Bulletins & correspondence
- 8007070052 Forwards IE Bulletin 80-07, Suppl 1, "BWR Jet Pump Assembly Fallure "No response required ENCELKEN, R H Region S, San Francisco, Office of the Director 80/05/14 ip
- 8009150326 Forwards IE Insp Rept 50-397/80-12 on 800530 No noncompliance noted

  noncompliance noted

  ENGELKEN, R H Region 5, San Francisco, Office of the Director

  80/06/17 2pp
- ---8009150378 IE insp Rept 50-397/80-12 on 800530 Na noncompliance noted Major areas inspected mgt meeting re results of Region 5 licensee performance evaluation for Apr 1979 through Apr 1980 1980 ENGELKEN, R H. BISHOP, T W Region 5. San Francisco, Office of the Director SPENCER, G S Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/06/17. 1p

- 8009120467 Forwards IE Insp Rept 50-397/80-07 on 800527-30 No ,...аоно, remerus 12 insp керт 50-397/80-07 on 800527-30 No noncompliance noted SPENCER,G S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/07/07 2pp
- --8009120472 IE Insp Rept 50-397/80-07 on 800527-30 No noncompliance noted Major areas inspected licensee actions in response to IE Circular 79-08 % review of dc electrical power distribution OldDS.R T Region 5. San Francisco. Reactor Construction & Engineering Support Branch ELIN.J O Region 5. San Francisco. Office of the Director 60/07/03 App
- 8009020233 Forwards IE Insp Rept 50-397/80-09 on 800618-20 No oncomplance noted
  GREMS.J L Region 5. San Francisco. Reactor Operations Nuclear
  Support Branch 80/07/16 2pp
- --8009020240 IE Insp Rept 50-397/80-09 on 800418-20 No noncompliance 109020240 IE Insp Rept 50-397/80-09 on 800618-20 No noncompliance noted Major areas inspected plant procedures, provisional acceptance packages, preoperational test procedures, & overall preoperational test program JOHKSON,P H , CARLSON,J D Region 5, San Francisco, Office of the Director STERNBERG.D M Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/07/15 3pp
- 8009260303 Forwards IE Info Notice 80-29, 'Broken Studs on Terry Turbine Steam Inlet Flange' No written response required ENCELKCH,R H Region 5, San Francisco, Office of the Director 80/0B/07
- 8009090023 Forwards updated response to 1E Builetin 79-02, Revision 2, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts' W/o encl Final response will be assued in first quarter [98] REMBERGER, D.L. Washington Public Power Supply System 80/08/08
- 800917038B Responds to TE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Two contracts identified where math may be used Math list requested from contractors RENUERGER.D.L. Washington Public Power Supply System 80/08/08
- 8007030272 Forwards Revision 1 to IE Bulletin BO-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required response required ENGELKEN, R H Region S. San Francisco, Office of the Director 80/08/15 lp
- B007040472 Forwards IE Investigation Rept 50-397/80-08 on 800403-0725 % notice of violation ENOBLKEN,R H Region 5. San Francisco. Office of the Director B0/08/15 2pp
- ---8009040474 Notice of violation from investigation on 800603-0729 # Region 5, San Francisco, Office of the Director 60/08/15 7pp
- --8009040482 IE Investigation Rept 50-397/80-08 on 800403-0725 Noncompliance noted failure to maintain QA freedom, from cost & schedule to maintain survey document of vendor & failure a schedule to maintain sorvey document of vandor's railore to document insp finding. DDDDS,R T Region 5, Sun Francisco, Reactor Construction & Engineering Support Branch BISHOP,T W, TDTH,A D Region Francisco, Office of the Director 80/08/15 47pp Region 5, San
- 8009290302 Forwards IE Info Notice 80-27 re degradation of reactor coolant pump studs ENOELKEN.R H Region 5, San Francisco. Office of the Director 80/08/18 4pp
- 8009120030 Forwards Suppl 3 to [E Bulletin 80-17, "Failure of Control Rods to Insert During Scram at 8NR " No written response ENOELKEN, R H Region 5. San Francisco. Office of the Director
- 8009150376 Forwards IC Insp Rept 50-397/80-11 on 800812 No noncompliance noted normalist Sent 50-397/80-11 on 800812 No moncompliance noted ENGELKEN, R H Region S. San Francisco. Office of the Director 80/08/22 2pp
- --8009180379 IE Insp Rept 50-397/80-11 on 800812 No honcompliance noted Major areas inspected special corporate mgt meeting in San Francisco to present results of Region 5 evaluation of licensee performance for Apr 1979 through Jul 1980 TOTH.A D . ENGELKEN.R H Region 5. San Francisco. Office of the Director 80/08/21 12pp

- 8009160189 Forwards IE Circular 80-18, "10CFRSO 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ENGELKBLAR H Region 5, San Francisco, Office of the Director 80/08/22 ip
- 800912046B Forwards 1E Info Notice 80-31, "Maloperation of Gould-Brown Soveri 480 Volt Type K-600S & K-DON 600S Circuit Breakers" No written response required EXOELKEN.R H Region 5. San Francisco, Office of the Director 80/08/27 lp
- 800912056B Responds to 1E Bullatin 80-19 No mercury-wetted matrix relays used in reactor protective sys or any safety-related sys RENBERGER. D. L. Washington Public Power Supply System 60/06/26 to
- 8009180134 Forwards Revision 1 to 1E Bulletin 79-26, "Boron Loss From Birk Control Blades" No written response required ENGELKELLAR Region 5, San Francisco. Office of the Director 80/98/29 ip
- 5 Reportable occurrences. LERs & related correspondence
- 8007240465 Deficiency rept re large diameter piping found to have less than ASME code required min wall thickness Caused by overgrinding while preparing weld profiles for ASME Section 11 inservice insp Contractors to revise procedures RENMERGER, D. L. Washington Public Power Supply System 80/07/16 Zpp
- 8009240464 Deficiency rept re Power Piping Co beam attachment. HS-142. Used in rigid sway brace assemblies supplied w/undersized welds Caused by bracket design deficiency Stop work order issued to all contractors installing subj brackets RENBERGER. D L Nashington Public Power Supply System 80/09/17 2pp
- 6009300415 Deficiency rept re primary containment pressure monitoring instrumentation sensing line routing to initiate ECGS PED 220-1-324 & -329 issued, reassigning instrumentation sensing lines to penetrations below instrument rack elevation RENUERGER, D. L. Washington Public Power Supply System 80/09/24 2m
- E007300379 Deficiency rept re lack of installation documentation for Class IE cables in main control room raceways Evaluation revealed inadequate insp criteria & OA program for installation of electrical cables Procedures being revised RENBERGER, D. L. Washington Public Power Supply System 80/09/26 2pp
- U Congressional/Executive Correspondence
- 8009110241 Forwards response to 800714 questions re financing guarantees provided to certain NRC licensees Also provides table of generating costs for nuclear plants DIRCKS, U. Office of the Executive Director for Operations 80/08/08 | 11pp
- DOCKET 50-400 BHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1

  A Application/construction stage documents & correspondence
- 8009090080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT
- 8009230772 Notification of 800905 meeting w/util in Bethesda.MD to discuss procedure for amending OLs to add addl owners WILSON.J N Licensing Branch I 80/08/29 App
- 3009170400 Summary of 800905 meeting w/CPbL 9 NC Municipal Power Agency 3 in BethesdarMD re-procedure for CL & CP amends WILSON, J N Licensing Branch 1 80/09/12 7pp
- 2009280141 Discusses interim steps needed prior to issuance of OL. pending final resolution of ATMS Emergency operating procedures should be developed in event of ATMS NRC evaluation may include site visit TEDESCO.R L Assistant Director for Licensing 80/09/12 3pp

- H General correspondence
- 8009120437 Advises of BWR owners group organizational changes & that future correspondence be forwarded to DB Waters Future requests for util action should be addressed to individual licensees & applicants
  HATERS.D B Carolina Power & Light Co 80/09/02 2pp
- 8009260509 Forwards "Mgt Capability Rept" & Section 13 i from FSAR remgt capability in support of preliminary NRC evaluation ordered 800417 Requests that preliminary evaluation begin immediately to expedite notice of opartunity for hearing UTLEY, E E Carolina Power & Light Co 80/09/22 210pp
- @ Inspection reports, IE Bulletins & correspondence
- 8008280106 Forwards IE Insp Repts 50-400/80-15,50-401/80-13, 50-402/80-13 & 50-403/80-13 on 800616-20 & notice of violation MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/25 2pp
- --8008280114 Notice of violation from insp on 800616-20
  \* Region 2, Atlanta, Office of the Director 80/07/25 ip
- --8008280126 IE Insp Repts 50-400/80-15,50-401/80-13,50-402/80-13 & 50-403/80-13 on 800616-20 Noncompliance noted failure to follow reinforcing steel storage procedure HERDI,A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/25 8pp
- BOO9020203 Submits response to IE Bulletin 79~03A No welded SA~312 or A~312. Type 300 series stainless stoel has been used or is planned for use in safety-related piping sys MCDUFFIE.M A Caralina Power & Light Co 80/08/05 ip
- 8009030163 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/15 1p
- 8009230067 Submits response to IE Bulletin 80-16 No Rosemount Inc Model (15) or 1152 pressure transmitters installed or planned for use in safety-related functions MCDUFFIE,H A Carolina Power & Light Co 80/08/20 ip
- 8009100241 Ack receipt of IE Insp Repts 50-400/80-14, 50-401/80-14, 50-402/80-14 & 50-403/80-14 on 800623-27 No proprietary info HOWE, P W Carolina Power & Light Co 80/08/22 1p
- --8009100250 Forwards IE Insp Repts 50-400/80-14, 50-401/80-14, 50-402/80-14 & 50-409/80-14 on 800623-27 No noncompliance noted MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/13 2pp
- --8009100258 IE Insp Repts 50-400/80-16.50-401/80-14.50-402/80-14 & 50-403/80-14 on 800623-27 No noncompliance noted Major areas inspected containment structural concrete, safety-related cable raceway support & pump motors

  CONLON.T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch MALTERS.D K Region 2, Atlanta, Office of the Director 80/08/12 6pp.
- 8009160124 Forwards IE Circular 80-18, "10CFR50 59 Bafety Evaluations for Changes to Radwasto Treatment Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22, 1p
- 8009120290 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Beveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No weitten response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/27
- 8009120593 Responds to IE Bulletin 80-19 Initial review of design indicates no mercury-wested matrix relays are used in reactor grotection sys Addl reviews & inquires are required MCDUFFIE, MA Carolina Power & Light Co 80/08/29 IP
- 8009180450 Ack receipt of IE Insp Repts 50-400/80-20,50-401/80-18, 50-402/80-18 & 50-403/80-18 on 800721-31 No proprietary info HOWE, P N Carolina Power & Light Cp 80/09/02 1p

- --9009180454 Forwards IE Insp Repts 50-400/80-20,50-401/80-19, 50-402/80-18 & 50-403/80-18 on 800721-31 No noncompliance noted KURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/21 2pp
- --B009180459 IE Insp Repts 50-400/80-20, 50-401/80-18, 50-402/80-18 & 50-403/80-18 on 800721-31 No noncompliance noted Major areas inspected equipment storage, containment steel & concrete placement HAKMELL. G F Region 2, Atlanta, Office of the Director BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/19 Spp
- BOO9230347 Ack receipt of BOOB19 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/80-15, 50-401/80-13, 50-402/80-13 & 50-403/80-13 KNRPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/09/09 ip
- --8009250351 Responds to NRC 800725 ltr re violations noted in IE Insp Repts 50-400/60-15,50-401/80-13,50-402/80-13 & 50-403/80-13 Corrective actions undercut area on hanger 1-CT-H-7 has been rewelded HOMEP W Carolina Power & Light Co 80/08/19 3pp
- 8009290287 Forwards IE Circular 80-21, "Regulation of Refueling Crews"
  No written response required
  O'REILLY, J.P. Region 2 Atlanta, Office of the Director 80/09/10
  5cc
- 8009300581 Submits response to IE Bulletin 80~20 Westinghouse Type W-2 control switches are not used in safety-related applications
  KCOUFFIE.M A Carolina Power & Light Co 80/09/12 1p
- BO092&0497 Submits changes in QA organization adding position of principal const specialist-insp.in response to follow-up item from IE insp on B00428-0502
  MCDUFFJE.If A Carolina Power & Light Co 80/09/19 4pp
- S Reportable occurrences, LERs & related correspondence
- BCO9100465 Deficiency rept re use of insufficient preheat in field welding of Seismic I hangers Item is still under investigation to determine reportability per 10CFR50 35e Evaluation will be completed by 8009705 (HIANGI
- BC09080254 Interim deficiency rept re procurement fabrication & insp of engineered plates for concrete embedment & support of safety-related loads Corrective action on 22 remaining plates to be completed by 801115

  CHIANGIN J Carolina Power & Light Co 80/08/29 ip
- DOCKET 50-401 GHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2

  A. Application/construction stage documents & correspondence
- E009080080 Forwards draft NUREO-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/o NUREO EISENRUT, D O Division of Licensing 80/08/01 119pp
- 8009230772 Notification of 800905 meeting w/util in Bathesda, MD to discuss procedure for amending OLs to add addl owners NTLSDN, J N Licensing Branch 1 80/08/29 4pp
- 8009170400 Summary of 800905 meeting w/CP&L & NC Municipal Power Agency 3 in Bethesda.MD re procedure for OL & CP amends MTLSON.J N Licensing Branch 1 80/09/12 7pp
- BGO9230141 Discusses interim steps needed prior to issuance of OL, pending final resolution of ATWS Emergency operating procedures should be developed in event of ATWS NRC swelpution may include site visit
  TEDESCO.R L Assistant Director for Licensing 80/09/12 Spp

### H. General correspondence

8009120437 Advises of BWR owners group organizational changes & that future correspondence be forwarded to DB Waters Future requests for util action should be addressed to individual licensees & applicants
WATERS.D B Carolina Power & Light Co 80/09/02 2pp

- 8009260509 Forwards "Mgt Capability Rept" & Section 13 1 from FSAR remgt capability in support of preliminary NRC evaluation ordered 800417 Requests that preliminary evaluation begin immediately to expedite notice of oportunity for hearing UTLEY. E E Carolina Power & Light Co 80/09/22 210pp
- Q Inspection reports, IE Bulletins & correspondence
- 8007020203 Submits response to IE Bulletin 79-03A No welded SA-312 pr A-312.Type 300 series stainless steel has been used or is planned for use in safety-related piping sys MCDUFFIE.R A Carolina Fower V Light Co BO/08/05 Ip
- 8009030163 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P. Region 2, Atlanta, Office of the Director 80/08/15 in
- 8007230067 Submits response to IE Bulletin 80-16 Na Rosemount Inc Model 1151 or 1152 pressure transmitters installed or planned for use in safety-related functions MCDUFFIE.N A Carolina Power & Light Co 80/08/20 1p
- 8009100241 Ack receipt of IE Insp Repts 50-400/80-16,50-401/80-14, 50-402/80-14 & 50-403/80-14 on 800623-27 No proprietary into HOWELP W Carolina Power & Light Co 80/08/22 1p
- --8009100250 Forwards IE Insp Repts \$0-400/80-14.50-401/80-14. 50-402/80-14 t 50-403/80-14 on 800623-27 No noncompliance noted MARPHY,C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/08/13 2pp
- --8009100258 IE Insp Repts 50-400/80-14, 50-401/80-14, 50-402/80-14 & 50-403/80-14 on 800523-27 No noncompliance noted Major areas inspected containment structural concrete, safety-related cable raceway support 8 pump motors COHLOH-T E Region 2. Atlanta, Reactor Construction & Engineering Support Branch HALYERS, DK Region 2, Atlanta, Office of the Director 80/08/12 &pp
- 8009160124 Forwards IE Circular 80-18. "IOCFRSO 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22
- B009120290 Forwards IE Info Notice B0-31, "Maluperation of Gould-Brown Boveri 480 Volt Type K-6005 & K-DDN 6008 Circuit Breakers" No written response required O'REILLY, J & Region 2, Atlanta, Office of the Director 80/08/27
- 8009120593 Responds to IE Bulletin 80-19 Initial review of design indicates no mercury-wetted matrix relays are used in reactor protection sys AddI reviews & inquires are required MCDUFFIE,M A Carolina Power & Light Co 80/08/29 ip
- 8009180450 Ack receipt of 1E Insp Repts 50-400/80-20,50-401/80-18, 50-402/80-18 \$ 50-403/80-18 on 800721-31 No proprietary info HOWE.P K Carolina Power & Light Co 80/09/02 1p
- --8009180454 Forwards IE Insp Repts 30-400/80-20,50-401/80-18, 50-402/80-18 \$ 50-403/80-18 on 800721-31 No noncompliance noted MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/21 2pp
- --8007180457 lE Insp Repts 50-400/80-20,50-401/80-18,50-402/80-18 & 50-403/80-18 on 800721-31 No noncompliance noted Major areas inspected equipment storage,containment steel & concrete placement MAXMELL.0 F Region 2, Atlanta, Office of the Director BRYANT,J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/17 Spp
- 8009280347 Act receipt of 800819 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/80-15. 50-401/80-13, 50-402/80-13 & 50-403/80-13 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/09/09 ip
- --8009250351 Responds to NRC 800725 ltr re violations noted in [E Insp Repts 50-400/80-15, 50-401/80-13, 50-402/80-13 & 50-403/80-13 Corrective actions undercut area on hanger 1-CT-M-7 has been reweided MOME.P W Carolina Power & Light Co B0/08/19 3pp

- 8009290287 Forwards IE Circular 80-21. "Regulation of Refueling Crews"
  No written response required
  O'REILLY, J.P. Region 2. Atlanta, Ortice of the Birector 80/09/10
- qqc
- 8009300581 Submits response to IE Bulletin 80-20 Westinghouse Type W-2 control suitches are not used in safety-related applications MCDUFFIE:II A Carolina Power & Light Co 80/09/12 ip
- 8009240497 Submits changes in OA organization.adding position of principal const specjalist-insp.in response to follow-up item tram IE insp on 800428-0502
  MCDUFFIE.H A Carolina Fower & Light Co 80/09/19 4pp
- S Reportable occurrences, LERs & related correspondence
- 8009100465 Deficiency rept re use of insufficient preheat in field welding or Seismic I hangers litem is still under investigation to determine reportability per 10CFR50 55e Evaluation will be completed by 800905 CHIANGLN J Carolina Power & Light Co 80/08/19 ip
- 8009080254 Interim deficiency rept re procurement, fabrication & insp of engineered plates for concrete embedment & support of safety-related loads Corrective action on 22 renaining plates to be completed by 801115
  CHIANOJ.# J Carolina Power & Light Co 80/08/29 1p
- DOCKET 50-402 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 3

  A Application/construction stage documents & correspondence
- B0090B00B0 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 enci N/o NUREO EISENYUT.D C Division of Licensing 80/08/01 119pp
- B009230772 Notification of B00905 meeting w/util in Bethesda:MD to discuss procedure for amending QLs to add addit owners WILSON, J N Licensing Branch 1 80/08/29 4pp
- 8009170400 Summary of 800905 meeting w/CP&L & NC Municipal Power Agency 3 in Bethesda MD re-procedure for QL & CP amends WHLSDN J N Licensing Branch 1 80/09/12 7pp
- 8009250(4) Discusses interim steps needed prior to issuance of CL. pending final resolution of ATMS Emergency operating procedures should be developed in event of ATMS NRC evaluation may include site visit TEDESCO.R L Assistant Director for Licensing 80/09/12 3pp
- H General correspondence
- 8009120437 Advises of BMR owners group organizational changes & that future correspondence be forwarded to DB Waters Future requests for util action should be addressed to individual litensees & applicants WATERS.D 8 Caroline Power & Light Co B9/09/02 2pp
- 8009260509 Forwards "Mgt Capability Rept" & Section 13 1 from FSAR remgt capability, in support of preliminary NRC evaluation ordered 800417 Requests that preliminary evaluation begin immediately to expedite notice of oportunity for hearing UTLEY, E E Carolina Power & Light Co 80/09/22 210pp.
- Q Inspection reports. IE Bulletins & correspondence
- 8009020203 Submits response to IE Bulletin 79-03A No welded SA-312 or A-312. Type 30D series staintess steel has been used or is planned for use in safety-related piping sys
  MCDUFFIE.H A Carolina Power & Light to 80/08/05 ip
- 8009030163 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/15
- 8007230067 Submits response to IE Bulletin 80-16 No Rosemount Inc Model 1151 or 1152 pressure transmitters installed or planned for use in safety-related functions MCDUFF1E.N A Carolina Power & Light Co 80/08/20 1p

- 6009100241 Ack receipt of IE Insp Repts 50-400/80-16,50-401/80-14, 50-402/80-14 & 50-403/80-14 on 800623-27 No proprietary info HOWE: P W Caroline Power & Light Co 80/08/22 ip
- --8039100250 Forwards IE Insp Repts 50-400/80-16,50-401/80-14, 50-402/80-14 & 50-403/80-14 on 800623-27 No noncompliants noted MARPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Granch 80/08/13 2pp
- --8009100258 IE Insp Repts 50-400/80-16.50-401/80-14.50-402/80-11 50-403/80-14 on 800623-27 No noncompliance noted Major areas inspected containment structural concrete.safety-related cable raceway support t pump motors CONLONITE Region 2. Atlanta. Reactor Construction & Engineering Support Branch WALTERS.D K Region 2. Atlanta. Office of the Director 80/08/12 6pp
- 8009160124 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluation for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/22
- 8009120290 Forwards IE Info Notice 80-31. "Maloperation of Could-Breen Bover: 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required CREILLY, J P Region 2. Atlanta, Office of the Director 80/08/27
- B009120593 Responds to IE Bulletin 80-19 Initial review of design indicates no mercury-wetted matrix relays are used in reactor protection sys Add1 reviews & inquires are required MCDUFFIE.M A Carolina Power 5 Light Co 80/08/29 lp.
- 8009180450 Ack receipt of IE Insp Repts 50-400/80-20.50-401/80-18.50-402/80-18 1 50-403/80-18 on 800721-31 No proprietary info MOME, P W Carolina Power & Light Co 80/09/02 1p
- --8007180454 Forwards IE Insp Repts 50-400/80-20,50-401/80-18, 50-402/80-18 & 50-403/80-18 on 800721-31 No noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/21 2pp
- --8007180457 IE Insp Repts 50-400/80-20,50-401/80-18,50-402/80-18 & 50-403/80-18 on 800721-31 No noncompliance noted Major areas inspected equipment storage, containment steel & concrete placement MAXMELL. OF Region 2. Atlanta, Office of the Director BRYANT. J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/19 Spp
- 8009280347 Ack receipt of 800819 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/80-15, 50-401/80-13, 50-402/80-13 & 50-403/80-13 MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/09 ip
- --8009250351 Responds to NRC 800725 ltr re violations noted in IE Insp. Repts 50-400/80-15, 50-401/80-13, 50-402/80-13 & 50-403/80-13 Corrective actions undercut area on hanger 1-CT-H-7 has been rewelded HOME, P. W. Carolina Power & Light Co. 80/08/19 3pp
- 8009290287 Forwards IE Circular 80-21, "Regulation of Refueling Craus"
  No written response required
  G'RETLLY, J.P. Region 2, Atlanta, Office of the Director 80/09/10
- 800730059f Submits response to IE Bulletin 80-20 Westinghouse Type 4-2 control sultches are not used in safety-related applications MCBUFFIE.M A Carolina Power & Light Co 80/07/12 ip
- 8007260497 Submits changes in QA organization, adding position of principal const specialist-insp.in response to follow-up item from IE insp on 800428-0502 MCDUFFIE, MA Carolina Power & Light Co 80/09/19 4pp
- S Reportable occurrences, LERs & related correspondence
- B007100465 Deficiency rept re use of insufficient preheat in field , welding of Seismic I hangers. Item is still under investigation to determine reportability per 10CFR50 55# Eyafuation unli be completed by 800905 CHIANGI.N J Carolina Power & Light Co 80/08/17 ip

- 8009080254 Interim deficiency rept re procurement, fabrication & Insp of engineered plates for concrete embedment & support of safety-related loads Corrective action on 22 remaining plates to be completed by 801115 CHIANGI, N. J. Carolina Power & Light Co. 80/08/29 1p CHIANGI,N J
- DOCKET 50-403 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 4 A Application/construction stage documents & correspondence
- 8007080080 Forwards draft NUREO-0696, "Functional Criteria for DUYOSOUND Forwards or art KOMEU-WOYD. Functional criteria for Emergency Response Facilities "Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/o NUREO EISEKHUT, D G Division of Licensing 80/08/01 119pp
- 8009230772 Notification of 800905 meeting w/util in Bethesda.MD to discuss procedure for amending OLs to add addl owners WILSON.J N Licensing Branch i 80/08/29 4pp
- 8007170400 Summary of 800905 meeting w/CPbL & NC Municipal Power Agency 3 in Bethesda-MD re procedure for OL & CP amends HILSON.J N Licensing Branch 1 80/09/12 7pp
- 8009250141 Discusses interim steps needed prior to issuance of OL, pending final resolution of ATMS Emergency operating procedures should be developed in event of ATMS NRC svaluation may include site visit TEDESCO, R L Assistant Director for Licensing 80/09/12 3pp
- H General correspondence
- 8009120437 Advises of BWR owners group organizational changes & that future correspondence be forwarded to DB Waters Future requests for util action should be addressed to individual licensees & applicants & applicants
  B Carolina Power & Light Co 80/09/02 2pp
- 8009260509 Forwards "Mgt Capability Rept" & Section 13 1 from FSAR re mgt capability in support of preliminary NRC evaluation ordered 800417 Requests that preliminary evaluation begin immediately to expedite notice of oper
- O Inspection reports, IE Bulletins & correspondence
- 8007020203 Submits response to IE Bulletin 79-03A No welded SA-312 or A-312. Type 300 series stainless steel has been used or is planned for use in safety-related piping sys MCDUFFIE.M A Carolina Power & Light Co 80/08/05 is
- 8009030163 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercuvy-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required 0°REILLY, J P Region 2, Atlanta, Office of the Director 80/01 Region 2, Atlanta, Office of the Director 80/08/15
- 8007230067 Bubmits response to IE Bulletin 80-16 No Rosemount Inc Model 1151 or 1152 pressure transmitters installed or planned for use in safety-related functions MCDUFFIE.M A Carolina Power & Light Co 80/08/20 1p.
- 8007100241 Ack receipt of IE Insp Repts 50-400/80-14, 50-401/80-14, 50-402/80-14 & 50-403/80-14 on 800423-27 No proprietary HOWE, PW Carolina Power & Light Co 60/08/22 ip
- --8009100250 Forwards IE Insp Repts 50-400/80-14,50-401/80-14, 50-402/80-14 % 50-403/80-14 pn 800623-27 No norcompliance noted MUXPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/08/13 2pp
- --B009(00258 IE Insp Repts 50-400/80-14, 50-401/80-14, 50-402/80-14 & 50-403/80-14 on 800623-27 No noncompliance noted Major areas inspected containment structural concrete, safety-related cable raceway support & pump motors CONLON.T E Region 2, Atlanta: Reactor Construction & Engineering Support Branch 80/08/12 App
- 8009160124 Forwards IE Circular 80-18, "100FRS0 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required 'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/08/22

- 8009120270 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-600S & K-DON 600S Corcuit Breakers " No written response required O'REILLY, J P. Region 2 Atlanta, Orfice of the Director 80/08/27
- 8009120393 Responds to [E Bulletin 80-19 Initial review of design indicates no mercury-wetted matrix relays are used in reactor protection sys Addi reviews 5 inquires are required MCDUFFIE.M A Carolina Power 5 Light Co 80/08/29 1p
- 8009180450 Ack receipt of IE Insp Repts 50-400/80-20,50-401/80-18, 50-402/80-18 & 50-403/80-16 on 800721-31 No proprietary
  - HOWE.P W Carolina Power & Light Co 80/09/02
- --8009180454 Forwards IE Insp Repts 50-400/80-20,50-401/80-18, 50-402/80-18 t 50-403/80-18 on 800721-31 No mangamaliance noted NURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/21 2pp
- --8007180457 IC Insp Repts 50-400/80-20.50-401/80-18.50-402/80-18 & 50-403/80-18 on 800721-31 No nancompliance noted Major areas inspected equipment storage.containment steel & concrete placement piacement MAXWELL.OF Region 2, Atlanta, Office of the Director 80/08/19
- BO09250347 Ack receipt of 800B19 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/80-15. 50-401/80-13. 50-402/80-13 & 50-403/80-13 MRZPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch B0/09/09 ip
- ---8009250351 Responds to NRC 800725 ltr re violations noted in IE Insp Repts 50-400/80-15, 50-401/80-13, 50-402/80-13 & 50-403/80-13 Corrective actions undercut area on hanger 1-CT-H-7 has been KOWE, P W Carolina Power & Light Co 80/08/17 3pp
- 8009290287 Forwards 1E Circular 80-2), 'Regulation of Refueling Crews " No written response required

  O'REILLY, J.P. Region 2. Atlanta, Office of the Director BO/09/10
- 8009300581 Submits response to 1E Bulletin 80-20 Westinghouse Type W-2 control switches are not used in safety-related applications
  MCDUFFIE,M A Carolina Power & Light Co 80/09/12
- 8009260497 Submits changes in QA organization, adding position of principal const specialist-insp, in response to follow-up item from IE insp on 800428-0502 MCDUFFIE. If A Carolina Power & Light Co 80/09/17 4pp
- S Reportable occurrences, LERs & related correspondence
- 8009100465 Deficiency rept re use of insufficient preheat in field welding of Seismic I hangers Item is still under investigation to determine reportability per 10CFR50 556 Evaluation will be completed by 8009705 CHIANGI
- BO09080254 Interim deficienty rept re procurement fabrication & insp of engineered plates for concrete embedment & support of safety-related loads Corrective action on 22 remaining plates to be completed by B01115 CHIANGI,N J Carolina Power & Light Co B0/08/29 ip
- DOCKET 50-404 NORTH ANNA POWER STATION, UNIT 3 F Security, medical, emergency & fire protection plans
- 8009230273 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency O'REILLY, J P Region 2. Atlanta, Office of the Director BO/08/22
- O Inspection reports, IS Bulletins & correspondence
- 8009100065 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Bide
  High Energy Line Rupture "No written response required
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/07/24

- 8009030141 Forwards Revision I to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required D'REILLY, J P Region 2. Atlanta, Orfice of the Director 80/08/15
- 8009160172 Forwards IE Circular 80-{8, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required

  O'REILLY, J P Region 2, Atlanta, Orfice of the Director 80/08/22

- 8009020234 Advises that review of IE Bulletin 80-16 re potential misapplication of Rosemount 1151 & 1152 pressure transmitters has been suspended Resumption pending results or studies re-reasibility of operation as nuclear units 880WN S C Virginia Electric & Power Co 80/08/27 ip
- B009020399 Responds to IE Bulletin 80-20, "Failures of Westinghouse, Type W-2 Spring Return to Neutral Control Switches" Review suspended during Feasibility study for facility Review will be resumed if study indicates continuance of nuclear units BRCWN.S C Virginia Electric > Power Co 80/09/27 1p
- 8009020416 Informs of suspending review of IS Bulletin 80-19 re failures of morcury-wetted matrix relays in reactor protective sys Feasibility study of units has curtailed activities in nuclear-related areas BROWN-S C Virginia Electric & Power Co 80/08/27 Ip
- 8009120314 Forwards IE Info Notice 80-31. 'Maloperation of Gould-Brown Boveri 480 Volt Type K-4005 8 K-DON 6008 Circuit Breakers " No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/08/27
- 8009250087 Responds to IE Bulletin 80-14 Feasibility study of units currently being conducted Activities in nuclear-related areas stopped Review of Rosemount Models 1151 & 1152 transmitters misapplication suspended BRCMN-8 C Virginia Electric & Power Co 80/08/27 ip
- 8007250517 Forwards IE Carcular 80-21, "Requaltion of Refueling Crews" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 60/07/10
- DOCKET 50-405 NORTH ANNA POWER STATION, UNIT 4 F Security, medical, emergency & fire protection plans
- B009230273 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency O'REILLY, J P Region 2. Atlanta. Office of the Director 80/08/22
- O Inspection reports, IE Bulletins & correspondence
- 8009100045 Forwards 1E Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture "No written response required O'REILLY, J.P. Region 2. Atlanta, Orfice of the Director 80/07/24
- 8009030141 Forwards Revision i to IE Bulletin 80-19. "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/08 Region 2. Atlanta. Office of the Director 80/08/15
- 8007160172 Forwards IE Circular 80-18, "100FR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/22
- 6009020236 Advises that review of IE Bulletin 60-14 re potential misapplication of Rosemount 1151 & 1152 pressure transmitters has been suspended Resumption pending results studies of feasibility of operation as nuclear u DWN:SC Virginia Electric & Power Co 80/08/27
- 8007020399 Responds to IE Bultetin 80-20, "Failures of Westinghouse. Type W-2 Spring Return to Neutral Control Suitches "Review suspended during feasibility study for facility Review will be resumed if study inductes continuance of nuclear units BROWN, S.C. Virginia Electric & Power Co. 80/08/27 ip

- 8009020416 Informs of suspending review of IE Builetin 80-19 re failures of dercury-wetted matrix relays in reactor protective sys Feas(bility study of units has curtailed activities in nuclear-related areas SRGHN.S C Virginia Electric & Power Co 80/08/27 1p
- 8009120314 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Bosen: 480 Volt Type K-6005 & K-DON 6005 Circuit Breakers" No written response required O'REILLY, J.P. Region 2. Atlanta, Orfice of the Director 80/08/27
  - 10
- 8009250087 Respunds to IE Bulletin 80-16 Feasibility study of units DVA2000) Responds to it suffering BO-To reasibility successfully confucted Activities in nuclear-related areas stopped Review of Rosemont Models 1151 & 1152 transmitters misapplication suspended

  BROAN, S.C. Virginia Electric & Power Co. 80/08/27 ip
- 8009260517 Forwards IC Circular 80-21. "Regualtion of Refueling Crest" No written response required G'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/09/10
- DOCKET 50-409 LA CROSSE BOILING WATER REACTOR F Security, medical, emergency & fire protection plans
- 8009230300 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency KEPPLER.J G Region 3. Chicago. Office of the Director 80/09/22 Эрр
- 8009250475 Informs of upcoming onsite appraisal of health physics program & requests nonemployee no escort required, picture badges for personnel identified in encl KEPPLER. J G Region 3. Chicago. Office of the Director 80/07/67
- O Adjudicatory correspondence
- 8007020041 Response in opposition to Coules Region Energy Coalition L FM Disen requests for hearing re 800225 order to show cause on site dewatering sys Hearing not required per Marble Hill std.CLI-90-10 Centificate of Svc encl HEISTAND.O S Dairyland Power Cooperative HEISTAND.O S Horsen Lewis & Bockius 80/08/28 13pp
- 8007020426 Forwards documents re comparative health effects of coal a nuclear fuel cycles in response to ASLB Question 3 at prehearing conference W/o encis MCDDHEAD.C P Hearing Branch 3 80/08/29 1P
- 8009030096 Responds to ASLB 800619 second prehearing conference questions Addresses Table S-3 of FES, justification for using Reg Guide 1 109 offsite doses computation & decommissioning cost after 10 yrs of operation Certificate of Svc enci BHCA, J. 1 Operating Reactors Branch 2 80/08/29, 12pp
- 8009030134 Response urging denial of Coulee Region Energy Coalition & FM Olsen requests for hearing re site dewatering sys, unless interest is adequately & sufficiently shown, Notices of appearances & Certificate of Svc encl
  BURNS S G , CYR.K D Rulemaking & Enforcement Division 80/08/27
- --8007030142 Forwards safety evaluation in support of licensee positive that design & installation of sits dewatering sys not required DENTON, H R Office of Nuclear Reactor Regulation, Director 80/08/29
- ---8009030147 Bafety evaluation in support of licensee position that design 8 installation of site decatoring sys not required Supporting documentation encl
  # Office of Nuclear Reactor Regulation, Director 80/08/29 1600
- --8009030150 Advises of Commissioner 800416 decision not to review
  Director's denial of enforcement action under 10CFR2 206
  CHILK.S J Office of the Secretary of the Commission 80/04/3 B0/04/17
- 8009090336 Response in opposition to FM Olsen of Coulee Region Energy Coalition motion to disqualify ASLB Unfavorable rulings not evidence of bias per 1974 ALAB-224 Notices of appearances & Certificate of Svc enci HIESTAND.O S . OALLEN.K P Dairyland Power Cooperative HIESTAND.O S . Morgan, Lewis & Bockius 80/09/05 8pp.

- 8009230001 Response to NRC second round of interrogatories Questions ability to enforce stds for protection against radiation & provisions of domestic licensing Supporting documentation encl Related correspondence HORSE.A K . NYOGARD.G R Coulee Region Energy Coalition 80/09/10
- --8009230002 Response to NRC request for admissions Denies that LACBUR is in compliance w/regulations, that offgas emissions are minimal & that radiological monitoring program is adequate KORRELA K Coulee Region Energy Coalition 80/09/11 3pp
- --B009230004 Request for admissions directed to NRC re adverse effects of offgas emissions & of radiological monitoring program BUAMASTER.M Coules Region Energy Coalition 80/09/10 2pp
- B009260014 Response in opposition to NRC & applicant responses which objected to intervenor request to disqualify ASLB Board errors ignoring LACBUR cost factors in hearting focussing on plant economic aspects, are grounds for disqualification OLSEN, F K Affiliation Unknown 80/09/11 3pp
- 8009150522 Order authorizing ASLB to perform review function re hearing on issues of 800225 order to show cause CHILK,S J. Office of the Secretary of the Commission 80/09/12 to
- 8009260672 Request for postponement of full term OL hearing until completion of show cause proceeding Intervenor human & manastary resources are insufficient to continue w/two proceedings, simultaneously MORRES, A K Coulee Region Energy Coalition 80/09/15 2pp
- --E007260677 Erratum to intervenor filing in response to request for admission Last paragraph of answer to Request 10.Page 3.to be disregarded Certificate of Svc encl KCRSE:A K Coulee Region Energy Coalition 80/09/15 2pp
- 8009250012 Memorandum & order denying FM Olsen 800919 motion & 800822 amend for disqualification of ASLB & referring denial to ASLAB for review BECHHOEFER.C Atomic Safety and Licensing Board Panel 80/09/19 400
- 800925000t Certification to Commission re Coulee Region Energy Coelition B00916 request for free hearing transcripts Applicability of new rule re free transcript does not govern show cause cases Requests that scope of rule be broadened EECHHOEFER.C Atomic Safety and Licensing Board Panel 80/09/22 5pp
- E009250032 Notice of constitution of ASLAB AS Resenthal chairman & JH Buck & TS Moore,members BISHOP,C J Atomic Safety and Licensing Appeal Panel 80/09/22 fo
- 8009260443 Decision, ALAB-614, affirming ASLB 800919 order in which FM Disen 800819 motion for ASLB disqualification was denied. Bias not established BISHDP, C J Atomic Safety and Licensing Appeal Panel 80/09/24 5pp
- 8009300008 Response in support of Coulee Region Energy Coalition 800915 request for deferral of full-term OL Suspension appropriate until completion of liquefaction show cause proceeding Certificate of Byc enc!

  HEISTAND

# H General correspondence

- BOO9ii04ii Requests establishment of LPDR in Madison, WI, on behalf of WI Public Svc Commission State agency personnel will review replacement of steam generators at Point Beach Unit 1 in 1996 or 82 Related correspondence YORK, S., PARBONS, E.M., NUNNERY, W.J. Wisconsin, State of BO/OB/26 200
- P Operating license stage documents & correspondence
- B009110554 Supple NRC 800707 request for proposed Tech Specs Changes ra scram discharge vol vent & drain valves, & reactor protection sys & control rod block limit switch surveillance requirements Class III license fee to be submitted w/change EISENHUT, D Q Division of Licensing 80/07/22 22pp
- 8009110612 Forwards request for addl info re anchorage & support of safety-related electrical equipment CRUTCHFIELD.D Operating Reactors Branch 5 80/07/28 5pp

- 8009020297 Submits interim criteria for shift staffing to all DL & CP licensees & applicants.per NRC 800507 ltr Discusses administrative provisions for emergency & overtime work Development & implementation to be reviewed within 90 days EISENHUT, D & Division of Licensing 80/07/31 7pp
- 8009080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 ent N/O NUREG EISENHUT.D 6 Division of Licensing 80/08/01 119pp
- 8009030239 Application to amend License DPR-45 re administrative control Tech Specs Amend reflects changes in facility mgt structure & staff & incorporates STS Class [I] amend fee encl LINDER.F Dairyland Power Cooperative 80/08/04 3pp
- --8009030243 Proposed Tech Spacs Section 6 0 for administrative controls, reflecting changes in facility mgt structure % staff % incorporating STS # Dairyland Power Cooperative 83/08/06 21pp
- 8009230052 Informs that exemption from fee re licensing action associated w/TMI-2 Lessons Learned is unjustified Previous determination should be disregarded Requested submittal should include proposed class of amend EISENHUT.D & Division of Licensing 80/08/07 60pp
- 8009220394 Responds to util 800701 itr re insp fees by forwarding corrected invoice Bafety & safeguards fees assessed for facility are flat fees established by regulation & are based on average cost M/o encl invoice & related mat!

  MILLER, W D License Fee Management Branch 80/08/22 2pp
- B009110746 Notification of 800916 meeting w/8EP owners group to discuss NRC initial review & recommendations for site-specific ground response spectra & owners group program plans for seismic functional qualification of Class IE equipment LEVIN.H A Division of Engineering 80/08/26 Ip
- 8009150042 Notification of 800908-11 meetings at plant sites w/utils to discuss environ qualification of electrical equipment PAULSON.W A Operating Reactors Branch 5 80/08/27 2pp
- 8007070529 Forwards answers to questions re TMI lessons learned scope & criteria for licensing exams Procedures for feedback of operating experiences to plant staff currently under review LINDER.F Dairyland Power Componative 80/09/03 App
- 8007290143 Notification of 800726 meeting w/utils & Kerr-McGee Chemical Corp in Nethesda.MD to discuss review 9 recommendations for site specific ground response spectra & program plans for seienic functional qualification of Class IE equipment ALLISON.D P Systematic Evaluation Program Branch 80/09/06 3pp
- 8009220145 Responds to questions forwarded w/NRC 800728 itr re presence of voids undermeath turbine bldg mat lwo borings, DM-12 & DM-13, indicated existence of minor voids in vicinity of borings Voids exist only within turbine bldg area LINDER, F Dairyland Power Cooperative 80/09/09 App
- 80092A0022 Notification of second rescheduling until 801003 for meeting w/SEP owners group & KMC. Inc to discuss NRC initial review of site-specific ground response spectia & util program for selmic functional qualification of Class IE equipment ALLISON, D.P. Systematic Evaluation Program Branch 80/09/10 3pp
- 8009240343 Forwards revised Tech Spec Table 6 2 2-1 re min shift crew composition, originally submitted in 800906 application for amend to License DPR-45 LINDER:F Dairyland Power Cooperative 80/09/16 3pp
- --8007240350 Revised Tech Spec Table 6 2 2-1 re min shift crew composition 4 Darryland Power Cooperative 80/07/16 1p
- Q inspection reports, IE Bulletins & correspondence
- 8009090028 Forwards IE Bulletin 80-07. Suppl 1, "BWR Jet Pump Assembly Failure" No response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/14 lp
- 800926041B Forwards IE Insp Rept 50-409/80-04 during June 1980 No noncompliance noted HEISHMANLR F Region 3. Chicago. Reactor Operations Nuclear Support Branch 80/07/10 2pp

- --8009260420 IE Insp Rept 50-409/80-04 during June 1980 Nd honcompliance noted Major areas inspected operational safety, surveillance, maint & TRE short-term mods BAKER.K R . RIDGHAY.K R Region 3, Chicago. Office of the Director 80/07/09 5pp
- 8009090008 Responds to IE Bullatin 80-20. "Failures of Westinghouse Type N-2 Spring Return to Neutral Control Switches" Switches are not used in safety-related applications at facility LINUER.F Dairyland Power Cooperative 80/08/08 ip
- 8009090010 Responds IE Bulletin 80-19, 'Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " C-E did not design facility Relays are not used in reactor protective sys LINOER, F Dairyland Power Cooperative 80/08/08 ip
- 8009030196 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written Region 3, Chicago. Office of the Director 80/09/15
- 8009150455 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Stram Function & Numerocation & Numerocation & Numerocation & Numerocation & Numerocation & Numerocation or response requested KEPPLER. J G Region 3. Chicago. Office of the Director 80/08/20
- 6007120044 Forwards Suppl 3 to 16 Bulletin 80-17. "Failure of Control Rods to Insert During Scram at BWR " Written response required KEPPLER, J.G. Region 3, Chicago, Office of the Director 80/08/22
- 8009170419 Forwards IE Circular 60-18, "10CFRSO 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required
  KEPPLER.J G Region 3. Chicago. Office of the Director 80/08/22
- 8009230087 Forwards [E Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required KEPPLERJ & Region 3. Chicago. Office of the Director 80/08/28
- DO9230497 Forwards Revision 1 to IE Bulletin 79-26, "Boron Loss From BWR Control Blades" Written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/08/29
- 209220157 Responds to IE Bulletin 80-15, "Possible Loss of Emergency Notification Bys (ENS) w/Loss of Offsite Power " Test conducted on 800702 w/all ENS extensions operating satisfactorily LINOER,F Dairyland Power Cooperative 80/09/02 2pp
- 8009240098 Forwards 1E Circular 80-2:, "Regulation of Refueling Crews" No written response required
  MERPLER, J G Region 3, Chicago, Office of the Director 80/09/10
- A Periodic operating reports & related correspondence
  - 09[60250 Forwards monthly operating rept for Aug 1980 INDER: F Dairyland Power Cooperative 80/09/08 1
  - D09160293 Monthly operating rept for Aug 1980 G00DMARL S Dairyland Power Cooperative 80/09/09 10ap
  - Reportable occurrences, LERs & related correspondence
  - 9030454 Forwards LFR 80-005/017-0 Dairyland Power Cooperative 80/08/27 5pp
  - OO9030457 LER 80-005/01T-0 on 800806.during operation.valve addition to shutdown condenser shell gauge tap found w/o design change Caused by personnel error Valve was removed.Pipe cap was installed & tested w/acceptable results
    GUDDMANL S Dairyland Power Cooperative 80/08/18 1p
  - 7230648 Forwards LERs 80-004/03L-0 % 80-007/03L-0 [NDER.F Dairyland Power Cooperative 80/07/12 17pp

- --8009230657 LER 80-006/03L-0 on 800814, during reactor shutdown, indicated alpha activity of primary coolant sample exceeded Tech Specs Caused by degraded fuel cladding Primary purification sys operation reduced concentration to allowable value GODDMAN.L. S Dairyland Power Cooperative 80/09/12 lp
- --8007230664 LER 80-007/03L-0 on 800816, during reactor shutdown, indicated alpha activity of primary coolant sample exceeded Tuch Spers Caused by degraded fuel cladding Primary purification sys operation reduced concentration to allowable value 80/09/12 Dairuland Power Cooperative
- 8009240430 Forwards LER 80-008/03L-0 LINDER, F Dairyland Power Cooperative 80/09/19 3pp
- --8009260636 LER 80-008/03L-0 B00819.18 high pressure svc water diesel did not start on manual activation Diesel did start locally from battery banks Caused by bad cell in one B bank battery Battery replaced GOODMAN.L S Dairyland Power Cooperative 80/09/19 ip
- T Hearing transcripts on non-antitrust matters
- 8009190763 Transcript of 800911 prehearing conference re show cause order in La Crosse WI Pp 1-67
  \* Atomic Safety and Liconsing Board Panel, 80/09/11 48pp
- 80092&0075 Transcript of B00911 Affirmation Session 80-40 in Hashington.DC re delegation of review authority in LaCrosse proceedings Pp 1-4 \* Commission 80/09711 6pp
- DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2 A Application/construction stage documents & correspondence
- BOOFOBOOBO Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities' Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl 4/o NUREG EIBENHUT.DO Division of Licensing 80/08/01 119pp
- 8009020248 Responds to NRC 800728 request re latest const completion date Schedule & reasons for delay in completion of const will be submitted by 810131 RHODE-6 K Niagara Hohawk Power Corp 80/08/27 1p
- 8009090035 Submits interim actions for plant operation, pending final resolution of ATWS Emergency operation procedural review may include NAC site visit prior to issuance of OL TEDESCO.R L Assistant Director for Licensing 80/08/29 3pp
- 8009110742 Notification of 800904-05 meeting w/Mark II owners group to discuss plants chugging C/O % lateral load specs ANGERSON, C Containment Systems Branch 80/08/29 14pp
- 8009110633 Notification of 800903 trip to facility to investigate terrestrial ecology of site for cooling tower rept review KIPER.K L Licensing Branch 1 60/09/02 2pp
- 8007150551 Requests NRC review of Gulf & Western FBD-2508 re main steam valve Review is needed by 801231 to maintain current engineering & const schedule RHGDE.G K Niegare Mohawk Power Corp 80/09/08 1p.
- 8009150560 Forwards requests for addl info re proposed cooling tower for plant. TEDESCO.R L Assistant Director for Licensing 80/09/09, 4pp
- 8009240333 Summary of 800814 meeting w/util,8&W & Dyckerhoff & Widmann, Inc in BethesdarMD re application of the DywiDay Threadbar Sys on secondary containment structure KIPER.K L Licensing Branch I 80/07/09, 4pp
- G Inspection reports. IE Bulletins & correspondence
- 8009090087 Forwards IE Builetin 80-07, Suppl 1, "BUR Jet Pump Assembly GRIER, B H Region 1, Philadelphia, Office of the Director 80/05/13 1p
- 8007050482 Forwards IE Insp Rept 50-410/80-04 on 800512-15. No noncompliance noted CARLSON R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 50/07/10 2pp

- --B009050426 IE Insp Rept 50-410/80-04 on 800512-15 No noncompliance noted Major areas inspected repair activities associated u/biological shield wail IRIPP.L E Region 1. Philadelphia, Reactor Construction & Engineering Support Branch MCSREARTY,R A , WALTON, G A Region 1. Philadelphia, Office of the Director 80/07/08 dpp
- S009153092 Forwards IE lnsp Rept 50-410/80-05 on 800617-19 No nancompliance noted CAMESON.R T Region i. Philadelphia, Reactor Construction & Engineering Support Branch 80/07/17 2pp
- --8009150097 IE Insp Rept 50-410/80-05 on 800617-19 No noncompliance noted Hajor areas inspected licenses action on previous findings & cadwelding on containment floor & wall MCGAUCHY, R W Region 1. Philadelphia, Reactor Construction & Engineering Support Branch Fell.R Region 1. Philadelphia, Office of the Director 80/07/16 Spp
- 0009230098 Responds to IE Bulletin 79-03A re use of SA-312 or A-312. Type 300 fusion welded pipe Analysis determined that identified piping will not be subj to stresses greater than code allowable No action required RHODE.O K Niagara Mohawk Power Corp 80/08/06 2pp
- 8009030087 Forwards Revision i to IE Bulletin 80-19. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER.B H Region i, Philadelphia. Office of the Director 80/08/15 io
- 8007120075 Forwards Suppl 3 to IE Bulletin 80~17, "Failure of Control Rods to Insert During Scram at BWR " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/08/22 1p
- 8009180023 Forwards IE Circular 80-18. "100FR50 59 Bafety Evaluations for Changes to Radwaste Treatment Sys " No written response required ORIER, 8 H Region 1. Philadelphia, Office of the Director 80/08/22 1p
- 8009120193 Forwards IE Info Notice 80-31. "Maloperation of Gould-Grown Bover1 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/08/27 1p
- 8009240033 Forwards IE Circular 80-21. "Regulation of Refueling Crews "
  No written response required
  GRIER, 3 H Region 1. Philadelphia. Office of the Director
  80/09/10 1p
- 8009240323 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matis " No written response required CRIER.B H Region 1, Philadelphia, Office of the Director 80/09/12 ip
- S Reportable occurrences, LERs & related correspondence
- BOOTOTOBER Ack receipt of final deficiency rept re environ & seismic qualification of electrical equipment CARLEDN.R T Region i. Philadelphia, Reactor Construction & Engineering Eupport Branch 80/08/20 1p
- 8007070844 Ack recupt of 800724 ltr re potential deficiency in radwasts bldg geologic feature CARLEON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/08/20 ip
- ---8003090848 Interim deficiency rept re potential deficiency in possible future movement of radwaste bldg geologic feature Forwards response to Ofc of Nuclear Reactor Regulation Geologic Info Request 00361 i Final rept will be submitted by 801231 RHODE.O K Niagara Mohawk Power Corp 80/07/24 11pp
- DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- BOOPOBOOSO Forwards draft NUREO-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/o NUREO EISENHUT.D O Division of Licensing 80/08/01 119pp

- I Financial information
- 8007230599 Apprises NRC of facts re proposed temporary transfer by OH Edison Co of ownership interest in facility Ownership interest will be transferred to Const Tryst which will not be involved in const & operation mafters or plant BYINGTON, J.H. Winthrop, Stimson, Putnam & Roberts 80/09/19 Spp
- Q Inspection reports, IE Bulletins & correspondence
- 8009100865 Forwards IE Insp Rept 50-412/80-07 on 800707-10 No noncompliance noted CARLSON:R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/07/25 2pp
- --8009100870 IE Insp Rept 50-412/80-07 on 800707-10 No noncompliance noted Major areas inspected welding of structural angle clips to embedment plates installation of snubber supports & unloading of steam generator supports MARROULL. Region 1. Philadelphia. Office of the Director MCGAUGH4/R W Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/07/24 7pp
- 9009030075 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER.8 H Region 1. Philadelphia. Office of the Director 80/08/19 1p
- B0091B0483 Forwards IE Circular 80-18 "10CFR50 57 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director B0/08/22 19
- 8009120219 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Voit Type K-5008 & K-DON 5008 Circuit Breakers " No written response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/09/27 ip
- 8009240031 Forwards IE Circular 80~21, "Regulation of Refueling Crews" No written response required GRIER.B H Region 1. Philadelphia, Office of the Director B0/09/10 tp
- 8009240342 Forwerds IE Info Notice 80-32. "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required ORIER B H Region i, Philadelphia, Office of the Director 80/09/12 1p
- S Reportable occurrences, LERs & related correspondence
- BOO9090248 Final Significant Deficiency Rept 80-04 re misapplication of welding electrode E-309-(6 Increased emphasis placed on verification of mechanical contractor electrode control progrem by creating welding supervisor position WOOLEVER.E J Duquesne Light Co BO/09/04 6pp
- DOCKET 50-413 CATAMBA NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT, D G Division of Licensing 80/08/01 119pp
- 8009040434 Forwards math re NRC review of ice condenser containment & hydrogen control measures for Sequoyah Nuclear Power Plant ACRB has scheduled meetings in Washington, DC on 800826, 0702 & 04 to discuss issue TEDESCO, R L Assistant Director for Licensing 80/08/22 5pp
- 8009190399 Responds to NRC 800520 ltr re NUREO-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " (to response needed, pending add 1 NRC guidance PARKER, M O Duke Power Co 80/09/16 lp
- G Inspection reports, IE Bulletins & correspondence

- -8009110425 Forwards IE Insp Repts 50-413/80-13 & 50-414/80-13 on 800s18-20 No noncompliance noted MJRPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/23 2pp
- -8009110427 [E Insp Repts 50-413/80-13 & 50-414/80-13 on 800618-20 No noncompliance noted Major areas inspected field performance, drawings & work procedures, engineering, QC, matls & equipment. procurement, receiving & storage COII(DN.TE Region 2. Atlanta, Reactor Construction & Engineering Support Branch BROWNLES, V.L., BURDETTE, T.E. Region 2. Atlanta, Orfice of the Director 80/07/23 App
- 009030175 Forwards Revision 1 to IE Bulletin 80-17, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Britten response required
  O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/15
- 109170371 Advises that final response to IE Bulletin 80-09 not submitted due to necessary info not available from vendors Final rept expected by 801201 PARKER, W. O. Duke Power Co. 83/08/15 1p
- 109140642 Responds to IE Bulletin 80-20 re failures of Westinghouse W-2 spring refurn to neutral control switches Identified switches are not used or planned for use in safety-related areas Thirteen manhours expended for review PARKER, W D Consumers Power Co 80/08/20 1p
- 109160137 Forwards IE Circular 80-18. ":OCFR50 59 Gafety Evaluations for Changes to Radwaste Treatment Sys " No written response
- required
  O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/22
- 09120343 Forwards IE Info Natice 80-31, "Maloperation of Gould-Brown Bover: 460 Volt Type K-6005 & K-DDN 6005 Circuit Breakers" No written response required 0'REILLY.J P Region 2, Atlanta, Office of the Director 60/08/27
- 09120587 Responds to 1E Bulletin 80-19 Mercury-wetted matrix relays are not used or planned for use in reactor protection sys PARKER, W O Duke Power Co 80/08/28 ip
- )9240282 Ack receipt of 600819 ltr informing NRC of steps taken to orrect violation noted in IE Insp Repts 50-413/80-10 & 30-414/80-10 William Region 2. Atlanta Reactor Construction & Engineering Support Branch 60/09/02 ip
- 0007240270 Responds to NRC 800623 itr re violations noted in IE Insp Repts 30-413/80-10 & 50-414/80-10 Corrective actions util uill insp addl component support welds PARKER.U O Duke Power Co 80/08/19 ip
- 009240294 Act receipt of 800715 ltr informing NRC of steps taken to correct violation noted in IE lnsp Repts 50-413/80-10 \$ 50-414/80-10 Requests add1 response MURPHY.C E Region 2. Atlanta. Reactor Construction \$ Engineering Support Branch 80/08/12 ip
- 007240278 Responds to NRC 800623 ltr re violations noted in IE Insp Repts 50-413/80-10 & 50-414/80-10 Corrective actions insp of component support welds initiated PARKER.W D Dute Power Co 80/07/15 2pp
- 009240302 Forwards IE Insp Repts 50-413/80-10 & 50-414/80-10 on 800827-30 & notice of violation hURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/06/23 2pp
- 099240306 Notice of violation from insp on 800527-30 \* Region 2, Atlanta, Office of the Director 80/0 80/06/20 10
- )09240313 IE Insp Repts 50-413/80-10 & 50-414/80-10 on 800527-30 Moncompliance noted undersized fillet weld HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch KLEINSORGE, W P. COLEY, J. L. Region 2, Atlanta, Office of the Director 80/06/20 10pp
- 240292 Ack receipt of B00919 ltr informing NRC of steps taken to rrect violations noted in IE lnsp Repts 50-413/E0-15 t -414/E0-15 RPHY, C E Region 2. Atlanta Reactor Construction & Engineering pport Branch 80/09/02 Ip

- --8009240297 Responds to NRC 800725 ltr re violations noted in IE lnsp Repts 50-413/80-15 & 50-414/80-15 Corrective actions GC welding inspectors restrained in requirements of GA procedures M-19 & M-4 Emphasis placed on documentation FARKER,W O Duke Power Co 80/08/19 2pp
- --8007240337 Forwards IE Insp Repts 50-413/80-15 & 50-414/80-15 on 800630-0703 & notice of violation //WRPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/25 2pp
- --8007240314 Notice of violation from insp on 800430-0703
  \* Region 2. Atlanta, Office of the Director 80/07/
- --8007240320 IE Insp Repts 50-413/80-19 % 50-414/80-15 on 800630-0703 DUY24032V LE Insp Repts 50-413/80-19 % 50-414/80-15 on 800630-0703 Noncompliance noted failure to document QC welding surveillance HERDI,A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch VANDOORN,P K Region 2, Atlanta, Office of the Director 80/07/25 6pp
- 8009250339 Ack receipt of IE Insp Repts 50-413/80-20 & 50-414/80-20 on 800804-05 No propiletary info PARKER.W O Dute Power Co 80/09/09 ip
- --800725034; Forwards JE Insp Repts 50-413/80-20 & 50-414/80-20 on 800804-08 No noncompliance noted BURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/25 2pp
- ---8007250343 IE Insp Repts 50-413/80-20 & 50-414/80-20 on 800804-09 No noncompliance noted Major areas inspected structural concrete, storage & preventive maint & const progress HARRIS.J R Region 2. Atlanta, Office of the Director CONLON.T E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/22 3pp
- 8009290297 Forwards IE Circular 80-21, "Regulation of Refueling Crews \* No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/10
- S Reportable occurrences, LERs & related correspondence
- 8009080312 Significant Deficiency Rept 413-414/80-11 re nonseismically qualified battery racks supplied w/dissel generator unit batteries Caused by manufacturer error Three new racks will be fabricated in accordance w/proper drawings & specs PARKER,N O Duke Power Co 80/08/28 3pp
- DOCKET 50-414 CATAWBA NUCLEAR STATION, UNIT 2 A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREO-0694, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0694 encl W/o NUREO EISENHUT, B C Division of Licensing 80/08/01 119pp
- 8009040434 Forwards matl re NRC review of ice condenser containment & hydrogen control measures for Sequoyah Nuclear Power Plant ACRS has scheduled meetings in Washington.DC on 800828,0902 X 04 to discuss issue.
  TEDESCO.R L Assistant Director for Licensing 80/08/22 5pp
- B009190399 Responds to NRC B00520 ltr re NUREO-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " No response needed.pending add1 NRC guidance PARKER.W O Duke Power Co 80/09/16 ip
- G Inspection reports, IE Bulletins & correspondence
- 8009110423 Ack receipt of IE Insp Repts 50-413/80-13 & 50-414/80-13 on 800618-20 No proprietary info PARKER, W O Duke Power Co 80/08/13 ip
- --8009110425 Forwards IE Insp Repts 50-413/80-13 & 50-414/80-13 on 800618-20. No moncompliance noted MURPHY, C.E. Region 2, Atlanta. Reactor Construction & Engineering Support Branch 80/07/23 2pp

- --8009110427 IE Insp Repts 50-413/80-13 & 50-414/80-13 on 800618-20 No nancompliance noted Major areas inspected field performance, drawings & work procedures engineering GC, matls & equipment, procurement receiving & storage CONLON.T E Region 2. Atlanta, Reactor Construction & Engineering Support Branch BROWNLEE.V L. BURDETTE.T E Region 2. Atlanta, Office of the Director 80/07/23 6pp
- BO09030375 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Mercury-Netted Matrix Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E " Written response required OfREILLY.J P Region 2. Atlanta, Office of the Director 80/08/15
- 8009170371 Advises that final response to IE Bulletin 80-09 not submitted due to necessary info not available from vendors Final rept expected by 801201 PARKER, W.D. Duke Power Co. 80/08/15 ip
- BO09160642 Responds to IE Bulletin 80-20 re failures of Westinghouse M-2 spring return to neutral control switches Identified switches are not used or planned for use in safety-related areas Thirbeen manhours expended for review PARKER. M O Consumers Power Co 80/08/20 ip
- 8009160137 Forwards IE Circular 80-18. "100FR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/22 Je
- BOO9120343 Forwards IE Info Notice BO-31, "Maloperation of Oould-Brown Boverl 480 Volt Type K-6008 & K-DDN 6008 Circuit Breakers" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/27
- EO:09120587 Responds to IE Bulletin 80-19 Mercury-wetted matrix relays are not used or planned for use in reactor protection sys
  PARKER, N O Duke Power Co 80/08/28 1p
- E-0-09240282 Ack receipt of 800819 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-413/80-10 & 50-414/80-10 MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/09/02 ip
- --8007240290 Responds to NRC 800623 ltr re violations noted in 1E Insp Repts 50-4(3/80-10 & 50-414/80-10 Corrective actions util util insp addl component support welds PARKER/H O Duke Fower Co 80/08/19 ip
- --8009240274 Ack receipt of 800715 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-413/80-10 & 50-414/80-10 Requests addl response MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/12 ip
- --8009240298 Responds to NRC 800423 ltr re violations noted in IE Insp Repts 50-413/80-10 & 50-414/80-10 Corrective actions insp of component support welds initiated PARKER:N O Duke Power Ca 80/07/15 2pp
- --8009240332 Forwards IE Insp Repts 50-413/80-10 & 50-414/80-10 on 800527-30 & notice of violation MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/06/23 2pp
- --B009240304 Notice of violation from insp on 800527-30
  \* Region 2. Atlanta, Office of the Director 80/06/20 ip
- --8009240313 IE Insp Repts 50-413/80-10 & 50-414/80-10 on 800527-30 Mancompliance noted undersized fillet weld HERDT, A.R. Region 2. Atlanta, Reactor Construction & Engineering Support Branch KLEINSQRGE-M P., GOLEY, J L. Region 2. Atlanta, Office of the Director 80/06/20 10pp
- 8009240292 Ack receipt of 800919 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/80-15 & 50-414/80-15 MURPN/C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/02 ip
- --8097240277 Responds to NRC 800725 itr re violations noted in IE Insp Repts 50-413/80-15 & 50-414/80-15 Corrective actions. GC welding Inspectors restrained in requirements of GA procedures M-17 & M-4 Emphasis placed on documentation PARKER. N O Duke Power Co 80/08/17 2pp

- ~~6009240307 Forwards [E Insp Repts 50-413/80-15 & 50-414/80-15 on 800630-0793 & notice of violation MURPHY, C E Region 2. Atlanta, Reacfor Construction & Engineering Support Branch 80/07/25 2pp
- --8009240314 Notice of violation from insp on 800630-0703 \* Region 2, Atlanta, Office of the Director 80/07/25 ip
- --B009240320 IE insp Repts 50-413/80-15 t 50-414/80-15 on B00630-0703 Noncompliance noted failure to document QC welding surveillance HERDT, A R Region 2. Atlanta. Reactor Construction & Engineering Support Branch VANDOURN, P K Region 2. Atlanta. Office of the Director 80/07/25 6pp
- 8009250339 Ack receipt of IE Insp Repts 50-413/80-20 & 50-414/80-20 on 800804-08 No proprietary info PARKER,N D Duke Power Co 80/09/09 1p
- --B009250341 Forwards IE Insp Repts 50-413/80-20 & 50-414/80-20 on 300804-08 No noncompliance noted MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch B0/08/25 2pp
- --8009250343 IE Insp Repts 50-413/80-20 % 50-414/80-20 on 800804-08 No noncompliance noted Major areas anspected structural concrete, storage & preventive maint & const progress HARRIS, J. R. Region 2. Atlanta. Office of the Director CONLON.T E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/08/22 3pp
- 8009290297 Forwards IE Circular 80~21, "Regulation of Refueling Crews" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/10 Spo
- S Reportable occurrences, LERs & related correspondence
- 8009080312 Significant Deficiency Rept 413-414/80-11 re nonseismically qualified battery racks supplied w/diesel generator unit battories Caused by manufacturer error Three new racks will be fabricated in accordance w/proper drawings & specs PARKCR, H O Duke Power Co 80/08/28 3pp
- DUCKET 50-414 GRAND GULF NUCLEAR STATION, UNIT 1

  A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREG-0694, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENNUT.D G Division of Licensing 80/08/01 119pp
- 8009020413 Forwards Amend 42 to application for OL, consisting of responses to NRC questions re FSAR & asserted matters & including miscellaneous refinements of design info Revised P&IDs encl
  MCGAVOHY, J P Mississippi Power & Light Co 80/08/29 ip
- --8009020418 Amend 42 to application for OL. consisting of responses to NRC questions re FSAR & assanted matters & including miscellaneous refinements of design info \* Mississippi Power & Light Co 80/08/29 2pp
- --8009020423 Amend to FSAR, constituting Amend 42 to application for OL # Mississippi Power & Light Co 80/08/29 300pp
- --8009020427 "P&tD Diagram Fuel Pool Cooling & Cleanup Sys.Unit 1 " \* Bechtel Corp 9645 80/06/26 1p
- --8009020430 "Public Address Sys Riser Diagram. Unit 1 & Common " \* Becktel Corp 9645 80/02/07 1p
- --8009020494 "Public Address Sys & Public Telephone Riser Diagram, Unit 1 Common" 4 Bechtel Corp 9645 80/01/02 1p
- --8009020438 "Public Address Sys Riser Diagram.Unit 2 " \* Bechtel Corp 9645 78/12/21 ip
- B009050352 Forwards "Environ Protection Program Preoperational Monitoring Regt" DALE-LF Mississippi Power & Light Co 80/08/29 1p

## DOCKETED ITEMS

- --8009050356 "Environ Protection Program Preoperational Monitoring Rept "
  4 Mississippi Power % Light Co 80/08/29 23pp
- 8009190099 Forwards request for add1 info resulting from FSAR review Dutstanding items include assessment of degree of damage due to tornado generated missles & description of amplification factors used in plant design TEDESCO.R L Assistant Director for Licensing 80/08/29 17pp
- B009110543 Notification of 800923-24 meetings w/ufil.Bechtel.GE & Savannah Raver Lab to review facility sys & discuss Reactor Sys Branch questions MARTORE.J A Licensing Branch 3 80/09/04 2pp
- B009230235 Notification of 800917 meeting w/util, OE & Savannah River Lab in Bethesda, MD to discuss applicant approach to HPCS Level B trip logic MARTERE, J.A. Licensing Branch 3 80/09/04 2pp
- BOO9150425 Expresses concern at meeting licensing schedule milestones, due to lack of NRC activity on second round questions Requests for addl info should be made immediately or questions should be replaced by draft SER for branches LUTKEN.D C Mississipp: Power & Light Co 80/09/08 2pp
- 8009150453 Endorses draft SER approach to formulating SER In comparing draft SER approach w/formal question method/approx 225 manhours saved in mechanical engineering using draft SER approach LUTKEN.O C Mississippi Power & Light Co 60/09/08 2pp
- 8009260531 Forwards request for addl info re FSAR FSAR should be amended to reflect responses TERESCORL Assistant Director for Licensing 80/09/09 9pp
- 8009230454 Confirms 800916 telcon re 800923 meeting to discuss resolution of GE supplied radiography problem at facilities HCGAUGHY, J.P. Mississippi Power & Light Co. 80/09/17 ip
- 8009300437 Forwards response to NRC Questions 031 56.031 71 % revised responses to Questions 031 38.031 54.031 60 % 031 75 Responses will be incorporated into Oct 1980 amend to FSAR DALE, L. F. Mississippi Power & Light Co 80/09/22 102pp
- F Socurity, medical, emergency ≥ fire protection plans
- 8009180002 Summary of 800813 meeting w/util 3 NVSAC in Bethesda.HD rephysical security plan MARTORE, J.A. Licensing Branch 3 80/09/09 3pp
- | General correspondence
- 1009030504 Informs NRC of organizational changes which will be incorporated into Revision 2 of operational OA nanual scheduled for submittat in Dec 1980
  REAVES.T E Mississippi Power & Light Co 80/08/27 ip
- Utility Final Safety Analysis Report (FSAR) & amends
- OC91504B9 Forwards affidavit of svc on distribution of Amend 42 to FBAR
  PALE.L F Mississippi Power & Light Co 60/09/08 2pp
- Inspection reports. IE Builetins & correspondence
- H009090069 Forwards IE Bulletin 80-07. Suppl 1, "BWR Jet Pump Assembly Failure" No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/13 ip
- 8007120135 Forwards IE losp Repts 50-416/80-14 & 50-417/80-10 on B00603-06 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch B0/07/21 2pp
- --8009120141 IE insp Repts 50-416/80-14 & 50-417/80-10 on 800603-06 No noncompliance noted Major areas inspected electrical equipment in-place storage & licensee actions on prior items
  MALVERS.D K Region 2. Atlanta, Office of the Director COULDN.T E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/21 5pp
- 8009120143 Forwards IE Insp Rept 50-416/80-15 on 800528-0627 No noncompliance noted LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/07/22 2pp

- --8009120240 IE Insp Rept 50-416/80-15 on 800528-0627 No noncompliance noted Major areas inspected preoperational test status, administrative QA & independent insp effort WAGNER, A G Region 2, Atlanta, Office of the Director KELLOGO, P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/07/22 3pp
- BOO9020218 Submits response to IE Bulletin 79-03A No SA-312 Type 304 series piping used in any safety-related sys at greater than 85% design stress Requests extension until 800901 to complete review of bulletin DALE.L F Mississippi Power & Light Co 80/08/06 1p
- 8009020292 Requests extension until 800901 to complete investigation in response to IE Bulletin 80-09. "Examination of Containment Liner Penetration Welds" DALE, L. F. Mississippi Power & Light Co. 80/08/15 ip
- 8009030128 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E " Written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/15 to
- B009160036 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE BUR Facilities "No specific action or response requested O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/19 ip
- 8009230092 Forwards response to IE Bulletin 80-09 Penetration closure details enc1 Radiography used for all full penetration butt uelds Final response expected by 801015 DALE.L F Mississippi Power & Light Co 80/08/21 14pp
- 8009120080 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR" No written response required
  - O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 89/08/22 ip
- 8009160115 Forwards IE Circular 80-18, "100FR90 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'RE[LLY, J P Region 2, Atlanta, Office of the Director 80/08/22
- 8007110581 Responds to IE Bulletin 80-16 Ten Rosemount, Inc Model 1151A transmitters schoolled to be used in safety-related applications were purchased Transmitters will be replaced before fuel loading DALE, L.F. Mississippi Power & Light Co. 80/08/27 2pp
- 8009120260 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required D'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/27
- 8009240318 Ack receipt of 800730 ltr informing NRC of steps taten to correct violation noted in IE Insp Repts 50-416/80-07 the S0-417/80-07 STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/08/28 ip
- --8009240331 Responds to NRC 800423 ltr re violations noted in IE Insp Repts 50-416/80-07 & 50-417/80-06 Corrective actions dredging operations will be completed by 800905 MCOAUOHY, J.P. Massissippi Power & Light Co. 80/07/30 lp
- 8009080328 Responds to violation noted in IE Insp Repts 50-416/80-16 & 50-417/80-17 Corrective action constructor reinspected 513 ABME socket welds to determine extent to which welds are undersized in safety-related applications MCGAUGHY, J P Mississippi Power & Light Co 80/08/27 2pp
- 8009270271 Forwards IE Circular 80-21, "Regulation of Refueling Creus" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/09/10
- 8009300026 Ack receipt of 800829 & 0902 ltrs informing NRC of steps taken to correct violations noted in lE Insp Repts 30-416/80-16 & 50-417/80-11 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/09/11 ip

- --8009300029 Responds to NRC 800805 ltr re violations noted in IE Insp Rapts 50-416/80-16 & 50-417/80-11 Corrective actions constructor audit procedures revised to allow documentation of concerns found & corrected during audit MCGAUGHY, JP Mississippi Power & Light Co 80/09/02 2pp
- --8009300031 Forwards IE Insp Repts 50-416/80-16 & 50-417/80-11 on 800715-18 & notice of violation HURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/08/05 2pp
- --8009300034 Notice of Violation from insp on 800715-18
  \* Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/05 1p
- --8009300041 IE Insp Repts 50-416/80-16 & 50-417/80-11 on 800715-18
  Noncompliance noted acceptance of undersize socket welds &
  failure to follow procedure for documentation of audit
  findings
  CROMLEY.B R Region 2. Atlanta, Office of the Director
  HARDT, A R Region 2. Atlanta, Reactor Construction & Engineering
  Support Branch 80/08/05 App
- 8009230627 Final deficiency rept re design nomagraphs used in sizing & selection of hydramotor electrohydraulic actuators supplied by ITY General Controls Condition determined not reportable under 10CFR50 55(e) MCOAUGHY.J P Mississippi Power & Light Co 80/09/15 2pp
- --8007230642 Advises no other application determined for NH90 Series hydramotor actuators No further action planned per IE Bulletin 80-09 DALE, LF Mississippi Power & Light Co 80/07/28 ip
- S Reportable occurrences, LERs & related correspondence
- 8009100566 RO Status Rept 3 on 800129.hand switch CR-2940-US203E supplied by GE failed to operate Util AE & Bechtel Power Corp will evaluate switches Final rept to be submitted by 800918 MCSAUGHY. J P Mississippi Power & Light Co 80/06/18 2pp
- BOOK270284 Deficiency rept re radiographs supplied by contractors to NSSS vendors which failed to meet ASME code requirements Radiograph components analyzed Final rept & determination of reportability by Oct 1980 MCGAUGHYJJ P Mississippi Power & Light Co 80/06/20 2pp
- 8009100335 Deficiency rept re radiographs supplied by contractors to NSSB vandors which failed to meet ASME code requirements Radiograph components being analyzed Final rapt & determination of reportability by Oct 1980 MCGAUDHY.JP Mississippi Power & Light Co 80/06/20 2pp
- BOOTIO0436 Btatus Rept 2 ro electrical cable insulation damaged during pulling process Damaged cable would not affect plant safety Final rept & determination of reportability by BIOI31 MCGAUGHY, J. P Mississippi Pawer & Light Co 80/06/23 Rpp
- 8009100558 RO Status Rept 2 on 800313 electrical cable insulation damaged during pulling process Caused by poly-propulene pulling rope damaging cables Cables replaced Training session initiated Final rept to be submitted by 810131 MCGAUGHY, J. P. Mississippi Power & Light Co. 80/06/23 3pp
- 8009100519 Deficiency rept re Rosemount Model 510 DU trip/calibr units & Model \$152 pressure transmitters Final rept re trip units will be submitted by 801022 Final rept re pressure transmitters encl
  MCGAUGHY, J P Mississippi Power & Light Co 80/06/24 5pp
- 8009100592 Final deficiency rept re design nomographs used in siring & salection of General Controls hydromotor electrohydraulic actuators Forwards 800616 response to IE Bulletin 80-09 Final rept to be submitted by 800915 MCGAUGHY. J P Mississippi Power & Light Co 80/07/21 2pp
- B009040489 Status Rept 2 of deficiency re nonconforming calibr sycs provided by Computer Sciences Corp Final rept by 800822 MCGAUCHY, J.P. Hinnesota Power & Light Go. 80/07/22 1p
- 8007150062 Part 21 rept re power plant noncomplying valves Reanalysis 90% complete Corrective action involves design changes & review by customer engineering & field personnel High priority on valves which must meet increased loading NIEMAUS:P W William Powell Co 80/08/03 2pp

- 8009100303 Final deficiency rept me incorrect bolt torquing on HPCS pump Deficiency could have caused pump degradation by subsequent failure Pumps disassembled & retorqued to Field Disposition Instruction 32-42382 MCGAUGHY. J P Mississippi Power & Light Co 80/08/04 4pp
- 8009100347 Status rept re feedwater pipe bend below design min wall thickness Feedwater pipe supplier will perform evaluation of pipe & bending process Unit 1 pipe will be ultrasonically tested final rept will be submitted by 801211 MCGAUCHY. J P Mississippi Power & Light Co 80/08/04 2pp
- 8009020064 Interim deficiency rept re calibr svcs provided by Computer Sciences Corp Evaluation of investigation results not completed Final rept to be submitted by 800930 MCGAUCHY, J.P. Mississippi Power & Light Co. 80/08/21 2pp
- 8009080249 Second interim deficiency mept no incorrect pipe supplied by TC Pipe Bending Heavier wall of spool will not cause overstressed condition on pipe support sys in application Final rept expected by 801010 RCOAUGHY.J P Mississippi Power & Light Co 80/08/27 1p
- B0090B0376 Interim deficiency rept re fractured actuator to damper shaft couplings in dissel generator bldg bay A Final evaluation to be completed by B01219 MCGAUGHY/J P Mississippi Pawer & Light Co 80/08/29 Ip
- B009100486 Interim deficiency reptile installation of expansion anchors for conduit hangers, instrument process tubing & air supply supports w/o proper approval Procedures have been revised Final rept will be submitted by B01111 MCQAUOHY, J.P. Mississippi Power & Light Co. 80/09/03 lp
- BOO9190301 Interim deficiency rept to inadequate control of supplier drawing revision notice program investigative action resulted in issuance of 34 nonconformance documents Procedure controlling notices revised Final rept by 810122 MCGAUGHY, J.P. Mississippi Power & Light Co. 80/09/05 2pp
- 8007160571 Interim deficiency rept re possibility of inflactive insulation in annular space between reactor vessel & shield dislodging during LDCA & shearing reactor pressure vessel level sensing lines final rept will be forwarded on 810515 MCGAUGHY. J P Mississippi Power & Light Co 80070908 Opp
- 8009250417 Part 21 rept re defects in diesel generator control panels mfg by Intl Control & Switchgear Co Equipment is being repaired per FDDR JB1-940 under supervision of Morrison-Knudsen Co MCOAUGHY, J.P. Mississippi Power & Light Co 80/09/08 Spp
- BOO9260473 Interim deficiency rept re failure of QE subcontractor 1%SE to establish & implement approved QA program for electrical work performed under GE field deviation requests & instructions Results of GE reinspection expected by 8/0131 MCGAUCHY.J P Mississipp: Power & Light Co 80/09/08 2pp
- 8009160387 Second interim deficiency rept re defective leak detection equipment used to qualify Farr Co NPP-2 carbon filters for use in control room standby air units Filters have been returned to vendor final rept will be submitted by 801125 MCOAUCHY, J.P. Mississippi Power & Light Co 80/09/09 2pp
- 8009230556 Interim deficiency rept.per 10CFR50 55(e) & Part 21 re Hilti Fastening Sys.Inc.anchor bolt pull out strength Specific applications of one-inch diameter KWIK bolts are being investigated Final rept will be filed by 801104 MCOAUCHY, J.P. Mississippi Pawer & Light Co. 80/09/12 1p
- B009230471 Interim deficiency rept re discrepancies in design documentation for Power Generation Control Complex panels & associated delivered hardware No deficiencies discovered that would adversely affect safety of operations MCOAUGHY, J P Mississippi Power & Light Co 80/09/15 2pp
- 8009230627 Final deficiency rept re design nomographs used in sizing & selection of hydramotor electrohydraulic actuators supplied by ITT General Controls Condition determined not reportable under 100FR50 55(s) MCGAUGHY, J P Mississippi Power 5 Light Co 80/09/19 2pp
- --B009230642 Advises no other application determined for NH90 Beries hydramotor actuators No further action planned per IE Bulletin BO-09 DALE,L F Mississippi Power & Light Co B0/07/28 1p

- 8009230595 Interin deficiency rept re unqualified cable insulation repairs in 680-volt cable supplied by Rockbestos Investigation continuing involving safety implications of deficiency Final rept by 801216 MCGAUGHY, J.P. Mississippi Power & Light Co. 80/09/14 2pp
- 8009240438 Final deficiency rept re failure of handswitch CR2940-US203E in nonsafety related area of plant svc water sys. Investigation indicates that deficiency does not exist in safety related sys % is not reportable per 10CFRS0 55e MCGAUGHY. J P. Mississippi Power & Light Co. 80/09/16 2pp
- BOO92404BO Final deficiency rept re incorrect translation of weld requirements from design drawings to field sketches Erroneous welding direction corrected Future field sketches will include instruction to refer to design drawing MCGAUGHY, J.P. Mississippi Power & Light Co. 80/09/16 2pp
- DOCKET 50-417 GRAND GULF NUCLEAR STATION: UNIT 2
- A Application/construction stage documents  $\lambda$  correspondence
- 8009080080 Forwards draft NUREO-05%. Functional Criteria for Emergency Response Facilities ' Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0596 encl N/o NUREO EISENMUT.D C Division of Licensing 80/08/01 119pp
- 8009020413 Forwards Amend 42 to application for DL.consisting of responses to NRC questions re FSAR & assorted matters & including miscellaneous refinements of design info Revised P&IDs enc! MCGAUGHY.J P Mississippi Power & Light Co 80/08/29 1p
- --8009020418 Amend 42 to application for DL.consisting of responses to NRC questions re FSAR & assorted matters & including miscellaneous refinements of design info \* Mississippi Power & Light CO 80/08/29 2pp
- ---8009020423 Amend to FSAR, constituting Amend 42 to application for OL

  \* Mississippi Power & Light Co 80/08/29 300pp
- --8009020438 "Public Address Sys Riser Diagram.Unit 2 " \* Bechtel Corp 9645 78/12/21 1p
- 6009050352 Forwards "Environ Protection Program Preoperational Monitoring Rept" DALE.L F Mississippi Power & Light Co 60/08/29 ip
- --8009050354 "Environ Protection Program Preoperational Monitoring Rept " a Mississippi Power > Light Co 80/08/29 23pp
- 8009190099 Forwards request for add1 info resulting from FSAR review Outstanding items include assessment of degree of damage due to tornado generated missies & description of amplification factors used in plant design
  TEDESCO.R L Assistant Director for Licensing 80/08/29 17pp
- 8009110543 Notification of 600923-24 meetings w/util.Bechtel.GE & Savannah River Lab to review facility sys & discuss Reactor Sys Dranch questions MARTORE.J A Licensing Branch 3 80/09/04 2pp
- 8009230235 Notification of 800917 meeting w/util.QE & Savannah River Lab in Bethesda.MD to discuss applicant approach to HPCS Level 8 trip logic MARTORE,J A Licensing Branch 3 80/09/04 2pp
- BOO9150425 Expresses concern at meeting licensing schedule milestones, due to lack of NRC activity on second round questions Requests for additions should be made immediately or questions should be replaced by draft SER for branches LUTKEN.D C Mississippi Power & Light Co 80/09/08 2pp
- 8009150453 Endorses draft SER approach to formulating SER in comparing draft SER approach w/formal question method, approx 225 manhours saved in mechanical engineering using draft SER approach LUTKEN.D C Mississippi Power & Light Co 80/09/08 2pp
- 8009260531 Forwards request for addl info re FSAR FSAR should be amended to reflect responses TEDESCO.R L. Assistant Director for Licensing 80/09/09 9pp
- 8009230456 Confirms 800916 telcon re 800923 meeting to discuss resolution of GE supplied radiography problem at facilities MCGAUGHY, J P Mississippi Power & Light Co 80/09/17 ip

- B007300437 forwards response to NRC Questions 031 56.031 71 & revised responses to Questions 031 38.031 54.031 60 & 031 75 Responses will be incorporated into Oct 1980 amend to FSAR DALE/L F Mississippi Power & Light Co 80/09/22 102pp
- F Security, medical, emergency & fire protection plans
- 8009180002 Summary of 800813 meeting w/util & NUSAC in Bethesda. MD rephysical security plan MARTORE, J A Licensing Branch 3 80/09/09 3pp
- H General correspondence
- B009030504 Informs NRC of organizational changes which will be incorporated into Rovision 2 of operational QA manual scheduled for submittal in Dec 1980 REAVES.TE Mississippi Power 8 Light Co 80/08/27 ip
- K Utility Final Safety Analysis Report (FSAR) & amends
- BOO7150487 Forwards affidavit of svc on distribution of Amend 42 to FSAR DALE.L F Mississippi Power & Light Co GO/09/08 2pp
- Q Inspection reports. IE Bulletins & correspondence
- 8009090069 Forwards IE Bulletin 80-07, Suppl 1, "BWR Jet Fump Assembly Failure " No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/05/13
- 8009120135 Forwards IE Insp Repts 50-416/80-14 & 50-417/80-10 on 800603-04 No noncompliance noted MURPHY C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/21 2pp
- ---B007120141 IE Insp Repts 50-416/80-14 & 50-417/80-10 on 800603-06 No noncompliance noted Major areas inspected electrical equipment in-place storage & licensee actions on prior items WALTERS, D K Region 2, Atlanta, Office of the Director CONLON, T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/21 Sp
- 8009020218 Submits response to IE Bulletin 79-03A No SA-312 Type 304 series piping Used in any safety-related sys at greater than 85% design stress Requests extension until 800901 to complete review of bulletin DALE.L F Mississippi Power & Light Co 80/08/06 1p
- 8007020292 Requests extension until 800901 to complete investigation in response to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds"

  DALE, F Mississippi Power & Light Co 80/08/15 ip
- 8009030128 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Marcury-Metted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/15 to
- 8009160036 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE BWR Facilities " No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/19 in
- BO09230092 Forwards response to 1E Bulletin BO-08 Penetration closure details encl Radiography used for all full penetration butt wolds Final response expected by BO1015

  DALE, L.F. Mississippi Power & Light Co. BO/08/21 14pp
- 8009120080 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BUR" No written response trequired O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/22
- B009i60115 Forwards IE Circular 80-18, "IOCFR50 S9 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22

- 8009110681 Responds to IE Bulletin 80-16 Ten Rosemount, Inc Model 1151A transmitters scheduled to be used in safety-related applications were purchased Transmitters will be replaced before fuel loading DALE/L F Mississippi Power & Light Co 80/08/27 2pp
- 8009120260 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DQN 6008 Circuit Breakers" No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/08/27
- 8009240318 Ack receipt of 800730 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-416/80-07 & 50-417/80-07 Region 2, Atlanta, Fuel Facility & Materials Safety Reach 80/08/28 10
- --2009240331 Responds to NRC 800423 itr re vialations noted in IE Insp Repts 50-416/80-07 & 50-417/80-06 Corrective actions dredging operations will be completed by 800905 MCGAUGHY, J P Mississippi Power & Light Co 80/07/30 ip
- 8009080328 Responds to violation noted in IE Insp Repts 50-416/80-16 & 50-417/80-17 Corrective action constructor reinspected 513 ABME sociat welds to determine extent to which welds are undersized in safety-related applications MCGAUGHY, J.P. Mississippi Power & Light Co. 80/08/29 2pp
- BOOP290271 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/10 500
- B004300026 Act receipt of B00829 & 0902 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-416/80-16 & 50-417/80-11 MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/09/11 ip
- --8009300027 Responds to NRC 800805 ltr re violations noted in IE Insp Repts 50-416/80-16 & 50-417/80-11 Corrective actions constructor audit procedures revised to allow documentation of concerns found & corrected during audit MCGAUGHY.J P Mississippi Power & Light Co 80/07/02 2pp
- --8009300031 Forwards IE Insp Repts 50-416/80-16 & 50-417/80-11 on B00715-18 & notice of violation HURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/05 2pp
- --8009300034 Notice of violation from insp on 800715-18 \* Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/05 ip
- --BOD936004( IE Insp Repts 50-416/80-16 & 50-417/80-11 on 800715-18 Noncompliance noted acceptance of undersize socket welds & failure to follow procedure for documentation of audit findings CROMLEY, B R Region 2, Atlanta, Office of the Director HARDT.A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/05 App
- BOG9239627 Final deficiency rept re design nomographs used in siring & selection of hydramotor electrohydraulic actuators supplied by ITT General Controls Condition determined not reportable under 10CFRS 55(e) HCGAUGHY. J P Mississippi Power & Light Co 80/09/15 2pp
- --8009230642 Advisos no other application determined for NH70 Series hydramotor actuators No further action planned per IE Bulletin 80-09

  DALE, L F Mississippi Power & Light Co 80/07/28 Ip
- S Reportable occurrences. LERs & related correspondence
- 8009100566 RU Status Rept 3 on 800125, hand switch CR-2740-U8203E supplied by QE failed to operate Util AE & Bechtel Power Corp with evaluate switches Final rept to be submitted by 900718 MCGAUCHY, J.P. Mississippi Power & Light Co. 80/06/18 2pp
- 8009100335 Deficiency rept re radiographs supplied by contractors to NSSS vendors which failed to meet ASME code requirements Radiograph components being analyzed Final rept & determination of reportability by Oct 1780 MCGAUGHY.JP Mississippi Power & Light Co 80/06/20 2pp

- 8009100436 Status Rept 2 re electrical cable insulation damaged during pulling process Damaged cable would not affect plant safety Final rept & determination of reportability by 810131 MCGAUGHY, J.P. Mississippi Power & Light Co. 80706723 2pp
- 8009100558 RO Status Rept 2 on 800313, electrical cable insulation damaged during pulling process Caused by poly-propylene pulling rope damaging cables Cables replaced Training session initiated Final rept to be submitted by 810131 MCGAUGHY. J P Mississippi Power & Light Co 80/06/23 3pp
- 8009100519 Deficiency rept re Rosemount Model 510 DU trip/calibr units & Model 1152 pressure transmitters Final rept re trip units will be submitted by 801022 Final rept re pressure transmitters encl MCGAUGHY. J P Mississippi Power & Light Co 80/06/24 5pp
- 8009100592 Final deficiency rept re design nomographs used in sizing & selection of General Controls hydromotor electrohydraulic actuators Forwards 800615 response to IE Bulletin 80-09 Final rept to be submitted by 800915 MCGAUGHY.J F Mississippi Power & Light Co 80/07/21 2pp
- 8009040489 Status Rept 2 of deficiency re nonconforming calibr svcs provided by Computer Sciences Corp Final rept by 800822 MCGAUGHY, J P Minnesota Power & Light Co 80/07/22 ip
- 8007150052 Part 21 rept re power plant noncomplying valves Reanalysis 90% complete Corrective action involves design changes % review by customer ongineering & field personnel High priority on valves which must neet increased loading NIEHAUS, P W William Powell Co 80/08/03 2pp
- 8009100303 Final deficiency rept re incorrect bolt torquing on HPCS pump Deficiency could have caused pump degradation to subsequent failure Pumps disassembled & retorqued to Field Disposition Instruction 32-42382 MCQAUGHY, J.P. Mississippi Power & Light Co. 80/08/04 4pp
- 8009100347 Status rept re feedwater pipe bend below design min wall thickness Feedwater pipe supplier will perform evaluation of pipe & bending process Unit i pipe will be ultrasomically tested Final rept will be submitted by 801211 MCGAUGHY. J F Mississippi Power & Light Co 80/08/04 2pp
- 8007020064 Interim deficiency rept re calibr axes provided by Computer Stances Corp Evaluation of investigation results not completed Final rept to be submitted by 800730 MCGAUGHY, J.P. Mississippi Power & Light Co. 80/08/21 2pp
- 8009080249 Second interim deficiency rept re incorrect pipe supplied by TX Pipe Bending Heavier wall of spool will not cause overstressed condition on pipe support sys in application Final rept expected by 801010 MCGAUGHY.JP Mississippi Power & Light Co 80/08/29 ip
- BO090B0376 Intorim deficiency rept re fractured actuator to damper shaft couplings in diesel generator bldg bay A Final evaluation to be completed by B01219 MCGAUGHY, J.P. Mississippi Power & Light Co. 80/08/29 1p
- B009100486 Interim deficiency rept re installation of expansion anchors for conduit hangers, instrument process tubing & air supply supports w/o proper approval Procedures have been revised Final rept will be submitted by B01111 MCGAUGHY, J P Mississippi Power & Light Co 80/09/03 1p
- B009150301 Interim deficiency rept re inadequate control of supplier drawing revision notice program Investigative action resulted in issuance of 34 nonconformance documents Procedure controlling notices revised Final rept by 810122 MCGAUGHY, J P Mississippi Power & Light Co 80/09/05 2pp
- 8009160591 Interim deficiency rept re possibility of inflective insulation in annular space between reactor vessel & shield dislodging during LOCA & shearing reactor pressure vessel level sensing lines Final rept will be forwarded on 810515 MCGAUGHY. U.P. Mississippi Power & Light Co. 80/09/08 Spp.
- 8009250417 Part 21 rept re defects in diesel generator control panels mfg by Intl Control & Switchgear Co Equipment is being repaired per FDDR J81-940 under supervision of Morrison Knudsen Co MCGAUGHY. J P Mississippi Power & Light Co 80/09/08 3pp
- BO09280473 Interim deficiency rept re failure of GE subcontractor 1%SE to establish & implement approved OA program for electrical work performed under GE field deviation requests & instructions Results of GE refinspection expected by 810131 MCGAUGHY, J P Mississippi Power & Light Co 80/09/08 2pp

- 8009160387 Second interim deficiency rept re defective leak detection equipment used to qualify Farr Co NPP-2 carbon filters for use in control room standby air units Filters have been returned to vendor Final rept will be submitted by 801125 MCGAUGHY.J P Mississippi Power / Light Co 80/09/09 2pp
- 8009230956 Interim deficiency rept,per 10CFR50 55(e) & Part 21 re Hilts Fastening Sys.Inc.anchor bolt pull out strength Specific applications of one-inch diamoter KUHK bolts are being investigated Final rept bill be filed by 801104 MCGAUCHY.J F Mississipp: Power & Light Co 80/09/12 ip
- 8007230471 Interim deficiency rept re discrepancies in design documentation for Power Generation Control Complex panels b associated delivered hardware No deficiencies discovered that would adversely affect safety of operations MCGAUGHY, J P Mississippi Power & Light Co 80/09/15 2pp
- 8009230627 Final deficiency rept re design nomographs used in sizing & selection of hydramotor electrohydraulic actuators supplied by ITT General Controls Condition determined not reportable under 10CFR90 55(a) MCGAUGHY, J P Mississippi Pawer & Light Co E0/09/15 2pp
- --8009230642 Advises no other application determined for NH90 Series hydramotor actuators No further action planned per IE Bulletin 80-07 DALE/LF Mississippi Power & Light Co 80/07/28 ip
- 8007230595 Interim deficiency rept re unqualified cable insulation repairs in 680-volt cable supplied by Rockbestos investigation continuing involving safety implications of deficiency final rept by 801216 MCOAUGHY.J P Mississippi Power & Light Co 80/09/16 2pp
- 8009240438 Final deficiency rept re failure of handswitch CR2940-U8203E in honsafety related area of plant svc water sys.

  Investigation indicates that deficiency does not exist in safety related sys 1 is not reportable per 10CFR50 59s.

  MCOAUGHY, J. P. Mississippi Power & Light Co. 80/09/16 2pp.
- 8009240480 Final deficiency rept to incorrect translation of weld requirements from design drawings to field sketches Erroneous welding direction corrected Future field sketches will include instruction to refer to design drawing HCGAUGHY, J P Hississippi Power & Light Co 90/09/16 2pp
- DOCKET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3
  A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREJ-0696, "Functional Criteria for Energency Response Facilities "Corments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 and W/o NUREO EISENHUT, D G Division of Licensing 80/08/01 119pp
- 8004110523 Discusses interim actions required for plant operation pending final resolution of ATMS in B&N PWR4, NUREC-0460 ATMS emergency operating procedures must be submitted by 801130 TEDESCO, R L. Assistant Director for Licensing 80/08/27 3pp
- 8009300403 Responds to RL Tedesco 800827 ltr to NO Counsil requesting emergency operating procedure to be used for prompt recognition of ATMS event & mitigation Procedure is premature to emergency operating procedure developed COUNSIL.N G Northeast Utilities 80/09/18 fp
- G Inspection reports, IE Bulletins & correspondence
- 8009100113 Responds to IF Bulletin 79-09A. "Longitudinal Weld Defects in ASME 5A-312. Type 304 Stainless Steel Pipe " No SA-312 or A-312 welded pipe used or planned for use at greater than 85% of code allowable stress COUNSIL.N C Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/08/06 | Ip
- 8009030081 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Ketted Matrix Relays in Reactor Protective Sys of Operating Nuclear Fower Plants Besigned by C-E " Written response required ORIER, BH Region 1, Philadelphia, Office of the Director 80/09/15 ip
- 8009180017 Forwards IE Circular 80-18, "100FR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GRIER, B H Region I, Philadelphia, Office of the Director 80/08/22 Ip

- 8009120190 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Dover: 480 Volt Type K-6005 & K-DDN 6008 Circuit Breakers " No written response required GRIER, B H Region I. Philadelphia, Office of the Director 80/08/27 1p
- BO09230791 Forwards IE Circular BO-21, "Regulation of Refueling Crems" No written response required GRIER.B # Region 1, Philadelphia, Office of the Director BO/09/10 1p
- 8009240319 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls " No written response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/09/12 1p
- S Reportable occurrences. LERs & related correspondence
- 8007220325 Ack receipt of 800730 final deficiency rept re rock anchor design Rept will be reviewed & evaluated Final deficiency rept dtd 800730 re structural problems in auxiliary, turbine & svc bidgs encl CARLEON.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/03 ip
- --R009220330 Final defictorcy rept re structural problems in auxiliary, turbing & svc bldgs Auxiliary & svc bldg problems caused by incomplete calculations & models originally used Stone & Webster technical review program modified COUMBIL.W G Northeast Utilities 80/07/30 3pp
- DOCKET 50-424 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 1

  A Application/construction stage documents & correspondence
- BOO9080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT, D O Division of Licensing 80/08/01 119pp
- O Adjudicatory correspondence
- B009300375 Requests that Georgians Against Nuclear Energy petition be reconsidered in light of new data projecting excess capacity of 40-46% after plant completion Requests hearings re need for power & EIS suppl Atlanta Journal 200822 article enci. FLACK.G Myer, Gowman, Stroup & Flack 80/09/25 3pp
- G Inspection reports. IE Bulletins & correspondence
- 8009040635 Responds to IE Bulletin 80-05 Vol control,boric acid storage & boron recycle holdup,component cooling water surge,waste evaporator concentrates holdup & auxiliary component surge tanks are acceptable No further action planned DVITON,D Georgia Power Co 80/08/05 2pp
- 8009040637 Responds to IE Bulletin 79-03A No welded SA-312 or A-312 piping identified that exceeds pressure design stresses of B5% max allowable stress at design temp Westinghouse requested extension until 801001 to reply DUITON.D Georgia Power Co 80/08/05 2pp
- 8009030154 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Netted Matrix Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E "Written response required G'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/08/15
- 8009:60147 Forwards IE Circular 80~18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22
- 8009120311 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boyeri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers."

  No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/27
- 8009220133 Responds to IE Bulletín 80-16 no Rosemount Models 1151 or 1152 pressure transmitters or Rosemount Model 510DU trip units used for any safety-related sys or components DUTTON.D Georgia Power Co 80/09/02 ip

- BC09240389 Reponds to IE Bulletin 80-19 re +ailures of mercury-wetted matrix relays in reactor protective sys Relays in question are not used in reactor trip circuits Forty menhours expended for review DUFTCKID Georgia Power Co 80/09/02 2pp
- B009290282 Forwards IE Circular B0-21, "Regulation of Refueling Crews" No written response required D'REILLY, J.P. Region 2, Atlanta, Orfice of the Director B0/09/(0
- B009300110 Submits response to IE Bulletin 80-20 Westinghouse Type W-2 control switches are not used in safety-related applications DUTTOM.D Georgia Power Co B0/09/16 2pp
- S Reportable occurrences, LERs & related correspondence
- B009100416 Interim deficiency rept re dewatering & erosion of backfill Various actions enabling util submittal of final rept will be completed in 6 to 8 wks
  MILLSLE M Georgia Power Co 80/07/23 2pp
- 8009030489 Final deficiency rept re dewatering & erosion of backfill in power block area resulting from heavy rainfalls Repair work campleted Aug 1980 Bechtel consultant rept dtd 800815 & GA Power Co 800815 itr to Southern Co Sycs encl DUITON, D Georgia Power Co 80/08/29 100pp
- 800904045B Final deficiency rept re dewatering & erosion of backfill All erosion in power block backfill was satisfactorily repaired, w/oxception of minor deviations There is no detrimental effect on existing structures

  DUTTON, D Georgia Power Co 80/08/29 75pp
- 8009190493 Interim deficiency rept re defective bolting matis from Sauthern Bolt & Factener Co Util has placed on hold all matl received from supplier Final rept will be submitted by BOI115
  DUITON, D Georgia Power Co 80/09/12 2pp
- GOCKET 50-425 ALVIN W VOOTLE HUGLEAR PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- 8007080080 Forwards draft NUREG-0676, "Functional Criteria for Emergency Response Facilities " Corments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl W/a NUREG EISEN
- G Adjudicatory correspondence
- 8009300375 Requests that Ocorgians Against Nuclear Energy petition be reconsidered in light of new data projecting excess capacity of 40-46% after plant completion Requests hearings re need for power & ELS suppl Atlanta Journal 800822 article and FLACK, O Hyer, Dowman, Stroup & Flack 80/09/25 3pp
- G. Inspection reports. IE Bulletins & correspondence
- 8009040835 Responds to IE Bulletin 80-05 Vol control, boric acid storage & boron recycle holdup, component cooling water surge, waste evaporator concentrates holdup % auxiliary component surge tanks are acceptable. No further action planned DUTTON.D Georgia Power Co 80/08/05 2pp
- 8009040637 Responds to IE Bulletin 79-03A No welded SA-312 or A-312 piping identified that exceeds pressure design stresses of 85% max allowable stress at design temp Westinghouse requested extension until 801001 to reply DUTTON.D Georgia Power Co 80/08/05 2pp
- 8009030154 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Marcury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY. J P Region 2. Atlanta. Office of the Director 80/08/15 to
- 8009160147 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22

- B009120311 Forwards IE Info Notice 80-31, "Maloperation of Qould-Brown Bovers 480 Volt Type K-6005 ( K-DON 6008 Circuit Bleakers " No written response required O'REILLY, J P Region 2 Atlanta, Ortice of the Director B0/08/27 Ip
- 8007220133 Responds to IE Bulletin 80-14 no Rosemount Models 1151 or 1152 pressure transmitters or Rosemount Model 510DV trip units used for any safety-related say or components DUTTON.D Georgia Power Co 807.097/02 ip
- 8009240389 Reponds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Relays in question are not used in reactor trip circuits Forty manhours expended for review

  DUTTOU-D Georgia Power Co 80/09/02 2pp
- 8009290282 Forwards IE Circular 80-21. "Regulation of Refueling Crews" No written response required O'REILLY.J P Region 2. Atlanta Gifice of the Director 80/09/10 500
- 8009300110 Submits response to IE Bulletin 80-20 Nestinghouse Type N-2 control switches are not used in safety-related applications DUITON D Georgia Power Co 80/09/16 2pp
- S Reportable occurrences, LERs & related correspondence
- 8009100416 Interim deficiency rept re dewatering & erosion of backfill Various actions enabling otil submittal of final rept will be completed in & to 8 wks
  MILLS, L M Georgia Power Co 80/07/23 2pp
- 8009030489 Final deficiency rept re dewatering & erosion of backfill in power black area resulting from heavy rainfalls Repair work completed Aug 1980 Bechtel consultant rept dtd 800815 & GA Power Co 800815 itr to Southern Co Bycs encl DUTTON D Georgia Power Co 80/08/29 100pp
- 8007040458 Final deficiency rept re douatering & erosion of backfill All erosion in power block bactfill was satisfactorily repaired, w/erception of minor deviations There is no detrimental effect on eristing structures

  DUTTON, D Georgia Power Co 80/08/29 75pp
- 8009190493 Interim deficiency rept re defective bolting matts from Southern Bolt & Fastener Co Util has placed on Anid all matt received from supplier Final Fept will be submitted by 801115 DUITON-D Georgia Power Co 80/09/12 2pp

DOCKET 50-431 GERKAL, UNIT 1

- A Application/construction stage documents & correspondence
- 8009090631 Notification of cancellation of 800827 meeting w/DWR licensing review group to discuss concensus positions on TMI issues (NUREG-0694) WILSON.JN Assistant Director for Licensing 80/08/04 10pp
- DOCKET 90-433 UC-SANTA BARBARA RESEARCH REACTOR
  F Security, modical, energency & fire protection plans
- 8009110552 Responds to 800615 % 1102 ltrs requesting approval of physical mods & revised security plan, respectively Ltrs were treated as license amend request Forwards Amend 2 to License R-124 identifying security plan
  MILLER, H J Standardization & Special Projects Branch 80/08/28
- --8009110583 Amend 2 to License R-124 identifying currently approved security plan MILLER, J.R. Standardization & Special Projects Branch 80/08/28 2pp

DOCKET STN-50-437 FLOATING NUCLEAR PLANT

- A Application/construction stage documents & correspondence
- B009080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl N/O NUREO EISENHUT,D O Division of Licensing 80/08/01 119pp

- 8009100586 Requests that ichedule be established for completing review of application for afg license that NRC resources be committed for that purpose NRC should initiate review of util 830715 responses to NUREG-0560 MAGALP 8 Offshore Power Systems (subs of Westinghouse Electric Corp.) 80/09705 3pp
- Q Inspection reports: 1E Bulletins & correspondence
- 8007030181 Forwards Revision 1 to 1E Bulletin 80-19, "Failures of Nercury-Retted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J.P. Region 2, Atlanta, Orrice of the Director 80/08/15 to
- 8009160108 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required G'REILLY, J P Region 2 Atlanta, Office of the Director 80/08/22
- 8009120248 Forwards IF Info Notice 80-31, "Maloperation of Gould-Brown Bovers 489 Volt Type K-6008 & K-DON 6005 Circuit Breakers "
  No written response required O'RETELLY, J.P. Region 2, Atlanta, Office of the Director 80/08/27 to
- 8005290269 Forwards IE Circular 80-21. "Regulation of Refueling Crews"
  No written response required
  O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/09/10

#### DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREC-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREC-0696 encl N/A NUREG EISENHUT.D © Division of Licensing 80/08/01 119pp
- 9007150016 Forwards minutes of 800806 meeting w/TVA concerning independent code stress analysis in process at ETEC for decay heat removal sys
  BOU9NIA.A Operating Reactors Branch 1 80/08/25 19
- 109120619 forwards request for addl info in area of reactor physics, for review of CL application TEDESCO.R L Assistant Director for Licensing 80/08/26 App
- 009110529 Discusses interim actions required for plant operation pending final resolution of ATMS in BAW PMRs.NUREG-0460 ATMS emergency operating procedures must be submitted by 801120 TEDESCO.R L Assistant Director for Licensing 80/08/27 3pp
- 8009090522 Forwards final response to Question F 15 of NRC 800925 ltr Const of all portions of plant justified & CP should not be modified, suspended ar revoked CROSS J L Tennessee Valley Authority 80/09/04 9pp
- 8009150440 Forwards addl info on Topical Rept CEB-74-25.Revision i. "Pipe Rupture Analysis for Guard Pipe" re util penetration design & CEB-78-14.Revision i. "Analysis of Bellefonte Main Steam Guard During Postulated Pipe Rupture "MILLS, L N Tennessee Valley Authority 80/09/09 3pp
- --8009150468 "Analysis of Bellefonte Main Steam Guard Pipe During Postulated Pipe Rupture " LDERMIS.J D Tennessee Valley Authority CEB-78-14 RI 80/06/16
- i009300400 Forwards technical questions re implementation of interim policy on 10CFR50 か 51 MILLS,し M Tennessee Valley Authority 80/09/23 3pp

## Financial information

1009090543 Forwards Annual Financial Rept [979 CROSS.J L Tennessee Valley Authority 80/09/04 ip

- --8009090563 Annual Financial Rept 1979
  \* Tennessee Valley Authority 80/09/04 44pp
- G Inspection reports, IE Bulletins & correspondence
- 8009100063 Forwards IE Bulletin 80-18, "Maint of Adequate Kin Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/07/24 to
- 8009020214 Forwards response to IE Bulletin 79-03A No SA-312 & A-312, Type 300 series fusion welded pipe used or planned for use in safety-related sys at greater than 85% design stress errept Natts Bar Matl under investigation at Matts Bar Midlunder Midlunder investigation at Matts Bar Midlunder investigation in the Midlunder investigation in the
- 8009090802 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Use of matis still under investigation for sys supplied by NSSS vendor MILLS, L.B. Tennessee Valley Authority 80/08/05 2pp
- 8007150300 Forwards IE Investigation Repts 50-438/80-10 & 50-439/80-10 on 800604-05 No noncompliance noted LONO,F J Region 2, Atlanta, Office of the Director 80/08/05 Epp
- --8007150304 IE Investigation Repts 50-438/80-10 & 50-439/80-10 on 800604-05 No noncompliance noted Major area inspected util handling of "Michelson Rept" re potential defect of B&W NSSS & applicable 10CFR21 requirements WILLIAMSON,E L , LONG,F J Region 2, Atlanta, Office of the Director BROWNLEE,V L Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/08/05 61pp
- 8007020303 Forwards IE Insp Repts 50-327/80-24, 50-328/80-15, 50-370/80-20, 90-371/80-14, 50-438/80-13, 50-439/80-13, 50-589/80-11, 50-580/80-11, 50-580/80-11, 50-580/80-11, 50-580/80-11, 50-553/80-11, 80-554/80-10, 50-566/80-10 & 50-567/80-10 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/05 2pp
- --8009020312 Natice of violation from insp on 800707-11
  \* Region 2, Atlanta, Office of the Director 80/08/06 4p
- --8009020337 IE Insp Repts 50-327/80-24, 50-328/80-15, 50-390/80-20, 50-391/80-14, 50-438/80-13, 50-439/80-13, 50-518/80-11, 50-519/80-11, 50-553/80-11, 50-553/80-11, 50-553/80-11, 50-553/80-11, 50-553/80-11, 50-553/80-10, 50-564/80-10, 50-564/80-10 on 800707-11 BROWNLEE, V L. Region 2, Atlanta, Office of the Director 80/08/06 24pp
- B009030146 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/15 to
- 8009140193 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22 1p
- 8007070524 Responds to IE Insp Repts 50-438/80-12 & 50-439/80-12 Corrective actions piping will be inspected & cleaned in accordance w/MEU-SDP-605 Expeditious capping of stainless steel piping received w/o caps has been emphasized MILLS.J II Tennessea Valley Authority 80/08/27 8pp
- 8009120040 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover: 480 Volt Type K-6008 & K-DDN 6006 Circuit Browkers "
  No written response required
  O'REILLY, J P Region 2: Atlanta, Office of the Director 80/08/27
  1p
- 8009186087 Forwards response to IE Sulletin 80-16 Rosemount Models 1151 & 1152 pressure transmitters are not used or planned for use except at Bellefonte Nuclear Plant where use will be evaluated MILLS.L M Tennessev Valley Authority 80/08/29 2pp
- 8005240454 Forwards response to IE Builetin 80-16 re potential misapplication of Rosemount pressure transmitters No corrective action required due to results of evaluation that indicated impossibility of anomalous output MILLS.I. M Tennessee Valley Authority 80/08/29 2pp.

- 8009120679 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Relays identified are not used in facility forty manhours expended for review MTLLS.L M Tennessee Valley Authority 80/09/04 ip
- 8009260375 Forwards IE Circular 80-21, "Regulation of Refueling Crews"
  No written response required
  D'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/10
  5pp
- S Reportable occurrences, LERs & related correspondence
- 8009120293 Part 21 final rept re defective NAMCO Type 170-42100 & 170-4100 limit switches Vendor revised all drawings to show proper physical layout Util currently revising cable termination, schematic & conduit drawings to reflect changes MILLS,L M Tennessee Valley Authority 80/07/10 3pp
- B009100401 First interim deficiency rept re improperly tubed differential pressure indicators on air cleanup units Appropriate tubing reworking method being investigated Next written rept will be submitted by B01110 MILLS.L M Tennessee Valley Authority B0/08/29 2pp
- 8009160648 Part 21 final rept re improper insertion of buffer cards
  Caused by possible ambiguity in wording of product
  Instruction book Maint instructions reworded to require
  buffer module be removed before buffer card insertion
  MILLS,L M Tennessee Valley Authority 80/08/29 3pp
- 8009100494 First interim deficiency rept re RCS pump cases out of level Appropriate info transmitted to B&N for review Next rept will be submitted by 801128 MILLS.L M Tennessee Valley Authority 80/09/04 2pp
- 8009160353 Interim deficiency rept re tensile anchor capacities lower than design allowables Util completed design review of auxiliary & control bldgs Next written rept to be submitted by 819401 MILLS.L M Tennessee Valley Authority 80/09/08 ip
- 8009140353 Interim deficiency rept re tensile anchor capacities lower than design allowables Util completed design review of avrillary 3 control bldgs Next written rept to be submitted by 810401 MILLS.L M Tennessee Valley Authority 80/09/08 ip
- 8009:40377 First interim deficiency rept re 480-volt motor control ctr control transformer fuses per 10CFR50 55e & 10CFR21 Design of control circuits is being re-evaluated to determine cause of fuse operation & what changes are required MILLS.L M Tennessee Valley Authority 80/09/08 2pp
- 8009160437 Third interim deficiency rept re nanconformance in const QA audit Plans being finalized to ensure that training & retraining of certified welders & foremen will be completed Final rept will be submitted B01023
  MILLS,L M Tennessee Valley Authority 80/09/10 1p
- 8009290286 First interim deficiency rept re excessive vibration in essential raw cooling water pump/motor assembly while running Util contacted vendor & requested assistance correcting problem Next rept to be submitted approx 801202 MILLS, L M Tennessee Valley Authority 80/09/17 2pp
- 8009250240 First interim deficiency rept re 600-volt & 8 & 15 kV power cables, Types CPJ & CPSJ, which do not meet IEEE 383-1974 flame tast requirements Cause not stated Alternatives being evaluated Next rept will be submitted by 801210 MILLS.L M Tennessee Valley Authority 80/09/18 2pp
- 8009290346 First interim deficiency re deficient fillet welds Program being implemented to reinspect & correct all deficient welds Next rept due by 801215 MTLLB.L M Tennessee Vallay Authority 80/09/19 ip
- BO07300411 Third interim deficiency rept re ITT incorrect selection of activators for dampers Caused by erroneous selection charts existe presenting thrust delivery to damper assembly MILLS.L II Tennessee Valley Authority 80/09/23 2pp
- 8009300480 Second interim deficiency rept re failure of main steam lines because of main feedwater overfill Util & 8&H proceeding w/evaluation to incorporate mitigative instrumentation Next rept by 801229 MILLS,L M Tennessee Valley Authority 80/09/23 ip

- 8009300348 Final deficiency rept re Intl Telephone & Telegraph actuator for Ruskin dampers Actuators supplied at facility will deliver sufficient torque w/o spring mod & have been accepted for use
  MILLS.L M Tennessee Valley Authority 80/09/24 2pp
- 8007300427 Fourth interim deficiency mept re water found in rock anchor tendon head protective grease cams Ground water pumped from 23 holes in Unit 1 tendon gallery Floor pumps will be installed permanently in Units 1 & 2 galleries MILLS.L M Tennessee Valley Authority 80/07/24 3pp
- DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT, D G Division of Licensing 80/08/01 119pp
- 8009150016 Forwards minutes of 800806 meeting w/TVA concerning independent code stress analysis in process at ETEC for decay heat removal sys BDURNIA.A Operating Reactors Branch 1 80/08/25 1p
- --B009150018 Summary of 800806 meeting w/TVA at site re outstanding items concerning independent code stress analysis in process at ETEC for focay heat removal sys CAFPUCCI.A J Mechanical Engineering Branch B0/08/20 3pp
- 8009120619 Forwards request for addl info in area of reactor physics. for review of DL application TEDESCO,R L. Assistant Director for Licensing 90/09/26 App
- 8009110529 Discusses interim actions required for plant operation pending final resolution of ATMS in B&W PMRs.NUREG-0460 ATMS emergency operating procedures must be submitted by 801130 TEDESCO.R L Assistant Director for Licensing 80/08/27 3pp
- 8007070522 forwards final response to Question F 15 of NRC 800325 ltr Const of all portions of plant justified % CP should not be modified suspended or revoked CROSS.V L Yennessee Valley Authority 80/09/04 9pp
- 8007180460 Forwards additinfo on Topical Rept CEB-76-25. Revision 1, "Pipe Rupture Analysis for Guard Pipe" re util penetration design & CEB-78-14. Revision 1, "Analysis of Bellefonte Main Steam Guard During Postulated Pipe Rupture" HILLS.L M Tennessee Valley Authority 80/07/09 3pp
- --8009150468 "Analysis of Belleronte Main Steam Quard Pipe During Postulated Pipe Rupture " LOEWNS.J D Tennessee Valley Authority CEB-78-14 Rt 80/06/16
- 8009300400 Forwards technical questions re implementation of interim policy on 10GFR50 & 51 MILLS.L M Tennessee Valley Authority 80/09/23 3pp
- f Financial information
- 8009090543 Forwards Annual Financial Rept 1979 CROSS, J. L. Tennessee Valley Authority 80/09/04 ip
- --B007070563 Annual Financial Rept 1979 \* Tennessee Valley Authority B0/07/04 44pp
- @ Inspection reports. IE Bulletins & correspondence
- 8007100063 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/07/24 ip
- 8007020214 Forwards response to IC Bulletin 77-03A No SA-312 & A-312, Type 300 series fusion wolded pipe used or planned for use in safety-related sys at greater than 85% design stress accept Watts Bar Matl under investigation at Watts Bar MILLS.L M Tennessee Valley Authority 80/08/05 2pp

- 8009090502 Responds to IF Sulletin 79-02A, "Longitudinal Neid Defects in ASPE SA-312, Type 304 Stainless Steel Pipe" Use of matts still under investigation for sys supplied by MSSS vendor MILLS, L.M. Tennessee Valley Authority 80/08/05 2pp
- 8009150300 Forwards IE Investigation Repts 50-438/80-10 & 50-439/80-10 on 600404-05 No noncompliance noted LOV3.F J Region 2. Atlanta, Office of the Director 80/08/05 2nd
- --8009150304 IE Investigation Repts 50-438/80-10 & 50-439/80-10 on 800604-09 No noncompliance noted Major area inspected util handling of 'Michelson Rept' re potential defect of B&W NSSS & applicable IOCFR2: requirements
  WILLIAMSOME L. LONG.F.J. Region 2. Atlanta. Office of the Director BROWNLEE.V. Region 2. Atlanta. Resctor Construction & Engineering Support Branch 80/08/05 4jpp
- 8009020303 Forwards IE Insp. Repts 50-327/80-24, 50-328/80-15, 50-399/80-20, 50-391/80-14, 50-438/80-13, 50-439/80-13, 50-518/80-11, 50-519/80-11, 50-519/80-11, 50-553/80-11, 50-554/80-10, 50-553/80-11, 50-554/80-10, 50-564/80-10 b, 50-567/80-10 C, REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/06
- --8009020312 Notice of violation from insp on 800707-11
  \* Region 2, Atlanta, Office of the Director 80/08/06 4pp
- --8007020337 IE Insp Repts 50-327/80-24,50-328/80-15,50-370/80-20,50-34/80-14,50-439/80-13,50-439/80-13,50-518/80-11,50-519/80-11,50-51/80-11,50-554/80-10 50-52/80-11,50-554/80-10 50-56/80-10 & 50-56/80-10 on 800707-11 BROWNLEE.V L Region 2, Atlanta, Office of the Director 80/08/04 24pr
- 8009030146 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Hetted Matraz Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Hritten response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/15 in
- 8009tA0153 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22 ip
- 8009090524 Responds to IE Insp Repts 50-438/80-12 & 50-439/80-12 Corrective actions piping will be inspected & cleaned in accordance w/MEU-80P-605 Expeditious capping of stainless steel piping Feceived w/o caps has been emphasized MILLS.J M Tennessee Valley Authority 80/08/27 8pp
- 8009120340 Forwards 1E Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DDN 6008 Circuit Breakers" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/27 ip
- 8009180087 Forwards response to 18 Bulletin 80-16 Rosemount Models 1151 & 1152 pressure transmitters are not used or planned for use except at Bellefonte Nuclear Plant where use will be evaluated

  MILLS.L N Tennessee Valley Authority 80/08/29 2pp
- 8009240454 Forwards response to IE Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters No corrective action required due to results of evaluation that indicated impossibility of anomalous output MILLS.L M Tennessee Valley Authority 80/08/29 2pp
- 8009120679 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Relays identified are not used in facility Forty manhours expended for review MILLS.L K Tennessee Valley Authority 80/09/04 ip
- 8009260375 Forwards IE Circular 80-21. 'Regulation of Refueling Crows "
  No written response required
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/10
- S Reportable occurrences. LERs & related correspondence
- 8009120293 Part 21 final rept re defective NAMCO Type 170-42100 & 170-41100 limit switches Vendor revised all drawings to show proper physical layout Util currently revising cable termination schematic & conduit drawings to reflect changes MILLS.L B Tennessee Valley Authority 80/07/10 3pp

- 8009100401 First interim deficiency rept re improperly tubed dirferential pressure indicators on air cleanup units Apprapriate tubing reworking method being investigated Next unitten lept will be submitted by 801110 MILLS, L M Tennessee Valley Authority 80/08/29 2pp
- B00916064B Part 21 final rept re improper insertion of buffer cards.
  Caused by possible ambiguity in wording of product
  Instruction book Maint instructions reworded to require
  buffer module be removed before buffer card insertion
  MILLS.L M Tennessee Valley Authority 80/08/29 3PP
- 8009;60353 Interim deficienty rept re tensile anchor capacities lower than design allowables Util completed design review of auxiliary 5 control bldgs Next written rept to be submitted by 810401 MILLS, L.M. Tennessee Vailey Authority 80/09/08 1p
- 8009160377 First interim deficiency rept ra 480-valt matar control ct control transformer fuses per 10CFR50 55e & 10CFR21 Design of control circuits is being re-evaluated to determine cause of fuse operation & what changes are required MILLS, L K Tennessee Valley Authority 80/09/08 2pp
- 8009160437 Third interim deficiency rept re nonconformance in const d audit Plans being finalized to ensure that training & retraining of certified welders & foremen will be completed Final rept will be submitted 801023 MILLS,L M Tennessee Valley Authority 80/09/10 ip
- 8009250240 First interim deficiency rept re 600-volt & B & 15 kV powsicables, Types CPJ & CPSJ, which do not meet IEEE 383-1974 flams test requirements Cause not stated Alternatives being evaluated Next rept will be submitted by 801210 MILLS.L M Tennessee Valley Authority 80/09/18 2pp
- 8009290346 First interim deficiency re deficient fillet welds Program being implemented to reinspect & correct all deficient welds Next rept due by 801215 MILLS,L ii Tennessee Valley Authority 80/09/19 ip
- B009300411 Third interim deficiency rept re ITY incorrect selection of actuators for dampers Caused by erroneous selection charts misrepresenting thrust delivery to damper assembly MILLS, L M Tennessee Valley Authority B0/09/23 2pp.
- 8009300480 Second interim deficiency rept re failure of main steam lines because of main feedwater overfiil Util & B&W proceeding w/evaluation to incorporate mitigative instrumentation Next rept by 801227 MILLS.L IF Tennessee Valley Authority 80/09/23. 1p
- 8009300348 Final deficiency rept re Intl Telephone & Telegraph actuatom for Ruskin dampers Actuators supplied at facility will deliver sufficient torque w/o spring mod & have been accepted for use MILLS.L M Tennesseo Valley Authority 80/09/24 2pp
- 8009300427 Fourth interim deficiency rept re water found in rock anchor kendon head protective grease cans Ground water pumped from 23 holes in Unit I tendon gallery Floor pumps wilk be installed permanently in Units i & 2 galleries MILLS.L M Tennessee Valley Authority 80/09/24 3pp
- DOCKET 90-440 PERRY NUCLEAR POWER PLANT, UNIT 1

  A Application/construction stage documents & correspondence
- 800 9080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 enci N/o NUREG EISENHUT, D G Division of Licensing 80/08/01 119pp
- 8009190431 Forwards replacement Pages 13 & 15 to 800626 OL application Page 13 is changed to reflect revised ownership shares among Central Area Power Coordination Group members & Page 15 to include notarised signature of Page 15 to DAVIDSON, D R Cleveland Electric filluminating Co 80/09/12 2pp
- --8009170435 Replacement Pages 13 & 15 to 800626 DL application, reflecting revised ownership shares among Central Area Power Coordination Group members & providing notarized signature, respectively & Cleveland Electric Illuminating Co 80/09/12 2pp

- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8009190133 Forwards Perry 1 % 2 FSAR Includes schedule for further transmittals of add1 info DAVIDSON, D R Cleveland Electric Illuminating Co 80/09/12 2pp
- --800717013B Perry 1 & 2 FSAR
  \* Cleyeland Electric Illuminating Co 80/09/12 10000ap
- BOO9190141 Chapter 1 to Perry 1 & 2 FBAR, "Introduction & General
- # Cleveland Electric Illuminating Co BO/09/12 4COpp
- B009190144 App 1A to Perry 1 % 2 FSAR, "NUREG-0694, TM1-Related Requirements for New OLs"

  \* Cleveland Electric Illuminating Co 80/09/12 10pp
- 8009190149 Chapter 2 to Perry i & 2 FBAR. "Site Characteristics "
  4 Cleveland Electric Illuminating Co 80/09/12 1300pp
- 8009190156 App 2A to Perry 1 & 2 FSAR, "Annual Joint Frequency Distributions for Cleveland & Eris" « Cleveland Electric Illuminating Co 80/09/12 22pp

- 8009190162 App 2B to Perry 1 % 2 FSAR. "Monthly & Annual Frequency Distributions for Perry Nuclear Power Plant.10-Mile Winds" \* Cleveland Electric Illuminating Co 80/09/12 92pp
- 8009190165 App 2C to Perry 1 & 2 FSAR, "Monthly & Amnual Joint Frequency Distributions for Perry Nuclear Power Plant, Frequency Distributions for Perry Nuclear Power Plant, 40-Hile Winds " 4 Cleveland Electric Illuminating Co 80/09/12 82pp
- 8069190219 App 2D to Perry 1 % 2 FSAR, "Bedrock Deformation in Cooling Water Tunnel"

  \* Cleveland Electric Illuminating Co 80/09/12 125pp
- 8009190224 App A to Perry 1 & 2 FSAR, "Study of Microtracks Associated W/Faulting at Perry Nuclear Power Plant Site " Prepared Apr 1979 

   Cleveland Electric Illuminating Co SIMMONS, O Affiliation Uninown 80/09/12 2ipp
- 8009190234 App B to Parry 1 & 2 FSAR, "Study of Isotopic Composition of Water From Fault in Intake & Discharge Tunnels at Perry Nuclear Power Plant " Prepared Apr 1979

   Cleveland Electric Illuminating Co SIMMONS.0 Affiliation Uninown 80/09/12 App
- 8009190240 App C to Perry 1 & 2 FBAR, "Geophysical Methods" Prepared
- Apr 1979

  \* Cleveland Electric Illuminating Co \* Weston Geophysical Corp ПОрр
- 6009190244 App D to Perry 1 & 2 FBAR, "Evaluation of Local Seismicity Around Perry Nuclear Power Plant Site " Prepared 790921 \* Cleveland Electric Illuminating Co \* Weston Geophysical Corp 12200
- 8009190248 App E to Perry 1 & 2 FSAR, "Stress Measurements Hydrofracturing Technique.Perry Nuclear Power Plant " Prepared for LD Schultz of Gilbert Associates.Inc in Sept 1979
- Cleveland Electric Illuminating Co ROEGIERS, J C , MCLENNAN, J D ronto, Univ of, 80/09/12 121pp

- 8009190252 App F to Perry | & 2 FSAR, "Independent Reviews of Cooling Water Tunnel Faulting" \* Cleveland Electric Illuminating Co 80/09/12 1p
- --8007170256 App F to Perry 1 % 2 FSAR. "Bedrock Deformation in Water Intake Tunnel.Perry Nuclear Power Plant.Lake County.OH "Prepared on 790219 RG LaFleur of Rensselaer Polytechnical Insp 790130 ltr to Gilbert Associates, Inc uncl & Cleveland Electric Illuminating Co MURPHY.J Ohio Historical Society 80/07/12 10pp
- --8009190263 App F to Perry I & 2 FBAR, "Investigation of Cooling Water Tunnel Faults,Perry Nuclear Power Plant, DH " \* Cleveland Electric Illuminating Co. VOIGHT,B Pennsylvania State Univ 80/09/12 78pp
- 8009190270 App 0 to Perry 1 & 2 FSAR. "TX-Series Boring Logs " Covers period 780821-790619 \* Cleveland Electric Illuminating Co & Gilbert/Gammonwealth Cos 80/09/12 128pp

- B009190272 App H to Perry 1 / 2 FSAR. "Consulidation Tests on Cooling Water Tunnel Fault Gouge Samples " Tables transmitted on 790705
  - 790/05

    \* Cleveland Electric Illuminating Co WALLER.F 8 Woodward-Clyde
    Consultants, Inc. 80/09/12 lico
- 8009190279 App 2E to Perry 1 & 2 FSAR, "Soil & Rock Borangs" \* Cleveland Electric Illuminating Co 80/09/12 500pp
- 8009190285 Chapter 3 to Perry 1 % 2 FSAR. "Design of Structures. Components, Equipment % Sys "
   Cleveland Electric [lluminating Co 60/09/12 1450pp
- 8009190293 App 3A to Perry 1 & 2 FSAR, "Hydrodynamic Loads for Perry Nuclear Power Plant" \* Cleveland Electric Illuminating Co 80/09/12 19pp
- 8009190296 App 3B to Perry 1 & 2 FSAR, "Containment Loads" \* Cleveland Electric Illuminating Co B0/09/12 500pp
- 8009190303 Chapter 4 to Perry 1 & 2 FSAR, "Reactor"

  \* Cloveland Electric Illuminating Co 80/09/12 400pa
- 8009190305 App 4A to Perry i & 2 FSAR, "Results of Core Simulation
- Cleveland Electric Illuminating Co 80/09/12 84pp
- 8009190309 Chapter 5 to Perry 1 & 2 FS4R. "RCS & Connected Sys "
  \* Cleveland Electric Illuminating Co B0/09/12 350pp
- 8009190312 Chapter & to Perry 1 & 2 FSAR. "Engineered Safety Features" \* Cleveland Electric Illuminating Co 80/09/12 400pp 400pp
- B009190314 Chapter 7 to Perry 1 & 2 FSAR. "Instrumentation & Controls" \* Cleveland Electric Illuminating Co 80/09/12 350pp
- 8009190318 Chapter 9 to Perry 1 & 2 FSAR. "Electric Power" \* Cleveland Electric Illuminating Co 80/09/12 250pp
- B009190321 Chapter 9 to Perry [ & 2 FSAR. "Auxiliary Bys \* Cleveland Electric Illuminating Co B0/09/12 900
- 8009190329 Chapter 10 to Perry 1 & 2 FSAR, "Steam & Power Conversion
- \* Cleveland Electric Illuminating Co 80/09/12 100pp
- 8007170334 Chapter ii to Perry 1 & 2 FSAR, "Radwaste Mgt \* Cleveland Electric Illuminating Co 80/07/12 350
- 8009i90337 Chapter 12 to Perry 1 & 2 FSAR. "Radiation Protection" \* Cleveland Electric Illuminating Co 80/09/12 200pp
- 8007190342 App 12A to Perry ! & 2 FSAR, "Dffgas Sys Component Inventory
  - Cleveland Electric Illuminating Co 80/07/12 17pp
- 8009190371 Chapter 13 to Perry 1 t 2 FSAR. "Conduct of Operations " \* Cleveland Electric Illuminating Co 80/09/12 150pp
- 8009190404 App 13A to Perry 1 % 2 FSAR, "Emergency Plan \* Cieveland Electric Illuminating Co 80/09/12 250
- 8009190406 Chapter 14 to Perry 1 & 2 FSAR. "Initial Test Program" \* Cleveland Electric Illuminating Co 80/09/12 130pp
- 8009190407 Chapter iS to Perry 1 & 2 FSAR, "Accider \* Cleveland Electric Illuminating Co 80/09/12 "Accident Analyses " 400pg
- 8009190408 App 15A to Perry 1 & 2 FSAR, "Objectives solveland Electric Illuminating Co 80/09/12 200a p
- 8009190410 App 15B to Perry 1 & 2 FSAR, "BWR/6 Generic Rod Withdrawal
- Error Analysis " \* Claveland Electric Illuminating Co 80/09/12 100pp
- 8007170411 Chapter 16 to Perry 1 5 2 FSAR. "Tech Specs " To be filed at
  - Cleveland Electric Illuminating Co 80/09/12 ip
- B009190413 Chapter 17 to Perry 1 & 2 FSAR. "GA"

  \* Cleveland Electric Filuminating Co B0/09/12 100pp

- G Inspection reports, IE Bulletins & correspondence
- 6009040536 Forwards IE Sulletin 80-07, Suppl 1, "BNR Jet Pump Assembly Failure' Response required WEPPLER, J G Region 3 Chicago, Orrice of the Director 80/05/14
- 8009100118 Forwards IE Insp Rept 50-440/80-10 on 800625-27 & notice of violation FIDRELLI.0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/09 2pp
- --8009100120 Notice of violation from insp on 800525-27

  + Region 3. Chicago. Reactor Construction & Engineering Support
  Branch 80/07/07 2pp
- ~-8039100126 IE Insp Rept 50-440/80-10 on 800625-27 Noncompliance noted failure to neet uelding procedure requirements & failure to identify honconrorring pipe hanger uelds
  DANIELSON D H Region 3 Chicago, Reactor Construction ★
  Engineering Support Branch LEE E W K Region 3, Chicago, Office of the Director 80/07/07 5pp
- 8009030195 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required REPPLER. J G Region 3, Chicago. Office of the Director 80/08/11
- 8009100105 Ack receipt of 800730 ltr informing NRC of steps taten to correct violations noted in IE Insp Repts 50-440/80-09 & 50-441/80-09 FIO9ELLI.9 Region 3. Chicago, Reactor Construction & Engineering Support Branch 60/08/15 ip
- --8009100112 Forwards response to NRC 800626 ltr re violations noted in IE Insp Repts 50-440/80-09 & 50-441/80-07 Corrective actions ultrasonic thickness measurements obtained on recirculation notifles & IE builterns & circulars reviewed DAVIOSON DR Cleveland Electric Illuminating Co 80/07/30 Gpp
- E009160536 Responds to IE Bulletin 80-19 re failure of C-E mercuryuetted matrix relays in reactor protective sys Identified relays are not used in facility Three manhours expended on review DAVIDSON, D R Cleveland Electric Illuminating Co 80/08/18 (p
- EO09290525 Forwards IE Insp Repts 50-440/80-12 & 50-441/80-11 on E00701-31 No noncompliance noted FigReLLI. Region 3. Chicago. Reactor Construction & Engineering Support Branch E0/08/19 2pp
- --8009290526 IE Into Repts 50-440/80-12 % 50-441/80-11 on 800701-31 No noncompliance noted Major areas inspected licensee action on previous findings.concrete work activities & related quality records & NSSS equipment HUGHES-J. MILLIAMS.C C. Region 3. Chicago, Office of the Director 80/68/18 9pp
- PO9120041 Forwards Suppl 3 to IE Bulletin 80-17. "Failure of Control Pois to Insert During Scram at BUR" No written response equired EPPLER, J G Region 3. Chicago. Office of the Director 80/08/22
- 2/20/40
- 7170412 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations or Changes to Radwaste Treatment Sys " No written response equired REPPLER, J G Region 3, Chicago, Office of the Director 80/08/22.
- O9230069 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boyer: 480 Volt Type K-6005 & K-800 6008 Circuit Breakers"
  No written response required KEPPLER, J O Region 3, Chicago, Oifice of the Director 80/08/28
- 8/00/250230 Act receipt of 800813 ltr informing NRC of ateps taken to correct violations noted in IE insp Rept 50-440/80-10
  FIGRELLIAG Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/30 19

- 8009240095 Forwards IE Circular 80-21, "Regulation of Refueling Craws "
  No written response required
  KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/10
  io
- 8 Reportable occurrences. LERs & related correspondence
- 8009260018 Part 21 rept re nonconforming maths that were sent to util job site Negotiation is in process for replacement of nonconforming terminal blocks & return of certain units for rewiring u/conforming wire REPROBUET.R G Eaton Corp Cutler-Hammer Products Div BO/08/20 200
- 8009020067 Final deficiency rept re post-LDCA hydrogen analyzers
  During functional testing, pump failed due to panel outlet
  valves being closed when pump started Relief bypass valve
  installed across pump to stabilize temp Analyzer muds made
  DAVIDSON, D R Cleveland Electric Illuminating Co 80/08/26 4pp
- 8009120297 Part 21 rept re drive shaft of Reliance IE motor driving Dia-Vac diaphragm pumps which stopped in two places during in-house functional test of post-LOCA hydrogen analyzer. Deficiencies not reportable per 100FRSO 55(e) or Part 21, DAVIDSON.D R Cleveland Electric Illuminating CO 80/08/29 2p;
- 8009240229 Act receipt of 800826 final deficiency rept re post-LOCA hydrogen analyzers FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/08 ip
- 8007270071 Ack receipt of 800829 ltr re Part 21 rept on post-LOCA deuterium analysers Matter will be reviewed during imap despite util statement that matter is not reportable per 10CRR50 55(s). Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/09/08 ip
- DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NURES-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/s NUREG EISENHUT, D 0 Division of Licensing 80/08/01 119pp
- 8009190431 Forwards replacement Pages 13 t 15 to 800626 OL application Page 13 is changed to reflect revised ownership shares among Central Area Power Coordination Group members & Page 15 to include notarized signature
  DAVIDSON.D R Cleveland Electric Illuminating Co 80/09/12 2pp
- ---8009190435 Replacement Pages 13 & 15 to 800626 OL application reflecting revised ownership shares among Contral Area Power Coordination Oroup members & providing notarized signature, respectively a Claveland Electric Illuminating Co 80/09/12 2pp
- K Utility Final Bafety Analysis Report (FBAR) & amends
- 8009190133 Forwards Perry 1 & 2 FSAR Includes achedule for further transmittals of addl info DAVIDSON.D R Cleveland Electric Illuminating Co 80/09/12 2pp
- --8009190138 Perry 1 & 2 FSAR a Cleveland Electric Illuminating Co. 60/09/12 10000pp
- 9009190141 Chapter i to Perry i & 2 FSAR, "Introduction & General Description of Plant " \* Cleveland Electric Illuminating Co 80/09/12 400pp
- 8009190144 App iA to Parry 1 & 2 FSAR, "NUREG-0694, TMI-Related Requirements for New OLs " \* Cleveland Electric Illuminating Co 80/09/12 10pp
- 8009190149 Chapter 2 to Perry 1 & 2 FBAR, "Site Characteristics." + Cleveland Electric Illuminating Co 80/09/12 1300pp.
- 8007190156 App 2A to Perry 1 & 2 FSAR, "Annual Joint Frequency Distributions for Cleveland & Erle " \* Cleveland Electric Illuminating Co 80/09/12 22pp
- 9009190162 App 28 to Perry 1 & 2 FSAR, "Monthly & Annual Frequency Distributions for Perry Nuclear Power Plant,10-Mile Winds " \* Cleveland Electric Illuminating Co 80/09/12 82pp

- 8009190165 App 2C to Perry 1 & 2 FSAR, "Monthly & Annual Joint Frequency Distributions for Perry Nuclear Power Plant, 60-Mile Winds" \* Cleveland Electric Illuminating Co 80/09/12 82pp
- 6009190219 App 2D to Perry 1 & 2 FSAR, "Bedrock Deformation in Cooling Hater Tunnel " \* Clevaland Electric Illuminating Co 80/09/12 125pp
- 8009190224 App A to Perry 1 & 2 FSAR, "Study of Microcracks Associated W/Faulting at Perry Nuclear Power Plant Site " Prepared
- ### Apr 1979
  # Cleveland Electric Illuminating Co SIMMONS, G Affiliation
  Internal 80/09/12 21pp
- 8009190234 App B to Perry 1 & 2 FSAR, "Study of Isotopic Composition of Mater From Fault in Intake & Discharge Tunnels at Perry Nuclear Power Plant " Prepared Apr 1979 

  \* Cleveland Electric Illuminating Co SIMMONS. G Affiliation Unknown 80/09/12 App
- 8009190240 App C to Perry 1 & 2 FSAR, "Geophysical Methods " Prepared
- Apr 1979

  \* Cleveland Electric Illuminating Co \* Weston Geophysical Corp
- 8009190244 App D to Perry 1 & 2 FSAR. "Evaluation of Local Seismicity Around Perry Nuclear Power Plant Site " Prepared 770921 \* Cleveland Electric Illuminating Co \* Weston Geophysical Corp
- 6009190248 App E to Perry i & 2 FSAR, "Stress Measurements Hydrofracturing Technique, Perry Nuclear Power Plant " Frepared for LD Schultz of Gilbert Associates, Inc. in Sept

12200

- Cleveland Electric Illuminating Co ROEGIERS, J C , MCLENNAN, J D Toronto, Univ of,
- 8009190252 App F to Perry 1 & 2 FSAR, "Independent Reviews of Cooling Water Tunnel Faulting" Cleveland Electric Illuminating Co 80/09/12 1p
- --8009190255 App F to Perry 1 % 2 FSAR, "Bedrock Deformation in Water Intake Twinel.Perry Nuclear Power Plant, Lake County, OH " Prepared on 790219 RQ LaFleur of Rensselaer Polytechnical Insp 790130 1tr to Gibbert Associates, Inc encl
  - \* Cleveland Electric Illuminating Co MURPHY.J Ohio Historical Bociety 80/09/12 10pp
- --8009190263 App F to Perry 1 % 2 FBAR, "Investigation of Cooling Water Tunnel Faults.Perry Nuclear Power Plant.OH" # Cleveland Electric Illuminating Co VOIGHT.B Pennsylvania State Univ 80/09/12 78pp
- 8009190270 App G to Perry 1 & 2 FSAR, "TX-Series Boring Logs " Covers period 780821-790619 \* Cleveland Electric Illuminating Co \* Gilbert/Commonwealth Cos
- 80/09/12 12500
- 8009190272 App H to Perry 1 & 2 FSAR, "Consolidation Tests on Cooling Water Tunnel Fault Gouge Samples " Tables transmitted on 790708
- Cleveland Electric Illuminating Co WALLER:F 8 Woodward-Clydensultants, Inc. 80/09/12 lipp Consultants, Inc
- 8009190279 App 2E to Perry 1 & 2 FBAR, "Soil & Rock Borings" \* Cieveland Electric Illuminating Co 80/09/12 500pp
- 8009190285 Chapter 3 to Perry 1 & 2 FSAR, "Design of Structures, Components, Equipment & Sys "

  \* Cleveland Electric Illuminating Co 80/09/12 1490pp
- 8009190293 App 3A to Perry 1 & 2 FSAR, "Hydrodynamic Loads for Perry Nuclear Power Plant" # Cleveland Electric Illuminating Co 80/09/12 19pp
- 8009190296 App 38 to Perry 1 & 2 FSAR. "Containment Loads"

  Cleveland Electric Illuminating Co BO/09/12 500pp
- 8009190303 Chapter 4 to Perry 1 & 2 FBAR, "Reactor "

  \* Cleveland Electric Illuminating Co 80/09/12 400pp
- 8009190305 App 4A to Perry 1 & 2 FBAR, "Results of Core Simulation
- Studies "

  Cleveland Electric Illuminating Co 80/09/12 84pp
- 8009190309 Chapter 5 to Perry 1 & 2 FSAR, "RCS & Connected Sys " \* Cleveland Electric Illuminating Co 80/09/12 350pp

- 8009190312 Chapter 6 to Perry 1 & 2 FSAR, "Engineered Safety Features" \* Cleveland Electric Illuminating Co 80/09/12 600pp
- 8009190314 Chapter 7 to Perry 1 ! 2 FSAR. "Instrumentation & Controls " \* Cleveland Electric Illuminating Co 80/09/12 350pp
- S00919031B Chapter 8 to Perry 1 & 2 FSAR, "Electric Power" \* Cleveland Electric Illuminating Co 80/09/12 250pp
- 8009190321 Chapter 9 to Perry 1 & 2 FSAR, "Auxiliary Sys"

  \* Cleveland Electric Illuminating Co 80/09/12 900pp
- 8009190329 Chapter 10 to Perry 1 & 2 FSAR, "Steam & Power Conversion
  - Sys " \* Cleveland Electric Illuminating Co 80/09/12
- 8009190334 Chapter il to Perry 1 % 2 FSAR, "Radwaste Mgt" \* Cleveland Electric Filuminating Co 80/09/12 330pp
- 8009190337 Chapter 12 to Perry 1 t 2 FSAR, "Radiation Protection"
  \* Cleveland Electric Filominating Co 80/09/12 200pp
- 8009190342 App 12A to Perry 1 & 2 FSAR, "Offgas Sys Component Inventory Cleveland Electric [Huminating Co 80/09/12 17pp
- 8009190371 Chapter 13 to Perry 1 & 2 FSAR, "Conduct of Operations" 
  \* Cleveland Electric Itluminating Co 80/09/12 150pp
- 8007170404 App 13A to Perry 1 & 2 FSAR, "Emergency Plan
  \* Cleveland Electric Illuminating Co 80/09/12 250 250pp
- 8009190406 Chapter 14 to Perry 1 % 2 FSAR, "Initial Test Program"

  \* Cleveland Clectric Illuminating Co 80/09/12 130pp
- B009190407 Chapter 15 to Perry 1 & 2 FSAR, "Accident Analyses "
  \* Cleveland Electric Illuminating Co 80/09/12 400pp
- B00919040B App 15A to Perry 1 & 2 FSAR. "Objectives "
  \* Cleveland Electric Illuminating Co S0/09/12 20000
- 8009190410 App 158 to Perry 1 & 2 FBAR. "BWR/& Generic Rod Withdrawal
- Cleveland Electric Illuminating Co 80/09/12 100pp
- B009190411 Chapter 16 to Perry 1 & 2 FBAR. "Tech Specs " To be filed at Cleveland Electric Illuminating Co BO/09/12 ip
- B009190413 Chapter i7 to Perry 1 & 2 FSAR. "QA" \* Cleveland Electric Illuminating Co 80/09. 80/07/12
- Q Inspection reports, IE Bulletins & correspondence
- 8009040536 Forwards IE Bulletin 80-07. Guppl 1. "BWR Jet Pump Assembly Failure " Response required KEPPLER, J G Region 3. Chicago. Office of the Director 80/05/14
- 8007030195 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys o Operating Nuclear Power Plants Designed by C-E " Written response required Region 3, Chicago, Dffice of the Director 80/08/15
- 8007100105 Ack receipt of 800730 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/80-09 & correct violations noted in IE Insp Repts 50-440/80-09 & 50-441/80-09 FileRELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/15 tp
- --8009100112 Forwards response to NRC 8006R6 ltr re violations noted in IE Insp Repts 50-440/80-09 \$ 50-441/80-09 Corrective actions ultrasonic thickness measurements obtained on recirculation noticles & IE bulletins & circulars reviewed DAVIDSON,D R Cleveland Electric Illuminating Co 80/07/30 3pp
- 8009140636 Responds to IE Bulletin 80-19 re failure of C-E mercurywetted matrix relays in reactor protective sys Identified relays are not used in facility Three manhours expended on DAVIDSON, D.R. Cleveland Electric Miluminating Co. 80/08/18 1p

- 8009290525 Forwards IE Insp Repts 50-440/80-12 & 59-441/80-11 on 800701-31 No noncompliance noted fluxELLI.G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/19 2pp
- --8009290526 IE Insp Repts 50-440/80-12 & 50-441/80-11 on 800701-31 No noncompliance noted Major areas inspected licensee action on previous findings, concrete work activities & related quality records & NSSS equipment HUGHES J. WILLIAMS, C.C. Region 3. Chicago, Office of the Director 60/08/18 9pp
- 8009150469 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Stram Function & Nonessential Control Air at Certain GE BHR Facilities " No specific action or response requested XEPPLER. J O Region 3. Chicago, Office of the Director 80/08/20-12
- 8009120041 Forwards Suppl 3 to 1E Bulletin 80-17, "Failure of Control Rods to Insert During Scram at SWR " No written response required KEPPLER.J O Region 3. Chicago, Office of the Director 80/08/22
- 8009170412 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER. J O Region 3. Chicago, Office of the Director 80/08/22
- 80092300&B Forwards IE Info Notice 80-31, "Maluperation of Gould-Brown Boveri 480 Volt Type K-500S & K-DON 500S Circuit Breakers "
  No written response required KEPPLER. J G Region 3. Chicago, Office of the Director 80/08/28
- 8009240095 Forwards IE Circular 80-21. "Regulation of Refueling Crews" No written response required KEPPLER.J O Region 3. Chicago, Office of the Director 80/09/10
- S Reportable occurrences, LERs & related correspondence
- 8009020067 Final deficiency rept re post-LOCA hydrogen analyzers
  During functional testing, pump failed due to panel outlet
  valves being closed when pump started Relief bypass valve
  installed across pump to stabilize temp Analyzer mods made
  DAVIDSON D R Cleveland Electric Illuminating Co 80/08/26 4pp
- B009120297 Part 21 rept re drive shaft of Reliance IE motor driving Dia-Vac diaphragm pumps which stopped in two places during in-house functional test of post-LOCA hydrogen analyzer Deficiencies not reportable per 10CFR50 55(e) or Part 21 DAVIDSON D R Cleveland Electric Illuminating Co R0/08/29. 2pp
- 8009240227 Ack receipt of 800826 final deficiency rept re post-LOCA hydrogen analyzers FIGRELLI.Q Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/08 ip
- 8007270071 Ack receipt of 800829 ltr re Part 21 rept on post-LOCA deuterium analyzers Matter will be reviewed during insp despite util statement that matter is not reportable per 100FR50 55(e) FIORELLI.O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/09/08 Ip
- DOCKET 50-443 SEADROOK NUCLEAR STATION, UNIT 1

  A Application/construction stage documents & correspondence
- 8007050194 Advises that Class I fee is due for 790516 amend application DIGOS.R M License Fue Management Branch 80/08/13 1p.
- O Adjudicatory correspondence
- 8009020036 Expressos disagreement, on behalf of Beacoast Anti-Pollution League, w/J Handrie decision to participate in 2 206 petition Although petition is not same proceeding as CP, from which JM Hendrie was disqualified, case is factually related BACKUS, R A O'Reil, Backus, Spielman 80/08/25 4pp
- 3009100597 Responds to 800825 ltr on behalf of Beacoast Anti-Pollution League apposing Hendrie participation in NRC action on 10CFR2. 206 petition Review period expired 800822 "articipation in areas outside CP proceeding will continue ENURIE. J M Commission 80/09/08 fp.

- 8009120398 Order granting extension until 800926 for Commission to review ALAB-422 % relevant portions of ALAB-561 CHILK, S J Office of the Secretary of the Commission 80/09/10 to
- 8009300037 Order, CLI-80-33, remanding ALAB-422 to ASLAB for adding evidence on Chinnery methodology Parties must discuss relation between max ground accelerations & max effective ground acceleration of Ahearne dissenting opinion enci CHILK.S J Office of the Secretary of the Commission 80/09/23 Abb
- H General correspondence
- 8009290220 Responds to 800630 ltr QLs will not be issued until util develops & implements emergency plan for safe evacuation of surrounding area DENIGN.H R Office of Nuclear Reactor Regulation, Director 80/09/05 | 2pp
- @ Inspection reports. IE Bulletins & correspondence
- E009110478 Responds to IE Bulletin 79-03A Results of review of SA-312, Type 304 fusion-welded stainless steel pipe indicate sufficient min pipe vall thickness
  DEVINCENTIS. J Public Service Co of New Hampshire 80/08/04 ip
- 8009190089 Ack receipt of 800627 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-443/80-04 & 50-444/80-04 CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/14 1p
- --8009190074 Responds to NRC 800523 ltr re violations noted in 1E Insp Repts 50-443/80-04 & 50-444/80-04 Corrective actions weld repair process sheets revised to include sequences for visual examination DEVINCENTIS. J Public Service Co of New Hampshire 80/04/27
- --8009190100 Forwards IE Insp Repts 50-443/80-04 & 50-444/80-04 on 800914-17 & notice of violation CARLSDN.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/23 2pp
- --8009190104 Notice of violation from insp on 800414-17

  \* Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/21 ip
- --8009190106 IE Insp Repts 50-443/80-04 & 50-444/80-04 on 800414-17 Noncompliance noted failure to provide sequence of pips weld repairs to assure code compliance MCGAUGHY, R M Region 1, Philadelphia, Reactor Construction & Engineering Support Branch CERNE, A C, VARELA, A A Region 1, Philadelphia, Diffice of the Director 80/05/21 8pp
- 8009030047 forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Watted Matrix Relays in Reactor Protective 8ys of Operating Nuclear Pawer Plants Designed by C-E "Written response required GRIER.9 H Region 1. Philadelphia, Office of the Director 80/08/15 ip
- 8009180048 Forwards IE Circular 80-18. "10CFR50.59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/08/22 Ip
- 8009120211 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/08/27 ip
- 8009230776 Forwards 1E Circular 80-21, 'Regulation of Refueling Crews' No written response required GRIER, B H Region 1. Philadelphia, Office of the Director. 80/09/10 ip
- 8009240332 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls "No written response required ORIER.8 H Region 1. Philadelphia, Office of the Director. 80/097/12 | Ip

## S Reportable occurrences, LERs & related correspondence

- 8009030553 Interim deficiency rept re rod drop analysis Nestinghouse topical rept unavailable until late Sept 1980 Final rept espected by Dec 1980 DEVINCENTIS, B Public Service Co of New Hampshire 60/08/21 ip
- 8009090419 Final deficiency rept re use of invalid seismic amplified response spectra Short-term audit of seismic Category i sys a components complete Redesign of containment annular steel complete Beismic verification program will be completed DEVINCENTIS. J Public Service Co or New Hampshire 80/08/28 5
- e009160645 Part 21 final rept re use of invalid seismic amplified oversound rain at final rept to use of invalid seismic amplifices needense spectra in design of components supported by containment bldg annular steel framing Annular steel redesigned to increase rigidity SARSTEN. Of United Engineers & Constructors, Inc. (subs. of Raytheon Co.). 80/08/29. Spp.
- DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8009050194 Advises that Class I fee is due for 790516 amend application DIGOS.R M License Fee Management Branch 80/08/13 ip
- G Adjudicatory correspondence
- 8009020036 Expresses disagreement, on behalf of Seacoast Anti-Pollution League: w/J Hendrie decision to participate in 2 206
  petition Although petition is not same proceeding as CP, from
  which JM Hendrie was disqualified.case is factually related
  BACKUS:R A Q'Neil, Dackus, Spielman 80/08/25 4pp
- 8009100597 Responds to 800825 ltr on behalf of Seacoast Anti-Pollution Descriptions to Goodas for an operate of Seacoast Anti-League opposing Hendrie participation in NRC action on ICCFR2 206 petition Review period expired 800822 Participation in areas outside CP proceeding will continue HENDRIE, J H Commission 80/09/08 ip
- B00912039B Order granting extension until B00926 for Commission to review ALAB-422 & relevant portions of ALAB-561 CHILK.S J Office of the Secretary of the Commission B0/09/10
- 8009300037 Order, CLI-80-33 remanding ALAB-422 to ASLAB for additional evidence on Chinnery methodology Parties must discuss relation between max ground accelerations & max effective ground acceleration JF Ahearne dissenting opinion encl CHILK.S J Office of the Socretary of the Commission 80/09. 80/09/25
- H General correspondence
- 8009270220 Responds to 800630 ltr OLs will not be issued until util develops & implements emergency plan for safe evacuation of surrounding area DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 80/09/03
- O Inspection reports. IE Bulletins & correspondence
- 8009110478 Responds to IE Bulletin 79-03A Results of review of SA-312, Type 304 fusion-welded stainless steel pipe indicate sufficient min pipe wall thickness DEVINCENTIS. J Public Service Co of New Hampshire 80/08/04 ip
- 8009190089 Ack receipt of 800627 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-443/80-04 & 50-444/80-04 CARL80/IR T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/14 1p
- --8009190094 Responds to NRC 800523 ltr re violations noted in IE Insp Repts 50-443/80-04 & 50-444/80-04 Corrective actions, weld repair process sheets revised to include sequences for visual examination DEVINCENTIS, J Public Service Co of New Hampshire 80/06/27
- --8009170100 Forwards IE Insp Repts 50-443/80-04 & 50-444/80-04 on 800414-17 & notice of violation CARLSON,R T Region i, Philadelphia, Reactor Construction & Engineering Support Blanch 80/05/23 2pp

- --8009190104 Notice of violation from insp on 800414-17
  4 Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/21 1p
- --8007190106 IE Insp Repts 50-443/80-04 & 50-444/80-04 on 800414-17 Noncompliance noted failure to provide sequence of pipe weld repairs to assure code compliance MCGAUGHY.R N Region 1, Philadelphia, Reactor Construction & Engineering Support Branch CERNE.A C , VARELA.A A Region 1, Philadelphia, Office of the Director 80/05/21 8pp
- 8009030047 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Mercury-Retted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required
  GRIER. O H Region L. Philadelphia. Office or the Director
  80/08/15 ip
- 8009180048 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwasto Treatment Sys " No written response required required GRIER B H Region L. Philadelphia. Office of the Director 80/08/22 lp
- 8009120711 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6005 & K-DON 6008 Circuit Breakers" No written response required GRIER.8 H Region 1. Philadelphia, Office of the Director 80/08/27 Ip
- 8009230796 Forwards IE Circular 80-21, "Regulation of Refueling Crews " No written response required GRIER, D H Region 1. Philadelphia, Office of the Director 80/09/10 1p
- 8009240332 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Erclusive-Use Shipments of Radioactive Matls "No written response required GRIER, B H Region 1, Philadelphia Office of the Director 80/09/12 1p
- S Reportable occurrences, LERs & related correspondence
- 8009030853 Interim deficiency rept re rod drop analysis Hestinghouse topical rept unavailable until late Sept 1980 Final rept expected by Dec 1980
  DEVINCENTIS: 8 Public Service Co of New Hampshire 60/08/21 1p
- 8009090419 Final deficiency rept re use of invalid seismic amplified response spectra Short-term audit of seismic Category 1 sys & components complete Redesign of containment annular steek complete Geismic verification program will be completed DEVINGENTIS, J Public Service Co of New Hampshire 80/08/20 5 80/08/28 5np
- DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA . UNIT 1
- A Application/construction stage documents & correspondence
- 8009020219 "Initial Draft Safety Evaluation on Metallurgy Review " ANDERSON, W. E., ATTERIDGE, D. G., OLSON, N. J. Battelle Memorial Institute, Pacific Northwest Laboratory 80/07/31 60pp
- 8009080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREO EISENHUT
- B00903066D Forwards requests for add1 info re instrumentation & control sys in order to complete evaluation of CL applications FSAR should be amended to include requested info TEDESCO.R L Assistant Director for Licensing 80/08/14 10pp
- 8009020491 Forwards request for additinfo re confirmatory piping analysis
  TEDESCO.R L Assistant Director for Licensing 80/08/18 App
- 8009100004 Notification of 600826 meeting w/util in Bethesda,MD to discuss implementation of NUREO-0676 functional criteria BURHELL.S B Operating Reactors Branch 2 60/08/22 3pp
- 8009170404 Forwards request for add1 info re environ review for facility Environ rept should be amended to include Encl 1 TEDESCO.R L Assistant Director for Licensing 80/08/27 1700

- 8009160352 Responds to 800814 request for add1 info Answers to questions from Instrumentation & Controls Sys Branch & ANL consultants will be submitted by amend to FSAR on 801031 GARY.R J Texas Utilities Generating Co
- 8009220334 Forwards add1 electrical instrumentation % control drawings to assist in IARC review
  OARY,R J Texas Utilities Generating Co 80/09/12 2pp
- --8009220333 "Diesel Generator & Monitor Lights Schematic & Connection Diagram Sheet Issue Record & Index " Sheet 0 \* Gibbs & Hill, Inc. (subs. of Dravo Corp.) 2323 80/09/12
- --8009220344 "Diesel Generator 1D91.Start Circuit Channel I.Schematic Diagram " Sheet 4! # Gibbs & Hill, Inc. (subs. of Dravo Corp.) 2323 80/08/27 ip
- --8009220348 "Diesel Generator 1DC1.Start/Stop Circuit Channe? II. Schematic Diagram " Sheet 42 \* Gibbs & Hill, Inc. (subs. of Dravo Corp.) 2323 80/08/27
- --8009220357 "Diesel Generator 1002.Start Circuit Channel I.Schematic Diagram " Sheet 43 \* Gibbs & Hill, Inc (subs of Dravo Corp ) 2323 80/08/27 to
- ~-8009220368 "Diesel Generator 1802.Start/Stop Circuit Channel II. Schematic Diagram " Sheet 44 \* Gibbs & Hill, Inc. (subs. of Dravo Corp.) 2323 80/08/27 Ip
- --6009220380 "Diesel Generator 1DG1.Miscellaneous Circuits Sheet 1. Schematic Diagram " Sheet 45 + Gibbs S Hill. Inc. (subs. of Dravo Corp.) 2323 80/08/27
- --8009220383 "Diesel Generator IDG).M(scellaneous Circuits Sheet 2. Schematic Diagram " Sheet 46 \* Gibbs & Hill, Inc. (subs. of Dravo Corp.) 2323 80/08/27
- ---B0092203B5 "Diesel Generator 1002.Miscellaneous Circuits Sheet 1, Schematic Diagram " Sheet 47 4 Gibbs & Hill, Inc. (subs. of Dravo Corp.) 2323 80/08/27 1p
- --8009220387 "Diesel Generator 1092/Miscellaneous Circuits Sheet 2. Scheratic Diagram " Sheet 48 • Gibbs & Hill. Inc. (subs. of Dravo Corp.) 2323 80/08/27 ip
- --8009220392 "Diesel Generator IDG1.Miscellaneous Circuits Sheet 3, Schematic Diagram " Sheet 49 # Gibbs & Hill, Inc (subs of Dravo Corp.) 2323 80/08/27 ip
- ---8007220373 "Dieset Generator [D92,Miscel]aneous Circuits Sheet 3, Schematic Diagram " Sheet 50 Globs & Hill, Inc. (subs. of Drayo Corp.) 2323 80/08/27
- 8009230623 Forwards response to NRC 800927 request for add1 info re environ review & amended environ review pages List of encls only encl Encls sent to J Lohr in separate package WERNER.R Texas Utilities Bervicos. Inc 80/09/12 3pp
- C Utility Environmental Report (ER), amends & correspondence
- 8009300442 Confirms 800925 telcon Review toam will use unofficial amended environ rept until docteted Amend 1 received HARRIS, V A Argonne National Laboratory 80/09/26 ip
- F Security, medical, emergency & fire protection plans
- 8007020143 Invites participation in 800822 workshop in Atlanta, GA to solicit comment we proposed functional criteria for emergency response facilities in NUREC-0636 Discussion to include location, size 2 staffing of emergency ctrs SEYPRIT, K V Region 4. Dallas, Office of the Director 80/08/12 in

- Q Adjudicatory correspondence
- 8009090239 Response in opposition to applicant Aug 1980 first set of interrogatories Moves for protective order due to harassment a intimidation Requests unspecified extension of time to answer interragatories Certificate of Svc encl HAWIHORNE, S. GAY, G. M. Association of Community Organizations for Reform Now-Texas HAWIHORNE, S. West Texas Legal Services 80/09/28 4pp
- 8009020432 Forwards 800725 FR notice re procedural assistance change in adjudicatory licensing proceeding effective 800725 Policy does not apply to RL Fouke 800815 request for 790522 transcript which may be paid for & obtained from PDR RDTHSCHILD, M U Hearing Branch 1 80/08/29 Sep
- 8009150045 Offer of proof in support of intervenor 800701 motion for reconsideration of 8A/OC contention Urges admission to modify Contention 5 to include issues raised in encl insprepts Certificate of 8vc enci AAY.0 M Association of Community Organizations for Reform Now-Texas CAY.0 M West Texas Legal Services 80/08/29 App
- --8009190050 Forwards IE Insp Repts 50-445/73-02 & 50-446/73-02 on 731203-06 & notice of violation H3NARD,E M Atomic Energy Commission 74/01/07 2pp
- ---8009150051 Notice of violation from insp on 731203-04 \* Atomic Energy Commission 74/01/07 Spp
- ~~8009150055 IE Insp Repts 50-445/73-02 % 50-446/73-02 on 731203-06
  Noncompliance noted GA program did not comply w/App B & not
  carried out per written policies
  WARNICK, R F , PERANICH, M W , MADGEN, G L Atomic Energy Commission
  74/01/07, 20pp
- --B007150057 Forwards IE Insp Repts 50-445/74-01 & 50-446/74-01 on 740313-14 No noncompliance noted HOWARD.E M Atomic Energy Commission 74/03/19 3pp
- --B009150040 IE Insp Repts 50-445/74-01 & 50-446/74-01 on 740313-14 Certain items of previous QA concerns remain open re requirement of ANSI, distribution of drawings & vendor qualification for bidders' list WARNICK-R F , MADSEN, G L Atomic Energy Commission 74/03/18 14pp
- --8009180063 Forwards IE Insp Repts 50-445/74-02 & 50-446/74-02 on 740627-28 HONARD, E.H. Atomic Energy Commission 74/07/11 3pp
- --B009150066 IE Insp Repts 50-445/74-02 & 50-446/74-02 on 740627-28 Noncompliance noted QA policy & gracedures do not meet ANSI state CRESMAN, W A. STEWART, R C., MADSEN, O. L. Atomic Energy Commission 74/04/11 10pp
- ~-8009150068 Forwards IE Insp Repts 50-445/74-03 & 50-446/74-03 on 740718-19 Noncompliance noted HOWARD, E M Atomic Energy Commission 74/07/30 2pp
- ---B009190071 IE Insp Repts 50-445/74-03 & 50-446/74-03 on 740718-19
  Noncompliance noted lack of delineation of GA/GC interface
  activities & failure to detail responsibilities
  STEKART.R C . CROSSMAN.W A , MADSEN.O L Atomic Energy Commission
  74/07/30 7pp
- ---B009150113 Forwards IE Insp Repts 50-445/74-04 & 50-446/74-04 on 741107-0B Noncompliance noted HOMARD.E M Atomic Energy Commission 74/11/19 3pp
- --8009150079 IE Insp Repts 50-445/74-04 \$ 50-446/74-04 on 741107-08
  Noncompliance noted OC procedures not adequately controlled
  § QA program manual had no procedural control re changes,
  revision or addition
  STEWART, R C , DICKERSON, M W , MADSEN, G L Atomic Energy
  Commission 74/11/19 11pp
- --8009150116 Forwards IE Insp Repts 50-445/75-12 & 50-446/75-12 on 750911-12 No moncompliance noted MADSEN, 0 L Region 4, Dallas, Reactor Construction & Engineering Support Branch 75/10/01 2pp
- --8009150077 IE Insg Repts 90-445/75-12 & 50-446/75-12 on 750911-32 No noncompliance noted Areas inspected licensee action on previously identified enforcement matter STEWART,R C . HUBACEN,W G . CROSSMAN,W A Region 4, Dallas, Office of the Director 75/10/01 App

- --8009150420 Forwards IE Insp Repts 50-445/76-01 % 50-446/76-01 on 740107-09 Noncompliance noted MADSEN, G L Region 4, Dallas, Reactor Construction & Engineering Support Branch 76/01/29 2pp
- --80091500B0 IE Insp Repts 50-445/76-01 1 50-446/76-01 on 760107-09
  Noncompliance noted OC/GA surveillance conducted w/o
  prescribed procedures
  STEWART,R C , DICKERSON,M W Region 4, Dallas, Office of the
  Director CROSSMAN,W A Region 4, Dallas, Reactor Construction &
  Engineering Support Branch 76/01/27 14pp
- --8089150122 Forwards IE Insp Repts 50-445/76-08 & 50-446/76-08 on 760726-30 Noncompilance noted SEIDLE,W C Region 4. Dallas. Office of the Director 76/08/20
- --8009150083 IE Insp Repts 50-445/76-08 % 50-446/76-08 on 760724-30 Noncompliance noted QA manager duties % responsibilities encompassed engineering functions beyond QA program manual STEMART, R C. ROSENBERG.A B. CROSSMAN, W. A. Region 4, Dallas, Office of the Director 76/08/19 15pp
- ---B009150125 Forwards IE Insp Repts 50-445/77-02 & 50-446/77-02 on 770301-04 Noncompliance noted BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 77/03/23 2pp
- --9009150087 IE Insp Repts 50-445/77-02 & 50-446/77-02 on 770301-04 Nancompliance noted failure to meet GA procedure reporting requirement CROSSMAN.W A , STEWART, R C , TAPIA, J I Region 4, Dallas, Office of the Director 77/03/23 lipp
- --8007150127 Forwards IE Insp Repts 50-445/78-05 & 50-446/78-05 on 770321-24 & notice of violation SEIDLE,W C. Region 4. Dallas, Reactor Construction & Engineering Support Branch 78/04/06 2pp
- --8009150091 Notice of violation from insp on 780321-24
  Region 4, Dallas, Office of the Director 78/04 70/04/05 1p
- --8009150093 IE Insp Repts 90-445/78-05 & 50-446/78-05 on 780321-24 Noncompliance noted vendor quality documentation unavailable TAYLOR.R O . HALL.R E . CROSSMAN,W A Region 4. Dallas, Office of the Director 78/04/05 5pp
- --8009190133 Forwards IE Insp Repts 50-445/78-07 & 50-446/78-07 on 780411-21 & notice of violation SEIDLE.W C Region 4, Dallas, Office of the Director 78/05/10
- --B009150094 Notice of violation from insp on 780411-21
  \* Region 4, Dallas, Office of the Director 78/05 78/05/10 1g
- --8009180100 IE Insp Repts 50-445/78-07 t 50-446/78-07 on 780411-21 Noncompliance noted failure to meet PSAR commitments re concrete testing frequency TAYLOR.R 9, FOSTER.W E. WARD, J J Region 4, Pallas, Office of the Director 78/05/10 10pp
- --8009150136 Forwards IE Insp Repts 50-445/78-11 & 50-446/78-11 on 780620-23 & notice of violation BEIDLE, H C Region 4, Dallas, Office of the Director 78/06/30
- --8009150102 Notice of violation from insp on 780620-23
  \* Region 4, Dallas, Office of the Director 78/06, 70/06/29 1p
- --B009150105 IE Insp Repts 50-445/78-11 & 50-446/78-11 on 780620-23 Noncompliance noted failure to follow piping installation Noncomparame procedures TAYLOR,R © , CROSSMAN,W A Region 4, Dallas, Office of the Director 70/06/29 App
- BOO9100435 Motion for extension until 800915 to respond to applicants' first set of interrogatories Certificate of Svc encl MCCOLL.A C , MILLS T , HART, J L Citizens for Fair Utility Regulation BO/09/02 2pp
- 8009090579 Forwards original of verification encl w/answers to applicant 800903 first set of interrogations & requests to produce Affidavit encl Wo verification ELLIS.J Citizens Association for Gound Energy 80/09/03. 2pp

- 8009110034 Response to applicants' first set of interrogatories & requests for production of documents Moves for 60-day extension to respond to Interrogatories 55-65 re cost/benerit balance Objects to revaining questions ELLIS, J Citizens Association for Sound Energy 80/09/03 42
- --9009110044 Forwards affidavit re intervenor 200903 response to applicants' first set of interrogatories Certificate of Svcencl\_ ELLIS, J Citizens Association for Sound Energy 80/09/03 3pp
- 8009080037 Response stating no objection to Citizens Association for Sound Energy 800820 motion for extension until 800903 to reply to applicants' first set of interrogatories Certificate of Svc encl ROTHSCHILD.M U Hearing Branch 1 80/09/04 3pp
- 8009110048 Response to Citizens Association for Sound Energy request for production of documents contained in 800707 first set of interrogatories Matls will be available for insp & copying upon arrangement w/HC Schmidt Certificate of Svc encl REYNOLDS,N S . HORIN,W A Texas Utilities Generating Co REYNOLOS,N S . Debevoise & Liberman 80/09/08 5pp
- 8009110369 Confirms conversation re objection & intent not to respond to util 800825 interrogatories & document requests Factual discovery closed since 800314 Interrogatories are ill-timed as efforts have been made to encourage settlement STAHL, D.M. Isham, Lincoln & Beate 80/09/08 1p
- 8009110781 Response stating no objection to Citizens for Fair Util Regulation 800702 request for extension until 800915 to respond to applicants' 800813 first set of interrogatories & request for production of documents W/Certificate of Byc REYNOLDS.N S , HORIN.N A Texas Utilities Generating Co REYNOLDS.N S Debevoise & Liberman 80/09/09 3pp
- 8009110794 Response stating no objection to Citizens for Fair Util Regulation 800902 motion for extension until 800915 to respond to applicants' first sets of interrogatories & request for production of documents Certificate of Evc encl ROTHSCHILD.M U Hearing Branch 2 80/09/11 3pp
- BOD9170361 Submits status of ropt on settlement negotiations on behalf of TX-LA Electric Cooperative of TX Inc No unresolved issues exist at present Certificate of Svc encl
  BURCHETTERW M Northcutt Ely BO/09/11 3pp
- 8009170141 Motion to compel TX Association of Community Organizations for Reform Now response to applicants interrogatories Opposes intervenor motions for protective order & for addlitime W/Certificate of Svc Related correspondence REYNOLDS,N S. HORIN.W A. Texas Utilities Generating Co. REYNOLDS,N S. Debevoise & Liberman. 80/09/12 16pp
- 8009240005 Response to applicants' first set of interrogatories & vo.covvou neaponse to applicants' first set of interrogatories request for production of documents Objects to majority of questions on basis of ambiguity Certificate of Svc encl FOUVE, R L , HART. J L , KCCOLL, A C Citisens for Fair Utility Regulation 80/09/15 17pp
- 8009230005 Motion to compel Citizens Associatin for Sound Energy 109230005 Motion to compel Citizens Associatin for Sound Ene response to first set of interrogatories Opposes motion for 60-day extension re Interrogatories 55,57,59,61,62 & 64 Responds to request for clarification W/Certificate of Syc REYNOLDS,N S , HORIN,W A Texas Utilities Generating Co REYNOLDS,N S Debevoise & Liberman 80/09/18 22pp
- 8009260008 Motion for protective order due to applicants' 800813 voluminous first set of interrogatories & request for production of documents consisting of 167 basic demands Certificate of Svc encil HART, J. MILLS, T., MCCOLL, A. Citizens for Fair Utility Regulation 80/09/18 7pp
- H General correspondence
- 800902010B Responds to 80080B ltr Advises that heat-induced illness being watched closely at plants Const has progressed to point that most work being done indoors Applicants have taken steps to improve working conditions by adding fans DENION. H.R. Office of Nuclear Reactor Regulation, Director
- ---8009020112 Informs that TX experiencing severe heat wave Requests that const on nuclear reactors be halted until temp at normal level for season Humanly impossible for const workers to do excellent work required LEVINE.H R Affiliation Unknown 80/07/08 1p

#### M Antitrust correspondence

- 8009040196 Response to applicants.Central & South West Corp & City of Austin T/ abjections to TY Border Cooperative petition to intervene Asserts interests under LBP-74-13 Urges full party participation U/Certificate of Svc O'Nell.R A Southwest Texas Electric Cooperative O'NEIL.R A Miller,Balis & O'Neil 80/07/31 16pp
- B009020282 Requests that info be provided to all parties re wheeling rate development per 800826 discussions Discusses principles to be considered to smaller util participation in facility ownership SPIEGEL, G Spiegel & McDiarmid SPIEGEL, G Brownsville, TX 80/08/28 4pp
- 8009030721 Advises that appropriate steps have been taken to insure svo of status repts % pleadings CHANANIA.F D Antitrust Division 80/08/29 Lp
- 8007040289 Joint motion for partial revision of ASLB 800813 order re procedural schedule Suggests 800712 for settlement status repts.800715 for prehearing conference & 801112 for evidentiary hearing connencement Certificate of Svc encl CHANNATAF D Antitust Division FLYNN,P 0 Houston Lighting & Power Co FABRIKANT,R Justice.Dept of 80/08/29 7pp
- 80071002bi Designates WA Russel) of UA Russel & Associates as expert engineering witness which DDJ may call at trial of facility licensing proceeding HCHILLERUN H Justice Dept of 80/07/03 1p
- 8009110792 Order revising procedural schedule set in ASLB 800813 order Settlement status rept shall be submitted on 800912, prehearing conference shall commence on 800915. trial briefs on 801008 \$ 22 & evidentiary hearing on 801112 MILLER, M.E. Atomic Safety and Licensing Board Panet 80/09/08
- 8009150417 Motion to compel Central Power & Light response to 800825 interrogatories Objection erroneous due to necessity to thou full scope of take-over plans W/DM Stohl 800908 ltr. excerpts of util corrected discovery & Certificate of Svc 8PIEGEL, 0, POIRIER, M.R. Brownsville, TX SPIEGEL, 0 Spiegel & McDiarmid 80/09/11 23pp
- 9009160275 Notice of taking WP Sayles & T Russell of CP&L 800923 & 24 depositions Examination will address possible purchase of Brownsyille electric util sys & related studies & issuance of bonds Certificate of Svc enci PDIRIER.N & Brownsyille.TX PDIRIER.N & Spiegel & McDiarmid 80/09/12 7pp
- )09170188 Settlement status rept Author approval of terms of stipulated licensing conditions not yet given No position on issues & procedures presented Certificate of SVC encl JCHM, DF, HUNTER, M South Teias Electric Cooperative JCHN, DF Medinaelectric Cooperative, Inc. 80/09/12 Spp
- 8009170359 Settlement status rept per ASLB 800813 order Agreement reached by util.NRC & DOJ which will dispose of all Comanche Peak issues when approved by ASLB Encl stipulation will insure OL would not violate antitrust laws SAMPLES.N D . KNOTTS.J B Texas Utilities Generating Co SAMPLES.N D Worsham, Forsythe & Sampels 80/09/12 2pp
- --BOD7170364 Stipulation incorporating encl license conditions Licensed denies past conduct w/o conditions violated antitrust laws Stipulation I conditions on not constitute admissions of violations CHANANIA,F D Antitrust Division \* Justice,Dept of BURCHETTE,W H Texas-Louisiana Electric Cooperative,Inc BO/07/12 10pp
- --8009170369 Stipulation incorporating encl license conditions Licensee denies past conduct w/o conditions violated antitrust laws Stipulation & conditions do not constitute admissions of violations W/o conditions Certificate of Syc encl STAHL.D Central & South West Corp KNOTTS, J B Texas Utilities Generating Co STAHL.D Isham, Lincoln & Beale 80/09/12 App
  - 9170229 Fourth settlement status rept Stipulations w/applicants mbodying two sets of license conditions accomplished Final sation re need for hearing will be submitted after amination of conditions by parties W/Certificate of Svc (ANANIA:F D Antitrust Division 80/09/14 7pp
  - 109170232 Stipulation incorporating new license conditions w/o admission of violation to antitrust laws CHANNIA,F D Antitrust Division FABRIKANT,R Justice.Dept of BURCHETTE,W H Texas-Louisiana Electric Cooperative, Inc 90/09/12 3pp

- --B009170235 Stipulation incorporating entl license conditions w/o admission of violation to antitrust laws STAHL.D M Central & South West Corp BOUKNIGHT.J A Teras Utilities Generating Co B0/09/12 17pp
- ---B009170239 Stipulation incorporating encl license condition w/o admission of violation to antitrust laws FABRIKANI,R Justice. Dept of CHANANIA.F D Antitrust Division STAHL.D M Central & South West Corp 80/09/12 20pp
- 8009160157 Settlement status rept per ASLB 800913 order Endorses encl stapulation re license condutions reached by DOJ.NRC.FERC & Houston Lighting & Power Resolves concerns evidencing intent to litigate DOE endorsed settlement entirely in FERC case COPELAND.J O Houston Lighting & Power Co COPELAND.J G Baker & Botts 80/09/15 2pp
- --8009160160 Stipulation incorporating license conditions Licensee past or planned action w/o conditions not inconsistent w/ antitrust laws Conditions do not consistivute admission or violations Certificate of Svc encl FABRIKANT, R Justice Dept of CHANANIA, F D Antitrust Division STAHL, D Houston Lighting & Power Co 80/09/15 17pp
- 8009160162 Settlement status rept per ASLB 80813 order Requests unspecified extension to receive 2 review new arguments & to determine 2 submit unresolved issues License conditions 2 settlement re FERC not yet received W/Certificate of Svc POIRIER. M R Brownsville.TX POIRIER.M R Spiegel & McDiarmid 80/09/15 9pp
- 8009170177 Settlement status rept Suggests approval of stipulated license conditions to maintain situation consistent w/ antitrust laws FERC & SEC approval of dc interconnections necessary for settlement execution Certificate of Svc encl STAHL, D M Central & South West Corp STAHL, D M Isham, Lincoln & Beals 80/07/15 12pp
- 8009180460 Suppl status rept per ASLB 800813 order DOJ reached agreement w/parties in Comanche Peak proceedings re proposed set of license conditions Agreement reached w/applicant in South TX proceeding Certificate of Svc encl MCMILLENEN H Justice Dept of 80/09/15 7pp
- 8009250028 Order granting extension until 800929 for Commission to review ALAB-608 CHILK B J Office of the Secretary of the Commission 80/09/22
- 8009260318 Motion for one-day extension to file comments on proposed settlement conditions Last minute consultations & discussions needed Certificate of Svc encl POIRIER.M R Drownsville,TX POIRIER.M R Spiegel & McDiarmid 80/09/24 6pp
- B009300035 Comments on proposed settlements per ASLB 800915 directive Proposed license conditions will serve to preclude or limit consideration of competitive implications of dc ties by FERC Certificate of 8vc encl O'NEIL.R A Southwest Texas Electric Cooperative O'NEIL,R A Miller,Balis & O'Neil 80/09/24 12pp
- 8009300488 Confirms that JR Choukas-Bradley was authorized to express position of Miller, Salis & O'Neil, P C on behalf of TX Border Cooperatives at 800918 status hearing re leave to interviene out of time O'NEIL, R A Miller, Balis & O'Neil 80/09/24 2pp
- ~-8009300474 Comments of TX Border Gooperatives on proposed settlements of NRC & DOJ re licensing proceedings Certificate of Syc enc!

  O'NEIL,R A Miller,Balis & O'Neil O'NEIL,R A Texas Border Cooperatives 80/09/24 10pp
- 8009300013 Motion in opposition to 800912 proposed license conditions due to failure to address crucial issues re effects of ac & dc interconnections Urges further proceedings to cure inconsistency w/antitrust laws Certificate of Svc encl SPIEGEL.G., JABLON.R A., ROTH.A.J. Brownsville,TX 80/09/25
- 8009300326 Order granting extension until 800925 for all parties to comment on 800915 stipulation & licensing conditions WOLFE.S J. Atomic Safety and Licensing Board Panel 80/09/25 ip
- N Antitrust hearing transcripts
- 8009190764 Transcript of 800915 prehearing conference in Bethesda, MD Pp 1078-1138 \* Atomic Safety and Licensing Board Panel 80/09/15 64PP

# Q Inspection reports. IE Bulletins & correspondence

- 8009180095 Discusses IE Insp Repts 50-445/80-15 & 50-446/80-15 on 800406 & 09 & forwards notice of violation SEIDLE-W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/06/23 2pp
- --B009180100 Notice of violation from insp on 800606 & 09 Noncompliance noted failure to establish QA program for Class 5 pipe support sys « Region 4, Dallas: Office of the Director 80/06/23 ipp
- 8009170420 Ack receipt of IE Insp Repts 50-445/80-11 & 50-446/80-11 No proprietary info CARY,R J Texas Utilities Generating Co 80/07/02 ip
- 8009150012 Responds to IE Bulletin 80-05 re vacuum condition resulting in damage to holdup or low pressure tanks Tanks have adequate protection against vacuum conditions Design of holdup tanks compatible w/overflow requirements GARY, R J Texas Utilities Generating Co 80/07/11 3pp
- 8009150337 Forwards IE Insp Repts 50-445/80-15 & 59-446/80-15 during June 1980 & notice of violation SEIDLE, W.C. Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/07/23 2pp
- --8009150363 Notice of violation from insp during June 1980 \* Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/07/22 1p
- --B009150367 IE Insp Repts 50-449/80-15 % 50-446/80-15 during June 1980 Nancompliance noted failure to establish QA program for Class 5 pipe support sys % failure to follow const pracedures required by drawings TAYLOR.R 6 . CROSSMAN.W A Region 4. Dallas. Office of the Director 80/07/22 &pp
- 8009180457 Submits response to IE Bulletin 79-03A SA-312 Type 304 & 316 fusion weld pipe has been used in safety-related sys which may be subj to design stresses in excess of 85% of code allowable stresses List of subj pipes encl CARY.R J Teras Utilities Generating Co 80/07/28 App
- 8009100269 Forwards IE Insp Repts 50-445/80-17 & 50-446/80-17 on 800714-18 & notice of violation SEIDLE W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 8D/07/31 2pp
- --8009100273 Notice of violation from insp on 800714-18 \* Region 4, Dallas, Office of the Director 80/07/31 1p
- --80091G0279 IE Insp Repts 50-445/80-17 & 50-446/80-17 on 800714-18
  Noncompliance noted failure to use proper weld preparation
  counterbore transition tapers
  HALL,R E , GILBERT L D Region 4, Dallas, Reactor Construction &
  Engineering Support Branch MARTIN.L E Region 4, Dallas, Office
  of the Director 80/07/31 Spp
- 8007290229 Responds to 800717 ltr Extends due date for response to notice of violation identified in IE Insp Repts 50-445/80-15 & 50-445/80-15 to 800820 SEIDLE,N C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/07/31 1p
- --8009290571 Requests extension until 800820 to determine scape of problem identified in IE Insp Repts 50-445/80-15 & 50-446/80-15 GARY,R J Texas Utilities Generating Co 80/07/17 ip
- 8009300055 Submits response to IF Bulletin 80-16 Rosemount Model 1151 or 1182 gressure transmitters have not been purchased nor are planned for safety-related applications QRRYR J. Texas Utilities Generating Co 80/08/08.
- BOO9030265 Forwards Revision 1 to IE Bulletin 80~19, "Failures of Mercury-Metted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required SEYFRIT.K V Region 4, Dallas, Office of the Director BO/OG/15 1p
- 8009170406 Forwards IE Circular 80-10, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required SEYFRIT.K V. Region 4, Dallas, Office of the Director BO/08/22

- 8009120434 Forwards IE Info Notice 80-31, "Maloperation of Could-Brown Bover1 480 Voit Type K-6005 / K-DDN 6005 Circuit Breakers " No written response required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/08/27
- B009300070 Submits response to IE Sulletin 80-20 re Westinghouse Type W-2 control switches Requests extension to 801201 to complete review 2 corrective action GARY. R J Texas Utilities Generating Co 80/08/29 ip
- 8009300045 Submits response to IE Bulletin 79-03A Etching ends of sarety-related EA-312 Type 300 series fusion-welded pipe is in progress Results of etching will be submitted by 801015 GARY. R J Texas Utilities Generating Co B0/09/08 ip
- 9009300076 Submits response to IE Bulletin 80-19. Revision 1 No CP Clare Model HG2X-1011 mercury-wetted relays in reactor protection sys GARY.R J Texas Utilities Generating Co 80/09/08 Ip
- S. Reportable occurrences, LERs  $\lambda$  related correspondence
- 8009180045 Interim deficiency lept re installation of welded conduit supports Typical engineering drawings for major support have been developed 8 included in conduit support package Inspiristruction revised GARY, R J Texas Utilities Generating Co. 80/07/25 3pp
- 8009230301 Deficiency rept re discrepancies in installation & insp requirements for Class V safety-related piping supports Caused by inadequate documentation to ascertain that supports satisfy design & seismic load requirements GARY, R J Texas Utilities Generating Co 80/09/18 2pp

### V Operator Examinations

- 8007070387 Forwards licensed operator training lessons for fluid flow heat transfer & thermodynamics in response to MRC 800388 ltr Training re mitigation of severe core damage per Inst for Nuclear Power Operations guidelines will be developed GARY, R J Texas Utilities Generating Co 80/08/11 184pp
- DOCKE: SO-446 COMANCHE PEAK STEAM ELECTRIC STA JUNIT 2

  A Application/construction stage documents & correspondence
- BD09020219 "Initial Draft Bafety Evaluation on Metallurgy Review " ANDERSON, W E , ATTERIDGE D Q , OLSON, N J Batteile Memorial Institute, Pacific Northwest Laboratory 80/07/31 60pp
- 8007080080 Forwards draft NUREG-0676, "Functional Criteria for Emergency Response Facilities" Corments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl W/o NUREG EISENHUT,D © Division of Licensing 80/08/01 119pp
- 80090300.60 Forwards requests for add1 info re instrumentation & control sys in order to complete evaluation of CL applications FSAR should be amended to include requested into TEDESCO.R L Assistant Director for Licensing 80/08/14 10pp
- 8009020491 Forwards request for addl info re confirmatory piping analysis TEDESCO,R L. Assistant Director for Licensing 80/09/19 4pp
- 8009100004 Notification of 800826 meeting w/util in Bethesda MD to discuss implementation of NUREG-0696 functional criteria BURNELL, 8 B Operating Reactors Branch 2 80/08/22 3pp
- 8007170404 Forwards request for addl info re environ review for facility Environ rept should be amended to include Encl i info TEDESCO.R L Assistant Director for Licensing 80/08/27 17pp
- 8009160362 Responds to 800814 request for add1 info Answers to questions from Instrumentation 2 Controls Sys Branch & ANL consultants will be submitted by amend to FBAR on 801031 GARY, R J Teyas Utilities Generating Co 60/09/08 tp
- 8009220334 Forwards addit electrical instrumentation & control drawings to assist in NRC review GARY.R J Taxas Utilities Generating Co. 80/09/12 2pp.

- --2009220333 "Diesel Generator & Monitor Lights Schenatic & Connection Diagram Sheet Issue Record & Index " Sheet O + Gibbs & Hill: Inc (subs of Dravo Corp.) 2323 60/09/12 ip
- --8009220344 "Diesel Generator iDGI.Start Circuit Channel I.Schematic Diagram " Sheet 41 • Gibbs & Hill, Inc. (subs. of Dravo Corp.) 2323 80/08/27 1p
- --B009220357 "Diesel Generator 1802 Start Circuit Channel I, Schematic Diagram " Sheet 43 # Gibbs & Hill Inc (subs of Dravo Corg ) 2323 80/08/27 ip
- --8009220369 "Diesel Generator 1802.Start/Stop Circuit Channel II. Schenatic Biagram " Sheet 44 # Gibbs & Hill, Inc. (subs. of Dravo Corp.) 2323 80/08/27
- --8009220380 "Diesel Generator IDGI, Miscellaneous Circuits Sheet 1, Schemafic Diagram " Sheet 45 • Gibbs S Hill, Inc. (subs of Dravo Corp.) 2323 80/08/27
- --8009220393 "Diesel Generator 1DG1.Miscellamenus Circuits Sheet 2. Schematic Diagram " Sheet 46 \* Gibbs & Hill. Inc (subs of Dravo Corp ) 2323 80/08/27
- --8009220335 "Diesel Generator 1002.Miscellanbous Circuits Sheet 1. Echematic Diagram " Sheet 47 • Gibbs & Hill, Inc (subs of Dravo Corp.) 2323 80/08/27 1p
- --8009220387 "Diesel Generator 1DG2.Miscellaneous Circuits Sheet 2. Schematic Diagram " Sheet 48 • Gibbs & Hill, Inc. (subs of Dravo Corp.) 2323 E0/08/27 ip
- --8009220392 "Diesel Generator IDGI, Hiscellaneous Circuits Sheet 3. Schematic Diagram " Sheet 47 \* Gibbs & Hill, Inc (subs of Dravo Corp ) 2323 80/08/27
- --8009220393 "Diesel Generator 1D02.Miscellandous Circuits Sheet 3, Schematic Diegram " Sheet 50 \* Gibbs & Hill, Inc (subs of Drave Corp.) 2323 80/08/27 1s
- 8009230623 Forwards response to NRC 800927 request for addl info re environ review & amended environ review pages List of encis only enci Encis sent to J Lehr in separate package WERNER, R Texas Utilities Services, Inc. 80/09/12 3pp
- C Utility Environmental Report (ER), amends & correspondence
- 8009300442 Confirms 800925 telcon Review team will use unofficial amended environ rept until docketed Amend 1 received HARRIS V A Argonne National Laboratory 80/09/26 ip
- F Security, medical, emergency & fire protection plans
- 8009020143 Invites participation in 800822 workshop in Atlanta. GA to solicit comment re proposed functional critoria for smergency response facilities in NUREO-0696 Discussion to include location. Size & staffing of emergency ctrs SEYFRIT. K V Region 4, Dallas. Office of the Director 80/08/12

# G Adjudicatory correspondence

- 8007070238 Response in opposition to applicant Aug 1980 first set of interrogatories Hoves for protective order due to harassment 1 intimidation Requests unspecified extension of time to answer interrogatories Certificate of Sv. enc. HAWIHORNE, 8. GAY, 8 M. Association of Community Organizations for Reform Now-Teras HAWIHORNE, 8. West Texas Legal Services 80/08/28.
- 009020432 Forwards 800725 FR notice re procedural assistance change in adjudicatory licensing proceeding effective 800725 Policy loes not apply to Rt. Fouke 800815 request for 790522 renseript which may be paid for & obtained from PDR YTHSCHILD, K U Hearing Branch 1 80/08/29 5pp

- 8009150045 Offer of proof in support of intervenor 800701 motion for reconsideration of GA/OC contention Urges admission to modify Contention 5 to include issues raised in encl insprepts Ceptificate of Svc encl GAY. O M Association of Community Organizations for Reform Now-Texas GAY. O M West Texas Legal Services 80/08/27 App
- ---9009150050 Forwards IE Insp Repts 50-445/73-02 & 50-446/73-02 on 731203-06 & notice of violation HOWARD,E M Atomic Energy Commission 74/01/07 2pp
- ---8009150051 Notice of violation from insp on 731203-06 \* Atomic Energy Commission 74/01/07 Epp
- --B009150055 IE Insp Repts 50-445/73-02 & 50-446/73-02 on 731203-06
  Noncompliance noted GA program did not comply w/App B & not
  carried out per written policies
  WARNIGK.R F. PERANICH.M W. MADSEN.G L. Atomic Energy Commission
  74/01/07 20pp
- --B009150057 Forwards IE Insp Repts 50-44B/74-01 & 50-44B/74-01 pn 740313-14 No noncompliance nobed HOWARD.E M Atomic Energy Commission 74/03/19 3pp
- --B009150060 IE Insp Repts 50~445/74-01 & 50-446/74-01 on 740312-14 Certain items of previous GA concerns remain open re requirement of ANSI, distribution of drawings & vendor qualification for bidders' list WARNICK, R F , MADSEN, G L Atomic Energy Commission 74/03/18, 1400
- --80915063 Forwards IE Insp Repts 50-445/74-02 & 50-446/74-02 on 740627-28 HOKARD, E M Atomic Energy Commission 74/07/11 3pp
- --8009150066 JE Insp Repts 90-445/74-02 & 50-446/74-02 on 740627-26 Noncompliance noted GA policy & procedures do not meet ANSI stds CROSMAN(W A , STEWART, R C , MADSEN, 9 L Atomic Energy Commission 74/04/ii 10po
- --8009150068 Forwards IE Insp Repts 50-445/74-03 & 50-446/74-03 on 740718-19 Noncompliance noted HOWARD E M Atomic Energy Commission 74/07/30 2pp.
- --8009180071 IE Insp Repts 50-445/74-03 & 50-446/74-03 on 740718-19
  Noncompliance noted lack of delineation of GA/GC interface
  activities & failure to detail responsibilities
  SIEMART.R C , CROSSMAN,W A , MADSEN,O L Atomic Energy Commission
  74/07/30 7pp
- --8009150113 Forwards IE insp Repts 50-445/74-04 & 50-446/74-04 on 741107-08 Noncompliance noted HOWARD, E M Atomic Energy Commission 74/11/19 3pp
- --B009150075 IE Insp Repts 50-445/74-04 & 50-446/74-04 on 741107-0B Noncompliance noted GC procedures not adequately controlled & GA program manual had no procedural control re changes, revision or addition STEWART.R C , DICKERBON,M W , MADBEN, G L Atomic Energy Commission 74/11/19 ilpp
- --E009150116 Forwards IE Insp Repts 50-445/75-12 & 50-446/75-12 on 750911-12 No noncompliance noted MADSEL O L Region 4, Dallas, Reactor Construction & Engineering Support Branch 75/10/01 2pp
- --8009150977 IE Insp Repts 50-445/75-12 & 50-446/75-12 on 750911-12 No noncompliance noted Areas inspected licensee action on previously identified enforcement matter. STEMART.R C. HUBACEK.W G. CROBSMAN,H A. Region 4. Dallas, Office of the Director 75/10/01 Spp
- --8007150120 Forwards IE Insp Repts 50-445/76-01 & 50-446/76-01 on 760107-09 Noncompliance noted MADSEN.0 L. Region 4. Dallas, Reactor Construction & Engineering Support Branch 76/01/29 2pp
- --8009150080 IE Insp Repts 50-445/76-01 & 50-446/76-01 on 760107-09.
  Noncompliance noted QC/GA surveillance conducted w/o
  prescribed procedures
  STEWART,R C. DICKERSON,M N Region 4. Dallas, Office of the
  Director CROSSMAN,W A Region 4. Dallas, Reactor Construction &
  Engineering Support Branch 76/01/29 14pp
- --B007150122 Forwards IE insp Repts 50-445/76-08 & 50-446/76-08 on 760726-30 Noncompliance noted SEIDLE, & C Region 4, Dallas, Office of the Director 76/08/20 3pp

- --8009150083 IE Insp Repts 50-445/74-08 & 50-446/76-08 on 740726-30 Noncompliance noted OA manager duties & responsibilities encompassed engineering functions beyond GA program manual STEWART,R C., ROSENBERG.A B. CROSSMAN,W A. Region 4, Dallas, Office of the Director 76/08/19 15pp
- --B009150125 Forwards IE Insp Repts 50-445/77-02 & 50-446/77-02 on 770301-04 Noncompliance noted SEIDLE,N C Region 4. Dallas. Reactor Construction & Engineering Support Branch 77/03/23 2pp
- --8009150087 IE Insp Repts 50-445/77-02 % 50-446/77-02 on 770301-04 Noncompliance noted failure to meet 9A procedure reporting requirement CROSSMAN, M A , STEWART, R C , TAPIA, J I Region 4, Dallas, Office of the Director 77/03/23 11pp
- --8009150129 Forwards IE Insp Repts 50-445/78-05 & 50-446/78-05 on 770021-24 & notice of violation GEIDLE,W C Region 4. Dallas, Reactor Construction & Engineering Gupport Branch 78/04/06 2pp
- --8009150091 Notice of violation from insp on 780321-24
  \* Region 4. Dallas, Office of the Director 78/04/05 1p
- --E009180093 IE Insp Repts 50-445/78-05 & 50-446/78-05 on 7B0321-24 Moncompliance noted vendor quality documentation unavailable TAYLOR,R 0 , HALL,R E , CROSSMAN,N A Region 4, Dallas, Office of the Director 7B/04/05 5pp
- --8007150133 Forwards IE Insp Repts 50-445/78-07 & 50-446/78-07 on 780411-21 & notice of violation SEIDLE, W C Region 4, Dallas, Office of the Director 78/05/10 2pp
- --8009150096 Notice of violation from insp on 780411-21 \* Region 4. Dallas. Office of the Director 78/05/10 ip
- --8009150100 IE Inap Repts 50-445/78-07 & 50-446/78-07 on 780411-21 Noncompliance noted failure to meet PSAR commitments re concrete testing frequency TAYLOR,R 0 - FOSTER, W E - WARD, J J Region 4, Dallas, Office of the Director 78/05/10 10pp
- --8009150136 Forwards IE Insp Repts 50-445/78-11 & 50-446/78-11 on 780620-23 & notice of violation SEIDLE, N C Region 4, Dailas, Office of the Director 78/06/30 2pp
- --8009150102 Notice of violation from insp on 780620-23 \*\* Region 4. Dallas. Office of the Director 78/06/29 ip
- --8009130105 IE Insp Repts 50-445/78-11 & 50-446/78-11 on 780620-23 Noncompliance noted failure to follow piping installation procedures TAYLOR.R Q , CROSSMAN,W A Region 4, Dallas, Office of the Director 78/06/29 App
- 8007100435 Motion for extension until 800715 to respond to applicants' first set of interrogatories Certificate of Bvc encl MCCOLL.A C . MILLS.T . HART.J L Citizens for Fair Utility Regulation 80/07/02. 2pp
- 8009090579 Forwards original of verification encl w/answers to applicant 800903 first set of interrogations & requests to produce Affidavit encl W/o verification ELLIS. J Citizens Association for Sound Energy 80/09/03 2pp
- 8009i10034 Response to applicants' first set of interrogatories & requests for production of documents Moves for 60-day extension to respond to Interrogatories 55-65 re cost/banefit balance Objects to remaining questions ELLIS, J Citizens Association for Sound Energy 80/09/03 42pp
- ~-B009110044 Forwards affidavit re intervenor 800903 response to applicants' first set of interrogatories Certificate of Svc enc1
  ELLIS,J Citizens Association for Sound Energy 80/09/03 3pp
- 8009080039 Response stating no objection to Citizens Association for Sound Energy 800820 motion for extension until 800903 to reply to applicants' first set of interrogatories Certificate of 8vc ancl ROTHSCHILD,M U Hearing Branch i 80/09/04 3pp

- 800911004B Response to Citizens Association for Sound Energy request for production of documents cantained in 800707 first set of interrogatories Matls will be available for insp & copying upon arrangement w/HC Schmidt Certificate of Svc enci REYNOLDS, N S . HORIA, W A Toxas Utilities Generating Co REYNOLDS, N S . Debevoise & Liberman 80/09/08 Spp
- 8009110369 Confirms conversation re objection & intent not to respond to util 800825 interrogatories & document requests Factual discovery closed since 800314 Interrogatories are ill-timed as efforts have been made to encourage settlement STAHL.D M Isham, Lincoln & Beale 80/09/08 ip
- 8009110781 Response stating no objection to Citizens for Fair Util Regulation 800902 request for extension until 800915 to respond to applicants' 800813 first set of interrogatories & request for production of documents W/Certificate of Svc REYNOLDS. N.S. HORIN, W.A. Tojas Utilities Generating Co REYNOLDS. N.S. Debevoise & Liberman 80/09/09 3pp
- 8009110794 Response stating no objection to Citizens for Fair Util Regulation 800902 motion for extension until 800915 to respond to applicants' first sets of interrogatories & request for production of documents Certificate of Evc encl ROTHSCHILD.M U Hearing Branch 2 80/09/11 3pp
- 8009170361 Bubmits status of rept on settlement negotiations, on behalf of TX-LA Electric Cooperative of TX, Inc No unresolved issues exist at present Certificate of Svc encl BURCHCTTE, W.H. Northcutt Ely 80/09/11 3pp
- 8009170141 Motion to compel TX Association of Community Organizations for Reform Now response to applicants interrogatories Opposes intervenor motions for protective order 5 for addition W/Certificate of Svc Related correspondence REYNOLDS.N S. HORIN.W A. Texas Utilities Generating Correspondence REYNOLDS.N S. Debevoise & Liberman. 80/09/12 16pp
- 8009260005 Response to applicants' first set of interrogatories & request for production of documents Gbjects to majority of questions on basis of ambiguity Certificate of Svc encl FOUXE.R L , HART.J L , MCCOLL.A C Citizens for Fair Utility Regulation 80/09/15 17pp
- 8009230005 Motion to compel Citizens Associatin for Sound Energy response to first set of interrogatories Opposes motion for 60-day extension re interrogatories 95, 57, 56, 61, 62 & 64 Responds to request for clarification W/Certificate of Svc REYMOLDS, N S , HORIN, W A Texas Utilities Generating Co REYMOLDS, N S Debevoise & Liberman 80/09/18 22pp
- B00926000B Motion for protective order due to applicants' B00Bi3 voluminous first set of interrogatories & request for production of documents consisting of 167 basic demands ' Certificate of Svc ancl HART, J. MILLS, T. MCCOLL, A Citizens for Fair Utility Regulation B0/09/18 7pp
- H General correspondence
- 8007020108 Responds to 800808 ltr Advises that heat-induced illness being watched closely at plants Const has progressed to point that most work being dane indoors Applicants have taken steps to improve working conditions by adding fans DENTON.H R Office of Nuclear Reactor Regulation. Director 80/08/12 ip
- --8009020112 Informs that TX experiencing severe heat wave Requests that const on nuclear reactors be halted until temp at normal level for season Humanly impossible for const workers to do excellent work required LEVINE, HR Affiliation Unknown 80/07/08 lp
- M Antitrust correspondence
- 8009010196 Response to applicants.Central & South West Corp & City of Austin.TX objections to TX Border Cooperative petition to intervene Asserts interests under LBP-74-13 Urges full party participation W/Certificate of Svc O'NEIL,R A Bouthwest Texas Electric Cooperative O'NEIL,R, A Miller.Balis & O'Neil 80/07/31 16pp
- 8009020282 Requests that info be provided to all parties re wheeling rate development per 800826 discussions Discusses principles to be considered re smaller util participation in facility ownership BPIEGEL. G Spiegel & McDiarmid SPIEGEL. G Brownsville, TX 80/08/28 4pp

- 8009030721 Advises that appropriate steps have been taken to insure svoor status repts & pleadings CHANANIA.F D Antitrust Division 80/08/29 1p
- 8009040289 Joint motion for partial revision of ASLB 800813 order re procedural schedule Suggests 800912 for settlement status repts 800915 for prehearing conference & 801112 for evidentiary hearing commencement Certificate of Svc encl CHANAMIA: FD Antitrust Division FLYNN, PG Houston Lighting & Pouer Co FABRIKANT, R Justice. Dept of 80/08/27 7pp
- 8009100261 Designates WA Russell of WA Russel & Associates as expert engineering witness which DOJ may call at trial of facility licensing proceeding MCMILLERAN H Justice. Dept of 80/09/03 ip
- 8009110792 Order revising procedural schedule set in ASLB 800Bi3 order Sattlement status rept shall be submitted on 800912, prehearing conference shall commence on 800195 trial briefs on 801008 & 22 & evidentiary hearing on 801112 MILLER.M.E. Atomic Safety and Licensing Board Panel 80/09/08 200
- 8009150417 Motion to compel Central Power & Light response to 800825 interrogatories Objection erroneous due to necessity to know full scope of take-over plans W/DM Stohl 800908 ltr, excerpts of util corrected discovery & Certificate of Syc SPIEOEL, O. POIRIER, M.R. Brownsville, TX SPIEOEL, O. Spiegel & McDiarmid 80/09/ii 23pp
- 8009160275 Notice of taking WP Sayles & T Russell of CP&L 800923 & 24 depositions Examination will address possible purchase of Brownsville electric util sys & related studies & issuance of bonds Certificate of Svc encl POIRIER, M R Brownsville, TX FOIRIER, M R Spiegel & McDiarmid 80/09/12 7pp
- 8009170188 Settlement status rept Author approval of terms of stipulated licensing conditions not yet given No position on issues & procedures presented Certificate of Svc encl JDHN, DF r, MUNTER, M South Texas Electric Cooperative. JOH Medinaelectric Cooperative, Inc. 80/09/12 Spp JOHN, D. F
- 8009170359 Settlement status rept per ASLB 800813 order Agreement reached by util,NRC & DOJ which will dispose of all Comanche Peak issues when approved by ASLB Encl stipulation will insure OL would not violate antitrust laws
  SAMPLES,M D, KNOTTS,J B Texas Utilities Generating Co
  SAMPLES,M D Worsham, Forsythe & Sampels 80/09/12 2pp
- --8009170364 Stipulation incorporating encl license conditions Licensee denies past conduct w/o conditions violated antitrust laws
  Stipulation & Conditions do not constitute admissions of Stipulation & conviolation of Justice, Dept of BURCHETTE, W H Texas-Louisiana Electric Cooperative, Inc BO/09/12 10pp
- --8009170369 Stipulation incorporating enci license conditions Licensee denses past conduct w/o conditions violated antitrust laws Stipulation & conditions do not constitute admissions of violations Wo conditions Certificate of Svc encl STAHL,D Central & South West Corp KNOTTS,J B Texas Utilities Generating Co STAHL,D Isham, Lincoln & Beale 80/09/12 App
- 8009170229 Fourth settlement status rept Stipulations w/applicants embodying two sets of license conditions accomplished Final position re need for hearing will be submitted after examination of conditions by parties W/Certificate of Svc CHANANIA,F D Antitrust Division 80/09/14 7pp
- --8009170232 Stipulation incorporating new license conditions w/o admission of violation to antitrust laws CHANANIA.F D Antitrust Division. FABRIKANT.R Justice.Dept BURCHETTE.W H Texas-Louisiana Electric Cooperative.Inc Justice, Dept of 80/09/12 3pp
- -8009170235 Stipulation incorporating encl license conditions w/o admission of violation to antitrust laws STAHL.D M Central & South West Corp BOUANIGHT, J A Texas Utilities Generating Co 80/09/12 17pp
- 09140157 Settlement status rept per ASLB 800813 order Endorses encl stipulation re license conditions reached by DBJ, NRC, FERC & ouston Lighting & Power Resolves concerns evidencing intent o litigate DDE endorsed settlement entirely in FERC case UPELAND, J G Houston Lighting & Power Co COPELAND, J G Baker & atts 80/09/15 2pp

- B009140182 Settlement status rept per ASLB 80813 order Requests unspecified extension to receive 8 review new arguments & to determine 8 submit unresolved issues License conditions 6 settlement re FERC not yet received W/Certificate of Svc PDIRIER.M R Brownsvills.TX PDIRIER.M R Spiegel & McDiard settlemen. POIRIER M R C Spiegel & McDiarmid
- 8009170177 Settlement status rept Suggests approval of stipulated
  license conditions to maintain situation consistent w/
  antitrust laws FERC & SEC approval of dc interconnections
  necessary for settlement execution Certificato of Svc encl
  8TAHL,D M Central & South West Corp STAHL,D M Isham, Lincoln &
  Beale 80/09/15 12pp
- 8009180460 Suppl status rept per ASLB 800813 order DOJ reached agreement w/parties in Comanche Peak proceedings re proposed set of license conditions Agreement reached w/applicant in South TX proceeding Certificate of Svc encl HCMILLEN,N H Justice,Dept of 80/09/15 7pp
- B009250028 Order granting extension until 800929 for Commission to review ALAB-608 CHILK,S J Office of the Secretary of the Commission 80/09/22
- 8009260318 Motion for one-day extension to file comments on proposed settlement conditions Last minute consultations & discussions needed Contributate of Svc enci. POIRIER, M.R. Brownsville, TX. POIRIER, M.R. Spiegel & McDiarmid 80/09/24
- B009300035 Comments on proposed settlements per ASLB B00915 directive Proposed license conditions will serve to preclude or limit consideration of competitive implications of dc ties by FERC Certificate of Svc encl G'NEIL.R A Southwest Texas Electric Cooperative G'NEIL.R A. Miller, Balis & G'Neil B0/09/24 12pp
- 8009300488 Confirms that JR Choukas-Bradley was authorized to express position of Miller,Balis & O'Neil,P C on behalf of TX Border Cooperatives at 800915 status hearing re leave to intervene out of time O'NEIL,R A Miller,Balis & O'Neil 80/09/24 2pp
- --8009300496 Comments of TX Border Cooperatives on proposed settlements of NRC & DOJ re licensing proceedings Certificate of Svc O'NEIL,R A Miller,Balis & O'Neil O'NEIL,R A Texas Bordør Cooperatives 80/09/24 10pp
- 8009300013 Motion in opposition to 800912 preposed license conditions due to failure to address crucial issues re effects of ac & dc interconnections Urges further proceedings to cure inconsistency whatitrust laws Certificate of 8vc encl SPIEOEL, 0. JABLON.R A. ROTH, A.J. Brownsville, TX 80/09/25 32pg
- 8009300326 Order granting extension until 800925 for all parties to comment on 800915 stipulation & licensing conditions WOLFE,S J Atomic Safety and Licensing Board Panel 80/09/25, ip
- N Antitrust hearing transcripts
- 8009190764 Transcript of 800915 prehearing conference in Dethesda. MD Pp 1078-1138 \* Atomic Safety and Licensing Board Panel 80/09/15 64pp
- G Inspection reports, IE Bulletins & correspondence
- 8009183095 Discusses IE Insp Repts 50-445/80-15 & 50-446/80-15 on 800806 & 09 & forwards notice of violation SEIDLE-N C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/06/23 2pp
- --8009180100 Notice of violation from insp on 800606 & 07 Noncompliance noted failure to establish OA program for Clase 5 pipe support sys \* Region 4. Dallas. Office of the Director 80/06/23 ipp
- 8009170420 Ack receipt of IE Insp Repts 50-445/80-11 & 50-446/80-11 Office the state of the list nepes of the first nepes of the first of the state of
- 8009160012 Responds to IE Bulletin BO-05 re vacuum condition resulting in damage to holdup or low pressure tanks Tanks have adequate protection against vacuum conditions Design of holdup tanks compatible w/overflow requirements GARY,R J Taxas Utilities Generating Co 80/07/11 3pp

- 8009150337 Forwards IE Insp Repts 50-445/80-15 5 50-446/80-15 during June 1980 & notice of violation EFIDLE.U C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/07/23 2pp
- --8009150363 Notice of violation from insp during June 1980 \* Region 4, Dallas: Reactor Construction & Engineering Support Branch 80/07/22 ip
- --8009150367 IE Insp Repts 50-445/80-15 & 50-446/80-15 during June 1980 Nancompliance noted failure to establish QA program for Class 5 pipe support sys & failure to follow const procedures required by drawings TAYLOR, R G . CROSSHAN, & A Region 4. Dallas, Office of the Director 80/07/22 App
- 8009180457 Submits response to IE Bulletin 79-03A SA-312 Type 304 & 316 fusion weld pipe has been used in safety-related sys which may be subj to design stresses in excess of 857 of code allowable stresses List of subj pipes encl CARY,R J Texas Utilities Generating Co 80/07/28 4pp
- 8007100269 Forwards IE Insp Repts 50-445/80-17 & 59-446/80-17 on 800714-18 & notice of violation SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/07/31 2pp
- --8009100273 Notice of violation from insp on 800714-18
  \* Region 4, Dallas, Office of the Director 80/07/31 ip
- --8009100279 IE Insp Repts 50-445/80-17 & 50-446/80-17 on 800714-18 Noncompliance noted failure to use proper weld preparation counterbone transition tapers HALL,R E , GILBERT,L D Region 4, Dallas, Reactor Construction & Engineering Support Branch MARTIN,L E Region 4, Dallas, Office of the Director 80/07/31 Spp
- BD09290229 Responds to 800717 ltr Extends due date for response to notice of violation identified in IE Insp Repts 50-445/80-15 & 50-445/80-15 to 800820 SEIDLE-N.C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/07/31 ip
- --B009290571 Requests extension until 800820 to determine scope of problem identified in IE Inep Repts 50-445/80-15 & 80-446/80-15 CARY.R J Texas Utilities Generating Co 80/07/17 ip
- 8009300055 Submits response to IE Bulletin 80-16 Rosemount Model 1151 or 1152 pressure transmitters have not been purchased nor are planned for safety-related applications OARY,R J. Texas Utilities Generating Co. 80/08/08
- 8009030265 Forwards Revision 1 to IE Bullotin 80-17, "Failures of Mercury-Hetted Matrix Relays in Reactor Protoctive 8ys of Operating Nuclear Power Plants Designed by C-E " Uritten response required EEYFRIT.K V Region 4, Dallas, Office of the Director 80/08/15
- BO0917040A Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required SEYFRIT, K V Region 4. Dallas. Office of the Director B0/08/22
- 8009120434 Forwards IE Info Notice 80-31, "Malaperation of Gould-Brown Boveri 480 Volt Type K-6005 & K-DON 6005 Circuit Breakers " No written response regulated SEYFRIT.K V Region 4, Dallas, Office of the Director 80/08/27
- 8009300070 Submits response to IE Bulletin 80-20 re Westinghouse Type W-2 control switches Requests extension to 801201 to complete review & corrective action GARY.R J Texas Utilities Generating Co 80/08/29 1p
- 8009300065 Submits response to IE Bulletin 79-03A Etching ends of safety-related SA-312 Type 300 series fusion-welded pipe is in progress Results of etching will be submitted by 801015 GARY, R. J. Texas Utilities Generating Co. 80/09/08 ip
- 8009300076 Submits response to IE Bulletin 80-19.Revision 1 No CP Clare Model H02X-1011 mercury-wetted relays in reactor protection sys GARY.R J Texas Utilities Generating Co 80/09/08 ip

- S Reportable occurrences, LERs & related correspondence
- 6009180045 Interim deficiency rept re installation of welded conduit supports Typical engineering drawings for major support have been developed 0 included in conduit support package Inspiristruction revised GARY, R J Texas Utilities Generating Co 80/07/25 3pp
- 8009230301 Deficiency rept we discrepancies in installation & insprequirements for Class V safety-related piping supports Caused by inadequate documentation to ascertain that supports satisfy design b seismic load requirements GARY,R J Texas Utilities Generating Co 80/09/18 2pp
- U Congressional/Executive Correspondence
- 8007170383 Requests assistance in securing hearing date for CP Util has sought for 3 yrs to secure trial date Further delays impact on util b customers HYATT.J House of Rep 80/09/10 2pp
- V Operator Examinations
- 8009090387 Forwards licensed operator training lessons for fluid flow heat transfer t thermodynamics in response to NRC 800328 ltr Training re mitigation of severe core damage por Inst for Nuclear Power Operations guidelines uill be developed OARY.R J Texas Utilities Generating Co 80/08/11 184pp
- DOCKET 90-452 GREENWOOD ENERGY CENTER, UNIT 2
- Q Adjudicatory correspondence
- 8009110603 Notifies of ASLB order granting 800709 request for withdrawal & honoring request to withhold documents per 10CFR2 790 CHRISTERBURY.E Hoarings Division 80/07/31 ip
- DOCKET 50-453 GREENWOOD ENERGY CENTER, UNIT 3
- O Adjudicatory correspondence
- 8007110403 Notifies of ASLB order granting 800709 request for withdrawal & honoring request to withhold documents per 100FR2 790 CHRISTENBURY,E Hearings Division 80/07/31 1p
- DOCKET 90-454 BYRON STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8009050032 Discusses void formation in vessel head during 8006; I natural circulation cooldown event Requests opinion repotential for voiding phenomenon in Westinghouse designed NSSS CHECK, P.S. Assistant Director for Plant Systems 80/07/28 2pp
- 8007080080 Forwards draft NUREG-0676, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl W/o NUREG EISENHUT, D G Division of Licensing 80/08/01 117pp
- 8007110327 Discusses review of pressurization analyses for pressurizer subcompartment Review should be focused on assuring that restricted vols do not result in unacceptably high local pressures MOON, C.W. Licensing Branch 1 80/07/03 ip
- 8009300455 Forwards drawing of block diagram on turbine trip protection in response to NRC request for add1 FBAR info NAUGHTON.W F Commonwealth Edison Co 80/09/24 1p
- .—B009300465 "Block Diagram Turbine Generator Emergency Fluid Trip Bys "

  → Sargent & Lundy, Inc. 4391 80/07/28 ig
- F Security, medical, emergency & fire protection plans
- 8009120091 Forwards emergency planning info for placement in local PDR W/o enci SUUDER, J. L. Library Branch 90/09/28 ip

- 8009120094 Forwards emergency planning anfo for placement in local PDR
- SOUDER, J L Library Branch 80/08/28 1p
- 8009120446 Forwards preliminary evacuation time studies of 10-mile radius emergency planning zone, in response to NRC 800702 ltr Studies have been submitted for review to state & local officials No significant comments resulted DELGEGRGE, L. O. Commonwealth Edison Co. 8 80/08/29 43pp
- 8009110187 Advises of acceptance of safeguards contingency plan submitted by 900324 ltr YOUV0810CDD,B J Licensing Branch 1 80/09/02 2pp Licensing Branch 1 80/09/02 2pp
- ¶ Inspection reports, IE Builetins & correspondence
- 8009110307 Forwards 1E Insp Repts 50-454/80-12 % 50-455/80-11 on 09110307 Forwards je trisp Repts of House to the Colonial Social Social
- --8009110313 Notice of violation from insp on 800417-19 # Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/09 2pp
- --8009110324 IE Insp Repts 50-454/80-12 & 50-455/80-11 on 800617-19
  Noncompliance mated improper design of component cooling
  water pipes presents possibility of accident rendering
  emergency diesel generators in & 18 insperable
  HAYES,D W Region 3, Chicago, Reactor Construction & Engineering
  Support Branch NAIDLY & 7, SCHAPKER,JF Region 3, Chicago,
  Office of the Director 80/07/09 10pp
- B009020109 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " SA-312 pipe not present in operating plants Final confirmation from suppliers anticipated by B00915 re const plant piping sys NAUGHTON.W F Communwealth Edison Co 80/08/07 2pp
- 8009030231 Forwards Revision I to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Unitten response required KEPPLER, J G Reg Region 3. Chicago. Office of the Director 80/08/15
- 8009110545 Responds to IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds." supplementing 800709 response Corrects Zion response re rings used for field circumferential butt weld Reviews accuracy of other statements ABEL.US Commonwealth Edison Co 80/08/15 4pp
- 8009110665 Forwards IE Insp Repts 50-454/80-13,50-455/80-12, 50-456/80-07 % 50-457/80-07 on 800722 % 24-25 No FIGRELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/08/15 2pp
  - -8007110675 IE Insp Repts 50-454/80-13,50-455/80-12,50-456/80-07 & 50-457/80-07 on 800722 & 24-25 No noncompliance noted Major areas inspected licensee actions re control of IE bulletins & circulars & mgt meeting NAIDU.K R Region 2. Atlanta, Office of the Director KONKLIN.J E. JONES.C E Region 3. Chicago, Office of the Director 80/08/14 9pp
- 80091402Bi Submits supplementary response to IE Bulletin 80-08, "Examination of Containment Liner Penetration Helds," correcting statement made in DL Peoples 800709 ltr Further review not necessary ABEL.J S Commonwealth Edison Co 80/08/(5 4pp
- 8007290188 Forwards IE Insp Repts 80-454/80-14 & 50-455/80-13 on 800728-27 No noncompliance noted FIORELLI, O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/08/19 Epp
- -8009290193 IE Insp Repts 50-454/80-14 & 50-455/80-13 on 800728-29 No overtoins it inspirely 30-49/40-14 & 50-493/20-13 on 30/20/22 Minoncompliance noted Major areas inspected setting & alignment of reactor pressure vessel & Unit 1 cavity liner & installation of in-core flux tubes WILLIAMS, C c . JONES, C E . ERB, C M Region S, Chicago, Office of the Director 80/08/18 App
- 8009180551 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response XEPPLER, J @ Region 3, Chicago, Office of the Director 80/08/22

- B009230094 Forwards IE info Notice B0-31, "Maloperation of Gould-Brown Bover1 480 Volt Type K-6005 & K-DDN 6008 Circuit Breakers "
  No written response required Region 3. Chicago, Office of the Director 80/08/28 KEPPLER, J G
- B007180466 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Identified relays are not used in facility No action required Twenty-four manhours expended on review RAUSCH, T J Commonwealth Edison Co 80/08/29 ip
- 8009190007 Responds to IE Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters Identified transmitters are not used in Byron & Braidwood safety-related areas LaBalle will comply w/requirements by defining mads by 801001 RAUSCH, T J Commonwealth Edison Co 80/08/29 2pp
- 8009250468 Supplemental response to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies" Deficient springs in actuators w/ Masoneilian valves for safety-related applications will be replaced prior to shipment to site RAUSCH,T J Commonwealth Edison Co 80/08/29 3pp
- 8009240133 Forwards IE Circular 80-21, "Regulation of Refueling Creus" No written response required
  KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/10
- 8009300200 Forwards response to IE Bulletin 80-20 No Westinghouse Type W-2 control switches are used in safety-related sys at Dresden, Guad Cities & LaSalle County Responses for Zion & Byron are encl RAUSCH, T J C Commonwealth Edison Co 80/09/15 Ann
- 8009300215 Responds to 800812 ltr re noncompliance noted in IE Insp Repts 50-454/80-12 & 50-455/80-11 on 800617-17 NRC position unchanged Response re present & future corrective steps & date of full compliance must be submitted within 30 days KEPPLER, J G Region 3. Chicago, Office of the Director 80/09/16 80/09/16

## V Operator Examinations

8009300287 Forwards preliminary topical outlines of proposed modules on thermal hydraulics & core damage mitigation to be included in revised reactor operator training program per 80032B' request NAUGHTON, W F Commanuealth Edison Co 80/09/15 7pp

#### DOCKET 50-455 BYRON STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8007050032 Discusses void formation in vessel head during 800611 natural circulation cooldown event Requests opinion repotential for voiding phenomenon in Westinghouse designed CHECK, P 8 Assistant Director for Plant Systems 80/07/28 2pp.
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT, D O Division of Licensing 80/08/01 119pp
- 8009110327 Discusses review of pressurization analyses for pressurizer subcompartment Review should be focused on assuring that restricted vols do not result in unacceptably high local pressures. MODN,C W Licensing Branch 1 60/09/03 ip
- 8009300455 Forwards drawing of block diagram on turbine trip protection in response to NRC request for addl FSAR info NAUOSTON U F Commonwealth Edison Co 80/09/24 ip
- --8009330465 "Block Diagram Turbing Generator Emergency Fluid Trip Sys "
  \* Sargant & Lundy, Inc. 4391 80/07/28 1p
- F Security, medical, emergency & fire protection plans
- BOO9120091 Forwards emergency planning info for placement in local PDR SOUDER, J. L. Library Branch 80/08/28 1p
- BOD9120094 Forwards emergency planning info for placement in local PDR W/o encl SOUDER, J L Library Branch 80/08/20 1p

- 8009120446 Forwards preliminary evacuation time studies of 10-mile radius emergency planning ione in response to NRC 800702 ltr Studies have been submitted for review to state % local officials No significant comments resulted DELGEGROE, LO Commonwealth Edison Co 80/08/29 43pp
- 8009110187 Advises of acceptance of safeguards contingency plan submitted by 800324 ltr YOUN08LOOD,B J Licensing Branch 1 80/09/02 2pp
- 9 Inspection reports: IE Bulletins & correspondence
- 8009110307 Forwards IE lnsp Repts 50-454/80-12 & 50-455/80-11 on 800617-19 & notice of violation FIORELLE, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/07/10 2pp
- --8009110313 Notice of violation from insp on 800517-19
  # Region 3. Chicago. Reactor Construction & Engineering Support
  Branch 80/07/09 2pp
- --B009110324 IE Insp Repts 50-454/80-12 % 50-455/80-11 on B00617-19
  Noncompliance noted improper design of component cooling
  water pipes presents possibility of accident rendering
  emergency diesel generators 1A % 1B inoperable
  HAYES, D W Region 3, Chicago, Reactor Construction & Engineering
  Bupport Branch NAIDU, K R , SCHAPKER, J F Region 3, Chicago,
  Office of the Director B0/07/09 10pp
- 8909020109 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " SA-312 pipe not present in operating plants Final confirmation from suppliers anticipated by 800915 real to 1 plant piping sys NAUOHTON. W F Commonwealth Edison Co 80/08/07 2pp
- 8009030231 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER.J O Region 3, Chicago, Office of the Director 80/08/15
- B009110545 Responds to IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds," supplementing 800709 response Corrects Iion response re rings used for field circumferential butt weld Reviews accuracy of other statements ABEL, J S Commonwealth Edison Co 80/08/15 App
- 8009110665 Forwards IE Insp Repts 50-454/80-13,50-455/80-12, 50-456/80-07 & 50-457/80-07 on 600722 & 24-25 No noncompliance noted FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/15 2pp
- --8009(10675 IE Insp Repts 50-454/80~13,50-455/60-12,50-456/80-07 & 50-457/80-07 on 800722 & 24-25 No noncompliance noted Major areas inspected licenses actions re control of IE bulletins & circulars & mgt meeting NAIDU.K R Region 2, Atlanta, Office of the Director KONKLIN.JE, JUNES, C E Region 3, Chicago, Office of the Director 80/08/14 9pp
- BCO9160481 Submits supplementary response to IE Bulletin 60-08, "Examination of Containment Liner Penetration Helds," correcting statement made in DL Peoples 800709 1tr Further review not necessary ABEL. J S Commonwealth Edison Co 80/08/15 4pp
- 800729018B Forwards IE Insp Repts 50-454/80-14 & 50-455/80-13 on 800728-29 No noncompliance noted FiGRELLI, & Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/19 2pp
- --8009290193 IE Insp Repts 50-454/80-14 & 50-455/80-13 on 800728-29 No noncompliance noted Major areas inspected setting & alignment of reactor pressure vessel & Unit 1 cavity liner & installation of in-core flux tubes WILLIAMS: C . JONES, C E . ERB, C, M Region 3. Chicago, Office of the Director 80/08/18 App
- 8009180551 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/08/22
- 8009230094 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6005 & K-DON 6005 Circuit Breakers " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/28

- 8009180466 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Identified relays are not used in facility No action required Twenty-four manhours expended on review RAUSCH.7 J Commonwealth Edison Co 80/08/29 ip
- 8009196007 Responds to JE Sullatin 80-16 re potential misapplication of Rosemount pressure transmitters Identified transmitters are not used in Byron 8 Braidwood safety-related areas LaBalle will comply w/requirements by defining mods by 801001 RAUSCH.T J Commonwealth Edison Co 80/08/29 2pp
- 800929046B Supplemental response to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies" Deficient springs in actuators of Masoneilian valves for safety-related applications will be replaced prior to shipment to site RAUSCH.T J Commonwealth Edison Co 80/08/29 3pp
- 8009240133 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required KEPPLER, J.G. Region 3, Chicago, Office of the Director 80/09/10 10
- 8009300200 Forwards response to IE Bulletin 80-20 No Westinghouse Type N-2 control switches are used in safety-related sys at Dresden, Guad Cities & LaSalle County Responses for Zion & Byron are encl RAUSCH.T J Commonwealth Edison Co 80/09/15 6pp
- 8009300215 Responds to 800812 itr re noncompliance noted in IE Insp. Repts 50-454/80-12 & 50-455/80-11 on 800617-19 NRC position unchanged Response represent & future corrective steps & date of full compliance must be submitted within 30 days KEPPLER, J O Region 3, Chicago, Office of the Director 80/09/16 200
- V Operator Examinations
- B0093002B7 Forwards preliminary topical outlines of proposed modules on thermal hydraulics t core damaga mitigation to be included in revised reactor operator training program per 80032B request
  NAUGHTON, W F Commonwealth Edison Co 80/09/15 7pp
- DOCKET 50-456 BRAIDWOOD STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8009050032 Discusses void formation in vessel head during 800611 natural circulation cooldown event Requests opinion repotential for voiding phenomenon in Westinghouse designed NSSS CHECK,PS Assistant Director for Plant Systems 80/07/28 2pp
- 8009080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl M/o NUREG EISENHUT.D G Division of Licensing 90/08/01 119pp
- BOO9110327 Discusses review of pressuritation analyses for pressuriter subcompartment Review should be focused on assuring that restricted vols do not result in unacceptably high local pressures
  MOGN.C W Licensing Branch & BD/09/03 & Sp
- 8009300455 Forwards drawing of block diagram on turbine trip protection in response to NRC request for addl FBAR info NAMOHTON W F Commonwealth Edison Co 80/09/24 1p
- --8009300465 "Block Diagram Turbine Generator Emergency Fluid Trip Sys " \* Sargent & Lundy, Inc. 4391 80/07/28 lp
- F Security, medical, emergency & fire protection plans
- 8009120444 Forwards preliminary evacuation time studies of 10-mile radius emergency planning jone, in response to MRC 800702 itr Studies have been submitted for review to state & local officials No significant comments resulted DELGEORGE, L O Commonwealth Edison Co 80/08/29 43pp
- 8009110397 Advises of acceptance of safeguards contingency plan submitted by 800324 itr YDUN08L00D.B J Licensing Branch i 80/09/02 2pp

### G. Inspection reports. IE Bulletins & correspondence

- 8009170217 Forwards IE Insp Repts 50-456/80-06 & 50-457/80-06 on 800709-10 No noncompliance noted FIORELLI.G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/07/28 2pp
- --8009170221 IE Insp Repts 50-456/80-06 & 50-457/80-06 on 800709-10
  No noncompliance noted Major areas inspected review action
  taken in previous insp findings.electrical contractor
  procedures 2 storage of electrical equipment
  MAIDU. A. R. SCHAPKER, J. Region 3. Chicago, Office of the Director
  HAYES, D. M. Region 3. Chicago, Reactor Construction & Engineering
  Support Branch 80/07/24 5pp
- 8007020109 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312 Type 304 Stainless Steel Pipe " SA-312 pipe not present in operating plants Final constrmation from suppliers anticipated by 800915 re const plant piping sys NAUGHTQU.N F Commonwealth Edison Co 80/08/07 2pp
- 8007030231 Forwards Revision 1 to TE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective 89s of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER, J. G. Region 3. Chicago, Ofrice of the Director 80/08/15 to
- 8009110545 Responds to IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds," supplementing 800709 response Corrects Zion response je rings used for field circumferential butt weld Reviews accuracy of other statements ABEL.J S Commonwealth Edison Co 80/08/15 App
- 8009110665 Forwards IE Insp Repts 50-494/80-13,50-455/80-12, 50-456/80-07 & 50-457/80-07 on 600722 & 24-25 No noncompliance noted FIDRELI,49 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/15 2pp
- --8009110675 IE insp Repts 50-454/80-13.50-455/80-12.50-456/80-07 & 50-457/80-07 on 800722 & 24-25 No noncompliance noted Major areas impacted licensee actions re-control of IE bulletins & circulars & mpt meeting NAIDU, K.R. Region 2. Atlanta, Office of the Director KONALIN, J.E., JONES, C.E. Region 3. Chicago, Office of the Director 80/08/14 9pp
- 8009160681 Submits supplementary response to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds." correcting statement made in DL Peoples 800709 ltr Further review not necessary ABEL.J S Commonwealth Edison Co 80/08/15 4pp
- 1009180551 Forwards IE Circular 80-18, "100FR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER, J G Region 3, Chicago. Office of the Director 80/08/22
- 009230094 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Boveri 490 Volt Type K-6008 & K-DDN 6008 Circuit Breakers" "No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/28
- :009180466 Responds to IE Bulletin 80-19 re failures of mercury-wetted matrix relays in reactor protective sys Identified relays are not used in facility No action required Twenty-four manhours expanded on review RAUSCH.T J Commonwealth Edison Co 80/08/29 tp
- -009190007 Responds to IE Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters Identified transmitters are not used in Byron & Braidwood safety-related areas LaBaile will comply w/requirements by defining mods by 801001 RAUSCH.T J Commonwealth Edison Co 80/08/29 2pp
- 1009250468 Supplemental response to IE Dulletin 80-09. "Mydramotor Actuator Deficiencies " Deficient springs in Actuators w/ Masonerlian valves for safety-related applications will be replaced prior to shipment to site RAUSCH.T J Commonwealth Edison Co 80/08/29 3pp
- 009240133 Forwards IE Circular 80-21. 'Regulation of Refueling Crews'' No written response required KEFFLER, J G Region 3. Chicago, Office of the Director 80/09/10 in

- 8009300200 Forwards response to 1E Bylletin 80-20 No Westinghouse Type W-2 control switches are used in safety-related sys at Dresden Guad Cities & LaSalle County Responses for Zion & Byron are enci RAUSCH.T J Commonwealth Edison Co 80/09/15 App
- V Operator Examinations
- 8009300287 Forwards preliminary topical outlines of proposed modules on theimal hydraulics & core damage mitigation to be included in revised reactor operator training program per 800328 request NAUGHTCH. W F Commonwealth Edison Co 80/09/15 7pp
- DOCKET 50-457 BRAIDWOOD STATION: UNIT 2
- A Application/construction stage documents & correspondence
- 8009050032 Discusses void formation in vessel head during 800611 natural circulation cooldown event Requests opinion repotential for voiding phenomenon in Westinghouse designed NSSS CHECK.PS Assistant Director for Plant Systems 80/07/28 2pp.
- 8007080D80 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT.D 0 Division of Licensing 80/08/01 119pp
- 8009110327 Discusses review of pressuritation analyses for pressuriter subcompartment Review should be focused on assuring that restricted vols do not result in unacceptably high local pressures MOON, C # Licensing Branch 1 80/09/03 1p
- 8009300455 Forwards drawing of block diagram on turbine trip protection, in response to NRC request for addl FSAR info NAUGHTQH.W F Commonwealth Edison Co 80/09/24 1p
- --8009360465 "Block Diagram Turbine Generator Emergancy Fluid Trip Bys \*
  # Bargent & Lundy, Inc 4683 80/07/28 ip
- F Security, medical, emergency & fire protection plans
- 8009120446 Forwards preliminary evacuation time studies of 10-mile radius emergency planning tone, in response to NRC 800702 its Studies have been submitted for review to state & local officials No significant comments resulted PELGEORGE, L.O. Commonwealth Edison Co. 80/08/29 43pp
- 8009110397 Advises of acceptance of safeguards contingency plan submitted by 800324 ltr YOUNGBLOOD,B J Licensing Branch 1 80/09/02 2pp
- Q Inspection reports, IE Bullatins & correspondence
- 8007170217 Forwards IE Insp Repts 50-456/80-06 & 50-457/80-06 on 800709-10 No noncompliance noted fidRELLI.0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/28 2pp
- --9007170221 IE Insp Repts 50-456/80-06 & 50-457/80-06 on 900709-10
  No noncompliance noted Major areas inspected review action
  taken on previous insp findings, electrical contractor
  procedures & storage of electrical equipment
  MAIDU.K R. SCHAPKER.J Region 3. Chicago, Office of the Director
  HAYEB.D W Region 3. Chicago, Reactor Construction & Engineering
  Eupport Branch 80/07/24 Spp
- 8007020109 Responds to [E Bulletin 79-03A, "Longitudinal Weld Defects in ASKE SA-312, Type 304 Stainless Steel Pipe " SA-312 pipe not present in operating plants Final confirmation from suppliers anticipated by 800915 re const plant piping sys NAUGHTON, W F Commonwealth Edison Co 80/08/07 2pp
- B009030231 Forwards Revision 1 to IE Bulletin B0-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director B0/08/15 to
- BO09110545 Responds to IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds," supplementing 800709 response Corrects Zion response re rings used for field circumferential butt weld Reviews accuracy of other statements ABEL, J.S. Commonwealth Edison Co. 80/08/15. 4pp

## DOCKETED ITEMS

- 8009110665 Forwards IE Insp Repts 50-454/80-13,50-455/80-12, 50-455/80-07 % 50-457/80-07 on 800722 % 24-25 No noncompliance noted FIGRECLI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/15 2pp
- --8009110475 IE Insp Repts 50-454/80-13.50-455/80-12.50-454/80-07 & 50-457/80-07 on 800722 & 24-25 No noncompliance noted Major areas inspected licensee actions re control of IE bulletins & circulars & mgt meeting NAIDUK R Region 2. Atlanta, Office of the Director 90/08/14
- 8009160681 Submits supplementary response to IE Bulletin 80-08, "Examination of Containment Liner Penetration Helds." correcting statement made in DL Peoples 800709 ltr Further review not necessary ABELJ 8 Commonwealth Edison Co 80/08/15 4pp
- BOO9180551 Forwards IE Circular 80-19. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER.J O Region 3. Chicago, Office of the Director 80/08/22
- BCO9230094 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bovert 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/08/28
- BC09180466 Responds to IE Bulletin 80-19 re failures of nercury-wetted matrix relays in reactor protective sys Identified relays are not used in facility No action required Twenty-four manhaurs expended on review RAUSCH, T J Commonwealth Edison Co 80/08/29 ip
- 8009190007 Responds to IE Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters Identified transmitters are not used in Byron & Braidwood safety-related areas LaSalle will comply w/requirements by defining mods by 801001 RAUSCH.T J Commonwealth Edison Co 80/08/29 2pp
- 8009250448 Supplemental response to IE Bulletin 80-09. "Hydramotor Actuator Deficiencies " Deficient springs in actuators w/ Masoneilian valves for safety-related applications will be replaced prior to shipment to site RAUSCH.T J Commonwealth Edison Co 80/08/29 3pp
- 8009240133 Forwards IC Circular 80-21, "Regulation of Refueling Crews " No written response required KEPPLER, J.G. Region 3, Chicago, Office of the Director 80/09/10
- 8007300200 Forwards response to IE Bulletin 80-20 No Westinghouse Type W-2 control switches are used in safety-related sys at Dresden. Quad Cities & LaSalle County Responses for Zion & Byron are encl RAUSCH.T J Commonwealth Edison Co 80/09/15 App

#### V Operator Examinations

- BOOP300207 Forwards preliminary topical outlines of proposed modules on thermal hydraulics & core damage mitigation to be included in revised reactor operator training program per 800320 request NAUGHTON.W F Commonwealth Edison Co 80/09/15 7pp
- DOCKET 50-458 RIVER BEND STATION, UNIT 1
- A Application/construction stage documents & correspondence
- BOO90B00B0 Forwards draft NURE9-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days.Proposed implementation schedule for meeting criteria of NURE9-0696 encl W/O NURE0 EISENMUT.D 0 Division of Licensing 80/08/01 119pp
- 8009120113 Forwards 800811 memorandum of agreement w/Advisory Council on Historic Preservation for proposed transmission line & expanded corridor Acknowledgement of agreement & contification of acceptance encl
  TEDESCORR L Division of Licensing 80/08/21 3pp
- 8009090409 Confirms telcon w/M Karlowicz re 791026 application to amend CPPR-145 Cajun Electric Power Cooperative share of const costs nuclear fuel 5 transmission lines will be financed through Rural Electrification Administration DRAPER.E L Gulf States Utilities Co 80/08/28 ip

- 8009300220 Advises that issue or continuation of transmission line activities through Port Hudson nat! historic landmark has been concluded to NRC satisfaction Commitments contained in 800821 ltr satisfactory MIRAGLIA.F J. Licensing Branch 3 80/09/16 2pp
- F Security, medical, emergency & fire protection plans
- 8009020134 Invites participation in 800822 workshop in Atlanta.GA to solicit comment to proposed functional criteria for emergency response facilities in NUREG-0696 Discussion to include location.size 5 staffing or emergency ctts
  SEYFRIT.K V Region 4, Dallas, Office of the Director 80/08/12
- 8009090532 Forwards "Evacuation Time Estimates for 10-Mile Emergency Planning Zone," in response to 800702 ltr DRAPER.E L. Gulf States Utilities Co. 80/08/29 Ip
- --8009090537 "Evacuation Time Estimates for 10-Mile Emergency Planning Zone " Approved by State of i.A atticials • Commonwealth Edison Co BOBLINGER, L H . BORDAN, A J Louisiana, State of 80/08/29 34pp

## G Adjudicatory correspondence

- 8009170410 Ack receipt of 800721 petition under 10CFR2 206 for halt to const of facilities based on allegations of questionable canst practices Denies request for immediate action since public health & safety is not affected STELLO.V Office of Inspection & Enforcement, Office of the Director 80/08/18 2pp
- --B009170414 Ack receipt of B00721 petition under 10CFR2 206 for halt to const of facilities based on allegations of questionable const practices Denies request for immediate action since public health t safety is not affected Forwards FR notice STELLO.V Office of Inspection & Enforcement, Office of the Director 80/08/18 2pp
- ---B009170417 Notice of UCS 800721 request for action under 100FR2 206 DEYOUND, R.C., STELLO, V. Office of Inspection & Enforcement, Office of the Director E0/08/18 ip
- 8009090406 Order granting extansion until 800922 for Commission to elect whether to review Director's 800818 decision under IOCFR2 206 not to suspend CP CHILK.8 J Office of the Secretary of the Commission 80/09/05 ip
- 8009290039 Order granting extension until 800929 for Commission to elect whether to review Director's 800818 decision not to suspend const of facility under 10CFR2 206 CHILK.B J Office of the Secretary of the Commission 80/09/22
- 9 Inspection reports, IE Bulleting & correspondence
- 8009040511 Forwards IE Sulletin 80-07, "BWR Jet Pump Assembly Failure " No response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/04/04 fo
- 8007070037 Forwards IE Bulletin 80-07. Suppl 1, "BNR Jet Pump Assembly Failure " No response required SEYFRIT.X V Region 4, Dallas, Office of the Director 80/00/13
- 8009020534 Forwards Suppl 2 to IE Bulletin 80-17, "Failures Revealed by Testing Subsequent to Failure of Control Rods to Insert During Scram at BWR " No written response required SEYPRIT.X V Region 4, Dailas, Office of the Director 80/07/22
- 9009150040 Forwards IE Insp Rept 50-459/80-06 on 800609-10,24-27 & 30 0703, notice of violation 3 notice of deviation SEIDLE.W C Region 4. Dailas, Reactor Construction & Engineering Support Branch 80/07/28 Ppp
- --8009180352 Notice of violation from insp on 800609-10,24-27 & 30 & 0703

  \* Region 4. Dailas, Reactor Construction & Engineering Support Branch 60/07/25 2pp
- --8009150353 Notice of deviation from Insp on 800609-10,24-27 & 30 & 0703 4 Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/07/25 ip

- --B009150357 IE Insp Rept 50-458/80-06 on B00607-10.24-27 & 30 & 0703
  Noncompliance noted failure to follow procedures for
  identification of training needs & use of air entrainment
  admixture in Category & concrete
  BEACH, A.B., OILBERT, L.D., TOALINSON, D.P. Region 4, Dallas, Reactor
  Construction & Engineering Support Branch B0/07/25 lipp
- 8009250390 Forwards IE Insp Rept 50~458/80-07 on 800715~18 & notices of violation & deviation SEIDLE,N C Region 4. Dailas. Reactor Construction & Engineering Support Branch 60/08/11 2pp
- --8009250393 Notice of violation from insp on 800715-18 4 Region 4, Dallas, Office of the Director 80/08/08 2pp
- --8009250375 Notice of deviation from insp on 800715-18 \* Region 4. Dallas, Office of the Director 80/08/08 2pp
- --8009250398 IE Insp Rept 50-459/80-07 on 800715-18 Noncompliance noted railure to follow procedurel requirements for good housekeeping & inappropriate accept/reject criteria for total air content in exterior uall placement HALL.R E Region 4, Dallas, Reactor Construction & Engineering Support Branch CROSSMAN, W A, BEACH, A 9 Region 4, Dallas, Office of the Director 80/08/08 Bpp
- 8009030271 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written respinse required SEY-RIT.K V Region 4, Dallas, Office of the Director 80/08/15
- 8007050517 Ack receipt of 800727 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-458/80-05 Addl info requested SEIDLE.W C Region 4, Dallas, Reactor Construction & Engineering Support Branch
- -8009050522 Responds to NRC 800710 ltr re violations noted in IE Insp Rept 30-458/80-05 Corrective actions GC Instruction FRI-D2 5 -010 revised & NAD 9400 superseded by NAD 9701 Air fry unit weight tests to be completed by SAN by 800901 DRAPER, E. L. Oulf States Utilities Co 80/07/29 10pp
- 9150338 forwards IE Insp Rept 50-458/80-08 on 800730-31 No oncompliance noted EIDLE,N C Region 4. Dallas, Reactor Construction & Engineering apport Branch 80/08/19 2pp
- 8009150362 IE insp Rept 50-458/80-08 on 800730-31 No noncompliance noted Major areas inspected licensee investigation of concerns expressed in UCS 800721 ltr to NRC BEACH A D . (BERG, C R Region 4. Dallas, Diffice of the Director HALL-R E Region 4. Dallas, Reactor Construction & Engineering Support Dranch 80/C8/18 App
- 8009160032 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE 3WR Facilities " No specific action or response requested GEYFRIT.K V Region 4, Dallas, Office of the Director 80/08/19 ip
- 3009120025 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR' No written response required SEYFRITIK V Ragion 4. Dallas, Office of the Director 80/08/22
- 1009170392 Forwards IE Circular 80~18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sgs " No written response required SEY-RJT.K V Region 4, Dallas, Office of the Director 80/08/22
- 009250412 Ack receipt of IE Insp Rept 50-458/80-08 on 800819 No proprietary (nro DRAPER E. L. Oulf States Utilities Co. 80/08/22 ip
- 3009120422 Forwards IE Info Notice 80-31. "Matoperation of Gould-Brown Boveri 480 Volt Type K-6005 & K-DON 6005 Circuit Breakers " No written response required SEY-RIT.K V Region 4. Dallas. Office of the Director 80/08/27
- CO9300086 Submits response to IE Bulletin 80-16 No Rosemount Model 1151 or 1152 pressure transmitters are to be used in safety-related applications DRAPER.E L Guif States Utilities Co GO/09/05 2pp

- 8009290325 Ack receipt of 800805 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-458/78-04 & 50-459/78-04 SEIDLEW C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/09/10 ip
- --8009270326 Forwards third annual status rept of progress of environ studies of effect of Alligator Bay Culver crossing in response to Request 3 of IE Insp Repts 50-458/78-04 & 50-459/78-04 BRAPER.E L Gulf States Utilities Co 80/08/05 3pp
- DOLKET 50-459 RIVER BEND STATION, UNIT 2
- A Application/construction stage documents & correspondence
- BOO9080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 entl W/o NUREO EISENHUT.D © Division of Licensing 80/08/01 119pp
- 8009120113 Forwards 800811 memorandum of agreement w/Advisory Council on Historic Preservation for proposed transmission line & expanded corridor Acknowledgement of agreement & certification of acceptance and TEDFSCO:R L Division of Licensing 80/08/21 3pp
- 8009300240 Advises that issue of continuation of transmission line activities through Port Hudson natl historic landmark has been concluded to NRC satisfaction Commitments contained in 800821 ltr satisfactory MIRAGLIA: F J Licensing Branch 3 80/09/16 2pp
- F Security, medical, emergency & fire protection plans
- BOO9020134 Invites participation in BOOB22 workshop in Atlanta, GA to solicit comment re proposed functional criteria for emergency response facilities in NUREG-0696 Discussion to include location, size & staffing of emergency ctrs SEYFRITK V Region 4. Dallas, Office of the Director BO/08/12 ip
- 8009090532 Forwards "Evacuation Time Estimates for 10-Mile Emergency Planning Zone." in response to 800702 ltr DRAPER.E.L. Gulf States Utilities Co. 80/08/27 1p
- --B009090837 "Evacuation Time Estimates for 10-Mile Emergency Planning Zone " Approved by State of LA officials " Componwealth Edison Co BOBLINGER,L H , BORDAN,A J Louisiana, State of 80/08/29 34pp
- G Adjudicatory correspondence
- 8009170410 Act receipt of 800721 petition under 10CFR2 206 for halt to const of facilities based on allegations of questionable const practices Denies request for immediate action since public health & safety is not affected STELLO, V Office of Inspection & Enforcement, Office of the Director 80/08/18 2pp
- --8009170414 Act receipt of 800721 patition under 10CFR2 206 for helt to const of faculties based on allegations of questionable const practices Denies request for immediate action since public health & safety is not affected Forwards FR notice STELLO,V Office of Inspection & Enforcement, Office of the Director 80/08/18 2pp
- --8007170417 Notice of UCS 800721 request for action under 10CFR2 204 DEYDUND, R C , STELLD, V Office of Inspection & Enforcement, Office of the Director 80/08/18 1p
- B009090406 Order granting extension until 800922 for Commission to elect whether to review Director's 800818 decision under 100FR2 206 not to suspend CP CHILK, S J Office of the Secretary of the Commission 80/09/05 to
- 8007250039 Order granting extension until 800727 for Commission to elect whether to review Director's 800818 decision not to suspend const of facility under 10CFR2 206 CHILK.S J Office of the Secretary of the Commission 80/07/22

#### @ Inspection reports, IE Bulletins & correspondence

- 8009040511 Forwards IE Bulletin 80-07, "BWR Jet Pump Assembly Failure" No response required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/04/04
- 8009090039 Forwards IE Bulletin 80-07, Suppl 1, "BWR Jet Pump Assembly Failure "No response required SEYFRIT.K V Region 4. Dallas, Orfice or the Director BO/05/13
- 6007020534 Forwards Suppl 2 to IE Bulletin 80-17, "Failures Revealed By Testing Subsequent to Failure of Control Rods to Insert
  During Scram at BWR " No written response required
  SEYFRIT, X V Region 4. Dalias. Office of the Director 80/07/22
- E009030271 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Mercury-Retted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required SEYFRIT,K V Region 4. Dallas. Office of the Director 80/08/1 Region 4. Dallas, Office of the Director 80/08/15
- 8009140032 Forwards IE Info Notice 80-30. "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain OE BWR Facilities " Rospecific action or response requested SEYFRIT, K V Region 4. Dallas. Office of the Director BO/08/19
- 8007120075 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/08/22 60
- 8009170392 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required
  SEYFRIT, K V Region 4. Dallas, Office of the Director 80/08/22
- 8009120422 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Baver1 480 Voit Type K-600S & K-DON 600S Circuit Breakers " No written response required BEYFRIT.K V Region 4. Dallas. Office of the Director 80/08/27
- 8009300086 Submits response to 1E Bulletin 80-16 No Rosemount Model 1951 or 1952 pressure transmitters are to be used in safety-related applications DRAPERLE L Gulf States Utilities Co 80/09/05 2pp
- 8009270325 Ack receipt of 800805 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-458/78-04 & 50-459/78-04 SEIDLE-W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/09/10 ip
- --809270326 Forwards third annual status rept of progress of environ studies of effect of Alligator Bay Culver crossing in response to Request 3 of IE Insp Repts 50-458/78-04 & DRAPER,E L Gulf States Utilities Co GO/OB/O5 3pp DRAPER, E L

### DOCKET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1

- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for 007080080 Farwards draft NOREO-0594, "Functional Criteria for Emergency Response Facilities "Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0676 encl M/o NUREO EIEENHUIT,D 0 Division of Licensing 80/08/01 117pp
- 8009120099 Recommends listed stups be taken to reduce risk from ATWB events during interim period before required mods Requires submission of ATWB emergency operating procedure, YEDESCO.R L Assistant Director for Licensing 80/08/27 Spp
- 8009090496 Forwards addl geologic info re time of latest movements of earth faults on Gable Mountain near ctr of reservation. No conclusions re significance have been reached & info is not considered reportable under IOCFR21
  RENBERGER, D. L. Washington Public Power Supply System 80/09/02

## F Security, medical, emergency & fire protection plans

- 8009030267 Notifies of 800819.22 & 30 regional workshops re development workshops re developments or BOOBLY, 22 % 30 regional workshops re development of guidance for acceptable method for coping wemergencies at racility Requests that representative be sunt Subjurces to be discussed include function of facilities & location ENOEL/ENR H Region 5, San Francisco, Orfice of the Director BO/OB/12 2pp
- G Inspection reports, IE Bulletins & correspondence
- B009160622 Responds to IE Bulletin B0-16. "Potential Misapplication of Rosemount, Inc Models 1151 & 1152 Pressure Transmitters w/
  Either A or D Output Codes " No subj transmitters installed or planned to be installed in sarety-related sys
  RENBERGER.D.L. Washington Public Power Supply System 80/08/07
- 8009170393 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Stael Pipe" No SA-312 or A-312 Type 304 fusion welded pipe in use or planned for use in safety-related sys at facilities RENBERGER, D.L. Washington Public Power Supply System 80/08/07
- 8009240303 Forwards IE Info Notice 80-27, "Broken Studs on Terry Turbine Steam Inlet Flange" No written response required INSELKEN,R H Region 5, San Francisco, Office of the Director 80/08/07 1p
- 8009120304 Ferwards IE Insp Repts 50-460/80-08 & 50-513/80-08 on 800714-18 No noncompliance noted SPENGER.G B Region S. San Francisco. Reactor Construction & Engineering Support Branch 80/08/12
- --8009120309 IE Insp Repts 50-460/80-08 & 50-513/80-08 on 800714-18 No noncompliance noted Major areas inspected RCPB piping insulation & licensee action on previous insp findings DODDS: R T Region 5, San Francisco, Reactor Construction & Engineering Support Branch HERNANDEZ. G . WAGNER: W J Region 5, San Francisco, Office of the Director 80/08/08 App
- 8009030292 Forwards Revision 1 to IE Dulletin 80-19. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/08/15 1p
- 8009290302 Forwards IE Info Notice 80-27 re degradation of reactor coolant pump studs ENGELKEN.R II Region 5, San Francisco. Office of the Director 80/08/18
- 8009110415 Ack receipt of 800725 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-460/80-07 & 50-513/80-07 SPENCER.0 S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/08/20 1p
- --8009110422 Responds to NRC 800626 ltr re violations noted in 1E Insp Repts 50-460/80-07 & 50-513/80-07 Corrective actions rework support 174-3413-2910 completed Support 1T-4-3404-300A not completed RENBERGER, D.L. Washington Public Power Supply System 80/07/25 Зрр
- -8009110424 Forwards IE Insp Repts 50-460/80-07 & 50-513/80-07 on 800401-30 & notice of violation SPENCER & S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/06/26 2pp
- -- 8009110426 Notice of violation from insp on 800401-30 \* Region 5, San Francisco, Office of the Director 80/06/25
- --8009110429 IE Insp Repts 50-460/80-07 & 50-513/80-07 on 800401-30 DUYIIOMEY IE Insp Repts 50-460/BD-07 & 50-513/BD-07 on 800401 Noncompliance noted deficiency in area of cable tray support wolding TOTHIR D Region 5, San Francisco, Office of the Director DODDS,R T Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/05/25 12pp
- 8007160187 Forwards IE Circular 80-i8 "10CFRS0 57 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ENGELMEN.R. H Region 5. San Francisco. Office of the Director 80/08/22

- 8009120468 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 % K-DON 6008 Carcuit Breakers " No written response required EMSELKELR H Region 5, San Francisco, Office of the Director 80/08/27 1p
- 8009120609 Ack receipt of 800819 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-460/80-10 & 50-513/80-10
- ~~8009120616 Forwards IE Insp Repts 50-460/80-10 & 50-513/80-10 on 800602-09 % notice of violation SPENCER.O S Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/07/17 Zpp
- ---8009120622 Notice of violation from insp on 800602-09
  4 Region 5. San Francisco. Office of the Director 80/07/16 1p
- --8009120631 IE Insp Repts 50-460/80-10 & 50-513/80-10 on 800602-09 Nancompliance noted fillet welds on columns 22704 & 2283 undersized.contrary to contract specs TOTH.A D., DODDS.R T Region 5. San Francisco, Office of the Director 80/07/16 5pp
- 8009300346 Updates 800124 response to IE Bulletsn 79-02. Revision 2, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Anchor bolt loads on existing designs will be recalculated by 810228 Related data encil RENBERGER, D.L. Washington Public Power Supply System 80/09/25 700
- DOCKET 50-461 CLINTON POWER STATION, UNIT 1
- Application/construction stage documents & correspondence
- 009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities "Corments requested within days Proposed implementation schedule for meeting criteria odly Frequency implementation schedule for meeting City of NUREG-0676 encl H/o NUREG EISENHUT, D G Division of Licensing 80/08/01 119pp
- 1009150494 Approves 800218 request for exemption of cortain containment Spray & discharge piping from hydrostatic testing Request ro Code Case N-241 must be rewritten to include only submerged portions of referenced sys SCHWENCER.A Licensing Branch 3 80/08/18 3pp
- 8009220130 Advises that recurculation dustharge block valve mods are complete Mod plan, procedures & related documents available at site for review Work, authorized for OE, was subcontracted to Baldan Associates ROCH,L J Illinois Power Co 80/08/19
- O9180575 Advises of planned repairs to weld preps of Valve 1E22-F010 & Piping Spool 1-HP-1-6 % body of Valve 1E-22-F010 Baldwin Associates authorized to perform work SPENCER.J S Illinois Power Co 60/08/20 ip
- 1007040491 Forwards design info re Category 1 masonry walls, per NRC 800421 request Oversize drawings available in Central Files
- WULLER.G E Illinois Power Co 80/09/25 19pp
- 1009020341 Forwards 800807 ltr transmitting petition to amend Rule 203 (1) (10) (aa) of Chapter 3 of fL Pollution Control Board rules & regulations & supporting exhibits Etr petition & exhibits available in Central Files only WULLER. 0 E lilinois Power Co 80/08/27 ip
- 8007080193 Forwards Amend 3 to OL application, requesting authorization to operate for 40 yrs at power levels up to 2.894 MMt per unit FBAR environ rept.physical security plan & antitrust info encl KOCH.L J Illinois Pawer Co 80/08/29 2pp
- --8009080197 Amend 3 to application for OL Requests authorization to operate for 40 yrs at power levels up to 2,894 MHt per unit \* Illinois Power Co 80/08/31 140pp
- 8009190115 Notifies of completed GL application review MRC safety review will be initiated Early response to encl request for additing the FSAR & environ rept necessary to facilitate detailed technical review M/o encl
  EISENHUT, D G Division of Licensing 80/08/27 3pp

- 8009190754 Forwards request for add1 info to complete technical review of 791201 OL application Forwards NUREO-0694, "TMI Related Requirements for New OLs " W/o encl NUREO EISENHUT, D G Division of Licensing 80/08/29 52pp
- BOO9190513 Certifies that direct distribution has been made of licensing documents re acceptance review of Units 1 & 2 Certificates of Svc encl WULLERG E Illinois Power Co 80/09/15 App
- C Utility Environmental Report (ER), amends & correspondence
- 8009080202 Forwards environ rept.Vols 1 & 2 Also forwards Amend 3 to DL application, requesting authorization to operate for 40 yrs at power levels up to 2.894 libt per unit, FSAR, physical security plan & antitrust info KOCH, L. J. Illinois Power Co. 80/08/27 2pp
- --8009080209 Environ rept for facility.Vol 1 \* Illinois Power Co 80/08/29 7724pp
- --8007080211 Environ rept for facility, Vol 2 \* Illinois Power Co 80/08/27 726pp
- F Security, medical, emergency & fire protection plans
- BOO904040B Issues invitation to send representatives to participate in regional workshop re emergency response facilities Workshop will focus on presenting & discussing criteria, receiving comments & answering questions KEPPLER.J G Region 3. Chicago, Office of the Director BO/OB/11
- H General correspondence
- 8009080347 Informs of reorganization re three technical dapts put under single corporate officer Establishes OA at same reporting level as managers of facility operations & nuclear station engineering KOCH.L J Illinois Power Co 80/09/02 ip
- 8007270383 Responds to 1tr to President Carter re White House position on TMI accident Informs of re-examination of design & operation of nuclear power plants including emergency evacuation plans to cope w/potential accidents BCKWENCER.A Licensing Branch 3 80/09/09 ip
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8009090254 Forwards Clinton Units 1 & 2 FSAR Includes Revisions 1-3 KGCH.L J Illinois Power Co 80/08/29 2pp
- ---8009070258 Clinton Units 1 & 2 FSAR Includes Revisions 1-3 \* Illinois Power Co 80/08/29 7700pp
- 8009090262 Chapter 1 to Clinton Units 1 & 2 FBAR, "Introduction & General Description of Plant" Includes Revisions 1-3 \* Illinois Power Co 80/08/27 350pp
- 8009090244 Chapter 2 to Clinton Units 1 & 2 FSAR, "Site Characteristics " Includes Revisions 1-3 \* Illinois Power Co 80/08/29 1190pp
- 8007070247 Chapter 3 to Clinton Units 1 & 2 FSAR, "Design of Structures, Components, Equipment & Sys " Includes Revisions
- 8009090272 Chapter 4 to Clinton Units 1 & 2 FSAR, "Reactor " Includes Revisions 1-3 \* Illinois Power Co 80/08/29 32000
- 8009090276 Chapter 5 to Clinton Units 1 & 2 FSAR, "RCS & Connected Sys " Includes Revisions 1-3 \* Illinois Power Co 80/08/29 250pp
- 8009090279 Chapter 6 to Clinton Units 1 & 2 FSAR, "Engineered Safety Features." Includes Revisions 1~3 # I.linois Power Co 80/08/29 550pp
- 8007070283 Chapter 7 to Clinton Units 1 & 2 FSAR, "Instrumentation & Control Sys" Includes Revisions 1-3

  \* Illinois Pawer Co 80/08/27 850pp

- 8009090286 Chapter 0 to Clinton Units 1 & 2 FGAR, "Electric Power" Includes Revisions 1-3 • [Hilmors Power Co 80/08/29 185pp
- 8009090289 Chapter 9 to Clinton Units 1 % 2 FSAR, "Awailiary Sys" [ncludes Revisions 1-3 + Illinois Power Co 80/08/27 625pp
- 8007070273 Chapter 10 to Clinton Units 1 & 2 FSAR, "Steam & Power Conversion Sys " Includes Revisions 1-3 • Illinois Power Co 80/08/27 100pp
- 8009090296 Chapter ii to Clinton Units i & 2 FSAR. "Radwaste Hgt " Includes Revisions i-3 \* Illinois Power Co 80/08/29 200pp
- 8009090299 Chapter 12 to Clinton Units 1 & 2 FSAR, "Rediation Protection " Includes Revisions 1-3 \* Illinois Power Co 80/08/29 200pp
- 8009090301 Chapter 13 to Clinton Units 1 & 2 FSAR, "Conduct of Operations " Includes Revisions 1-3 \* Illinois Power Ca 80/08/29 150pp
- 6009090304 Chapter 14 to Clinton Units 1 & 2 FSAR, "Initial Test Program " Includes Revisions 1-3 • Illinois Power Co 80/08/29 150pp
- 8009090307 Chapter 15 to Clinton Units 1 & 2 FSAR, "Accident Analysis "
  Includes Revisions 1-3

  \* Illinois Power Co 80/08/29 400pp
- B009090310 Chapter 16 to Clinton Units 1 & 2 FSAR. "Tech Specs "
  Includes Revisions 1-3

  + Illinois Power Co 80/08/29 ip
- 8009090313 Chapter 17 to Clinton Units 1 & 2 FSAR. "QA" Includes Revisions 1-3 + Illinois Power Co 80/08/29 50pp
- 8009090317 App A to Clinton Units 1 & 2 FSAR, "Glossary " Includes Revisions 1-3 + 111inois Power Co 80/08/29 18pp
- 8009090321 App B to Clinton Units 1 & 2 FSAR: "Const Mat1 Stds & QC Procedures" Includes Revisions 1-3 s Ellinois Power Co 80/08/29 41pp
- 8009090323 App C to Clinton Units 1 & 2 FSAR. "Computer Programs " Includes Revisions 1-3 • Illinois Power Co 80/08/29 200pp
- 8009240457 Forwards proprietary info for FSAR Includes info re initial core fuel design for use of gadolinia & offgas sys tachnology Affidavit for withholding encl Info available in Central Files only
  HULLER.O E Illinois Power Co 80/09/17 6pp
- @ Inspection reports. IE Bulletins & correspondence
- 8009090043 forwards IE Bulletin 80-07. Suppl 1. "BWR Jet Pump Assembly Failure" No response required KEPPLER, J Q Region 3. Chicago, Office of the Director 80/05/14 lp
- 8009250346 Ferwards IE Insp Rept 50-461/80-11 on 800624-27 & notice of violation FighReLLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/18 2pp
- --8009250349 Notice of violation from insp on 800624-27

  \* Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/17 ip
- --8009250352 IE Insp Rept 50-461/80-11 on 800624-27 Noncompliance noted failure to follow procedures re storage of matls KNOP.R C , NEISLER, J , WESCOTT, H in Region 3, Chicago, Office of the Director 80/07/17 8pp
- 8007180043 Forwards IE Insp Rept 50-461/80-13 on 800709-10 No noncompliance noted FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/07 200

- --8009180061 IE Insp Rept 50-461/BO-13 on 800709-10 No noncompliance noted Major areas inspected station coundation subgrade preparation 8 concerns of certain employees not having access to NRC KHOP, R C . WESCOTT, H M . GALLACHER, E J . Region 3, Chicago, Office of the Director 80/08/05 App
- 8007090808 Responds to IE Bulletin 79-03A, "Longitudinal Weld Defects in ASME SA-31P, Type 304 Stainless Steel Pipe" No SA-312 or A-312. Type 300 series fusion welded pipe is planned for use in safety-related sys subj to stresses greater than 85% WULLER, G E Illinois Power Co 80/08/12 ip
- 8009260249 Forwards IX Insp Rept 50-461/80-15 on 800729-31 No noncompliance noted FIDRELLIO Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/14 2pp
- --8009260256 IE Insp Rept 50-461/80-15 on 800729-31 No noncompliance noted Mayor areas inspected reactor coolant pressure boundary b safety-related piping LEC.E N K. DANIELSON.D H. Region 3. Chicago. Office of the Director 80/08/11 5pp
- 8007030204 Forwards Revision ( to IE Bulletin 80-19, "Failures of Mercury-Netted Katris Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/08/15 to
- 8009150483 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE BWR Facilities " No specific action or response requested KEPPLER, J G Region 3: Chicago, Office of the Director 80/08/20
- 8009120053 Forwards Suppl 3 to IE Bulletsn 80-17. "Failure of Control Rods to Insert During Scram at BNR " No written response required KEPPLER, J.D. Region 3. Chicago, Office of the Director 80/08/22
- 8009170430 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER, J.G. Region 3. Chicago, Office of the Director 80/08/22
- 8009110631 Responds to IE Bulletin 80-16. "Potential Misapplication of Rosemount. Inc Models 1151 & 1152 Pressure Transmitters w/ Either A or D Dutput Codes " Pressure transmitters are not currently used on safety-related sys WULLER: 9 E Illinois Power Co. 80/08/23 1p
- 8009250457 Responds to IE Bulletin 80-19. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys or Operating Nuclear Fower Plants Designed by C-E ' No mercury-wetted switches are used in facility safety-related sys WULLER, G E Illinois Power Co 80/08/26 ip
- 8009100826 Ack receipt of 800723 % 0813 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-461/80-10 FIORELIA Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/28 ip
- --8009100830 Responds to NRC 800623 ltr re violations noted in IC Insp Rept 50-461/80-10 Corrective actions personnel reinstructed on requirements for performing safety-related activities GERSTMER.W C Illinois Power Co 80/07/23 2pp
- --8009100833 Responds to NRC 800623 lfr re violations noted in IE Insp Rept 50-461/80-10 Clarifies 800723 reply re authorization for drilling operation GERSTNER.W C Illinois Power Co 80/08/13 2pp
- 8009230073 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6005 5 K-DDN 6008 Circuit Breakers " No written response required KEPPLER, J O Region 3, Chicago, Diffice of the Director 80/08/28
- 8009250205 Ack receipt of 800818 itr informing NRC of steps taken to correct violations noted in IE Imap Rept 50-461/80-11 FIDRELLI.Q Region 3. Chicago, Reactor Construction & Engineering Support Branch 80708/30 ip

# DOCKETED ITEMS

- ~-8009250208 Responds to NRC 800718 ltr re violations noted in IE Insp Rept 50-461/80 11 Corrective actions safety-related & nonsarety-related cable reels in electrical cable laydown area were segregated KOCH-L J llinois Power Co 80/08/18 2pp
- 8009240104 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required KEPPLER, J.G. Region 3, Chicago, Office of the Director 80/09/10
- S Reportable occurrences. LERs & related correspondence
- 8007020188 Ack receipt of 800715 interim rept re status of investigation or Sargent & Lundy soil characteristics error Final rept will be reviewed upon receipt FIORELLIO Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/08/01 ip
- 8009250474 Ack receipt of 800819 interim deficiency rept re thin-walled elbow in reactor pressure vessel drain line Final rept will be revisued upon receipt FIORELLIG Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/08/30 ip
- 8009250252 Ack receipt of 800728 & 0815 deficiency repts re RHR heat exchanger lateral support provisions Confirms that addl stiffeners & supports will be installed to meet original design criteria FIGRELLI.O Region 3. Chicaga. Reactor Construction & Engineering Support Branch 80709705 ip
- 8009296339 Interim deficiency mept me failure of attachment welds swing barriers dividing termination cabinets into bays during shipment Repairs will not be completed until late 1981 No generic corrective action taken to avoid recurrence ROCH, L. J. Illinois Power Co. 80/09/22 Spp

## DOCKET 50-462 CLINTON POWER STATION, UNIT 2

- A Application/construction stage documents & correspondence
- BO09080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities "Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl N/O NUREG EISENHUT.D G Division of Licensing 80/08/01 119pp
  - 09150491 Approves 800218 request for exemption of certain containment spray & discharge piping from hydrostatic testing Request re Code Case N-241 must be rewritten to include only submerged portions of referenced sys SCHMENCER, A Licensing Branch 3 80/08/18 3pp
  - 0902034i Forwards 800807 ltr transmitting petition to amend Rule 203 (i) (10) (ad) of Chapter 3 of IL Pollution Control Board rules & regulations & supporting exhibits Ltr petition by exhibits available in Central Files only JULLER, 9 E Illinois Power Co. 80/08/27 1p
- 107080193 Forwards Amend 3 to Dt. application, requesting authorization to operate for 40 yrs at power levels up to 2,874 MWt per unit FSAR environ rept, physical security plan & antitrust info encl
  KOCH-L J Illinois Power Co 80/08/29 2pp
- -8009080197 Amend 3 to application for CL Requests authorization to operate for 40 yrs at power lovels up to 2,894 MWt per unit \* filings Power Co 60/08/31 140pp
- 3009190115 Notifies of completed OL application review NRC safety review will be initiated Early response to encl request for addline re FEAR & environ rept necessary to facilitate detailed technical review M/o encl
  EISC
- 1009190754 Forwards request for addl info to complete technical review of 791201 OL application Forwards NURRO-0694. "TMI Related Requirements for New Ols "W/o encl NUREO EISENRUT.D O Division of Licensing 80/08/29 52pp
- |009190513 Cortifies that direct distribution has been made of licensing documents re acceptance review of Units 1 % 2 Certificates of Svc encl WULLER 9 C Illinois Power Co 80/09/15 App

- C Utility Environmental Report (ER), amends & correspondence
- 8009080202 Forwards environ rept.Vols 1 & 2 Also forwards Amend 3 to OL application requesting authorization to operate for 40 yrs at power levels up to 2.894 MUt per unit.F9AR.physical security plan & antitrust info KOCH.L U Illinois Power Co 80/08/27 2pp
- --B009080209 Environ rept for facility, Vol 1 \* Illinois Power Co 80/08/29 7726pp
- ---80070802i1 Environ rept for facility, Vol 2
  4 Illinois Power Co 80/08/29 726pp
- F Security, medical, emergency & fire protection plans
- 8009040465 Issues invitation to send representatives to participate in regional workshop re emergency response facilities. Workshop will focus on presenting & discussing criteria, receiving comments & answering questions

  KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/11
- H General correspondence
- 8007080347 Informs of reorganization re three technical depts put under single corporate officer Establishes GA at same reporting level as managers of facility operations & nuclear station engineering KOCHL J Illinois Power Co 80/07/02 ip
- 8009290383 Responds to ltr to President Carter re White House position on TMI accident Informs of re-examination of design & operation of nuclear power plants including emergency evacuation plans to cope w/potential accidents
  SCHWEYCER. A Licensing Branch 3 80/09/09 ip
- K. Utility Final Safety Analysis Report (FSAR) & amends
- B009090254 Forwards Clinton Units 1 & 2 FSAR Includes Revisions 1-3 KDCH.L J Illinois Pawer Co B0/08/29 2pp
- --8007070258 Clinton Units 1 & 2 FSAR Includes Revisions 1-3 \* Illinois Power Co 80/08/29 7700pp
- 8009090262 Chapter i to Clinton Units 1 & 2 FSAR, "Introduction & General Description of Plant " Includes Revisions 1-3 \* Illinois Power Co 80/08/29 350pp
- 8009090266 Chapter 2 to Clinton Units 1 & 2 FSAR, "Site Characteristics " Includes Revisions 1-3 \* Illinois Power Co 80/08/29 1150pp
- 8009090269 Chapter 3 to Clinton Units 1 & 2 FSAR, "Design of Structures, Components, Equipment & Sys " Includes Revisions 1-3 \* 1111nois Power Co 80/08/29 1100pp
- 8007070272 Chapter 4 to Clinton Units 1 % 2 FSAR, "Reactor." Includes Revisions 1-3 \* 1111mpis Power Co 80/08/27 320pp
- 8009090276 Chapter 5 to Clinton Units 1 & 2 FSAR, "RCS & Connected Sys " Includes Revisions 1-3 \* Illinois Power Co 80/08/29 250pp
- 8009090279 Chapter 6 to Clinton Units 1 & 2 FSAR. "Engineered Safety Features " Includes Revisions 1-3 \* Illinois Power Co 80/08/29 550pp
- 8009090283 Chapter 7 to Clinton Units 1 & 2 FSAR, "Instrumentation & Control Sys " Includes Revisions 1-3 \* Illinois Power Co 80/08/29 850pp
- 8009090286 Chapter 8 to Clinton Units 1 & 2 FSAR, "Electric Power" Includes Revisions 1-3
  \* Illinois Power Co 80/08/29 185pp
- 8009090289 Chapter 7 to Clinton Units 1 & 2 FSAR, "Auxiliary Sys "
  Includes Revisions 1-3
  \* Illinois Power Co 80/08/29 629pp
- 8009090293 Chapter 10 to Clinton Units i & 2 FSAR, "Steam & Power Conversion Sys " Includes Revisions 1-3 \* Illinois Power Co 80/08/29 100pp

- 8009090296 Chapter 11 to Clinton Units 1 & 2 FSAR, "Radwaste Mgt " includes Revisions 1-3 f Illinois Power Co 80/08/29 200pp
- 8009090299 Chapter 12 to Clinton Units i & 2 FSAR, "Radiation Protection "Includes Revisions 1-3 + Illinois Power Co 80/08/29 200pp
- 8009090301 Chapter 13 to Clinton Units 1 & 2 FSAR, "Conduct of Operations" Includes Revisions 1-3 \* Illinois Power Co 80/08/29 150pp
- B009090304 Chapter 14 to Clinton Units 1 & 2 FSAR, "Initial Test Program" Includes Revisions 1-3 \* Illinois Power Co 80/08/29 150pp
- 8007090307 Chapter 15 to Clinton Units 1 & 2 FSAR. "Accident Analysis " Includes Revisions 1-3 4 Illinois Power Co 80/08/27 400pp
- 8009090310 Chapter 16 to Clinton Units 1 & 2 FSAR, "Tech Specs "
- Includes Revisions 1-3 # 111ings Power Co 80/08/29 1p
- 8009090313 Chapter 17 to Clinton Units 1 % 2 FSAR, "QA " Includes
- Ravisions 1-3 111:nois Power Co 80/08/29 50pp
- 8007090317 App A to Clinton Units 1 & 2 FBAR, "Glossary " Includes Revisions 1-3
- [11] ingis Power Co 60/08/29 18pp
- B009090321 App B to Clinton Units 1 % 2 FSAR. "Const Matl Stds & GC Procedures " Includes Revisions 1-3 # Illinois Power Co 80/08/29 4ipp
- 8007090323 App C to Clinton Units 1 & 2 FSAR. "Computer Programs "
  Includes Ravisions 1-3
  \* Illinois Power Co 80/08/29 200pp
- 8009240457 Forwards proprietary info for FSAR Includes info re initial core fuel design for use of gadolinia % offgas sys technology Affidavit for withholding encl Info available in Central Files only WULLER.O E Illinois Power Co 80/09/17 6pp
- Q Inspection reports. IE Bulletins & correspondence
- BO09070043 Forwards IE Bulletin 80-07. Suppl 1. "BWR Jet Pump Assembly Failure." No response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/05/14
- 8009090808 Responds to IE Bulletin 79-03A. "Longitudinal Held Defects in ABME SA-312. Type 304 Stainless Steel Pipe " No SA-312 or A-312. Type 300 series fusion welded pipe is planned for use in safety-related sys subj to stresson greater than 85% MVLLER.O E Illinois Power Co 80/08/12 ip
- 8009030204 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required
  KEPPLER.J Q Region 3. Chicago, Office of the Director 80/08/15
- 8009150483 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE BNR Facilities " No specific action or response requested
  REPPLER.J.Q Region 3. Chicago, Office of the Director 80/08/20
- 8009120053 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/22
- 8009170430 Forwards IE Circular 80-18, "10CFR50 59 Gafaty Evaluations for Changes to Radwaste Treatment Sys " No written response required KEPPLER. J. G. Region 3. Chicago, Office of the Director 80/08/22

- 8009110631 Responds to IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & (152 Pressure Transmitters of Either A or D Output Codes " Pressure transmitters are not Currently used on safety-related sys WULLER, G.E. Illinois Power Co. 80/08/23 1p
- 8009250457 Responds to IE Bulletin 80-19. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E 'No mercury-wetted switches are used in facility safety-related sys WULLER.O E Illinois Power Co 80/08/26 1p
- 8009230073 Forwards IE Info Notice 80-31. 'Maloperation of Gould-Brown Bover: 480 Voit Type K-6005 & K-DON 6005 Circuit Breakers " No written response required KEPPLER, J O Region 3. Chicago. Office of the Director 80/08/28
- 8009240104 Forwards IE Circular 80-21, "Regulation of Refueling Crews " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/10
- S Reportable occurrences, LERs & related correspondence
- 8009250252 Ack receipt of 800728 & 0815 deficiency repts re RHR heat exchanger lateral support provisions Confirms that addl stiffeners & supports will be installed to meet original design criteria FICRELLI, G Re ... Region 3. Chicago, Reactor Construction & Engineering ch 80/09/05 (p Support Branch
- DOCKET 50-466 ALLENS CREEK NUCLEAR STATION, UNIT 1 Q Adjudicatory correspondence
- B009050473 Add1 response to F0IA request for 20 documents for use as intervenor in facility proceeding Forwards nonproprietary version of NEOD-24154, Vols 1 ½ 2, "Oualification of One-Dimensional Core Transient Model for BHRs "W/o encl FELTON, J M Division of Rules and Records 80/08/12 1p
- 8009080065 Suppls 800801 response to FOIA request for 64 documents for use in facility proceeding Forwards addit documents listed in App A Items 38.61.64 \$ 65 have not been located W/a encls
  FELTON J K Division of Rules and Records 80/08/18 App
- 8009080447 Supplemental response to FOIA request for 64 decuments for use in faculity proceeding Forwards documents listed in App A M/o encis
  FECTOM J M Division of Rules and Records 80/08/22 2pp
- 8009020058 Response to Polthoff first set of interrogatories Restates facts from FES.NUREO-0470.re obstacles to production of methane from organic matl Marine biomass farm environ affects not evaluated Waffidavit & Certificate of Svc Assistant Director for Licensing 60/09/27
- 8009020066 Motions to strike second, third & fifth paragraphs of TX PIRQ & Dogget 800813 proposed emergency planning contention Proposes form to be admitted in proceeding Certificate of Syc enc 1 SOMINKLIS M Hearing Branch 3 80/08/27 7pp
- 8009040271 Response in apposition to W Schuessler, S Doggett & TX PIRG DOVOTOR Response in opposition to Wistnessier's bogget a TX Find BOOBIS reworded contention except portion re capability of plan w/location Remaining portions do not comply w/ASLB 800724 order Certificate of Svc encl RASKIN. D B . COPELAND. J G Houston Lighting & Power Co RASKIN. D B Lowerstein, Newman, Reis, Axelrad & Toll 80/08/28 12pp
- 8009090451 Urges ABLBP not to consider applicant 800B13 appeal for reconsideration of Jan 1981 hearing date Applicant is trying to harass other parties & deny due process in attempt to rush hearing MARRACK.D Affiliation Unknown 80/08/28 1p
- 8009040297 Forwards 800819 FR notice re amends to emergency planning regulations SDHINKI,8 M Hearing Branch 3 80/09/02 14pp
- 8009110014 Ack receipt of applicant 800822 ltm directed to RM Lazo Concurs w/applicant motion to set schedule for evidentiary hearings Supports any action that may move proceeding expeditiously BLACK.R L. Hearing Branch 1 80/09/09 3pp

80/09/19

- 8009170149 Motion for summary disposition of Contention 48 alleging superiority of South TX site to Allens Creek

  \* Texas Public Intelest Research Group 80/09/09 lp
- ---B009170153 Statement of matl facts as to which no genuine issues exist in support of motion for summary disposition of Contention 68 re superiority of South TK site + Texas Public Interest Research Group B0/09/09 2pp
- --8009170154 Affidavit in support of motion of summary disposition of Contention 68 re superiority of South TX site to Allens Creek Discusses environ & economic lissues JOHNSCH.C Texas Public Interest Research Group 80/09/09 7pp
- ---8009170157 Affidavit in support of summary disposition of Contention 6B re superiority of South TX site to Allens Creek
  BAXIOIH Texas Public Interest Research Group 80/09/05 4pp
- 8009180475 Further response to TX PIRO 16th interrogatories Discusses future prices of gas, nuclear & coal energy, personnel qualifications, control room design, safety relief valve setpoints & hydrogen explosion Certificate of Svc entl COPELAND, J G , NEHMAN, J R Houston Lighting & Power Co COPELAND, J G Baker & Botts 80/09/09 25pp
- 8009150253 Forwards revised Pages 7-10 % 13 to applicant 800807 response in apposition to TX PIRG Class 9 motion Applicant overlooked provision precluding parties from citing statements at open Commission meetings WCertificate of Svc NENMAN, J R Lowenstein, Neuman, Reis, Apelrad & Toll 80/09/10
  - 8009150256 Revised Pages 7-10 & 13 to response in opposition to TX
- JOO9160527 Response in opposition to NRC & applicant motions to strike portion of emergency planning contention Consolidated language does not incorporate new issues \* Terras Public Interest Research Group SCHUESSLER, W J Affiliation Unknown DOGGETT, S A Doggett, S A 80/09/10 2pp
- 9009160201 Mution for extension until 800919 to file affidavits in support of request for protective treatment re GE & Brown & Root documents Appropriate persons unavailable Certificate and Svc encl
  CULP.R H, COPELAND, J G Houston Lighting & Power Co
  Lowenstein, Newran, Reis, Azelrad & Toll 80/09/81 App
- CULE, R H
- O9180418 Motion for summary disposition of Contention 74 re environ impact of transmission lines DDI 780328 ltr to util, portions of EIG.Royal Soc for Protection of Birds 770822 ltr to TR Scottings & Certificate of Svc encl MARRHCK.D Marrack.D 80/09/i1 20pg
- 009160520 Order granting extension until 800919 for applicant to file affidavits due to unavailability of appropriate GE & Brown & Root officers
  - Atomic Safety and Licensing Board Panel 80/09/12 1p
- 009170223 Motion for summary disposition of Contention 43 (AC 8) re natural gas generation & for extension to file motion Alleges availability, sufficiency & superiority of natural gas as alternative to facility M/Certificate of Svc SCOTT, J M Texas Public Interest Research Group 80/09/12 ip
- --8009170225 Affidavit comparing natural gas generation to nuclear fission generation of electricity as superior alternative to facility JOHNSON.C Telas Public Interest Research Group. 80/09/09 12pp
- 8007180542 informs of no need to reconstitute ASLB due to prospect of imminent settlement, in response to 800822 ltr
  LAZO.R M Atomic Safety and Licensing Board Panel 80/09/15 ip
- 8009190229 Memorandum & order denying TX PIRC 800724 motion for preparation of suppl to EIS to Class 9 accidents NRC alone may bring cases warranting consideration of severe environ impacts to Commission attention LINENBERGER. G . WOLFE. S J Atomic Safety and Licensing Board Panel Брр
- 8009220417 Memorandum for PDR summarizing 800916 telcon w/J Robbins, legislative assistant to Congressman R Paul re results of 800915 conference Parties will be advised of hearing when decided WDLFE,S J Atomic Safety and Licensing Board Panel 80/09/16 ip

- ---8009220420 Forwards envelope addressed to Congressman R Paul for sending copy of ASLB 800916 memorandum FITT1.C Atomic Safety and Licensing Board Panel 80/09/17 2pp
- 8009220415 Order advising of B01201-05.08-12,15-19 & B10105 as convenient dates for hearing on environ matters Whether schedule is desirable & feasible must be decided by parties no later than B00926 WOLFE,S J Atomic Safety and Licensing Board Panel B0/09/17 2pp
- 8009260007 Response in opposition to applicant motion for to file affidavits Good cause required per ASLB 800713 prohearing conference directive not established MARRACK.D Affiliation Unknown 80/09/18 2pp
- 8009230691 Forwards affidavits of NC Cang & SH Grate of GE & Brown & Root, respectively, re claims that certain documents receive protective treatment Affidavits comply w/ASLB 800821 order Related correspondence Lowenstein, Newman, Reis, Axelrad & Toll 80/09/19 15pp
- 8009250058 Urder striking Paragraphs I.II & VI of Schuessler, TX PIRQ & Doggett consolidated contention Accepts Paragraphs III u/o Item (d).IV & V w/o Brazos River contamination Discovery shall cornence immediately & must be completed by 801020 LINENBERGER.G , HOLFE.S J Atomic Safety and Licensing Board Panel
- 8009240565 Forwards original affidavit by WO Gang re GE document known as Reed Rept W/o encl Related correspondence CULP.R H Lowenstein, Newman, Reis, Axelrad & Toll 80/09/22 Zpp
- B009300027 Response to FH Potthoff third set of interrogatories Objects to all questions due to irrelevancy Affidavits & Cartificate of Svc enci Related correspondence HANCOCK, D. NEWHAN, J.R. Houston Lighting & Power Co HANCOCK, D. Baker & Botts 80/09/22 9pp
- 8009260674 Memorandum warning intervening parties to read Rules of Practice & amends re svc of documents in adjudicatory proceedings Atomic Safety and Licensing Board Panel 80/09/23 16
- 8009260207 Forwards applicant response to first set of interrogatories Provides status of ASLB actions re final language of emergency planning contention Applicant will file updated response; if necessary, following review of ASLB order RASKIN.D B Lowenstein.Neuman.Reis.Axelrad & Toll 80/09/24 ip
- -8009260210 Response to intervenor Schuessier first set of interrogatories & requests for production of documents Requested documents & Certificate of 8vc encl RASKIN, D B Houston Lighting & Power Co RASKIN, D B Lowenstein, Newman, Reis, Axelrad & Toll 80/07/24 78pp
- 8009300012 Response to ASLB 800917 order proposing hearing schedule re environ issues Doherty may respond to applicant & NRC motion for summary disposition by B01023 Opposes TX PIRO motion for add1 time to move for disposition Certificate of Syc encl BLACK.R L Hearing Branch 1 80/09/25 Spp
- 8009303469 Response in opposition to JF Doherty 800915 motion for additime to reply to NRC & util motion for summary disposition Intervenor made no attempt to inspect documents needed for answers until 800911 W/Certificate of Svc & documentation COPELAND, J & NEMMAN, J R Houston Lighting & Power Co COPELAND, J & Baker & Botts 80/09/25 10pp
- 8009300456 Order admitting & consolidating intervenors amended contentions. Cumings 9, Griffith 1, Johnson 1 & Lemmer 1 Intervenors shall agree on lead party Discovery shall start immediately & be completed by 801027 LINENBERGER, G. A. WOLFE, S. J. Atomic Safety and Licensing Board Panel 2010 14 Зрр
- H General correspondence
- 8009240540 Provides Subcommittee an Oversight & Investigations w/status of actions re results of hearing on facility CP application, in response to concerns of C Johnson w/intervenor TX PIRO FR excerpt encl PIRCKS, W J Office of the Executive Director for Operations PIRCKS, N J D 80/09/19 6pp
- U Congressional/Executive Correspondence
- 8009170268 Urges immediate action be taken to institute long overdue formal hearings on CP Related correspondence LOEFFLER, T House of Rep. 80/09/12 ip

- 8009240483 Requests that NRC set date for CP hearing on new nuclear power plant Related correspondence PICKLE, J J House of Rep 80/09/17 ip
- DOCKET 50-467 ALLENS CREEK NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for DOYOBOOBO Forwards draft NUREO-0845. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0876 encl W/a NUREO ETBENHUT.\$ 0 Division of Licensing 80/08/01 119pp
- G Adjudicatory correspondence
- 8007050473 Add1 response to FOIA request for 20 documents for use as intervenor in facility proceeding Forwards nonproprietary version of NEDO-24154, Vols 1 & 2. "Qualification of One-Disensions! Core Fransient Model for BMRs "(1/o encl FELTO)& J M Division of Rules and Records 80/08/12 1
- 8007050065 Suppls 800801 response to FOIA request for 64 documents for use in facility proceeding Forwards add1 documents listed in App A Items 38.61.64 % 65 have not been located H/o encis
  FELTON, J M Division of Rules and Records 80/08/18
- 8009080449 Supplemental response to FOIA request for 64 documents for use in facility proceeding Forwards documents listed in App A W/o encls FELTON.U II Division of Rules and Records 80/08/22 2pp

- BCO9240340 Provides Bubcommittee on Oversight & Investigations w/status of actions Te results of hearing on facility CP application in response to concerns of C Johnson w/intervenor TC PIRG FR excerpt entl
  DIRGKS.N J Office of the Executive Director for Operations DIRCKS.N J O 80/09/19 App
- SOCKET 50-471 PILORIM NUCLEAR POWER STATION, UNIT 2
- 4 Application/construction stage documents & correspondence.
- 3009080080 Forwards draft NUREQ-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREO EISENHUT, D 0 Division of Licensing 80/08/01 119pp
- Security, medical, emergency & fire protection plans
- 3009090569 Forwards recommendation for Item 3 1 6/3 2 4 re cable combustibility for fire protection review Recommends that licensee be required to coat okonite & kerite cables HALL.R E Brookhaven National Laboratory 80/07/14 3pg
- Adjudicatory correspondence
- 1009100421 Motion to include latest util 10-yr energy & peak demand forecasts in 790718 hearings re need for power Urgos opportunity to suppl findings of fact by all parties redecline in growth rates Certificate of Svc encl
  WRIGHT.F S Massachusetts, State of 80/09/03 7pp
- 009190277 Responds to FDIA request for 15 documents listed in bibliography of NURCO-0625. "Rept of Siting Policy Task Force " Documents 6-8 % 13 are available in PDR Forwards remaining documents FELTON.J M Division of Rules and Records 80/09/04
- -BOO91905B7 Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants, for determination of site acceptability & adequacy of engineered safety features MINDOUS.R B Office of Standards Development, Director, SECY-79-362 79/06/04 7pp
- -8009190630 Requests that encl, "Differences in Procedures for Estimating Atmospheric Dispersion Conditions at Inland & Coastal Sites," be sent to appropriate Boards SCINTO, J F Hearings Division 79/04/04 16pp

- 8009250049 Response stating no objection w/o conculring in State of MA motion to suppl hearing record on need for power re energy to peak demand forecasts Reserves right to appose future attempts to reopen record Certificate or Svc encl LEWALD.G H. DIGNAN.T G. Boston Edison Co. LEWALD.G H. Ropes & Gray. 80709718 Spp.
- 8009260310 Response stating no objection to State of MA 800903 motion to suppl record on need for power w/applicant & NEPOOL latest 10-yr power demand forecasts Objects to conclusory & argumentative content of motion Certificate of Svc encl GODDARD.R J Hearing Branch 2 80/09/24 5pp
- DOCKET 50-472 PILGRIM NUCLEAR POWER STATION, UNIT 3 F Socurity, medical, emergency & fire protection plans
- 8009090569 Forwards recommendation for Item 3 1 6/3 2 4 re cable combustibility for fire protection review Recommends that licensee be required to cost okonite 3 kerite cables HALLAR E Brookhaven National Laboratory BO/07/14 Jpp
- DOCKET STN-50-482 WOLE CREEK GENERATING STATION
- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for EISENHUT.D O Division of Licensing 80/08/01 119pp
- 8009030685 Describes interim actions needed prior to issuance of UL to further reduce risk from ATHS before required plant mods, as determined by Commission, are completed ATMS emergency operating procedure should be submitted TEDESCO.R L Division of Licensing 80/08/15 3pp
- 8009030541 Forwards addl info that resulted from preliminary review of PERRY NO. 200731 request
  PETRICK.N A Standardized Nuclear Unit Power Plant System
  B0/08/28 10pp
- 8009190773 Notification of 801007 & 08 meeting w/util in Burlington,KA to discuss NRC case load forecast
  STARK,R M Licensing Branch 1 80/08/29 App
- .8009300397 Comments on draft NUREG-0696 AIF comments endorsed Deletion recommended for sections prohibiting use of plant process computer to process info for emergency response facilities SCHMDERER.F. Standardized Nuclear Unit Power Plant Bystem 80/09/24 3pp
- F Security, medical, emergency & fire protection plans
- 8009020140 Invites participation in 800822 workshop in Atlanta. QA to solicit comment re proposed functional criteria for emergency response facilities in NUREG-0676 Discussion to include location size & staffing of emergency ctrs
  SEYRRIT, K V Region 4, Dallas, Office of the Director 80/08/12
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8009190441 Forwards Revision 1 to SNUFPS FSAR, containing responses to NRC acceptance review questions & add1 info generated since initial FSAR submittal in Oct 1979 PETRICK,N A Standardized Nuclear Unit Power Plant System 80/09/17 ip
- --- 8009190445 Revision 1 to SNUPPS FSAR, containing responses to NRC
- @ Inspection reports. IE Bulletins & correspondence
- B009100047 Discusses IE Insp Rept 50-482/80-12 on 800606-10 & forwards notices of violation and deviation BEIDLE.W C Region 4. Dallas. Reactor Construction & Engineering Support Branch 80/06/19 2pg
- --8009160052 Natice of violation from into an 800406-10 Noncompliance noted failure to establish housekeeping zone designations \* Region 4. Dallas. Office of the Director 80/06/19 ip

- --8007100059 Notice of deviation from insp on 800606-10 Noncompliance noted failure to establish fire protection & prevention requirements.
  - \* Region 4. Dallas, Office of the Director 80/06/19 1p
- 8009150014 Responds to IE Bulletin 80-08 re examination of containment liner penetration welds Design uses flued head for penetration connections Field installation just begun & nondestructive examination results not available KDESTER.O L. Kansas Gas & Electric Co. 80/07/01 App
- 8009170384 Forwards IE Insp Rept 50-482/60-16 on 800708-11 No noncompliance noted SEIDLE.U C Region 4. Dalias, Reactor Construction & Engineering Support Branch 80/07/16 2pp
- --8009170387 IE Insp Rept 50-482/80-16 on 800708-11 No noncompliance noted Major areas inspected licenses action on previous insp findings, site tour & review of procedures & records for welding CROSSMAN, WA Region 4, Dalias, Office of the Director HALL, R E, GLISERT, L D Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/07/16 3pp
- 8009090644 Forwards IE Insp Rapt 50-482/80-12 in June, 1980 SEIDLE, W.C. Region 4: Dallas, Reactor Construction & Engineering Support Branch 80/07/21 2pp
- --8009090648 IE Insp Rept 50-482/80-12 in June 1980 Noncompliance noted failure to establish housekeeping ione designation & to establish fire protection & prevention requirements GBERG, C R. HUBACEK, W. G., CROSSMAN, W. A. Region 4, Dallas, Office of the Director 80/07/18 7pp
- 1009150342 Forwards IE Insp Rept 50-482/80-15 on 800630-0703 & notice of violation SEIDLE N C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/07/28 App
- --8009150345 Notice of violation from insp on 800630-0703 \* Region 4. Dallas. Reactor Construction & Engineering Support Branch 80/07/25 2pp
- --8009150348 IE insp Rept 50-482/80-15 on 800630-0703 Noncompliance noted failure to provide appropriate procedures for activities affecting quality MARTIM-L E. OBERG-C R. CROSHAN,W A. Region 4, Dallas, Office of the Director 80/07/25 Spp
- 1009030263 Forwards Revision i to IE Bulletin BO-19. "Failures of Mercury-Notted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required SEYRIT, K V Region 4. Dallas, Office of the Director 80/08/15 to Page 10 per 10 per
- 009150334 Ack receipt of 800624 ltr informing NRC of steps taken to correct deviation noted in IE Insp Rept 50-482/80-08 Add1 info required SEIDLE.U C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/08/20 ip
- --8009150381 Responds to NRC 809523 itr re deviation noted in IE Insp Rept 50~482/80-08 Corrective actions Raceway Seismic Test Program conducted by AE confirmed structural adequacy of commercial grade cable trays KOESTER.O L. Kansas Gas & Electric Co. 80/06/24 2pp
- 8009170096 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/08/22 ip
- 8009170416 Responds to IE Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters identified transmitters are not used in safety-related areas One hundred fifty manhours expended for review PETRICK.N A Standardized Nuclear Unit Power Plant System 50/08/26 1p
- 8009120426 Forwards IE info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6009 & K-DON 6005 Circuit Breakers" No written response required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/08/27 ip
- 800930060B Ack receipt of 800828 itr informing NRC of steps taken to correct violation noted in IE Insp. Rept 50-482/80-15 SEIDLE-W C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/09/15 ip

- --B009300612 Responds to NRC 800728 ltr re violation noted in IE [ns) Rept 50-482/80-15 Corrective actions Daniel procedures to be revised for controlling insp & inskallation of supports & raceway more effectively KDESTER.G L Kansas Gas & Electric Co 80/08/28 3pp
- S Reportable occurrences, LERs & related correspondence
- 8009170442 Deficiency rept re excessive pressures in feedwater lines following postulated high energy line break Pressure can be reduced by relocating feedwater check valves Util no longer considers matter reportable under 10CFR90 59e PETRICK:N A Standardized Nuclear Unit Power Plant System 80/06/30 ip
- 8009290218 Discusses investigation of 3 5 inch diameter nuts & bolts used in NSSS lateral supports Bolts & nuts provide adequate safety margins against thread failure at max design load flatter not reportable per 10CFRSO 55e KOESTER: 0 L Kansas Gas & Electric Co 80/07/28 1p
- 8009150193 Ack receipt of 800724 final deficiency rept re loose bushings in pips support sway struts CARLSON.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/08/06 1p
- --8009150196 Final deficiency rept re loose bushings in pipe support tway struts Struts found with loose bushings will be replaced Corner & Lada 800724 rept encl PETRICK, N A Standardized Nuclear Unit Power Plant System 80/07/24 100p

#### DOCKET STN-50-483 CALLOWAY PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 8007080080 Forwards draft NUREC-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT. D O Division of Licensing 80/08/01 119pp
- 8009090982 Informs that "accepted" version of CL application, consisting of CL application, vol 1, SNUPPS FSAR Vol 1-9 & FSAR Addendum Vol 1-9 will be sent under separate cover 8000ER, J L Division of Rules and Records 80/08/14 ip.
- 8009030672 Pescribes interim actions needed prior to issuance of OL to further reduce risk from ATWS before required plant mods, as determined by Commission, are completed, ATWS energency operating procedure should be submitted TEDESCO,R L. Division of Licensing 80/08/15 2pp
- 8009020093 Forwards Dames & Moore 800729 rept, "Results of Detailed Excavation Mapping, Ultimate Heat Sink Area, Essential Svc Water Sys, & Unit 1 Power Block Subgrade, Callaway Plant, Units 1 & 2 "
  SCHNELL, D F Union Electric Co 80/08/25 1p.
- ---8007020097 "Results of Detailed Excavation Mapping, Ultimate Heat Gina Area Essential Svc Water Sys. & Unit 1 Power Block Subgrade, for Facilities " 4 Dames & Moore 80/07/29 83pp
- 8009030541 Forwards add1 info that resulted from preliminary review of FSAR per 800731 request PETRICK.N A Standardized Nuclear Unit Power Plant System 80/08/28 10pp
- 8009230770 Notification of 801007 % 10 meetings w/util in Motane & Fulton.KD to discuss NRC case load forecast STARK.R M Licensing Branch 1 80/08/29 App
- G Adjudicatory correspondence
- 8009270034 Response in opposition to JG Read 800910 petition to intervene Unges denial w/o prejudice to refile petition within 25 days after ruling Concerns of petitioner unclear H/appearance statement & Certificate of Svc LESSY,R P Antitrust Division 80/09/25 6pp
- 8009300570 Response in opposition to JO Reed Sept 1980 petition requesting deferral of OL issuance until local emergency response is adequately operational Intervention defective, but limited appearance feasible Certificate of Svc encl. CHARNOFF, G. BAXYER, T. A. Union Electric Co. CHARNOFF, G. Bhaw. Pittman, Potts & Trombridge 80/09/25 App

- 8009020127 Responds to 800625 ltr & L Drey concerns re accountability of in-place embedded anchors Addl testing necessary to develop data to substantiate anchor acceptability NRC evaluation to be conducted following testing completion DIRCKS.W J Office of the Executive Director for Operations 80/08/04 2pp
- 800912026B Bubmits petition to withhold issuance of GL until adequate local emergency response capability has been planned funded & made operationally effective REED.J G Affiliation Unknown 80/09/10 2pp
- M Utility Final Safety Analysis Report (FSAR) & amends
- BCC9190441 Forwards Revision 1 to SNUPPS FSAR, containing responses to NRC acceptance review questions & add1 info generated since initial FBAR submittal in Oct 1979 PETRICK:N A Standardized Nuclear Unit Power Plant System BD/09/17 ig
- ~~BOG9170445 Revision 1 to GNUPPS FSAR containing responses to NRC acceptance review questions & add1 info generated since initial FSAR submittal in Oct 1979 Includes description of changes made to attain cold shutdown

  \* Standardized Nuclear Unit Power Plant System BD/09/17 1500pp
- 8009230662 Forwards Revision 1 to FSAR site addendum BRYAN, J K Union Electric Co 80/09/18 1p
- --8009230667 Revision 1 to FSAR site addendum
  4 Union Electric Co 80/09/18 200pp
- @ Inspection reports, IE Bulletins & correspondence
- 8009030218 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Hercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/15
- 8009170440 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Bys " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/22
- 8009170416 Responds to 1E Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters Identified transmitters are not used in safety-related areas One hundred fifty manhours expended for review FETRICK.N A Standardized Nuclear Unit Power Plant System 80/08/26 ip
- 8009230041 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-6005 & K-DON 6008 Circuit Breakers " No written response required KEPPLER.J O Region 3. Chicago. Office of the Director 80/08/28
- B009240122 Forwards IE Circular 80-21, "Regulation of Refueling Craws " No written response required KEPPLER, J. Q. Region 3, Chicago, Office of the Director B0/09/10
- S Reportable occurrences. LERs & related correspondence
- 8009170442 Deficiency rept re excassive pressures in feedwater lines following postulated high energy line break Pressure can be reduced by relocating feedwater check valves Util no longer considers matter reportable under 10CFR50 55e PETRICK.N A Standardized Nuclear Unit Power Plant System 80/06/30 ip
- 8009150193 Ack receipt of 800724 final deficiency rept re loose bushings in pipe support sway struts CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/08/05 1p
- --8009150196 Final deficiency rept re loose bushings in pipe support sway struts Struts found with loose bushings will be replaced Corner & Lada 800724 rept enci
  PETRICK.N A Standardized Nuclear Unit Power Plant System 80/07/24 10pp

- 8009020331 Ack receipt of 800730 interim deficiency rept re Berger-Paterson pipe support strut w/mechanical shock arrestor FIORELLI.G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/13 ip
- 8009100070 Ack receipt of 800731 final deficiency rept re anchor bolt thread tolerance FIDRELLI,0 Region 3, Chicago. Reactor Construction & Engineering Support Branch 80/08/19 Ip
- --8009100080 Final deficiency rept re NSSS lateral support anchor bolt nuts Had noncomportance gone undetected no significant safety problem would have arisen Item withdrawn as significant deficiency BRYAN.J K. Union Electric Co. 80/07/31 1p
- 8009090546 Final deficiency rept re adequacy of application & insp of fireproofing maths applied to structural steel previously reported on 800801 Defective areas noted in reinsp will be reworked to assure application conformance BRYAN. J K Union Electric Co 80/08/29 ip
- 8009230651 Final deficiency ropt no putential bolt head-pipe clamp interferance which could hinder full function of Bergen-Patterson pipe support strut assemblies Bechtel Power Corpadvised that all assemblies corrected prior to shipment BRYAN, J K Union Electric Co 80/09/10 2pp
- DOCKET STN-50-485 STERLING POWER PROJECT NUCLEAR, UNIT t Q Inspection reports. IE Bulletins & correspondence
- 8009030059 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Metted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/08/15 19
- 8009180051 Forwards IE Circular 80-18, '10CFR30 59 Safety Evaluations for Changes to Radwasto Treatment Sys " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/08/22 1p
- 8009120213 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Bover: 480 Volt Type K-6008 & K-DON 4008 Circuit Breakers "
  No written response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/08/27 ip
- 8009230798 Forwards IE Circular 80-21, 'Regulation of Refueling Craws " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/09/10 ip
- 8009240335 Forwards IC Info Notice 80-32. "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls" No written response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/09/12 ip
- S Reportable occurrences, LERs & related correspondence
- 8009170442 Deficiency rept re excessive pressures in feedwater lines following postulated high energy line break Pressure can be reduced by relocating feedwater check valves Util no longer considers matter reportable under 1007R50 55e PETRICK.NA Standardized Nuclear Unit Power Plant System 80/06/30 ip
- DOCKET STN-50-486 CALLOWAY PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8007080080 Forwards draft NUREG-0676, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0676 encl M/O NUREG EIGENHUT.D G Division of Licensing 80/08/01 119pp
- 8009090082 Informs that "accepted" version of OL application, consisting of OL application. Vol 1. SNUPPS I SAR Vol 1-9 & FSAR Addendum Vol 1-5 will be sent under separate cover SOUDER, J L Division of Rules and Records 80/09/14 1p

- 8009030672 Describes interim actions needed prior to issuance of OL to rurther reduce risk from ATWS before required plant mods, as determined by Commission, are completed ATWS emergency operating procedure should be submitted TEDESCO,R L Division of Licensing 80/08/15 2pp
- BO07020073 Forwards Dames 5 Moore 800729 rept. "Results of Detailed Excavation Mapping.Ultimate Heat Sink Area Essential Svc Water Sys. b. Unit 1 Power Block Subgrade.Callaway Plant. Units 1 & 2 "
  SCHWELL, D F Union Electric Co 80/08/25 ip
- --8007020077 "Results of Detailed Excavation Mapping, Ultimate Heat Sink Area.Essential Svc Water Sys. & Unit 1 Power Block Subgrade. For Facilities " 4 Dames & Moore 80/07/27 83pp
- 8009030541 Forwards additinfo that resulted from preliminary review of FSAR per 800731 request PETRICK.N A Standardized Nuclear Unit Power Plant System 80/08/28 10pp
- 8009230770 Notification of 801009 & 10 meetings w/util in Mokane & Fulton, MO to discuss NRC case load forecast STARK,R M. Licensing Branch 1. 80/08/29 6pp

# G Adjudicatory correspondence

R009290034 Response in opposition to JC Reed B00910 petition to intervene Urges denial w/o prejudice to refile petition within 25 days after ruling Concerns of petitioner unclear W/appearance statement 5 Certificate of Svc

105300570 Response in opposition to JQ Reed Sept 1780 petition requesting deferral of OL issuance until local emergency response is adequately operational intervention defective, but limited appearance feasible Certificate of Svc encl CHARNOFF, Q. BAXTER, T. A. Union Electric Co. CHARNOFF, Q. Shaw, Pittman, Potts & Troubridge 80/09/25 4pp

# H General correspondence

8009020127 Responds to 800629 ltr Z. L. Drey concerns to accountability of in-place embedded anchors Addl testing necessary to develop data to substantiate anchor acceptability NRC evaluation to be conducted following testing completion DIRCKS: If J. Dffice of the Executive Director for Operations 80/08/04 2pg

O9120268 Submits petition to withhold issuance of OL until adequate local emergency response capabilisty has been planned funded & made operationally effective REED, J 9 Affiliation Unknown 80/09/10 2pp

# Utility Final Safety Analysis Report (FSAR) & amends

- 3009190441 Forwards Revision 1 to SNUPPS FSAR, containing responses to NRC acceptance review questions & addl info generated since initial FSAR submittal in Oct 1979 PETRICK. N A Standardized Nuclear Unit Power Plant System 80/09/17 ip
- --8009190445 Revision 1 to SNUPPS FSAR, containing responses to NRC acceptance review questions & add1 info generated since initial FSAR submittal in Oct 1979 Includes description of changes made to attain cold shutdown

  # Standardized Nuclear Unit Power Plant System 80/09/17 1609pp
- B009230662 Forwards Revision 1 to FSAR site addendum BRYAN.J K Union Electric Co 60/09/18 1p
- --8009230267 Revision 1 to FSAR site addendum → Union Electric Co 80/09/18 200pp
- G Inspection reports, IE Bulletins & correspondence
- 8009030218 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Kercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER. J G Region 3. Chicago, Office of the Director 80/08/15 to

- 8009170440 Forwards IE Circular 80-18, "10CFR50 57 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response regulred KEPPLER.J G Region 3. Chicago. Office of the Director 80/08/22
- 8009170416 Responds to IE Bulletin 80-16 re potential misapplication of Rosembunt pressure transmitters Identified transmitters are not used in safety-related areas One hundred fifty manhaurs expended for review PETRICK. N A Standardized Nuclear Unit Power Plant System 80/08/26 ip
- 8009230061 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover( 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/28
- 8009240122 Forwards IE Circular 80-21. "Regulation of Refueling Craus" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/09/10
- 8 Reportable occurrences, LERs & related correspondence
- BO09170442 Deficiency rept re excessive pressures in feedwater lines following postulated high energy line break Pressure can be reduced by relocating feedwater check valves Util no longer considers matter reportable under 10CFR50 55e PETRICK.N A Standardized Nuclear Unit Power Plant System 80/06/30 1p
- 8009150193 Ack receipt of 800724 final deficiency rept re loose bushings in pipe support sway struts CARLSONR T Region i. Philadelphia. Reactor Construction & Engineering Support Branch 80/08/06 ip
- --8009150196 Final deficiency rept re loase bushings in pipe support way struts Struts found with loase bushings will be replaced Corner & Lada 800724 rept encl PETRICK,N A Standardized Nuclear Unit Power Plant System 80/07/24 10pp
- 8007020331 Ack receipt of 800730 interim deficiency rept re Berger-Paterson pipe support strut w/mechanical shock arrestor FIDRELI.6 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/08/13 ip
- 8009100070 Ack receipt of 800731 final deficiency rept re anchor bolt thread tolerance FIORELLI,O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/08/19 ip
- --8007100080 Final deficiency rept re NSSS lateral support anchor bolt nuts Had nonconformance gone undetected no significant safety problem would have arisen Item withdrawn as significant deficiency BRYAN, J. K. Union Electric Co. 80/07/31 ip

DOCKET SYN-50-488 PERKINS NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8009080080 Forwards draft NUREC-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREC-0696 encl W/o NUREG EISENHUT.D G Division of Licensing 80/08/01 119pp

## Q Adjudicatory correspondence

- 8007030696 Notice of appeal from ASLB 800222 partial initial decision re-alternative sites Seeks exceptions re-ASLB 780717 order which limited reopening of record to evidence re-staff analysis of site alternative Certificate of Svc encl PFEFFERKORN, W Pfefferkorn & Cooley, P A 80/08/27 48pp
- 8009050297 Forwards notice of appeal & brief Requests oral argument on issues
  BPRINGER, D Affiliation Unknown 80/09/02 ip
- -8007050300 Notice of appeal from ASLB order denying appellant 800415 motion NRC misrepresented to ASLB state position re availability of once-through-cooling No consideration given to alternative sites
  SPRINGER, D Affiliation Unknown 80/09/02 Zpp

- --B039050303 Brief of D Springer in support of 800415 petition to hear oral argument re opposition to location of facilities No consideration given to how energy, water & financial resources can be conserved Certificate of Evc encl SPRINGER.D Affiliation Unknown 80/09/02 7pp
- 8009050437 Notice of reconstitution of ASLAB in proceeding AS Rosenthal assigned chairman, JH Buck & TS Moore members
  BISHOP, C J Atomic Safety and Licensing Appeal Panel 80/09/02
- 8009160176 Motion for extension until 800930 to respond to A Springer appeal from ASL8 800814 denial of 800415 petition to intervene Parties including A Springer have no objection to such extension Certificate of Svc encl BARTH, C A Hearing Branch 3 80/09/12 3pp
- 8009170116 Order granting extension until 800924 for NRC to file brief re D Springer 800902 appeal from ASLB 800814 order denying intervention BIBHDP,C J Atomic Safety and Licensing Appeal Panel 80/09/15
- 8009180537 Order granting extension until 800924 for all parties to file responsive briefs on D Springer appeal BISHOP,C J Atomic Safety and Licensing Appeal Panel 80/09/15
- 8009250015 Motion for 30-day extension to file brief re intervenors' H00827 exceptions to ASLB B00222 partial initial decision Counsel involved in serious family matter Certificate of Svc enci Granted on 800922 PFEFFERKORN, W Pfefferkorn 3 Cooley, P A 80/09/18 2pp
- BCC9260251 Responsive brief in opposition to D Springer 800902 notice of appeal & brief from ASLB 800814 order denying petition to intervene Urges affirmation of order due to unjustified late intervention Certificate of Svc encl
  BARTH.C A Hearing Branch 3 80/09/24 27pp
- 8009290028 Responsive brief in opposition to D Springer 800902 notice of appeal from ASLB 800814 order denying petition to intervene Urges affirmation of order due to unjustifiable late intervention Certificate of 8vc encl MCGARRY.J M PDRYER.W L Duke Power Co MCGARRY.J M Debevoise & Liberman 80/09/24 18pp
- O Inspection reports. IE Bulletins & correspondence
- 8007020211 Submits response to IE Bulletin 79-03A No SA-312 or A-312. Type 300 series fusion welded pipe in use or planned for use is subj to design stresses greater than 85% of ASME code allowable stresses
  DAILLL C Duke Power Co 80/08/06 ip
- 8009020139 Responds to IE Bulletin 80-20. Failure of Westinghouse Type W-2 Spring Return to Neutral Control Switches " Review showed no Westinghouse Type W-2 switches used in safety-related applications
  DAIL.L C Duke Power Co 80/08/14 lp
- 8009030137 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Hercury-Webted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/15
- B007160133 Forwards IE Circular 80-18, "10CFR50 89 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY.J P Region. 2, Atlanta, Office of the Director 80/08/22
- 8009120576 Responds to IE Bulletin 80~16 No Rosemount Models 1151 & 1152 pressure transmitters are used in safety-related applications
  DAILL C Duke Power Co 80/08/26 ip
- 8009120300 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bovert 480 Volt Type K-6008 & K-DDN 6008 Circuit Breakers " No written response required G'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/08/27
- 8009120212 Responds to IE Bulletin 80-19. Revision 1 No mercury-wetted matrix relays are used or planned for use in reactor protection sys
  DAILL C Duke Power Co 80/08/29 1p

- 8009290293 Forwards IE Circular 80-21." Regulation of Refueling Crews "No written response required O'REILLY. J P Region 2, Atlanta, Office of the Director 80/09/10 5pp
- DOCKET STN-50-489 PERKING NUCLEAR STATION, UNIT 2

  A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISENHUT, D G Division of Licensing 80/08/01 119pp
- O Adjudicatory correspondence
- 8009030696 Notice of appeal from ASLB 800222 partial initial decision re-alternative sites Seeks exceptions re-ASLB 780717 order which limited reopening of record to evidence re-staff analysis of site alternative Certificate of Svc encl PFEFFERKORN.W Pfefferkorn & Cooley, P A 80/08/29 48pp
- 8009050297 Forwards notice of appeal & brief Requests oral argument on issues SPRINGER, D. Affiliation Unknown 80/09/02 ip
- --8009050300 Notice of appeal from ASLB order denying appealant 600415 motion NRC misrepresented to ASLB state position re availability of once-through-cooling No consideration given to alternative sites SPRINGER, D Affiliation Unknown 60/09/02 2pp
- --8009050303 Brief of D Springer in support of 800415 petition to hear oral argument re opposition to location of facilities No consideration given to how energy, water & financial resources can be conserved Certificate of Svc encl SPRINGER.D Affiliation Unknown 80/09/02 7pp
- 8009050437 Notice of reconstitution or ASLAB in proceeding AS Rosenthal assigned chairman, JN Buck & 18 Moore members
  BISHOP, C. J. Atomic Safety and Licensing Appeal Panel 80/09/02
- B009160176 Motion for extension until B00930 to respond to A Springer appeal from ASLB B00814 denial of B00415 petition to intervene Parties including A Springer have no objection to such extension Certificate of Bvc encl
- 8009170116 Order granting extension until 800924 for NRC to file brief re D Springer 800902 appeal from ASLB 800814 order denying intervention BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/09/15
- 8009180537 Order granting extension until 800924 for all parties to file responsive briefs on D Springer appeal 815HDP.C J Atomic Safety and Licensing Appeal Panel 80/09/15
- 8009250015 Motion for 30-day extension to file brief re intervenors' 800929 exceptions to ASLB 800222 partial initial decision Counsel involved in serious family matter Certificate of 8vc entl Granted on 800922 PFEFFERKORN.H Pfefferkorn & Cooley, P A 80/09/19 2pp
- 8009260251 Responsive brief in apposition to D Springer 800902 notice of appeal & brief from ASLB 800814 order denying petition to intervene Urges affirmation of order due to unjustified late intervention Certificate of Evc encl 8ARTH.C A Hearing Branch 3 80/09/24 27pp
- 8009290028 Responsive brief in apposition to D Springer 800902 notice of appeal from ASLB 800814 order denying petition to intervene Urges affirmation of order due to unjustifiable late intervention Certificate of Svc encl MCGARRY, J M. Perenew L. Dute Power Co. MCGARRY, J M. Debevoise & Liberman 80/09/24 18pp
- G Inspection reports, IE Bulletins & correspondence
- 8009020211 Submits response to IE Bulletin 79-03A No SA-312 or A-312, Type 300 series fusion welded pipe in use or planned for use is subj to design stresses greater than 85% of ASME code allowable stresses BAILL C. Duke Power Co 80/08/06 ip

- B009020137 Responds to IE Bulletin B0-20. Failure of Westinghouse Type M-2 Spring Return to Neutral Control Switches " Review showed no Westinghouse Type W-2 switches used in safety-related applications

  DAIL.L C Duke Power Co 80/08/14 1p
- 80D9030137 Forwards Revision 1 to IE Sulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Hritten response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/15 10
- 8009160133 Forwards IE Circular 80-18. "10CFRSO 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/22 to
- 8007120576 Responds to IE Bulletin 80-16 No Rosemount Models 1151 & 1152 pressure transmitter, are used in safety-related applications
  DAIL.U. C. Duke Power Co. 80/08/26 1s
- 8009120300 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-600S & K-BDN 600S Circuit Breakers " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/27
- 8009120212 Responds to IE Bulletin 90-17.Revision I No mercury-wetted materix ralays are used or planned for use in reactor protection sys

  DAIL.L. C Dute Power Co 80/09/29 Ip
- 007290293 Forwards IE Circular 80-21," Regulation of Refueling Crews " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/10 555
- DOCKET STN-50-490 PERKINS NUCLEAR STATION: UNIT 3

  G Adjudicatory correspondence
- 8009030696 Notice of appeal from ASLB 800222 partial initial decision re-alternative sites Seeks exceptions re-ASLB 780717 order which limited reopening of record to evidence re-staff analysis of site alternative Certificate of Svc encl PFEFFERKORN, W Pfefferkorn & Cooley, P A 80/08/29 48pp
  - )09050297 Forwards notice of appeal & brief Requests oral argument on issues SPRINGER,D Affiliation Unknown 80/09/02 1p
- 8009050300 Notice of appeal from ASLB order denying appellant 800415 motion NRC misrepresented to ASLB state position re availability of once-through-cooling No consideration given to alternative sites SPRINGER, D. Affiliation Unknown 80/09/02 2pp
- -6009050303 Brief of D Springer in support of 800415 potition to hear dral argument re opposition to location of facilities No consideration given to how energy, water & financial resources can be conserved Certificate of Syc encl SPRINGER, D Affiliation Unknown 80/09/02 7pp
- 009050437 Notice of reconstitution of ASLAB in proceeding AS Rosenthal assigned chairman, JH Buck & TS Moore members
  BISHOP.C J Atomic Safety and Licensing Appeal Panel. 80/09/02
- 8009160176 Motion for extension until 800930 to respond to A Springer appeal from ASLS 800814 denial of 800415 petition to intervene Parties including A Springer have no objection to such extension Certificate of Svc encl
- 8009170116 Order granting extension until 800924 for NRC to file brief re D Springer 800902 appeal from ASLB 800814 order denying intervention BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/09/15 200
- 8009190537 Order granting extension until 800924 for all parties to file responsive briefs on D Springer appeal BISHOP.6 J Atomic Safety and Licensing Appeal Panel 80/09/15 in

- 8009250015 Motion for 30-day extension to file brief re intervenors' 800829 exceptions to ASLB 800222 partial initial decision Counsel involved in serious family matter Certificate of Svc encl Granted on 800922 PFEFFERKORN, W Pfefferkorn & Cooley, P A 80/09/18 2pp
- 8009260251 Responsive brief in opposition to D Springer 800902 notice of appeal & brief from ASLB 800814 order denying petition to intervene Urges affirmation of order due to unjustified late intervention Certificate of Svc encl
  BARTH.C A Hearing Branch 3 80/09/24 27pp
- 8007290028 Responsive brief in opposition to D Springer 800902 notice of appeal from ASLD 800814 order denying petition to intervene Urges affirmation of order due to unjustifiable late intervention Certificate of Svc oncl KCGARRY.J M. PORTER.W. Duke Power Co. MCGARRY.J M. Debevoise & Liberman 80/09/24 18pp
- G Inspection reports, IE Bulletins & correspondence
- 800902011 Submits response to IE Bullstin 79-08 No 8A-312 or A-312. Type 300 series fusion welded pipe in use or planned for use is subj to design stresses greater than 85% of ABME code allowable stresses DAIL.L C Duke Power Co 80/08/06 ip
- 8009020139 Responds to IE Bulletin 80-20. Failure of Westinghouse Typs W-2 Spring Return to Neutral Control Switches, "Review showed no Hestinghouse Type W-2 switches used in safety-related applications
  DAIL, C Duke Power Co 80/08/14 1p
- B009030:37 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Mercury-Netted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY. J P Region 2. Atlanta, Office of the Director B0/08/15 to
- 8009160133 Forwards IE Circular 80-18, "10CFR50 59 Bafety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22 ip
- 8009120576 Responds to IE Bulletin 80-16 No Rosemount Models 1151 & 1152 pressure transmitters are used in safety-related applications BAIL. C Duke Power Co 80/08/26 ip
- 8009120300 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-600S & K-DDN 6008 Circuit Breakers"
  No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/27 ip
- 8009120212 Responds to IE Bulletin 80-19.Revision 1 No mercury-wetted matrix relays are used or planned for use in reactor protection sys. DAIC.L C Duke Power Co 80/08/29 1p
- 8009290293 Forwards IE Circular 80-21." Regulation of Refueling Crews \*\*
  No written response required
  D'REILLY, J P Region 2. Atlanta, Office of the Director 80/09/10
- DOCKET STN-50-491 CHEROKEE NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8007080080 Forwards draft NUREC-0696. "Functional Criteria for Energancy Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREC-0696 encl W/o NUREC EISENHUT, D 9 Division of Licensing 80/08/01 119pp
- 8009090037 Submits interim actions for plant operation, pending final resolution of ATMS Emergency operation procedural review may include NRC site visit prior to issuance of OL TEDESCO.R L Assistant Director for Licensing 80/08/27 3pp
- G Inspection reports, IE Bulletins & correspondence
- 8007020211 Submits response to IE Bulletin 79-03A No SA-312 or A-312. Type 300 series fusion welded pipe in use or planned for use is subj to design stresses greater than 85% of ASME code allowable stresses

  DAIL. C Duke Power Co 80/08/06 1p

- 8009020139 Responds to IE Bulletin 80-20. Failure of Westinghouse Type W-2 Spring Return to Neutral Control Switches " Review showed no Westinghouse Type W-2 switches used in safety-related applications
  DAILL C Duke Power Co 80/08/14 1p
- 8009030137 Forwards Revision 1 to IE Sulletin 80-19. "Failures of Mercury-Wetted Matrix Rolays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08
- 8009160133 Forwards IE Circular 80-18, "JOCFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 60/08/22
- 8009120576 Responds to IE Bulletin 80-16 No Rosemount Models 1151 & 1152 pressure transmitters are used in safety-related applications
  DAILL C Duke Power Co 80/08/26 ip
- 8009120300 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Bovers 480 Volt Type K-6005 & K-DDN 6008 Circuit Breakers "
  No written response required
  O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/27
- 8009120212 Responds to IE Bulletin 80-19. Revision 1 No mercury-wetted matrix relays are used or planned for use in reactor protection sys DAILL C Dute Power Co 80/08/29 1p
- 8009290293 Forwards IE Circular 80-21." Regulation of Refueling Crews " No written response required O'REILLY,J P Region 2, Atlanta, Office of the Director BD/09/10 Soc

## DOCKET STN-50-492 CHEROKEE NUCLEAR STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for DOYOUNDED FORWARDS GRAFT NOREU-LOSS. "Functional Criteria for Emergency Response Facilities "Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/o NUREO EISEENHUT,D O Division of Licensing 80/08/01 119pp
- 8009090037 Bubmits interim actions for plant operation pending final resolution of ATMB Emergency operation procedural review may include NRC site visit prior to issuance of OL TEDESCO,R L Assistant Director for Liconsing 80/08/25 80/08/29
- G Inspection reports, IE Bulletins & correspondence
- 8009020211 Submits resonne to IE Bulletin 79-03A No SA-312 or A-312. Type 3DD series fusion welded pipe in use or planned for is subj to design stresses greater than 85% of ASME code allowable stresses

  DAIL, L. C. Duke Power Co. 80/08/06 ip
- 8009020139 Responds to IE Bulletin 80-20. Failure of Westinghouse Type W-2 Spring Return to Neutral Control Switches "Review showed no Westinghouse Type W-2 switches used in safety-related applications

  DAIL.L C Duke Power Co 89/08/14 ip
- 8009030137 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Mercury-Wettod Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required.

  O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08 Region 2, Atlanta, Office of the Director 80/08/15
- 8009160133 Forwards IE Circular 80-19, "100FR50 59 Safety Evaluations for Changes to Radwasto Treatment Sys " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/22
- 8009120576 Responds to IE Bulletin 80-16 No Rosemount Models 1151 & 1152 pressure transmitters are used in safety-related applications Duke Power Co 80/08/24 1p DAIL L C

- 8009120390 Forwards IE Info Notice 80-31. 'Maloperation of Guuld-Brown Bover: 480 Voit Type K-6005 & K-DON 6008 Circuit Breakers " No written response required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/08/27 1 p
- 8009120212 Responds to IE Bulletin 80-19, Revision 1 No mercury-wetted matrix relays are used or planned for use in reactor protection sys
  DAIL-L C Duke Power Co 80/08/29 1p
- 8009290293 Forwards IF Circular 80-21, 'Regulation of Refueling Crews " No written response required O'REILLY J P Region 2. Atlanta, Office of the Director 80/09/10
- DOCKET STN-50-493 CHERDKEE NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NURE3-0496, "Functional Criteria for Emergency Response Facilities Comments requested within 30 days Praposed Implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISEN-MUT-D G Division of Licensing B0/08/01 L19pp
- 8009090037 Submits interim actions for plant operation, pending final resolution of ATMS Emergency operation procedural review may include NRC site visit prior to issuance of EL TEDESCO.R L Assistant Director for Licensing 80/08/29 3pp
- G Inspection reports, IE Bulletins & correspondence
- 8009020211 Submits response to 1E Bulletin 79-03A No SA-312 or A-312. Type 300 series fusion welded pipe in use or planned for use is subj to design stresses greater than 85% of ASME code allowable stresses Duke Power Co 80/08/06 1p
- 8009020139 Responds to IE Bulletin 80~20. Failure of Westinghouse Type W-2 Spring Return to Neutral Control Switches " Review showed no Westinghouse Type W-2 switches used in safetyrelated applications
  DATL.L C Duke Power Duke Power Co 80/08/14 ip
- 8009030137 Forwards Revision 1 to 1E Bulletin 80-19. "Failures of Mercury-Netted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Reg Region 2. Atlanta, Office of the Director 80/08/15 1 p
- 8009160133 Forwards IE Circular 80-18, "100FR50 59 Bafety Evaluations for Changes to Radwaste Treatment Sys " No written response O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/22
- 8009120576 Responds to IE Bulletin 80-16 No Rosemount Models 1151 & 1152 pressure transmitters are used in safety-related applications DAIL L C Duke Power Co 80/08/26
- 8009120300 Forwards IE Info Notice 80-31. "Malaperation of Gould-Brown Boveri 480 Volt Type K-6005 8 K-DDN 6008 Circuit Breakers " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/08/27
- 8009120212 Responds to IE Bulletin 80-19.Revision 1 No mercury-wetted matrix relays are used or planned for use in reactor protection sys DAIL.L.C. Duke Power Co 80/08/29 1p
- 8009290293 Forwards IE Circular 80~21." Regulation of Refueling Crews " No written response required

  O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/09/10
- DOCKET STN-50-498 BOUTH TEXAS PROJECT, UNIT 1
- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREG-0696. "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 entl M/o NUREG EISENHUT, D & Division of Licensing 80/08/01 119pp

- 8009030272 Forwards request for addl info re instrumentation & control sys in order to complete evaluation of facility FSAR TEDESCO.R L. Assistant Director for Licensing 80/08/15 9pp
- 8007080201 Forwards info & response to NRC questions re Category I masonry calls Fifty-four eversite drawings available in Central Files only DPREA.0 O Houston Lighting 3 Power Co 80/09/04 Bpp
- f Security, medical, emergency & fire protection plans
- 8009020147 Invites pairicipation in 800822 workshop in Atlanta, 0A to solicit comment le proposed functional criteria for emergency response facilities in NUREO-0696 Discussion to include location, size 6 staffing of emergency thrs. SEYFRIT, K. V. Region 4. Dallas, Office of the Director 80/08/12 to
- G Adjudicatory correspondence
- 800905036: Requests extension until 801001 to respond to order to show cause. Item 7 re design change control program

  OPREA.G U Houston Lighting & Power Co 80/08/28 3pp
- 8009040241 Forwards recently promulgated amends to emergency planning regulations DN Boidenick is lead counsel per encl notice of appearance RL Black backup counsel N/a encls
  BORDENICK, B M Hearing Branch 4 80/09/02 2pp
- 80091(0369 Confirms conversation re objection & intent not to respond to util 800825 interrogatories & document requests Factual discovery closed sinte 800314 Interrogatories are ill-timed as efforts have been made to encourage settlement STAHL.D M. Isham. Lincoln & Seale 80/09/08 1p
- 300917036f Submits status of rept on settlement negotiations on behalf of TX-LA Electric Cooperative of TX. Inc No unresolved issues exist at present Certificate of Svc entl BUNCHETTE.W H Northcutt Ely 80/09/11 3pp
- 8007250042 Memorandum & order, CLI-80-32, denying Citizens Concerned About Nuclear Power & Citizens for Equitable Utils request for hearing on IC 800430 order to show cause re deferral of safety-related const until completion of mods Waddi views CHILK, S. J. Office of the Secretary of the Commission 80/07/22 200
- 8005250045 Addendum to Commission 800922 memorandum & order.CLI-80-32 Feetnate re ALAB-594 was omitted from JF Ahearne separate views CHILK, S J. Office of the Secretary of the Commission 80/09/22
- D9250020 Advises that parties may contact BM Bordenick if desiring to borrow 800817 public meeting transcript for review purposes JORDENICK, B M Hearing Branch 4 80/09/23 ip
- (U09300030 Memorandum & order advising parties to agree on contentions reflecting NRC 800430 show cause order CLI-80-32, but not within 0A/OC Contentions 1 & 2 Rept on issues must be filed by 801015 b identification of add idiscovery by 801201 BECHHOEFER. C Atoms: Safety and Licensing Board Panel 80/09/24
- ( General correspondence
- 8007020108 Responds to 800808 ltr Advises that heat-induced illness being watched closely at plants Const has progressed to point that most work being done indoors Applicants have taken steps to improve welking conditions by adding fans DENION, HR Office of Nuclear Reacts: Regulation, Director 80/08/12 lp
- --8007020112 Informs that TX experiencing severe heat wave Requests that const on nuclear reactors be halted until temp at normal level for season Numarky impossible for const workers to do excellent work required LEVINE, If R Affiliation Unknown 80/07/08 1p
- K Utility Final Safety Analysis Report (FSAR) & amends
- BOO9150559 Forwards Amend 12 to FSAR
  OPREA, 9 N Houston Lighting & Power Co 80/09/15 5pp
- --8009150561 Amend 12 to FSAR # Houston Lighting & Power Co 80/09/15 140pp

- 8007250051 Certifies svc of Amend 12 to FSAR, on 800915 \* Houston Lighting & Power Co 80/09/15 2pp
- M Antitrust correspondence
- 8009040196 Response to applicants, Central & South West Corp & City of Austin. To objections to TX Border Cooperative petition to intervene Asserts interests under LBP-74-13 Urges full party participation W/Certificate of Svc O'NEIL.R A Southwest Texas Electric Cooperative O'NEIL.R A Miller. Balis & O'Ne(1 80/07/31 16pp
- 8009020202 Requests that info be provided to all parties re wheeling rate development per 800826 discussions Discusses principles to be considered re smaller util participation in facility ounership SPIEGEL. O Spiegel & McDiarmid SPIEGEL. O Brownsville. TX 80/08/28 4pp
- 8009030721 Advises that appropriate steps have been taken to insure svc of status repts & pleadings CHANANIA.F D Antitrust Division 80/08/29 ip
- 8009040289 Joint motion for partial revision of ASLB 800813 order re procedural schedule Suggests 800912 for settlement status repts.800915 for prehearing conference 9 801112 for evidentiary hearing commencement Certificate of Svc encl CHANANIA.F D Antitrust Division FLYNN, P G Houston Lighting & Pawer Ca FABRIKANT.R Justice.Dept of 80/08/29 7pp
- 8009090483 Forwards typescript version of intervenor Utils Board of City of Brownsville.TX 800829 proposed modified license conditions POIRIER.M R Spiegel & McDiarmid 80/09/03 10pp
- 8007100261 Designates WA Russell of WA Russel & Associates as expert engineering witness which DDJ may call at trial of facility licensing proceeding MCMILLENN H Justice.Dept of BD/09/03 1p
- 8009110792 Order revising procedural schedule set in ASLB 800B13 order Settlement status rept shall be submitted on 800912, prehearing conference shall commence on 800915, trial briefs on 80100B & 22 & evidentiary hearing on 801112 MILLER, N & Atomic Safety and Licensing Board Panel 80/09/08 200
- 8009150417 Motion to compel Central Power & Light response to 800828 interrogatories Objection erroneous due to necessity to know full scope of take-over plans W/DM Stohl 800908 ltr. excerpts of util corrected discovery & Certificate of 8vc SPIEGEL, G , POIRIER, H R Brownsville, TX SPIEGEL, G Bpiegel & McDiarmid 60/09/11 23pp
- 8009160332 Notifies that City of Austin has reached tentative agreement to settle w/NRC & DOJ re proposed license conditions
  Settlement contingent on final wording of draft document.
  Final version projected for 800915
  BALDUGH, R C Texas, State of 80/09/11 2pp
- 8009160275 Notice of taking WP Sayles & T Russell of CP&L 800923 & 24 depositions Examination will address possible purchase of Brownsville electric util sys & related studies & issuance of bonds Certificate of Svc encl POIRIER, MR & Spiegel & McDiarmid 80/09/12 7pp
- B009170188 Settlement status rept Author approval of terms of stipulated licensing conditions not yet given No position on issues & procedures presented Certificate of Svc encl JOHN, D F, HUMTER, M South Texas Electric Cooperative JOHN, D F Medinaelectric Cooperative, Inc. 80/09/12, 5pp
- 8009170359 Settlement status rept per ASLR 800813 order Agreement reached by util·NRC & DOJ which will dispose of all Comanche Peak issues when approved by ASLB Encl stypulation will insure DL would not violate antitrust laws SAMPLES, M D , KNOYTS, J B Texas Utilities Generating Co SAMPLES, M D Worsham, Forsythe & Sampels, 80/09/12 2pp
- 8009170229 Fourth settlement status rept Stipulations w/applicants embodying two sets of license conditions accomplished Final position re need for hearing will be submitted after examination of conditions by parties W/Certificate of Svc. CHARANIA, F.D. Antitrust Division 80/09/14 7pp
- --B007170239 Stipulation incorporating encl license condition w/o admission of violation to antitrust laws FABRIKANT,R Justice, Dept of CHANANIA,F D Antitrust Division STAHL, D M Central & South West Corp B0/09/12 20pp

- B009160157 Settlement status rept per ASLB 800B13 order Endorses and stipulation re license conditions reached by DOJ.NRC.FERC & Houston Lighting & Power Resolves concerns evidencing intent to litigate DDE endorsed settlement entirely in FERC case COPELAND.J & Houston Lighting & Power Co COPELAND.J & Baker & Botts 80/09/15 2pp
- --8009i&0i60 Stipulation incorporating license conditions Licensee past or planned action w/o conditions not inconsistent w/ antitrust laws Conditions do not consistitute admission or violations Certificate of Svc encl FABRIKANT, R Justice-Dept of CHANANIA, F D Antitrust Division STAHL, D Houston Lighting & Power Co 80/09/15 17pp
- 8009160192 Settlement status rept per ASLB 80813 order Requests unspecified extension to receive & review new arguments & to determine & submit unresolved issues License conditions & settlement re FERC not yet received W/Certificate of Svc POIRIER, M.R. Brownsville, TX. POIRIER, M.R. Spiegel & McDiarmid 80/09/15 9pp
- 8009170177 Settlement status rept Suggests approval of stipulated license conditions to maintain situation consistent w/ antitrust laws FERC & SEC approval of & interconnections necessary for settlement execution Certificate of Svc encl STAHL.D M Central & South West Corp STAHL.D M Isham, Lincoln & Deale 80/09/15 12pp
- BO091B0460 Suppl status rept per ASLB B00813 order DOJ reached agreement u/parties in Comanche Peak proceedings re proposed set of license conditions Agreement reached w/applicant in South TX proceeding Certificate of Svc encl HCMILLEN,N H Justice, Dept of 80/09/15 7pp
- 8009250028 Order granting extension until 800929 for Commission to review ALAB-608 CHILK, S. J. Office of the Secretary of the Commission B0/09/22
- 800926031B Motion for one-day extension to file comments on proposed settlement conditions Last minute consultations & discussions needed Certificate of Svc encl POIRIER. H R Brownsville, TX POIRIER, H R Spiegel & McDiarmid B0/09/24 App
- 8009300035 Comments on proposed settlements ger ASLB 800915 directive Proposed license conditions will serve to preclude or limit consideration of competitive implications of dc ties by FERC Certificate of Svc encl O'NEIL.R A Southwest Texas Electric Cooperative O'NEIL.R A Miller, Balis & O'Neil 80/09/24 12pp
- B009300488 Confirms that JR Choukas-Bradley was authorized to express position of Miller, Balis & O'Neil, P C on behalf of TX Border Cooperatives at 800919 status hearing re leave to intervene out of time O'NEIL, R A Miller, Balis & O'Neil 80/09/24 2pp
- --8007300476 Comments of TX Border Cooperatives on proposed settlements of NRC & DOJ re licensing proceedings Certificate of Svc enc!
  O'MEIL,R A Miller,Balis & O'Neil O'NEIL,R A Texas Border
  Cooperatives 80/09/24 10pp
- 8009300013 Mation in opposition to 800912 proposed license conditions due to failure to address crucial issues re effects of ac & dc interconnections Urges further proceedings to cure inconsistency w/antitrust laws Certificate of Svc encl SPIEGEL. G., JABLON, R.A., ROTH, A.J. Brownsville, TX: 80/09/25 32pp
- 8009300326 Order granting extension until 800925 for all parties to comment on 800915 stipulation & licensing conditions MOLFE, B. J. Atomic Safety and Licensing Board Panel 80/09/25 ip
- 8009300833 Comments on stipulation & proposed license conditions
  Recommends approval although solution to all antitrust
  problems is not guaranteed through incorporation of
  conditions Reserves right to be full party if hearing held
  JOHN, D.F. South lexas Electric Cooperative JOHN, D.F.
  Hedinaelectric Cooperative, Inc. JOHN, D.F. McDermott, Will & Emery
  80/09/25 2pp
- --B009300542 Motion for one-day extension to comment on stipulation & proposed license conditions Ratification at Board of Directors 800935 meeting needed Certificate of Svc encl JCHN, D.F. South Texas Electric Cooperative JCHN, D.F. Medinaelectric Cooperative, Inc. JCHN, D.F. McDermott, Will & Emery B0/09/24 & App

### N Antitrust hearing transcripts

- 8009190764 Transcript of 800915 prehearing conference in Bethesda.MD Pp 1078-1138 \* Atomic Safety and Licensing Board Panel 80/09/15 44pp
- 9 Imspection reports, IE Bulletins & correspondence
- 8007050525 Forwards IE Insp Repts 50-478/80-17 & 50-499/80-17 on 800623-26 No noncompliance noted SEIDLE.N C Region 4. Dallas. Reactor Construction & Engineering Support Branch 80/07/16 2pp
- --8009050533 IE Insp Repts 50-498/80-17 & 50-499/80-17 on 800623-26
  No noncompliance noted Major areas inspected const
  activities including observation of work & review of records
  pertaining to IE insp Repts 50-498/79-19 & 50-499/79-19
  HALL.R E Region 3. Chicago, Reactor Construction & Engineering
  Support Branch TAPLA, J I. CHAUDHARY, S K. Region 3. Chicago,
  Office of the Director 80/07/16 7pp
- 8007170380 Forwards IE Insp Repts 50-479/80-16 & 50-497/80-16 during June 1980 No noncompliance noted SEIDLE.N C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/07/16 2pp
- --8009170395 IE Insp Repts 50-498/80-16 & 50-499/80-16 during June 1980
  No nuncompliance noted Major areas inspected insp of safetyrelated components containment structural steel welding @A
  records sys & mgt meetings
  CROSSMAN, W A , PHILLIPS, H S Region 4. Dallas, Office of the
  Director 80/07/16 5pp
- 8009180467 Submits response to 1E Bulletin 80-08 Plant contains flued head penetration design w/containment boundary butt welds between penetration alseve & process piping Penetration welds radiographically examined GPREA.G W. Houston Lighting & Power Co. 80/08/04 7pp
- 8009180473 Confirms understanding to IE Bulletin 79-03A Pipe stress evaluation will be limited to calculations concerned w/pressure BARKER, D.G. Houston Lighting & Power Co. 80/08/05 Ip
- 8009180461 Submits response to 1E Bulletin 79-03A Desired info should be available for submittal by 801030 OPREA.0 W Houston Lighting & Power Co 80/08/06 2pp
- 8009250402 Forwards IE Insp Repts 50-498/80-19 & 50-499/80-19 on 800722-24 No noncompliance noted SEIDLE.N C Region 4. Dallas. Reactor Construction & Engineering Support Branch 80/08/08 2pp
- --8009250405 IE Insp Repts 50-498/80-19 & 50-499/80-19 on 800722-24
  No noncompliance noted Major areas inspected records re IE
  Insp Repts 50-498/79-19 & 50-499/79-19 findings on earthwork & concrete
  HALLIR E , TAPIA, J 1 Region 4, Dallas, Reactor Construction &
  Engineering Support Branch CROSSMAN, W A Region 4, Dallas,
  Office of the Director 80/08/08 5pp
- 8009030159 Ack receipt of 800722 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-498/77-03 & 50-499/77-03 SEIDLE:N C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/08/14 ip
- --B009030170 Responds to NRC ltr re violations noted in IE Insp Repts 50-498/77-03 & 50-499/77-03 Corrective actions sys of reviews & muititiered supervision implemented OPREA G W Houston Lighting & Power Go B0/07/22 2pp
- 600903026B Forwards Revision i to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays'in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/08/15
- 8009300098 Forwards IE Insp Repts 50-498/80-20 & 50-499/80-20 on 800728-29 No noncompliance noted BEIDLE.W C Region 4, Dallas. Reactor Construction & Engineering Support Branch 80/08/18 2pp
- --B009300102 IE Insp Repts 50-498/80-20 t 50-499/80-20 on 800728-29
  No noncompliance noted Major areas inspected issuance &
  disposition of nonconformance repts
  YOMLINSON,D P : HALL,R E Region 4, Dallas, Reactor Construction &
  Engineering Support Dranch CROSSMAN,W A Region 4, Dallas,
  Office of the Director B0/08/12 3pp

- 8009170394 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required SEYFRIT,X V Region 4. Dallas, Office or the Director 80/08/22
  - 1p
- 8009300546 Submits response to IE Bulletin 80-16 Rosemount Model 1151 or 1152 pressure transmitters will not be used in any safety-related applications and submitted and
- 8009300555 Submits response to IE Bulletin 80-19 Mercury-wetted relays are not used in reactor protection sys OPREA.G W Houston Lighting & Power Co 80/08/26 2pp
- 8009120423 Forwards If Info Notice 80-31, "Maloperation of Gould-Brown Bover: 480 Volt Type K-6005 % K-80% 6005 Circuit Breakers " No written response required SEYFRIF,K V Region 4, Dallas, Office of the Director 80/08/27
- 8009300535 Submits response to IE Sulletin 80-20 Westinghouse Type W-2 control switches are not used in safety-related applications OPREA.0 K Houston Lighting & Power Co 80/09/09 2pp
- S Reportable occurrences. LERs & related correspondence
- 8009180479 Interim deficiency rept re breakdown im quality program for concrete placement. Evaluation will be conducted in conjunction w/response to show cause order Item 3(b) Next rept will be submitted 800905 QPREA.G W Hauston Lighting & Power Co 80/08/01 4pp
- 8009190147 Interim deficiency rept re broken tie-down studs for reactor bldg polar crane rail sys Brown & Root continuing to evaluate as-built conditions Stud failure not caused by inadequate design Next rept due by 800917 OPREA.G U Houston Lighting & Power Co 60/08/01 4pp
- 8009020288 Final deficiency rept re 800717 safety injection sys piping Submits addi info re disposition of seal weld between process pipe & emergency sump lines por 800717 request Recirculation valve end loads within stress limit OPREA.G W. Houston Lighting & Power Co. 80/08/22 7pp
- 8009020290 Second interim deficiency rept re mail control of ASTM A-325 structural steel bolts Documentation for installed bolts in Category 1 applications being identified & located & partial release in Stop Mork S-22 issued OPREA:0 W Houston Lighting & Power Co 80/08/22 4pp
- 009040377 Interim deficiency rept re stud welding on concrete embedments Preliminary evaluation showed that 0 02% of welds were rejectable Status rept will be submitted by 801007 OPREA ON Houston Lighting & Power Co 80/08/28 Jpp
- 9009110384 Final deficiency rept re diesel generator fuel oi, tank room exhaust fans Hold on engineering drawings will be lifted upon procurement of qualified IE motors

  OPREA.G W Houston Lighting & Power Co 80/09/03 5pp
- 3009110367 Final deficiency rept re breakdown in quality program for concrete placement CII-W90 Addi QC inspectors have been added to assure that preplacement insps are conducted thoroughly Placement lighting has been added to checklist QPREA-Q W Houston Lighting & Power Co 80/09/04 12pp
- 1009230603 Third interim deficiency rept re rejectable indications for welds which had been previously accepted Cause not stated Re-examination & repair program for essential cooling water sys will be performed Progress rept by 801215 GPREA.O W Houston Lighting & Power Co 80/09/12 4pp
- 009230&17 Second Interim deficiency re breakdown in quality program for procurement cycle of purchased matls & equipment Cause not stated Brown & Root developing procedures & implementation schedule for performing verification program OPREA, G W Houston Lighting & Power Co 80/09/12 3pp
- 100923065B Fourth Interim deficiency rept re polar crane rail tie-down stud failure Caused by porosity & lack of complete fusion of stud wolds Deviations from design did not significantly contribute to failures Existing studs will be removed OPREA.0 W Houston Lighting 3 Power Co 80/09/15 App
- 8007240439 Final deficiency rept is spent fuel storage racks Evaluation of condition indicates safety of operations not affected & is not reportable under 10CFR50 55e

  OFREA.C W Houston Lighting & Power Co 80/09/17 3ps

- 8009230402 Final deficiency rept on motor pump shaft failure in Commip containment hydrogen monitoring sys Nonconformance rept has been prepared & hold tags issued against equipment until pump is shipped back to manufacturer Pump uill be replaced OPREA.O N Houston Lighting & Power Co 80/09/18 3pp
- 8009300161 Second interim deficiency rept re radiographs w/rejectable indications in previously accepted welds Caused by weld spatter & sharp corners All indications to be repaired & reinspected for final acceptance unless concrete embedded OPREA, G W Houston Lighting & Power Co 80/09/23 App
- 8009300453 Fourth interim deficiency rept re damaged steel liner plate in Unit 2 reactor containment bldg Submits updated repair logic Subcontract change order for repair work negotiated & erecuted Defermed section of plate removed OPREA, C. H. Houston Lighting & Power Co. 80/09/25 5pp
- T Hearing transcripts on non-antitrust matters
- 8009260288 Forwards transcript & record of 800819 public meeting refacilities w/util & NRC errata & related documentation STELLO.V Office of Inspection & Enforcement, Office of the Director 80/09/19 4pp
- --8009260290 Transcript of 800819 public meeting re facilities in Bay City.TX Pp 1-379 Util & NRC errata & related documentation & correspondence encl + Office of Inspection & Enforcement, Office of the Director 80/09/19 450pp
- DOCKET STN-50-499 SOUTH TEXAS PROJECT, UNIT 2

  A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergancy Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl M/o NUREO EISENMUT, D O Division of Licensing 80/08/01 119pp
- 8009030272 Forwards request for add1 info re instrumentation & control sys in order to complete evaluation of facility FSAR TEDESCO.R L. Assistant Director for Licensing 80/08/15 9pp
- 8007080201 Forwards info & response to NRC questions re Category I masonry unlls Fifty-four oversize drawings available in Central Files only OPREA.G W Houston Lighting & Power Co 80/09/04 8pp
- F Security, medical, emergency & fire protection plans
- 8007020147 Invites participation in 800822 workshop in Atlanta, 0A to solicit comment re proposed functional criteria for emergency response facilities in NUREO-0576 Discussion to include location, size & staffing of emergency ctrs SEYFRIT, X V Region 4. Dallas, Office of the Director 80/08/12
- G Adjudicatory correspondence
- 8009050364 Requests extension until 801001 to respond to order to show cause. Item 7 re design change control program

  OPREA: G. H. Houston Lighting & Power Co. 80/08/28 3pp
- 8007040261 Forwards recently promulgated amends to emergency planning regulations BM Dordenick is lead counsel per encl notice of appearance Rt. Black backup counsel W/o encls BERDENICK, B M Hearing Branch 4 80/07/02 2pp
- B009110369 Confirms conversation re objection & Intent not to respond to util 800825 interrogatories & document requests Factual discovery closed since 800314 Interrogatories are ill-timed as efforts have been made to encourage settlement STAHL,D M Isham, Lincoln & Beale 80/09/08 ip
- 8009170361 Submits status of rept on settlement negotiations,on behalf of TK-LA Electric Cooperative of TX.Inc No unresolved issues exist at present Certificate of Svc encl BURCHETTE, W M Northcutt Ely 80/09/11. 3pp
- BO092B0042 Memorandum & order.CLI-BO-32, denying Citizens Concerned About Nuclear Power & Citizens for Equitable Utils request for hearing on 1E 800430 order to show cause re deferral of safety-related const until completion of mods Waddl views CHILK.S J Office of the Secretary of the Commission B0/09/22 200

- BO09250045 Addendum to Commission 800922 memorandum & order, CLI-80-32 Fortnote re ALAB-594 was omitted from JF Absarce separate views CHILK, 8, J Office of the Secretary of the Commission 80/09/22
- BOO9250020 Asvises that parties may contact BK Bordemick if desiring to barrow BOOB19 public meeting transcript for review purposes BORDENICK.B M Hearing Branch 4 80/09/29 1p
- BOOT300030 Hemorandum & order advising parties to agree on contentions reflecting NRC 800430 show cause order/CLI-80-32, but not within QA/OC Contentions 1 & 2 Rept on issues must be filed by BOJ015 & identification of add1 discovery by BOJ201 BECHNOEFER.C Atomic Safety and Licensing Board Panel 80/09/24 386.

- BOOTO20108 Responds to BOOBOB Itr Advises that heat-induced illness being watched closely at plants Const has progressed to point that most work being done indoors Applicants have taken steps to improve working conditions by adding Pans DENTON-H R Dffice of Nuclear Reactor Regulation, Director BO/OB/12. 19
- K Utility Final Safety Analysis Report (FBAH) & amends
- BCC9150559 Forwards Amend 12 to FBAR

  DPREA, 0 H Houston Lighting & Power Co 80/09/15 5pp
- --HOO9150561 Amend 12 to FSAR # Hauston Lighting & Pawer Co. 80/09/15 140pp
- 8009250054 Certifies syc of Amend 12 to FSAR.on 800915. \* Houston Lighting & Power Co 80/09/15 2pp

#### M. Antitrust correspondence

- 8009040196 Response to appaicants. Central & South Hest Corp & City of Austin, TX objections to TX Border Cooperative petition to Intervene Asserts interests under LBP-74-13 Urges full party participation M/Certificate of Suc
- 8007020282 Requests that info be provided to all parties re wheeling rate development per 800826 discussions Discusses principles to be considered re smaller util participation in facility ownership SPIECEL. G. Spiecel & McDiermid 80/08/28 4pp
- BOOT030721 Advises that appropriate steps have been taken to insure eve of status repts & pleadings. CHANANIA:F D Antitrust Division 80/08/29, 1p.
- BO09040289 Joint motion for partial revision of ASLB 8008i3 order reprocedural schedule Suggests 8009i2 for settlement status repts, 8009i5 for prehearing conference & 80iii2 for evidentiary hearing commencement Certificate of Svc sncl. CHANANIA: F D Antitrust Division DALOUDH, R C Austin, TX HO00, J C. San Antonio, TX. 80/08/29 7pp
- 8009090453 Forwards typescript version of intervenor Utils Board of City of Brownsville, TX 800829 proposed modified license conditions. POIRTER:N R Spiegel & McDiarmid 80/09/03, 10pp
- BOOP100261 Designates WA Russell of WA Russell & Associates as expert engineering witness which DOJ may call at trial of facility litensing proceeding MCHILLEN.N.H Justice.Dept of 80/09/03 ip
- 8007110792 Order revising procedural schedule set in ABLB 800813 order Bettlement status rept shall be submitted on 800912, prehearing conference shall commence on 800915 trial briefs on 801008 % 22 & evidentlary hearing on 801112. MILLER, K E. Atomic Safety and Licensing Board Panel. 80/07/08 2ps.

- 8009150417 Motion to compel Central Power & Light response to 800825 interrogatories Objection erroneous due to necessity to know full scope of take-over plans W/DH Stohl 800908 ltr. stceppts of util corrected discovery & Centificate of Svc 8PIEGEL-0 Brownsvills.TX POIRIER, M R Spiegel & McDiermid 80/09/11 23po
- 8009160332 Notifies that City of Austin has reached tentative agreement to settle w/NRC & DOJ re proposed license conditions Settlement contingent on final wording of draft document Final version projected for 800915 BALOUGH,R C Telas, State of 80/09/11 2pp
- 8009140275 Notice of taking WP Sayles & T Russell of CP&L 800923 & 24 depositions Examination will address possible purchase of Brownsville electric util sys & related studies & issuance of bonds Certificate of Svc encl POIRIER.M R Brownsville.TX 80/09/12 7pp
- 8009170188 Settlement status rept Author approval of terms of stipulated licensing conditions not yet given No position on issues & procedures presented Certificate of Svc encl JOHN.D F South Texas Electric Cooperative JOHN.D F HCDermott.Will & Emery HUNTER.H McDinnis, Lochridge & Kilgare 80/09/12 Spp
- 8009170339 Settlement status rept per ASLB 800813 order Agreement reached by util,NRC & DOJ which will dispose of all Comanche Peak issues when approved by ASLB Encl stipulation will insure OL would not violate antitrust laws SAMPLES.M D. Texas Utilities Oenerating Co 80/09/12 2pp
- 8009170229 Fourth settlement status rept Stigulations w/applicants embodying two sets of license conditions accomplished Final position re need for hearing will be submitted after examination of conditions by parties W/Gertificate of Svc CHANANIA,F D Antitrust Division 80/09/14 7pp
- --8009170239 Stipulation incorporating encl license condition w/o admission of violation to antitrost laws FABRIKANT.R Justice, Dept of CHANANIA, F. D. Antitrost Division STAHL.D M. Central & Bouth West Corp. 80/09/12 20pp
- 8009140157 Settlement status rept per ASLB 800813 order Endorses encl stipulation re license conditions reached by DQJ, NRC, FERC & Houston Lighting & Power Resolves concerns evidencing intent to litigate DDE endorsed settiment entirely in FERC case COPELAND, J Q Houston Lighting & Power Co 80/09/15 2pp
- --8007160160 Stipulation incorporating license conditions.Licensee past or planned action w/o conditions not inconsistent w/ antitrust laws Conditions do not consistitute admission or violations.Certificate of Svc encl FABRIKANT, R Justice, Dept of CHANANIA, F D Antitrust Division STANL, D Houston Lighting & Power Co 80/07/15 17pp
- 8009160182 Settlement status rept per ASLS 80813 order Requests unspecified extension to receive & review new arguments & to determine & submit unresolved issues License conditions & settlement re FERC not yet received W/Gertificate of Svc. PDIRIER, M R Brownsville, TX 80/09/15 9pp.
- B009170177 Bettlement status rept Suggests approval of stipulated license conditions to maintain situation consistent  $\omega/$  antitrust laws FERC & SEC approval of dc interconnections necessary for settlement execution Certificate of Svc and STAHL, D M Gentral & South West Corp 80/09/15 12pp
- 8009180460 Suppl status rept per ASLB 800813 order.DGJ reached agreement w/parties in Comanche Peak proceedings re proposed set of license conditions.Agreement reached w/applicant in South TX proceeding Certificate of Svc ench MCMILLEN.N H Justice.Dept of 80009/15 7pp
- 8009250028 Order greating extension until 800929 for Commission to review ALAB-608. CHILK G J Office of the Becretary of the Commission. 80/09/22 to
- 8009240318 Motion for one-day extension to file comments on proposed settlement conditions Last minute consultations & discussions needed Certificate of Evc encl
  POIRIER M R Brownsville TX 80/09/24 App.
- BO09300035 Comments on proposed settlements per ASLB 800915 directive Proposed license conditions will serve to preclude or limit consideration of competitive implications of do ties by FERG Cortificate of Box ancl 0'NEIL, R A Southwest Texas Electric Cooperative BO/09/24 12pp

- B009300488 Confirms that JR Choukas-Bradley was authorized to express position of Miller, Balis & D'Neil, P C on behalf of TX Border Cooperatives at 800915 status hearing re leave to intervene out of time O'NEIL, R A Miller, Balis & D'Neil 80/09/24 2pp
- --8009300496 Comments of TX Border Cooperatives on proposed settlements of NRC & DQJ re licensing proceedings Cartificate of Svc encl O'NEIL.R A Miller.Dalis & O'Neil 80/09/24 10pp
- 8009300013 Motion in apposition to 800912 proposed license conditions due to failure to address crucial issues re effects of ac & dc interconnections Urges further proceedings to cure inconsistencies w/antitrust laws Certificate of Bvc entl SPIEOEL, O Brownsville, TX 80/09/25 32pp
- 8009300326 Order granting extension until 800928 for all parties to commont on 800915 stipulation & licensing conditions MOLFE: 5 J Atomic Safety and Licensing Board Panel 80/09/25 Ip
- 8009300533 Comments on stipulation & proposed license conditions Recommends approval although solution to all antitrust problems is not guaranteed through incorporation of conditions Reserves right to be full party if hearing held JOHN, D.F. South Taxas Electric Cooperative JOHN, D.F. McDermott, Will & Emery 80/09/25 2pp
- 80/09/24
- ! Antitrust hearing transcripts
- 8009190764 Transcript of 800915 prehearing conference in Bethesda, MD
  - Pp 1078-1138 # Atomic Safety and Licensing Board Panel 80/09/15 64pp
- Q Inspection reports, IE Bulletins & correspondence
- 8007090925 Forwards IE Insp Repts 50-478/80-17 & 50-499/80-17 on 800623-26 No noncompliance noted BEIDLE: AC Region 4. Dallas Reactor Construction & Enginearing Support Branch 80/07/16 2pp.
  - O09050303 IE Insp Repts 30-498/80-17 & 50-499/80-17 on 800623-26. No noncompliance noted Major areas inspected const activities including observation of work & review of records apartaining to IE Insp Repts 50-498/77-19 & 50-499/77-19 HALL.R E Region 3. Chicago. Reactor Construction & Engineering Support Branch TAPIALJ I, CHAUDHARY.8 K Region 3. Chicago. Office of the Director. 80/07/16 7pp
  - 7170380 Forwards IE Insp Repts 50-498/80-16 & 50-499/80-16 during the 1980 No nancompliance noted IDLE.N.C Region 4. Delias, Reactor Construction & Engineering upport Branch 80/07/16 2pp
  - 209170385 IE Inep Repts 50-498/80-16 & 50-499/80-16 during June 1980 No noncompliance noted Major areas inspected insp of safety-related components.containment structural steel welding. GA records sys & most mastings CROSSIANN, W.A., PHILLIPS.H.B., Region 4, Dallas, Office of the Director 80/07/16 5pp
- 009180467 Submits response to IE Bulletin 80-08 Plant contains flued head penetration design w/containment boundary butt welds between penetration sleeve & process piping Penetration welds radiographically examined OPREA.
- 8009180473 Confirmt understanding re IE Bulletin 79-03A.Pips stress evaluation will be limited to calculations concerned w/pressure SARKER.D 0 Houston Lighting & Power Co 80/08/05 1p.
- 3009180461 Bubmits response to IE Bulletin 79-03A Desired info should be available for submittal by 801030 OPREA.O.W Howston Lighting & Power Co 80/08/06 2pp.
- 1009250402 Forwards IE Insp Repts 50-498/80-19 & 50-499/80-19 on 800722-24 No noncompliance noted 8EIDLE,W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/08/08. 2pp

- --8009250405 IE Insp Repts 50-498/80-19 & 50-499/80-19 on 800722-24 No noncompliance noted Major areas inspected records re IE Insp Repts 50-498/79-19 & 50-499/79-19 findings on earthwork & concrete
  HALL,R E , TAPIA,J I Region 4. Dailss, Reactor Construction &
  Engineering Support Branch CROSSMAN,W A Region 4. Dallss.
  Office of the Director S0/08/08 Spp
- 8007030157 Ack receipt of 800722 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/77-03 & 50-499/77-03 SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering Eupport Branch 80/08/14 ip
- ---8009030170 Responds to NRC ltr re violations noted in IE Insp Repts 50-498/77-03 & 50-499/77-03 Corrective actions sys of reviews & multitiered supervision implemented OREA.9 W Houston Lighting & Power Co 80/07/22 2pp.
- 8009030268 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E " Written response required BEYFRIT, K V Region 4, Dallas, Office of the Director 80/08/15,
- 8009300098 Forwards IE Insp Repts 50-498/80-20 & 50-499/80-20 on 800728-29 No moncompliance noted SEIDLE-W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/08/18 2pp
- --8009300102 IE Insp Repts 80-498/80-20 & 50-499/80-20 on 800728-29
  No noncompilance noted Major areas inspected issuance &
  disposition of nonconformance repts
  TOM\_ENSBN.D.P. HALL,R E Region 4. Dellas, Reactor Construction (
  Engineering Support Branch CROSMAN,W. A Region 4. Dellas,
  Office of the Director 80/08/12 Spp
- 8009170394 Forwards IE Circular 80-18, "10CFR50,59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required BEYFRIT.K.V Region 4. Dallas, Office of the Director 80/08/22
- 8009300545 Submits response to IE Bulletin 80-16 Rosemount Model 1151 or 1152 pressure transmitters will not be used in any safety-related applications OPREA.0.W Howston Lighting & Power Co 80/08/22. 2pp.
- 8007300555 Bubmits response to IE Bulletin S0-19 Mercury-wetted relays are not used in reactor protection sys.

  OPREA, O. H. Houston Lighting & Power Co. 80/08/26 2pp.
- 8009120429 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover! 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers," No written response required. SEYFRIT.K V Region 4: Dallas, Office of the Director, 80/08/27.
- 8009300536 Submits response to IE Bulletin 80-20 Westinghouse Type W-2 control switches are not used in safety-related applications
  UPREA, 0 W Houston Lighting & Power Co 80/09/09. 2pp
- S. Reportable occurrences, LERs & related correspondence
- 8009180479 Interim deficiency rept re breakdown in quality program for concrete placement Evaluation will be conducted in conjunction w/response to show cause order Item 3(b) Next rept will be submitted 800905.

  DPREA.O W Houston Lighting & Power Co 80/08/01. App.
- 8009190147 Interim deficiency rept re broken tie-down studs for reacto:
  bldg poler crane rail sys, Brown & Root continuing to
  evaluate as-built conditions Stud failure not caused by
  inadequate design Next rept due by 800917.

  GPREA: 0 W Houston Lighting & Power Co 80/08/01 App
- 8009020288 Final deficiency rept re 800717 safety injection sys piping Submits addi info re disposition of seal weld between process pipe & emergency sump lines per 800717 request. Recirculation valve end loads within stress limit OPREA: 0.W Houston Lighting & Power Co 80/08/22 7pp.
- 8009020290 Second interim deficiency rept re meth control of ABTM A~321 structural steel bolts Documentation for installed bolts in Category 1 applications being identified & located & partial release on Stop Mork B~22 issued CPREA.0 W. Houston Lighting & Power Co. 80/08/22. 4pp

- 8009040377 Interim deficiency rept re stud welding on concrete embedments Preliminary evaluation showed that 0 02% of welds were rayectable Btatus rept will be submitted by 801009 UPREA. 6 W Houston Lighting & Power Co 80/08/29 3pp
- 9007110384 Final deficiency rept re dissel generator fuel oil tank room exhaust fans Hold on engineering drawings will be lifted upon procurement of qualified IE motors OFREA:0 W Houston Lighting & Power Co 80/09/03 5pp
- 9009110367 Final deficiency rept re breakdown in quality program for concrete placement CII-M90 Add1 QC inspectors have been added to assure that preplacement inspectors conducted thoroughly Placement lighting has been added to checklist OPREA, Q W Houston Lighting & Power Co 80/09/04 12pp
- 8009230603 Third interim deficiency rept re rejectable indications for welds which had been previously accepted Cause not stated Re-examination & repair program for essential cooling water sys will be performed Progress rept by 801215
  OPREA.9 W. Houston Lighting & Power Co 80/09/12 4pp
- 8009230617 Second interim deficiency re breakdown in quality program for procurement cycle of purchased matls & equipment.Cause not stated.Brown & Root developing procedures & laplementation schedule for performing verification program DPREA.Q W Houston Lighting & Powe, Co 80/09/12 3pp
- 8009230658 Fourth interim deficiency rept re polar crame rail tie-down stud failure Caused by porosity & lack of complete fusion of stud walds. Deviations from design did not significantly contribute to failures Existing studs will be removed OPREA: 0 W. Houston Lighting & Power Co 80/09/15 App
- 8009240439 Final deficiency rept re spent fuel storage racks Evaluation of condition indicates safety of operations not affected & is not reportable under 10CFRSO 55e OPREA, 0. W Houston Lighting & Power Co BO/09/17 3pp
- მ009230402 Final deficiency rept on motor pump shaft failure in Comsip containment hydrogen monitoring sys Nonconformance rept has been prepared & hold tags issued against equipment until pump is shipped back to manufacturer Pump will be replaced OPRFA.O W Houston Lighting & Power Co 80/09/18 3pp
- 8007300161 Becond interim deficiency rept re radiographs w/rejectable indications in previously accepted welds Caused by weld spatter & sharp corners All indications to be repaired & reinspected for final acceptance unless concrete embedded DPRFA:0.W. Houston Lighting & Power Co 80/09/23. 4pp
- 8009300453 Fourth interim deficiency rept re demaged steel liner plate in Unit 2 reactor containment bidg Submits updated repair logic Subcontract change order for repair work negotiated & executed, Deformed section of plate removed
  DPREA: 0 W Houston Lighting & Power Co 80/09/25 3pp
- T Hearing transcripts on non-antitrust matters
- BO09260288 Forwards transcript & record of BO0819 public meeting refacilities w/util & NRC errets & related documentation STELLO.V Office of Inspection & Enforcement, Office of the Director 80/09/19 4pp
- --8009260290 Transcript of 800819 public meeting re facilities in Bay City, TX. Pp 1-379 Util & NRC errata & related documentation & correspondence encl & Office of Inspection & Enforcement, Office of the Director 80/09/19. 450pp
- DOCKET 50-500 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 2

  Adjusticatory correspondence
- BOO9190299 Responds to FOIA request for 15 documents listed in bibliography of NUREO-0625. "Rept of Siting Policy Task Force." Documents 6-8 & 13 are available in PDR. Forwards remaining documents FELTON.J. M Division of Rules and Records BO/09/04 1p
- ---BO09190587 Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants for determination of site acceptability & adequacy of engineered safety features.

  HINDOUELR B Office of Standards Development, Director BECY-79-362, 79/06/04 7pp.

- --8009190630 Requests that encl. "Differences in Procedures for Estimating Atmospheric Dispersion Conditions at Inland & Coastal Sites." be sent to appropriate Boards BCINTD, J F Hearings Division 79/04/04 16pp
- DOCKET 50-501 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 3

  G Adjudicatory correspondence
- B007190297 Responds to FOIA request for 15 documents listed in bibliography of NUREO-0625, "Rept of Siting Policy Task Force" Documents 6-8 & 13 are available in PDR Forwards remaining documents FELTON-J M Division of Rules and Records 80/09/04 1p
- --B009190587 Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants for determination of site acceptability & adequacy of engineered safety features MINDOUE.R B Office of Standards Development. Director SECY-79-362 79/06/04 7pp
- --8009190630 Requests that encl. "Differences in Procedures for Estimating Atmospheric Dispersion Conditions at Inland & Coastal Bites." be sent to appropriate Boards BCINTO.J F Hearings Division 79/04/04 idep
- DOCKET STN-50-502 HAVEN NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- B009110856 Forwards FR motice of withdrawal of application for CP YOUNOBLOOD, B J Licensing Branch 1 80/09/04 2pp
- ~~B009110B59 Notice of withdrawal of application for CP YOUNGBLOOD, B J Licensing Branch 1 B0/09/03 ip
- DOCKET STN-90-508 WPPSS NUCLEAR PROJECT, UNIT 3
- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREC-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREC-0696 entl M/o NUREC EISENHUT, D O Division of Licensing 80/08/01 119pp
- 8007120102 Recommends listed steps be taken to reduce risk from ATH9 events during interim period before required mods Requires submission of ATH9 emergency operating procedure TEDESCO.R L Assistant Director for Licensing 80/08/27 3pp.
- 8009120173 Informs of NRC position re welding procedure specs for use in applications requiring impact testing for notch toughness Specs should be qualified using max anticipated amperage & voltage setting to be used in production welding. SPENCER.0 S Region 5, San Francisco. Reactor Construction & Engineering Support Branch 80/09/04 2pp
- F. Security, medical, emergency & fire protection plans
- 8009030267 Notifies of 800819,22 & 30 regional workshops re development of guidance for acceptable method for coping w/emergencies at facility Requests that representative be sent 8063 areas to be discussed include function of facilities & location ENGELKEN.R.H. Region 5, San Francisco, Office of the Director 80/08/12. 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 8009100179 Responds to IE Bulletin 80-08, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Containment penetration connections are of flued head design w/containment boundary butt welds RENBERGER.D L. Washington Public Power Supply System 80/07/15. 2pp
- 8009240303 Forwards IE Info Notice 80-29, "Broken Bluds on Terry Turbine Steam Inlet Flange" No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/08/07, 1p.

- 8007030272 Forwards Revision 1 to IE Bulletin 80~19. "Failures of Memcury-Hetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required EMGELKEN,R H Region 5, San Francisco, Office of the Director 80/08/15 ip
- 8009290302 Forwards IE Info Notice 80-27 re degradation of reactor coolant pump studs ENGELKER.R M Region 5, San Francisco, Office of the Director. 80/08/18 4pp
- 8009160189 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ENGELKEN.R H Region 5. San Francisco. Office of the Director 80/08/22 1s
- 8009120468 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6005 & K-DON 6008 Circuit Breakers " No written response required ENGELKELLR H Region 5, San Francisco, Office of the Director 80/08/27 1p
- S Reportable occurrences. LERs & related correspondence
- B00903033B Ack receipt of 800625 interim deficiency rept re shutdown cooling heat exchangers
  ENGELKENIR H Region 5. San Francisco. Office of the Director
  80/07/09 1p
- --8009030342 Intersm deficiency rept re shutdown cooling heat exchangers
  Breatdown of mat! selection & mfg processes resulted in
  chloride contamination in tubes, below min design weld
  overlay thickness & cracking of meld overlays C-E rept encl
  REMBERGER, D L Hashington Public Power Supply System 80/06/23
  7pp
- DOCKET STN-50-509 WPPSS NUCLEAR PROJECT, UNIT 5
- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft MUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl M/A NUREO EISENHUT, D Q Division of Licensing 80/08/01 119pp
- 9009120102 Recommands listed steps be taken to reduce risk from ATHS swents during interim period before required mode Requires submission of ATHS merepancy operating procedure TEDESCO, R. ... Assistant Director for Licensing 80/08/27 3pp
- BOO9120173 Informs of NRC position re walding procedure specs for use in applications requiring impact testing for notch toughness Specs should be qualified using max anticipated amperage & voltage setting to be used in production welding SPENCER, O. S. Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/09/04 2pp
- F Security, medical, emergency & fire protection plans
- 8009030267 Notifies of 800819,22 & 30 regional workshops re development of guidance for acceptable method for coping w/emergencies at facility Requests that representative be sent Subjarces to be discussed include function of facilities & location ENGELKEN, R. H. Region S. San Francisco. Office of the Director 80/08/12 2pp
- G Inspection reports. IE Bulletins & correspondence
- 8009100179 Responds to IE Bulletin 80-08. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Containment penetration connections are of flued head design w/containment boundary butt welds RENBERGER. D. L. Washington Public Power Supply System 80/07/15 2pp
- BO09240303 Forwards IE Info Notice 80-29, "Broken Studs on Terry Turbine Steam Inles Flange" No written response required. ENGELKEN.R H Region 5. San Francisco, Office of the Director BO/03/07 ip
- 8009030292 Forwards Revision 1 to 1E Bulletin B0-19. "Feilures of Marcury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Dasigned by C-E " Written response required ENGELKEN.R H Region 5. Gan Francisco. Office of the Director 80/03/15 ip

- 8009270302 Forwards IE Info Notice 80-27 re degradation of reactor coolant pump studs ENGELKEN,R H Region 5. Ban Francisco. Office of the Director. 80/08/18 4pp
- 8009160189 Forwards IE Circular 80~18, "10CFR50.59 Bafety Evaluation; for Changes to Radwaste Treatment Bys " No written response required ENGELKEN, R H Region 5, San Francisco, Office of the Director. 80/08/22 10
- 8009120468 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers" No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/08/27 ip
- 8 Reportable occurrences, LERs & related correspondence
- 8009030338 Ack receipt of 800625 interim deficiency rept re shutdown cooling heat exchangers ENGELKEN,R H Region 5, Sen Francisco, Office of the Director. 807/07/09. Ip
- --B009030342 Interim deficiency rept re shutdown cooling heat exchangers
  Breakdoun of matl selection & mfg processes resulted in
  chloride contamination in tubes; below min design wald
  overlay thickness & cracking of weld overlays C-E rept encl
  RENBERGER, D. C. Washington Public Power Supply System, B0/06/25,
  7pp
- DOCKET 50-510 BLUE HILLE STATION, UNIT 1
- G Adjudicatory correspondence
- 8009090245 Motion for issuence of partial initial decision resultability Case uncontested & pending for 13 months Notice of appearance & Certificate of 8vc encl.
  TREBY.8 A Hearing Branch 1, 80/09/05 4pp
- 8009110803 Order directing applicant & NRC to submit briefs reflecting position on applicability of NRC siting-related pronouncements to present early site review. Orders NRC to respond to applicant reply to NRC proposed findings of fact. LITTLE-L W , MILLER, M E Atomic Safety and Licensing Board Panel. 80/09/99 4pp
- DOCKET 50-511 BLUE HILLS STATION, UNIT 2

  9 Adjudicatory correspondence
- 8009090245 Motion for issuance of partiel initial decision re-site suitability Case uncontested & pending for 13 months Notice of apparance & Certificate of Svc encl TREBY, 8 A Hearing Branch 1 80/09/05 4pp.
- 8009110803 Order directing applicant & NRC to submit briefs reflecting position on applicability of NRC siting-related pronouncements to present early site review. Orders NRC to respond to applicant reply to NRC proposed findings of fact LITILE L.W. MILLER.M.E. Atomic Safety and Licensing Board Panel 80/09/09 App.
- DOCKET 50-513 WPP66 NUCLEAR PROJECT, UNIT 4
- A Application/construction stage documents & correspondence
- 8007080080 Forwards draft NUREQ-0696, "Functional Critaria for Emergency Response Facilities" Comments requested within 90 days Proposed implementation schedule for meeting criteria of NUREQ-0696 encl W/o NUREQ. EIBENMUT, D Q. Division of Licensing. 90/08/01 119pp.
- 8009120099 Recommends listed steps be taken to reduce risk from ATMS events during interim period before required mods. Requires submission of ATMS emergency operating procedure.

  TEDESCO, R L Assistant Director for Licensing. 80/08/27 Spp
- 8D07090496 Forwards addl geologic info re time of latest movements of earth faults on Gable Mountain man ctr of reservation No conclusions re significance have been reached & info is not considered reportable under IOCFR21 RENBERGER.D L Washington Public Power Supply System B0/09/02.

### F Security, medical, emergency & fire protection plans

- 8009030267 Notifies of 800819.22 & 30 regional workshops re development of guidance for acceptable method for coping w/emergencies at facility Raquests that representative be sent Subj areas to be discussed include function of facilities & location EMOELKEN.R H Region 5, San Francisco, Office of the Director 80/08/12. 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 8009160622 Responds to IE Bullevi, 80-16, "Potential Misapplication of Rosenount, Inc Models 1151 & 1152 Pressure Transmitters of Either A or D Dutput Codes "No subj transmitters installed or planned to be installed in safety-related sys REMBERGER, D L. Washington Public Power Supply System 80/08/07
- BOO9170393 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASKE BA-312, Type 304 Stainless Steel Pipe " No 8A-312 or A-312, Type 304 fusion welded pipe in use or planned for use in 44fety-related sys at facilities RENBERGER, D. L. Washington Public Power Supply System 80/08/07
- 8009260303 Forwards IE Info Notice 80-29. "Broken Stude on Terry Turbine Steam Inlet Flange " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director, 80/08/07 1p.
- 8009120304 Forwards IE Insp Repts 50-460/80-08 & 50-513/80-08 on 800714-18 No noncompliance noted 8PENCER.Q.S Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/08/12 2pp
- --8009120309 IE Insp Repts 50-460/80-08 & 50-513/80-08 on 800714-18 No noncompliance noted Major areas inspected RCPB piping insulation & licensee action on previous insp findings DODDB,R T Region 5, San Francisco, Reactor Construction & Engineering Bupport Branch HERNANDEZ,Q , MAONER,W J Region 5, San Francisco, Office of the Director 80/08/08 App
- 8009030292 Forwards Revision i to IE Bulletin 80-19, "Failures of Marcury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E." Written response required EAXQELMEN.R H Region 5, San Francisco, Office of the Director 80/08/15. ip
- BC09290302 Forwards IE Info Notice 80-27 re degradation of reactor collant pump studs.
  EMGELKEN,R.H Region 5, San Francisco, Office of the Director 80/08718 4pp.
- 8009110415 Ack receipt of 800725 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-460/80-07 & 50-513/80-07 Region 5, Ban Francisco, Reactor Construction & Engineering Support Branch, 80/08/20
- --8009110422 Responds to NRC 800626 itr re violations noted in IE Insp Repts 50-460/80-07 & 50-513/80-07 Corrective actions.rework of support 176-3413-2710 completed Support 17-4-3404-300A rework not completed RENBERGER.D.L. Washington Public Power Supply System 80/07/25 30p
- ---B009ii0424 Forwards IE Insp Repts 50-460/H0-07 & 50-513/H0-07 on H00401-30 & notice of violation.

  BPENCER.0 8. Region 5, Ban Francisco. Reactor Construction & Engineering Support Branch B0/06/26 2pp
- --G009110426 Notice of violation from insp on 800401-30.
  \* Region 5. San Francisco. Office of the Director 80/06/25 ip.
- ---BD09110429 IE Insp Repts 30-440/80-07 & 50-513/80-07 on 800401-30 Noncompliance noted deficiency in area of cable tray support welding TOTHER D. Region 5, Ban Francisco, Office of the Director DODOB, R. T. Region 5, Ban Francisco, Reactor Construction & Engineering Support Branch. 80/06/25 12pp.
- 8009160189 Forwards IE Circular 80-18, "10CFRSO 59 Bafety Evaluations for Changes to Radwaste Treatment Bys." No written response required.
  ENGELKEN.R.H. Region 5, Ban Francisco. Office of the Director BO/08/22 1p

- 8009120468 Forwards IE Info Notice 80-31, "Malogeration of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers " No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/08/27 ip
- 8009120609 Ack receipt of 800819 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-460/80-10 & 50-513/80-10 SPENCER.0 B Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/09/02 Ip
- --8009120616 Forwards IE Insp Repts 50-460/80-10 & 50-513/80-10 on 800602-09 & notice of violation SPENGER. G B Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/07/17 2pp
- --8009120622 Notice of violation from insp on 800602-09
  \* Region 5, San Francisco, Office of the Director 80/07/16 ip
- --B009120631 IE Insp Repts 50-460/80-10 & 30-513/80-10 on 800602-09 Noncompliance noted fillet welds on columns 22704 & 2283 undersized contrary to contract specs TOTH.A D , DDDS.R T Region 5. San Francisco. Office of the Director 80/07/16 Spp.
- 8009300345 Updates 800124 response to IE Bulletin 77-02, Revision 2, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts." Anchor bolt loads on existing designs will be recalculated by 810228 Related data encl RENSERGER.D L. Washington Public Power Supply System. 80/09/25 700
- DOCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1

  A Application/construction stage documents & correspondence
- 8007080080 Forwards draft NUREO-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl N/o NUREO EISENHUT, D & Division of Licensing 80/08/01 119pp
- DOCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NURES-0696. "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Pronosed implementation schedule for meeting criteria of NURES-0696 encl M/o NURES EISENHUT.D 9 Division of Licensing 80/08/01 119pp
- DOCKET STN-50-516 JAMESPORT NUCLEAR STATION, UNIT 1

  Adjudicatory correspondence
- 8009190299 Responds to FOIA request for 15 documents listed in bibliography of NUREO-0625, "Rept of Siting Policy Task Force " Documents 6-8 & 13 are available in PDR Forwards remaining documents FELTON, J M Division of Rules and Records 80/09/04 ip
- --800919038/ Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants, for determination of site acceptability & adequacy of engineered safety features
  MINGQUE, R B Office of Standards Development, Director SECY-79-362 79/06/04 7pp
- ---8009190630 Requests that encl. "Differences in Procedures for Estimating Atmospheric Dispersion Conditions at Inland & Coastal Sites." he sent to appropriate Boards BCINTO.J F. Hearings Division. 79/04/04 16pp
- 8009170194 Status Rept 4 re NY State Siting Board 800708 opinion & order in Case 80003, recommending const of facility Decision re request for judicial review not yet decided Certificate of Svc encl REVELEY, W T Long Island Lighting Co. REVELEY, W T Hunton & Williams 80709710 Spp

## Q Inspection reports. IE Bulletins & correspondence

- 8009030087 forwards Revision 1 to IE Bulletin 80-19. "Failures of Marcury-Wetted Matrix Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E " Written response required QRIER, B H Region 1, Philadelphia, Office of the Director 80/08/15 1p
- 8009180009 Forwards IE Circular 80-18, "10CFR50.59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required GRIER.8 H Region 1, Philadelphia, Office of the Director 80/08/22 ip
- 8009120180 Forwards IE Info Notice 80-31. "Maloperation of Quald-Brown Boveri 480 Volt Type K-400S & K-DON 400S Circuit Breakers "
  No written response required ORIER, B H Region i, Philadelphia, Office of the Director 80/08/27 1p
- 8009230786 Forwards IE Circular 80-21, "Regulation of Refueling Crews " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/09/10 1p
- 8009240315 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Mat14 " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director BO/09/12 1p
- DOCKET STN-50-517 JAHESPORT NUCLEAR STATION, UNIT 2

  O Adjudicatory correspondence
- BO09190299 Responds to FOIA request for 15 documents listed in bibliography of NUREO-0625, "Rept of Siting Policy Task Force" Documents 6-8 & 13 are available in PDR Forwards remaining documents FELTON.J M Division of Rules and Records. BO/09/04. ip
- --8009190587 Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants, for determination of site acceptability & adequacy of engineered safety features HINGOUE, R B. Office of Standards Development, Director SECY-79-362 79/06/04 7pp
- ---BOD9190630 Requests that encl. "Differences in Procedures for Estimating Atmospheric Dispersion Conditions at Inland & Coastal Sites," be sent to appropriate Board. BCINTO.J F Hearings Division 79/04/04 16pp.
- B009170194 Status Rept 4 re NY State Siting Board 800908 opinion & order in Case B0003, recommending const of facility.

  Decision re request for judicial review not yet decided Certificate of Svc encl

  REVELEY.N T Long Island Lighting Co REVELEY.W T Hunton & Williams 80/09/10. 3pp
- G Inspection reports, IE Bulletins & correspondence
- 8007030087 Forwards Revision i to IE Bulletin 80-17. "Failures of Marcury-Wetted Matrix Ralays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required ORIER, B H Region I, Philadelphia, Office of the Director 80/08/15 Lp
- 9009180009 Forwards IE Circular 80-18, "100FR50.59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ORIER, B.H. Region 1, Philadelphia, Office of the Director 80/08/22, ip
- Be09120180 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6009 & K-DON 6008 Circuit Breakers." No written response required CRIER,8 H Region 1, Philadelphia, Office of the Director 80/08/27 1p.
- 8009230786 Forwards IE Circular 80-21. "Regulation of Refueling Crews." No written response required CRIER, B.H. Region 1. Philadelphia. Office of the Director 80/09/10. 1p

- B009240315 Forwards IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive-Use Shipments of Radioactive Matls." No written response required ORIER, B. H. Region 1, Philadelphia, Office of the Director.
- DUCKET STN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREO EISEMRUT, D © Division of Licensing 80/08/01 119pp
- 8009300400 Forwards technical questions re implementation of interia policy on 100FR50 & 51 MILLS,L M Tennessee Valley Authority 80/09/23. 3pp.
- I Financial information
- 8009090543 Forwards Annual Financial Rept 1979 CROSS,J L Tennasses Valley Authority 80/09/04. 1p
- --8009090563 Annual Financial Rept 1979
  \* Tennessee Valley Authority 80/09/04 44pp
- u Inspection reports, IE Bullatins & correspondence
- 8009090075 Forwards IE Bulletin 80-07. Suppl 1, "SWR Jet Pump Assembly Failure" No response required O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/05/13 ip.
- 8009110111 Forwards IE Insp Repts 50-519/80-13.50-519/80-13. 50-520/80-13 & 50-521/80-13 on 800601-28 No noncompliance nated. MURPHY, C B Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/07/28 2pp
- --8007110177 IE Insp Repts 50-518/80-13,50-519/80-13,50-520/80-13 & 30-521/80-13 on 800A01-28 No noncompliance noted Major areas inspected earth compaction & structural concrets for spray & containment activities

  BWAN.R W Region 2, Atlanta, Office of the Director

  CANTRELL,F 8 Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/28 6pp
- 8007020184 Submits response to IE Bulletin 79-03A No SA-312 or A-312. Type 300 series fusion welded pips is in use or planned for use in safety-related sys MILLS,L M Tenmessee Valley Authority, 80/08/06, 1p.
- 8009020303 Forwards IE Insp Repts 50-327/80-24, 30-328/80-15, 30-390/80-20, 50-391/80-14, 50-438/80-13, 50-439/80-13, 50-439/80-11, 50-518/80-11, 50-518/80-11, 50-553/80-11, 50-553/80-11, 50-553/80-11, 50-553/80-10, 50-56
- --8007020312 Notice of violation from insp on 800707-11.
  \*\* Region 2, Atlanta: Office of the Director. 80/08/06 4pp
- --8007020337 IE Insp Repts 50-327/80-24,50-328/80-15,50-390/80-20,50-391/80-14,50-438/80-13,50-439/80-13,50-518/80-11,50-521/80-11,50-521/80-11,50-521/80-10,50-553/80-11,50-521/80-10,50-54/80-10,50-54/80-10 & 50-547/80-10 on 800707-11 RROUNLEE,V L Region 2, Atlanta, Office of the Director 80/08/06 24pp
- B007030146 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director. B0/08/15.
- 8009140045 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain OE BWR Facilities." No specific action or response requested D'REILLY, U.P. Region 2: Atlanta, Office of the Director. 80/08/19 1p

- 8009120046 Forwards Suppl 3 to IE Bulletin 80-17, "Failurs of Control Rods to Insert During Scram at BWR " No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/22
- 8009160153 Forwards IE Circular 80-18, "10CFR50 59 Bafety Evaluations for Changes to Radwasta Treatment Sys " No written response required
  - O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22
- BOO9240357 Responds to NRC 800617 ltr 80P-90 will be ravised & implemented by 800829 resulting in full compliance Ref IE Insp Repts 50-518/80-09, 50-519/80-09, 50-521/80-09 & 50-521/80-07
  - Tennessee Valley Authority 80/08/22 ip MILLS, L M
- BO09120340 Forwards IE Info Notice 80-31. "Maloperation of Opuld-Brown Bover1 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers "No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/08/27
- BOO918006B Forwards response to IE Bulletin 80-16 Resembunt Models 1151 & 1152 pressure transmitters were planned for installation.

  OE will analyze applications of transmitters to determine out-of-range conditions out-of-range conditions
  HILLS.L.M. Tennessee Valley Authority 80/08/29 2pp
- BOOGRA0427 Forwards response to IE Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters List of identified transmitters used in safety-related areas being compiled Rept will be filled after resolution of deficiency MILLS.L M. Tennessee Valley Authority 80/08/29 2pp
- 9009240380 Ack receipt of 800821 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-518/80-12, 50-520/80-12 & 50-521/80-12 RMRPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/02 ip
- --8009240387 Responds to NRC 800720 ltr re violations noted in IE Insp Repts 50-518/80-12,50-519/80-12,50-520/80-12 & 50-521/80-12 Corrective actions reinforcing steel bars cited in rept are being placed on cribbing MILLS,L M. Tennessee Valley Authority 80/08/21 2pp.
- --8009240398 Forwards IE Insp Repts 50-518/80-12,50-519/80-12, 50-520/80-12 & 50-521/80-12 on 800430-0703 & notice of violation

  \*\*WIRPHY,C E Region 2, Atlanta, Reactor Construction & Engineering

  \*\*Bupport Branch 80/07/28 2pp.\*\*
- 80/07/25 in
- --B009240421 IE Inap Repts 50-518/80-12.50-519/80-12.50-520/80-12 & 50-521/80-12 on B00630-0703 Noncompliance noted failure to follow reinforcing steel storage procedure HERDY. A Region 2. Atlanta. Reactor Construction & Engineering Bupport Branch. KLEINBORGE, W P Region 2. Atlanta. Office of the Director. 80/07/25. Spp
- 8009240375 Forwards IE Circular 80-21, "Regulation of Refueling Crews." No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/09/10.
- 8. Resortable occurrences, LERs & related correspondence
- 8007040449 Final deficiency rept re containment anchor boit chair welds All identified deficient welds will be repaired to original specs & repaired areas tested Investigation conducted on previously accepted welds MILLB,L M Tennessee Valley Authority 80/07/24. 4pp.
- BO09100526 Final deficiency rept re improper anchor spacing on surface—mounted plates All improperly installed surface—mounted plates have been identified & will be remounted by 801114 MILLS.L.M Tennesses Valley Authority 80/08/11 2pp.
- BO09090427 Final deficiency rept re wiring discrepancies in high pressure core spray metal-clad switchgear Defective 88-12 switches replaced. Hardware corrections will be completed by 810130 & software corrections by 810630 MILLS.L.M Tennessea Valley Authority. 80/08/28, 3pp.

- 8009090530 First interim deficiency rept re inadequate drawing control Caused by breakdown of GA program re drawing control Drawings will be updated on daily basis by using TVA receipt forms Final rept to be transmitted on or before 801119 MILLS.L M Tennessee Valley Authority 80/08/28 2pp
- 8009090434 Final interim deficiency rept re 4-inch Borg-Harner gate valves Valves may fail due to error in design Gate could disengage from guide: when valve in backseat position Valve failure may lead to RHR sys degradation MILLS.L M Tanmessee Valley Authority 80/08/29 2pp
- 8007070440 Final interim deficiency rept re wiring discrepancies on MPCB components Discrepancies involve wiring terminations not matching wiring diagrams.missing wires & nonlabeling of parts Components will be reworked MILLS,L M Tennassee Valley Authority 80/08/27 3pp
- 8009160643 Part 2: rept re design deficiencies in nuclear sys protection sys power distribution panels Panels returned to GE for redesign & rework to corrected design MILLS, L M Tennessee Valley Authority 80/09/03 3pp
- 8009240425 Final deficiency rept re inadequate document control Caused by failure of manual holders to follow procedures in filing or removing matl Quarterly internal survey will be conducted MILLS, L.M. Tennessee Valley Authority 80/09/15 Spp
- 8007240372 Second interim deficiency rept re Rosemount Model 1152 pressure transmitter defects Util is preparing lists of Rosemount 1151 & 1152 transmitters for GE to analyze & replace if necessary final rept will be provided by 810403 MILLS,L M Tennessee Valley Authority 80/09/17 3pp
- 8007270375 Second interim deficiency rept re steam tunnel embedment stiffner plate weld. Cause not stated Util continuing to monitor Atlas OA program to help correct deficiencies MILLS.L M Tennessee Valley Authority 80/09/19 1p.
- 8009300445 Third interim deficiency rept re reactor pressure vessel shield wall weld. Investigation is continuing & repairs will be made as required. Final rept should be submitted by 801224. MILLS, L. H Tennessee Valley Authority 80/09/24. 1p
- DOCKET STN-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREG-0694, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days. Proposed implementation schedule for meeting criteria of NUREG-0696 encl Wo NUREG EISENHUT, D & Division of Licensing 80/08/01 119pp
- 8009300400 Forwards technical questions re implementation of interim policy on 100FR90 & 51
  MILLB.L M. Tennessee Valley Authority 80/09/23 3pp.
- I Financial information
- 8009090543 Forwards Annual Financial Rept 1979. Tennessee Valley Authority 80/09/04 1p
- -8009090563 Annual Financial Rept 1979
  \* Tennesses Valley Authority 80/09/04 44pp.
- O Inspection reports, IE Bulletine & correspondence
- 8009090078 Forwards IE Bulletin 80-07, Suppl 1, "BWR Jet Pump Assembly Failure " No response required
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director, 80/05/13
- 8007110111 Forwards IE Insp Repts 50-518/80-13,50-519/80-13, 50-520/80-13 & 50-521/80-13 on 800401-28 No noncompliance noted. NURPHY.C.E Region 2: Atlanta, Reactor Construction & Engineering Bupport Branch BO/07/28. 2pp Support Branch
- --8009110177 IE Insp Repts 50-518/80-13, 50-519/80-13, 50-520/80-13 & 50-521/80-13 on 800601-28 No noncompliance noted Major areas inspected earth compaction & structural concrete for spray & containment activities SWAN, H Region 2, Atlanta, Office of the Director CANTRELL,F 8 Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/28. opp

- 8009020184 Submits response to IE Bulletin 77-03A No 5A-312 or A-312. Type 300 series fusion welded pipe is in use or planned for use in safety-related sys MILLS: L M Tennessee Valley Authority 80/08/04 ip
- MEDDIC II MAINTENANT TO THE PROPERTY OF THE PR
- 8009020303 Forwards IE Insp Repts 50-327/80-24.50-328/80-15. 50-390/80-20.50-391/80-14.50-438/80-13.50-439/80-13. 50-518/80-11.50-519/80-11.50-520/80-11.50-521/80-11. 50-553/80-11.60-556/80-10.50-526/80-10 & 50-547/80-10 0'REFLLY, J P Region 2. Atlanta, Office of the Director 200
- --8009020312 Notice of violation from insp on 800707-11 \* Region 2. Atlanta. Office of the Director 80/08/06 4pp
- --8009020337 IE Insp Repts 50-327/80-24.50-328/80-15.50-390/80-20, 50-391/80-14.50-438/80-13.50-437/80-13.50-518/80-11. 50-519/80-11.50-520/80-11.50-553/80-11.50-553/80-11.50-554/80-10.50-556/80-10 & 50-557/80-10 an B00707-11 BROWNLEE.V L Region 2. Atlanta, Office of the Director 90/08/06 24pp
- 8009030146 Forwards Revision 1 to IE Bulletin 80-19. "Failures of Marcury-Watted Matrix Relays in Reactor Protective 8gs of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/15.
- 8009160045 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE BWR Facilities," No specific action or response requested
- 8009120066 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22
- 8009i60153 Forwards IE Circular 80-19, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/08/22.
- 8009240957 Responds to NRC 800617 ltr 80P-30 will be revised & implemented by 800827 resulting in full compliance Ref IE Insp Repts 50-518/80-07, 50-519/80-07, 50-520/80-07 & S0-521/80-09 MILLS, L M Tennessee Vailey Authority 80/08/22 in
- HO09120340 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-BDN 6009 Circuit Breaters "
  No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/08/27 is
- 800918006B Forwards response to IE Bulletin 80-16 Resemburt Models 1131 & 1132 pressure transmitters were planned for installation OE will analyze applications of transmitters to determine out-of-reading conditions MILLS: L M Tennessee Valley Authority 80/08/29 2pp.
- 8009240427 Forwards response to IE Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters. List of identified transmitters used in sefety-related areas being compiled Rept will be filed after resolution of deficiency MILLS, L M Tennessee Valley Authority. 80/08/29 2pp.
- 8009240380 Ack receipt of 800821 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-518/80-12, 50-520/80-12 & 50-521/80-12. MURPHY: C Region 2, Atlanta. Reactor Construction & Engineering Support Branch 80/09/02 ip
- --8009240387 Responds to NRC 800728 itr re violations noted in IE Insp Repts 50-518/80-12,80-519/80-12,50-520/80-12 & 50-521/80-12. Corrective actions reinforcing steel bars cited in rept are being placed on cribbing MILLS,L M Tannessee Valley Authority 80/08/21. 2pp
- --8009240398 Forwards IE Insp Repts 50-518/80-12, 50-519/80-12, 50-520/80-12 & 50-521/80-12 on 800630-0703 & notice of violation, MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/28 2pp

- --8009240406 Notice of violation from insp on 800630-0703 • Region 2. Atlanta, Office of the Director 80/07/25 ip
- --8009240421 IE Insp Repts 50-518/80-12,50-519/80-12,50-520/80-12 t 50-521/80-12 on 800630-0703 Noncompliance noted failure to follow reinforcing steel storage procedure HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch KLEINSORGE, W.P. Region 2, Atlanta, Office of the Director 80/07/25 8pp
- 3009260375 Forwards IE Circular 80-21, "Regulation of Refueling Crews." No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director. 80/09/10,
- 8 Reportable occurrences, LERs & related correspondence
- 8007040449 Final deficiency rept re containment anchor bolt chair welds All identified deficient welds will be repaired to original space & repaired areas tested Investigation conducted on previously accepted welds MILLS,L M Tennesses Valley Authority 80/07/24 App
- S007090427 Final deficiency rept re wiring discrepancies in high pressure core spray metal-clad switchgear Defective 8B-12 switches replaced Hardware corrections will be completed by 810130 & software corrections by 810430.

  MILLS.L M Tennesses Valley Authority 80/08/28 3pp.
- 8007070530 First interim deficiency rept re inadequate drawing control.
  Caused by breakdown of GA program re drawing control.
  Drawings will be updated on daily basis by using TVA receipt forms, Final rept to be transmitted on or before 80119.
  MILLS.L M Tennessee Valley Authority 80/08/28. 2pp
- 8009090494 Final interim deficiency rept re 6-inch Borg-Harner gate valves Valves may fail due to error in design. Gate could disengage from guide, when valve in backsest position, Valve failure may lead to RHR sys degradation
  MILLB. L M Tennessee Valley Authority. 80/08/29 2pp
- 8009090440 Final interim deficiency rept re wiring discrepancies on HPCS components. Discrepancies involve wiring terminations not matching wiring diagrams: missing wires & nonlabeling of parts Components will be reworked.

  HILLS.L M Tennesses Valley Authority. 80/08/29. 3pp
- 8007240425 Final deficiency rept re inadequate document control, Gaused by failure of menual holders to follow procedures in filing or removing matl Guarterly internal survey will be conducted.

  MILLS, L. H. Tennessee Valley Authority. 80/09/15 3pp
- 8009240092 Second interim deficiency rept re Rosemount Model 1152 pressure transmitter defects Util is preparing lists of Rosemount 1151 & 1152 transmitters for GE to analyze & replace if necessary Final rept will be provided by 810403 MILLS.L. M. Tennessee Valley Authoritu. 80/09/17. 3pp.
- 8009290375 Second interim deficiency rapt re steam tunnal embedment stiffner plate weld Causa not stated, Util continuing to monitor Atlas GA program to help correct deficiencies. MILLS, L. M. Tennassee Valley Authority 80/09/19 ip.
- 8007300445 Third interim deficiency rept re reactor pressure vessel shield well weld. Investigation is continuing & repairs will be made as required. Final rept should be submitted by 801224.

  MILLS:L M Tennessee Valley Authority. 80/09/24. 1p.
- DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3
- A Application/construction stage documents & correspondence
- BOOFOBOOBO Forwards draft NUREQ-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl. W/a NUREG EISENHUT, D. O Division of Licensing 80/08/01. 119pp
- 8009300400 Forwards technical questions re implementation of interim palicy on 100FR50 & 51.
  MILLS.L M Tennessee Valley Authority. 80/09/R3. 3pp.
- I Financial information .
- 8009090543 Forwards Annual Financial Rept 1979 CROSS, J. L. Tennessee Valley Authority 80/09/04 ip

- --8009090563 Annual Financial Rept 1979
   Tennesses Valley Authority 80/09/04 44pp
- & Inspection reports: IE Bulletins & correspondence
- 800707075 Forwards IE Bulletin 80-07. Suppl 1. "BWR Jet Pump Assembly Failure" No response required O'REILLY, J P Region 2, Atlanta, Office of the Director, 80/05/13 is.
- 8007110111 Forwards IE Insp Repts 50-518/80-13,50-519/80-13, 50-820/80-13 & 50-521/80-13 on 800401-28 No noncompliance nated. MURPHY, C E Region 2, Atlanta: Reactor Construction & Engineering Support Branch 80/07/28 2pp
- --8009110177 IE Insp Repts 50-518/80-13,50-519/80-13,50-520/80-13 & 50-521/80-13 on 800601-28 No noncompliance hoted Major areas inspected serth compaction & structural concrete for spray & containment activities
  SHAN.R W. Region 2, Atlanta, Office of the Director.
  CANTRELL, F. S. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/28 App
- 8007020184 Submits response to IE Sulletin 79-03A No GA-312 or A-312, Type 300 series fusion welded pipe is in use or planned for use in safety-related sys.

  HILLS,L M Tennessee Valley Authority 80/08/06 ip.
- 8009020303 Forwards IE Insp Repts 50-327/80-24.50-328/80-15. 50-390/80-20.50-391/80-14.50-638/80-13.50-639/80-13. 50-518/80-11.50-519/80-11.50-520/80-11.50-521/80-11. 50-553/80-11.80-554/80-10.50-56/80-10.50-56/780-10.
- --8009020312 Notice of violation from insp on 800707-11 + Region 2, Atlanta, Office of the Director. 80/08/06 App.
- --8009020337 IE Insp Repts 50-327/80-24,50-328/80-15,50-390/80-20,50-391/80-14,50-438/80-13,50-439/80-13,50-518/80-11,50-519/80-11,50-529/80-11,50-529/80-11,50-554/80-10,50-564/80-10 & 50-567/80-10 on 800707-11 SRONNLEE,V L Region 2, Atlanta, Office of the Director BO/08/06. 24pp
- 8007030145 Forwards Revision 1 to IE Bulletin 80-17, "Failures of Mercury-Wested Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J. P Region 2, Atlanta, Office of the Director 80/08/15, 1p
- 8009160045 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nanessential Control Air at Certain GE BHR Facilities." No specific action or response requested D'AEILLY, J P Region 2, Atlanta, Office of the Director 80/08/19.
- 9009120066 Forwards Suppl 3 to IE Builetin 80-17. "Failure of Control Rods to Insert During Scram at BMR" No written response required.

  O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/08/22
- BOOP160133 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written, response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. B0/08/22 Ip
- 8009240357 Responds to NRC 800617 ltr 80P-30 will be revised & implemented by 800829 resulting in full compliance Ref IE lasp Repts 50-518/80-09, 50-519/80-09, 50-520/80-09 & 50-521/80-09.

  MILLS,L. H Tennessee Valley Authority 80/08/22 ip.
- 8009120340 Forwards IE Info Notice 80-31, "Maloperation of Qould-Brown Bover! 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers," No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director, 80/08/27. io.
- 8009180068 Forwards response to IE Bulletin 80-16 Rosemount Models 1151 & 1152 pressure transmitters were planned for installation. OE will analyze applications of transmitters to determine out-of-range conditions.

  KKLLS.L.M. Tannessee Valley Authority 80/08/29 2pp.

- 8007180087 Submits response to IE Bulletin 80-19 No mercury-wested matrix relays are in use in reactor protection sys HILLS,L M Tennessee Valley Authority 80/08/29 ip
- BO09240427 rorwards response to IE Bulletin 80-14 re potential misapplication of Rosemount pressure transmitters List of identified transmitters used in safety-related areas being compiled Rept will be filed after resolution of deficiency MILLS,L M Tennessee Valley Authority B0/08/27 2pp
- 80092403B0 Ack receipt of 800821 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-518/80-12, 50-519/80-12, 50-520/80-12 & 50-521/80-12 MVRPHY.C E Region 2: Atlanta: Reactor Construction & Engineering Support Branch 80/07/02 ip
- --8009240387 Responds to NRC 800728 ltr re violations noted in IE Insp Repts 50-518/80-12,50-519/80-12,50-520/80-12 & 50-521/80-12 Corrective actions reinforcing steel bars cited in rept are being placed on cribbing MILLS.L M Tennessee Vailey Authority 80/08/21 2pp
- --8009240398 Forwards IE Insp Repts 50-518/80-12,50-519/80-12, 50-520/80-12 & 50-521/80-12 on 800430-0703 & notice of violation MURPHY,C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/28 2pp
- --8009240406 Notice of violation from insp on 800630-0703. \* Region 2, Atlanta, Office of the Director 80/07/25 ip
- --8009240421 IE Insp Repts 50-518/80-12,50-519/80-12,50-520/80-12 & 50-521/80-12 on 800630-0703 Noncompliance noted failure to follow reinforcing steel storage procedure HERDT.A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch KLEINSURGE.W P Region 2, Atlanta Office of the Director 80/07/28 8pp.
- 8009260375 Forwards IE Circular 80-21, "Regulation of Refueling Graws "
  No written response required
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/10
  Spp.
- 8. Reportable occurrences, LERs & related correspondence
- 8007070427 Final deficiency rapt re wiring discrepancies in high pressure core spray metal-clad switchgear Defective 89-12 switches replaced. Hardware corrections will be completed by 810130 & software corrections by 810530 MILLS,L M. Tennessee Valley Authority 80/08/28 3pp
- 8009090434 Final interim deficiency rept re 6-inch Borg-Warner gate valves Valves may fail due to error in design Gate could disengage from guide: when valve in backseat position Valve failure may lead to RHR sys degradation MILLS.L.M Tennessee Valley Authority 80/08/29 2pp.
- BOD7070440 Final interim deficiency rept re wiring discrepancies on MPCB components Discrepancies involve wiring terminations not matching wiring diagrams.missing wires & nonlabeling of parts Components will be reworked.

  MILLS.L.M Tennesses Valley Authority 80/08/27 3pp
- 8009240425 Final deficiency rept re inadequate document control Caused by failure of manual holders to follow procedures in filing or removing matl Quarterly internal survey will be conducted.

  MILLS, L. M. Tennessee Valley Authority 80/09/15 Spp
- 8009240392 Second interim deficiency rept re Rosemount Model 1152 pressure transmitter defects Util is preparing lists of Rosemount 1151 & 1152 transmitters for OE to amalyze & replace if necessary. Final rept will be provided by 810403 MILLS,L M Tennessee Valley Authority 80/09/17. 3pp
- 8009270375 Second interim deficiency rept re steam tunnel embedment stiffner plate weld. Cause not stated Util continuing to monitor Atlas GA program to help correct deficiencies MILLS,L M Tennessee Valley Authority 80/09/19 ip.

- DOCKET STN-80-521 HARTSVILLE NUCLEAR PLANT, UNIT 4
- A Application/construction stage documents & correspondence
- 8007080080 Forwards draft NUREG-0o76, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl W/o NUREG EISEMHUT, D O Division of Licensing. 80/08/01. 119pp
- 8009300400 Forwards technical quastions re implementation of interim policy on 100FR90 & 31 MILLS,L M Tennessee Valley Authority 80/09/23 3pp
- I Financial information
- 8007090543 Forwards Annual Financial Rept 1979 CRBSS, J.L. Tennessee Valley Authority 80/09/04 1p
- --8009090563 Annual Financial Rept 1979
  \*\* Tennessee Valley Authority 80/07/04 44pp
- G Inspection reports, IE Bulletins & correspondence
- 8007070075 Forwards IE Bulletin 80-07. Suppl 1, "BHR Jet Pump Assembly Failure" No response required D'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/13, ip
- 8009110111 Forwards IE Insp Repts 50-519/80-13:50-519/80-13: 50-520/80-13 & 50-521/80-13 on 800601-28 No noncompliance noted MURPHY.C E Region 2, Atlanta. Reactor Construction & Engineering Support Branch 80/07/28 2pp
- --8007110177 IE Insp Repts 50-518/80-13, S0-519/80-13, 50-520/80-13 & S0-521/80-13 on 800601-28 No noncompliance noted Major areas inspected earth compaction & structural concrete for spray & containment activities
  SHAN.R W Region 2, Atlanta, Office of the Director. 80/07/28
- 8009020184 Submits response to IE Sulletin 79-03A No 8A-312 or A-312. Type 300 series fusion welded pipe is in use or planned for use in safety-related tys.

  MILLS.L.M. Tennessee Valley Authority. 80/09/06. ip
- 8007020303 Forwards IE Insp Repts 50-327/80-24,50-328/80-15, 50-397/80-20,50-391/80-14,50-438/80-13,50-439/80-13, 50-518/80-11,50-519/80-11,50-520/80-11,50-521/80-11,50-593/80-11,50-593/80-10,50-366/8
- --8009020312 Notice of violation from insp on 800707-11.

  \* Region 2, Atlanta, Office of the Director 80/08/06 4sp
- --8007020337 IE Insp Repts 50-327/80-24.50-328/80-15.50-390/80-20.50-391/80-14.50-438/80-13.50-439/80-13.50-518/80-11.50-51/80-11.50-52/80-15.50-51/80-11.50-52/30-15.50-51/80-10.50-554/80
- 8007030146 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Marcury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required.

  O'REILLY, J P. Region 2, Atlanta, Office of the Director, 80/08/15 ip
- G009160045 Forwards IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Stram Function & Nonessential Control Air at Certain GE BWR Facilities " No specific action or response requested O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/08/19 is
- 8009120066 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BUR." No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22.

- 8009160153 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required
- O'REJLLY, J.P. Region 2, Atlanta, Office of the Director. 80/08/22.
- 8009240387 Responds to NRC 800617 ltr 80P-30 will be revised & implemented by 800829 resulting in full compliance Ref IE Insp Repts 50-518/80-09, 50-519/80-09, 50-520/80-09 & 50-521/80-09 MILLS,L M Tennessee Valley Authority 80/08/22 ip
- 8009120340 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brow. Bover( 450 Volt Type K-6005 & K-DON 6005 Circuit Breakers." No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director. BO/08/27
- O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/08/27 ip
- B0091B00AB Forwards response to IE Bulletin B0-16. Rosemount Models ii51 & 1152 pressure transmitters were planned for installation OE will analyze applications of transmitters to determine out-of-analyze conditions
  MICLB.L M Tennessee Valley Authority 80/08/29, 2pp.
- 8009180087 Submits response to IE Bulletin 80~19 No mercury-usatted matrix relays are in use in reactor protection sys MILLS.L M Tennessee Valley Authority 80/08/29 ip
- 8007240427 Forwards response to IE Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters. List of identified transmitters used in safety-related areas being complied Rept will be filed after resolution of deficiency MILLS.L.M. Tennassee Valley Authority 80/08/27. 2pp.
- 8009240390 Ack receipt of 800821 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-518/80-12, 50-519/80-12, 50-520/80-12 & 50-521/80-12 MVRPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/09/02 ip
- --8009240387 Responds to NRC 800728 ltr re violations noted in IE Insp Repts 50-518/80-12,50-519/80-12,50-520/80-12 & 50-521/80-12. Corrective actions reinforcing steel bars cited in rept are being placed on cribbing MILLS.L M Tennessee Valley Authority 80/08/21. 2pp
- --8009240398 Forwards IE Insp Repte 50-518/80-12,50-519/80-12, 50-520/80-12 & 50-521/80-12 on 800630-0703 & notice of violation MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/28, 2pp.
- --8009240406 Notice of violation from insp on 800630-0703,
  \* Region 2, Atlanta, Office of the Director, 80/07/25 1p
- --8009240421 IE Insp Repts 50-518/80-12,50-519/80-12,50-520/80-12 k 50-521/80-12 on 800630-0703 Noncompliance noted failure to follow reinforcing stesi storage procedure HERDT A R. Region 2. Atlanta Reactor Construction & Engineering Support Branch 80/07/25 Spp
- 8009260375 Forwards IE Circular 80-21, "Regulation of Refueling Craws."
  No written response required
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/09/10
- 8. Reportable occurrences. LERs & related correspondence
- 8007070427 Final deficiency rept re wiring discrepancies in high pressure core spray metal-clad switchgear Dafective 88-12 switches replaced Hardware corrections will be completed by 810130 % software corrections by 810530 % of the same corrections by 810530 MILLS,L M Tennessee Valley Authority 80/08/28 3pp
- 8007070434 Final interim deficiency rept re 6-inch Borg-Warner gate valves Valves may fail due to error in design Cate could disengage from guide, when valve in backseat position Valve failure may lead to RHR sys degradation MILLS.L M Tennessee Valley Authority, 80/08/27. 2pp
- 8007070440 Final interim deficiency rept re wiring discrepancies on HPCB components Discrepancies involve wiring terminations not matching wiring diagrams: missing wires & nonlabeling of parts Components wiil be reworked MILLS.L M Tennessee Valley Authority 80/08/27 3pp.

- 9009240425 Final deficiency rept re inadequate document control Caused by failure of manual holders to follow procedures in filing or removing mat! Quarterly internal survey will be MILLE, L M Tennessee Valley Authority 80/09/15
- 8009240392 Becond interim deficiency rept re Rosemount Model 1152 pressure transmitter defects Util is preparing lists of Rosemount 1151 & 1152 transmitters for QE to analyze & replace if necessary Final rept will be provided by 810403 Hill& L. M Tennessee Valley Authority 80/09/17 3pp
- 8009290375 Second interim deficiency rept re steam tunnel embedment stiffner plate weld Cause not stated Util continuing to monitor Atlas GA program to help correct deficiencies MLLS, L. M. Tennessee Valley Authority 80/09/19. ip
- DOCKET RIN-50-522 SKAQIT NUCLEAR POWER PROJECT, UNIT 1
- A. Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREO-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days, Proposed implementation schedule for meeting criteria of NUREO-0696 encl M/o NUREO. EISENHUT.D.O Division of Licensing 80/08/01 119pp.
- O. Adjudicatory correspondence
- BOO9180528 Statement suggesting that full Commission review of orders & opinions below not necessary due to moothess ASLB 800827 order indicates proceeding has terminated BUBCH, R. W., MEANS, D.S. Affiliation Unknown, 80/09/11 2pp
- DOCKET BIN-50-523 SKAQIT NUCLEAR POWER PROJECT, UNIT 2
- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 NOPOBOOBU Forwards graft NUREO-0595, "Functional Criteria for Emergency Response Facilities "Comments requested within 3 days.Proposed implementation schedule for meeting criteria of NUREO-0696 encl. W/o NUREO EIBENNUT.D.O. Division of Licensing 80/08/01. 119pp
- 9. Adjudicatory correspondence
- 8009180528 Statement suggesting that full Commission review of orders & spinions below not necessary due to mootness. ASLE 800827 order indicates proceeding has terminated.
  BUSCH.R W., MEANS, D 8 "Affiliation Unknown 80/09/11 2pp
- DOCKET BIN-50-529 PALO VERDE NUCLEAR STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- 8007030205 Responds to 800417 request for info re NRC involvement in archeological data recovery activities for FY77 Completed quastionnaire encl DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 80/06/11. 7pp
- 8009080080 Forwards draft NUREO-0676, "Functional Criteria for Emergancy Response Facilities." Comments requested within 30 days. Proposed implementation schedule for meeting criteria of NUREO-0676 encl. M/o NUREO. Division of Licensing, 80/08/01, 119pp ETRENHUT, D. O.
- 9009020335 Notification of 900815 meeting w/util in Bethesda, MD to discuss whether auxiliary feedwater sys meets design
  - KERRIGAN, J Licersing Branch 3, 80/08/14, 2pp.
- BOO9120551 Notification of 800821 & 22 meeting w/util in Phoenix, AZ to discuss auxiliary feedwater sys review, KERRIGAN, J. Licensing Branch 3, 80/08/15. 3pp
- BOOT030511 Submits response to NRC 800421 info request on Category 1 mesonry walls employed by plants under CP & OL review.

  Brewings 19-A-ZJD-509 through 511, 13-A-ZAD-203 & 13-A-ZAD-207 evaliable in Central Files.

  VAN BRUNT, E. E. Arizona Public Service Co 80/08/25. 3pp
- 9009120508 Forwards updated distribution list for suppl & amend to FBAR & environ rept Supersedes 800618 list KERRIGAN, J. Licensing Branch 3 80/08/25 5pg.

- 8007090523 Forwards comments of util review board re open items from Class IE do power sys review Six items identified which require addictarification VAN BRUNT.E E Antiona Public Service Co 80/07/04 4pp
- 8009150538 Advises that ASME Code Cases N-274 & N-275 may be used in piping Spec 13-DM-204 sub, to conditions re ferritic metls for N-274 & full weld thickness removal for N-275 Code cases should be documented in FSAR Assistant Director for Licensing 80/09/04 3pp.
- 8009180534 Notification of 800925 sys review meeting w/util & Bechtel in Phoenix,AZ re equipment qualification Agenda encl KERRIGAN,J D Licensing Branth 3 80/09/05 3pp
- 8009160595 Notification of 800925 meeting w/util & Bechtel in Phoenix. AZ to conduct sys review meeting re equipment qualification KERRIGAN, J.D. Licensing Branch 3 80/09/12 3pp
- 8009240422 Forwards Bethbel Power Corp responses to outstanding open items of Class IE do power sys review Responses are intended to resolve outstanding concerns of BC Power Sys Review Board Final resolution of open items will be provided VAN BRUNT, E. E. Arizona Public Service Co. 80/09/18 12pp
- C Utility Environmental Report (ER), amends & correspondence
- B00912050B Forwards updated distribution list for suppl & amend to FSAR & environ rept Supersedes 800618 list KERRICAN, J. Licensing Branch 3 60/08/25 5pp
- 8009090392 Forwards Suppl 1 to environ rept for facility.
  VAN BRUNT, E. E. Arizona Public Service Co. 80/09/08 1p
- --8007090398 Suppl 1 to facility environ rapt
  \* Arizona Public Service Co. 80/09/30 53pp
- 8007230701 Forwards proof of svc for Buppl 1 to environ rept.OL stage required by 10CFR2, 101 & D Eisenhut B00608 ltr
  VAN BRUNT, E E Arizona Public Service Co. 80/09/15 5pp
- F Security, medical, emergency & fire protection plans
- 8007030262 Notifies of 800819.22 & 30 regional workshops re development of guidance for acceptable method for coping w/emergencies at facility Requests that representative be sent Sub; areas to be discussed include function of facilities & location ENGELKEN, R H. Region 5. San Francisco. Office of the Director, 80/08/12 2pp
- Q. Adjudicatory correspondence
- 8007030714 Response in opposition to PL Hourihan.K Dahl & C Shuey 800811 patition to intervane Petitioners failed to establish standing or specify interest Aspects affecting patitioners not identified W/Certificate of Syc GEHR.A C , BISCOFF.C.A Arizona Public Service Co GEHR.A C Snell & Wilmer 80/08/26 Opp.
- 8009040274 Response in support of P Hourihan 800811 patition to intervene & request for hearing conditioned on particularization of aspects of concern Supports holding hearings in Phoenix area W/appearance & Certificate of Svc KCGURREN, H J Hearing Branch 1 80/09/02 11pp
- 8007080514 Notice of establishment of ASLB to preside in DL applications, environ rept & opportunity for hearing proceedings, RM Lazo appointed chairman, RF Cole & B Callahan members, LAZO.R M Atomic Bafaty and Licensing Board Panel 80/09/03 200
- H General correspondence
- 8009100457 Ack receipt of 800705 itr & forwards Friends of the Earth Class 9 petition & Director's decision on patition M/o encl 80HMENGER, A Licensing Branch 2 80/08/27, 2pp
- ~-8009100463 Requests Director's decision on Friends of the Earth petition to consider Class 9 accidents in supplemental EIB FRIESEMA, H P Northwestern Univ. 80/07/05 ip
- 8009050083 Forwards 800725 FR notice re procedural assistance change in adjudicatory licensing proceedings, per 800902 telcon W/o encl MCGURREN, H J Hearing Branch 1 80/09/03 ip

- 8009250466 Responds to 800620 ltr re NRC licensing procedures rules of practice docketing procedures & milestones for facilities 8CHWENGER.A Licensing Branch 3 80/09/12 Rop
- X Utility Final Safety Analysis Report (FBAR) & amends
- 8009120508 Forwards updated distribution list for suppl & amend to FSAR & environ rept Supersedes 800518 list KERRIGAN. J. Licensing Branch 3 80/08/25 5pp
- 8009300402 Forwards Amend 2 to FSAR
  VAN BRUNT.E E Arizona Public Service Co 80/09/29 1p.
- --B009300405 Amend 2 to FSAR.responding to NRC 800618 questions & correcting text App 148 & oversize drawings encl # Arizona Public Service Co 80/09/29 300pp
- @ Inspection reports, IE Bulletins & correspondence
- 8009030674 Responds to IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Facility design incorporates butt welded sleeve connections for continuity of containment boundary Sixty-three joints have been welded VAN BRUNT, E. Arizona Public Service Co. 80/07/08 2pp
- 8007050477 Requests 60-day extension to respond to IE Bulletin 79-03A. "Longitudinal Held Defects in ASME 8A-312, Type 304 Steinless Steel Pips " VAN BRUNT, E E Arizona Public Service Co 80/07/10 1p
- 209120292 Forwards IE Insp Rapts 50-528/80-10.50-529/80-10 & 50-530/80-10 on 800402-27 No noncompliance noted SPENCER.O S. Ragion 5. San Francisco, Reactor Construction & Engineering Support Branch 80/08/05 2pp
- -8009120296 IE Insp Repts 50-528/80-10, 50-529/80-10 to 50-530/80-10 on 800602-27 No noncompliance noted Major areas inspected. installation of Unit 1 spray pond piping & Unit 2 dome spray headers DGDDS: R T Region 5, Ban Francisco. Reactor Construction & Enginering Support Branch VORDERBRUEGOEN Region 5, San Francisco. Dffice of the Director 80/08/05 App.
- 8009120234 Responds to IE Bulletin 80-16 No Rosemount Model 1151 & 1152 pressure transmitters are used in any safety-related applications VAN SRUNTIE E Arizona Public Service Co 80/09/11 (p. 7
  - 9120496 Forwards IE Imag Repts 30-528/80-08,50-529/80-08 & 0-530/80-08 on 800520-23 No noncompliance noted PENCER, G B Region b. San Francisco. Reactor Construction & ngineering Support Branch. 80/08/42 2pg
  - pu09120500 IE Imap Repts 50-528/80-08, 50-529/80-08 & 50-530/80-08 on 800520-23 No noncompliance noted Major areas inspected const activities, preheat & post-weld treatment & containment liner welding DoDDS: R T Region 5, San Francisco, Reactor Construction & Engineering Support Branch ECKHARDT. J H., NARBUT, P. P. Region 5, San Francisco, Office of the Director 80/08/11 7pp
  - 9030276 Forwards Revision i to IE Bolletin 80-19, "Failures of ercury-Wetted Matrix Relays in Reactor Protective Sys of perating Nuclear Power Plants Designed by C-E " Written asponse required. WOELKEN.R.H Region 5, San Francisco, Office of the Director #0/08/15 1p
  - >9290307 Forwards IE Info Notice 80-27, "Degradation of Reactor collent Pump Studs." No written response required NOELKEN, R H Region 9, San Francisco, Office of the Director 10/08/18 4pp
  - 9160178 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations or Changes to Radwaste Treatment Sys " No written response equired NGELKEN, R H Region 5, San Francisco, Office of the Director 0/08/22 ip
  - )9190159 Forwards IE Inep Repts 80-528/80-11, 50-529/80-11 & 10-530/80-11 on 800610. No noncompliance noted NGELKEN, R H Region 5, San Francisco, Office of the Director 10/08/22 Ip

- --8009190169 IE Insp Repts 50-528/80-11:50-529/80-11 & 50-530/80-11 on 800610 No noncompliance noted Major areas inspected meeting to discuss results of Region 5 licensee performance evaluation for May 1979 through May 1980 ENDELKEN, R H, VORDERBRUEGGEN Region 5, wan Francisco. Office of the Director SpENCER, O S. Region 5, San Francisco. Reactor Construction & Engineering Support Branch 80/08/20 4pp.
- --B009190178 Discusses semiannual regional evaluation of facilities for May 1979 through May 1990 Licensee performance is generally satisfactory & strong licensee effort should be made to ensure current & future work is adequately controlled DIDDG.R T Region 5. San Francisco, Reactor Construction & Engineering Support Branch ECHHARDT.J H., VORDERBRUEGOEN Region 5. San Francisco, Diffice of the Director B0/08/20 Bpp
- --8009190183 Confirms actions to be taken.per 790508 telcon.re severe misfit & distortion problems w/installation of containment dome liner segments & current field procedures to make force fit-ups.

  ENGELKEN.R H Region 5, San Francisco, Office of the Director. 79/03/09 3pp
- BOO9:20456 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Bover: 480 Volt Type K-6005 & K-DON 6008 Circuit Breakers " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director, 80/08/27 1p
- & Reportable occurrences, LERs & related correspondence
- 8007020528 Ack receipt of final deficiency rept re Borg-Warner valve stem extension loosening problem ENGELKEN.R H Region 5, Sen Francisco, Office of the Director. BO/08/15 1p
- --8009020532 Final deficiency rept re Borg-Warner valve stem extension lossening problem Mod to correct deficiency will be completed prior to startup.

  VAN BRUNTLE E Arizona Public Bervice Co 80/07/29. 3pp.
- 8007030556 Final deficiency rept re undersized structural steel fillet welds Welds are sufficient to handle design loading while providing adequate safety margin for crack prevention Dispositioned as not reportable VAN BRUNT, E.E. Arizona Public Service Co. 80/08/25, app.
- ~~8009030563 "Evoluation of Structural Fillet Weid Bamples for Underhead Cracking." FULLING.C., SCHMIDT, G.R., HACKNEY, B.D. Bechtel National, Inc 80/02/06. 30pp
- 8009230653 final deficiency rept re failure of vertical fire dampers to close Investigation of closure problem determined that design tolerances not maintained between frame & damper slide Deficient frame & damper blade will be replaced.

  VAN BRUNT, E. E. Arizona Public Service Co 80/09/15 7pp.
- T. Hearing transcripts on non-antitrust matters
- 8009160373 Forwards transcript of 800709 review re Class IE ac power sys includes discussion of open items re review board & NRC unanswered questions & requests for info. VAN SRUNTIE. E. Arizona Public Service Co 80/09/11 ip.
- DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8009030285 Responds to 800417 request for info re NRC involvement in archeological data recovery activities for FY79. Completed questionnairs encl.
  DENTON H R. Office of Nuclear Reactor Regulation, Director.
  80/06/11. 7pp
- BOO9080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days. Proposed implementation schedule for meeting criteria of NUREG-0696 encil W/a NUREO EISENKUT, D O Division of Licensing, 80/08/01, 119pp.
- 8009020335 Notification of 800815 meeting w/util in Bathesda: MD to discuss whether auxiliary feedwater sys meets design criteria KERRIGAN, J. Licensing Branch 3 80/08/14 2pp.

- BOO9120551 Notification of BOO921 & 22 meeting w/util in Phoenix.AZ to discuss auxiliary feedwater sys review KERRIOAN, J Licensing Branch 3 80/08/15 3pp
- a009030511 Submits response to NRC 800421 info request on Category 1 masonry walls employed by plants under CP & OL review Drawings 13-A-ZJD-509 through 511.13-A-ZAD-203 & 13-A-ZAD-207 available in Central Files VAN RRUNT,E E Arizona Public Service Co 80/08/25 3pp
- BO09120308 Forwards updated distribution list for suppl & amend to FBAR & environ rapt Supersedes 800618 list XERRIGAN, J Licensing Branch 3 80/08/25, 5pp
- 8009090323 Forwards comments of util review board re open items from Class IE do power sys review Bix items identified which require add1 clarification
  VAN BRUNT.E E Arizona Public Service Co 80/09/04 App.
- 9009180338 Advises that ASME Code Cases N-274 & N-275 may be used in piping Spec 13-DM-204 subj to conditions re ferritic matts for N-274 & full weld thickness removal for N-275 Code cases should be documented in FBAR TEDESCO.R L Assistant Director for Licensing 80/09/04 3pp
- BOO9180534 Notification of 800925 sys review meeting w/util & Bechtel in Phoenix, AZ re equipment qualification Agenda encl KERRIGAN, J D Licensing Branch 3 80/09/05 3pp
- 9009160595 Notification of 800925 meeting w/util & Bechtel in Phoenix. AZ to conduct sys review meeting re equipment qualification KERRIOAN, J. D. Licensing Branch 3 80/09/12 3pp
- BOO9240422 Forwards Bachtel Power Corp responses to outstanding open items of Class IE do power sys review Responses are intended to resolve outstanding concerns of DC Power Sys Review Board, Final resolution of open items will be provided VAN BRUNT, E.E. Arizona Public Service Co. 80/09/18 12pp
- C Utility Environmental Report (ER), amends & correspondence
- BOO912050B Forwards updated distribution list for suppl & amend to FBAR & environ rept Supersedes 800618 list KERRIGAN, J. Licensing Branch 3 80/08/25 5pp
- SOOPO70392 Forwards Suppl 1 to environ rept for facility
  VAN SRUNT, E E Arizona Public Service Co 80/09/08 ip
- --8009070378 Suppl i to facility environ rept.

  # Arizona Public Service Co 80/09/30 53pp
- BOO9230701 Forwards proof of svc for Suppl 1 to environ rept.CL stage required by 10CFR2.101 & D Eisenhut 800608 ltr VAN BRUNT, E.E. Arizone Public Service Co 80/09/15 5pp
- F. Security, medical, emergency & fire protection plans
- BOO9030262 Notifies of 800819.22 & 30 regional workshops re development of guidance for acceptable method for coping w/emergencies at facility. Requests that representative be sent 80bj areas to be discussed include function of facilities & location. EMDELKEN.R.H. Region 5. San Francisco. Office of the Director 80/09/12. 2pp.
- Adjudicatory correspondence
- BOG9030714 Response in opposition to PL Hourihan, K Dahl & C Shuey BOOS11 petition to intervene Petitioners failed to establish standing or spacify interest Aspects affecting petitioners not identified H/Certificats of Syc.

  OCTM: A C., BISCOFF.C. A Arizona Public Service Co OEHR: A C., Bnell & Wilmer 80/08/26 Opp
- OO9040276 Response in support of P Hourihan 800811 patition to Intervene & request for hearing conditioned on particularization of aspects of concern Supports holding hearings in Phoenix area. W/appearance & Certificate of Syc PSCOURREN.H. J Hearing Branch 1 80/09/02 11pp.
- MODOB0514 Notice of establishment of ASLB to preside in OL applications, environ rept & opportunity for hearing proceedings. RM Lazo appointed chairman, RF Cole & B Gallshan members LAZO, R M Atomic Safety and Licensing Board Panel 80/09/03 2pp.

- H General correspondence
- 8009100457 Ack receipt of 800705 ltr & forwards criends of the Earth Class 9 petition & Director's decision on petition W/o encl SCHWENCER A Licensing Branch 2 80/08/27 2pp
- --8009100463 Requests Director's decision on Friends of the Earth petition to consider Class 9 accidents in supplemental EIS FRIEDEMA: HP Northwestern Univ 80/07/05 19
- 8009050083 Forwards 800725 FR notice re procedural assistance change in adjudicatory licensing proceedings.per 800902 telcon. W/o encl MCGURREN, H J Hearing Branch 1 80/09/03. 1p
- 8009250466 Responds to 800620 ltr re NRC licensing procedures.rules of practice, docketing procedures 8 milestones for facilities 8CKWENCER.A Licensing Branch 3 80/09/12 2pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8009120508 Forwards updated distribution list for suppl & amend to FBAR & environ rept Supersedes 800618 list KERRIGAN, J. Licensing Branch 3 80/08/25. Spp
- 8009300402 Forwards Amend 2 to FSAR
  VAN BRUNT, E E Arizona Public Service Co 80/09/29 ip
- ---8007300405 Amend 2 to FSAR, responding to NRC 800618 questions & correcting text App 148 & oversize drawings encl \* Artisma Public Service Co 80/09/29 300pp
- G Inspection reports, IE Bullstins & correspondence
- 8009030674 Responds to IE Bulletin 80-08; "Exam of Containment Liner Penetration Wolds " Facility design incorporates butt welded sleeve connections for continuity of containment boundary Sixty-three joints have been welded VAN BRUNT, E.E. Arizona Public Service Co. 80/07/08 2pp
- 8007050497 Requests 40-day extension to respond to IE Bulletin 77-03A, "Longitudinal Weld Defects in ASME SA-312. Type 304 Btainless Steel Pipe "
  VAN BRUNT, E. E. Arizona Public Service Co 80/07/10. ip
- 8007120272 Forwards IE Insp Repts 50-528/80-10,80-927/80-10 & 50-630/80-10 on 800602-27 No noncompliance hoted BPENCER. © 8 Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/08/05 2pp
- --8009120294 IE Insp Repts 50-528/80-10.50-529/80-10 & 50-530/80-10 on B00602-27 No noncompliance noted Major areas inspected: installation of Unit i spray pond piping & Unit 2 dome spray headers DDDDB.R T Region 5, San Francisco. Reactor Construction & Engineering Bupport Branch VORDERBRUEOGEN Region 5, San Francisco, Office of the Director 80/08/05 6pp
- 8009120234 Responds to IE Bulletin 80-16 No Rosemount Model 1151 & 1152 pressure transmitters are used in any safety-related applications VAN BRUNT; E E Arizona Public Service Co 80/08/11 ip.
- 8007120474 Forwards IE Insp Repts 50-528/80-08.50-529/80-08 & 50-530/80-08 on 800520-23 No noncompliance noted SPENCER, G & Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/08/12 2pp
- 1009120500 IE Insp Repts 50-528/80-08.50-529/80-08 & 50-530/80-08 on 800520-23 No noncompliance noted Major areas inspected const activities, preheat & post-weld treatment & containment liner welding DODDS, R.T. Region 5, San Francisco, Reactor Construction & Engineering Support Branch. ECKHARDT, J. H., NARBUT, P. P. Region 5, San Francisco, Office of the Director 80/08/11 7pp.
- B009030274 Forwards Revision 1 to 1E Bulletin 80-19. "Failures of Hercury-Wetted Hatrix Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E " Written response required ENOBELKEN, R H Region 5, San Francisco, Office of the Director B0/08/15 ip
- 8009290307 Forwards IE Info Notice 80-27, "Degradation of Reactor Coglant Pump Stude " No written response required ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/08/18 4pp

- 8009160178 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/08/22 16
- 8009190159 Forwards IE Insp Repts 50-528/80-11, 50-529/80-11 & 50-530/80-11 on 800610 No noncompliance noted ENGELKEN, R H Region 5, San Francisco, Office of the Director. 80/08/22 1p
- --B009190169 IE Insp Repts 50-528/80-11.50-529/80-11 & 50-530/80-11 on B00610 No noncompliance noted Major areas inspected meeting to discuss results of Region 5 licensee performance evaluation for May 1977 through May 1980 ENCELMEN, R H , VORDERBRUEGOEN Region 5. San Francisco, Office of the Director SPENCER, G S Region 5. San Francisco, Reactor Construction & Engineering Support Branch B0/08/20 4pp
- --BCO9190178 Discusses semiannual regional evaluation of facilities for May 1979 through May 1980 Licenses performance is generally satisfactory & stong licensee effort should be made to ensure current & future work is adequately controlled DDDS.R T Region 5, San Francisco, Reactor Construction & Engineering Support Branch ECKHARDT.J H, VORBERBRUEGOEN Region 5, San Francisco, Office of the Director 80/08/20 Spp
- 8009120456 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Voit Type K-6008 & K-DON 6008 Circuit Breakers " No written response required ENMELKENR H Region 5, San Francisco. Office of the Director 80/08/27 Ip
- } Reportable occurrences, LERs & related correspondence
- 3009020528 Act receipt of final deficiency rept re Borg-Warner valve stem extension loosening problem ENGELKEN.R.H Region 5, San Francisco, Office of the Director 80/08/15 ip
- --8009020532 Final deficiency rept re Borg-Warner valve stem extension loosening problem Mod to correct deficiency will be completed prior to startup VAN BRUNTLE E Arizona Public Service Co 80/07/29 3pp
- BOO9030556 Final deficiency rept re undersized structurel steel fillet welds Helds are sufficient to handle design loading while providing adequate safety margin for crack prevention Dispositioned as not reportable VAN BRUNT, E E Arizona Public Service Co 80/08/25 App
- --8009030563 "Evaluation of Structural Fillet Hald Samples for Underbead Cracking " PULINS.C. SCHMIDT.OR. HACKNEY.B D Bechtel National, Inc B0/02/06 30pp
- 8009230653 Final deficiency rept re failure of vertical fire dampers to close investigation of closure problem determined that design tolerances not maintained between frame & damper slide Deficient frame & damper blade will be replaced VAN BRUNT, E & Arizona Public Service Co 80/09/15 7pp.
- 8009300355 Final deficiency rept re dowel ammission from concrete wall pours of control bldg Condition is being corrected following approved deposition to drill & grout required dowels into wall following design drawing requirement VAN BRUNT, E E Arizona Public Service Co 80/09/24. 3pp.
- T Hearing transcripts on non-antitrust matters
- 8009140373 Forwards transcript of 800709 review re Class IE ac power sys Includes discussion of open items re review board & NRC unanswered questions & requests for info VAN BRUNTLE E. Arisona Public Service Co. 80/09/11, ip
- --8009160379 Transcript of 800709 review re Class IE ac power sys in Bethesda, MD Pp 1-195 W/supporting documentation. \* Arizona Public Service Co 80/09/11 275pp.
- DOCKET STN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3

  A Application/construction stage documents & correspondence
- 8007030285 Responds to 800417 request for info re NRC involvement in archeological data recovery activities for FY79, Completed questionnaire encl DENTON-H R Office of Nuclear Reactor Regulation. Director 80/06/11 7pp

- 8007080080 Forwards draft NUREO-0676, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Progosed implementation schedule for meeting criteria of NUREO-0676 encl M/a NUREO EISENHUT,
- 8009020335 Notification of 800815 meeting w/util in Bethesda, MD to discuss whether auxiliary feedwater sys meets design criteria KERRIOAN, J. Licensing Branch 3 80/08/14 2pp
- 8009120551 Natification of 800821 & 22 meeting w/util in Phoenix, AZ to discuss auxiliary feadwater sys review KERRIGAN, J Licensing Branch 3, 80/08/15 3pp
- B009030511 Submits response to NRC B00421 info request on Category 1 masonry walls employed by plants under CP & OL review Drawings 13-A-ZJD-509 through 511.13-A-ZAD-203 & 13-A-ZAD-207 available in Central Files VAN BRUNT.E E Arizona Public Service Co 80/08/25 3pp.
- 8009120508 Forwards updated distribution list for suppl & amend to FBAR & environ rept Supersedes 800618 list KERRIGAN-J Licensing Branch 3 80/08/25 5pp
- 8007090523 Forwards comments of util review board re open items from Class IE &c power sys review Six items identified which require addictarification VAN BROWTE & Arizona Public Service Co 80/09/04 4pp
- 8009150538 Advises that ASME Code Cases N-274 & N-275 may be used in piping Spec 13-DM-204 subj to conditions re ferritic matls for N-274 & full weld thickness removal for N-275. Code cases should be documented in FSAR TEDESCO.R L Assistant Director for Licensing. 80/09/04 3pp.
- 8009180534 Notification of 800925 sys review meeting w/util & Bechtel in Phoenix, AZ re equipment qualification Agenda encl KERRIGAN, J.D. Licensing Branch 3 80/09/05. 3pp
- 8009160595 Notification of 800925 meeting w/util & Sechtel in Phpenix. AZ to conduct sys review meeting re equipment qualification. KERRIGAN, J D Licensing Branch 3, 80/09/12, 3pp
- 8009240422 Forwards Bechtel Power Corp responses to outstanding open items of Class IE dc power sys review Responses are intended to resolve outstanding concerns of BC Power Sys Review Board. Final resolution of open items will be provided.

  VAN DRUNT, E. Arizona Public Service Co 80/09/18 12pp
- C Utility Environmental Report (ER), amends & correspondence
- BOO9090392 Forwards Suppl i to anviron rept for facility.
  VAN BRUNT, E E Arizona Public Service Co 80/09/08 1;
- --8009070378 Suppl 1 to facility environ rept.
  # Arizona Public Service Co. 80/07/30. 53pp
- 8009230701 Forwards proof of svc for Suppl 1 to environ rept.OL stage required by 10CFR2 101 t D Elsenhut 800408 ltr VAN SRUNT, E E Arizona Public Service Co 80/09/15 Spp.
- F Security, medical, emergency & fire protection plans
- 8009030262 Notifies of 800819.22 & 30 regional workshops re development of guidance for acceptable method for coping w/emergencies at facility Requests that representative be sent 8 bbj areas to be discussed include function of facilities & location, ENGELKEN,R H Region 5, San Francisco, Office of the Director, 80708/12 2pp
- 9 Adjudicatory correspondence
- 8009030714 Response in opposition to PL Hourihan, K Dahl & C Shuey 800811 petition to intervene Petitioners failed to establish standing or specify interest Aspects affecting petitioners not identified, W/Gertificate of Svc OEHR, A C. BIBCOFF.C A Artiona Public Service Co GEHR, A.C. Binell & Wilmer 80/08/26 Opp.
- 8007040276 Response in support of P Hourihan 800811 petition to intervene & request for hearing, conditioned on particularization of aspects of concern Supports holding hearings in Phoenix area M/appearance & Centificate of Svc. NCGURREN, H J Hearing Branch 1 80/09/02 11pp

- BOOTOBOSIA Notice of establishment of ASLB to preside in OL applications environ rept & opportunity for hearing proceedings RM Lazo appointed chairmen.RF Cole & B Callahan members
  LAZO,R H Atomic Safety and Licensing Board Panel 80/09/03 2pp

- 8009100457 Ack receipt of 800705 ltr & forwards Friends of the Earth Class 9 petition & Director's decision on petition W/o encl. BCHWENCER, A Licensing Branch 2 80/08/27 2pp
- ---8009100463 Requests Director's decision on Friends of the Earth petition to consider Class 9 accidents in supplemental EIS FRIESMA, H P Northwestern Univ 80/07/05 ip
- 8009050083 Forwards 800725 FR notice re procedural assistance change in adjudicatory licensing proceedings.per 800902 telcon W/a encl W/m encl MCGURREN, H J Hearing Branch 1 80/09/03 1p
- 8009230466 Responds to 800620 ltr re NRC licensing procedures, rules of practice, docksting procedures & milestones for facilities 80HWENGER, A Licensing Branch 3 80/09/12 2pp
- K. Utility Final Safety Analysis Report (FSAR) & amends
- GOOP12050B Forwards updated distribution list for suppl & smend to FSAR & environ rept Supersedes GOO618 list KERRIGAN, J. Licensing Branch 3 GO/OB/25 5pp
- 8009300402 Forwards Amend 2 to FBAR.
  VAN BRUNT, E E Arizona Public Service Co 80/09/29 1p.
- --8009300405 Amend 2 to FBAR, responding to NRC 800618 questions & correcting text App 148 & oversize drawings encl # Arizona Public Service Co 80/09/29 300pp
- G Inspection reports, IE Bulletins & correspondence
- BO09030674 Responds to IE Bulletin 80-08, "Exam of Containment Liner Penetration Helds." Facility design incorporates butt welded sleeve connections for continuity of containment boundary Sixty-three joints have been welded VAN BRUNT, E E Arizona Public Service Co. 80/07/08 2pp
- BOO9120292 Forwards IE Insp Repts 50-528/80-10, 50-529/80-10 & 50-530/80-10 on 800602-27. No noncompliance noted. BPENCER, 9 S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/08/05 2pp.
- --BOOY120296 IE Insp Repts 50-528/80-10.50-529/80-10 & 50-530/80-10 on 800602-27. No noncompliance noted Major areas inspected installation of Unit 1 spray pond piping & Unit 2 dome spray Installation of Color of the Director BO/08/05. App.
- BOOP120234 Responds to IE Bulletin 80-16 No Rosemount Model 1151 & 1152 pressure transmitters are used in any safety-related applications.

  VAN BRUNT: E Arizona Public Service Co 80/08/11 ip.
- 9009120496 Forwards IE Insp Repts 50-528/80-08,50-529/80-08 & 50-530/80-08 on 800320-23 No noncompliance noted SPENCER. 9 B Region 5, Ben Francisco, Reactor Construction & Engineering Support Branch. 80/08/12 2pp
- --8009120500 IE Insp Repts 50-528/80-08,50-529/80-08 & 50-530/80-08 on 800520-23 No noncompliance noted Major areas inspected const activities, preheat & post-wald treatment & containment liner welding
  DODDB.R T. Region 5, Ban Francisco, Reactor Construction &
  Engineering Support Branch. ECKHARDT.J H. NARBUT.P P. Region 5,
  Ban Francisco, Office of the Director 80/08/11. 7pp
- 8009030276 Forwards Revision 1 to IE Builetin 80-19. "Failures of Asrcury-Metted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E." Written response required. ENOELMEN.R. H Region 5. San Francisco, Office of the Director. 80/08/15. 1p.

- 8009290307 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Fump Btuds " No written response required ENGELKEN.R H Region 5. San Francisco, Office of the Director 80/08/18. 4pp
- 8009160178 Forwards IE Circular 80-18. "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sus " No written response Region 5, San Francisco, Office of the Director 80/08/22 1.0
- 8009190159 Forwards IE Insp Repts 50-528/80-11, 50-529/80-11 & 50-520/80-11 on 800610 No noncompliance noted ENGELKEN, R H. Region S. San Francisco. Office of the Director 80/88/22 ip
- --8009190169 IE Insp Repts 50-528/80-11.50-529/80-11 & 50-530/80-11 on 800610 No noncompliance noted Major areas inspected masting to discuss results of Region S Licensee performance evaluation for May 1979 through May 1980 ENGELKENR H , VORDERBRUEGERN Region 5, Ban Francisco, Office of the Director SPERNCERG S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/08/20 4pp
- --8009170178 Discusses semiannual regional evaluation of facilities for NO919017B Discusses semiannual regional evaluation of facilities for May 1979 through May 1980 Licensee effort should be made to satisfactory & strong licensee effort should be made to ensure current & future work is adequately controlled DODDBS.R T Region 5. San Francisco, Reactor Construction & Engineering Support Branch ECKHARDT.J H . VORDERBRUEGGEN Region 5. Ban Francisco, Office of the Director 80/08/20 8pp
- 8009120456 Forwards IE Info Notice 80-31. "Maloperation of Gould-Brown Boveri 480 Voit Type K-6008 & K-DON 6008 Circuit Breakers " No written response required ENGELKEN.R H Region 5, Sen Francisco, Office of the Director 80/08/27 1p
- S. Reportable occurrences, LERs & related correspondence
- 8007020528 Ack receipt of final deficiency rept re Borg-Warner valve stem extension loosening problem
  EMOCLKEN,R H Region 5. San Francisco, Office of the Director
  80/08/15 ip
- --8009020932 Final deficiency rept re Borg-Warner valve stem extension loosening problem Mod to correct deficiency will be completed prior to startup VAN BRUNTLE E Arizona Public Service Co. 80/07/29 3pp
- 8009030556 Final deficiency rept re undersized structural steel fillet welds Welds are sufficient to handle design loading while providing adequate safety margin for crack prevention. Dispositioned as not reportable VAN BRUNT, E.E. Arizona Public Service Co. 80/08/25 6pp
- ---B009030563 "Evaluation of Structural Fillet Weld Samples for Underbeat Cracting " PULLING.C , SCHMIDT, Q R , HACKNEY, B.D Bechtel National, Inc. B0/02/05 30pp
- 8007230653 Final deficiency rept re failure of vertical fire dampers to close Investigation of closure problem determined that design tolerances not maintained between frame & damper slide. Deficient frame & damper blade will be replaced.

  VAN BRUNT.E.E. Arizona Public Service Co. 80/09/15 7pp
- T Hearing transcripts on non-antitrust matters
- 8009160373 Forwards transcript of 800709 review re Class IE ac power sys.Includes discussion of open items re review board & NRC whanswered questions & requests for info.

  VAN BRUNT, E. Arizona Public Bervice Go. 80/09/11 ip.
- --8009160379 Transcript of 800709 review re Class IE ac power sys in Bethesda:MD Pp 1-195.W/supporting documentation \* Arizona Public Service Co. 80/09/11 275pp

#### DOCKET 50-536 GOSGEN

- P. Operating license stage documents & correspondence
- 8009260466 Application by GE to amend license to export U to Buitterland by adding Fabricationi Nucleari as intermediate consignes. . WOLFE.B. General Electric Co. 80/09/16 2pp

#### DOCKET 50-537 CLINCH RIVER BREEDER REACTOR

- A Application/construction stage documents & correspondence
- 8007020014 Forwards "Clinch River Breeder Reactor Plant Fuel Assembly Structural Analysis in Support of Final Design Review." as partial response to Guestion 7 of IP Speis 751006 ltr Add1 rept will be submitted COPELAND,R L Energy, Dept of, Clinch River Breeder Reactor Plant 80/08/22 ip
- ---B009020017 "Clinch River Breeder Reactor Plant Fuel Assembly Structural Analysis in Support of Final Design Revieu " PREVENSLIK.T.V", SANE.A D , BITNER.J L Westinghouse Electric Corp GRBR-ARD-0204 78/01/31 389pp
- B Utility Preliminary Safety Analysis Report, amends
- 8009020002 Amend to application for OL Forwards Amend 56 to PSAR COPELAND.R L Energy.Dept of, Clinch River Breeder Reactor Plant 80/08/29 4pp
- --8009020003 Amend 56 to PSAR

  \* Energy,Dept of, Clinch River Breeder Reactor Plant 80/08/29 125pp.
- 8009090549 Forwards affidavit confirming distribution of Amend 56 to PSAR to designated local public officials & representatives of EPA COPELAND, R L Energy, Dept of 80/09/05 2pp
- BO09090575 Forwards affidavit confirming distribution of Amend 36 to facility PBAR to EPA & local officials Related correspondence COPELAND, R L Energy, Dept of, Clinch River Breeder Reactor Plant BO/09/05 2pp

## DOCKET STN-50-546 MARBLE HILL NUCLEAR STATION, UNIT 1

- A Application/construction stage documents & correspondence
- SOCOCOBOORD Forwards draft NUREC-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREC-0696 encl M/o NUREC EISENHUT, D 0 Division of Licensing 80/08/01 119pp
- 8009180533 Submits add1 characterizations of two categories of surface irregularities identified & mapped in accordance w/const varification program
  SHIELDB.S N Public Service Co of Indiana, Inc 80/08/13 3pp
- 3009180521 Submits clarification & commitments on repairs & evaluations for concrete patches & repair areas identified to date & which may be identified in future SHIELDS,S W Public Service Co of Indiana, Inc. 80/08/25 2pp.
- 3009030500 Requests that NRC forward nomination form to Kemper of NATION REQUESTS that AND TOTAINS DIMENSION FOR TO RESP NATI Register for final determination re eligibility of McM(el) Stone Fort (Site 12 JE 4) located at planned power location along Marble Hill-Columbus transmission line SHIELDS.S W Public Service Co of Indians. Inc 80/08/2: 80/08/27 2pp
- 8009260071 Submits interim actions for plant operation pending final resolution of ATMS Emergency operation procedural review may include NRC site visit prior to issuance of OL TEDESCO.R.L. Assistant Director for Licensing 80/09/12. Spp
- 80092905ii Forwards "Const & Hatl Verification Program," final rept. Presents results & conclusions of GA program per App Item G.1 & 2 & Item D.i & 2 of V Stello 8005i5 graduated recission order SHIELDS:S W Public Service Co of Indiana: Inc 80/09/12 2pp.
- --8009270513 "Const & Matl Verification Program," final rept \* Public Service Co of Indiana, Inc 80/09/30 725pp
- F Security, medical, emergency & fire protection plans
- B009090782 Confirms util interpretation of Evaluation Criteria J 6 of 009090762 Confirms util interpretation or Evaluation Criteria U NUREO-0654/FEMA-REP-1, in response to 800718 request Criteria apply to staff remaining onsite during radiological emergency Language will be clarified GRIMES, B K Emergency Preparedness Program Office 80/08/28

### @ Adjudicatory correspondence

- 8009200094 Responds to NRC 800915 graduated recission of 790815 order & requests partial lifting of order confirming suspension of const Util has completed activities prerequisite for receipt insp SHIELDS, S W Fublic Service Co of Indiana, Inc. 80/08/26
- 8009180226 Forwards Director's decision under 100FR2 206 denying Save the Valley request for action re resumption of work at Save the value of Fractisty
  DENTON-H R Office of Nuclear Reactor Regulation. Director 80/09/02 4pp
- --8009180232 Director's decision under 10CFR2 206 denying Save the Vallag request for action re resumption of work at facility Evidence of extension of fault zone towards plant site is DENTON, H R Office of Nuclear Reactor Regulation, Director. DENTON, H R 0: 80/09/02 App.
- --8009180237 Notifies of 771129 site visit to examine foundation maxle in response to NRC request Memorandum rept on vigit and BROWN,F R. Army, Dept of, Corps of Engineers. 77/12/12 3pp
- --8009180242 Notice of issuance of Director's decision under 10CFR2 204 DENTGN.H R Office of Nuclear Reactor Regulation, Director 80/09/02 2pp
- 8009260467 Order granting extension until 801006 for Commission to elect whether to review Director's decision under 10FR2 206 CHILK, S.J. Office of the Secretary of the Commission 60/09/23

#### H Ogneral correspondence

- 8009090874 Forwards organizational changes revising organizations description in GA program SHIELDS, S W Public Service Co of Indiana, Inc. 80/09/02
- --8009090580 Organizational changes revising QA program. New organization charts re project, project engineering, project const.project control.project administration, QA & project testing enci.

  \* Public Service Co. of Indiana, Inc. 80/09/02 9pp
- 8009300452 Advises that HM Petro assumed full responsibilities as project director effective 800919 SHIELDS, S H Public Service Co of Indiana, Inc. 80/09/23, 1p
- G Inspection reports: IE Bullevine & correspondence
- 8009150172 Forwards IE Insp Repts 50-546/80-25 & 50-547/80-25 on 800&01-30 No noncompliance noted FIGRELI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/28 2pp.
- --8009150177 IE Insp Repts 50-546/80-25 & 50-547/80-25 on 800601-30. No noncompliance noted Major areas inspected auxiliary bldg, fuel handling bldg.Units 1 & 2 containments & storage & maint facilities for safety-related items WILLIAMS, C C , HARRISON, J J Region 3, Chicago, Office of the Director 80/07/25 4pp
- 8009110764 Forwards IE Insp Repts 50-544/80-21 & 50-547/80-21 on 800403-06 & 0707-11 No noncompliance noted FIDRELLI.0 Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/07/31. 2pp
- --8009110769 IE Insp Repts 50-546/80-21 & 50-547/80-21 on 800603-06 & 0707-11 No noncompliance noted Major areas inspected blasting work.completed ESP line backfill work & const verification procedures HAYES,D W Region 3, Chicago, Reactor Construction & Engineering Support Branch HAWKINS,F C., HARRIS,J R. Region 3, Chicago, Office of the Director 80/07/29, Opp
- 8009180211 Forwards IE Insp Repts \$0-546/80-24 & 50-547/80-24 un 800524-27 No noncompliance noted, KEPPLER, J 9 Region 3, Chicago, Office of the Director 80/08/05
- --800918022: IE Insp Repts 50-546/80-24 & 50-547/80-24 on 800624-27. No noncompliance noted Major areas inspected GA/GC insp personnel qualifications > relationship between project GA manual & ASME GA manual manual & ASME GA manual FIDRELLIA © Region G. Chicago, Reactor Construction & Engineering Support Branch SCHWEIBINZ,E.R.; HARRIBON,J,J. Region G. Chicago, Office of the Director 80/08/04 11pp.

,

- 8009150894 Forwards IE Insp Repts 50-546/80-23 & 50-547/80-23 on 800610-12, 16-20 & 26-27 & notice of violation FIDRELLI. © Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/08/07 2pp
- --8009180600 Notice of violation from insp on 800610-12.16-20 & 26-27 \* Region 3. Chicago, Office of the Director 80/08/05 ip
- --8009150602 IE Insp Repts 50-546/80-23 & 50-547/80-23 on 800610-12.
  16-20 & 26-27 Noncompliance noted failure to follow procedures in implementation of Special Process Procedure 7 SCHMEIBIRZ.E. ERB.C M. CORDERO, Z C Region 3. Chicago, Office of the Director 80/08/05 lipp
- 8009030213 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Bys of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/08/15
- 8007270104 Forwards IE Insp Repts 50-546/80-27 & 50-547/80-27 on 800717-18 No noncompliance noted FIORELLI.G. Region S. Chicago, Reactor Construction & Engineering Support Branch 80/08/19 2pp
- --8009290107 IE Insp Repts 50-546/80-27 & 50-547/80-27 on 800717-18 No noncompliance noted Major areas inspected technical adequacy of util action re Marbie Hill concrete issue HAMMINS.F.C., HAYES.D W Region 3, Chicago, Office of the Director 80/08/18 3pp
- 8007270110 Forwards IE Insp Repts 50-546/80-27 & 50-547/80-27 on 800727-0801 No noncompliance noted FIORELLI.0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/08/17 2pp
- ---B009290114 IE Insp Repts 50-546/80-29 & 50-547/80-29 on 800729-0801.No noncompliance noted Major areas inspected nondestructive examination. Lab equipment & procedures; personnel certifications & radiographs of field welds SCHAPKER.J F Region 3. Chicago Office of the Director DANIELBON, D. H Region 3. Chicago Resctor Construction & Engineering Support Branch 80/08/18 Opp.
- 8009170436 Forwards IE Circular 80-18, "100FR90 59 Bafety Evaluations for Changes to Radwaste Treatment Sys " No written response required.

  KEPPLER, J. & Region 3, Chicago, Office of the Director 80/08/22
- BO09230079 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover: 480 Volt Type K-5008 & K-DON 5008 Circuic Breakers" No written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/08/28
- 9009250447 Responds to IE Bullstin 80-19, "Failures of Hercury-Watted Matrix Relays in Reactor Protectiva Sys of Operating Nuclear Power Plants Designed by C-E " No mercury-wetted relays are being used in reactor protection sys BHIELDB,8 W Public Service Co of Indiana, Inc 80/08/28 ip
- 9007180346 Responds to IE Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters Identified transmitters will be installed but will not be subj to input pressures Signal of differential pressure to be provided across tube SHIELDS, B. W. Public Service Co of Indiana, Inc. 80/08/27 1p.
- BO09240116 Forwards IE Circular 80~21, "Regulation of Refueling Crews." No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/09/10
- 8009270202 Ack receipt of 800820 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/80-23 & 50-547/80-23. FIDRELLI, Q Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/15 ip
- --B009290208 Responds to NRC 800807 ltr re violations noted in IE Insp Repts 50-546/80-23 & 50-547/80-23. Corrective actions.util util perform audits of special process procedure program to ensure that required data are included in checklists. BHIELDS.S W. Public Service Co of Indiana. Inc 80/08/20 3pp

- S Reportable occurrences. LERs & related correspondence
- 8009020249 Ack receipt of 800728 final rept re repair welds which were not reradiographed after repair welding was completed FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/07 ip
- --8009020253 Final deficiency rept re regair sleeve welds not reradiographed after repair welding was completed Ultrasonic testing of sleeve welds performed indicating that welds were not defective but acceptable as is SHIELDS, BW Public Service Co of Indiana, Inc B0/07/28 ip Available at NRC nrc
- 8009150491 Ack receipt of 800730 interim deficiency rept re 46 of 49 documentation packages for Mestinghouse supplied mattermissing quality records Final rept will be reviewed upon receipt FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/18 1p
- 8009030480 Interim deficiency rept re operation of centrifugal charging gumps during high energy line rupture Alternative mods being evaluated by Westinghouse Final rept will be submitted 80114
  SHIELDS, 8 W Public Service Co of Indiana, Inc. 80/08/20 ip
- 8009040427 Interim deficiency rept re inadequate documentation of cadweld splice sampling & testing Reinsp & evaluation of cadweld splices is being performed as part of const verification program Final rept will be submitted by 801001 SHIELDS,8 W Public Service Co of Indiana, Inc 80/08/28 2p
- 8007100469 Interim deficiency rept re inability of contractor GA program to assure that AE design changes were incorporated into plant const activities Visual insp delayed Final rept will be submitted by 801601
  SHIELDS,8 W. Public Service Co of Indiana, Inc. 80/09/02 1p
- 8009250483 Ack receipt of 800813 interim deficiency rept re certain radiographs of steam generator upper lateral support embedments not meeting density requirements of Bection V of ABME BP&V code FIORELLI.9 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/09/03 ip
- 8009250479 Ack receipt of 800820 interim rept re operation of centrifugal charging pumps during high energy line rupture FIORELLI, & Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/08 ip
- --8009250482 Interim deficiency rept re centrifugal charging pumps during high energy line rupsure Mestinghouse enalyses problem & recommended plant mods Final rept will be sent by 801114 SHIELDS.8 W Public Service Co of Indiana, Inc. 80/09/20. 1p
- 8009160400 Final deficiency rept re possible nonconformances in reinforcing steel in areas of clear cover.member thickness & size of reinforcing bar Corrective actions described in Section 2 of "Const Verification Program"

  8HIELDS.8 W Public Service Co of Indiana. Inc 80/09/11 Rep.
- 8009160419 Interim deficiency rept re undercut welds, undersize fillet welds & incorrect weld contour on steel used to support pipe hangers Deficiencies being investigated Final rept will be submitted by 801215
  SHIELDS, B W Public Service Co of Indiana, Inc 80/09/11 ip
- 8009290197 Ack receipt of 800828 deficiency rept re Cadweld splice sampling & testing FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/15, ip
- 8007240561 Potentially reportable deficiency meptime failure of previously inspected cadwelds to meet visual inspiciteria, Noncomformance thoroughly evaluated including radiography Machanical splices will meet design strength requirements SHIELDS,8 W Public Service Co. of Indiana, Inc. 80/09/18 ip
- DOCKET STN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2

  A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREG-0496, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0494 encl W/o NUREG EISENHUT, D O Division of Licensing 80/08/01 119pp

- 8009180533 Submits add1 characterizations of two categories of surface (regularities identified & mapped in accordance w/const verification program SHIELDS,S W Public Bervice Co of Indiana. Inc 80/08/13 3pp
- 8007180521 Submits clarification & commitments on repairs & evaluations for concrete patches & repair areas identified to date & which may be identified in future
  SHIELDS S W Public Service Co of Indiana, Inc. 80/08/25 2pp
- 8009030500 Requests that NRC forward nomination form to Keeper of Natl Register for final determination re eligibility of McNiell Stone Fort (Site 12 JE 4) located at planned power location along Marble Hill-Columbus transmission line SHIELDS.S W Public Service Co of Indiana. Inc 80/08/27 2pp
- 8007240071 Bubmits interim actions for plant operation, pending final resolution of ATMS Emergency operation procedural review may include NRC site visit prior to issuance of DL TEDESCO.R L Assistant Director for Licensing 80/09/12 5pp
- 80092905(1 Forwards "Const & Matl Verification Program," final rept Presents results & conclusions of GA program per Ap C.1 & 2 & Item D.1 & 2 of V Stello 800515 graduated recission order SHIELDS-8 H Public Service Co of Indiana, Inc. 80/09/12 Rpp.
  - 8009270513 "Const & Matl Verification Program," final rept # Public Service Co. of Indiana, Inc. 80/09/30 725pp

## Adjudicatory correspondence

- 09300094 Responds to NRC 600515 graduated recission of 790815 order & requests partial lifting of order confirming suspension of const Util has completed activities prerequisite for receipt SHIELDS, S H. Public Service Co of Indiana, Inc. 80/08/24 2pp.
- 8009180226 Forwards Director's decision under 10CFR2 206 denying Save the Vallay request for action re resumption of work at facility DENION.H R Office of Nuclear Reactor Regulation, Director, 80/09/02 App
  - 9009180232 Director's decision under 100FR2 206 denying Bave the Valley request for action re resumption of work at facility Evidence of extension of fault zone towards plant site is
  - )9180237 Notifies of 771129 sits visit to examine foundation matls in response to NRC request Memorandum rept on visit encl BRDWN.F R Army,Dept of, Corps of Engineers 77/12/12 3pp
  - O9180242 Natice of issuance of Director's decision under 100FR2.206. DENTUN-H R. Office of Nuclear Reactor Regulation. Director 80/09/02. 2pg
  - 260467 Order granting extension until 801006 for Commission to ect whether to review Director's decision under 3FR2 206 ILK.S J Office of the Secretary of the Commission 80/09/23

#### uneral correspondence

- 090574 Forwards organizational changes revising organization scription in GA program lELDS, S W Public Service Co. of Indiana, Inc. 80/09/02 ip
- .09090580 Organizational changes revising GA program, New organization Charts re project, project engineering, project const, project control, project administration, GA & project testing encl \* Public Service Co of Indiana. Inc 80/09/02 9pp
- 9300452 Advises that WM Petro assumed full responsibilities as roject director effective 800919
  HIELDS.6 W Public Service Co. of Indiana, Inc. 80/09/23 ip
- Inspection reports: IE Bulletins & correspondence
- 09150172 Forwards IE Insp Repts 50-546/80-25 & 50-547/80-25 on 800601-30 No noncompliance noted. FIORELLI, 0. Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/07/20 2pp

- --8009180177 IE Insp Repts 30-546/80-25 & 50-547/80-25 on 800601-30 No noncompliance noted Major areas inspected auxiliary bldg, fuel handling bldg. Units 1 & 2 containments & storage & maint facilities for safety-related items WILLIAMB.C C, HARRISON.J J Region 3, Chicago, Office of the Director 80/07/25 App
- 8009110764 Forwards IE Insp Repts 50-546/80-21 & 50-547/80-21 on BOG603-06 & 0707-11 No noncompliance noted FIDRELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/31 2pp
- --9009110769 IE Insp Repts 80-946/80-21 & 50-547/80-21 on 800603-06 & 0707-11 No noncompliance noted Major areas inspected. blasting work.completed ESP line backfill work & const verification procedures
  HAYES.D W Region 3. Chicago, Reactor Construction & Engineering Support Branch HAHKINS.F C . HARRIES.J R Region 3. Chicago, Office of the Director 80/07/29. App
- 8009180211 Forwards IE Insp Repts 30-546/80-24 & 50-547/80-24 on 800624-27 No noncompliance noted KEPPLER.J C. Region 3. Chicago. Office of the Director 80/08/05
- --8009180221 IE Insp Repts 50-546/80-24 & 50-547/80-24 on 800624-27 No NOVIBORAL IE INSPIRED S SU-UNIO ROME A SUU-UNIONE UNION TO MODELLE IN MODELLE
- 8009190594 Forwards 1E Insp Repts 50-546/80-23 & 50-547/80-23 on 800610-12,16-20 & 26-27 & notice of violation FIORELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/08/07 2pp
- --8009150500 Notice of violation from insp on 800510-12,16-20 & 25-27. \* Region 3. Chicago, Office of the Director, 80/08/05 1p
- -8009150602 IE Insp Repts 50-546/80-23 & 50-547/80-23 on 800610-12.
  16-20 & 26-27 Noncompliance noted failure to follow procedures in implementation of Special Process Procedure 7 SCHMEISIMI,E , ERB.C M., CORDERO, Z C, Region 3, Chicago. Office of the Director 80/08/05 lipp
- 8009030213 Forwards Revision I to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective 8gs of Operating Nuclear Power Plants Designed by C-E " Written response required KEPPLER, J. O Region 3, Chicago, Office of the Director 80/08, Region 3, Chicago: Office of the Director 80/08/15
- 8009290104 Forwards IE Insp Repts 50-546/80-27 & 50-547/80-27 on 800717-18. No noncompliance noted FIGRELL, 9 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/08/19 2ps.
- --8009290107 IE Insp Repts 50-544/80-27 & 50-547/80-27 on 800717-18.Wa noncompliance noted Major areas inspected technical adequacy of util action re Harble Will concrete issue, HAKKIRS.F. C. HAYES.D W Region 3, Chicago, Office of the Director, 80/08/18 3pp
- 8007270110 Forwards IE Insp Repts 50-546/80-27 & 50-547/80-29 on B00727-0801 No noncompliance noted FIDRELLI, C Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/08/17 2pp
- --8009290114 IE Insp Repts 50-546/80-29 & 50-547/80-29 on 800729-0801.No noncompliance noted. Major areas inspected nondestructive examination lab equipment & procedures personnel certifications & rediographs of field welds SCHAPKER.J F. Region 3. Chicago. Office of the Director. DANELSON, D.H. Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/08/18 App
- 8009170436 Forwards IE Circular 80~18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response KEPPLER, J. Q. Region 3, Chicago, Office of the Director 80/08/22
- 8007230079 Forwards IE Info Notice 80-31, "Maloperation of Qould-Brown Bover: 480 Volt Type K-6008 & X-DON 6008 Circuit Breakers." No written response required. KEPPLER.J O Region 3, Chicago, Office of the Director. 80/08/28

**DOCKETED ITEMS** 

- 8009250447 Responds to IE Bulletin 80-19. "Failures of Mercury-Wetted Histrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " No mercury-wetted relays are being used in reactor protection sys SHIELDS.8 W Public Service Co of Indiana, Inc. 80/08/28 ip
- 8009180346 Responds to IE Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters Identified transmitters will be installed but will not be sub; to input pressures Bignal of differential pressures to be provided across tube SNIELDS.8 W Public Service Co of Indiana. Inc 80/08/29 ip
- B009240116 Forwards IE Circular 80-21, "Regulation of Refusiing Crews" No written response required KEPPLER, J O Region 3, Chicago, Office of the Director B0/09/10
- 8009290202 Ack receipt of 800820 ltr informing NRC of steps taken to correct violations noted in IE Inso Repts 50-546/80-23 & 50-546/80-23 & 50-546/80-23 FIORELLI.O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/09/15 ip
- --8009290208 Responds to NRC 800807 ltr re violations noted in IE Insp Repts 50-546/80-23 & 50-547/80-23 Corrective actions util will perform audits of special process procedure program to ensure that required data are included in checklists SHIELDS.8 W Public Service Co of Indiana. Inc 80/08/20 3pp
- B. Reportable occurrences, LERs & related correspondence
- BOO9020249 Ack receipt of 800728 final rept re repair welds which were not reradiographed after repair welding was completed FIDRELLI,O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/08/07. ip.
- --8009020253 Final deficiency rept re repair sleeve welds not rerediographed after repair welding was completed Ultrasonic testing of sleeve welds performed indicating that welds were not defective but acceptable as is SHIELDS,8 W Public Service Co of Indiana, Inc 80/07/28. 1p. Available at NRC nrc
- 8009130491 Ack receipt of 800730 interim deficiency rept re 45 of 49 documentation packages for Westinghouse supplied matls missing quality records Final rept will be reviewed upon receipt.
  FIORELLI, U megion 3, Chicago, Reactor Construction & Engineering Support Branch. 30/08/15 ip
- 8009030480 Interim deficiency rept re operation of centrifugal charging pumps during high energy line rupture Alternative mode being evaluated by Wessinghouse Final rept will be submitted 801114.
- BHIELDS, B. W. Public Service Co. of Indiana, Inc. BO/08/20 ip
- BO09040427 Interim deficiency rept re inadequate documentation of cadweld splice sampling & testing Reinsp & evaluation of cadweld splices is being performed as pert of const varification program final rept will be submitted by 801001 SHIELDS. B.W. Public Service Co. of Indiana. Inc. 80/08/28 2pp
- BOOGIOUADY Interim deficiency rept re inability of contractor QA program to assure that AE design changes were incorporated into plant const activities. Visual insp delayed Final rept will be submitted by 80:101
  SHIELDS, S. W. Public Service Co. of Indiana, Inc. 80/09/02, 1p
- BO07250483 Ack receipt of BO0863 interim deficiency rept re certain radiographs of steam generator upper lateral support embedments not meeting density requirements of Bection V of ABME BPAV ode FIORELLI,O. Region 3, Chicago, Reactor Construction & Engineering Bupport Tranch 80/07/03 ip
- 8009250479 Ack receipt of 800820 interim rept re operation of centrifugal charging pumps during high energy line rupture. FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/08 ip
- --8009230482 Interim deficiency rept re centrifugal charging pumps during high energy line rupture Westinghouse analyzed problem & recommended plant mods Final rept will be sent by 801114. SHIELDS:8 M. Public Service Co of Indiana. Inc 80/08/20 ip
- BOO9150400 Final deficiency rept re possible nonconformances in reinforcing steel in areas of clear cover, member thickness & size of reinforcing bar Corrective actions described in Bection 2 of "Const Verification Program."

  BHIELDS, B, W. Public Service Co of Indiana, Inc. 80/09/11. 2pp.

- B009160419 Interim deficiency rept re undercut welds undersize fillet welds & incorrect weld contour on steel used to support pipe hangers Deficiencies being investigated Final rept will be submitted by 801219
  SHIELDS, B W Public Bervice Co of Indiana. Inc B0/09/11 1p
- 8009290197 Ack receipt of 800828 deficiency rept re Cadweld splite sampling & testing FIGRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/19 ip
- B009240561 Potentially reportable deficiency rept re failure of previously inspected cadwelds to meet visual inspectivate Noncomformance thoroughly evaluated including radiography Mechanical splices will meet design strength requirements SHIELDS, B.W. Public Service Co. of Indiana, Inc. 80/09/18 1p.
- DOCKET STN-50-559 PRIPPS BEND NUCLEAR PLANT, UNIT :

  A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation achedule for meeting criteria of NUREG-0696 entl N/A NUREG EISENHUT, D 0 Division of Licensing 80/08/01 119pp
- 0009040404 Forwards description of fault zone in rock foundation for Unit 1 control & diesel generator bldgs Drawing encl
  MILLS.L M Tennessee Valley Authority 80/08/22 4pp
- ---8009040487 "Plan View Geologic Map.Unit I "
  \* Tennessee Valley Authority 80/07/21 ip
- 8009100472 Forwards info re add1 faults discovered at facility in area of essential svc water spray pond Photographs & drawings available in Central Files
  MILLS L M Tennesses Valley Authority 80/08/22 3pp
- I Financial information
- 8007070543 Forwards Annual Financial Rept 1979 CROSS-J L Tennessee Valley Authority 80/09/04 1p
- --BD09090563 Annual Financial Rept 1979 \* Tennessee Valley Authority B0/09/04 44pp
- G Inspection reports, IE Bulletins & correspondence
- 8009090075 Forwards IE Bulletin 80-07.Suppl 1, "BWR Jet Pump Assembly Failure" No response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/13 ip
- 8009070233 Forwards IE Insp Repts 50-553/80-10 & 50-554/80-09 on 800623-27 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/07/21 2pp
- --B009090289 IE Insp Repts 50-553/80-10 & 50-554/80-09 on 800623-27 No noncompliance noted Major areas inspected licensee action on previous insp findings.VSL heavy lifting & transporting activities.const & IE bulletin status CANTRELL.F & Region 2. Atlanta. Reactor Construction & Engineering Support Branch WRIGHT.R W Region 2. Atlanta. Office of the Director 80/07/21 10pp
- 8009020184 Submits response to IE Bulletin 79-03A No BA-312 or A-312, Type 300 series fusion welded pipe is in use or planned for use in safety-related sys MILLS, L. M Tennessee Valley Authority B0/08/04 ip
- 8007020303 Forwards IE Insp Repts 50-327/80-24,50-329/80-15, 50-390/80-20,50-391/80-14,50-438/80-13,50-439/80-13, 50-518/80-11,50-519/80-11,50-521/80-11,50-521/80-11, 50-553/80-11,50-554/80-10,50-566/80-10 t 50-567/80-10 0 (REILLY, J P Region 2, Atlanta, Office of the Director 80/08/06.
- --8009020312 Notice of violation from insp on 800707-11 \* Region 2, Atlanta, Office of the Director. 80/08/06 4pp

- --8009020337 IE Insp Repts 50-327/80-24,50-328/80-15,50-390/80-20, 50-391/80-14,50-438/80-13,50-439/80-13,50-518/80-11, 50-519/80-11,50-520/80-11,50-521/80-11,50-553/80-11,50-554/80-10,50-366/60-10 & 50-567/80-10 on 800707-11, 8ROUNLEE,V L. Ragion 2, Atlanta, Office of the Director 80/08/06 24pp
- 8009030146 Forwards Revision 1 to IE Builetin 80-19. "Failures of Mercury-Watted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Mritten response required O'REILLY.J P. Region 2. Atlanta. Office of the Director 80/08/15
- B009160045 Forwards IE Info Notice B0-30, "Potential for Unacceptable Interaction Setween Control Rod Drive Scram Function & Nonessontial Control Air at Certain OE BHR Facilities "No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/19 to
- 8007120066 Forwards Suppl 3 to 16 Bulletin 80-17, "Failure of Control Rads to Insert During Scram at BMR" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22
- 8009160153 Forwards IE Circular 80-18, "10CFRSO 59 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/08/22 io.
- BO09120340 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers "
  No written response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/08/27 fp.
- 3009180068 Forwards response to IE Bulletin 80-16 Rosemount Models 1151 & 1152 pressure transmitters were planned for installation. 0E will analyze applications of transmitters to determine out-of-range conditions. MILLS,L M Tannessee Valley Authority 80/08/29 2pp
- 100918006# Submits response to IE Bulletin 80-19 No marcupy-wetted matrix relays are in use in reactor protection sys fillS.L.M. Tannessee Valley Authority 80/08/29 ip.
- )9240427 Forwards response to IE Bulletin 80-15 re patential disapplication of Rosemount pressure transmitters List of dentified transmitters used in safety-related areas being compiled Rept will be filed after resolution of deficiency MILLS, L. M. Tennessee Valley Authority, 80/08/29 2pp
- 09260375 Forwards IE Circular 80-21, "Regulation of Refueling Craws." No written response required O'REILLY, J.P. Region 2, Atlanta, Defice of the Director 80/09/10, Spp
- Reportable occurrences. LERs & related correspondence
- )09160643 Part 21 rept re design deficiencies in nuclear sys protection sys power distribution panels Panels returned to QE for redesign & rework to corrected design MILLS.L M Tennessee Valley Authority 80/09/03 3pp
- 109240392 Second interim deficiency rept re Rosemount Model 1152 pressure transmitter defects Util is preparing lists of Rosemount 1151 & 1152 transmitters for GE to analyze & replace of necessary Final rept will be provided by BIO403 MILLS, L. M Tennessee Valley Authority 80/09/17. 3pp
- 009290355 Interim deficiency rept re deficient welds on weir well liner plates All welds made w/incorrect electrodes will be removed & replaced by welds w/proper steinless steel electrode Addl corrective action may be warranted MILLB.L M Tennessee Vallay Authority. 80/09/19 2pp
- NOOPZ70375 Becond interim deficiency rept re steam tunnel embedment stiffner plate weld Cause not stated, Util continuing to monitor Atlas OA program to help correct deficiencies HILLB.L M. Tennessee Valley Authority 80/09/19 1g

- DOCKET STN-50-554 PHIPPS BEND NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREG-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREG-0696 encl. W/o NUREO EIBENHUT.D O Division of Licensing 80/08/01 '119pp
- 8009100472 Forwards info re add1 faults discovered at facility in area of essential svc water\_spray pond Photographs & drawings available in Central Files
  MILLS L M Tennessee Valley Authority 80/08/22 3pp
- I Financial information
- 8009090543 Forwards Annual Financial Rept 1979 CROSS.J L Tennessee Valley Authority 80/09/04 ip
- ---B009090563 Annual Financial Rept 1979 \* Tennessee Valley Authority 80/09/04 44pp.
- Q Inspection reports. IE Bulletins & correspondence
- 8009090075 Forwards IE Bullatin 80-07, Suppl 1, "BWR Jet Pump Assembly Failure " No response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/05/13
- 8007070233 Forwards IE Insp Repts 50-553/80-10 & 50-554/80-07 on 800623-27 No noncompliance noted MURPHY.C.E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/21 2pp
- --9009090259 IE Insp Repts 50-553/80-10 & 50-554/80-09 on BO0623-27.Ne noncompliance noted Major areas inspected licensee action on previous insp findings.vBL heavy lifting & transporting activities.const & IE builetin status CANTRELL.F.S Region 2. Atlanta. Reactor Construction & Engineering Support Branch MRIGHT.R.W Region 2. Atlanta Office of the Director GO/07/21 10pp
- 8007020184 Bubmits response to IE Bulletin 79-03A No 8A-312 or A-312 or Type 300 series fusion welded pipe is in use or planned for use in safety-related sys MILLS, L H Tennessee Valley Authority 80/08/06 ip
- 8009020303 Forwards IE Insp Repts 50-327/80-24,50-328/80-15, 50-390/80-20,50-391/80-14,50-438/80-13,50-439/80-13 50-518/80-11,50-519/80-11,50-520/80-11,50-521/80-11, 50-553/80-11,80-554/80-10,50-566/80-10 t 50-567/80-10 0'REILLY,J P. Region 2, Atlanta, Office of the Director 60/08/06.
- --8009020312 Notice of violation from insp on 800707-11.
  \* Region 2. Atlanta, Office of the Director 80/08/06 4pp
- --8007020337 IE Insp Repts 50-327/80-24,50-328/80-15,50-390/80-20,50-391/80-14,50-438/80-13,50-439/80-13,50-519/80-11,50-519/80-11,50-520/80-11,50-521/80-11,50-53/80-11,50-54/80-10,50-566/80-10 & 50-567/80-10 on 800707-11 BROWNLEE,V L Region 2, Atlanta, Office of the Director. 80/08/06 24pp
- 8007030144 Forwards Revision 1 to IE Builetin 80-19, "Failures of Marcury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by G-E " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director, 80/08/15.
- 8009160045 Forwards IE Info Notice 80-30. "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Certain GE BMR Facilities." No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/08/19
- 8009120066 Forwards Suppl 3 to IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BWR " No written response required G'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/08/22 to

- 8009140133 Forwards IE Circular 80-10, "10CFR50 59 Safety Evaluations for Changes to Radwasta Treatment 8ys " No written response required nyserilly, J.P. Region 2, Atlanta, Office of the Director BO/OB/22
- 9009120340 Forwards IE Info Notice 80-31. "Haloperation of Gould-Brown Boyeri 480 Volt Type K-6005 & K-DON 6008 Circuit Breakers " No written response required O'REILLVJ P Region 2, Atlanta, Office of the Director 80/08/27
- 8009180068 Forwards response to IE Bulletin 80-16 Rosemount Models 1151 ### 1152 pressure transmitters were planned for installation OE will analyze applications of transmitters to determine out-of-range conditions
  MILLS.L M Tennessee Valley Authority 80/08/27 2pp
- BOO918006B Submits response to IE Bulletin 80-19 No marcury-wetted matrix relays are in use in reactor protection sys MILLS. L.M. Tennessee Valley Authority BO/08/29 1p.
- 8009240427 Forwards response to IE Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters List of identified transmitters used in safety-related areas being compiled Rept will be filed after resolution of deficiency HILLS, L. H. Tennessee Valley Authority 80/08/29 2pp.
- 8009240375 Forwards IE Circular 80-21, "Regulation of Refueling Crews " No written response required G'REILLY, J P Region 2, Atlanta, Office of the Director 80/09/10.
- 8 Reportable occurrences, LERs & related correspondence
- 8009240392 Becond interim deficiency mept me Rossmount Hodel 1152 pressure transmitter defects Util is preparing lists of Rossmount 1151 & 1152 transmitters for GE to analyze & replace if necessary Final mept will be provided by 810403 MILLS.L.M Tennassee Valley Authority 80/09/17. Spp.
- 8009290355 Interim deficiency rept re deficient welds on weir wall liner plates. All welds made w/incorrect electrodes will be removed & replaced by welds w/proper stainless steel electrode Addl corrective action may be warranted.

  MILLS, L. H Tennessee Valley Authority 80/09/19 2pp
- 8009290375 Becond interim deficiency rept re steam tunnel embedment stiffner plate weld. Cause not stated Util continuing to monitor Atlas GA program to help correct deficiencies WILLS.L.M Tennessee Valley Authority 80709719. Ip
- DOCKET STN-50-556 BLACK FOX STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8009080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities " Comments requested within 90 days. Proposed implementation schedule for meeting criteria of NUREO-0696 encl. W/o NUREO EISENHUT, D. O Division of Licensing. 80/08/01 119pp
- F Becurity, medical, emergency & fire protection plans
- 8009020137 Invites participation in 800822 workshop in Atlanta, CA to solicit comment re proposed functional criteria for emergency response facilities in NUREO-0696 Discussion to include location, size & staffing of emergency thes.

  BEYFRIY, K. V. Region 4, Dallas, Office of the Director 80/08/12
- O Adjudicatory correspondence
- BCC9230010 Memorendum & order re ALAB-573 certified question. Holds that environ health effects associated w/App I design objectives for effluent releases may be litigated in licensing proceedings JF Ahearns dissenting opinion encl CMILK. & J Office of the Secretary of the Commission 80/09/22.
- 8009260639 Mod of Commission 800922 memorandum & order to ALAB-573 cartified question Corrected version of JF Ahearne dissenting views encl
  CHILK, S J Office of the Secretary of the Commission 80/09/23.

- 8007260639 Mod of Commission 800722 memorandum & order re ALAB-573 cartified question Corrected version of JF Ahearne dissenting views encl CHILK-8 J Office of the Secretary of the Commission 80/09/23
- DOCKET STN-50-557 BLACK FOX STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 800908Q080 Forwards draft NUREQ-0496, "Functional Criteria for ERENPIERCY Response Facilities "Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO 0496 encl W/o NUREO EISENHUT. D 0 Division of Licensing 80/08/01. 119pp
- F Security, medical, emergency & fire protection plans
- 8009020137 Invites participation in 800822 workshop in Atlanta, 6A to solicit comment re proposed functional criteria for emergency response facilities in NURGO-0696 Discussion to include location, size & staffing of emergency ctre SEYFRIT.K V Region 4. Dallas, Office of the Director 80/08/12
- Q Adjudicatory correspondence
- 8009250010 Memorandum & order re ALAB-573 certified question Holds that environ health effects associated w/App I design objectives for effluent releases may be litigated in licensing proceedings UF Ahearne dissenting opinion encl CHILK.8 J Office of the Secretary of the Commission 80/09/22.
- 8009260639 Mod of Commission 800922 memorandum & order re ALAB-573 cartified question corrected version of JF Ahearne dissenting views encol CHILK-8 J Office of the Secretary of the Commission 80/09/23. Goo
- DOCKET 50-559 MAANBHAN NUCLEAR STATION, UNIT 2
- O Adjudicatory correspondence
- 8007070233 Response in opposition to Citizens Against Nuclear Power, J J Runyon & E Osgol petition for review of ABLAB 800727 order affirming ASLB 800530 dismissal of contentions Const will not be allowed prior to environ review W/Certificate of Bvc MILLER, H J Commonwealth Edison Co. BIELAHGKI, A P Isham, Lincold & Beale 80/08/27 12pp
- DOCKET 50-584 NUCLEAR FUELS RECOVERY & RECYCLE CENTER
- O Adjudicatory correspondence
- 8009170366 Comments on rulemaking 50-5 re mixed oxide fuel QESMO & other recycle-related licensing proceedings should continue Positive affirmative action to approve licenses recommended KIRK, W F William F Kirk 80/08/28
- 8009160224 Requests CESMO re fueld be completed Info is needed for future decisions re reprocessing of spent nuclear fuel VILLEMY, Q R Affiliation Unknown 80/09/08 1p
- B007i60420 Comments on rulemaking 50-5 OEBMO proceedings should be reopened to provide sarly procedural framework for subsequent licensing.
  RICHARDS,R B General Electric Co B0/09/08. 2pp
- 8009300514 Expresses concern re reopening of GESMD & other related licensing proceedings for reprocessing sites FEIQ, D Affiliation Unknown 80/09/13 ip
- 8009240641 Urges resumption of GESMD hearings BOLDN, A. E. Affiliation Unknown, 80/09/16
- --8009260646 Opposes reopening of QESMO hearings BURRELL.A Affiliation Unknown B0/09/13 ip
- --8009260652 Urges reopening GESMO & recycle-related proceedings & consideration of expanding scope to include recycle of LWR fuel in breeder reactors MCCORNACK, M House of Rep. 80/09/22 2pp

## DOCKETED ITEMS

BOO9300525 Forwards comments in response to Commission 800807 order reterminated GESMO proceedings Reopening would be intmiced to natis security & defense & at odds u/nonproliferation objectives

BIALIK, E. I. New York, State of 80/09/23 7pp

BOO9300540 Comments on reopening of GESMO proceedings Addl use of nuclear generated electricity should be paced to preserve significant quantities of hydrocarbon reserves for use as rew matis in future chemical mfg

BURRIS, L. American Institute of Chemical Engineers 80/09/23 2pp

8009300561 Supports reopening of GESMO & other recycling license proceedings
PRICE, J E Affiliation Unknown 80/07/23 ip

#### H General correspondence

BOO9100490 Comments on RM 50-5 public should be advited of advantages & disadvantages of implementing Pu recycle NRC should not have transinated efforts on CESMO fuels
DECHER.U Affiliation Unknown 80/09/03 ip

DOCKET STN-50-566 YELLOW CREEK NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8007080080 Forwards draft NUREO-0696. "Functional Criteria for Emergency Response Facilities " Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 enci H/O NUREO EIGENHUT.D 0 Division of Licensing 80/08/01 119pp

#### I Financial information

8009090543 Forwards Annual Financial Rept 1979 CR099,J L Tennessee Valley Authority 80/09/04 ip

## Q Inspection reports: IE Bulletins & correspondence

009100063 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/07/24 fp

009250109 Forwards IE Insp Repts 50-566/80-11 & 50-567/80-11 on 800715-17 & notice of violation HURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/04 2pp

3009230112 Notice of violation from insp on 800715-17
\* Region 2. Atlanta, Office of the Director 80/08/04. 1p

D09250114 IE Insp Repts 50-556/80-11 & 50-567/80-11 on 800715-17 Noncompliance noted failure to follow procedure for curing cancrete test cylinders AMTRELLE S Region 2. Atlanta, Reactor Construction & Ingineering Support Branch. THOMAS, M Region 2. Atlanta, Office of the Director 80/08/04, 4pp

20214 Forwards response to IE Bulletin 79-03A No BA-312 & A-312. s 300 series fusion welded pipe used or planned for use safety-related sys at greater than 85% design stress upt Watts Bar Hati under investigation at Watts Bar LS:LM Tennessee Valley Authority 80/08/05 2pp

)802 Responds to IE Bulletin 79-03A, "Langitudinal Weld Defects ME SA-312. Type 304 Stainless Steel Pipe " Use of matls under investigation for sys supplied by NBSB vendor I.L.M. Tennessee Valley Authority 80/08/05 2pp

0303 Forwards IE Insp Repts 50-327/80-24, 50-328/80-15, 90/80-20, 50-391/80-14, 50-438/80-13, 50-439/80-13, 18/80-11, 50-519/80-11, 50-520/80-11, 50-521/80-11, 50-51/80-10, 50-366/80-10 t 50-567/80-10 il.LV, J P Region 2. Atlanta, Office of the Director 80/08/06

J9020312 Notice of violation from insp on 800707-11 \* Region 2. Atlanta, Office of the Director 80/08/06 4pp

--8009020337 IE Insp Repts 50-327/80-24,50-328/80-15,50-496/80-20,50-391/80-14,50-438/80-13,50-439/80-13,50-518/80-11,50-518/80-11,50-518/80-11,50-553/80-15,50-518/80-11,50-554/80-10,50-566/80-10 & 50-567/80-10 on 800707-11 BROWNLEE,V L Region 2, Atlanta, Office of the Director 80/08/06 2890

8007030146 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Hercury-Wetted Matrix Relays in Reactor Protective 8ys of Operating Nuclear Power Plants Designed by C-E," Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/15 in

8009160183 Forwards IE Circular 80-18, "10CFR50 89 Safety Evaluations for Changes to Radwaste Treatment Sys " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/22 ip

8007120340 Forwards IE Info Notice 80-31, "Maloperation of gould-Brown Boveri 480 Volt Tupe K-6008 & K-DON 6008 Circuit Breakers," No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director, 80/08/27

8009180087 Forwards response to IE Bulletin 80-16 Rosemount Hodels 151 & 1152 pressure transmitters are not used or planned for use except at Beliefonte Nuclear Plant where use will be evaluated MILLS, L. M. Tunnessee Valley Authority 80/08/29. 2pp.

8007240454 Forwards response to IE Bulletin 80-16 re potential misapplication of Rosemount pressure transmitters. No corrective action required due to results of evaluation that indicated impossibility of anomalous output.

MILLS.L K Tennessee Valley Authority. 60/08/27 2pp.

8007240583 Ack receipt of 800818 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-566/80-03 & 30-567/80-03 MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 90/09/02 ip.

--8009240600 Responds to NRC 800228 ltr re violations noted in IE Insp Repts 50-566/80-03 & 50-567/80-03 Corrective actions: radiographs before 800207 re-examined & radiographers instructed in requirements of shim placement MILLS,L M Tennessee Valley Authority 80/08/18, 3pp

8009120679 Responds to IE Bulletin 80-19 re failures of mercury-wested matrix relays in reactor protective sys. Relays identified are not used in facility Forty manhours expended for review MILLS, L. N. Tennessed Valley Authority 80709704 Ip.

8009260375 Forwards IE Circular 80-21, "Regulation of Refueling Crews No written response required, O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/10-5pp

# 8 Reportable occurrences, LERs & related correspondence

8007160368 Final deficiency rapt re 84 reinforcing bars left out of wall pour CI-Fi located in control bldg Caused by inspector error Mor rebar removed for other installations Missing rebar replaced, Detail checkoff list initiated to aid inap. MILLS, I. M. Tennessee Valley Authority. 80/09/11. 3pp

DOCKET STN-50-567 YELLOW GREEK NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8009080080 Forwards draft NUREO-0696, "Functional Criteria for Emergency Response Facilities" Comments requested within 30 days Proposed implementation schedule for meeting criteria of NUREO-0696 encl W/o NUREO EISENHUT, D 9 Division of Licensing. 80/08/01 i19pp.

## Q Adjudicatory correspondence

8009300549 Request extension of time for comment on Commission 800007 order re reopening GESMO proceeding MOLDEN, R B Allied General Nuclear Bervices 80/09/23 1p

#### I Financial information

8009090343 Forwards Annual Financial Rept 1979 CRDS8,J L Tennessee Valley Authority 80/09/04 ip

- -8009090363 Annual Financial Rept 1979 \* Tannesse Valley Authority 80/09/04, 44pp.
- & Inspection reports, IE Bulletins & correspondence
- 8009100063 Forwards IE Bulletin 80-18, "Maint of Adequate Min Flow Through Centrifugal Charging Pumps Following Secondary Side High Energy Line Rupture " No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/07/24.
- 9009250109 Forwards IE Insp Repts 50-566/80-11 & 50-567/80-11 on BO0715-17 & notice of violation MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/08/04 2pp
- --8009250112 Natice of violation from insp on 800715-17
   Region 2: Atlanta: Office of the Director 80/08/04 ip
- ~-8009250114 IE Insp Repts 50-566/80-11 & 50-567/80-11 on 800719-17
  Noncompliance noted failure to follow procedure for curing
  concrete test cylinders
  CANTRELL.F S. Region 2. Atlanta: Reactor Construction &
  Engineering Support Branch THOMAS,M Region 2. Atlanta, Office
  of the Director. 80/08/04. App
- 8009020214 Forwards response to IE Bulletin 79-03A. No 8A-312 & A-312, Type 300 series fusion welded pipe used or planned for use in sefety-related sys at greater than 85% design stress except Hatts Bar, Matl under investigation at Watts Bar. MILLS.L.M Tennesses Valley Authority 80/08/05, 2pp
- 8009070802 Responds to IE Bulletin 79-03A, "Longitudinal Held Defects in ASHE 8A-312, Type 304 Stainless Steel Pipe." Use of matts still under investigation for sys supplied by NSSS vendor HILLELL M Tennessee Valley Authority 80/08/05 2pp.
- 8009020303 Forwards IE Insp Repts 50-327/80-24, 50-328/80-15, 30-390/80-20, 50-391/80-14, 50-438/80-13, 50-439/80-13, 50-519/80-11, 50-553/80-11, 50-553/80-11, 50-553/80-11, 50-553/80-10, 50-56/80-10 & 50-56/7/80-10 0'REILLY, J P. Region 2, Atlanta, Office of the Director. 80/08/06
- --8009020337 IE Insp Repts 50-327/80-24,50-328/80-15,50-390/80-20, 50-391/80-14,50-438/80-13,50-439/80-13,50-518/80-11, 50-519/80-11,50-520/80-11,80-321/80-11,50-553/80-11, 50-554/80-10,50-564/80-10 t 50-547/80-10 on 800707-11 BROWNLEE.V.L. Region 2, Atlanta, Office of the Director 80/08/06 24pp.
- 8009030146 Forwards Revision 1 to IE Bulletin 80-19, "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/08/15, in.
- 8009160183 Forwards IE Circular 80-18, "10CFR50 59 Safety Evaluations for Changes to Radwaste Treatment Sys." No written response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/08/22 is
- 8009120340 Forwards IE Info Notice 80-31, "Maloperation of Gould-Brown Bover; 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers."

  No written response required, U'REILLY, J. P. Region 2/ Atlanta, Office of the Director 80/08/27. ip.
- 8009180087 Forwards response to IE Bulletin 80-16 Rosemount Models 1151 & 1152 pressure transmitters are not used or planned for use except at Bellafonte Nuclear Plant where use will be evaluated.

  MILLS, L M Tennessee Valley Authority 80/08/29. 2pp
- B009240454 Forwards response to IE Bulletin 80-16 rs potential misapplication of Rosemount pressure transmitters No corrective action required due to results of evaluation that indicated impossibility of anomalous output.

  MILLE/L M Tennessee Valley Authority 80/08/29. 2pp
- 8009240383 Ack receipt of 800818 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50~566/80-03 & 50-567/80-03 MURPHY.C. E. Region 2. Atlanta. Reactor Construction & Engineering Support Brench. 80/09/02 ip.

- --8009240600 Responds to NRC 800228 ltr re violations noted in IE Insp. Repts 50-966/80-03 & 50-967/80-03 Corrective actions radiographs before 800207 re-examined & radiographers instructed in requirements of shim placement MILLS.L.M. Tennessee Valley Authority 80/08/18 3pp
- 8009120679 Responds to IE Bulletin 80-19 re failures of marcuny-wetted matrix relays in reactor protective sys Relays identified are not used in facility Forty manhours expanded for review MILLS.L M. Tennessee Valley Authority 80/09/04 Lp
- 8009260375 Forwards IE Circular 80-21, "Regulation of Refueling Crews" No written response required C'REILLY, J P Region 2, Atlanta, Office of the Director, 80/09/10

DOCKET STN-50-574 BAGNAC NUCLEAR POWER PROJECT

- Q. Adjudicatory correspondence
- 8008250025 Bupports Movement of Concerned Citizens of Philippines petition to intervene Justification of NRC actions redropping safety.health & environ review requested HATSON,M Australia. 80/08/05 ip
- DOCKET 50-582 BUNDESERT, UNIT 1 O. Adjudicatory correspondence
- 8009170169 Motion for withdrawal of application for CP NEWMAN, J R. Ban Diego Gas & Electric Co NEWMAN, J R Lowenstein, Newman, Reis, Axelrad & Toll 80/09/11. ig
- --8009170171 Motion for termination of proceeding due to withdrawal of application for CP Cartificate of Byc encl
  NEWMAN.J.R. Ban Diego Gas & Electric Co 80/09/11 3pp.

DOCKET 50-583 SUNDESERT, UNIT 2

O Adjudicatory correspondence

- BOO9170169 Motion for withdrawal of application for CP NEWHAN, J R Sam Diago Gas & Electric Go NEWHAN, J, R Lowenstein, Newman, Reis, Azelrad & Toll BO/09/11. 1p
- --8009170171 Motion for termination of proceeding due to withdrawal of application for CP Certificate of Svc encl
  NEWMAN.J R. San Diego Gas & Electric Go 80/09/11 3pp

ROCKET STN-50-592 PALO VERDE NUCLEAR STATION, UNIT 4

A Application/construction stage documents & correspondence

8009030811 Submits response to NRC 800423 info request on Category i masonry walls employed by plants under CP & OL review. Drawings 13-A-ZJD-509 through \$11.13-A-ZAD-203 & 13-A-ZAD-207 re concrete & auxiliary bidgs encl VAN BRUNT.E E Arizone Public Bervice Co 90/08/28 3pp

DOCKET STN-50-593 PALO VERDE NUCLEAR STATION, UNIT 5

A Application/construction stage documents & correspondence

8009030511 Bubmits response to NRC 800421 info request on Category 1 masonry walls employed by plants under CP & OL review. Orawings 13-A-ZJD-309 through 511,13-A-ZAD-203 & 13-A-ZAD-207 re concrete & auxiliary blogs encl VAN BRUNT, E Arizona Public Service Co 80/08/25 3pp

DOCKET 50-599 CARROLL FACILITY I

O. Adjudicatory correspondence

BOO7070233 Response in opposition to Citizens Against Nuclear Power, J J Rungon & E Gogol petition for review of ASLAB 800729 order affirming ASLB 800530 dismissal of contentions Const will not be allowed prior to environ review M/Certificate of Svc MILLER, M I., BIELANSKI, A P Commonwealth Edison Co MILLER, M I. Isham: Lincoln & Beale 80/08/29, 12pp. 8009160142 Order granting extension until 801006 for Commission to CHILK, S J Office of the Secretary of the Commission BO/09/11

DOCKET 50-600 CARROLL FACILITY II G Adjudicatory correspondence

B009090233 Response in opposition to Citizens Against Nuclear Power, J J Runyon & E Dogol petition for review of ASLAB 800729 order affirming ASLB 800530 dismissal of contentions Const will not be allowed prior to environ review W/Certificate of Svc. HILLER, M I . BIELAMSKIAP Commonwealth Edison Co HILLER, M I Isham, Lincoln & Beale 80/08/29 12pp

8009160142 Order granting estansion until 801006 for Commission to review ALAB-601 CHILK.S J Office of the Secretary of the Commission 80/09/11

#### DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DOCKET 70-0008 BATTELLE COLUMBUS LABORATORIES

6009090886 Forwards physical security plan for protection of GNM of moderate or low strategic significance Plan withheld (ref 10CFR2 790). TOY, H L Battelle Memorial Institute, Columbus Laboratories BO/05/22 ip

8009120691 Forwards NUREC-0561 & info on transportation routes through populated areas W/o enci MCCORKLE, G W Physical Security Licensing Branch 80/07/08 ip

8007230376 Forwards IE Circular 80-20, "Changes in Safe-Blab Tank Dimensions" No written response required. KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/08/21, 400

DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP.

8007120620 Requests restission of approved security plan.AI-74-86.for protection of greater than threshold quantities of 8NM at 8anta Susana plant forseable plans do not involve possession & handling of greater than threshold quantities REMLEY.ME Roctuell International Corp., Energy Systems Div 80/07/17 2pp.

8007120161 Notifies that Section 9.0 of Amend MPP-1 to License BNM-21 is amended deleting Section 9 B re physical protection plan, effective immediately MCCORKLE.O W Physical Security Development Branch 80/07/24, 1p.

8009090839 Advises of refund re fee submitted w/800626 application to amend License SNM-21 MILLER, W.O. License Fee Management Branch 80/08/06 ip.

8009050188 Forwards IE Insp Rept 70-0025/80-05 on 800515-20 No noncompliance noted Entl withheld (ref 10CFR2 790) NGRUERHAUGO, R. Region 5, San Francisco, Safeguards Branch 80/08/12 2pg

8009230371 Forwards IE Circular 80-20, "Changes in Safe-Slab Tank Dimensions " No written response required EMOELMEN.R H Region 5, San Francisco. Office of the Director 80/09/21. 4pp

B009240589 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network. Bys installed for govt use during emergency ENGELERN.R H Region 5, San Francisco, Office of the Director 80/08/22 3pp

DUCKET 70-0027 BABCOCK & WILCOX CO

8007030001 Application for amend to License 8NM-0042, Amend provides for quarterly sampling of airborne radioactive effluent released from laundry operations GORDANI.R A Babcock & Wilcox Co 80/06/05 5pp

3009120157 Forwards response to site-specific questions of SNM search requirement & security lighting MCCORKLE.0 W Physical Security Licensing Branch. 80/07/10 2pp.

8009110767 Requests exemption from 10CFR70 51(e)(3)(i) to delaw commencing Jul/Aug 1980 SNM inventory until 800905 CGRDANI R A Babcock & Wilcox Co , Naval Nuclear Fuel Div. 80/07/25

8009090885 Informs of tentative meeting w/United Nuclear Corp re recovery contract for beginning of Aug Requests Joint meeting w/NRC in late Aug pending resolution of contractural/safeguards problems ECKERT.J P. Babcock & Wilcox Co , Navel Nuclear Fuel Div 80/07/29,

8009090836 Advises that no add1 fee required for review & approval of Amend 11 to License SNM-42 MILLER.W O License Fee Management Branch 80/08/06 1p

8009090124 Requests analysis & evaluation of airborne sampling data for two previous urs to provide justification for change from continuous to quarterly sampling requested on 800605 Data should include sampling methods & counting technique KETZLAGH.N Uranium Recovery Licensing Branch 80/08/11

8009230391 Forwards IE Circular 80-20, "Changes in Bafe-Slab Yank Dimensions " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 69/08/21

8009230323 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network 8ys installed for govt use during emergency O'REILLY, J & Region 3, Chicago, Office of the Director 80/08/22.

8009100790 Forwards IE Insp Rept 70-0027/80-11 on 800701-03 & 07-11 noncompliance noted NNA, W. B Region 2, Atlanta, Bafeguards Branch, 80/08/26 1p.

--8009100795 IE Insp Rept 70-0027/80-11 on 800701-03 & 07-11 No noncompliance noted Hajor areas inspected physical inventory verification Details withheld (ref 100FR2.790) CLAY.E L. TODD.O A Region 2. Atlanta. Defice of the Director. OILLESPIE.F P Region 2. Atlanta. Safeguards Branch 80/08/28.

DOCKET 70-0033 TEXAS INSTRUMENTS, INC.

8009150078 Requests consideration of extension of submission date for printed required by safeguards upgrade rule implementation. Delay due to need to reflect substantive change in status Bubaitsi date would be extended from SOOB22 to 0930, CHURCHILL, R L. Texas Instruments, Inc 80/06/18, 2pp.

8009110702 Requests extension from 800822 to 801231 for submittel of addl info required by NRC re-application to renew License BNR-23 Portions of NRC request require sycs of outside consultants CHURCHILL,R L Texas Instruments, Inc 80/06/19 2pp

8009120170 Responds to 800618 ltr. Grants extension until 800930 for JUVICUTOR RESPONDED TO GOUGHT IFF. WEARTH WATERSTON DURING SUBDITED A PHYSICAL PROPERTY OF THE PROPERTY OF THE

8009170084 Confirms 800701 telcon re 800619 ltr requesting relief from request for addl info to suppl license renewal application info needed to provide sufficient justification for addl flexibility requested in application CROM.W T Uranium Fuel Licensing Branch 80/07/07 1p.

B00912066B Advises of withdrawal of license renewal application submitted 790829 Requests extension of existing license until termination of HFIR operation BHERNAN.F.L. Texas Instruments, Inc. 80/07/16, ip.

8007180487 Ack receipt of 800721 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0033/80-07 Util ltr to be withheld (ref 10CFR2 790) MARTIN.W O. Region 1. Philadelphia, Safeguards Branch. 80/08/05

--8009180491 Forwards IE Insp Rept 70-0033/80-07 on 800609-13.
MARTIN.W. G Region 1, Philadelphia, Safeguards Branch E 80/07/01

- --B009180497 IE Insp Rept 70-0033/80-07 on B00609-13 Noncompliance noted failure to implement weighing sampling or gamma counting training program & failure to update control limits Details withheld (ref 100FR2 790)

  MOLDDY, D. J. Region 1. Philadelphia, Office of the Director JOYNER, J. H. Region 1. Philadelphia, Safeguards Branch. B0/06/30 is
- 8009240334 Amends License SNM-23, extending expiration data until 820630 & adding Conditions 26-30 re personnel qualifications & sampling of radioactivity in fuel mfg area PAGE, R Q Uranium Fuel Licensing Branch 80/08/15 2pp
- --8009240339 Bafety evaluation of 800716 application to amend License 8NM-23, authorizing extension of license Recommends issuance of license amend subj to addl Conditions 26-30 NETZLACH.N., CROM, W.T. Uranium Fuel Licensing Branch 80/08/15 4pp.
- 2009230415 Forwards IE Circular 80-20, "Changes in Bafe-Slab Tank Dimensions" No written response required SRIER, B. H. Region 1. Philadelphia, Office of the Director 30/08/21, 4pp
- 8009230220 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency GRIER.B.H Region i. Philadelphia, Office of the Director 80/08/22 Spp
- 8009020255 Forwards "Effluent & Waste Disposal Semiannual Rept for Jandune 1980," supplemental info MCBAVITY.D F. Texas Instruments, Inc. 80/08/25 ip
- --8009020259 "Effluent & Haste Disposal Semiannual Rept for Jan-Juni 1980." Supplemental Info \* Texas Instruments: Inc 80/08/25 3pp

#### DOCKET 70-0036 COMBUSTION ENGINEERING, INC

- 8009150166 Forwards IE Insp Rept 70-0036/80-02 on 800709-11 No noncompliance noted. DAVIS:A B Region 3: Chicago: Fuel Facility & Materials Bafety Branch 80/07/30 2pp
- 8009230377 Forwards IE Circular 80-20. "Changes in Safe-Slab Tank Dimensions " No written response required. AEPPLER, J. C. Region 3. Chicago, Office of the Director. 80/08/21.
- 8009250419 Ack receipt of 800829 16r informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0036/80-03, HIND, J. A. Region 3, Chicago, Safeguards Branch, 80/09/09 ip
- --8009250422 Responds to NRC 800808 ltr re violations noted in IE Insp Rept 70-0036/80-03. Corrective actions individuals authorized to sign internal transfer forms have been instructed on proper procedures ESKRIDGE, H. E. C-E Power Systems 80/08/29 2pp

## DOCKET 70-0135 BABCOCK & WILCOX CO

- 8009110244 Requests 2-wk extension for reconciling plant ledgers & filing low enriched U plant SNM inventory rept Reconciliation of available physical inventory data shows inventory difference meeting 1/2% spec.
  AUBTIN.H.A Babcock & Wilcox Co., Nuclear Material Div 80/06/25 fp.
- 3009160179 Forwards IE Insp Repts 70-0135/80-16 & 30-0364/80-14 on 800609-13. No noncompliance noted.
  MARTIN, M. Q. Region I, Philadelphia, Safeguards Branch. 80/07/08.
  2pp
- -8009160186 IE Imsp Repts 70-0135/80-16 & 30-0364/80-14 on 800609-13 No nancompliance noted, Major areas inspected physical inventory & assessment & observation of nondestructive assay work performed by licensee Datails withheld (ref 10CFRZ 790). BIBBETT.P.H., SUMMERS.R.J. Region 1, Philadelphia, Office of the Director, JUYNER, J.H. Region 1, Philadelphia, Safeguards Branch. 80/07/01. 19
- M09090874 Forwards application to amend License BNM-145; requesting revision to approved Apollo plant high enriched U plan covered by License Condition 2.1 in MPP-1 Encl & attachments withheld (ref lOCFR2 790).
  AUSTIN: A Babcock & Wilcox Co., Nuclear Material Div. B0/07/18

- 8009150403 Responds to 800718 request for limited exemption to permit highly enriched U leaching operation Forwards Amend MPP-1 to License SINH-145 Request will not endanger public health & safety or common defense & security

  MCCORKLE, O W Physical Security Licensing Branch 80/07/24 ip
- --8009150406 Adds condition to Amend MPP-1 to License SNM-145 granting limited exemption to permit high enriched U leaching operation within incinerator area \* Physical Security Licensing Branch 80/07/24 ip
- 8009150347 Forwards IE Insp Rept 70-0135/80-19 t on 800707-10 No noncompliance noted MARTIN.W 0 Region 1. Philadelphia, Safeguards Branch 80/07/25
- --8009150358 IE Insp Rept 70-0135/80-19 on 800707-10 No honcompliance noted Major areas inspected independent measurements by NRC inspectors of residual U-235 holdup in high enriched U facility Details withheld (ref 10CFR2 790) BISSETT,P H. COHEN,I. JUYNER,J H. Region 1. Philadelphia. 8d/egvards Branch 80/07/22 ip
- 8009110262 Ack receipt of 800718 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0135/80-15 & 70-0364/80-13.

  MARTIN.W.Q Region i, Philadelphia, Safeguards Branch 80/08/05
- --8007110274 Forwards IE Insp Repts 70-0135/80-15 & 70-0364/80-13 on 800505-30 & notice of violation MARTIN.W O Region I, Philafelphia, Safeguards Branch 80/06/24 20a
- --8009i10276 Notice of violation from insp on 800505-30
  \* Region 1, Philadelphia, Office of the Director 80/06/23 ip.
- --8009110281 IE Insp Repts 70-0135/80-13 & 70-0364/80-13 on 800505-30 Noncompliance noted failure to perform nuclear criticality evaluation JOYNER,J H Region 1. Philadelphia, Bafaguards Branch KUSHNER, W L Region 1. Philadelphia, Office of the Director 80/06/23 9pp
- 8007180183 Informs of out-of-specs condition of five cylinders of low enriched U hexaflouride received 800731 Cylinders will not be introduced to production sys Requests one-time exemption to return math to govt at shipper values Fee forthcoming AUSTIN, M A Babcock & Wilcox Co , Nuclear Material Div 80/08/05 ip.
- ---R009180196 Forwards check for administrative amend fee re one-time examption relative to mat: returns at shipper values

  AUSTIN:M A Babcock & Wilcox Co . Nuclear Material Div 80/08/05
- 8009150480 Forwards rept on radioactive effluents discharged to unrestricted areas as result of work performed under Licenses 8NM-145 & SNM-414 Rept covers Jan-June 1980 AUSTIN.M.A Babcock & Hilcor Co., Nuclear Material Div 80/08/13.
- 8009110263 Ack receipt of 800715 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0135/80-14 MARTIN, W G Region 1, Philadelphia, Bafeguards Branch. 80/08/19
- --- 2007110269 Forwards IE Insp Rept 70-0135/80-14 on 800527-30. No moncompliance noted MARTIN, W O Region 1, Philadelphia, Safeguards Branch 80/06/25. 2pp
- ---8009110272 IE Insp Rept 70-0135/80-14 on 800527-30 No noncompliance noted Major areas inspected effluent waste treatment sys in low enriched U plant Datalis withheld (ref 100FR2 790) JOYNER J. ZIBULSKY, H. Region 1. Philadelphia, Safeguards Branch 80/06/24, 1p
- 8009230409 Forwards IE Circular 80-20, "Changes in Bafe-Elab Tank Dimensions" No written response required ORIER:R H. Region 1. Philadelphia. Office of the Director 80/08/21 4pp
- 8009230211 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency GRIER, BH Region 1. Philadelphia, Office of the Director, 80/08/22 Spp.

- DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC.
- 9009050179 F01A request for documents re inventory difference at facility COCMRAN,T B Natural Resources Defense Council 79/12/10 2pp
- B009050480 FOIA request for list of facilities for which comprehensive evaluation repts have been prepared, NUREG repts re MUF, list of documents re facility MUF & NRC decision to reopen plant DAVIS.PS Affiliation Unknown 80/06/25 ip
- 8009050180 Forwards IE Insp Rept 70-0143/80-23 on 800714-18 No noncompliance noted KENNA, W B Region 2. Atlanta. Safeguards Branch 80/08/07 1
- --B0090501B4 IE Insp Rept 70-0143/80-23 on 800714-18 No noncompliance noted Major areas inspected training, maint, nuclear criticality safety, followup on IE info notices & independent areas independent areas AHLE.J B Region 2. Atlanta, Office of the Director KENNA,W B Region 2. Atlanta, Safeguards Branch B0/08/07 3pp
- 8009150027 Forwards Revision 18 to fundamental nuclear material control plan Encl withheld (ref 10CFR2 790)
  HENSLEY.K D Nuclear Fuel Services. Inc (subs of Getty Oil Co ) 80/08/07 2pp
- 8009050408 Responds to FOIA request for list of facilities for which comprehensive evaluation repts have been prepared NUREOs re MUF, list of documents re facility MUF & NRC decision to reopen plant Forwards NUREO-0350 & 0430 M/o encis FELTON, J N Division of Rules and Records 80/08/08 2pp
- 8009120096 Advises that security plan for low enriched matl of low strategic significance meets requirements Matls & plant protection Amend MPP-1 to License SMM-124 is amended by adding Saction 12 re physical protection requirements MCCORKLE.0 W Physical Security Development Branch. 80/08/11 ip
- 8007050168 Responds to FOIA request for matl received, considered or approved by Commission during consideration of inventory at facility Forwards App A documents App B documents withheld. restricted data (ref FOIA Exemption 3) FELTON.J M Division of Rules and Records 80/08/14 3pp
- B007050177 Responds to FOIA request for documents re inventory difference at facility reported on 790917 List of documents listed in App A & App B App B documents withheld restricted data (ref FOIA Exemption 3) FELTON. J N Division of Rules and Records 80/08/14 3pp.
- 8007100702 Ack receipt of 800718 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0143/79-44 & 70-0143/80-20

  O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/14.
- ---8009100906 Responds to NRC 800624 ltr re violations noted in IE insp Repts 70-0143/79-44 & 70-0143/80-20 Corrective actions withheld (ref lOCFR2 790) MANSER: W C Nuclear Fuel Services, Inc (subs of Getty Uil Co.) 80/07/18 ip
- --8009100910 Forwards IE Insp Rept 70-0143/80-20 on 800617-19 Noncompliance noted O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/06/24 2pp
- --8009100914 IE Insp Rept 70-0143/80-20 on 800617-19 Noncompliance noted corrective action on previous item of noncompliance dealing w/item control Details withheld (ref 100FR2 790).
  TODD, 9 A Region 2, Atlanta, Office of the Director.
  GILLESPIE,F.P. Region 2, Atlanta, Safeguards Branch. 80/06/24, ip
- BOO9120147 Ack receipt of IE Insp Rept 70-0143/80-23 on BO0714-18 No proprietary info HANSER, M C Nuclear Fuel Bervices: Inc. (subs of Getty Oil Co ). BO/08/18 ip

- --8009120224 Forwards IE Insp Rept 70-0143/60-23 on 800714-18. No noncompliance noted KENNA, W B Region 2, Atlanta, Bafeguards Branch 80/08/07 ip
- --8009120227 IE Insp Rept 70-0143/80-23 on 800714-18 No noncompliance noted Major areas inspected training,maint,nuclear criticality safety & followup on IC info notices KAFR.E.J B Region 2. Atlanta, Office of the Director KENNA, U. 8 Region 2. Atlanta, Safeguards Branch 80/08/07 Spp.
- 8009120124 Ack receipt of 800801 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/80-21 KENNA,W B Region 2, Atlanta, Bafeguards Branch 80/08/20, Ip
- --8009120126 Responds to NRC 800717 ltm re violations noted in IE Insp Rept 70-0143/80-21 Corrective actions taken & results withheld (ref 10CFR2 790) HANSER W C Nuclear Fuel Services. Inc (subs of Oatty Dil Co.). 80/08/01
- --8009120130 Forwards IE Insp Rept 70-0143/80-21 on 800616-20 & notice of violation Notice of violation withheld (ref 100FR2 790).

  KENNA, W B Region 2. Atlanta. Bafeguards Branch. 80/07/17. 2pp.
- --8009120133 IE Insp Rept 70-0143/80-21 on 800616-20. Noncompliance noted failure to determine systematic weighing errors & failure to evaluate measurement control data Details withheld (ref 10CFR2 790).
  UNEED W. Region 2. Atlanta, Office of the Director.
  OILLESPIE.F. P. Region 2. Atlanta, Safeguards Branch. 80/07/17.
- 8009230404 Forwards IE Circular 80-20, "Changes in Bafe-Blab Tank Dimensions," No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/21.
- 8009150395 Responds to 800818-21 site visit re safeguarde sys for highly enriched U Forwards new conditions for Amend MPP-1 to License SNM-124 clarifying intent of temper-safing program. PARTLOW U Q Material Control Licensing Branch 80/08/22 Ip.
- --8009150398 Revises Amend MPP-1 of License SNN-124, incorporating Conditions 2.30 & 2.31 re personnel performance of item control audits & changing Condition 7.3 re tamper-wafing surveillance = Material Control Licensing Branch 80/08/22 1p.
- 8009230325 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency O'REILLY.J P Region 3. Chicago, Office of the Director. 80/08/22
- 8009090465 RO on 800728, fire occurred in Bidg 302 tube cleaning room Fire involved ductuors, HEPA filter media, plexigles & other matis, releasing carbonaceous soot. Room void of all radioactive matis except low level surface contamination. HANSER: H C Nuclear Fuel Services, Inc (subs of Ostty Oil Co.) 80/80/27 bpg
- 8009040258 Motion for extension until 801015 to file direct submissions Awaiting confirmation of new NRC chairman prior to decision. Certificate of Svc enci. WEISS.E R Natural Resources Defense Council WEISS,E R Sheldon, Harmon & Weiss 80/08/29 3pp.
- 8009090504 Forwards "Rept of Effluent Monitoring & Release to Unrestricted Areas, Jan-June 1980 " MICHEL, C J Nuclear Fuel Services, Inc. (subs. of Getty Gil Co.) 80/08/29 1p
- --8009090507 "Rept of Effluent Monitoring & Release to Unrestricted Areas, Jan-June 1980."

  \* Nuclear Fuel Bervices, Inc. (subs. of Getty Gil Co ). 80/08/29.
- 8009240742 Advises that 800819 request for amend to safeguards plan requires major amend to License ENM-124. Payment of Category 1A fee should be made to NRC. WEISS.D License Fee Management Branch. 80/09/04 1p
- 8009110391 Forwards "Proposed Program for Determination & Demonstration of Whatman-41 Filter Media Efficiency for Collection & Retention of Soluble U Particles at NFS Perimeter Air Sampling Stations "
  MICHELIC J Nuclear Fuel Services, Inc. (subs. of Oetty Oil Co.).
  80/09/05 ip

- --B009110393 "Proposed Program for Determination & Demonstration of Whatman-41 Filter Media Efficiency for Collection & Retention of Boluble U Particles at NFS Perimeter Air Sampling Stations "

   Nuclear Fuel Services, Inc., (subs. of Getty Oil Co.) 80/09/05
- 9007110392 Forwards response to NRC 800813 ltr re violations noted in IE insp Rept 70-0143/80-22 Response withheld (ref 100FRZ 770) MANSER,H C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 80/07/05. 1p
- BOO9250435 Forwards IE Insp Rept 70-0143/80-22 on 800714-16 No nancompliance noted Insp summary only encl (ref 100FR2 790) KENNA:N B Region 2: Atlanta: Safeguards Branch 80/08/13 2pp
- --9009250437 IE Insp Rept 70-0143/80-22 on 800714-16 No noncompliance noted Major areas inspected corrective actions to items 80-08-1.80-08-02 % 79-46-01.security organization & barriers Details withheld (ref 10CFR2 790)
  TOBIN.H.J., PERNY.C D. Region 2, Atlanta, Office of the Director GillESPIE.F P. Region 2, Atlanta, Safeguards Branch. 80/08/05
- 8009120421 Forwards Chapter 19 of physical safeguards plan W/o encl MICHEL,C.J. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.) 80/09/08 19
- 8009240624 Ack receipt of 800721 ltr.informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/80-13
  8TOHR, J.P. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch. 80/09/08 lp
- --B009240631 Responds to NRC 800626 ltr re violations noted in IE Insp Rept 70-0143/80-13 Corrective actions employee exposure repts & effluent release data updated MANSER, N C Nuclear Fuel Services. Inc (subs of Getty Dii Go.), 80/07/21 4pp
- --B009240637 Forwards IE Insp Rept 70-0143/80-13 on 800321,0421-25 & notice of violation STOHR,J.P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch B0/06/26 2pp
- --B009240640 Notice of violation from insp on B00321,0421-25,

  \* Region 2, Atlanta, Office of the Director 80/06/23, ip
- 8009270374 Revises License Condition 2 1 of Amend MPP-1 to incorporate revised Section 6.0 & App C Revised Sections 1 0 & 8 O require addl clarification PARTLOW.J O Physical Security Licensing Branch. 80/09/10 2pp.
- 8009260435 Natifies of intention to be represented by NRBC for written testimony before 801001 SHERBONDY, S.N. Affiliation Unknown 80/07/16 ip
- 8009240559 Advises that Plant 1 inventory difference for Jul 1980 high enriched U physical inventory exceeded limit of error Encl withheld (ref 100FR2,790). HENSLEY,K D. Nuclear Fuel Services, Inc. (subs. of Oetty Gil Co.). 80/09/19 1p
- 8007250053 Order effectively denying NRDC 800714 petition to stay effectiveness of decision that granted legislative hearing w/o discovery privileges. Sets schedule for hearing. Grants addl limited participations JF Ahearne separate views encl CHBLK.S J Office of the Secretary of the Commission. 80/09/22 App.
- BO09300475 Forwards mat) balances covering inventory period May-Aug 1980 Enc: withheld (ref 100FR2 770) HERBLEY,K.D. Nuclear Fuel Services, Inc. (subs of Oetty Gil Co ). BO/09/24 1p

## DOCKET 70-0258 ILLINDIS, UNIV OF, URBANA-CHAMPAIGN

BOO9120611 Application to amend License SNM-236, increasing max amount of U-235 to 300 g. Description of use & analysis of hazards encl.

MANDEL:H. Illinois, Univ. of, Urbana-Champaign BO/06/03 Bpp

- --8009120614 "UF6 Handling Sys for Nuclear-Pumped Laser Experiments "
  BOODY, F.P. Illinois, Univ. of, Urbana-Champaign 78/12/31 27pp
- 8009150181 Amend 1 to License 9NM-236, authorizing posession of up to 300 g U-235 to be used in experiments
  PAGE, R O Uranium Fuel Licensing Branch 80/09/29 ip
- --8009150183 Safety evaluation supporting Amend 1 to License SNM-236 SGBNO.A L , CROW, W T Uranium Fuel Licensing Branch 80/08/29 20a
- DOCKET 70-0312 MASSACHUSETTS, UNIV OF
- 8009100634 Ack receipt of 800806 ltr informing NRC of steps taken to correct supiration of license noted in IE Insp Rept 70-0312/80-02 KINNEMAN, J D Region 1, Philadelphia, Office of the Director 80/08/14 ip
- --8009100647 IE Insp Rept 70-0312/80-02 on 800707 No noncompliance noted Major areas inspected expiration of license & application for new license KINNEMAN, J D. Region 1. Philadelphia, Fuel Facility & Materials Bafety Branch ROME, C A Region 1. Philadelphia, Office of the Director 80/08/13 2pp
- --B009100651 Application for renewal of License SNM-292 KOFFLER, H Massachusetts, Univ of 80/09/06 ip.
- DOCKET 70-0343 RUTGERS, NEW JERSEY, THE STATE UNIV OF
- 8009120529 Ack receipt of 800710 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 70-0343/80-01. 30-06991/80-01 & 30-00395/80-01 BMITH.0 H Region 1. Philadelphia, Fuel Facility & Materials Bafety Branch 80/08/14 1p
- --8009120536 Responds to NRC 800624 ltr re violation noted in IE Insp Repts 70-0343/80-01.30-00883/80-01,30-04791/80-01 & 30-00356/80-01 Corrective actions research procedures will be reviewed & bulletin issued NOMELL.D.B Rutgers, New Jersey, State Univ of, Busch Campus 80/07/10 2pp
- --8009120542 Forwards IE Insp Repts 70-0343/80-01, 30-06893/80-01, 30-06991/80-01 & 30-00356/80-01 on 800501-02 & notice of violation KINNEMAN, J D Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/06/24 2pp
- --8009120548 Notice of violation from insp on 800501-02 Noncompliance noted individual in biochemistry dept worked w/mCi quantities of tritium w/o registering or w/o authorization from radiation safety ofc \* Region i, Philadelphia, Office of the Director 80/06/24 ip
- DOCKET 70-0349 NORTHWESTERN UNIV . EVANSTON CHICAGO
- 9009110827 Requests amend to Licenses 12-00382-03,12-00382-05, 12-00094-04,8UD-554 & BNM-330 to reflect encl membership of radiation safety committee MILLER, D.R. Northwestern Univ 80/06/25, 2pp
- --8009110831 Notifies that amend to Licenses 12-00382-03, 12-00382-03, 12-00382-03, 12-00984-06, 8UD-556 & SNM-330 is fee exempt CODPER, J. Region 3, Chicago, Office of the Director 80/06/30 ip
- --9009110935 Notifies that amend to Licenses 12-00382-03.12-00382-05. 12-00094-06.SUD-556 & GNM-330 is fee exempt MILLER, M. D. License Fee Management Branch 80/07/18 ip.
- DOCKET 70-0364 PARKS TOWNSHIP SITE, BABCOCK & WILCOX CO
- 8009230136 Requests amend to Tech Spec I B 5 revising Pages I.B.5 14 & I B 5 14(a), providing criteria for use of continuous monitors & clarifying use of general air samplers at Pufacibley
  AUSTIN.M A Babcock & Milcox Co., Nuclear Material Div. 80/07/02.

- --8009230139 Revised Tech Spec Pages I B 5 14 & I B 5 14(a).providing criteria for use of continuous monitors & clarifying use of ganeral air samplers at Pu facility # Babrock & Wilcor Co , Nuclear Material Div 80/07/02 2pp
- 8009150179 Forwards IE Insp Repts 70-0135/80-16 & 30-0364/80-14 on 800509-13 No noncompliance noted MARTIN.W G Region 1, Philadelphia, Safeguards Branch 80/07/08.
- --B009(50185 IE Insp Repts 70-0135/80-15 & 30-0364/80-14 on 800509-13 No noncompliance noted Major areas inspected physical inventory & assessment & observation of nondestructive assay work performed by licenses Details withheld (ref 10CFR2 790) BISSETT, P H. SUMMERS, R J. Region 1, Philadelphia, Office of the Director JOYNER, J H. Region 1, Philadelphia, Safeguards Branch B0/07/01 1p
- 8009110262 Ack receipt of 800718 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0135/80-15 & 70-0364/80-13 MARTIN-W C Region 1. Philadelphia, Safeguards Branch 80/08/05
- --8009110274 Forwards IE Insp Repts 70-0135/80-13 & 70-0364/80-13 on 800505-30 & notice of violation MARTIN,W © Region 1, Philadelphia, Safeguards Branch 80/06/24
- ~-8009110276 Notice of violation from insp on 800505-30 # Region 1, Philadelphia. Office of the Director 80/06/23 1;
- --8007110281 IE Insp Repts 70-0135/80-15 & 70-0364/80-13 on 800505-30. Noncompliance noted failure to perform nuclear criticality evaluation JOYNER.J H. Region 1. Philadelphia. Safeguards Branch KUSHNER.W L. Region 1. Philadelphia, Office of the Director 80/06/23. 70p
- 800911044B Forwards amend to Section 9 0 of Amend MPP-1 to License SNM-414, approving interim physical security plan by withdrawing License Conditions 9 1.9 1A.9.18 & 9 iC & reissuing License Condition 9 i MCCORKLE.0 W Physical Security Licensing Branch 80/08/11 2pp
- 8009150524 Grants 800326 & 0623 requests for exemption from certain code requirements for packaged SNM in form of waste Waste must be limited to solid matls & afforded physical protection per code BURNETION F Division of Safeguards 80/08/11 2pp
- 8009150480 Forwards rept on radioactive effluents discharged to unrestricted areas as result of work performed under Licenses SNM-145 & SNM-414 Rept covers Jan-June 1980 AVSTIN.M A Babcock & Wilcox Co . Nuclear Material Div 80/08/13 Spp
- 8007230409 Forwards IE Circular 80-20, "Changes in Safe-Blab Tank Dimensions" No written response required ORIER-B H Region 1. Philadelphia, Office of the Director 80/08/21 4pp
- 8009230211 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency ORIER, 8 H. Region 1. Philadelphia, Office of the Diractor 80/08/22 3pp

## OCKET 70-0371 UNITED NUCLEAR CORP

- 09120150 Forwards IE Insp Rept 70-0371/80-10 on 800416-20 No noncompliance noted MARTIN.W G Region 1, Philadelphia, Safeguards Branch 80/07/11 to
- 8009120235 IE In\*p Rept 70-0371/80-10 on 800616-20 No noncompliance noted Major areas inspected; facility Drganization & measurement control program Details withheld (ref 100FRZ 790) ZIBULSXV.H , MOLTMERLE Region 1, Philadelphia, Office of the Director JOYNER, J H Region 1, Philadelphia, Safeguards Branch 80/07/08 1P
- 8009240668 Discusses requirement that central & secondary alarm stations must have ability to take control of all electronic security sys in event of collusion by guards or takeover by intruders

  KIRK.W F. United Nuclear Corp., Naval Products Div 80/07/15 Spp

- B009100642 Responds to 800530 itr in response to IE Insp Rept 70-0371/80-05 & notice of violation Item of noncompliance remains MARTIN N Q Region 1. Philadelphia, Safeguards Stanch. 80/08/13.
- --8009100646 Forwards IE Insp Rept 70-0971/80-05 on 800401-03 & notice of violation Notice of violation withheld (ref 10CFR2 790).
  MARTIN.W G. Region 1. Philadelphia, Safeguards Branch. 80/05/09
- --G009100652 IE Insp Rept 70-0371/80-02 on 800401-03 Noncompliance netsf failure to properly store & tamper-wafe seal unattended SNM container & to maintain exit portal SNM detector in operable condition Details withheld (ref 100FR2 790) MADDEN.W Region i. Philadelphia, Office of the Director DEVLIN,J Region i. Philadelphia, Safeguards Branch. 80/05/07.
- 8009230416 Forwards IE Circular 80-20, "Changes in Bafe-Slab Tenk Dimensions" No written response required ORIER.B H Region 1, Philadelphia, Office of the Director. 80/08/21 4pp
- 8009230223 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Bys installed for govt use during emergency GRIERS BH Region 1. Philadelphia. Office of the Director 80/08/22 3pp

## DOCKET 70-0398 COMMERCE, DEPT OF

8009230421 Forwards IE Circular 80-20, "Changes in Safe-Sigh Tank Dimensions" No written response required GRIER H Region 1, Philadelphia, Office of the Director 80/08/21 4pp

#### DOCKET 70-0575 LEBANON VALLEY COLLEGE

8009140217 Discusses IE Insp Repts 70-0575/80-01 & 30-00895/80-01 on 800220 No noncompliance noted Major areas inspected actions taken to correct 750911 noncompliance HGCLINTOCHER OF Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/02/27 ip

#### DOCKET 70-0600 SEATTLE UNIV

8009120043 Forwards Reg Quide 5-59 to develop physical security plan.in response to 800717 conversation Plan must be submitted by 800831. M/o encl
MCCORKLE.O W Physical Security Development Branch 80/07/25 1p

## DOCKET 70-0687 UNION CARBIDE CORP

- 8009:20:39 Forwards Union Carbide routs w/revised guidance NUREQ-0561, reflecting latest amend to interim rule for physical protection of irradiated reactor fuel in transit Reguirements must be implemented by 800703 W/o encls, MCCORKLE.G M Physical Security Development Branch 80/07/07 ip
- 8009080489 Revises Amend MPP-3 to License SNM-639, Condition 2 i. & adds Condition 2.6 to require rept of first yr recovery date from U-waste form process operation PARTLOW, J G Material Control Licensing Branch 80/08/06.
- 8009100046 Ack receipt of 800729 ltr informing NRC of add1 steps taken to correct violations noted in IE insp rept. & payment of civil penalty STELLO.V Office of Inspection & Enforcement. Office of the Director 80/08/21.
- 8007230419 Forwards IE Circular 80~20, "Changes in Bafe-Slab Tank Dimensions " No written response required. GRIER-B H Region 1, Philadelphia, Office of the Director 80/08/21 App

#### DOCKET 70-0710 MERRIMACK COLLEGE

BOO9240044 Ack receipt of BO0125 & O724 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0710/79-01, 30-08305/79-01 KINNEMAN.J.D. Region I, Philadelphia, Fuel Facility & Materials Safety Branch BO/08/11 1p

- --9009240051 Responds to NRC 791204 ltr re violations noted in IE Insp Repts 70-0710/79-01 & 30-08305/79-01 Corrective action removal of sealed Pu-Be source Required surveys & tests conducted & records maintained re NRC regulations MCLAUGHLIN, J.P. Merrimack College 80/07/24 ip
- --B009240060 Notice of violation from insp on 791105-06 Noncompliance noted:failure to test Pu-Be source for contamination, to conduct & record required surveys w/OM survey meter & to maintain records of disposals of licensed matle a Region i, Philadelphia, Office of the Director 79/12/04. 2pp

#### DOCKET 70-0734 GENERAL ATOMIC CO

- 8007120646 Advises that 800506 request for approval to ship HTQR fuel is approved Forwards approved route & data re initial arrangements w/law enforcement agencies along route Encis withheld (ref 100FR2 790) MCCORKLE.Q.W Physical Security Licensing Branch 80/06/06 ip.
- 8009020254 Forwards IE Insp Rept 70-0734/80-05 on 800603-06 No noncompliance noted BDOK.H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/07/11 2pp
- --8004020261 IE Insp Rept 70-0734/80-08 on 800603-06 No moncompliance noted Major areas inspected organization, facility changes & mods: employee training: maint operations review & criticality safety COULEY. H. J. Region 5, San Francisco, Office of the Director. THOMAB. R. D. Region 4, Dallas, Office of the Director BOOK, H. E. Region 5, San Francisco, Fuel Facility & Materials Safety Branch. 80/07/11 Spp
- 8009170212 Discusses IC Insp Rept 70-0734/B0-07 conducted on 800714-18 No noncompliance noted Major ereas inspected program for centrolling & accounting for BNM per license requirements Rept withheld (ref 100FR2 790) NORDERHAUD, L. R Region 5, San Francisco, Bafaguards Branch 80/08/10 10
- 8009040896 PNO-V-80-064 on 800811, explosion of aluminum container of UC-ThC contaminated five suployees Explosion was caused by leakage of inerting gas or by reaction w/impurities Licensee has initiated investigation THOMAS,R.D. COOLEY,H.J. Region 5, Ban Francisco, Office of the Director, 80/08/11. 2pp
- 8009170209 Discusses IE Insp Rept 70-0734/80-08 conducted on 800728-0801. No noncompliance noted, Major areas inspected activities re-physical protection against industrial sabotage & against thaft of SNM Rept withheld (ref 10CFR2 790) MORDERHAUG, L. R. Region 5, San Francisco, Bafeguards Branch 80/08/20 2pp
- 3009230363 Forwards IE Circular 80-20, "Changes in Bafe-Blab Tank Bimensions " No written response required ENGELKEN,R M Region 5, San Francisco, Office of the Director 80/08/21, 4pp.
- BOO9160561 PNO-V-BO-064A updating rept of BO0811 explosion of centainer of UC-ThC. Nasal wipes indicate some internal apposition may have occurred Region 5 evaluation indicates no exposures in excess of IOCFR2O limits.

  THONAB.R D . COOLEY, N. J. Region 5, San Francisco, Office of the Director 80/08/22, 2pp
- 8009230334 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys Installed for govt use during emergency EMPELKEN.R.H Region 5. San Francisco. Office of the Director Bn/08/22 Spp
- DOCKET 70-0754 VALLECITOS NUCLEAR CENTER: GENERAL ELECTRIC CO
- 6009190751 Forwards proposed security plan. Plan withheld (ref 10GFR2 79D).

  MBSCHRER.R A., CUNNINGHAM.G.E. General Electric Co. 80/05/09. ip.
- 8009110225 Forwards confirmation of understanding re NRC interpretation of 10CFR73 discussed in 800617 telcon. Site licensed to passess BNM requiring physical security may passess & use less than 10w strategic significance amount w/o security CUNNINOHAM. O E General Electric Co 80/06/20. 1p

- 8009120149 Forwards QE route w/revised guidance NUREO-0561, reflecting latest amend to interim rule for physical protection of irradiated reactor fuel in transit Requirements shall be implemented by 800703 M/o encis MCCORKLE.Q W Physical Security Development Branch 80/07/07 ip
- 8007110227 Forwards administrative amend fee as requested in NRC 800708 Ltr CUNNINGHAM.9 E General Electric Co 80/07/15 ip
- --8009110246 Responds to 800620 ltr re use of SNM outside secured dreas License amend & administrative amens fee required Requests payment WEISS:D License Fee Management Branch 80/07/08 ip
- 8009120089 Forwards info requesting route approval of irradiated fuel samples shipment Immediate attention requested W/o encl KIRKLAND, M W General Electric Co 80/07/28 ip
- 8009110279 Forwards info requesting rouse approval of irradiated reactor fuel samples W/o encl KIRKLAND, M W General Electric Co 80/08/05 ip
- BOO7160235 Approves of 800330 request to amend License BNM-760, adding License Condition 1 1 % modifying License Condition 2.1 re fundamental nuclear matl control & accounting plan PARTLOW, J O Material Control Licensing Branch. 80/08/13 ip
- \*\*-8009160241 Amend MPP\*-2 to SNM\*-960, superseding all previous safegaurds amends. Adds License Condition 1.1 & modifies License Condition 2 1 re fundamental nuclear matl control & accounting program \*\* Material Control Licensing Branch 80/08/13 5pp.
- B009100741 Forwards TERA Corp repts. "Seismic Risk Analysis for GE Pu Facility, Pleasanton, CA: "Parts I & II. NRC has endorsed repts for application in succeeding analyses. Byc list encl RQUSE, L. C Advanced Fuel & Spent Fuel Licensing Branch B0/08/18
- ---H009100745 "Beismic Risk Analysis for GE Pu Facility Pleasanton, CA," Part I \* TERA Corp. 78/07/G1 57pp
- --8009100748 "Seismic Risk Analysis for GE Pu Facility, Pleasanton, CA " Part II \* TERA Corp 80/06/27 100pp
- 8009230370 Forwards IE Gircular 80-20. "Changes in Safe-Blab Tank Dimensions " No written response required ENGELKEN,R H Region 5, San Francisco. Office of the Director 80/08/21 4pg
- 8009180289 Forwards IE Insp Rept 70-0754/80-05 on 800218-19 No noncompliance noted Encl withheld (ref 10CFR2 790 )
  NORDERHAUG, L R Region 5, Sam Francisco, Safeguards Branch 80/08/29 ip

## DOCKET 70-0820 UNITED NUCLEAR CORP

- BOO7180927 Advises that present decommissioning plans include roundthe-clock operation, w/possibility of six to seven days/wk. Guardforce levels to be implemented on BOO707 BOMERS, C E United Nuclear Corp., UNC Recovery Systems Div BO/06/24 1p
- 8009110221 Informs of decision to terminate recovery of highly enriched U at facility Requests exemption from requirements contained in 100FR73, 20,73 45 & 73 46 BOWERS.C E United Nuclear Corp , UNC Recovery Systems Div. 80/06/26 2pp
- ---B009110249 Ack receipt of 800626 ltr re exemption from requirements of 100FR73 20,73 45 & 73 46 Request requires minor emend to license Minor safeguards amend fee required WEIBS,D License Fee Management Branch 80/07/08
- --B009110252 Forwards minor safeguards amend fee requested in NRC 80070B Itr Payment made under protest BOMERS, C E United Nuclear Corp , UNC Recovery Systems Div B0/07/18 2pp.
- 8009110235 Requests waste shipments to burial be exempted from 10CFR73 67(e) & (g) requirements Potential theft of U-235 minimal Fee payment made under protest BOMERS,C. E. United Nuclear Corp., UNC Recovery Systems Div 80/06/24 2pp

## DOCKETED ITEMS

- 009250334 Forwards IE Insp Rept 70-0820/80-08 on 800602-05 & notice of
- H. Region i, Philadelphia, Fuel Facility & Materials Safety 80/07/01 2pp
- 8009250335 Notice of violation from insp on 800602-05 \* Region (, Philadelphia, Fuel Facility & Materials Safety Branch 60/06/30 ip
- 8009250336 IE Insp Rept 70-0820/80-08 on 800602-05 Noncompliance noted failure to post nuclear criticality safety limit in warehouse for storage of fissile matl in inner containers from URC-2600 Shipping containers CROCKER.H W Region i, Philadelphia, Fuel Facility & Materials Safety Branch Kinner, W W Region i, Philadelphia, Office of the Director 80/06/30 lipp
- O9110267 Requests response to concerns raised by town of Charlestown, RI re contamination of groundwater by radwastes BEARD, E P House of Rep 80/07/02 2pp
- 99080444 FOIA request, on behalf of Concerned Citizens of RI, for four categories of Info re facility
  JORDAN, W. 8. Sheldon, Harmon & Weiss 80/07/23 3pp.
- J9220064 Submits questions on behalf of Concerned Citizens of RI rejurial of radwaste at plant site & presence of Sr-90 in soil w/or in storage or elsewhere JORDAN, H S Sheldon, Harmon & Weiss 80/07/23 4pp.
- 39120155 Responds to 800826 ltr Grants specific exception from BNK remsport requirements re-scrap for burial described in ltr ICCORKLE, G W Physical Security Development Branch 80/07/31 1p
- :9110230 Informs of engaging svcs of consultants Goldberg-Zoino & ssociates. Inc Consultants will evaluate info at facility & ill identify optimum placement & depth of test wall to best ategories contamination profile
  OMERS.C £ United Nuclear Corp , UNC Recovery Systems Div O/OB/06 1p
- 9170001 Forwards correspondence received or generated by Governor olicy Ofc re facility Viewpraphs from 800708 meeting enci ROW, W T Uranium Fuel Licensing Branch 80/08/14 6pp
- 309170002 Lists concerns of client, Concerned Citizens of RI re burial of radwaste & presence of 8r-90 at site JORDAN, V S Schiff, Hardin & Waite 80/07/23 4pp.
- JOP170005 Requests consideration in establishing realistic bactground radiation basis Excerpt from data taken in Apr 1963 encl BDNERBS,C E United Nuclear Corp UNC Recovery Systems Div. 20 p 80/07/09
- '230413 Forward: IE Circular BO-20, "Changes in Safe-Slab Tank mensions" No written response required IER.B H Region 1. Philadelphia, Office of the Director /08/21 4pp
- 080439 Responds to FOIA request on behalf of Concerned Citizens of for four categories of info re facility Documents are allable in PDR tofic of NMSS LTON.J M Division of Rules and Records 80/08/22. 2pp
- 230225 Requests that all personnel be reminded of purpose of argency notification sys & health physics network Sys stalled for govt use during emergency IER. 8 H Region i. Philadelphia. Office of the Director /08/22 3pp
- 110294 PNO-I-80-124: water samples taken from test wells close to fluent waste lagoons have shown presence of radionuctides withly samples from test wells indicate byproduct matl lionuctides (NEY,W H . CROCKER,H H . SMITH,G H Region 1. Philadelphia, Office the Director 80/08/28 2pp
- T 70-0824 BARCOCK & WILCOX CD
- 30388 Forwards IE Circular 80-20. "Changes in Safe-Slab Tank ensions " No written response required
  EiLLY, J P Region 2, Atlanta, Office of the Director. 80/08/21.

- 8009230277 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Bys installed for gott use during emergency O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/08/R2
- 8009110667 Responds to IE Bulletin 80-19. Emergency notification systested during site power trip on 800705 Each unit tested & no difficulties were noted OLSEN, A F Babcock & Wilcox Co 80/08/27 2pp
- DOCKET 70-0925 CIMMARON FACILITY, KERR-MCGEE CORP
- 8009150233 Submits info in response to IE Bulletin 80-15. Emergency notification sys determined to be powered by onsits power instead of by local telephone company Equipment will be relocated for power backup to safeguard instrumentation bus.

  SHELLEY, W J Kerr-McGee Nuclear Corp 80/08/20 2pp.
- 8009230380 Forwards IE Circular 80-20, "Changes in Safe-81ab Tank Dimensions" No written response required. KEPPLER, J G Region 3, Chicago, Office of the Director 80/08/21
- 8009230280 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency.

  KEPPLER, J G Region 3. Chicago, Office of the Director 80/08/22.
- DOCKET 70-0959 NUCLEAR FUEL SERVICES, INC . (SUBS OF DETTY OIL CO )
- 8009230215 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency ORIER. B H. Region i. Philadelphia. Office of the Director. 80/08/22 3pp
- DOCKET 70-0984 PACIFIC NORTHWEST LAS
- 8009020235 Forwards IE Insp Rept 70-0784/80-01 on 800424-25 No noncompliance noted 800K.H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/07/16 2pp 2pp
- --8009020237 IE Insp Rept 70-0984/80-01 on 800424-25, No noncompliance noted Major areas inspected internal review & audit, employee training, criticality safety & radioactive waste mgt. COLEY, W.J. TROMAS, R.D. Region 5, San Francisco, Office of the Director 800K, M.E. Region 5, San Francisco, Fuel Facility & Materials Safety Branch. 80/07/14 4pp.
- 8009230375 Forwards IE Circular 80-20, "Changes in Bafe-Slab Tank Dimensions" No written response required SNOELKEN, R H Region 5, Ban Francisco, Office of the Director. 80/08/21 4pp
- 8009230329 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency ENGELKEN,R H Region 5. San Francisco. Office of the Director.
- DOCKET 70-1007 GENERAL ELECTRIC CO
- 8009180509 Requests amend to Conditions 34 & 35 of License BNM-54 CUNNINGHAM: G E. General Electric Co 80/06/27 2pp.
- 8009230370 Forwards IE Circular 80-20, "Changes in Bafe-Blab Tank Dimensions "No written response required ENGELKEN,R H Region 5, San Francisco: Office of the Director 80/08/21 4pp
- DOCKET 70-1097 GENERAL ELECTRIC CO.
- 8009230396 Forwards IE Circular 80-20, "Changes in Safe-Slab Tank Dimensions "No written response required.

  O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/21.

## DOCKET 70-1100 COMBUSTION ENGINEERING. INC.

- BOOP15002B Application for review of reviewd Saction 5 1.inventory requirements, of fundamental nuclear mati control plan for License SNf-1067 Plan is being forwarded under separate cover.
  LICHTENBERGER C-E Power Systems 80/06/17 ip
- GCO9110706 Informs NRC that quarterly reporting requirement for 1980 second quarter was exceeded as result of absolute filter change in FA-4 ventilation sys Caused by failure to replace filters in tight-sealing configuration

  LICHTENBERGER Combustion Engineering, Inc. 80/07/10 2pp
- 8009160136 Act receipt of 800710 ltr reporting incident during du0624 MEPA filter installation, resulting in minor release of radioactivity into environ Corrective actions will be raviewed CUMMINGHAM, R.E. Division of Fuel Cycle & Material Safety 80/08/06.
- B009230405 Forwards IE Circular 80-20, "Changes in Safe-Slab Tank Dimensions." No written response required. ORIER.B H. Region I. Philadelphia, Office of the Director B0/08/21 4pp

#### DOCKET 70-1113 GENERAL ELECTRIC CO

- 8007070866 Application for Amend 8-19 to License SNM-1097, authorizing exclusion of review & audit required by iOCFR70 97(b)(3) for DDE or Nati Labs Details withheld (ref 10CFR2 790) KAPLAN,A.L. General Electric Co , Nuclear Energy Products Div 80/06/ii. ip
- BOOQ190111 Requests amend to License BNM-1097 to construct warehouse bidg on plant site Details encl KAPLAN.A.L. General Electric Co., Nuclear Energy Products Div BO/06/11 4pp
- 8009240312 Discusses environ assessment for facility mods Forwards questions re conversion plant expansion, incinerator replacement & environ rept SPAETH.M.E. Beience Applications, Inc. 80/07/21 12pp.
- 8009170242 Responds to 800611 ltr re application for Amend N-8, proposing warehouse bldg const Prior to bldg use, fundamental nuclear mat1 control plan must be modified.
  PARTLOW J C. Material Control Licensing Branch. 60/08/12 ip.
- B009100290 Forwards IE Insp Rept 70-1113/80-13 on 800811-13. No noncompliance noted.

  KENRA, M B Region 2. Atlanta, Safsguards Branch 80/08/20. 2pp
- BOO9110126 Ack receipt of 800815 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1113/80-10 KENNA, W B. Region 2. Atlanta, Safeguards Branch. 80/08/27 ip.
- --B009110156 Forwards in insp Rept 70-1113/80-10 on B00623-27 & notice of violation. KENNAL B. Region 2. Atlanta, Bafeguards Branch. B0/07/17. 2pp.
- --BOC9110153 Notice of violation from inep on 800623-27

  a Region 2. Atlanta, Office of the Director. 80/07/16 ip.
- --8009110150 IE Insp Rept 70-1113/80-10 on 800623-27. Noncompliance noted: failure to keep fuel rod cabinet doors closed when unattended. KAHLE.J.B., KENNA, W. B., Region 2, Atlanta, Safeguerds Branch. 80/07/16 6pp
- BOOT150601 Ack receipt of 800821 ltr forwarding IE Insp Rept 70-1113/80-12 KAPLAN.A.L. General Electric Co , Nuclear Energy Products Div BO/08/28. 1p.

- --8009150604 Forwards 1E insp Rept 70-1113/80-12 on 800811 No noncompliance noted KENNA W B Region 2, Atlanta, Bafeguards Branch. 80/08/21 2pp
- --8009150605 IE Insp Rept 70-1113/80-12 on 800811 No noncompliance noted Major areas inspected license conditions & storage procedures KARLE, J. B. Region 2, Atlanta, Safeguards Branch CORYELL, 9 P. Region 2, Atlanta, Office of the Director 80/08/21 3pp
- 8009260525 Forwards request for add1 environ info re license amend application on installation & use of incinerator & major plant expansion Response should be submitted by 800922 SHUM.E Y Uranium Fuel Licensing Branch 80/09/15 7pg

### DOCKET 70-1120 WESTINGHOUSE ELECTRIC CO

- 8009030046 Advises that procedures for decommissioning activities must be submitted & approved by NRC before any shipments can be made PARTIGULIO Material Control Licensing Branch F0/09/06 to
- DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP
- 9009100187 Forwards application for amend to License BNH-1120, adding encl description for decontaminating & decommissioning glove boxes
  DIPIAZA, R P Westinghouse Electric Corp. 80/06/12 Spp
- ---B009100193 Application for amend to License BNM-1120, describing steps for decontaminating & decommissioning glove boxes. \* Westinghouse Electric Corp. 80/06/12 21pp
- 8009230169 Forwards marked-up fraft fundamental nuclear matl control plan for decommissioning activities & fraft proposed license conditions re measurement control Lists suggested revisions for control plan W/o encls
  PARTLOW, J. G. Material Control Licensing Branch. B0/07/23 1p
- BOD9150360 Amends License BNM-1120, adding License Condition 5.3 retemporary storage of contaminated equipment in temper-safe containers at estimated BNM values, in response to B00709 request.

  PARTLOW, J 0 Material Control Licensing Branch. 80/08/06 ip
- 8009230406 Forwards IE Circular 80-20, "Changes in Safe-Slab Tank Dimensions" No written response required ORIER, DH Region 1. Philadelphia, Office of the Director. 80/08/21 App
- 8009230228 Requests that all personnel be reminded of purpose of emergency notification sys & health physics network Sys installed for govt use during emergency ORIER, B H Region 1, Philadelphia, Office of the Director 80/08/22. Spp

## DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP

- 8007100681 Approves 800624 request for withholding proprietary pages of application for amend Pages contain trade secrets, confidential or commercial info CUNNINGKAM.R.E Division of Fuel Cycle & Material Sefety 80/08/11.
- 8009170079 Advises that 1:200 lb of molybdenum scrap described in 800329 ltr may be released for unrestricted use. PAGE.R 0 Uranium Fuel Licensing Branch. 80/08/il 1p.
- 8009050173 Forwards IE Insp Rept 70-1151/80-19 on 800721-22 No noncompliance noted MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/08/12 2pp
- --B009050176 IE Insp Rept 70-1151/80-19 on 800721-22.No noncompliance noted Major areas inspected fire protection/prevention.
  MILLER.W.H. Region 2: Atlanta. Office of the Director.
  CONCONT E. Region 2: Atlanta. Reactor Construction & Engineering Support Branch. 80/08/12 5pp

- 8009230397 Forwards IE Circular 80-20, "Changes in Safe-Slab Tank Dimensions" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/21 Ann
- 8009110122 Ack recaipt of 800811 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1151/80-18
  KENNA<sub>C</sub>H 8 Region 2, Atlanta Safeguards Branch 80/09/27 lp
- --B009110138 Responds to NRC B00728 ltr re violations noted in IE Insp Rept 70-1151/80-18 Corrective actions withheld (ref 10CFR2.790) G00DHIN.H L , D"AMGRE.M Westinghouse Electric Corp 80/00/11
- --8009110139 Forwards JE Insp Rept 70-1151/80-18 on 800624-26 & notice of violation Notice of violation withheld (ref 10CFR2 790)
  KENNA.W B Region 2, Atlanta, Safeguards Branch 80/07/28 2pp
- --8009110142 IE Insp Rept 70-1151/80-18 on R00624-26 Noncompliance noted failure to establish adequate inventory procedures Details withheld (raf 10CFR2 790)
  TODD,0 A Region 2, Atlanta, Diffice of the Director, GILLESPIE,F P Region 2, Atlanta, Safeguards Branch 80/07/28
- 9009250062 Forwards IE Insp Rept 70-1131/80-24 on 800812-14 No noncompliance noted KENNA-N B, Region 2, Atlanta, Safeguards Branch 80/08/29, 2pp
- --8009250066 IE Insp Rept 70-1151/80-24 on 800812-14 No noncompliance noted Major areas inspected facility organization matl control measurements.physical inventory & matl control Details withheld (ref 100FR2 790) GILLESPIE.F P Region 2. Atlanta, Safeguards Branch. JONES, D. W. Region 2. Atlanta, Office of the Director 80/08/29 ig.
- 8009250464 Amend 6 to License SNM-1107, authorizing use of SNM in advanced waste treatment process PAGE:R O Uranium Fuel Licensing Branch 80/09/11 4pp.
- --8009250470 Refety evaluation re 800407 & 0624 applications to authorize operation of advanced weste treatment process Concludes that U recovery operations can be conducted w/o undue risks to public & personnel health & sefety Recommends approval SEEVENSON.R L . CROW.R T Uranium Fuel Licensing Branch 80/09/11 3pp
- DOCKET 70-1167 NORTHWESTERN OKLAHOMA STATE UNIV
- 8009260389 Forwards IE Bulletin 79-19, "Packaging of Low Level Radwaste for Transport & Burial " Response required SEYRIT, K V Region 4, Dallas, Office of the Director 79/08/10, ip
- --B009260416 Responds to IE Bulletin. "Packaging of Low Level Radwaste for Transport & Burial " Licensee reminded of written response requirement. • Northwestern Oklahoma State Univ. 79/11/01 1p
- --8009260419 Responds to IE Bulletin 79-19, "Packaging of Low Level Radwaste for Transport & Burial" No radwaste generated BRDWG K H Northwestern Okiahoma State Univ. 79/11/07 ip
- DOCKET 70-1193 CIMARRON FACILITY, KERR-MCGEE CORP
- 8009150233 Submits info in response to IE Bulletin 80-15 Emergency notification sys determined to be powered by onsite power instead of by local telephone company. Equipment will be relocated for power backup to safeguard instrumentation bus SMELLEY, W. J. Kerr-McGes Nuclear Corp. 80/08/20. 2pp
- B009230380 Forwards IE Circular 80-20, "Changes in Safe-Slab Tank Dimensions " No written response required KEPPLER. J G Region 3, Chicago, Office of the Director, 80/08/21. 4pp
- 8007230280 Requests that all personnel be reminded of purgose of emergency notification sys & health physics network. Sys installed for govt use during emergency KEPLER, J. O Region 3. Chicago, Office of the Director. 80/08/22 3pp
- 8009190760 Requests amend fee re 800821 NRC granting of specific esymption from requirements of upgrade rule for Category I SNM WEISS.D License Fee Management Branch 80/09/03. ip

- DOCKET 70-1201 UF & CONVERSION FACILITY. BABCOCK & WILCOX CO
- 8009030004 Application for amend to License 8NM-116B revising action levels for air effluent releases to unrestricted areas & isolation criteria between fuel assembly storage array & shipping container loading area # Babcock & Hilcox Co. 80/06/12, 10pp
- 8009090874 Application to amend SNM-1168, authorizing storage of SNM over 12 months w/measurement uncertainties greater than 10% & limited use of nonrepresentative stds Attachments withheld (ref 10CFR2 790)

  ZEFF, D W Owneral Electric Co 80/06/26 ip.
- BO09180517 Forwards fundamental nuclear mati control plan for NRC approval Plan submitted as Revision O, including revised table of contents & page-date index Plan withheld (ref 100FR2 790)
  ZEFF.D W Babcock & Wilcox Co. 80/07/15. 1p
- B009230457 Ferwards gaseous effluent monitoring results for Jan-June 1980 . ZEFF,D.H Babcock & Wilcox Co 80/08/20 2pp.
- 8009230398 Forwards IE Circular 80-20, "Changes in Safe-Slab Tank Dimensions." No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 90/08/21
- 8009290266 Informs that review of fundamental nuclear math control plants complete Recommends deleting License Conditions 1.1.2 4, 2.5.3 i.4.2.5 3,6 1.6.2.7 i & 8 i & adding License Condition 7 3 re tamper-waafing.

  PARTLOW, J O Physical Security Licensing Branch 80/09/09. 1p.
- DOCKET 70-1220 GENERAL ELECTRIC CO
- 8009230383 Forwards IE Circular 80-20, "Changes in Gafe-Blab Tank Dimensions" No written response required KEPPLER.J O. Region 3. Chicago, Office of the Director. 80/08/21 400
- DOCKET 70-1257 MIXED OXIDE FABRICATION PLANT, EXXON NUCLEAR CO., INC.
- 8009040473 Forwards upgraded & clarified revisions to SNH-1227 license renewal application. ESTEV.H P. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 80/06/05 Rpp
- --8009040475 Application for amend to 8NM-1227, authorizing activity of mechanical operations involving recovery of U from solid wastes

  \* Exxon Nuclear Co., Inc. (subs. of Exxon Corp.), 80/08/05
- 8009110278 Application to amend license to require only single storage stage HEPA filtration of skhaust air from U processing facilities Amended Table 3 3-1 k Figure 2.3-2 and ESTEY, H. P. Exxon Nuclear Co , Inc (subs of Exxon Corp.). 80/06/19 3pp.
- 8009110718 Application to amend License SNM-1227, authorizing increase in possession limit of SNM in form of enriched U from 10 to 35 g
  ETSEY, H P Exxon Nuclear Co , Inc (subs. of Exxon Corp.), 80/06/27. ip
- 8009160523 Responds to IE Bulletin 80-15, "Possible Loss of Emergency Notification Sign (ENB) w/Loss of Offsite Power." ENB equipment located at General Telephone Co North Richland Central Ofc physically inspected on 800624 ESTEV. H P Exxon Nuclear Co , Inc (subs. of Exxon Corp.) 80/07/07 Spp
- 8009100232 Forwards "Risk Analysis for Postulated Pu Releases From Erxon Nuclear Mixed Oxide Fuel Plant as Result of High Winds & Earthquetes." Recommends review & conclusions be adopted as staff position subj to approval. AVER, J E . BURKHARDT, W. Advanced Fuel & Spent Fuel Licensing Branch. 80/08/14 1p.
- --8009100235 Bubmits NRC approved final increment of analysis of effects of natural phenomena re mixed oxide fuel operations at Richland, MA ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch 60/08/14

- --B00910023B "Risk Analysis of Postulated Pu Releases From Exxon Nuclear Mized Oxide Fuel Plant As Result of High Winds & Earthquates " # Probabilistic Analysis Staff 80/08/14 29pp
- 8009150399 Requests review of procedures for SNM accounting determination re changes required to solve problems listed & revision of fundamental nuclear math control plan to facilitate incorporation of addl procedures PARTLOW, J Q Material Control Licensing Branch 80/08/14 2pp
- 8007230367 Forwards IE Circular 80-20, "Changes in Safe-Blab Tank Dimensions." No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/08/21 4pp
- 8009230332 Requests that all personnel be reminded of purpose of amergency notification sys & health physics network Sys installed for govt use during emergency EMPELKEN,R H. Region 5. San Francisco, Office of the Director, 80/08/22 Spp
- 8009250472 Forwards revised License SNM-1227 & safety evaluation rept PAGE.R 0 Uranium Fuel Licensing Branch 60/09/10 ip
- ---B009250476 Revised License SNM-1227, authorizing possession & use of 10,000 kg contained U-235,100 kg Pu in sealed sources & up to 100 kg Pu oxide or Pu oxide-U oxide in encapsulated fuel rods or NRC approved containers
  FAOE.R. 9. Uranium Fuel Licensing Branch 80/09/10 2pp
- DOCKET 70-1908 HORRIS OPERATIONS, GENERAL ELECTRIC CO
- 8007110488 Ferwards info re ages & average burnup of fuel presently in storage in response to 800630 telcon & request by T Clark. DAMSON, D M General Electric Co 80/07/01 3pp
- 8009120543 Summary of 800610 meeting w/OE re 800123 request for amend to License 8MM-1265 CLARK.A T Advanced Fuel & Spent Fuel Licensing Branch 80/07/09
- B009080431 FOIA request for documents re possible purchase, lease or condemnation of facility by federal govt
  MILLER.M E Mudge, Rose, Guthrie & Alexander 80/07/18, 2pp.
- 8009050409 Requests that date referenced in revised amend request be changed to 800123 from 800118 DAMBON,D M. General Electric Co 80/07/18 2pp
- 8009150408 Forwards 780010 memo ra meeting between Southwest Muclear Co & NRC.as followup to 800804 telcon EMPBON,F M. Advanced Fuel & Spent Fuel Licensing Branch 80/08/06
- --8009180412 Summary of meeting w/Southwest Nuclear Co re use of Carey Salt Mine in Lyons KS for low level waste disposal. Lyons Chamber of Commerce 780327 ltr & sketch of receiving area JOHNBON, T. C. High Level Waste Technical Development Branch. 78/08/10. Sep
- ROOPOSO445 Add1 response to FOIA request for documents re possible purchase, lease or confernation of facility by federal govt Forwards documents listed in App A. FELTOW, J. H. Division of Rules and Records 80/08/11 2pp.
- 8009270070 Forwards IE Insp Rept 70-1308/80-04 on 800727-0801. No noncempliance noted

  DAVIS, A B. Region 3, Chicago, Fuel Facility & Materials Bafety 80/08/18.
- -8009290094 IE Insp Rept 70-1308/80-04 on 900729-0801. No noncompliance workhouth is imp mept /0-1308/80-04 on 900729-0801. No nonco-noted. Major areas inspected, fuel receipt & storage.external exposure control respiratory protection & bioassay program PECK.C.C. Region 3, Chicago, Office of the Director FIBM Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/08/13, opp. FISHER, W.L.
- 8009230383 Fu. savés IE Circular 80-20. "Changes in Bafe-Slab Tank Dimensions " No written response required KEPFLER J. Q. Region 3. Chicago, Office of the Director. 80/08/21.

- 800703057B Forwards revised description of compressed air sys Only few changes necessary to adapt description to current configuration of sys, per 800716 telcon DAWBON, D ti General Electric Co 80/08/25 4pp
- 8009170078 Requests assistance in evaluation of contentions admitted by ASLB re renewal of GE License 8NM-1265 for storage of irradiated LWR fuel & in preparation of testimony for ASLB hearing RDUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch 80/08/27
- B0091700B3 Requests assistance in evaluation of contentions admitted by ASLB re renewal of GE License SNN-1265 for storage of irradiated LWR fuel & in preparation of testimony for ASLB ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch 80/08/27
- 8009170086 Requests assistance in evaluation of contentions admitted by ABLB re renewal of OE License SRM-1265 for storage of irradiated LWR fuel & in preparation of testimony for ASLB hearing ROUSE, L C Advanced Fuel & Scent Fuel Licensing Branch 80/08/27
- 8009080033 Advises that NRC does not intend to respond to applicant 800819 motion to compel State of IL answers to 800804 discovery requests ROTHSCHILD, M U. He Hearing Branch 1 80/09/04
- 8009100325 Informs that deposition of DM Dawson re license renewal will begin in Chicago on 800912 Related correspondence. RODNEY, M A Mayer, Brown & Platt 80/09/04 1p
- 8009090461 Advises that responses to GE 800814 motion to compel discovery against Rorem due 800829 GE believes motion to be complete: since no response has been received Also believes that ASLB is ready to rule Related correspondence ROONEY, H A Mayer, Brown & Platt 80/09/05 2pp
- 8007110015 Advises that NRC will attend & examine at DM Dawson 800712 deposition in Chicago, IL per 800704 telcon during which no objection was stated BACHMANN.R O Rulemaking & Enforcement Division 80/09/07. ip
- 8009120022 Order advising BL Rorem, et al to respond to applicant & NRC interrogatories by 800930 Motions for summary disposition shall be filed by parties by 801020 & subsequent responses by 801110
  QCODHOPE, A. C. Atomic Safety and Licensing Board Panel 80/09/09
- 8009140403 Requests AT Clark & FD Fisher for depositions in Chicago, IL on 801001 AT Clark deposition will concern present facility operation, licensing application & planned operation, Fisher will be deposed re Contentions 4-6 SEKULER, & N Illinois, State of 80/09/10 1p
- 8009160394 Discusses OE 800819 motion to comps) discovery against State of IL No response was received from State of IL by 800903 Record re motion is complete & ready for ruling by Board ROCKEY.H A Mayer Brown & Platt. 80/09/11. ip.
- B009230044 Advises that AT Clark & FD Fisher will be available for BOIOOI deposition at NRC afes in Hashington, DC rather than Atty Ceneral ofc in Chicago, IL ROTHSCHILD, N U Hearing Branch 1 BO/09/19 ip.
- 8009300580 Forwards GE 800917 ltr & Revision 5 to NEBD-2077&, "Spent Fuel Sycs Operation GA Plan" Related correspondence RDDNEY, M A Mayer, Brown & Platt. B0/09/24 2pp.
- --8009300585 Forwards Revision 5 to NEDO-20776, "Spent Fuel Svcs Operation GA Plan," Svc list encl.
  DAWSON.D M General Electric Co. BO/09/17. 2pp.
- --8009300586 Revision 5. "Spent Fuel 8vcs Operation GA Plan" \* Operal Electric Co NEOD-20776 R5. 80/07/15 10pp
- B00930001B Advises of B00919 approval of new 100FR72, "Licensing Requirements for Storage of Spent Fuel in Independent Spent Fuel Btorage Installations "Regulation will be provided upon Issuance & publication of final form

- 8009300049 Anticipates delay in issuance of NRC safety evaluation due to Commission approval of iOCFR/2 for which add1 info & review are required firm issuance date will be provided when established BACHMANN.R Q Rulemaking & Enforcement Division 80/09/26 1p.
- DOCKET 70-1309 MORRIS OPERATIONS, SOURCES & STANDARDS, GENERAL
- 8009230383 Forwards IE Circular 80-20, "Changes in Safe-Slab Tank Dimensions " No written response required. KEPPLER, J. G. Ragion 3, Chicago, Office of the Director 80/08/21
- DOCKET 70-1327 UF & CONVERSION FACILITY. ALLIED GENERAL NUCLEAR
- 8009170346 Comments on relemating 50-5 re mixed oxide fuel GESMO & other recycle-related licensing proceedings should continue Positive affirmative action to approve licenses recommended KIRR/W F William F Kirk BO/08/28 4pp
- 8009100490 Comments on RM 50-5 public should be advised of advantages & dissadvantages of implementing Pu recycle NRC should not have terminated efforts on GESMO fuels
  DECHER.U Affiliation Uninown 80/09/03 ip
- 8009160224 Requests GESMO re fueld be completed Info is needed for future decisions re reprocessing of spent nuclear fuel VILLEMY.0 R Affiliation Unknown 80/09/08 ip
- 8009160420 Comments on rulemaking 50-5-0ESMO proceedings should be reopened to provide early procedural framework for subsequent licensing RICKARDS,R B General Electric Co 80/09/08 2pp
- 8009300514 Expresses concern re reopening of OEBMO & other related licensing proceedings for reprocessing sites.
  FEIG.D Affiliation Unknown 80/09/13 ip
- 8009220226 Comments on rulemaking 50-5 GESMO proceedings should be respensed Technical economic & safety issues must be addressed in order for decisions to be made re use of mixed-oxide fuels
  WEITZBERG, A Affiliation Uninown 80/09/15 ip.
- 8009260641 Urgss resumption of GESHO hearings BOLON: A. E. Affiliation Unknown 80/09/16 1p.
- --8007260646 Opposes reapening of GESMO hearings BURRELL:A Affiliation Unknown 80/09/13 is
- --8009260652 Urges reopening GESMO & recycle-related proceedings & consideration of expanding scope to include recycle of LWR fuel in breader reactors

  MCCRMACK.M House of Rep. 80/09/22 2gp
- 8009300525 Forwards comments in response to Commission 800807 order reterminated 0ESMO proceedings Reopening would be inimical to nati security & defense & at odds w/nonproliferation objectives
  BIALIK.E. I New York, State of 80/09/23 7pp
- 8009300540 Comments on reopening of QESMO proceedings Add1 use of nuclear generated electricity should be paced to preserve significant quantities of hydrocarbon reserves for use as raw matts in future chemical mfg BURRIS
- 8009300549 Request extension of time for comment on Commission 800B07 order re reopening 6ESMO proceeding HOLDEN,R.B. Allied Ceneral Nuclear Services 80/09/23 ip
- 8009300361 Supports respening of DESMO & other recycling license proceedings
  PRICE-JE Affiliation Unknown 80/09/23 ip

## DUCKET 70-1349 HUSPITAL PAVIA

8009260274 Forwards IE Circular 80-19, "Noncompliance W/License Requirements for Medical Licensees " No written response required O'REILLY, J.P. Ragion 2, Atlanta, Office of the Director. 80/08/26 is.

- DOCKET 70-1377 HANNA MINING CO
- 8009300606 Discusses IE insp of Licenses 22-05587-01, 22-015755-01, SNM-1353, SNM-1841, SNM-1864 on 800814-15 & forwards notice of violation DAVIS, A B Region 3. Chicago, Fuel Facility & Materials Safety Branch. 80/09/02 2pp
- --8009300611 Notice of vigilation from insp on 800814-15 Noncompliance noted physical inventories not being performed as required.

  \* Region 3, Chicago, Office of the Director 80/09/02, 1p

#### DOCKET 70-1397 ST MARY'S HOSP RICHHOND, VA

8009260317 Forwards IE Circular 80-19, "Noncompliance H/License Requirements for Medical Licensees" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/26

#### DOCKET 70-1401 VET ADMIN, HOSP DALLAB, TX

- 8009100362 Forwards IE Circular 80-19, "Noncompliance W/License Requirements for Medical Licensees " No written response required SEYFRIY.K V Region 4, Dallas, Office of the Director 80/08/26.
- DOCKET 70-1417 GREATER SOUTHEAST COMMUNITY HOSP WASHINGTON, D. C.
- 8009230142 Ack receipt of 800710 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-01334/80-01 k 70-1417/80-01 k RINNEMANJ B Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/07/30 ip
- --B009230147 Responds to NRC 800708 telcon re violations noted in IE In:
  Repts 30-01334/80-01 & 70-1417/80-01. Corrective actions:
  personnel will use syrings shields
  RRBINBON, CR Oreater Southeast Community Hosp Washington, D. C.
  80/07/10 ip
- ---8009230150 Discusses IE Insp Repts 30-01334/80-01 & 70-1417/80-01 en 800312 & forwards notice of violation GROCKER.H W Region 1, Philadelphia, Fuel Facility & Materials Bafety Branch. 80/03/31 2pp
- ---8009230152 Notice of violation from insp on 800312 Noncompliance note: individuals prepared patient doses in mCi quantities w/o using syringe shields \*\* Region i. Philadelphia, Office of the Director. 80/03/31 Ip
- DOCKET 70-1432 RECYCLE FUELS PLANT, WESTINGHOUSE ELECTRIC CORP.
- 8007170366 Comments on rulemaking 30-5 re mixed oxide fuel, OEBMO & other recycle-related licensing proceedings should continue. Positive affirmative action to approve licenses recommended KIRK-W F William F Kirk 80/08/28 4pp
- 8009100490 Comments on RM 50-3 public should be advised of advantages & disadvantages of implementing Pu recycle NRC should not have terminated efforts on GEBMO fuels
  DECHER.U. Affiliation Unknown. 80/09/03. ip
- 8009160224 Requests GESMO re fuel be completed. Info is needed for future decisions re reprocessing of spent nuclear fuel VILLEMY. 8.R Affiliation Unknown. 80/09/08 ip
- 8009i60420 Comments on rulemaking 50-5:0E8MO proceedings should be reopened to provide early procedural framework for subsequent licensing.
  RICHARDS, R.B General Electric Co. 80/09/08 2pp.
- 8009300514 Expresses concern re reopening of QESMO & other related licensing proceedings for reprocessing sites FEIG.D Affiliation Unknown 80/09/13. 1p.
- 8007220226 Comments on rulemaking 50-5 GEBMD proceedings should be reopened Technical, economic & safety issues must be addressed in order for decisions to be made re use of mixed-oxide fuels
  WEITZDERO, A Affiliation Unknown 80/07/15. ip

- BOG9260641 Urges resumption of GESMO hearings
  RDLON: A E Affiliation Unknown 80/09/16 ip
- --9009260646 Opposes reopening of GESMO hearings BURRELL, A Affiliation Unknown 80/09/13
- --8009260652 Urges reopening GEBMO & recycle-related proceedings & consideration of expanding scope to include recycle of LHR fuel in breader reactors MCCORMACK, M House of Rep 80/09/22 2pp
- 9009390525 Forwards comments in response to Commission 800807 order reterminated GESMO proceedings Reopening would be inimical to natl security & defense & at odds w/nonproliferation objectives.

  BIALIK, E. I. New York, State of 80/09/23 7pp
- 8009300540 Comments on respensing of CESMO proceedings Addl use of nuclear generated electricity should be paced to preserve significant quantities of hydrocarbon reserves for use as raw matts in future chemical mg BURRIS, L. American Institute of Chemical Engineers 60/09/23. 2pp
- B009300549 Request extension of time for comment on Commission 800807 order re reopening GEGMO proceeding MOLDEN.R B Allied General Nuclear Services 80/09/23 ip
- 8009200561 Supports reopening of OESMO & other recycling license proceedings.
  PRICE, J E Affiliation Unknown 80/09/23 ip
- DOCKET 70-1470 VET ADMIN, HOSP LOS ANGELES, CA
- 8009260311 Forwards IE Circular 80-19. "Noncompliance W/License Requirements for Hadical Licensees " No written response required ENOELHEN, R H Region 5. San Francisco, Office of the Director 80/88/24 10
- DOCKET 70-1729 FUEL REC & STOR STA . ALLIED GENERAL NUCLEAR SERVICES
- 8009230038 Responds to 800918 ltr directed to T Engelhardt, Every effort will be made to advise of development of facility use as away-from-reactor storage unit.
  MCGURREN.H. J Hearing Branch 1 80/09/19 2pp
- DOCKET 70-1738 PACIFIC GAS & ELECTRIC CO
- 8009020107 Requests renewal of Licenses SNM-1503 & SNM-1667, extending application date to 801231 Addl time necessary to complete facility licensing process SNACHELFORD.B. Pacific Oas & Electric Co 80/06/25 ip
- DOCKET 70-1739 TRI-STATE MOTOR TRANSIT CO
- 8009150545 Discusses IE Insp Rept 70-1739/80-02 conducted on 800616-18 & 20-25. No noncompliance noted Major areas inspected activities re physical protection against industrial sabotage & theft of SNM Rept withheld (ref 100FR2,790) NORDERHAUG, L. R. Region 5, Ban Francisco, Safeguards Branch, 80/08/20 2pp.
- DOCKET 70-1821 PLUT PROD FACIL. . ALLIED GENERAL NUCLEAR BERVICES CORP.
- 8009170366 Comments on rulemaking 50-5 re mixed oxide fuel.GESMD & other recycle-related licensing proceedings should continue Positive affirmative action to approve licenses recommended KIRK-M.F. William F. Kirk 80/08/28. 4pp
- 8009100490 Comments on RM 50-5.public should be advised of advantages & disadvantages of implementing Pu recycle NRC should not have terminated efforts on GEBMO fuels
  DECHER.U. Affiliation Unknown. 80/09/03, ip.
- 8009160224 Requests GEBMO re fuel be completed Info is needed for future decisions re reprocessing of spent nuclear fuel VILLEMY, G.R. Affiliation Unknown. 80/09/08, ip.
- 8009160420 Comments on rulemaking 80-5 QESMO proceedings should be respensed to provide early procedural framswork for subsequent licensing.
  RICHARDS.R.B. General Electric Co 80/09/08 2pp.

- 8009300514 Expresses concern re reopening of GERMO & other related licensing proceedings for reprocessing sites FEIG.D Affiliation Unknown 80/09/13 1p
- 8009220296 Comments on rulemaking 50-5 GEBMO proceedings should be reopened Technical, aconomic & safety issues must be addressed in order for decisions to be made re use of mixed-oxide fuels
  WEITZBERO, A Affiliation Unknown BO/09/15 1p
- 8009260641 Urges resumption of GESMD hearings BGLON, A E Affiliation Unknown 80/09/16 1p
- --8009260646 Opposes respening of GESMO hearings BURRELL-A Affiliation Unknown 80/09/13 1p
- --8009260652 Urges reapening GEBMO & recycle-related proceedings & consideration of expanding scope to include recycle of LHR fuel in breeder reactors
  MCCORMACK.M House of Rep 80/09/22 2pp
- 8009300525 Forwards comments in response to Commission 800807 order re terminated GESMO proceedings Reopening would be inimical to matl security & defense & at odds w/nonproliferation objectives BIALIK.E I New York, State of 80/09/23 7pp
- 8009300840 Comments on reopening of CESMO proceedings Addl use of nuclear generated electricity should be paced to preserve significant quantities of hydrocarbon reserves for use as raw matts in future chemical mfg
  BURRIB.L American Institute of Chemical Engineers. 80/09/23 2pp.
- 8009300549 Request extension of time for comment on Commission 800807 order re reopening GESMO proceeding HOLDEN.R. 8 Allied General Nuclear Services 80/09/23 1p
- 8009300541 Supports reopening of OESMO & other recycling license proceedings
  PRICE, J E Affiliation Unknown 80/09/23 in
- DOCKET 70-2192 PITTSTON CO COAL GROUP
- 8007080450 IE Insp Findings & Licensee Ack dtd 800722 of License 8MM-1617. Insp findings no noncompliance noted # Region 2. Atlanta, Office of the Director 80/07/22 1p
- DOCKET 70-2313 NUCLEAR FUEL SERVICES
- 8009020475 Notification of contract execution, Mod 1 to "Hest Valley Haste Burial & Storage Facilities" Contractor Univ of State of NY HADEY, H. Research Contracts Branch. FIN 8-6350 80/08/18 ip
- --8009020481 Mod 1.granting no cost extension for 1 yr.to "West Valley Waste Burial & Storage Facilities" \* New York, State Univ of. (Albany). MORTON, K V Research Contracts Branch FIN 8-6350 80/08/18 2pp
- DOCKET 70-2322 EDLOW INTERNATIONAL CO
- 8009120129 Forwards Edlow Intl routs w/revised guidance NUREG-0561.
  reflecting latest amend to interim rule for physical
  protection of irradiated reactor fuul in transit
  Requirements must be implemented by 800703 W/o encis
  MCCORKLE.Q W Physical Security Development Branch 80/07/07 ip
- DOCKET 70-2375 PACIFIC GAS & ELECTRIC CO
- 8007020107 Requests renewal of Licanses SNM-1503 & SNM-1667, extending expiration date to B01231 Addl time necessary to complete facility licensing process SHAGKELFORD. B Pacific Gas & Electric Co 80/06/25 ip
- DOCKET 70-2478 TRANSNUCLEAR, INC
- 8009120136 Forwards Transnuclear route w/revised guidance NURE9-0561, reflecting latest amend to interim rule for physical protection of irradiated reactor fuel in transit. Requirements must be implemented by 800703 W/o encis. MCCORKLE.O.W. Physical Security Development Branch 80/07/07 ip

- 8009180512 Forwards safeguard plan for shipments of irradiated test reactor fuel Plan withheld (ref 10CFR2 790) MANQUSI, J Transnuclear, Inc. 80/07/10 ip
- 8009110240 Forwards Revision i of safeguard plan for shipments of irradiated test reactor fuel Revision withheld (ref. 100FR2, 790)
  MANOUSI, J. Transnuclear, Inc. 80/08/01 ip

#### DOCKET 70-2479 TRANSNUCLEAR, INC

- 8009120136 Forwards Transnuclear route w/revised guidance NUREO-0561, reflecting latest amend to interim rule for physical protection of irradiated reactor fuel in transit Requirements must be implemented by 800703 W/o encls MCCORKLE,O W Physical Security Development Branch 80/07/07 ip
- 8007:10240 Forwards Revision I of safeguard plan for shipments of irradiated test reactor fuel Revision withheld (ref IOCFR2 790) MANUBLIJ Transnuclear, Inc. 80/08/01 19
- DOCKET 70-2520 WEST VIRGINIA UNIV MEDICAL CENTER HORGANTOWN, NV
- 8009260316 Forwards IE Circular 80-19, "Nancompliance W/License Requirements for Medical Licensess" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/26

#### BOCKET 70-2554 VALLEY HOSP RIDGEHOOD

- 8009240712 Discusses IE Insp Rept 70-2554/80-01 conducted on 800620 No noncompliance noted License inactive KINNEMAN, J D Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/07/30 tp
- DOCKET 70-2540 OXLAHOMA OSTEOPATHIC HOSP TULGALOK
- 8009260392 Forwards IE Bulletin 79-19. "Packaging of Low Level Radwaste for Transport & Burial " Response required SEYFRIT, K V Region 4, Dallas, Office of the Director. 79/08/10
- --8009260405 Responds to IE Bulletin, "Packaging of Low Level Radwaste for Transport & Burial " Waste allowed to decay to background levels & then disposed of in normal trash MORRIS.H D Oklahoma Osteopathic Hosp Tulsa.Ok 80/09/22 1p

# DOCKET 70-2599 BERRIEN GENERAL HOSP BERRIEN CENTER, MI

8009160023 IE Insp Findings & Licenses Ack dtd 800808 of License SNM-1736 Insp findings no items of noncompliance or unsafe conditions noted REICHHOLD, W.P. Region 3, Chicago, Dffice of the Director. BO/08/08 in

#### DOCKET 70-2609 COMMONWEALTH EDISON CO

- 8009180261 Forwards request for amend to Licenses SNM-1802 & SNM-1803 Mod to fuel assemblies to address potential fratting concern on water-rook in assemblies has resulted in numerous transfers of fuel between spent fuel storage pools PEOFLES.D L. Commonwealth Edison Co. 80/07/11 2pp
- 3009110217 Forwards Revision 1 to security plan in response to NRC 800509 ltr Revision withheld (ref 10CFR2 790) PEOPLES, D. L. Commonwealth Edison Co. 80/07/28 ip
- ICKET 70-2621 RIVERSIDE HOSP NEHPORT NEWS, VA
- 109260314 Forwards IE Circular 80-19, "Noncompliance H/License Regulrements for Medical Licenses" No written response sequired 1/REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/08/26,

- DOCKET 70-2623 MCGUIRE SPENT FUEL POOL, DUKE POWER CO
- 8009110275 Forwards Revision 3 to spent fuw, transportation security plan, which meets requirements of 100FR73 37, as amended 800603 Requests approval of primary route for shipment of Ocones spent fuel Revision withheld (ref 100FR2 790) PARKER, W. O. Duke Power Co. 80/07/02 1p
- 8009150049 Advises that list of 60 addl heavily populated areas has been included in encl revised guidance document, NUREO-0561, per NRC amend rule for physical protection of irradiated reactor fuel in transit.effective 800703 H/o encl MCCORKLE.OW Physical Security Licensing Branch 80/07/07 1a
- 8009150392 Responds to util 800417.20 & 0702 ltrs re physical protection of irradiated reactor fuel in transit Approvas Revision 3 to spent fuel transportation plan MCCORKLE.0 W Physical Security Licensing Branch 80/07/11 lp
- BO09260527 Forwards comments re storage & in-transit security plan for BNN of low strategic significance Response requested within 30 days Comments withheld (ref 10CFR2 790) MCCCRRLE, 0 W Physical Security Licensing Branch B0/08/08 lp
- 8009190236 Forwards FR notice re relocation of local PDR to Atkins Library Univ of NC.Charlotte.NC FELTON, J H Division of Rules and Records 80/09/02. 2pp
- --8009190242 Notice of relocation of local FDR to Atkins Library, Univ of NG, Charlotte, NC FELTON, J M Division of Rules and Records 80/09/02 2pp
- 8009160343 Forwards FR notice of relocation of LPDR KETCHEN, E 0 Hearing Branch 4 80/09/12, ip
- --B009160347 Forwards notice of relocation of LPDR.
  CHILK: B J Office of the Secretary of the Commission 80/09/05
- --8009160352 Notice of relocation of LPDR to Atkins Library. Univ of NC. Charlotte. UNCC Station. NC FELTON, J M Division of Rules and Records 80/09/02 1p
- DOCKET 70-2705 ST FRANCIS MEDICAL CENTER HOSP LYNHOOD, CA
- 8009300188 Responds to IE Bullstin 80-22, "Automation Industries Model 200-820-008 Sealed Source Connectors " Hosp does not utilize subj equipment MCGRATH.E T 8t Francis Peorta, IL 80/09/15 ip.

#### DOCKET 70-2786 GENERAL ELECTRIC CO

- 8009110763 Forwards info requesting route approval for shipment of irradiated reactor fuel W/O encl ELDER,K General Electric Go 80/07/01 1p
- 8009050454 Requests excort svc for irradiated fuel shipment expected to arrive in Los Angeles.CA on 800825 New requirements in 10CFR73 require surveillance of shipment vessel while docked in populated area KIRKLAND.H W. General Electric Co 80/07/17. 2pp
- 8009120152 Forwards approved spent fuel route & law enforcement contact info in response to 800701 ltr Approval not intended to provide relief from licenses assurance of highway safety Encl withheld (ref 100FR2.790)

  MCCORKLE, G.W. Physical Security Development Branch. 80/07/21 ip.
- 8009240680 Forwards comments, lesson plans & list of individuals who have completed escort training requirements per 100FR73.37.

  MORTENSEN, W General Electric Co 80/07/21 19pp

#### DOCKET 70-2883 HANNA MINING CO

- 8009300606 Discusses IE insp of Licenses 22-05587-01, 22-015785-01, SNM-1353, SNM-1841, SNM-1864 on 800814-15 & forwards notice of violation DAVIS, A B. Region 3, Chicago, Fuel Facility & Materials Safety Branch, 80/09/02. 2pp
- ---B0093006ii Notice of violation from insp on B00Bi4-15 Noncompliance noted physical inventories not being performed as required \* Region 3, Chicago, Office of the Director 80/09/02. 1p.

#### DOCKET 70-2885 COMMONHEALTH EDISON

8009180261 Forwards request for amend to Licenses SNM-1802 & SNM-1803 Mod to fuel assemblies to address potential fretting concern on Mater-rods in assemblies has resulted in numerous transfers of fuel between spent fuel atorage pools PEOPLES.D.L. Commonwealth Edison Co. 80/07/11 2pp

9009110217 Forwards Revision 1 to security plan in response to NRC 800609 ltr Revision withheld (ref 100FR2 790). PEOPLES:D L Commonwealth Edison Co 80/07/28 1p

#### DOCKET 70-2892 AUXILIO MUTUO HOSP

8009260277 Forwards IE Circular 80-19, "Noncompliance H/License Requirements for Medical Licensess" No written response required. D'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/26 fo.

#### DOCKET 70-2908 VET ADMIN HOSP SAN DIEGO, CA

BOO9260309 Forwards IE Circular 80-19, "Noncompliance W/License Requirements for Medical Licenses" No written response required EMSELKEN, R. H. Region 5, San Francisco, Office of the Director, 80/08/26, 1p.

#### DOCKET 70-2909 WESTINGHOUSE ELECTRIC CORP POWER SYSTEMS

BOOT020453 Transcript of BOOB21 hearing in Montgomery, AL re Wastinghouse application for SNM license Pp 1-190 Morning session. Atomic Bafety and Licensing Board Panel BO/08/21 190pp

8009150411 Forwards comments from appropriate state agencies to DEB for Westinghouse fuel fabrication plant in Prattville, AL AMOS, M.R. Alabama, State of 80/07/01 10pp

8009040242 Motion for 20-day extension to file add1 valid contentions per ASLB 800821 special prehearing conference order, Certificate of Svc encl, ALLRED,D.L. Affiliation Unknown 80/08/29 2pp

8009160330 Hemorandum & order granting withdrawal of R Aronov, CO Butler, MF Butler, RH Campball, S Draut, RE Ely, JA Johnson, LO Moore, A Tolado & W Carroll B00807 petitions Affirms denial of DL Allred petition for continuance FORENAN, H. STEINOLER, M. J. WOLF, J. F. Atomic Bafety and Licensing Board Panel 80/09/11 6pp

BOOT170126 Response stating no objection to DL Alired & Gafe Energy Alliance of Central AL 800821 motions for extension until 800920 to file contentions
TURK, 8 E Hearing Branch 1 BACHMANN, R. G Rulemaking & Enforcement Division. 80/09/15 2pp

--8009170129 Response in support of R Aronov.CO Butler, MF Butler, RM Campbell, 6 Braut, RE Ely, JA Johnson, LO Moore, A Toledo & W Carroll 800925 withdrawal of original patitions Interests rapresented by Safe Energy Alliance of Central AL TURK, S. E. Hearing Branch 1. 60/09/15. 4pp

---9009170133 Suggested corrections to 800821 special prehearing conference transcript. Notice of appearance & Certificate of Byr smil.

a Hearing Branch 1 80/08/21 5pp.

#### DOCKET 70-2910 TENNEBBEE VALLEY AUTHORITY

8009190759 Application for amend to Licenses SNM-1863 & SNM-1861, extending expiration dates to 810331 & 1231.respectively MILLS, L.M Tennesses Valley Authority. 80/07/23 ip.

8009150206 Forwards add1 comments re transportation portion of fuel storage physical security plan dtd 800516 Requests that response be consolidated with responses to NRC 800716 ltr & be submitted within 30 days of receipt of ltr.

MCCORKLE. O W Physical Security Licensing Branch 80/08/11 1p.

DOCKET 70-2913 TENNEBSEE VALLEY AUTHORITY

8007190757 Application for amend to Licenses BNM-1863 & BNM-1861, extending expiration dates to 810331 & 1231 respectively MILLB.L N Tennessee Valley Authority 80/07/23 ip

DOCKET 70-2914 HANNA MINING CO

9009300404 Discusses IE insp of Licenses 22-05587-01,22-015755-01. SNM-1353,81M-1841.8NM-1854 on 800814-15 & forwards notice of violation DAVIS.A B Region G, Chicago, Fuel Facility & Materials Safety Branch 80/09/02 2pp

--8009300611 Notice of violation from insp on 800814-15 Noncompliance noted physical inventories not being performed as required \* Region 3. Chicago. Office of the Director 80/09/02 ip.

#### DUCKET 70-2932 TEXAS UTILITIES GENERATING CO.

BO09150213 Forwards application for ENM License to permit receipt, possession storage, insp & package for transport of university and stated nuclear fuel assemblies, for period beginning B10101 OARY, R J Texas Utilities Generating Co B0/07/10 ip

--8009150215 Application for SNM license to permit, receipt, possession, storage: insp & package for transport of unirradiated nuclear fuel assemblies for period beginning 810101 GARY, R J Texas Utilities Generating Co 80/07/10. 8pp.

# PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0002 CHEM-NUCLEAR SYSTEMS. INC.

8009260074 Notifies of intent to change vendor name to ATCOR Engineerad Bys.Inc Official mod will appear in revised GA program projected for Oct 1980 MDLF.C.R. ATCOR 80/09/27 ip

#### DOCKET 71-0017 RHODE IBLAND ATOMIC ENERGY COMMISSION

8009230785 Forwards GA program approval for radioactive mat1 package MACDONALD, C.E. Transportation Branch 80/08/29 ip

---8009230787 GA program approval for radioactive matl package 0017.
Revision 0
MACDONALD.C E Transportation Branch 80/08/29 ip

DOCKET 71-0018 NUCLEAR ASSURANCE CORP

8009150542 Forwards requests for add1 info re GA manual HACDCHALD, C E Transportation Branch. 80/09/04 2pj

#### DOCKET 71-0035 ROCKHELL INTERNATIONAL

GOO9230753 Forwards request for add1 info to complete review of GA program MACDONALD, C E Transportation Branch. BO/08/29. 2pp

## DOCKET 71-0082 KERR-MODEE NUCLEAR CORP

8009180334 Responds to 800703 itr requesting add1 info re GA program Revisions to GA program will be submitted by 810131 SHELLEY, W J. Kerr-McGae Nuclear Corp 80/08/04, ip

DOCKET 71-0108 MISSOURI, UNIV OF

8009250494 Forwards QA program approval for radioactive mati package MACDQNALD,C E Transportation Branch 80/09/10 ip

--8009250498 GA program approval for radioactive matl package.0108, Revision 0 MACDONALD.C E Transportation Branch 80/09/10 ip

## DOCKET 71-0109 UNION CARBIBE CORP

- 8009110995 Forwards GA program approval for radioactive matl package MACDONALD, C.E. Transportation Branch 80/08/26 ip
- --809110397 OA program approval for radioactive mati package 0109. Revision O MACDOMALD.C E Transportation Branch 80/08/26 1p/

#### DOCKET 71-0112 NAVY, DEPT OF

- 8009150188 Notifies of transfer of Certificates of Compliance 4888 & 5862 to Naval Engineering & Environ Support Activity.
  Forwards GA program for approval
  HENDRIK.G W Navy, Dept of, Naval Facilities Engineering Command 80/08/15 200
- --8009150189 GA program for radioisotope thermolectric generators

  \* Navy, Dept of: Naval Facilities Engineering Command 80/07/31
  Too

### DOCKET 71-0138 BATTELLE COLUMBUS LABORATORIES

8009230752 Forwards request for add1 info to complete review of GA program
MACDONALD.C E Transportation Branch 80/09/02 2pp.

## DOCKET 71-0192 NUCLEAR PACKAGING, INC

- 8009250500 Forwards GA program Approval for radioactive mat1 package MACDONALD, C.E. Transportation Branch 80/09/10 ip
- --B009280502 GA program approval for radioactive matl package:0192. Revision O MACDDMALD.C E Transportation Branch 80/09/10 ip

## DOCKET 71-0198 NUCLEAR FUEL SERVICES, INC

8007270237 Advises that modified QA program does not mest applicable criteria of App β to 10CFR50 Requests submittal within 60 days of revised application addressing 790605 request for addl info MACDONALD.C.E Transportation Branch 80/09/11. 1p

#### DOCKET 71-0244 NL INDUSTRIES, INC.

8009190492 Forwards request for add1 info to complete raview of GA program MACDDNALD.C E Transportation Branch 80/09/02 App.

## DOCKET 71-0370 AMERSHAM CORP.

8009150407 Forwards request for addl info to complete review of GA program

MACDUNALD, C E Transportation Branch 80/08/26 4pp

## DOCKET 71-0382 INTERIOR, DEPT OF, GEOLOGICAL SURVEY

8009230758 Forwards request for addl info to complete review of QA program MACDONALD:C E Transportation Branch 80/08/29 3pp.

## DECKET 71-0385 NAVY, DEPT OF, NAVAL NUCLEAR POWER UNIT PORT HUENEME, CA

- 8007020522 Forwards Change 1 to GA program for packaging of radioactive mati for transport & transportation of radioactive mati under certain conditions

  JARDINE, E. F. Navy, Dept. of, Forces Afloat, 80/08/12 2pp.
- -8009020525 Change 1 to GA program for packaging of radioactive matl for transport & transportation of radioactive matl under certain conditions JARDINE, E. F. Navy, Dept of, Forces Afloat 80/06/30, 2pp.

#### DOCKET 71-0394 NUCLEAR SOURCES & SERVICES, INC

- 8009150405 Forwards request for add1 info to complete review of QA program
  MACDONALD, C. E. Transportation Branch 80/08/26 lipp.
- DOCKET 71-0395 NAVY, DEPT. OF, NAVAL FACILITIES ENG 'COMMAND
- 8009150188 Notifies of transfer of Certificates of Compliance 4888 k 5862 to Naval Engineering & Environ Support Activity Forwards QA program for approval HENORIX, O H Navy, Dept of, Naval Facilities Engineering Command 80/08/15. 200
- --8009150189 GA program for radioisotops thermolectric generators, + Navy.Dept of, Naval Facilities Engineering Command. 80/07/3: 7pp

#### DOCKET 71-0396 ATCOR WASHINGTON, INC

- 8009290024 Informs of upcoming name change to ATCOR Engineered Bys.Inc. Revised GA program will be submitted by mid-Oct. WDLF.C R. ATCOR. 80/08/27, 1p
- 8007300207 Forwards OA program for approval to finalize plans for shipping excess fuel to Oak Ridgs, TN, GA program was written using radiography guide for GA plans NELBON, P.R. HARRIB, D.R. Rensselaer Polytechnic Inst. 80/09/04.
- --8009300210 GA program for shipping packagew
  \* Rensselaer Polytechnic Inst 80/09/04 2pp
- DOCKET 71-4888 MODEL: SENTINEL-25A, B, C, C3, D, E, F, TELEDYNE ENGRY
- B007080442 Advises that Command has no further need for Certificates of Compliance 4889 & 3862 which should be registered under present user. Naval Energy & Environ Support Activity Approval of encl GA program requested HENDRIX.O. W Navy, Dept of, Naval Facilities Engineering Command-80/08/15 2pp
- --8007080445 GA program for radicisotope thermoelectric generators.

  \* Navy, Dept of 80/07/31. 7pp

## DOCKET 71-4986 MODEL RA-2, EXXON NUCLEAR CO , INC

- 8009240127 Forwards Revision B to Certificate of Compliance 4986 for Models RA-11RA-2,RA-3 & RA-1. MACGUNALD.C E. Transportation Branch 80/09/02. 2pp
- --8009240132 Certificate of Compliance 4986, Revision 8, for Models RA-1, RA-2, RA-3 & RA-J, MACDONALD, C.E., Transportation Branch 80/09/02 App
- 8009240739 Advises of partial refund of smend fee for review of application for revision to Certificate of Compliance 4986. Expenditures were calculated for NRC review effort from 800402 submittal date until 800722 withdrawal. MILLER.W O License Fee Managament Branch. 80/09/08 1p.

#### DOCKET 71-5088 MODEL, D34710-1, U 8 NUCLEAR, INC

- 8009150396 Requests relewal of registration as user of Model D34710-10 REMLEY, M E Rockwell International Corp., Energy Systems Div 80/08/11 ip
- 8009190594 Application for renewal of Cartificate of Compliance 5088 for Model D34710-1 shipping container. Atomics Intl is primany user Univ should be listed as secondary user BRUGGER.R M. Missouri Univ. of, Columbia. 80/08/29. 2pp.
- DOCKET 71-5442 MODEL LA-34, BABCOCK & WILCOX CO.
- 8009150053 Informs renewal of Certificate of Compliance 5442 for Model LA-36 shipping container not desired.
  AUSTIN, M. A. Babcock & Wilcox Co., Nuclear Material Div 90/08/26 1p

DOCKET 71-5450 MODEL RCC-1, -2, -3, WESTINGHOUSE ELECTRIC CORP

BOOTO20114 Notification of registration as user of Hodel RCC in response to util request MACDONALD,C E Transportation Branch 80/07/24 ip

DOCKET 71-5740 MODEL ORNE TRU OF SHIPPING CONTAINER, ENERGY, DEPT OF

8009270263 Request registration as user of ORNL TRU Cf shipping container BPIEGEL, Commerce, Dept of, National Bureau of Standards 80/08/18 ip

BO09250521 Denies request for registration as user of Model ORNL TRU Cf (DDE~CR).Rev 2 packaging Package not approved by NRC, but currently under review MACDONALD.C E Transportation Branch BO/09/11 ip

DOCKET 71-5862 HODEL, BENTINEL-100F, TELEDYNE ENERGY BYSTEMS

B0090B0442 Advises that Command has no further need for Certificates of Compliance 4888 & 5862 which should be registered under present user. Naval Energy & Environ Bupport Activity, Approval of encl GA program requested HEMPRIX.0 W Navy.Dept of, Naval Facilities Engineering Command 80/08/15

---BO070B0445 QA program for radioisotope thermoelectric generators. -- Navy.Dept of 80/07/31. 7pp

DOCKET 71-5926 MODEL 100, GENERAL ELECTRIC CO

BO09240703 Application for amend to Certificate of Compliance 5926 re GE Model 100 permitting shipment of byproduct & SNM in solid nonfissile irradiated metal hardware Fee encl GUNNINGHAMIO. E General Electric Co 80/08/26

B009260100 Advises of forthcoming amend fee refund re Revision 5 to Certificate of Compliance 5926 MILLER, W. O License Fee Management Branch 80/09/11 1p

DOCKET 71-5942 MODEL GE-700, GENERAL ELECTRIC CO.

8009050379 Advises that personnel-hour expenditures required for review of 800318 application for amend to Certificate of Compliance 5942 have been reviewed Actual fee is less than fee paid for request review approval. Controller of notified re refund MILLER, M. O. License Fee Management Branch 80/08/06 1p

DOCKET 71-5957 MODEL, BMI-1, ENERGY, DEPT OF

B009110370 Notification of registration as user of Model BHI-1 in reapones to util request.

MACDONALD.C E Transportation Branch 80/07/28 ip.

DOCKET 71-5971 MODEL. GE-200, GENERAL ELECTRIC CD

8009260106 Application for amend to Certificate of Compliance 5971 for QE Model 200, permitting shipment of byproduct & SNM in fuel rod. plate & fuel assembly form & solid honfissils matl contained in metal cladding. Fee

DOCKET 71-3980 MODEL: QE-600, GENERAL ELECTRIC CO.

8009130001 Application for revision of Certificate of Compliance 3980 to permit shipment of 300/300/300 g fissile loading as Fissile Class 2 CUNNINGNAM, G. E. General Elactric Co., Nuclear Energy Products Div 80/03/21 2pp.

B009080454 Requests escort svc for irradiated fuel shipment expected to arrive in Los Angelas, CA on 800825. New requirements in 10CFR73 require surveillance of shipment vessel while docked in populated area
KIRKLAND, H W General Electric Co. 80/07/17 2pp

8009300122 Forwards Revision 5 to Certificate of Compliance 5780 for Model 6E-500 MACDONALD,C E Transportation Branch 80/09/17 2pp

--8009300125 Certificate of Compliance 5980 Revision 5 for Model 0E-600 MACDONALD C E Transportation Branch 80/09/17 3pp

DOCKET 71-5998 MODEL QF-400, GENERAL ELECTRIC CO

B009260051 Application for among to Certificate of Compliance 5998 for OE Model 400, permitting shipment of byproduct math maeting special form requirements or solid monfissile math in metal cladding Fee sncl CUNNIGNHAM.0 E General Electric Co 80/08/26 1p

DOCKET 71-4058 MODEL 83-1, NUCLEAR ENGINEERING CO

800926016B Application for amend to Certificate of Compliance 6058 for Model B-3, deleting annual O ring replacement requirement Fee encl
BAER, T S Nuclear Engineering Co , Inc , (subs of Feledyne, Inc )
80/05/30 ip

--8009260173 Forwards NRC 800627 ltr requesting fee for 800530 request for amend to Cartificate of Compliance 6058 Fee remains outstanding WEISS.D License Fee Management Branch 80/08/05 in

--8009260176 Notifies that 800530 request for amend to Certificate of Compliance 6053 has been classified as minor & requires add1 fee MEI89.J.D. License Fee Management Branch 80/06/27 ip

DOCKET 71-6144 MODEL 6144, NUCLEAR ENGINEERING CO

B009300602 Requests registration as user of Model CNSI-6144 JONES,R A R J Reynolds Tobacco Co 80/08/18 ip

DOCKET 71-6357 MODEL: NNFD-10, BABCOCK & WILCOX

8009190544 Notification of registration as user of Model NNFD-10 MACDONALD.C E Transportation Branch 80/09/10. ip

DOCKET 71-6400 MODEL SUPER TIGER, WESTINGHOUSE ELECTRIC CORP

8007150017 Forwards info requested to 800710 application to amend Certificate of Compliance 6400 Info provides discussion of safety significance of deviations from Protective Pactaging. Inc Drawing No 32106-1 AUSTIN.M A Babcock & Wilcox Co , Nuclear Material Div 80/08/15 4pp

8009300227 Requests remaining as registered user of Model Super Tiger, Certificate of Compliance 6400 Vallectics Nuclear Ctr does not own any containers, but rents from Nuclear Engineering Co.
CUNNINGHAM, G. E. General Electric Co. 80/08/18 ip.

B009180153 Requests add1 documentation re B00B1S application for amend to Model Super Tiger MACDONALD,C E Transportation Branch. 80/09/29 1g

DOCKET 71-6458 MODEL: BU-5, GENERAL ELECTRIC CO

8009190552 Notification of registration as user of Model 8U-5 MACDONALD, E.C. Transportation Brench. 80/09/10. 1p

DOCKET 71-6581 MODEL \$1032-1 & 1A, EXXON NUCLEAR CO , INC

8009260105 Forwards Page 2-14 to 800806 amended consolidated license renewal application for Models 51032-1 & la Page inadvertently omitted from original. HANSEN,L,E Exxon Nuclear Co , Inc. (subs of Exxon Corp ) 80/08/15 ip

--8009260117 Page 2-14 to 800806 consolidated license renewal application for Models 51032-1 & ia. \* Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) XN-52-02 R1 80/08/15 1p

## DOCKETED ITEMS

## DOCKET 71-6717 MODEL 6717 8

- 8009170136 Requests continuation of registration as user of Certificate of Compliance 6717
  DALLINGER, J. F. General Dynamics Corp. Electric Boat Div. 80/08/12
  Lo.
- 8009180529 Application by NC Dept of Transportation, Div of Highways, Matls & Tests Unit for use of transportation packages identified as Certificates of Compliance 6717 & 9036 WAGNER.F T North Carolina. State of 80/08/12 1p
- DOCKET 71-9001 MODEL IF-300, GENERAL ELECTRIC CO
- B009230756 Forwards Revision 10 to Certificate of Compliance 9001 for Model IF-300 MACDICALD. E Transportation Branch 80/08/27 2pp
- --8009230761 Certificate of Compliance 9001, Revision 10, for Hodel IF-300 NACDONALD, C.E. Transportation Branch B0/08/27 App
- DOCKET 71-9009 MODEL FL 10-1, GENERAL ELECTRIC CO
- 8009110750 Forwards Revision 9 to Certificate of Compliance 9009 for Model FL 10-1 MACDONALD.C E Transportation Branch 80/09/03, 2pp
- --8009110759 Certificate of Compliance 9009, Revision 9, for Model FL 10-1 MACDONALD, C E Transportation Branch 80/09/03 8pp
- DOCKET 71-9018 MODEL: BU-6, GENERAL ELECTRIC CO
- 8009250463 Requests changes of user registration for Models CNSI-14-195-H.CRSI-AL-33-90 & CNSI-6-80-2 New contect individual is CP Yundt YUNDT,C.P Portland General Electric Co 80/08/07 IP
- DOCKET 71-9019 HODEL BU-7, GENERAL ELECTRIC CO
- 8009050414 Forwards Application Amend T-16 for revision of Certificate of Compliance 9019 W/o encl KAPLAN.A, L General Electric Co . Nuclear Energy Products Div 80/08/21 ip
- --8009050417 Forwards Application Amend T-16 for revision of Certificate of Compliance 9019 for GE Bu-7 transport package, changing allowed H/U ratio in package contents from 0 45 to 1.577 KAPLAN, A L General Electric Co , Nuclear Energy Products Div 80/07/25 ip
- ~-8009050419 Application for amend of Certificate of Compliance 9019, consolidating prior applications for revision & test results & changing H/U ratio in package contents from 0 45 to 1 577 a General Electric Co , Nuclear Energy Products Div 80/07/25, 152pp
- DOCKET 71-9022 MODEL: CE-250-2, COMBUSTION ENGINEERING CO , INC
- 3007240184 Application for amend to Certificate of Compliance 7022, to permit closure of Model CE-250-2 by either licensed or proposed alternate closure sys Fee enci HANSEN, LE Exxon Corp 80/08/14 3pp
- DOCKET 71-9027 MODEL 741, TECHNICAL OPERATIONS, INC.
- 8009020125 Notification of registration as user of Models 650,680 & 741 in response to US Navy request MACODIALD, C E Transportation Stanch 80/07/24 ip.
- DOCKET 71-9032 MODEL 650, TECHNICAL OPERATIONS, INC.
- 6009020125 Notification of registration as user of Models 650.680 & 741 in response to US Navy request MAGDONALD.C E Transportation Branch 80/07/24 ip

- DOCKET 71-9033 MODEL 660 & 660E. TECHNICAL OPERATIONS, INC
- BOO9909093 Requests registration as user of Tech/Ops Model &&C DAHSON, R Contra Costa Industrial X-Ray Co 80/07/23 ip.
- DOCKET 71-9034 MODEL TRIGA-1, GENERAL ATOMIC CO
- B009300135 Forwards Revision 3 to Certificate of Compliance 9034 for Model TRIOA-1 MACDDNALD, C E Transportation Branch 80/09/17 is
- --8009300137 Cartificate of Compliance 9034 Revision 03, for Model TRIGA-1.
  MACDONALD, C E Transportation Branch 80/09/17 2pp.
- POCKET 71-9035 MODEL: 680, TECHNICAL OPERATIONS, INC.
- 8009020125 Notification of registration at user of Models 450,480 & 741 in response to US Navy request MACDONALD, C.E. Transportation Branch 80/07/24 lp.
- DOCKET 71-9036 MODEL, C-1, SOURCE PRODUCTION EQUIPMENT CO.
- 8009180523 Application by NC Dept of Transportation. Div of Highways, Matls & Tests Unit for use of transportation packages identified as Certificates of Compliance 6717 & 9036 WAGNER, F. T. North Carolina, State of 80/08/12 1p.
- DOCKET 71-9037 MODEL TRIGA-2, GENERAL ATOMIC CO.
- B009300127 Forwards Revision 3 to Certificate of Compliance 9037 for Model TRIGA-2, MACDUMALD-C E Transportation Branch B0/09/17 ip
- --B009300130 Certificate of Compliance 9037, Revision 3. for Model TRIGA-2 MACDONALD, C E Transportation Branch 80/09/17 2pp
- DOCKET 71-9039 MODEL 715, TECHNICAL OPERATIONS, INC.
- 8009020313 Forwards into to support renswel of Certificate of Compliance 9039, per 800811 teleon MUNRO, J J Tech/Ops (Technical Operations, Inc.). 80/08/12, 4pp
- 8009080494 Forwards Revision 5 to Certificate of Compliance 9039 for Model 719, MACDONALD,C E Transportation Branch 80/08/19 4pp.
- --8007080457 Certificate of Compliance 9039, Revision 5, for Model 715. MACDONALD, C E Transportation Branch 80/08/19 2pp.
- 8009190548 Notification of registration as user of Model 715. HACDONALD, C. E. Transportation Branch 80/09/10. 1p
- DOCKET 71-9044 MODEL, DE-1600, GENERAL ELECTRIC CO
- 8009150390 Requests registration as user of Model OE 1600 shielded container HARVEY.J L. South Hest Nuclear Co. 80/08/19 1p.
- 8009260391 Application for amend to Certificate of Compliance 9044 for GE Model 1600, permitting shipment of Pu in excess of 20 Ci in metal alloy or reactor byproduct & 8NM as solid metal or oxide Fee encl.

  CUNNINGHAM.O E. General Electric Co. 80/08/26 1p.
- DOCKET 71-9049 MODEL GE-500. GENERAL ELECTRIC CO
- BOO9260881 Application for amend to Certificate of Compliance 9049 for GE Model 500, permitting shipment of byproduct matl meating special form requirements & solid nonfissile irradiated metal hardware contained in metal cladding. Fee encl CUNNINGHAM. O. E. General Electric Co. 80/08/26 ip

8009290144 Advises of partial refund of amend fee for NRC review of 800208 & 21 applications for Revision 2 to Certificate of Compliance 9049 MILLER:W U License Fee Management Branch 80/09/08 1p

DOCKET 71-9074 MODEL AP-100, ANEFCO, INC

9009150591 Requests registration as user of Model AP-100 to ship radioactive matle HKLLB, L.H Tennessee Valley Authority 80/08/11 1p

DOCKET 71-9080 MODEL HN-600, HITTMAN NUCLEAR & DEVELOPMENT CORP

8009220172 Opposes Revision 4 incorporating Certificates of Compliance 9113 & 9080 into single package Differences between Model HM-500 & CNB 7-100 are sufficient to warrant issuance of separate certificates COMBETT.J B. Chem-Nuclear Systems, Inc. 80/08/14 1p

DOCKET 71-9081 MODEL; CN81-16Q0: CHEM-NUCLEAR SYSTEMS: INC

9009170561 Notification of registration as user of Model CMS-1600 MACDONALD-C, E. Transportation Branch 80/09/10 ip.

DOCKET 71-9094 MODEL CN81-14-195-H, CHEM-NUCLEAR SYSTEMS, INC.

8009020121 Notification of registration as user of Model CNSI-14-195-H in response to util request MACDONALD, C.E. Transportation Branch. 80/07/24 ip

BOO9250463 Requests changes of user registration for Models CNSI-14-195-H.CNSI-AL-33-70 & CNSI-6-80-2 New contact individual is CP Yundt YUNDI.C.P Portland General Electric Co. 80/08/07. 1p

DOCKET 71-9094 MODEL: CN81-21-300, CHEM-NUCLEAR BYSTEMS, INC.

9009110756 Requests registration as user of Model CNSI 21-300 CRANE.P. A Pacific Cas & Electric Co 80/08/12 ip

8009090624 Forwards Revision 4 to Certificate of Compliance 9096 for Model CNS 21-300 MACDONALD: C. E. Transportation Branch 80/08/28 3pp

--BOGF090526 Revision 4 to Certificate of Compliance 9096.for Model CNS 21-300 MACDONALD.c.E Transportation Branch 80/08/28 2pp

DOCKET 71-9097 MODEL: CHSI-14-195L, CHEM-NUCLEAR SYSTEMS, INC.

8009260039 Requests hearing re NRC 800807 denial of application for design approval for Model CNBI 14-195L REYNOTH E Chem-Nuclear Systems, Inc. 80/08/26 ip.

JOCKET 71-9108 HODEL AL-33-90, ATCOR, INC

8009020116 Notification of registration as user of Model Al-33-90 in response to util request MAGDONALD, C.E. Transportation Branch. 80/07/24. 1p.

8009020119 Notification of registration as user of Model Al-33-90 in response to util request
MACDDNALD.C E Transportation Branch 80/07/24 is

8009170555 Notification of registration as user of Modal AL-33-90 MACDONALD.C E Transportation Branch 80/09/10 1p

DOCKET 71-9111 MODEL CN6-80A, CHEM-NUCLEAR, INC

8007250463 Requests changes of user registration for Models CNSI-14-175-H.GNSI-AL-33-90 & CNSI-6-80-2 New contact individual is CP Yundt YUNDT, CP Portland General Electric Co 80/08/07 ip

DOCKET 71-9113 MODEL 7-100. CHEM-NUCLEAR SYSTEMS, INC.

8009130399 Requests registration as user of Model 7-100 ABEL, J S Commonwealth Edison Co 80/08/11 1p

B009220172 Opposes Revision 4 incorporating Certificates of Compliance 9113 & 9080 into single package Differences between Model HN-600 & CNB 7-100 are sufficient to warrant issuance of separate certificates

CORBETT, J S Chem-Nuclear Systems, Inc. 80/08/14 1p

DOCKET 71-9114 MODEL CN6-BOB, NUCLEAR PACKAGING, INC

8009050458 Requests hearing re-denial of application for approval of Model CNA-BOB shipping package BIMCHUK, J D Nuclear Packaging, Inc. 80/08/20 ip

800924021: Confirms telcon re NRC 800731 denial of application re design approval for Model CN6-808 & vendor 800820 request for formal adjudicatory hearing informal discussion w/NRC required prior to initiation of formal hearing JAKEL. E Regulations Division 80/09/09.

DOCKET 71-9136 MODEL GE 9136, GENERAL ELECTRIC CO

8009230766 Notification of registration as user of Models QE-9136-01, QE-9136-02 & QE-9136-03 in response to 800331 request MACDDNALD, C E Transportation Branch 80/08/29 2pp

DOCKET 71-9808 MODEL: DOT SPEC &M. ENERGY, DEPT. OF

8009050205 Forwards Certificate of Compliance 9508, engineering evaluation & safety analysis for mod to allowed contents of 6M spec packaging.
RD86, DM Energy, Dept of, 80/08/05 2pp

--B007030207 Certificate of Compliance 7508 for Package 6M RDEDER, J.R. Energy, Dept. of 77/04/01 Spp

--8009050214 "Use of DOT Spec 6M Container for Shipping Polystyrene-Pu Compacts " SHITH.D R . BROWN.W K Los Alamos Scientific Laboratory 80/08/05 5pp

DOCKET 71-9953 MODEL DRNL - BNL - NBS UN FUEL CONTAINER, ENERGY,

8009050453 Requests registration as user of Model ORNL-BNL-NBB O'ROURKE,8 A Los Alamos Scientific Laboratory. 80/08/13. 1p

•		

# NONDOCKETED ITEMS

COMMISSION MEETING RECORDS 8009030074 Forwards further Commission guidance for power reactor OLs for FR publication on 800620 CHILK.S J Office of the Secretary of the Commission B0/06/17 --8009030079 "Further Commission Guidance for Power Reactor CLs.
Statement of Policy "
CHILK.S J. Office of the Secretary of the Commission 80/06/16 8009030093 Forwards notice of Commission meetings during wk of 800423 CHILK, B J Office of the Secretary of the Commission 80/06/18 --B009030098 Notice of Commission meetings during wk of B00A23 to discuss proposed interim hydrogen requirements for small containments & financial status of utils MAGEE.W Office of the Secretary of the Commission B0/06/17 8007030102 Forwards notice of Screening Committee for Lawyer Vacancies on Licensing Board Panel 800618 meeting in Washington.DC for FR publication on 800618 MDYLE, J C Office of the Becretary of the Commission 80/06/17 --8009030105 Notice of Screening Committee for Lawyer Vacancies on Licensing Board Panel 800618 meeting in Washington, DC HOYLE, J C Office of the Secretary of the Commission 80/06/17 8009050481 Transcript of 770608 discussion of NRC safety reviews of foreign facilities in Washington, DC Pp 1-25

\* Commission 77/06/08 27pp B009090641 Transcript of 770603 discussion of proposed Commission legislative program in Washington, DC Pp i-51 • Commission 77/06/03 53pp 6009070649 Transcript of 770322 discussion on research budget in Hashington, DC Pp 1-50 • Commission 77/03/22 32pp 8009100001 Transcript of 770503 briefing on Commission testimony on Benate Bill 897 in Washington, DC Pp 1-13 # Commission 77/05/03 14pp B009100020 Transcript of 771229 discussion of hearing board for clearance rule proceeding in Washington, DC Pp 1-24 Portions withheld as noted in encl \* Commission 77712/29 29pp

8009100087 Commission determination releasing encl transcript of 770903 briefing on possible classified & litigative aspects of GEBMD in Hashington DC Pp 1-23 Page 23 Lines 7-9 remain

8009100115 Commission determination releasing encl transcript of 770425 discussion of policy decisions/NRC Authorization Bill in Washington DC Pp 1-72 Page 3 Line 11 through Page 4 Line 17 remain withheld, 6 Commission 77/04/25 73pp

8009160443 Transcript of 800904 discussion of SECY-80-399 re proposed interim amends to 100FR50 rs hydrogen control & certain degraded core considerations in Washington, DC Pp 1-86 Viewgraphs encl # Commission 80/09/04, 95pp

Commission 77/05/03 24pp

8009180133 Transcript of 800903 Affirmation Session 80-38 in Washington.DC Pp 1-3 \* Commission 80/09/03 6pp 8009180269 Transcript of 800904 public meeting in Washington.DC re discussion & yote on enforcement policy Pp 1-91 \* Commission 80/09/04 93pp --8009180277 SECY-80-139A Novince/ section 139A

Recommends adoption of proposed policy of enforcement action as interim guidance Draft FR notice and

STELLD, V Office of Inspection & Enforcement, Office of the Director 80/08/27 50pp --B009180284 Summary of Commission B00319 meeting in Washington.DC re BECY-B0-139 dealing w/NRC enforcement program Revised policy discussed but no final conclusions reached CHILK:8 J Office of the Secretary of the Commission B0/03/28 ---B009180291 Comments on SECY-80-139 re enforcement policy NRC divs must submit alternatives to Executive Director of Operations AMEARNE, J.F. Commission 80/03/24 App --8009180298 Comments on proposed enforcement policy Policy paper is good first step but of little use if licensee commitments & NAC stas are not in enforceable form BRADFORD.PA Commission 80/04/09 18pp 8009190771 Transcript of 800903 public briefing by EPA on draft general stds (occupational exposures mill tailings) in Washington, DC Pp i-101 

\* Commission 80/09/03, 101pp --8009190775 Requests comments on draft disposal stds for U mill tailings ramedial action program.Draft FR notice & EIS encl ROSENBAUM,D M Environmental Protection Agency 80/08/11 70pp G009290276 Transcript of 800904 Affirmation Session 80-39 to discuss fees for withdrawl of applications for CPs & DLs in Washington, DC Pp 1-2 Draft proposed rules and \$ 80709704, 20pp --8007250280 SECY-80-364 Recommends recovery of licensing review fees for applications denied, withdrawn, suspended or postponed Draft FR notice encl
DDNOGHUE.D J Office of Administration 80/09/04 lipp BO09290021 Transcript of 800916 public meeting in Hashington,DC rediscussion & vote on Commission program to review DL applications,AM session Pp 1-62
AHEARNE,J A Commission B0/09/16 45pp --B009290032 SECY-80-414

JUVATUOUSE BECYTUP-414
Requests approval of conceptual draft plan re systematic safety evaluation of all currently operating nuclear power reactors H/draft 90-day status rept.considerations re ridentification of regulations & draft public announcement DENYGN.H R Office of Nuclear Reactor Regulation. Director, 80/09/09 Sipp

BOO7160467 Transcript of B0070B discussion of Commission program to review DL applications in Washington, DC Pp 1-63 Related documentation & correspondence enci \* Commission B0/09/0B 154pp

#### ACRE ADVISORY COMMITTEE ON REACTOR BAFEQUARDS

- 8009030648 Forwards notice of ACRS 800904-06 meetings in Weshington. DC for publication in FR CHILK.S J Office of the Secretary of the Commission. 80/08/19
- --8009030650 Notice of ACRS 800904-06 meetings in Washington, DC. HOYLE, J C Office of the Secretary of the Commission. 80/08/19.
- 8007050388 Transcript of ACRS Subcommittee on Class 7 Accidents 800828 hearing in Washington DC Pp 1-251

  ACRS Advisory Committee on Reactor Bafeguards 80/08/28
- 8007080250 Transcript of ACRS Reactor Fuel Subcommittee 800703 meeting in Washington DC Pp 1-213 
  ACRS Advisory Committee on Reactor Bafaguards 80/09/03 21400
- 8007080255 Transcript of AGR8 Bubcommittee on Safety Philosophy. Technology & Criteria 800703 meeting in Hashington BC Pp. 1-275.

  e ACR8 Advisory Committee on Reactor Safeguards 80/07/03 276pp.
- 8009080385 Transcript of 245th ACRS meeting on 800904 in Washington. DC. Pp 1~308. Supporting documentation and 1. # ACRS Advisory Committee on Reactor Safeguards. 90/09/04.
- 8009090620 Transcript of ACRS Subcommittee on Fuel 800821 meeting in ID Falls, 1D. Pp. 1-220. W/supporting documentation + ACRS Advisory Committee on Reactor Safeguards. 80/08/21
- 9009100157 Bunmary of AGRE LER Subcommittee 800422 meeting in Washington DC re status of new NRC Ofc for Analysis & Evaluation of Operational Data. # AGRE Advisory Committee on Reactor Safeguards. 90/07/11, 11pp
- 8009100160 Summary of ACRS Subcommittee on Natural Heat Removal 800326 meeting in Mashington.DC re-various modes of natural circulation heat removal in PMRs.

   ACRS Advisory Committee on Reactor Safeguards. 80/05/30 9pp
- 8009100180 Summary of ACRS Subcommittee 800424 meeting or natural circulation decay heat removal in reactor sys under various conditions.

  \* ACRS Advisory Committee on Reactor Safaguards. 80/06/25. 10pp.
- 8009100183 Bummary of ACRB Bubcommittee on Reliability & Probabilistic Assessment 800430 meeting in Mathington DC re budget, research on flood program & development of quantitative safety criteria.

  \*\*ACRB Advisory Committee on Reactor Bafeguards. 80/07/09. 7pp.
- 8009100195 Summary of ACRS Subcommittee on Regulatory Activities 800604 meeting in Mashington DC re proposed revisions to 10CFR55, 10CFR50 % proposed Reg Quide 1.23.Revision 1. # ACRS Advisory Committee on Reactor Safeguards. 80/06/27. 7pp.
- 8009100472 Forwards corrected pages & supplemental info submitted as encl to 800410 ltr re proposed reg guide. "Lightning Protection for Nuclear Power Plants."

  JOHNOON I. B Affiliation Unknown. 80/04/18 16pp.
- B009100917 Forwards 800807 FR notice of ACRS Subcommittee on Consideration of Class 9 Accidents 800828 meeting CHILK.S.J. Office of the Secretary of the Commission. B0/08/07.
- ---B009100920 Notice of ACRB Subcommittee on Consideration of Class 9
  Accidents 800828 meeting re hydrogen generation & control
  methods w/degraded core conditions
  HOVLE, J. G. Diffice of the Secretary of the Commission. 80/08/07.
- 8009110293 Transcript of 800906 ACRS Thedani presentation in re ATMS Hashington: DC. Pp 1-29.

  \* ACRS Advisory Committee on Reactor Sefeguards. 80/09/06. Sipp
- 8009110697 Summary of ACRS Subcommittee on Safeguards & Security 800826 meeting in Washington DC re-review of FYB2 budget.

  \* ACRS Advisory Committee on Reactor Safeguards. 80/07/23, Spp.

- 8009110864 Transcript of 245th meeting of ACRS on 800905 in Washington, DC Pp 1-109. # Commission 80/09/05. 120pp
- 8009180245 Provides addl comments on hydrogen control & improvement of contesiment capability. Recommendations in ACRS 791213 ltr re reliability assessments & design features for core damage & core melt accidents should be adopted & given priority. PLESSET, M S. ACRS Advisory Committee on Reactor Bafeguards. 80/09708. 2pp
- BO09150249 Discusses 245th ACRB meeting re final version of NUREO-0630, "Cladding Swelling & Rupture for LOCA Analysis "
  Implementation should be held in abeyance until NRC revises code requirements
  PLESSET.M 8 ACRB Advisory Committee on Reactor Safeguards. 80/09/09. 2ng
- 8009150A40 Notice of ACRB Bubcommittee on Bafety Philosophy & Criteria 800903 meeting in Mashington.DC HDYLErJ, C. Office of the Secretary of the Commission. 90/08/13.
- 8009150443 Notice of ACRS Subcommittee on Reactor Fuel 800821 meeting in Idaho Falls, ID.
  CHILK, S. J. Office of the Secretary of the Commission. 80/07/31.
- BOO9160074 Notice of various ACRB subcommittee Aug-Nov 1980 meetings in Washington.DC & Idaho Falls.ID & ACRB full committee BO0904-06:1009-11 & 1106-08 meetings. HOYLE,J C Office of the Secretary of the Commission. BO/08/19.
- 8007160079 Notice of ACRS Subcommittee on Reactor Fuel 800703 meeting in Hashington DC to review NUMEC-0630, "Cladding Swelling & Ruyture Models for LDCA Analysis."
  HOYLE, J. C. Office of the Secretary of the Commission, 80/08/13
- 8009160503 Notice of room change for ACRS Subcommittee on Befety Philosophy & Criteria 800806 meeting. Discussion of proposed schedules for developing quantitative safety goals added to agenda. CHILK, S. J. Office of the Secretary of the Commission. 80/07/31.
- 8009190261 Forwards FR notice of change in status of ACRS meetings. Requests publication on 800626 CHILK, S. J. Office of the Secretary of the Commission. 80/06/23.
- --8009190266 Notice of change in status of ACRS meetings Determined that closed sessions will not be necessary HOYLE.J C. Office of the Secretary of the Commission 80/06/23
- 8009190416 Discusses response to ACRS 800716 ltr re reactor coolant pump trip & HPI termination criteria Agrees w/comments by ACCRS w/exception of two items ZECH-0.0 Technical Support Branch. 80/09/03. 2pp.
- 8009190778 App. summary & table of contents to minutes of 238th ACRS meeting on 800207-09.

  \* ACRS Advisory Committee on Reactor Safeguards. 80/02/09 1600p.
- 8009230111 Comments on 800604 presentation re evaluation of seismic risk in states lying east of Rocky Mountains due to rarity of earthquakes in majority of area, Calculation of max expectable seismic acceleration would not be satisfactory. MAXHELL.J.C. Affiliation Unknown. 80/06/14 4pp.
- BO09230113 Discusses SIMMER code for advanced reactor safety research. Limitations result from assuming droplet field & associated assumptions re-drop size & heat transfer. Focus should be on physical process being modeled. CATTON, I. ACRS Advisory Committee on Reactor Bafeguards, 30/07/09. 1p.
- BOOV240690 Comments on ACRS 800722 meeting re Class 9 accident safety analyses. Mental stress resulting from continued presence of substantially degraded core should be considered. Emphasis should be placed on prevention.

  SIEQEL 8. Advanced Energy Systems. 80/07/22 3pp
- 8009260219 Comments on matters discussed at ACRS 800630 meeting re SIMMER effort to describe core disruptive accident in complex sys Principal priority & emphasis should be placed on prevention as compared W/mitigation. SIEOEL,S Advanced Energy Systems. 80/07/08. 3pp.

## CONSCISSION NRC CONNISSIONERS

- \$000020202 Provides status of GERMO proceedings in response to 800402 lit requesting that Commission re-examine 1777 decision to terminate proceedings w/completion of Intl Nuclear Fuel Cycle Evaluation (INFGE) H/o enci.
  HENDRIE-J, M Commission 80/08/08. 2pp

- --BOOP020207 Provides status of QESMO proceedings in response to 800402 like requesting that Commission re-examine 1977 decision to terminate proceedings w/completion of Intl Nuclear Fuel Cycle Evaluation (INFCE) M/o encl. HENDRIEJ M Commission. 80/08/08 2pp.
- --BODFOGOZIO Provides status of GEBMO proceedings in response-to 800402 ltr requesting that Commission re-examine 1977 decision to terminate proceedings w/completion of Intl Nuclear Fuel Cacle Evaluation (INTCE). M/o encl. HENDRIEL J. M. Commission. 80/08/08 2pp.

- 9009020348 Provides Bubcommittee on Federal Spending Practices w/ request for assistance in implementing Bunshine Act. Supports cencept of openess in conduct of Commission business, AMEZAME, J.F. Commission. 80/08/13. 2pp.
- --- 8009020375 Requests that MRC include encl info in annual rept to Congress on compliance w/Sunshine Act requirements. Also requests comments on experience in implementing Sunshine Act.
  CHILES.L. Senate, Governmental Affairs. 80/03/03. App
- 8007080573 Responds to 800605 request for Commission to begin rulemaking to establish safety goal for licensing & regulating nuclear plants, Ofc of Nuclear Regulatory Research expanding research on safety decisionmaking, AMEARNE, J. F. Commission 80/07/31, 3pp
- --8009080375 Forwards draft notice of intention to promulgate regulations establishing safety goal for licensing & regulation of nuclear power plants. Bix questions to be addressed by releasting re-accident sequences & addl safety sys encl MEISB.E.R. Shelden, Harson & Weise 80/06/05. 9pp.
- 8004040083 SECY-80-293
  Weekly info rept for wk ending 800613
  REPH,T.A. Office of the Executive Director for Operations.
  80/06/18 40pp.
- 8009070579 Forwards plan for investigation of interaction between abectromagnetic pulse & commercial nuclear plant sys. DENTON.M R. Office of Nuclear Reactor Regulation, Director 60/08/05. 10pp.
- BOOF0T0601 Accepts 800723 lecture invitation for 801119 HEMORIE, J. M. Commission 80/07/30. ip.
- --BOOTOTOGOT Requests presence of Commissioner for lecture on BO1117, KANTER: M. A. Argonne National Laboratory. BO/07/22, ip.
- 8009090632 Heakly info rept for wk anding 800815. REMM.T.A. Office of the Executive Director for Operations. 80/08/21. 28pp.

- 9009090639 Ack receipt of 800528 ltr re NRC rulemaking on emergency planning for nuclear facilities & forwards final rules on emergency planning AMEGARME.JF Commission 80/08/14 lp.
- --8007090451 Comments on proposed rules 10CFR50 & 70 re emergency planning:detailed evaluation planning unnecessary Fifteen-minute warning requirement should be rejected in favor of PBAR criteria
  COX.F.T Texas, State of 80/05/28 7pp
- --8009090555 Comments on draft guidelines published as NUREQ-0610, "Draft Emergency Action level Guidelines for Nuclear Power Plants." NRC should give more cognitance to programs & responsibilities of federalistate & local govt agencies, COX.F.T Texas, State of 79/11/29. Spp
- --B009090462 Comments on AUREO-0654 re emergency response plans Objects to provisions seesingly included for benefit of federal personnel reviewing state & local plans COX.F T Texas. Beats of B0/05/13 7pp
- 8009100084 Comments on 8, 2880. Consultant Reform Act of 1980. Supports basic thrust of legislation re-maximizing competition. considering organizational conflicts of interest & providing documented record of gort contracts.

  AHEARNE, J. F. Commission 80/08/20, 2pp
- ---8009100093 Requests comments on ancl S. 2980, Consultant Reform Act of 1980. RIBICOFF.A. Senate, Covernmental Affairs. 80/07/02, 27pp
- 8009100098 Comments on 8, 2443 re authorizing DOE to carry out high level liquid nuclear waste mgt demonstration project at Western NY Svc Ctr. Supports project initiation to DOE involvament. Recent seemd raises some problems. AHEARNE. J F. Commission. 80/08/20, 2pp
- ~~B009100102 Comments on 8 2449 re authorizing DDE to carry out high level liquid nuclear waste mgt demonstration project at Western NY BVC Ctr. Supports project initiation & DQE involvement Recent assend raises some problems AHEARNE, J F Commission. 80/08/20 2pp.
- --8009100107 Requests comments on encl 8, 2443 re authorizing DDE to carry out high level liquid nuclear wasts mpt demonstration project at Western NY Svc Ctr in West Valley.

  JACKSON, H M Senate, Energy & Natural Resources, 80/04/04 7pp.
- ---8009108108 Requests comments on encl 8. 2443 re authorizing DOE to carry out high level liquid nuclear waste mgt demonstration project at Western NY Svc Ctr in West Valley W/o encl. BTAOSERS.H. O. House of Rep., Interstate & Foreign Commerce, 80/03/24 7pp.
- 8009100111 Forwards repts to Congress on number of full-time permanent employees hired & promoted during second & third quarters of FYBO, NRC procedures unchanged from previous rapts. H/o encl AMEGRINE, J. F. Commission 80/09/22, 1p.
- --8009100114 Forwards repts to Congress on number of full-time permanent amployees hired & promoted during second & third quarters of FYBO,NRC procedures unchanged from pravious repts. M/o and AMEARNE, J F Commission. 80/08/22 ip.
- ~~8009100116 Provides Subcommittee on Energy & Power w/repts to Congress on number of full-time permanent amployees hired & promoted during second & third quarters of FYBO NRC procedures unchanged from previous repts. W/o encl.

  AHEARNE, J F. Commission 80/08/22 19.
- ---8009100122 Provides Subcommittee on Environ, Energy & Natural Resources w/regts to Congress on number of full-time permanent employees hired & promoted during second & third quarters of FY60, NRC procedures unchanged from previous repts W/o encl AHEARNE, U.F. Commission. 80/08/22 1p.
- --B009100124 Provides Subcommittee on Nuclear Regulation w/repts to Congress on number of full-time permanent employees hired & promoted during second & third quarters of FYSO NRC procedures unchanged from previous repts, W/o encl. AHEARNE, J. F. Commission, 80/08/22. 1p.

- 8009110408 Forwards response to 800512 inquiry re Commission implementation of export authority under Nuclear Romproliferation Act, particulary concerning supply reliability Includes supporting documents AHEARNE. J F Commission 80/08/15. 280pp
- ~-B009110413 Forwards questions re Commission implementation of Nuclear Nonproliferation Act CHURCH,F Senate, Foreign Relations Committee 80/05/12 3pp.
- 8009i104i7 Responds to 8006i7 ltr enclosing news article re risk assessment techniques Commission uses risk assessment techniques.particularly where comparison of alternative courses of action can be made HENDRIC, J M Commission 80/07/29 ip.
- ---8009110418 Forwards articles re 800514 & 15 hearings on H R 4939 re comparative rists. RITTER,D House of Rep. 80/06/17. 4pp
- 8009110825 Forwards MRC ltr to Senator Hart addressing matters re NRC 800404 response to Subcommittee on Nuclear Regulation questions about pressure suppression containments. W/o encl HENDRIE. J M Commission. 80/08/19. ip
- 8009110753 Weekly info rept for wk ending 800822 REHM.T A. Office of the Executive Director for Operations 80/08/27. 28pp.
- 8009120477 Provides Subcommittee on Energy Research & Production w/ position on Commission pilot program for procedural assistance in response to 800731 request. Program should not be considered as "funds for intervenors."

  AHEARNE, J. F. Commission, 80/08/22. 1p.
- --8009120480 Discusses position on Commission pilot program for procedural assistance, in response to 800731 request Program should not be considered as "funds for intervenors " AHEARNE, J. F. Commission 80/08/22. 1p.
- ---8009120483 Discusses position on Commission pilot program for procedural assistance, in response to 800791 request Program should not be considered as "funds for intervenors." AMEARNE, J.F. Commission. 80/08/22 ip.
- --8009120484 Discusses position on Commission pilot program for procedural assistance, in response to 800731 request Program should not be considered as "funds for intervenore." AHEARNE, J. F. Commission 80/08/22 ip.
- ---8009120485 Discusses position on Commission pilot program for procedural assistance, in response to 800731 request Program should not be considered as "funds for intervenors " AHEARNE, J. F. Commission 80/08/22. Ip
- --80091204B9 Discusses position on Commission pilot program for procedural assistance, in response to 800731 request Program should not be considered as "funds for intervenors" AHEARNE, J. F. Commission. 80/08/22 1p.
- --8009120494 Requests response to suggestion that NRC plans to implement pilot program for procedural assistance should be suspended due to inconsistency w/legislative history on intervenor funding.

  HCCDRHACK, M , BEVILL, T. , SATTERFIELD, D. House of Rep , Science & Technology. 80/07/31. 2pp.
- 8009130026 Forwards response to questions raised during Committee on Environ & Public Works 800228 hearing & UCB criticisms re ATMS safety HENDRIE, J M Commission 80/04/04 32pp
- --8009150030 Responds to questions re ATWS position Itr ACRS should reply to ltr at Apr meeting AEC/ACRS Itr exchanges & info paper on ATWS should be placed in PDR.
  HENDRIEJ H Atomic Energy Commission, Deputy Director for Technical Review (Pre-1975), 73/03/20 2pp.
- ---BO09150035 Responds to request for comments on methods for evaluating effectiveness of complete SARs. One round of questions is necessary to clarify details. Reduction of preparation & review time is prime concern of applicant in CP review HENDRIE, J M. Atomic Energy Commission, Deputy Director for Technical Review (Pra-1975). 72/04/14. 2pp.

- ---BO09180047 Comments on encl proposed rule re separate hearing on single issues Intolerable burdens will be imposed on AEC.w/delays in overall review of cases HEMDRIE.J M. Atomic Energy Commission, Deputy Director for Technical Review (Pre-1975), 72/11/15 ip
- --8009150052 Comments on encl proposed rule change providing for separate hearing on selected issue or issues. Change would affect licensing, Requests views from Director of Licensing. Forwarding its encl HUNTZING. L. M. Atomic Energy Commission 72/10/30. 5pg.
- --B009150054 Discusses implementation of position on BMR MBIV sealing sys. Bealing sys will be required to suppl MBIV for BMR plants from Duane Arnold Bhoreham & Fitzpatrick onward HENDRIE. J.M. Atomic Energy Commission. Deputy Director for Technical Review (Pre-1975). 73/02/27. 3pp.
- --8009180086 Discusses Calvert Cliffs' fuel densification analysis difficulties. Matter should be addressed in suppl for ACRB June meeting indicating that further info is forthcoming & will be evaluated. HENDRIE: J. M. Atomic Energy Commission. Deputy Director for Technical Review (Pre-1975). 73/04/19. ip
- --8009150061 Recommends encl proposition as test case for early const start on new plant HENDRIE,J.M. Atomic Energy Commission, Deputy Director for Technical Review (Pre-1973) 74/01/09. 1p
- ---8009150064 Describes proposed procedure for expedited licensing of facility near Charleston.RI. Early site acceptability review provides mechanism to expedite licensing process. Agreements W/state & utils on procedures are required to proceed. BALLARD.R L. Atomic Energy Commission. Directorate of Licensing. 74/01/07 App.
- ~~8009180090 Comments on working paper re BMR main steam line scaling sys. Urges deletion of phrase indicating that turbine stop valves should maintain integrity during SBE HENDRIEJ. M. Atomic Energy Commission, Deputy Director for Technical Review (Pre-1975). 74/07/23 4pp.
- 8009180410 Forwards responses to 800527 questions re into provided by NRC on 800501 concerning differences in role of NRC & Executive Branch in processing export requests. Supporting focumentation entil.

  AHEARNE, J.F. Commission. 80/08/22, 13pp.
- --8009150418 SECY-78-216A
  Forwards documents re proposed license for Transmuclear, Inc
  to export high-enriched U to Sweden.
  SHEALUR Office of International Programs, Director. 78/05/11.
- --8009180422 Submits conclusions re proposed license for Trensnuclear, int to export high-enriched U to Sweden. License issuance would be consistent w/Nuclear Nonproliferation Act.
  HORRER. N. Office of International Programs, Director 78/05/10.
- --BOO9150423 Provides comments on proposed license for Transnuclear, Inc to export high-enriched U to Sweden. Supporting documentation encl. TARNOFF, P State, Dept. of. 78/03/03. Spp.
- ---8009150428 Forwards revised analysis of Transnuclear, Inc application to export high-enriched U to Sweden, NOSENIO, L.V. State, Dept. of: Bureau of Oceans & Internati Environ. & Scientific Affairs 78/05/08. 17pp.
- --8009180433 Application by Transnuclear, Inc to export 21 053 kg U hexafluoride, enriched to max 93 90% U-235, to Sweden. End use statement encl MATSON.V. Transnuclear, Inc. 77/01/25 2pp.
- --8007150438 Forwards application for license to export 19.642 kg U-235, contained in 21 053 kg U ss U hexafluoride enriched to 93 3%, to Swaden. H/o encl. Proposed license encl. MATSON, V Transnuclear, Inc 77/01/25, 4pp

- -9009150442 Bubmits conclusions re Edlow Intl Co application to export BMM to Bwaden No math changed circumstances re application from those existing at time of issuance of XBNM-1074 & XBNM-1248. License may be issued MOCRE, N. Office of International Programs, Director 79/09/06.
- ---B009:50446 Advises of no meth changed circumstances re application from those sricting at time of issuance of XBNM-1532 License may be issued. Office of International Programs: Director 80/02/28.
- ---B009150448 Ack receipt of NRC 800501 response to 800327 ltr re difference in role of NRC & Executive Branch in processing export requests Requests add1 info HEINZ,J Senate, Banking, Housing & Urban Affairs 80/05/27
- 8009150521 Weekly info rept for wh ending 800829. REMN.T.A. Office of the Executive Director for Operations 80/09/04. 26pp.
- 8009i40644 Responds to 800619 ltr re impact of resident inspector program on resident inspector family unit. Every reasonable step will be taken to reduce personal hardships associated w/program, AMEARNE, J. F. Commission, 80/08/18, 5pp
- --- 9007160647 Expresses concerns re impact of resident inspector program on resident inspector family unit. Focuses on hidden costs of relocation. COOK.L. Affiliation Unknown. 80/06/19 5pp.
- 8009190569 Forwards estimate of resources required by NRC & Defense Nuclear Agency for investigation of interaction between platfromagnetic pulse & commercial nuclear plant eys DENION, H. R. Diffice of Nuclear Reactor Regulation, Director, 2pp. 80/09/10.
- S009270081 Comments & recommends actions in response to 800819 memo re new unresolved safety issues, BECY-BO-325. Issues of concern must be added to list of items requiring further study. Draft special rept to Congress incorporating concerns underway. SENTON, M.R. Office of Nuclear Reactor Regulation, Director 80/09/10. Spp.
- 8009300188 Weekly info rept for wk ending 800912. REPH.T.A. Office of the Executive Director for Operations 80/09/19. 25pp.
- BOOT300280 Discusses draft GAD rept, "Proposed Interim Consolidation of MRC." Agrees that scattered physical locations seriously affect MRC operations. DMB suggestion preferable to GAD plan. AMEZAMELJ.F. Commission. B0707/03. 2p.

#### NRC CONTRACTS AND MODIFICATIONS CONTRACT

- BOOPCOODE Notification of contract execution, Mod 2 to "Bhuttle Bus Byc." Contractor: Beltway Limousine Byc. Inc. FLYNY, H. J. Administrative Contracts Branch. NRC-10-80-372. BO/08/19. ip.
- --S009030088 Mod 2, changing daily schedule to "Shuttle Bus Svc."
  ROBERTSON, J. D. Baltway Limousine Service, Inc. MATTIA, M
  Administrative Centracts Branch. NRC-10-S0-372 80/08/19. Spp
- 800703020B Notification of contract execution. Mod 4 to "Kinematics of Translating Tornado Mindfields." Contractor.TX Tech Univ. HA0EY.H. Research Contracts Branch. FIN B-6177. NRC-04-77-016. 80/08/13. ip.
- --BOOTO30216 Med 4, granting no cost extension, to "Kinematics of Translating Tornado Hindfields " JONES, J.K. Texas Technologial College. HORTON, K.V. Research Contracts Branch. FIN 8-6177. NRG-04-77-016. B0/08/13. 2pp.
- 8009040448 Notification of contract execution: "Technical Assistance to Bupport NRC IE Personnel in Investigations of Incidents: "
  awarded to Parameter: Inc.
  BAISBENL. Research Contracts Branch. FIN 8-1270, NRC-05-80-251.
  80/07/02, ip.

- 8009100002 Notification of contract execution "Environ Monitoring Program H/8tate of MS," awarded to State of MS. BAIBDEN,L Research Contracts Branch FIN 8-1257 NRC-05-80-289 80/88/22 19
- --B009100003 Contract, "Environ Monitoring Program W/Btate of MS," awarded to State of MS COBB, A B Mississippi, State of MORTON, K V Branch FIN B-1237 NRC-05-80-289 80/08/22 9pp
- 8009100010 Notification of contract execution. Mod 3 to "Study of Grush Loads in Transportation Accidents " Contractor SRI Thei.

  HAIRBTON, C A Technical Assistance Contracts Branch FIN 8-6124

  NRC-03-78-084. 80/08/08 ip
- ---8009100012 Mod 3, modifying final rapt requirements to "Study of Crush Loads in Transportation Accidents." \* BRI International QLA001A.A.F Branch FIN B-6124 NRC-03-78-084 80/08/08 1p
- BOO910003B Notification of contract execution, Mod 10 to "Analysis of Hypothetical Accidents Resulting from Core Meltdown." Contractor:Battelle Columbus Labs MORTON K V. Research Contracts Branch FIN A-4067. NRC-04-76-293
- ---B009100041 Mod 10. adding funding & changing scope of work to "Analysis of Hypothetical Accidents Resulting from Core Meltdown."

  LUKZ.F. J. Battelle Mamorial Institute. Columbus Laboratories HORTON.K V. Research Contracts Branch FIN A-4067.

  NRC-04-76-293 80/08/11, ip.
- 8009100054 Notification of contract execution "Presentation of GE BAR/6 Design & Operation Courses," awarded to GE BAISDEN, L. Research Contracte Branch FIN 8-1224, NRC-05-80-282 80/08/18, 1p.
- --8009100061 Contract: "Presentation of GE BUR/& Design & Operation Gourses," awarded to OE. PIERCE.R.L & General Electric Co. MORTON, K V. Research Contracts Branch. FIN B-1224 NRC-05-80-282. BO/08/18. 4pp.
- S009100071 Notification of contract execution. Mod 9 to "Investigations in States of Stress in Crusts Under Northeastern US." Contractor. NY State Energy Research & Development Authority. MCRION, K.V. Research Contracts Branch FIN 8-3615. NRC-04-75-145 80/05/01, ip.
- ---B009100077 Mod 9.extending period of performance, to "Investigations in Btates of Stress in Grusts Under Northeastern US." PRIME,H J. New York, State of. MORTON,K.V. Research Contracts Stanch. FIN 8-3615 NRC-04-75-145.
- B009100405 Notification of contract execution. "Subscription to 1980 Edition of ABME Boiler & Pressure Vessel Code, Including Automatic Addenda Byc," awarded to ABME. COLEMAN, R. Administrative Contracts Branch. NRC-10-80-696. B0/08/22. 1p.
- --8009100409 Contract: "Bubscription to 1980 Edition of ASME Boiler & Pressure Vessel Code Including Automatic Addenda Svc." awarded to ASME.
  AGULERA, W.F. American Society of Mechanical Engineers.
  MATTIA:H J. Administrative Contracts Branch NRC-10-80-676-80/08/22 58pp.
- 8009110001 Notification of contract execution, Task Orders 1.2.3 & 4 to, "Technical Assistance to Bupport NRC IE Technical Personnel in Investigations of Incidents " Contractor: Parameter Inc.
  BAIBDEN.L. Research Contracts Branch. FIN B-1270 NRC-05-80-251.
  80/08/09. 1p.
- --8007i10002 Forwards Task Order 1.authorizing expenditure of funds currently obligated for expenses & in-house fees to "Technical Assistance to Support NRC IE Technical Personnel in Investigations of Incidents." HORTON, K. V. Research Contracts Branch FIN 8-1270. NRC-05-80-251 80/07/24. 3pp.
- --8007110003 Forwards Task Order 2. authorizing expenditure of funds currently obligated to provide assistance as technical consultant, to "Technical Assistance to Support NRC IE Technical Personnel in Investigations of Incidents." HORTON.K. V Research Contracts Branch FIR B-1270 NRC-05-80-251, 80/07/24, 5pp

- --8009110004 Forwards Task Order 3, authorizing expenditure of currently obligated funds to provide technical assistance & svcs.to "Technical Assistance to Support NRC IE Technical Personnel in Investigations of Incidents "MRRTON, K V Research Contracts Branch FIN B-1270 NRC-05-80-251 80/07/24 Spp
- --8009110005 Forwards Tast Order 4, authorizing expanditure of currently obligated funds to provide technical assistance & svcs, to "Technical Assistance to Bupport NRC IE Technical Personnel in Investigations of Incidents"
  HORTON, K. V. Research Contracts Branch FIN 8-1270
  NRC-05-80-251. 80/08/07. 4pp
- 8009110022 Notification of contract execution "Conduct courses entitled "Medical Uses of Radionuclides for State Ragulatory Personnel," awarded to Memorial Sloan-Kettering Cancer Ctr FLYNN. M J Administrative Contracts Branch FIN 8-5090 NRC-06-80-302 80/07/28. 1p.
- --B009110025 Contract. "Conduct courses entitled "Medical Use of Radionuclides For State Regulatory Personnel" awarded to Remortal Bloan-Kettering Cancer Ctr # Hemortal Bloan-Kettering Cancer Center New York, NY MATTIA, M J Administrative Contracts Branch FIN B-5090 NRC-06-80-302 80/07/28 67pp.
- 8009110215 Notification of contract execution. Mod 1 to "Development of Automated Vendor Belection Sys " Contractor: Cassar Associates HAGAN. T.F. Administrative Contracts Branch FIN 8-1214. NRC-05-80-253 80/07/29. App
- --8009110222 Mad 1.correcting dollar amount on cover sheet & clarifying delivery schedule.to "Davelopment of Automated Vendor Selection Bys " QABBER,E.R Qasser Associates, MATTIA,M J Administrative Contracts Branch FIN 8-1214 NRC-05-80-253 80/07/28 3pp.
- 8009110293 Notification of contract siscution. Hod 5 to "FLECHT-SEABET." Contractors: Wastinghouse & EFRI HDRTON.K.V Research Contracts Branch. FIN 9-6204. NRC-04-77-127 80/08/19 ip
- --8009110256 Mod 5, providing addi funds. to "FLECHT-BEAGET" FARRAR: A C Electric Powar Research Institute. MORTON, K V. Research Contracts Branch \* Westinghouse Electric Corp FIN B-6204 NRC-04-77-127 80/08/19. 2pp
- 8007110331 Notification of contract execution, Mod 3 to "TMI Special Inquiry Team " Contractor: BC Doyle, MORTON: K V Research Contracts Brench, NRC-17-79-453 80/08/25 ip.
- ---8009110338 Mod 3.deobligating funds to "TMI Special Inquiry Team "
  DOYLE, B. C. Bernard C. Doyle MORTON, K. V. Research Contracts
  Branch NRC-17-79-453 80/08/23. tp
- 8009110346 Notification of contract execution "Environ Monitoring Program W-State of MI," awarded to State of MI BAIBDEN.L. Research Contracts Branch, FIN 8-1244, NRC-05-08-284, 80/08/22 1p
- --8009110350 Contract. "Environ Monitoring Program W/State of MI."
  awarded to State of MI.
  REIZEN, M S Hichigan, State of MORTON, K V Research Contracts
  Branch FIN B-1244 NRC-05-80-284. 80/08/22 9pp
- 8009110375 Notification of contract execution. Mod 6 to "Bafeguards for High Lavel Wasts Repositories" Contractors Science Applications. Inc. FORTER, J. H. Technical Assistance Contracts Branch. FIN 8-6376-9. NRC-02-79-035 80/07/31. ip
- --B009i10379 Mod 6, extending period of performance & revising Article I. to "Bafeguards for High Level Waste Repositories" TREVING. T. Beience Applications, Inc. OLAGOLA.A.F. Technical Assistance Contracts Branch. FIN 8-6376-9 NRC-02-79-035
- 8009110409 Notification of contract execution, Hod 3 to "Btudy of IN Fault Locations .. New Madrid, MO Region " Contractor IN Univ HA9EV, H Research Contracts Branch FIN E-6262 NRC-04-77-164 80/08/25, 2pp
- --BO09110410 Mod 3.extending period of performance w/add1 funds, to "Ekudy of IN Fault Locations . New Madrid, MD Region "MULHOLLAND.) Indiana Univ MORTON, K, V. Research Contracts Branch FIN B-6262, NRC-04-77-164 B0/08/25, 3pp

- BO09110412 Notification of contract closeout for "Madular Appreach to Fault Tree & Reliability Analysis " Contractor MIT. HAGEY, H Research Contracts Branch FIN 8-6256 80/08/04. 2pp.
- 8009120004 Notification of contract execution, Mod 3 to "Caardination of Cooperative Beismotectonic Study in New Madrid Area." Contractor St Louis Univ. HADEY, H. Research Contracts Branch. FIN 8-6335. NRC-04-78-251 80/09/03 1p
- ---B009120007 Mod 3.extending period of performance, to "Coordination of Cooperative Beismotectonic Study in New Madrid Area." PATTON,L M. 6t Louis Univ MORTON,K,V Research Contracts Branch. FIN B-6335 NRC-04-76-251 B0/09/03. 2pp.
- 8007120010 Notification of contract execution. Hod 3 to "Evaluation of Oross Operator Error Rates Based on Past Experience in Commercial Nuclear Power Plants." Contractor IA State Univ. BROMBERO, B Research Contracts Branch FIN 8-6305 NRC-04-78-221 80/08/27 to
- --8009120012 Mod 3.extending period of performance, to "Evaluation of Oross Operator Error Rates Based on Past Experience in Commercial Nuclear Power Plants "
  HABBROOK, R. E. Iowa Btate Univ HORTON, K. V. Research Contracts
  Branch. FIN 8-6305. NRC-04-78-221. 80/08/27 2pp.
- 8009120013 Notification of contract execution, Mpd 1 to "Furnish Sand & Dust Data Base Occurrences for US." Contractor. NDAA.

  OUSTAVE, R P. Research Contracts Branch FIN 8-10748

  NRC-01-79-015 80/08/15 1p
- --8007120014 Mod 1, extending period of performance, to "Furnish Band & Dust Data Base Occurrences for US"

  MITCHELL, D. B. Commerce, Dept. of National Oceanographic & Akmospheric Administration. HORTON, K.V. Research Contracts Branca FIN B-1074S NRC-01-78-015 90/08/15. 1p.
- 8009120017 Notification of contract execution, Mod 6 to "Study of Earthquake Hazards in NY State & Adjacent Areas "Contractor: NY State Energy R&D Authority MORTON, K. V Research Contracts Branch. FIN 8-6046 NRG-04-76-369.
- ---8009120019 Mod 6, extending period of performance & increasing funds, to "Btudy of Earthquake Hazards in NY State & Adjacent Areas." PRIME, M. J. New York, State et. HORTUN, K. V. Research Contracts Branch FIN B-6046 NRC-04-76-369 B0/08/01 1p
- 8009120023 Notification of contract execution, Mod 3 to "Seismicity & Tectonic Relationship for Upper Great Lakes Precambrian Bhisid Province." Contractor MI Technological Univ BROMBERO, B Research Contracts Branch, FIN 8-6174. NRC-04-77-112 80/08/28 ip.
- ---8009120033 Mod 3.extending period of performance, to "Seismicity & Tectonic Relationship for Upper Great Lakes Precambrian Shield Province"

  EVANS.T.P. Hichigen Technological Univ. MORTON, K. V. Research Contracts Branch FIN 8-6174, NRC-04-77-112 80/08/28 2pp
- 8009120028 Notification of contract execution: "Review of Staffing Requirements for Near-Term OL Facilities:" awarded to BioTechnology. Inc.
  MILES.E. Purchasing Section FIN 8-75-2. NRC-03-80-147. 80/08/18.
  1p.
- --BO09120037 Contract "Review of Staffing Requirements for Mear-Term OL Facilities," awarded to BioTechnology, Inc BHANAHAN, W P Biotechnology, Inc PERLMAN, J. Administrative Contracts Branch, FIN B-75-2, NRC-03-08-147, B0/08/18, 5pp
- 8009120068 Notification of contract execution: "Environ Monitoring Program W/State of GA." Contractor State of GA BAIBBENLL. Research Contracts Branch FIN 8-5203. NRC-05-90-279. 80/09/03. ip.
- --8009120075 Contract: "Environ Monitoring Program W/Stats of GA," awarded to State of GA
  LEDBETTER.L. Georgia: State of, MORTON.K.V Research Contracts
  Branch FIN 8-5203. NRC-05-80-279 80/09/03 14pp
- 8009120070 Notification of contract execution, Mod 2 to "Technical Editing Sycs for DESMO Fuel," Contractor JF Holman 4 Co. HARTIN.L.C. Technical Assistance Contracts Branch. FIN B-1492 NRC-02-76-290 80/07/21. ip

- --B009120083 Mod 2, deabligating funds, to "Technical Editing Svcs for QCBMO Fuel" HOLMAN, J.F. John F. Holman & Co., Inc. DOUOHERTY, D. J. Technical Assistance Contracts Branch FIN B-1492 NRC-02-76-290 B0/07/21. 1p
- 8009120104 Notification of contract execution "Gomparative Review of Risk Assessments, Bafety Coals & Related Concepts For Commercial Nuclear Power & Alternative Sources of Energy, " awarded to Inti Flanning Mgt HOYLE.A. Administrative Contracts Branch FIN 8-7501 NRC-03-80-146 80/08/18 ip
- --BOOFIZO115 Contract. "Comparative Review of Risk Assessments, Bafety Ocals & Related Concepts For Commercial Nuclear Power & Atternative Bources of Energy," awarded to Intl Planning Mgt. s International Planning Management. PERLMAN, J Administrative Contracts Branch, FIN 8-7501. NRC-03-80-146 80/08/18 App.
- 6009120559 Notification of contract execution "Electrostatic Copying Sycs." swarded to Literature Research Co. FLYNN.H.J. Administrative Contracts Branch NRC-17-80-450 80/08/27 1g
- BOO9120665 Notification of contract execution. Mod ii to "Document Control Bys" " Control Con
- BOOPISD14D Notification of contract execution, Med 3 to "Economic Consulting Byce in Connection H/Stanislaus Nuclear Unit "Contractor P Quimann. QLAOCAA F. Technical Assistance Contracts Branch. FIN E-6521, NRC-03-79-113.
- --B009150143 Mod 5.extending period of performance & increasing ceiling amount, to "Economic Consulting Bycs in Connection W/ Stantslaus Nyclear Unit," SUMANN.P. GUTEN, Peter. GLAGGLA: A F. Technical Assistance Contracts Brench. FIN 8-4521. NRC-03-79-113. 80/04/30 ip.
- 9009180146 Notification of contract execution, Mod 10 to "Review of Environ Impacts of High Level Radwaste Mgt " Contractor. Tetnskron. BKITH,P.A. Technical Assistance Contracts Branch. NRC-02-77-165. 80/07/21. ip.
- --8009150147 Mod 10, modifying delivery date of Bubtask 2 rept & to key personnel clause; to "Review of Environ Impacts of High Level Radwaste Mgt."
  COMEN.B. Teknekron, Inc. DOUGHERTY, D. J. Technical Assistance Contracts Branch, NRC-02-77-165, 80/07/21 1p.
- BOOFERGITA Notification of contract execution "Development of Nuclear Reactor Plant Data Bank," awarded to Small Business Administration, Subcontractor: Technology Development of CA, Inc. JACOBB.A. Research Contracts Branch, FIN 8-7077, NRC-04-80-215, BO/08/22, 1p
- --BO09150178 Contract: "Development of Nuclear Power Plant Data Bank" awarded to Small Business Administration. Subcontractor Tecnology Development of CA: Inc HOPHERSON: H. Small Business Administration. CRACRAFT. T. M Technology Development of California. Inc. HORTON, K V. Research Contracts Branch. FIN 8-7077. NRC-04-80-215 80/08/22 64pp
- 8009150409 Notification of contract execution. Mod 1 to "Assessment of Strength of Ice Condenser Containment."
  Contractor: R&D Associates.
  FLEENRR. C. M. Administrative Contracts Branch FIN 8-1314.
  NRC-17-80-451. B9/08/25 1p.
- BOO9160485 Notification of contract execution Hod 4 to "Wind Tunnel Heasurements of Dispersion & Turbulance in Wakes of Muclear Reactor Plants." Contractor: CO State Univ MARY, H. Research Contracts Branch. FIN 8-5829. NRC-04-76-236-80/08/22. ip

- --B009160488 Mod 4.providing add1 funds & extending period of performance to "Hind Tunnel Measurements of Dispersion & Turbulence in Wates of Nuclear Reactor Plants "BROWN.JF Colorado State Univ HORTON,K V Research Contracts Branch. FIN B-5829 NRC-04-76-236 80/08/22 5pp
- BOO9150491 Notification of contract execution.Mod 4 to "Assessing Capability of Existing Pu Facilities to Withstand Natural Phenomena." Contractor NK Newmark OLAOOLA.A.F Technical Assistance Contracts Branch FIN B-6150-9
- --B009i60475 Mod 4.extending period of performance to "Assessing Capability of Existing Pu Facilities to Withstand Natural Phenomena"

  \* N K Newmert Consulting Engineering Services GLACOLA.A F. Technical Assistance Contracts Branch FIN B-6150-9 NRC-03-78-150. B0/07/29 1p
- 8009160511 Notification of contract execution, Mod 4 to "Advanced Process Control " Contractor. Belence Applications, Inc FOSTER, J M Technical Assistance Contracts Branch FIN 8-6930-0 NRC-02-79-043-1. 80/07/21 1p
- --8009160315 Mod 4.adding accounting & appropriations date contained in Item 10 to "Advanced Process Control." # Brience Applications, Inc. DOUGHERTY, D J Technical Assistance Contracts Branch FIN 8-6930-0 NRC-02-79-043-1 80/07/21 ip
- 8009180143 Notification of contract execution MoS 8 to "Maint of Data General Corp C-330 Computers & Associated Paripherals " Contractor Data Consultants Inc MERCHALLA K Administrative Contracts Branch NRC-10-77-196 80/08/28 Ip
- --8009180150 Mod B.correcting effective date of Mod 7 to "Maint of Data Qeneral Corp G-330 Computers & Associated Peripherals " \* Data Consultants.Inc HATTIA.M J Administrative Contracts Branch NRC-10-77-196. 80/08/28 ip
- 8009180159 Notification of contract execution Hod 11 to "Document Control Bys." Contractor TERA Advanced Svcs Corp LEBD.C D Technical Assistance Contracts Branch NRC-10-78-580 80/09/04 1p.
- --8009180165 Mod 11. increasing funds, to "Document Control Bys "
  \* TERA Corp. MATTIA, M.J. Administrative Contracts Branch
  NRC-10-78-580. 80/09/04. 2pp
- 8009180167 Notification of contract execution Mod 1 to "Publication Distribution Syce " Contractor Computer Data Sys Inc HAGAN, T F Administrative Contracts Branch NRC-10-80-362 80/09/08 1p
- ---8009180191 Mod 1.adding requirement for add1 storage capacity & increasing funds to "Publication Distribution Bycs "
  COMBB.C. Computer Data Systems. Inc. MATTIA.M.J Administrative Contracts Branch. NRC-10-80-362 80/09/08
- 8009180207 Notification of contract execution. "Bource Term Characterization Resulting from Explosively-Caused Becondary Violations of Spant Fuel Chipping Casks." awarded to BMI. HOLLETT, B. Research Contracts Branch. FIN 8-6710 NRC-04-80-180 80/09/03 1p.
- --8009180217 Contract. "Source Term Characterization Resulting from Explosively-Caused Secondary Violations of Spent Fuel Shipping Casks:" awarded to BMI LUKZ, F. J. Battells Hemorial Institute. Columbus Laboratories HORTON, K. V. Research Contracts Branch FIN B-6710. NRC-04-80-180, 80/09/03 18pp.
- 8009180320 Nabification of contract execution, Mod 3 to "KY-70 Secure Voice Terminals," Contractor Natl Security Agency MEDROWLA, K. Administrative Contracts Branch. NRC-10-77-170. 80/04/04 ip
- ---B009180329 Mod 3; decreasing total amount of agreement & completing classous action to "KY-70 Secure Voice Terminals " DAVIEB,D.L. National Becurity Agency MATTIA-M.J Administrative Contracts Branch NRC-10-77-170 80/09/04, 1p.
- BOO9190051 Notification of contract execution Hod 3 to "Union Carbide Urayan Mill Tailings Evaluation " Contractor, Geotechnical Engineers: Inc HAIRSTON, C. A. Technical Assistance Contracts Dranch FIN B-4926 NRC-02-79-035 80/08/21 1p

- ---8009190057 Mod 3.extending period of performance.to "Union Carbide Uravan Hill Tailings Evaluation."

  LAQATTA.D P. Geotechnical Engineers.Inc HAIRSTON.C.A Technical Assistance Contracts Branch FIN B-6926, NRC-02-79-055 80/08/21 in
- 8009190188 Notification of contract execution Mod 6 to "Oncall Maint for NRC Computer Peripheral Equipment " Contractor:Computer Bys Bupport Corp MEDROW,L.A.K. Administrative Contracts Branch NRC-10-79-395 80/08/28. 1p
- --8009190190 Mod 6.correcting effective date of Mod 9.to "Oncall Maint for NRC Computer Peripheral Equipment" \* Computer Systems Support Corp HATTIA.M J. Administrative Contracts Branch. NRC-10-79-375. 80/08/28 p
- 8009190702 Notification of contract execution. Mod 4 to "Development & Implementation of Flaw Analysis Sys Based on Synthetic Aperture Ultrasonic Imaging Technique " Contractor: Southwest Research Inst HOLLETT'S Research Contracts Branch FIN 8-3605 NRC-04-77-145. 80/09/29. ip
- BO09190727 Notification of contract execution, Mos 9 to "Critical Experiments. Measurements & Analysis to Establish Crack Arrest Methodology for Nuclear Pressure Vessel Steels." Contractor Battelle Calumbus Labs MORTON.K. V Research Contracts Branch. FIN A-4046 NRC-04-76-293. BO/08/29 1p
- ---BO09190738 Mod 9, increasing morkscope & providing add1 funding to, "Critical Experiments Measurements & Analysis to Establish Crack Arrest Methodology for Nuclear Pressure Vessel Bteels."

  LUKZ, F. J. Battelle Memorial Institute, Columbus Laboratories HORTON-K. V Research Contracts Branch. FIN A-4046, NRC-04-74-293. B0/08/29. ip.
- 8009230157 Notification of contract execution. Mod 1 to "Licensing Assistance/Tailings Mgt Program Technical Evaluation." Contractor.J.H Klainfalder & Associates HAIRSTON.C A. Technical Assistance Contracts Branch. NRC-02-79-031. 80/08/20 ip
- --BOO7230161 Mpd i.extending period of parformance to B10707 to,
  "Licensing Assistance/Tailings Mgt Program Technical
  Evaluation"
  KLEINFELDER, J. J H Kleinfelder & Associates. GLACOLA, A.F.
  Technical Assistance Contracts Branch, NRC-02-77-031 80/08/20
- 8009230354 Notification of contract execution. Mod 2 to "Bafety Assessment of Concrete Nuclear Structures " Contractor: HIT BROMBERO, B Research Contracts Branch. FIN 8-6618 NRC-04-79-181 80/04/01 ip.
- --8009230359 Mod 2.extending period of performance to "Safety Assessment of Concrete Nuclear Structures."

  DUMMER: 9 H. Hassachusetts Institute of Technology MORTON, K. V. Research Contracts Branch. FIN B-6618 NRC-04-79-181 80/04/01 2pp
- 8009230364 Notification of contract execution. Mod 4 to "Spismological Study of Northern Extent of New Madrid Spismic Zone."
  Contractor: Baint Louis Univ.
  BROWSERG.B. Research Contracts Branch. FIN 8-5964 NRC-04-76-282 80/08/26.
- --8009230372 Mod 4, increasing funds & estending period of performance, to "Belamplogical Bludy of Northern Extent of New Madrid Seismic Zone" STANDER: B J. St. Louis Univ MORTON, K, V Research Contracts Branch FIN 8-5944, NRC-04-76-282, 80/08/26 App
- 8009230751 Notification of contract execution Mod 5 to "Seismotectonic Study of New England & Adjacent Areas." Contractor Boston College,

  JACOBBIA. Research Contracts Branch. FIN 8~5961 NRC~04-76-291,
  80/08/27. Ip
- --8009230755 Mod 5, extending pariod of parformance & increasing funds & workscope to "Seismotectonic Study of New England & Adjacent Areas."
  SMITH, J. R. Boston College, MORTON, K. V. Research Contracts Branch Fix 8-5961, NRC-04-76-291 80/08/27 7pp

- B009230768 Notification of contract execution Mod 1 to "Eastern TN/ Western NC Regional Esismic Network." Contractor: Hemphia State Univ HA0EY.H Research Contracts Branch. FIN 8-6675 NRC-04-79-214 B0/08/27 1p
- ---8009230771 Mod 1.extending pariod of parformance until 801130.to
  "Eastern TN/Mastern NC Regional Seismic Network."
  CARPENTER.T 0 Hemphis State Univ MORTON.K.V Research
  Contracts Branch FIN 8-6675 NRC-04-79-214 80/08/27. 2pp.
- B009230774 Notification of contract execution. Mod 3 to "Biructural Framework of MS Embayment of Southern IL." Contractor Univ of IL at Urbana HAGEY. H Research Contracts Branch FIN B-6251 NRC-04-77-159. 80/08/29. 1p.
- --8009230777 Mod 3.estending period of performance & increasing funds.ts "Btructural Framework of MS Embayment of Southern IL," BRADY.R.W Illinois, Univ. of, Urbana-Champaign MORTON, K.V. Research Contracts Branch FIN 8-6251 NRC-04-77-159, 80/08/27
- 8009240023 Notification of contract execution "Coordination of Cooperative Organizations Participating in Geological, Ocophysical & Beismological Studies," awarded to 8t Louis Univ WOLLETTS, Research Contracts Branch FIN 8-7242 NRC-04-80-229, 80/09/03, 1p
- ~-8009240028 Contract "Coordination of Gooperative Organizations Participating in Geological, Geophysical & Seismological Bitudies," awarded to St Louis Univ STAUDER, W. St. Louis Univ. MORTON, K V. Research Contracts Branch FIN 8-7242. NRC-04-80-229. 80/09/03. 5pp.
- BO09240034 Notification of contract execution: "Fission Product Transport Analysis," awarded to Battelle Columbis Labs. HAGEY.H. Research Contracts Branch. FIN 8-6747 NRC-04-80-177. 80/09709. ip.
- --8009240038 Contract. "Fission Product Transport Analysis," awarded to Battelle Columbus Lebs RICHARDBON, T. F. Battelle Memorial Institute, Columbus Laboratories, MORTON, K. V. Research Contracts Branch. FIN 8-6747, NRC-04-80-177. 80/09/09. 6pp
- BOOTE40065 Notification of contract execution. Hod & to "Std Containers for BNM Btorage, Transfer & Measurement," Contractor: IRT Cosp., QUBTAVE, R. P. Research Contracts Branch. FIN B-1051. NRC~01-78-001. BO/08/12 1p.
- ---8009240069 Mod 6, providing no cost extension to "Std Containers for BM Storage, Transfer & Measurement."

  MCVEIN.J. IRT Corp MORTON, K. V. Research Contracts Branch. FIN 8-1051 NRC-01-78-001 80/08/12 ip.
- BOO9240073 Notification of contract execution. "Independent Assessment: Destructive Testing & Analysis." Contractor: Franklin Inst. BAIBDEN, L. Research Contracts Branch. FIN.B-1212 NRC-05-79-253 BO/08/21. 1p.
- ---8009240079 Forwards Contract NRC-05-79-253, Task Order A, authorizing #25,000,00 to provide assistance in systematic review of responses to IE Bulletin 79-018. HORTON K.V. Research Contracts Branch, FIN 8-1212. NRC-05-79-253. 80/07/22 4pp.
- 9009240123 Notification of contract execution: "Wabash Valley Seismic Profile," awarded to Purdue Research Foundation. MCLLETT, B Research Contracts Branch. FIN B-7223. NRC-04-80-224 B0/09/08. ip
- --B009240130 Contract: "Mabash Vailey Seismic Profile," awarded to Purdua Research Foundation, GREENGEN, R.A. Purdua Research Foundation. MORTON, K.V. Research Contracts Branch. FIN 8-7223, NRC-04-80-224, 80/09/08, 17pp.
- 8009250258 Notification of contract execution, Mod 7 to "Svcs of LR Johnson on ASLAP," Contractor: Univ of VA COLEMAN, R. Administrative Contracts Branch NRC-10-75-140 80/09/01. 19
- ---8009250263 Mod 7, extending period of performance & providing complete funding adjustment to "Sycs of MR Johnson on ABLAP"

  " Virginia: Univ. of. MATTIA:N J Administrative Contracts Branch. NRC-10-75-140. 80/09/01. 1p.

- BOOP250493 Notification of contract execution Mod 5 to "Study of Consumer Products Containing Radioactive Hatl " Contractor Science Applications Inc HAIRSTON: G Technical Assistance Contracts Branch FIN B-0280 NRC-02-78-045, 80/08/15 Ip
- --8009250497 Mod 5, providing due dates for Task 2 repts, to "8tudy of Consumer Products Containing Radioactive Matl " MCDOMALD, R J. Science Applications, Inc QLAODLA, A F Technical Assistance Contracts Branch FIN 8-0260 NRC-02-78-045 80/08/15, ip.
- 8009260229 Notification of contract execution Hod 1 to "Development of Automated Vendor Belection Bys." Contractor Gasser Associates.

  1440AN, T.F. Administrative Contracts Branch FIN B-1214

  NRC-05-80-253 80/07/28 1p
- 8009260232 Notification of contract execution Mod 2 to "Ogneral Ogglogy, Ogglogical Survey of AL, Univ of AL. BROMBERG. B. Research Contracts Branch. FIN B-6617 80/09/04. 1p.
- --8009260238 Mod 02.extending period of performance & adding addl funds, to "General Geology, Geophysics & Beismicity of Northwest AL "
  - AL F.
    JUINER, T. J. Alebana, State of MORTON, K. V. Research Contracts
    Branch FIN 8-6617 NRC-04-78-262 80/09/04 2pp.
- 8007260243 Netification of contract execution Mod 1 to "Habash Valley Seismic Profile". Contractor Purdue Research Foundation WOLLEYT.S. Research Contracts Branch. FIN 8-7223 80/09/10 1p.
- --8009260247 Mod 1.increasing FY80 funding.to "Wabash Velley Seismic Profile". = Purdue Research Foundation MORTON.K V Research Contracts Branch, FIN 8-7223 NRC-04-80-224 80/09/10, 1p.
- BOO9260676 Notification of contract execution, Mod 2 to "Two Phase Flow Aspects of Reactor Bafety " Contractor: Dartmouth College HAIRSTON.C. Technical Assistance Contracts Branch FIN B-6525, IRC-03-77-102 80/08/29. 1p.
- 8009290139 Notification of contract execution: "Environ Monitoring Pregram w/State of SC." awarded to State of SC. BAISDEN.L. Research Contracts Branch. FIN B-5112 NRC-05-80-273 80/09/09. 1p.
- 800730093 Notification of contract execution, Mod 1 to "Keypunch & Verification Svcs." Contractor: Small Business Administration, Subcontractor: Intl Business SVc, Inc. W100185.E. Administrative Contracts Branch. NRC-10-80-695 80/09/03. ip
- BOOT300118 Notification of contract execution, Med 1 to "Nondestructive Examination Mobile Van.Region 1." Contractor Mobile Sys. MIGGINS.E. Administrative Contracts Branch. NRC-05-80-259 BO/09/02 1s.
- BO09300193 Notification of contract execution, Mod 8 to "Design of IFMIS," Contractor Small Business Administration, Business Educator: Technosociates, Inc. HAOMI, T.F. Administrative Contracts Branch, NRC-10-80-395, B0/09/09 1p.

- --B00930019B Hod B, increasing funds, to "Design of IFMIS "
  TUNBTALL, J E Babil Business Administration MATTIA, M J
  Administrative Contracts Branch YTHIER, P Technosocciates, Inc
  NRC-10-B0-395 B0/09/05 3pp
- S009300206 Natification of contract execution.Mod 1 to "ADP Sys Support " Contractor Smell Business Administration, Subcontractor Technossociates.Inc. FLYNN.M J Administrative Contracts Branch NRC-10-80-673 B0/09/09 1p
- --8009300209 Hod i, changing dates for project status repts & adding consultant category, to "ADP Bys Support" TUNSTALL, J E Gmail Business Administration YTHIER, P Technassociates, Inc MATILAM J Administrative Contracts Branch NRC-10-80-673 80/09/09 3pp
- 8007300257 Notification of contract execution: "Containment Safety Under Internal Explosions: " awarded to MIT JACOBS.A. Research Contracts Branch FIN 8-7085 NRC-04-80-194 80/09/12 1p
- --8009300264 Contract: "Containment Safety Under Internal Explosions" awarded to MIT.

  DUMMER, G. H. Massachusetts Institute of Technology MORTON, K. V. Research Contracts Branch FIN 2-7085 NRC-04-80-194 80/09/12 650.
- BOO9300271 Notification of contract execution "Prepare Summary of NUREO-0578, Absorption of Krypton & Xenon on Activated Carbon," awarded to Univ of Pittsburgh, FLEENOR, C. M. Administrative Contracts Branch FIN B-1557 NRC-11-80-403. 80/09/ii ip
- --8009300276 Contract: "Prepare Bummary of NUREG-0678 Absorption of Krypton & Xenon on Activated Carbon." awarded to Univ of Pittsburgh UNDERHILL, D H Pittsburgh Univ. of, PERLMAN, J Administrative Contracts Branch FIN 8-1557 NRG-11-80-403 80/09/11 4ρρ
- 9007300572 Notification fo contract execution, Mod 1 to "Coordination of Cooperative Organizations Participating in Geological, Geophysical & Beismological Studies, "Contractor Bt Louis Univ.

  WOLLETT, B. Research Contracts Branch FIN 8-7242 NRC-04-80-229 80/09/09 ip
- --B009G00597 Mod 1, increasing funds & extending period of performance to "Coordination of Guoperative Organizations Participating in Geological Geophysical & Beismological Studies "

  8 Bt. Louis Univ. MORTON, K V Research Contracts Branch FIN B-7242 NRC-04-80-229 80/09/09.
- 8009300393 Notification of contract execution: "Environ Assessments of Burface & Groundwater Impacts From U Racovery Operations," awarded to Ott Mater Engineers, Inc. HAIRSTON, C Technical Assistance Contracts Branch NRG-02-80-028-01, 80/09/04, ip.
- ---B009300595 Contract "Environ Assessments of Surface & Groundweter Impacts from U Recovery Operations," awarded to Ott Hater Engineers Inc.
  OTT.R.F. Ott Hater Engineers Inc. DOUGHERTY.D J Technical Assistance Contracts Branch. NRC-02-80-028-01. 80/09/04 1888
- DISCLOSURE FINANCIAL DISCLOSURE INFORMATION
- BOO9180101 Advises that review of Confidential Statement of Employment & Financial Interests revealed vested interest in Union Carbide Co. Exemption granted from requirements of IOCFRO 733-21
  DIRCKS.W.J. Office of Nuclear Material Safety & Safeguards
  BO/08/19 10
- 8009250055 Grants examption from provisions of iOCFRO 735-21 allowing for participation in matters affecting Bachtel Power Corp. while having vested interest in company employee trust fund ROSS:D Division of Systems Integration. 80/09/03 ip.
- POIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES
- 7903230216 Confirms actions undertaken on 790131 re use of licensed byproduct mat1 by individuals not authorized as users. Corrective actions will halt use of mat1. secure licensed mat1 on hand & resume use only by approval REPPLER, J. C. Region 3. Chicago. Office of the Director. 79/02/01 is.

- 7904120080 Discusses IE insp of License 12-18044-01 on 790131-0202 & forwards notice of violation KEPPLER. J G Region 3. Chicago. Office of the Director 79/04/05
- --7404120082 Notice of violation from insp on 740131-0202 Noncompliance noted procured seven bulk shipments of Xe-133 marked "Not for Human Use." no licensed supervision of licensed mati & no program to measure radioactive mati in air \* NRC Regional Offices 79/04/05 Spp
- 7904170409 Schedules 790323 meeting to discuss noncompliance items noted in imap of Licenses 4B-17466-01MD & 12-18044-01MD KEPPLER. J G. Region 3. Chicago. Office of the Director 79/03/19
- 7904170412 Schedules 790323 meeting to discuss noncompliance items noted in insp of License 48-17466-01MD KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/19
- 7904010084 Ack receipt of 790306 itr informing NRC of steps taken to correct violations noted in IE insp of License 08-18308-01MD on 790208 on 790208 MCCLINTOCK,R O Region 1, Philadelphia, Office of the Director 79/03/23
- --7906010086 Responds to NRC 790223 ltr re violation noted in IE insp of License 08-18308-01MD on 780208 Corrective actions no further transfers of Xe-133 to individuals lacking necessary license info & thert w/licensing info posted IRWIN.R F Pharmatopes, Inc 79/03/06 2pp.
- ---790&010088 Discusses IE insp 30-14826-01 of License 08-18308-01 on 790208 & forwards notice of violation MCCLINTOCK.R.O Region 1, Philadelphia, Office of the Director, 79/02/23 2pp
- ---7906010091 Notice of violation from insp on 790208 Noncompliance noted shipped X=-133 to hosp w/o verifying that hosp license authorized X=-133.

  \* Region 1, Philadelphia, Office of the Director 79/02/23 1p
- 7905290524 Ack receipt of 790425 ltr informing NRC of steps taken to correct violations noted in IE insp of License 12-18044-01 on 790405 con 790405
  KEPPLER, J. & Region 3, Chicago, Office of the Director 79/05/18
- --7906290556 Responds to NRC 790405 itr re violations noted in IE insp of VOAYUSSO RESPONSE to ARK /74040 IEFF & VIGLENIS HOUSE License 12-18044-01 an 790405 Corrective actions will not buy Xe-123 w/o label "for human use," bidassay procedure changed & bired add1 personnel ZIMKER.A.M Nuclear Pharmacy, Inc 79/04/25 7pp
- 7910020407 Grants extension to 791022 for submission of response to 790817 notice of violation served on Nuclear Pharmacy Inc STELLO.V Office of Inspection & Enforcement, Office of the Director 79709707 2pp
- 7911090069 Discusses IE insp of License 12-17910-01MD on 790926 & 1010 & forwards notice of violation DAVIS.A B Region 3. Chicago. Fuel Facility & Materials Safety Branch 12-17910-01MD 79/10/25 ip
- --7911090077 Notice of violation from insp on 790926 & 1010 Noncompliance noted failure to make surveys re radiation exposure to personnel extramities failure to made monthly thyroid readings of person using I-131 & failure to make lab survey # Region 3, Chicago, Office of the Director 12-17910-01MB 79/10/25 1p
- 7912040149 Ack receipt of 791105 ltr informing NRC of steps taken to correct violation noted in IE insp of License 12-17190-01MD on 791025

  DAVIGA B Region 3, Chicago, Fuel Facility & Materials Gafety Branch, 79/11/21 ip
- --7912040156 Responds to NRC 791025 ltr re violations noted in IE insp of License 12-17190-01MD on 791025 Corrective actions evaluations on personnel ring badge readings for 781225-791024 & 0625-0725 sent to R S.Landauer.JR & Co for records COMER.F H Pharmaco Nuclear. Inc 79/11/05 4pp
- 7912180310 Discusses IE insp of License 37-18461-01 MD on 790828-29 No noncompliance noted Major areas inspected review of circumstances surrounding receipt of package containing Reclintock, R G Region 1: Philadelphia: Office of the Director 79/10/05. ip

- 7912190014 Ack receipt of 790917 ltr informing NRC of steps taken to correct violation noted of License 37-18461-01MD on 790618 ORIER B H Region i. Philadelphia. Office of the Director 79/10/03 ip
- --7912190023 Responds to NRC 790910 ltr re violation noted in IE insplot License 37-18461-01MD on 790618 Corrective actions restricted area workers will be instructed additor will survey radiation hazards & syringe shields will be used. DESSEL.8 Nuclear Pharmacy, Inc. 79/09/17 4pp
- --7912190047 Responds to NRC 790821 ltr re violation noted in IE insportions 37-18461-01MD on 790618 Corrective actions: sent copy of guidelines for radwaste packaging & pick up to customers & Institued training program for transporters DESSEL.8 Nuclear Pharmacy, Inc 00618 79/09/10 34pp
- ---7912190054 Ack receipt of 790807 ltr informing NRC of steps taken to correct violation noted in IE insp of License 37-18461-DIMD on 790618 Requests add1 info re mgt control sys.to be received within 7 days of ltr EMITH.0 H Region 4. Dallas. Office of the Director 79/09/10
- --7912190067 Responds to NRC 790723 ltr re violations noted in IE image? License 37-18461-01MD on 790618 Corrective actions: surveys of radioactive matls discharged in effluent air from fume hood will be done routinely DESSEL.8. Nuclear Phermacy, Inc. 79/08/07 3pp
- --7912190073 Forwards notice of violation from IE insp of License 37-18461-01MD on 790618. GRIER, B. H. Region I. Philadelphia. Office of the Director. 79/07/23 2pp
- --7912190080 Notice of violation from insp on 790618,
  \* Region 1, Philadelphia, Office of the Director 79/06/23 3pp
- 8001020069 Ack receipt of 791120 ltr informing NRC of steps taken to correct violations noted in IE insp of License 08-18308-01MD on 790913 MCCLINTOCK,R O Region 1, Philadelphia, Office of the Director. 79/12/10
- ---B001020073 Responds to NRC 791114 ltr re violations noted in IE inspet License OB--1B308-01MD on 790913 Corrective actions, dose calibrator will be adjusted or repaired when activity measurements during linearity tests differ by more than BX. IRHIN,R F Pharmatopes, Inc 79/11/20 ip.
- --8001020078 Ack recuipt of 791017 ltr informing NRC of steps taken to correct violations noted in IE insp of License 08-18308-01HD on 790913. Requests additinfor a dose calibrator adjustment & wipe tests
  MGCLINTOCK, R. D. Region 1, Philadelphia, Office of the Director.
- --8001020083 Responds to NRC 790922 ltr re violations noted in IE inspet License 08-18308-01MD on 790913 Corrective actions syrings shields will be used at all times & linearity tests will be repeated upon indication of more than 10% IRMIN.R F Pharmatopes, Inc 79/10/17 3pp
- --8001020105 Discusses IE insp of License 08-18308-01MD on 790913 & forwards notice of violation.

  MCCLINTOCK.R O Region 1. Philadelphia, Office of the Director 79/09/27
- --800102010B Notice of violation from insp on 770913 Noncompliance noted failure to use lead syrings shields, failure to record constancy checks on 770820-21 & failure to perform wipe test on incoming packages.

  \* Region 1, Philadelphia, Office of the Director 77/09/27. 289
- 8001270275 Ack receipt of 800107 ltr informing NRC of steps taken to correct violations noted in IE insp of License 24-14617-01MD.

  DAVIS, A B Region 3. Chicago. Fuel Facility & Materials Safety Branch 80/01/18. ip.
- --B0012702B1 Responds to NRC 800102 ltr re violations noted in IE inspections 24-16617-01MD Corrective actions have requested NRC to amend to license from three months to yearly calibr for radiation monitors KEESEE,R. Pharmaco Nuclear, Inc. 80/01/07. ip.
- 8002150275 Confirms meeting to be held between NRC & Nuclear Pharmacy. Inc on 800122 in King of Prussia.PA to discuss results of NRC 770802-03 insp & noted noncompliance. GRIER.B H Region 1. Philadelphia, Office of the Director. 80/01/07 ip

- 8002150283 Discusses error in 800109 ltr Purpose of meeting is to discuss results of 800103 insp Meeting date is 800122 at Region i ofc BMITH, Q H Region i, Philadelphia, Fuel Facility & Materials Safety Branch 80/01/15 ip
- 8002190229 Ciarifies Nuclear Pharmacy, Inc comments made during 800121 meeting re NRC notice of violation Forwards summary of facts available to NRC prior to issuance of notice Urges dismissal or remission of civil penalties
  VAKERICS.T V O'Connor & Hannan 80/02/05 7pp
- 8003050215 Ack receipt of 791221 ltr informing NRC of steps taken to correct violations noted in IE insp of License 37-18461-01MD on 791109 ltem A corrective & preventive actions will be discussed at 800122 NRC meeting GRIER, B # Region 1, Philadelphia, Office of the Director 80/01/21.
- --9003050219 Responds to NRC 791211 ltr re violations noted in IE insp of License 37-18461-01MD on 791109. Corrective actions steps have been taken to lower employee radiation exposure Syringe shield will be used whenever possible. DEBSEL. 8 Nuclear Pharmacy. Inc 79/12/21 4pp
- --8003050224 Forwards notice of violation from IE insp on 791109 One item of noncompliance noted in NRC 790723 ltr has not been totally corrected NRC has no further questions re Item 2 corrective actions. GRIER, B. H. Region i, Philadelphia, Office of the Director. 79/12/11 2pp
- --BOC3030226 Notice of violation from insp on 791107 Noncompliance noted: saployee overexposure.failure to report overexposures, failure to conduct required surveys
  4 Region 1. Philadelphia, Office of the Director 79/12/11 Opp.
- --B003050232 Bubmits revised quarterly figures re extremity exposures Gompany has instituted adequate anasures to ensure significantly lower exposure levels.

  DEBEL, 8 Nuclear Pharmacy, Inc. 79/11/12 2pp.
- 8003190817 Ack receipt of 800128 ltr informing NRC of steps taken to correct violations noted in IE insp of License 45-18378-01 MB on 791205.

  BTOHR.J.P Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 80/02/06
- --8003190529 Discusses IE insp of License 45-18378-01MD on 791204 & forwards notice of violation.

  8TOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/01/18 2p.
- --B003190537 Notice of violation from insp on 791216. Noncompliance noted: linearity tests not conducted on dose calibrators between Apr & Nov 1979 Records of radiation surveys performed on bags of syringes at disposal not recorded \* Region 2. Atlanta. Office of the Director B0/01/18. ip.
- BOO324003B Forwards on behalf of Nuclear Pharmacy, Inc. cashier check recivil penalty imposed per 800219 notice of violation to Elfreth Alley Apothecary in Philadelphia, PA Will not challenge penalty, Situation will be corrected per encl. MCDONALD, M E Butin, Thayer & Browns. 80/03/10 Spp
- B003250232 Forwards reconstructed 1978 film badge summary rept Results of summary repts from R8 Landauer Co & Searle Diagnostic will be forwarded within next month Advises of move to new licensed facility. Nuclear Pharmacy, Inc 80/02/19, 3pp.
- 9003260087 Submits closeout radiation survey of facility under License 12-18044-DIND HUBER, 8 A., DEBANTIS, M. Nuclear Pharmacy, Inc. 02836 80/02/14
- B004110323 Forwards results of clossout radiation survey for facility located at 770 Church Road, Suite F. Elmhust, IL, under License 12-18044-01MD. DE SANTIG, Nuclear Pharmacy, Inc. 03125 80/03/07 Spp

- 8005090553 Informs of change in 790807 proposed corrective actions re IE lnsp Rept 30-15125/79-01. Instead of installing portal monitor in threshold area between ofcs & lab.plans to install permanent contamination survey station STEPHENB.C W Nuclear Pharmacy. Inc CHS-280-8 80/02/20 2pp
- 8005160027 Submits claseout survey for facility authorized under License 12-17910-01 MD COMER.F M Pharmaco Nuclear, Inc 03545 80/04/18 5pp
- 8005230654 Ack receipt of full civil penalty payment imposed in NRC 800219 ltr & receipt of licensee 800310 ltr re corrective actions Info on mgt controls & audit program expected by 900512 800512 STELLO.Y Office of Inspection & Enforcement, Office of the Director 80/04/07 ip
- 8005300691 Forwards IE Insp Rept 30-14386/80-02 on 800403 of activities under License 12-18044-01 No noncompliance noted DAVIB:A 8 Region 3 Chicago, Fuel Facility & Materials Safety Branch 80/04/21 2pp
- --8005300695 IE Insp Rept 30-14386/80-02 on 800403 No noncompliance noted Major areas inspected decontaminated radiopharmaceutical facility ADAM, U J. PAPERIELLO, C J. Region 3, Chicago. Office of the Director 80/04/13. 3pp.
- 8006120881 Forwards IE Insp Rept 30-1362280-01 on 800416 of activities under License 12-17910-01 MD No noncompliance noted DAVIS.A B. Region G. Chicago, Fuel Facility & Haterials Safety Branch. 80/05/07 2pp
- --9006120884 IE Insp Rept 30-13622/80-01 on 900416 No noncompliance noted Major areas inspected matls.facilities & equipment, receipt & transfer of matls.urveys & radioactive effluents & waste disposal.

  DBERO.C Y Region 3. Chicago, Diffice of the Director PAPERIELLO, C J. Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/05/06 12pp
- 8006240527 Submits info re reorganization of radiation safety program for Matl/Syproduct License 37-18461-01MD in response to NRC 800219 & 0407 ltms. Corrective actions to reduce radiation exposure listed.

  NCCLINTOCK.R D Elfrath Alley Apothacary 1039 80/05/05 3pp
- 8009020175 Responds to FDIA request for NRC Annual Rept on FOIA for 1977,1978 & 1979 Forwards repts W/o and Is FELTON.J M Division of Rules and Records 80/08/12 ip
- 8009020176 FOIA request for NRC Annual Rept on FOIA for 1977, 1978 & MOSS.L. S. Babson College 60/08/06 1p
- 8009020182 Responds to FOIA request for winning technical proposal & contract NRC-05-80-253 awarded to Gasser Associates Forwards basic contract & nonproprietary version of technical proposal, summary of qualifications & experience H/o encis FELTON, J. M. Division of Rules and Records 80/08/12 ip nce W/o encls 80/08/12 1
- 8007020185 F0IA request for contract NRC-05-80-283 & Gasser Associates winning proposal submitted in response to RFP-RS-0IE-80-283. "Automated Vendor Selection Sys"

  EBERLEIN-F Control Data Corp 80/07/31 ip
- 8009020495 Responds to FOIA request for paper entitled, "Intensified Nuclear Safeguards & Civil Liberties." prepared under Contract AT(49-24)-0190 Document is available in FDR FELTON.J. M Division of Rules and Records 80/08/19 ip
- B009020505 F0IA request for paper entitled, "Intensified Nuclear Bafeguards & Civil Liberties," prepared under Contract AT(49-24)-0170 GROSSMAN.K Island Closeup News Service B0/08/11. ip.
- 8009050123 Add1 response to FDIA request for records pertaining to proposed fire protection rule FELTON, J M Division of Rules and Records, 80/08/05 ip
- --BO0905012& Forwards Sandia Labs 790919 & 0904 memos re fire protection in nuclear plants & BECY-79-478 updating status of NRC actions in response to UCB patitions. HANAUER.B.H. TMT-2 Unresolved Safety Issues 79/11/08 5pp

- --8009050131 EECY-79-478
  Informs Commission of present status of NRC actions in response to USS petition for smergency & remedial action & petition for reconsideration Seven items have been completed DENTON.H R Office of Nuclear Reactor Regulation, Director 79/08/08 4pp
- 8007050402 Forwards atd order for DDE work, "Geoscience Case Reviews 11."

  BCHREDER.F Division of Systems Safety FIN A-7118-9 79/09/18
- --B009080412 Std order for DOE work. "Geoscience Case Reviews II." issued to LASL Btatement of work encl.
  TRIPLETT.H P Division of Systems Safety FIN A-7118-9
  20-79-192 79/09/17 Bgp
- 8009050455 Submits list of AMSS away-from-reactor spent fuel cases included in budget. Budgeted resources are adequate to satisfy DOE requirements SARRY,L H Office of the Controller 78/08/10. 1p
- ---B009050462 Discusses BBE 771018 press conference on new spent fuel policy Includes briefing highlights Final text of DOE public announcement encl FOUCHARD. J Office of Public Affairs 77/10/18 5pp
- B009030491 Responds to FGIA request for 47 documents concerning GESMO. Forwards 28 documents listed in App A.Remaining 19 documents cannot be located M/o encis FELTON.J M Division of Rules and Records. B0/08/19 4pp
- --B009230141 BECY-75-338

  Recommends that Commission approve correspondence w/
  concerned parties to obtain clarification of comments on
  75050B FR notice re-provisional view on Pu recycle
  CHAPMAN,K R Office of Nuclear Material Safety & Bafeguards
  75/07/03 5pp
- ---S009230145 Responds to SECY-75-338 re comments received during Purecycle proceedings. Recommendation should be accepted w/caution Request for clarification will delay comment procedures

  BTRAUSS.P.L. Office of the General Coursel. 75/07/09, 2pp
- --8009230156 Informs that QESMO comment logs were delivered to Commission as requested by MA Rouden at 750811 Folicy Session 75-42 CHILK, S. J. Office of the Secretary of the Commission. 75/08/11
- --8009230159 Notifies of 750902 meeting w/ERDA to Pu racycle as requested at 750814 Policy Session 75-45
  CHILK: 8 J Office of the Secretary of the Commission. 75/08/20, ip
- --8009230164 Forwards compromise schedule for comment review on Purecycle provisional views
  CHILK-8 J. Office of the Secretary of the Commission. 75/08/20
  480
- --B009230174 Discusses issue of providing guidance to NRC staff concerning specific alternatives for further analysis re Pu recycling. Recommends that final guidance be transmitted in written form to minimize possibility of misinterpretations. HUBERMAN, B. Commission 75/09/12. 3pp
- --8009230183 Fowards corrected pages revising staff paper relissues & alternatives concerning Pu recycle provisional views.

  LCHENBERG.H Assistant Director for Operations & Technology. 75/09/12. 23pp.
- ---8009230187 Discusses B Huberman 780912 memo re providing guidance re Pur recycle. Lists four assumptions implicit in analysis Advises that discussion be held HASDN.E.A. Commission. 75/09/17, ip.
- --8009230190 Discusses staff paper on Pu recycle -- final decision procedures & interia licensing. Requests decision re whether range of reasonable alternatives is unduly restrictive. HUBERMAN.B. Commission. 75/10/07. 2pp.
- ---8009230195 Draft Commission paper providing Commission w/alternatives to facilitate formulation of views on procedures for reaching decision on widescale use of Pu recycle in LWRs & on interim actions.

  CHAPMAN K R Office of Nuclear Material Safety & Bafeguards 75/10/07. 141pp

- --8009230201 Discusses Commission agenda re procedures for reaching final decision governing widescale Fu recycle in LMRs & interim licensing of Pu facilities Discussion topics encl. MABON-E A. Commission 75/10/08 9pp
- --8009230170 Forwards draft staff paper presenting issues & alternatives re provisional views concerning upcoming Pu recycle decision.

  CHAPMAN K R Defice of Nuclear Material Bafety & Bafeguards
- --8009230206 Discusses need for hearing in GESMO & procedures to expedite hearing. Since GESMO is policy decision, legislative proceeding is more appropriate HEISS.L. A. Commission 75/09/05. Spp.
- --8009230209 Discusses treatment of licensing.pending final Pu racycle decision. Continuing licensing actions is consistent w/past judicial interpretations & AEC/NRC practice MEIBG.L A Commission 75/09/05. 4pp.
- --B009230213 Discusses scope of licensing activity, pending outcome of OESMO proceedings Individual licensing applications & reviews should be allowed through final decision, subj to reasonable policy of restraint WEISS, L. A. Commission 75/09/05, 2pp.
- --8009230218 Discusses procedures NRC may employ to expedite OESMO hearings Hearings will be very complex Commission should adopt comprehensive scheme to deal w/all foreseeable occurrences
  HE185.L A Commission 75/10/06. 3pp.
- --8009230224 Documents statements made at meeting re decision concerning procedures for reaching final decision on DESMO. Authorizing widescale use of Pu will involve litigative risks STRAUSS.P.L. Office of the Oeneral Counst. 75/10/14 Bpp.
- ---8009230229 Draft Commission paper providing Commission w/add1 alternatives for interim licensing of Pu recycle plants. Add1 info re interim licensing of reactors using Pu recycle fuel & environ inpact will be forwarded. BHAPAR: H K Office of the Executive Legal Director. 75/10/15, 130s.
- ---8009230232 Forwards draft instructions covering content of FR notice to add back-up mather Pu recycle in response to Commission request Also forwards tentative schedule of activities leading to 751030 date for publicizing FR notice. HALLERIN Commission. 75/10/15. 4pp
- ---8009230234 Draft Commission paper forwarding draft FR notice re scope & procedures for generic Pu recycle environ statement & interim licensing actions

  BHAPAR.H. K. Office of the Executive Legal Director. 75/10/20.
  42pp
- ----BOOT23023B Summarites V Oilinsky views on draft OESMO FR notice, Term
  "person" to refer to those commenting is inaccurate.
  "Retrospective implementation" or similar phrase might be
  substituted for "backfitting"

  SPECTOR.L S Office of the Executive Legal Director, 75/10/22,
  Spp
- ---8009230251 Comments on encl draft FR notice to Pu recycle decision.
  Notice should be prefaced by summary which sets out purpose,
  states objectives of decision & describes what is being
  decided. H/o encl draft FR notice
  KENNEDY, R T Commission 75/10/22, 2pp.
- --8009230254 Expresses appreciation for collating Commission comments on draft FR notice. Requests preparation of document to support schedule mentioned in FR notice.
  MADON.E A. Commission. 75/10/24. ip.
- --8009230260 Comments on interim licensing of Pu recycle facilities. Supports Commission position re licensing other Pu fuel cycle facilities on interim basis per safeguards rules to be proposed following publication of DES OILINSKY, V. Commission, 75/10/24, Spp.
- ---B009230266 Forwards revised draft FR notice re scope & procedures for ganeric Pu recycle environ statement & interim licensing actions Draft FR notice reflects input of Ofcs of General Counsel Policy Evaluation & Executive Legal Director, BMAPAR, H. K. Office of the Executive Legal Director 75/10/29.

## NONDOCKETED ITEMS

- ---9009230268 Forwards revised draft FR notice re-scope & procedures for generic Pu recycle environ statement & interim licensing actions. Revised FR notice reflects input of Ofice of General Counsel, Policy Evaluation & Executive Legal Director BHAPAR, H K Office of the Executive Legal Director 75/11/03.
- ~~8009230272 Responds to 751105 request for supplemental info re draft DOGENOUS Responds to 751105 request for supplications of the considerations & comparison of overall NRC vs AEC plans to arrive at decision on widescale Pu recycle
  CHAPHANK R Office of Nuclear Material Safety & Bafeguards 75/11/07 9pp

- --B009230291 Forwards discussion paper re Pu recycle provisional views. Paper shows revisions suggested by Ofc of Executive Legal Director.W/o encl. LGMENBERO,H. Assistant Director for Operations & Technology 75/09/11. ip.
- --8009230297 Lists assignments for prime responsibility in preparation of draft input to Commission paper re Pu recycle. Drafts should be completed by noon on 750926.
  LCHENBERG.H. Assistant Director for Operations & Technology.
  78/09/23. 2pp
- 9009050492 FOIA request for 47 documents concerning QEBMO Descriptive list entl. METLAY, D. Indiana Univ 80/04/16 App
- BO09080251 Responds to FOIA request for L Bickwit 791018 memo, adequate protection of health & safety of public Forwards memo. FELTON.J. H. Division of Rules and Records 80/08/05, ip.
- -80090B026: Provides definition of "adequate protection of public health & safety" & responde pertially to UF Ahearne request for views on using economic factors in NRC decisions. Term "adequate protection" focuses on radiological risk. BIGMNIT,L. Office of the General Counsel. 79/10/18 34pp.
- BOOTOBO256 FOIA request for L Bickwit 79:018 memo re adequate protection of health & safety of public BIELAHEKI, A Isham, Lincoln & Beale, 80/07/16, 2pp.
- SCOONSCIR Addl response to FOIA request for existing regulations radisposal of high & low level wastes. Forwards SECY-79-580 discussing procedural aspects of disposal of high level radwaste in geologic repositories H/o encl FELTON.J. M Division of Rules and Records. 80/08/05 1p
- 8007070348 Responds to 710722 itr transmitting calculation of thyroid dose for LGCA. Lists two assumptions in calculational model accounting for computed thyroid doses above guidelines. "Methyl lodids Fraction in Containment Atmosphers" encl. PORRISD P.A. Atomic Energy Commission, Directorate of Licensing. 71/10/04. 8pp.
- 8001110286 Responds to FGIA request for winning proposal, "Effects of Shift Hanning Strategies on Nuclear Operator Performance." awarded to Biotechnology Inc under NRC-03-80-147. Forwards nonproprietary version of proposal.
  FELTON.J. M. Division of Rules and Records. 80/09/04. 1p.
- --B009110296 Forwards proposal in response to RFP to "Review & Interpret RBD Literature Relevant to Staffing Requirements for Control Room Operations." Includes technical & cost proposals & fully executed Std Form 18 BHANAMAN.W.P. Bio-Tec. Inc. 80/08/18. 1p.

- NRC-03-80-147. 80/08/18 17pp Dio-Tec, Inc
- BO09110291 FOIA request for winning technical proposal. "Effects of Shift Hanning Btrategies on Nuclear Operator Performance." awarded to Biotechnology, Inc under NRC-03-80-147. RUTHERFORD, J F BDM Gorp BDM/W-JFR-6315. B0/08/22 ip
- 8009110335 Responds to FDIA request that specific listed documents be placed in PDR D9 Eisenhut 760302 memo to K Goller will be placed in PDR Division of Rules and Records 80/09/04 ip
- --8009110347 Forwards topical rept evaluation of NEDE-21156, "Suppl Info for Plant Mod to Eliminate Bignificant In-Core Vibration " EISENHUT.D Q. Division of Operating Reactors 76/03/02 2pp
- --8009110351 Topical rept evaluation of NEDE-21154, "Suppl Info for Plant Mod to Eliminate Significant In-Core Vibration " Mods are accoptable Office of Nuclear Reactor Regulation, Director. 76/02/28.
- 8009110339 FOIA request that encl listed documents be placed in PDR CONNOR.L Doc Search Associates 80/08/13. 2pp
- 8009110354 Responds to FOIA request for released portions of IE manual change notices, beginning w/Change Notice 80-03 Forwards documents. W/o encis FELTON, J H Division of Rules and Records 80/09/05. 1g
- 8007110356 FDIA request for released portions of IE manual change notices, beginning w/Change Notice 80-03 JOHNBON, J K Carolina Power & Light Co GGA-80-227 80/08/27 ip
- BOO9110359 Responds to FOIA request for documents re-granting of License 45-00034-26 to Univ of VA.Forwards documents listed in App A W/o encls. FELTON.J M. Division of Rules and Records. BO/09/05. 2pp
- 8009110361 FOIA request for documents re granting of License 43-00034-26 to Univ of VA BEEGLE.C.W Affiliation Unknown. 80/08/19. 2pp.
- 8009110527 Responds to FOIA request for details of spent fuel rod transportation from San Unofre, CA to Morris, IL, including emergency & evacuation plans Forwards one page tabulation of spent fuel shipments & KNREO-0535, H/o encl NNREO, FELTON, J. M. Division of Rules and Records 80/09/08, ip
- --8009110533 "Shipments of Spent Fuel from San Onofre,CA to Morris, IL. 790101-800825 " Commission 80/08/25 1p.
- 8009110531 FOIA request for details of spent fuel rod transportation from San Onofre.CA to Morris,IL,including emergency & svacuation plans.

  80/08/10.8 F. Affiliation Unknown. 80/08/13. ip
- 8009110838 Responds to FOIA request for text, "Los Alamos Primer," part of Los Alamos Project Document is under DOE jurisdiction Request has been forwarded to DOE for direct response, FELTON, J.M. Division of Rules and Records, 80/09/08 ip.
- 8009110542 FOIA request for text. "Los Alamos Primer." part of Los Alamos Project Bocument was declassified between 1984-1964 MARKER.J L. Affiliation Unknown. 80/09/04 19
- BO0911054& Responds to FOIA request for new control & accounting stds proposed by NRC for strategic BNM Proposed rule is being developed. Hriefing charts re stds are available in PDR. FELTON.J.M. Division of Rules and Records B0/09/0B. 1p
- 8009110849 FOIA request, submitted on behalf of NRDC, for new control & accounting stds proposed by NRC for strategic BNM Nucleonics Hk 800821 erticle citing proposed stds encl.

  WE188, E.R. Sheldon Harmon & Weiss. 80/09/21. Spp.
- 8009110867 Add1 response to FOIA request for NRC file on WE Kessler Memorial Hosp in Hammonton, NJ Forwards documents listed in App A. H/o encis. Division of Rules and Records, 80/09/08. 2pp.

- 8009120586 "Analysis Summary in Support of Early Reactor Coolant Pump ip " Babcock & Wilcox Co 80/08/28 Sipp.
- 8009120583 FOIA request for two documents concerning ECCS in B&W reactors WEISS.E.R. Sheldon, Harmon & Waiss 80/08/21 ip
- 8009120591 Responds to FOIA request for Science Applications, Inc winning proposal under RFP RS-RES-79-200 Forwards nonproprietary version of proposal FELTON, J H Division of Rules and Records 80/09/02 ip
- --B009120597 Nonpropriatary response to RFP RS-RES-79-200, "Risk Assessment Methodology Development for Waste Isolation in Osologic Media " Includes technical approach, statement of work, related experience & evaluable resources & facilities # Bolence Applications, Inc. RB-REB-79-200 79/08/31 24
- 8009120594 FOIA request for Science Applications, Inc winning proposal under RFP RS-REB-77-200 ORMONDE, 8 Affiliation Untrown 80/08/08, 1p
- 8009150002 Responds to FOIA request for NRC records re organization, Mobilization for Survival Forwards documents listed in App A FELTON, J.K. Division of Rules and Records 80/08/26 2pp.
- -- 9009150004 "Btop Nuclear Exports to Philippines." Statement to NRC Commissioners & 790306 flyer re March on Washington and # Affiliation Unknown 80/02/15 4pg.
- ---S009150005 NRC Announcement 48 re 790506 march from Ellipse to US Capitol & 790507 mass lobby day at Congress, DCE & NRC Demonstrators should be treated in courteous manner. QCBSICK, L. V. Office of the Executive Director for Operations, 79/05/03, ip
- 8009150003 FOIA request for NRC records re grownization, Mobilization Village Voice BO/07/28 fp.
- 8009150302 Responds to FOIA request for info re release of U hexafluoride from Piketon,OH Gaseous Diffusion Plant & procedures & stds.concerning waste disposal. Request is under DDE jurisdiction & has been referred for direct response FELTON,J M Division of Rules and Records. 80/09/10. 1p
- 8009180305 FOIA request for info re release of U hexafivoride from Piketon.OH gaseous diffusion plant & procedures & stde concerning waste disposal ZITO.N Affiliation Unknown 80/09/02 ip
- 8009180368 Responds to FOIA request for rept, "Review of Delegations of Authority Within NRC " Document is available in PDR. FELTON, J M Division of Rules and Records. 80/08/28 ip.
- 8009150371 FOIA request for rept. "Review of Delegations of Authority Within NRC."
  FIDELL, E.R. LeBosuf, Lamb. Leiby & MacRee 80/08/12. 1p.
- 009170049 Responds to FOIA request for statistical summaries of DOYI/DUTY Responds to thin request for statistical summary personnel monitoring for radiation exposure at nuclear plants in SC.Forwards NUREO-0463, "Occupational Radiation Exposure" & five pages of 1978 summary repts. H/o NUREO FELTON.J.M. Division of Rules and Records 80/09/02. 1 80/09/02. in.
- 8009170054 Excerpt from "Annual Summary Repts for 1976." Rept consists of personnel monitoring for radiation exposure at facilities in SC.

  # Affiliation Unknown RIS6276 79/12/07 5pp.
- 09170052 FOIA request for statistical summaries of personnel nonitoring for radiation exposure at nuclear plants in SC KITTRELL, J. O Affiliation Unknown 80/08/18 1p
- 309170057 Responds to FOIA request for documents provided on request of J McKeever re evaluations of cracks & reactor containment problems for various sites. Forwards listing of requested documents per 800828 telcon. FELTON J M Division of Rules and Records. 80/09/02. 3pp. Division of Rules and Records, 80/09/02, 3pp.
- BOO9170059 FOIA request for documents provided on request of J McKeever re evaluations of cracks & reactor containment problems for various sites.

  CHONG, L. K. Affiliation Unknown BO/08/13 ip

- 8009170063 Responds to FGIA request for bidder invitation list for RFP R8-NRR-80-111 Forwards document FELTON.J M Division of Rules and Records. 80/09/02 is
- --8009170070 Provides list of applicants submitting proposals in response to RFP RB-NRR-80-111 to NFP RE-NRR-80-111 DOUGHERTY, DJ , MENCZER, W B Technical Assistance Contracts Branch, 80/01/18 5pp
- 8009170065 FOIA request for bidder invitation list for REP SE-NOR-CAL PUSCHEL, H. A Consumers Power Co PUSC 33-80 80/08/14 is
- 8009190299 Responds to FOIA request for 15 documents listed in bibliography of NUREO-0625, "Rept of Siting Policy Task Force." Documents 6-8 & 13 are available in PDR Forwards FORCE." DOCUMENTS OF A 13 are evaluable in FDK Forwards remaining documents.
  FELTON, J H Division of Rules and Records BO/09/04 is.
- --8009190320 SECY-75-518 009190320 SECV-75-518
  Responds to Commission direction to develop alternative plans for revision of code re power feactor siting regulations. Forwards diagram of scheduling network, makeup of study panel & study at task scope of work.

  MINOOUE, R. B. Office of Standards Development, Director. 75/09/12.
- --8009190326 Bummarizes 750611 briefing re adequacy of 10CFR100. Commission requested that staff devise more specific plan of action for proposed revision of code.Plan will return as policy session item CHILK.B J Office Office of the Becretary of the Commission. 75/06/12. 200
- --8009190358 Forwards SECY-75-286, concerning reactor siting policy. Issue is large & complicated, NRC will prepare or all briefing to outline principal areas of concern & potential solutions.

  9088ICK, L V Office of the Executive Director for Operations 76/09/25 1p.
- ---8009170366 SECY-76-286
  Forwards "Staff Review of Site Evaluation Policy & Practice." Recommends that Commission hold further discussions w/Directors of NRC ofcs to develop basis for decisions concerning future site evaluation policy.
  HIMOQUE, R. B. Office of Standards Development, Director. 76/05/23
- ---8009190370 "Staff Review of Site Evaluation Policy & Practice "
  + Commission 76/05/25, 55ee.
- --- 8009190383 Informs that Commission has reviewed SECY-75-518 re reactor siting. Program described re development of policy paper is not fully consistent w/intent of Commission directive Lists Commission requests re program ANDERS.W.A. Office of the Executive Director for Operations. 75/10/30 3pp
- ---8009190386 Discusses review of 760301 memo re reactor site evaluation to practice. Paper needs significant improvement in defining further actions & providing basis for Commission decision on those actions
  HUBERHAN. B. Office of Policy Evaluations. 76/03/19. 1p
- ---8009190390 Discusses review of reactor site evaluation policy & practice. Review is well written & makes persuasive statement for thorough revision of existing site evaluation policy. Proposed actions re siting policy issues encl. BTRAUSS, P. L. Office of the General Counsel. 76/04/01. 13pp
- --8009190394 SECY-76-286A NOTIONOTA SECY-76-285A
  Requests Commission approval of development plan for nuclear facility siting policy & practice revision. Recommends that Commission approve proposed plan & direct staff to proceed w/programs Related documentation encl.
  MINDOUE.R. B Diffice of Standards Development, Director. 76/12/14
- ---9009190397 Forwards comments on development plan for nuclear facility siting policy & practice. Requests that comments be reviewed, modified commented on & summarized.

  REMM.T.A. Office of the Executive Director for Operations. 76/11/23. 1p

- --8009190400 Discusses development plan for nuclear facility siting policy & practice revision Principal concern is whether NEPA considerations will receive adequate attention STRAUSS.F.L. Office of the Ceneral Counsel 76/11/23 2pp
- --8009190464 Comments on 761103 draft of "Davelopment Plan for Nuclear Facility String Policy & Practice Revision " Draft is not adequate response to Commission 760830 guidence Ofc of Stds Development response encl. HUBERMAN, B Office of Policy Evaluations 76/11/11 13pp
- --BO09190470 Provides Commission comments on SECY-76-286 re reactor site avaluation policy study Rept provides valuable partial background for site avaluation policy formulation Lists banefits of cohesive.explicit siting policy CHILM.B J Office of the Secretary of the Commission 76/08/31
- --BOOTIFOABO Responds to 760831 request for comments on Commission review of BECY-76-286. "Staff Review of Reactor Site Evaluation Policy & Practice " Ofc of Bids Development will produce program plan re reformulation of siting policy.
  HINDOUS.R.B Office of Standards Development. Director 76/09/24
- Ωрρ.
- of Ceneral Counsel

  BHAPAR, H. K. Office of the Executive Legal Director 77/03/18.
- --8009190507 Forwards updated program outline & schedule of development plan for nuclear facility siting policy & practice Status rept on extending scope to include fuel cycle facilities and MINDQUE, R.B. Office of Standards Development, Director 77/04/15
- -- #009190514 SECY-77-288 009190514 SECY-77-203 Forwards proposed general policy statement on nuclear reactor sits eveluations. Recommends that Commission provide guidance on proposed policy statement & directive re development of replacement regulation. HINDOUE, R.B. Office of Standards Development, Director. 77/06/07
- -- #009190520 SECY-77-298 NO9190520 SECY-77-208 Comments on general policy statement re nuclear reactor site evaluations. Paper is inadequate & does not set forth range of options open to Commission Possible legal problems exist w/general policy statement approach as proposed KELLY, J. L. Diffice of the General Counsel. 77/06/02. Spp.
- --- 8009190526 Forwards comments on 770527 draft of "General Policy Statement on Nuclear Reactor Bite Evaluation Policy."

  General approach is inadequate for Commission decision regeneral reactor site evaluation policy
  TERRELLN. Office of Policy Evaluations. 77/06/02 11pp.
- -8009190532 SECY-77-433 NOTIPOSOZ SECY-77-453

  Rubmits policy statement on alternative sits evaluations under NEPA for nuclear generating stations. Recommends that Commission require review & approval of applicant site selection process prior to acceptance of CP application MINDOUE, R. B. Office of Standards Development, Director 77/08/16.
- --8009190539 Comments on draft of "Policy Statement on Alternative Site Evaluation Under NEPA for Nuclear Stations," Paper is suitable for Commission review, Value of paper could be enhanced by encl comments.

  PEDERGEN.K. Office of Policy Evaluations 77/07/18. 6pp.
- --B007170346 Comments on proposed policy statement on evaluation of alternate sites. Policy statement does not cleanly identify how Commission will act to enforce stds. Related documentation encl. KELLEY, J. L. Office of the General Counsel. 77/07/25. Spp.
- --8009190550 BECY-78-371
  Revises BECY-77-288, "General Policy Statement on Nuclear Power Reactor Site Evaluations," Recommends approval of general statement of current policy on nuclear power site evaluations for publication in FR & draft ltr.
  MINDOUG, R. B. Office of Standards Development, Director, 78/07/03. 30pp.

- --8009190557 Lists Commission requests for further action to be taken on SECY-77-288 concerning siting policy & practice Four siting policy issue papers should be forwarded to Commission as proposed in scheduls

  CHILK.S J Office of the Secretary of the Commission 77/06/30
- -8009190368 Comments on general policy statement on current nuclear reactor site evaluation Lists items which should be considered before statement is adopted & published Ofc of 8tds Bevelopment responses encl BHAPAR.H K Office of the Executive Legal Director 78/05/08
- --8009190587 BECY-79-362
  Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants, for determination of site acceptability & adequacy of engineered safety features
  MINDOUE, R B Office of Standards Development, Director. 79/06/04
- --8009190612 Draft Reg Quide 88 724-4, "Atmospheric Dispersion Models for Potential Accident Consequence Assessments at Nuclear Power Plants." Office of Standards Development, Director. 79/06/04 29pp
- ---8009190624 Draft value/impact assessment of proposed Reg Guide 88
  724-4. "Atmospheric Dispersion Hodels for Potential Accident
  Consequence Assessments at Nuclear Power Plants " Reg guide
  should be developed. Documentation encl
  # Office of Standards Development: Director. 79/06/04. 34pp
- 8009190313 FOIA request for 15 documents listed in bibliography of NUREO-0625. "Rept of Siting Policy Task Force "DAVIS.R J NUS Corp E80-80-170(EC). 80/08/15. 2pp.
- 8009190614 Add1 response to FOIA request for nine categories o documents re ACC amend to 10CFR50 57(c) proposed on 701028 & adopted on 710514, Forwards documents listed in app FELTON.J M. Division of Rules and Records. 80/09/02 2pp
- --8009190634 Forwards 10CFR50, "Authorization of Low Power Operation," Requests publication, MCGODL, W.B. Atomic Energy Commission 71/05/10 1p
- --8009190638 "Authorization of Low Power Operation," 10CFR50 effective rule Proposed amends define extent of preoperational activities which could be conducted prior to issuance of DL & provide for authorization of low power testing.
  HOBBS.F.T Atomic Energy Commission 71/05/03. Spp
- ---B009190A42 Discusses proposed rule 100FR80 re authorization of low power operation Commission should adopt rule in effective form Adoption of proposed amend re fuel loading under CP is not recommended Braft FR notice encl.

  PRICE, H. L. Atomic Energy Commission 71/04/21 lipp
- ---9009190A47 Forwards draft FR notice re proposed rule 10CFR50, "Licensing of Production & Utilization Facilities" & public announcement, Proposed rule provides for operation during pending DC proceedings. FR notice only encl. PRICE, A. L. Atomic Energy Commission 71/04/13 App.
- --8009190653 Bummary of 710115 Regulatory Info Meeting 445 List of attendess included Proposed amends to 10CFR50 & 2 re effective date of initial decision authorizing issuance of OL approved.

  HCCDDL, W B. Atomic Energy Commission. 71/01/15. 2pp.
- --8009190468 Forwards comments on proposed rules 10CFR2 & 50 re effective date of initial decision authorizing issuance of GL Bone features of groposed rules unless clarified could introduce further uncertainty into licensing process GLEASON, O. L. Atomic Industrial Forum. 10CFR2. 70/12/31 23pp

- --BO091906B2 Responds to request for info re proposed changes in AEC regulations concerning definition of CPs & low power testing of nuclear facilities Provides details of proposed changes. Changes will minimize licensing delays MANN.H M Atomic Energy Commission 70/12/03 3pp
- --BO09190688 Speech entitled "Reactor Licensing Delays in Perspective Froblems, Progress, New Directions" presented at AIF 1970 Annual Conference in Hashington, DC RAMEY, J T Atomic Energy Commission B-41-70 70/11/17 36pp.
- --BO09190695 Forwards 700716 memo which supersedse 700707 memo re possible rule & legislative changes concerning authorization of low power reactor operation Memo should be used as basis for Commission of discussion W/o encl memo PRICE.H L Atomic Energy Commission 70/08/11 ip
- --8009190701 Summary of 700717 Regulatory Info Meeting 414 List of meeting attendees included MCCOOL.48 B Atomic Energy Commission 70/07/17 2pp
- BOO9190629 FOIA request for nine categories of documents re AEC amend to IOCFR50 57(c) proposed on 701028 & adopted on 710514 BROMM, H H Hill Christopher & Phillips 80/08/07 2pp
- BOO9240012 Responds to FOIA request for nine categories of documents re AEC amend to 10CFR50 57(c) proposed on 701028 k adopted on 710514 Forwards documents listed in App A responding to Items 1-5 Bearch is continuing for add1 records FELTON, J. M Division of Rules and Records BO/08/21 2pp.
- --- 6007240014 Submits questions for response re undue delays in licensing process Delays will disrupt efforts concerning devalopment of peaceful uses of nuclear energy. Licensing delays are attributed to administrative obstacles PASTORE, J D Senate 71/03/08, 2pp
- -8009240016 Forwards responses to specific questions in 710308 ltr concerning delays in licensing process Expanding technological demands, strikes during conet, late delivery of component parts & const problems cause licensing delays SEABORG.0 T Atomic Energy Commission 71/04/27 15pp.
- ---BO09240018 Forwards draft notice of proposed rules iOCFR2 & IOCFR50. Proposed amends authorize nuclear fuel loading in reactor core w/o attainment of critical reaction & authorize Director of Regulation to issue license PRICE, H L Atomic Energy Commission 70/10/22 12pp
- --8009240021 Forwards FR notice re AEC proposed rules 10CFR2 & 10CFR50, "Rules of Practice" & "Licensing of Production & Utilization Facilities DLs " Requests publication.
  HCCOOL, H B Atomic Energy Commission 70/10/22 1p
  - B009240024 Notice of AEC proposed rules iOCFR2 & iOCFR50, "Rules of Practice" & "Licensing of Production & Utilization Facilities OLF," respectively MCCOOL, W B Atomic Energy Commission 70/10/20 Bpp.
- BO09240026 Approvas proposed rules 10CFR2 & 50 discussed at Regulatory Info Neeting 421 re authorization of low power reactor operation regulations Proposed rules & legislative amend enci PRICE:H L Atomic Energy Commission 70/09/14 12pp
- -BO09240041 Submits possible rule & legislative changes re authorization of low power reactor operation regulations No showing of good cause would be required for authorizing low power operation M/proposed rules 10CFR2 & 50 & legislative amend PRICE, H L Atomic Energy Commission. 70/08/26 12pp
- ---BO09240047 Discusses possible rule & legislative changes re authorization of low power reactor operation Commission approved changes subj to comments by Commissioners Ramey & Thompson & deferred action for statutory change PKCCOCLW. B. Atomic Energy Commission 70/09/22 ip.
- --8009240034 Recommends listed changes in AEC regulations re authorization of low power reactor operation CPs would authorize fuel loading short of criticality Proposed rules 10CFR2 & 50 & legislative amond encl. PRICE.H L Atomic Energy Commission 70/07/16 11pp

- --8007240063 Comments on proposed rules 10CFR2 & 50.on behalf of Bave New England. Commission should undertake thorough & comprehensive review of entire licensing scheme contained in proposed rule. w/full public hearing KESSLER. G Affiliation Unknown 10CFR2 70/12/20 11pp.
- --B009240070 Comments on proposed rules 10CFR2 & 50 re effective date of initial decisions authorizing issuance of OLs. Change in procedures undercute congressional review procedures for objections to issuance of OL Draft FR notice encl.

  BUTLER.W A Environmental Defense Fund 10CFR2. 70/12/28. 7pp.
- --B009240075 Forwards FR notice re rules 10CFR2 & 50 \*Effective Date of Initial Decisions Authorizing Issuance of OLs \* Requests publication HCCOOL.M.B Atomic Energy Commission 71/01/18 1p.
- --9009240086 "Effective Date of Initial Decisions Authorizing Issuance of OLs." 10CFR2 & 50 effective rule. Amend provides for immediate effectiveness of initial decisions authorizing issuance of OLs.

  HOSBS.F. T. Atomic Energy Commission. 71/01/15 4pp
- --8009240092 Forwards HL Price 710421 memo & info for Commission consideration at info meeting Includes draft notice of rulemaking draft ltr to EJ Bauser & draft public announcement.

  HCCOOL.W.B. Atomic Energy Commission. BECY-R 221. 71/04/21. ip.
- --8009240108 Discusses proposed rule 10CFR50 re authorization of low power operation. Recommends that Commission adopt rule in effective form Draft notice of rulemaking, ltr to EJ Bauser & draft public announcement encl.

  PRICE, H L Atomic Energy Commission. 71/04/21. 15pp.
- ---8009240113 Informs that Commission approved SECY-R 221 ra proposed rule 10CFR50 concerning authorization of low power operation.

  MCCOOL, W. B. Atomic Energy Commission. 71/04/29 1p.
- --8009240082 Responds to 700924 ltr sepressing concern about AEC procedural & administrative mechanisms for licensing nuclear plants. Forwards statement reviewing licensing record from 1957 to present & discusses efforts to improve process. SEABORG. O. T. Atomic Energy Commission. 70/11/27. Spp
- 8009240141 Responds to FOIA request for list of firms responding to announcement in Commerce Business Daily re NRC RFF-RR-NRR-80-138 Forwards document, "Bolicitation Document Distribution," containing firm names & addresses. FELTON.J.H Division of Rules and Records. 80/09/10. 1p.
- --8009240151 "Salicitation Document Distribution," Commission. 80/09/10. 10pp.
- 8009240147 FOIA request for list of firms responding to announcement (e. Commerce Business Daily re NRC RFF-RB-NRR-80-138. "Technical Assistance in Support of NRC Reactor DL Action Program " STERN: A Al Stern Associates. B0/08/22. 1p.
- 9009250448 Responds to FOIA request for NRC responses to SH Hanauer 790406 msmo. Forwards CF Miller 790423 memo. FELTON, J. M. Division of Rules and Records. 80/09/16. 1p.
- ---8009250453 Discusses environ qualification & instrumentation to follow course of accident as result of TMI accident. Lists items which should be reconsidered HANAUER, S. H. Assistant Director for Plant Systems. 79/04/06 ip
- 8009250452 FOIA request for NRC responses to 8H Hansust 790406 memor MEISB, E.R. Sheldon, Harmon & Weiss, BO/08/25, 1p.
- B009250484 Responds to FBIA request for info re U mining & effects upon environ & people, repts on Natl U Resource Evaluation Program & Council of Energy Resource Tribes activities & repts of safety violations by TVA Forwards documents in app. FELTON, J. M. Division of Rules and Records. 80/09/15. 2pp.
- 8009230486 FOIA request for info re U mining & effects upon environ & people, repts on Natl U Resource Evaluation Program & Council of Energy Resource Tribes activities & repts of safety violations by Union Carbide & TVA.

  FREEMAN, J Affiliation Unknown. 80/08/17. 1p.

- POOP290025 Responds to FOIA request for documents to NRC Jan 1979-June 1980 insp of facilities owned & operated by Pharmatopes Inc Pharmaco Nuclear, Inc & Nuclear Pharmacy Inc Documents 4-6 partially withheld individual names (ref FGIA Exemption 6) FELTON, J. M. Division of Rules and Records 80/09/08 5pp.
- ---8009290031 IE Insp Repts 30--10975/79-01 & 30--11415/79-01 on 790816 No noncempliance noted Hajor areas inspected internal audits, training, retraining a instruction of workers, radiological protection procedures, instrumentation & matis BCHART, H. H., PAGLAIRO, J. Region 3. Chicago, Office of the Director 30--11419/79-01 79/08/23 14pp.
- --B009290041 1E Insp Rept 30-15134/79-01 on 791129 Noncompliance noted failure to use gloves during generator elution.
  COSTELLO,F.M. Region 3, Chicago, Office of the Director MCCLINTOCK: R O. Region i. Philadelphia, Fuel Facility & Materials Safety Branch. 79/12/04 11pp.
- -- 8009290052 Notice of violation from inep on 791212 e Region S. Chicago, Fuel Facility & Materials Safety Branch. 79712/27. 1p.
- --B009290084 IE Insp Rept 30-14826/79-02 on 790913. Noncompliance noted. failure to use springe shields to survey incoming packages & used lead containers. Dose calibrator checks unrecorded info gartially withheld: individuals names (ref FOIA Exemption 6). CAMPRELL. M. MCCLINTOCK. R. O. Region i, Philadelphia, Office of the Director. 79/09/10 22pp
- --- GOGP270073 IE Inap Rept 30-14964/79-01 on 791206. Noncompliance noted: 3-yr linearity tasts were not performed on calibrators. Byrings box surveys were not recorded, although syringes were stored for decay for min of 90 days before transferring MOORWEF.R.L. Region 2, Atlanta, Defice of the Director 89/01/02. 18pp.
- --B009290085 Mati/Byproduct License 12-01721-01 for Univ of Chicago is ananded in its entirety per 730821 application. Amend 15 authorizes possession to use of 500 mGi of each byproduct mati between Atomic Numbers 3-83 in any form.
  BOMYER, J. E. Atomic Energy Commission, Directorate of Licensing, 74/01/15. 3pp.
- --BOOP290087 IE Inse Rept 30-15128/79-03 on 791109. Noncompliance noted: failure to perform swipes of external container of incoming packages & to monitor boxes prior to delivering. Info partially withheld: individuals names (ref FOIA Exemption 6). DAVIS, J., HCOINNIS, J. A., OLENN, J. E. Region 1, Philadelphia, Office of the Director. 79/11/21. 11pp.
- -BOOG270092 Draft IE Insp Rept 30-15125/79-02 on 790828-31. No nencompliance noted Major areas inspected notification of incident; package history, visits to licenses, visit to Federal Express Philadelphia station & Hemphis Station. BAVIS, JERMAN, P.C. Region 1, Philadelphia, Office of the Diractor, MCCLINTOCK, R.O. Region i, Philadelphia, Fuel Facility & Materials Stafety Branch, 79/10/05. App.

- ---8009290096 Responds to 790829 notification that package of Xe-i33 shipped by Federal Express had excessive radiation levels Forwards insp of Federal Express facility in Memphis.TN Dosage to any individual was minimal SUTHERLAND, J T Region 2. Atlanta, Fuel Facility & Materials Bafety Branch. 79/09/07. 3pp.
- ---B009270099 IE Insp Rept 30-15125/79-01 on 790618 Noncompliance noted failure to survey for radiation levels in unrestricted areas & to evaluate radiation overexposure to individual preparing doses w/o using surings shield O'NEILL.B., MCGINNIB-J Region i, Philadelphia, Office of the Director MCCLINTOCK.R.O Region i, Philadelphia, Fuel Facility & Materials Safety Branch 79/06/28 11pp
- ---8009290102 Act receipt of 800307 ltr re results of closeout survey of Elahurst, IL facility. DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/03/24. is.
- --8009290105 Ack receipt of 800219 ltr w/1978 film badge summary rept Closeout survey will be conduted to vacating of Eleburst facilities, after receipt of consultant closeout survey. KEPLER.J.O. Region 3. Chicago, Fuel Facility & Materials Safety Branch. 80/03/17 1p
- --8009290111 Discusses 800214 closeout survey & NRC 800228 confirmatory survey. NRC survey results are consistent w/vendor results. Facility meets NRC decontamination guidelines. Approves facility release for unrestricted use KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/03/13 to
- --B009290113 Responds to 800125 notification of intended move NRC has no objections to proposed decontamination & decommissioning procedures, NRC closeout survey will be conducted upon receipt of final survey & wips test results.

  KEPPLER, J. O Region 3, Chicago, Office of the Director 1p
- --B009290116 Ack receipt of 800123 ltr informing NRC of steps taken to correct violations noted in IE inep of License 12-18044-01MD on 800122 DAVIS-A B. Region 3: Chicago: Fuel Facility & Materials Sefety Branch. 80/01/31
- --8009290122 Discusses consolidation of operations at one location Radioactive maths will be moved to second facility until Chicago facility is ready. No problems anticipated w/residual activity
  DESANTIS,N Nuclear Pharmacy, Inc. 80/01/25 2pp
- --8009290127 Responds to violations noted in IE into of License 12-18044-01MD on 800122 Corrective actions: within 45-day extension will do everything possible to bring facility into compilance res recordkeeping & safety DESANTIS,N Nuclear Pharmacy, Inc. 80/01/23, ip.
- --B009270140 Forwards IE Imp Rept 30-15125/80-01 on 800103. GRIER.B.H Region 1, Philadelphia, Office of the Director B0/02/20. 2pp.
- ---8009290182 IE Insp Rept 30-15128/80-01 on 800103. Noncompliance noted, overexposure to extremities of one individual & failure to use syrings shields during dispensing operations. HCCLINTOCK, R. O. HCCLINNES J., OLENN, J.E. Region 1, Philadelphia, Office of the Director. 80/01/23 Spp.
- ---8007270156 Submits rept to overexposure of employee Inadvertent placement of ring bedge in vicinity of glove disposal box is apparent cause of high exposure readings. Added precaution shall be taken to insure proper response to actual exposure. 'BROHNINO, M. Nuclear Pharmacy, Inc. 100FR 020.405 79/12/28. ip.
- --8009290188 Forwards draft insp rept of 790131 & 0202 insp of License 12-18044-01MD. W/o encl. KEPPLER, J. O. Region 9, Chicago, Office of the Director. 79/08/21.
- --8009290163 Discusses IE insp of License 97-18461-01MD on 800122 & forwards notice of violation & notice of proposed imposition of civil paralties.

  STELLOV. Diffice of Inspection & Enforcement, Office of the Director. 80/02/19. 2pp.
- --8009270166 Notice of violation from insp on 800122.
  \*\* Office of Inspection & Enforcement, Office of the Director.
  80/02/19. 1p.

- --8009290170 Notice of proposed imposition of civil penalties \* Office of Inspection & Enforcement, Office of the Director 80/02/19 ip.
- ---B009290176 Requests 60-day extension on behalf of Nuclear Phermacy, Inc for responding to 790817 notice of violation Vendor would like to prepare effective, tharough written reply Excerpts from IE insp manual encl. VAKERICS:T V O'Connor & Hennen. 79/08/29 Sipp
- 8009290027 FDIA request for documents re NRC Jan 1979-June 1980 insp of facilities owned or operated by Pharmatopes, Inc. Pharmaco Nuclear, Inc & Nuclear Pharmacy, Inc VEVE, M.E. D'Connor & Hannen 80/06/30 2pp.
- 8009290414 Responds to FOIA request for listing of specific info re current contracts. Forwards list entitled, "Contracts Executed in FYBO " FELTON, J H Division of Rules and Records 80/09/18 ip
- 8009290423 FDIA request for listing of specific info re current contracts. OILLOQUEY.J PRC Information Services Corp. 80/09/04 ip
- 8009290443 Responds to FDIA request for NUREO-0654/FEMA-REP-1,1964-65 revision of MASH-740, "Theoretical Possibilities & Consequences of Major Accidents in Large Nuclear Power Plants" & NUREO-0610, Forwards documents in app. W/o encls. FELTON, J M Division of Rules and Records. 80/09/22 2sp.
- 8009290449 FDIA request for NUREC-0554/FEMA-REP-1,1964-65 revision of MASH-740, "Theoretical Possibilities & Consequences of Najor Accidents in Large Nuclear Power Plants" & NUREC-0510 CAPAKANA, S Affiliation Unknown. 80/09/07. 1p.
- )09300109 Responds to appeal re denial of J Holiver FOIA request for rept. "Economic Evaluation of Alternatives," associated itr & summary rept Document is still being withheld. Forwards correspondence between NRC & Cincinnati Gas & Electric Co. FELTON, J M Division of Rules and Records. 80/09/11 ip.
- ~-8009300119 Responds to NRC request for add1 info re FDIA request for rept, "Economic Evaluation of Alternatives " Release of document could cause substantial harm to involved parties, NRC should deny appeal & continue to withhold rept. WETTERHAHN, M.J. Conner, Moore & Corber, 80/02/15 2pp.
- --8009300126 Responds to NRC 791221 request for eddl info re FOIA request for rept. "Economic Evaluation of Alternatives " NRC should continue to withhold document Info is significant to competitive positions Supporting documentation encl.
  BORGMANN-E.A Cincinnati Gas & Electric Co 80/01/11 7pp
- --8009300136 Requests response to questions to aid in NRC determination of whether Sargent & Lundy Engineers Rept 8L-2561, "Economic Evaluation of Alternatives," associated ltr & summary rept is exempt from public release under FOIA Exemption 4. CARR, J. C. Division of Rules and Records 79/12/21 2pp.
- 8009300113 Requests on behalf of J Woliver, that NRC reconsider denial of FOIA request for Sargent & Lundy Engineers rept, "Economic Evaluation of Alternatives," associated ltr & summary rept.

  MEYER, K.A. Public Citizen Litigation Group. 80/06/27, 2pp
- 8009300284 Responds to FOIA request for listing of locations where nuclear matis are stored, user or dumped in US, Forwards documents listed in App A & discusses four categories of nuclear waste. Listing of agreement states only encl. FELTON, J M Division of Rules and Records. 80/09/23 4pp.
- 8009300289 FDIA request for listing of locations where nuclear matla are stored used or dumped in UB BOSMORTH, O. R. Affiliation Unknown. BO/08/20 ip
- 8009300330 Responds to FOIA request for written rept & ltr involving 800619 insp of Diagnostic Isotopes, Inc Forwards documents. Info partially withheld name, birthdata & social security number (ref FOIA Ezemption 6). Wo encls.

  FELTON, J. K. Division of Rulss and Records 80/09/23, 1p
- 8009300333 FDIA request for written rept & 1tr involving 800619 insp of Diagnostic isotopes Inc. ZNICK, E.J. Affiliation Unknown. 80/09/03 ip.

- GO09300620 Responds to FOIA request for all notifications received by NRC re shipment of radioactive matis through FL from Jan 1979 to present No documents have been located subj to request FELTOM. J M. Division of Rules and Records. 80/09/16. 1p.
- 8009300624 FDIA request for all notifications received by NRC reshipment of radioactive matts through FL from Jan 1979 to present.
  WILLIE,R J. Florida Rural Lagel Services, Inc. 80/09/01 2pp.

#### GEN TEC IS GENERIC TECHNICAL ISBUES

- 9009020519 "Evolution of Wake in Unsteady Flow & Transverse Forces," Unpublished mame. SARPKAYA.T Affiliation Unknown 80/08/25 18pp.
- 9009030667 Forwards FR notice of issuance & availability of NUREO-0612, "Control of Heavy Loads at Nuclear Power Plants Resolution of Task A-36."

  CHILK-S.J. Office of the Secretary of the Commission 90/08/15.
- --8009030669 Notice of issuance & availability of NUREO-0612, "Control of Heavy Loads at Nuclear Power Plants Resolution of Task A-36," EISENHUT, D. O. Division of Licensing, 80/08/12 4pp.
- 8009230430 Forwards nonproprietary version of NEDO-24798. "Mark II Containment Program Caorso Extended Discharge Test Rept." on behalf of Mark II owners group as part of Task 8-5. BUCHEDIZ.R.H. General Electric Operating Plant Cuners Group. MFN-158-80 80/09/12. 1p.
- --8009230431 NEDD-24798
  Nonproprietary version of "Mark II Containment Program,
  Caorso Discharge Test Rept "
  HOLAN, J., MINTZ, S., MUZZY, R. J. General Electric Co BONED282
  80/08/31 35pp
- 8009230472 Forwards nonproprietary version of NEDO-24811, "4T Condensation Oscillation (4TCD) Test Program Final Test Rept: "on behalf of Mark II owners group as part of Task A-17.

  BUCHHOLZ, R. H. General Electric Operating Plant Owners Group. MPN 153-80 80/09/03, 1p
- --8009230475 NEDO-24811
  Numproprietary version of "AT Condensation Oscillation (4TCO) Test Program Final Test Rept."
  BYRD.P.K., FITTRIHMONS,C., ROPERS, A E General Electric Co. 80NED057, 80/07/31 100pp.
- 8009300214 Summary of 800827 meeting w/nuclear industry representatives in Bathesda, MD re resolution of differences that exist between NRC & industry approaches to component support fracture toughness problem.

  SNAIDER, R P. Systematic Evaluation Program Branch (Pre 791030).

  80/09/10 2ipp

#### IAE INSPECTION AND ENFORCEMENT

- 8005050055 IE Bulletin 80-07. Suppl 1: "BWR Jat Pump Assembly Failure." # Office of Inspection & Enforcement, Office of the Director. 80/05/03 1p.
- 8003050070 IE Circular 80-19, "Noncompliance W/License Requirements for Medical Licensees," \* Office of Inspection & Enforcement, Office of the Director 80/08/26. 3pp.
- 8006190028 IE Info Notice 80-29, "Broken Stude on Terry Turbine Steam Inlet Flange." \* Office of Inspection & Enforcement, Office of the Director, 80/08/07. 2pg.
- 8006190036 IE Circular 80-20, "Changes in Safe-Slab Tank Dimensions." \* Office of Inspection & Enforcement, Office of the Director. 80/08/21 3pp.
- 8006190038 IE Circular 80-18. "10CFR50.59 Safety Evaluations for Changes to Radwatte Treatment Sys." # Office of Inspection & Enforcement. Office of the Director 80/08/22 4pp

- 8006190040 IE Info Notice 80-31, "Maloperation of Gould-Brown Bovers 480 Valt Type K-6008 & K-DON 6008 Circuit Breakers " # Office of Inspection & Enforcement, Office of the Director 80/08/27, 7pp.
- 8006190042 IE Bulletin 79-26, Revision i, "Boron Lots from BWR Control Blades."

   Office of Inspection & Enforcement, Office of the Director, 80/08/29 dos
- 8006190044 IE Info Notice 80-32, "Clarification of Certain Requirements for Exclusive Use Shipment of Redicactive Matl " a Office of Inspection & Enforcement, Office of the Director 800/00/00 11mm
- 6006190052 IE Bulletin 80-19.Revision 1. "Failures of Marcury-Hattad Matrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E " = Office of Inspection & Enforcement, Office of the Director. 80/08/15 3pp
- 900419008: IE Circular 80-21, "Regulation of Refueling Crews" \* Office of Inspection & Enforcement, Office of the Director, 80/09/10, 4pp
- 8008210619 EN-80-036.on 900811; order to show cause why license should not be revoked & order suspending license (effective immediately) are being issued. Action based on alleged items of noncompliance re double dosage for certain scans.

  BROCKETT.T.M., THOMPSON.D. Office of Inspection & Enforcement, Office of the Director 80/08/11. 19
- BOOT020501 PNO-I-80-122: on 800815, unplanned release of gaseous radioactivity from Unit 3 reactor bidg vent occurred. Release rate was 33% of Tech Spec limit. Caused by malfunction of Unit 2 offgas sys during mods.

  OREENMAN.E. Region 1, Philadelphia, Office of the Director 80/08/15. 2pp.
- 9009100372 PNO-I-80-125: on 800829, Region i received inquiries about fire in commercial garbage truck which contained radioactive math. State of PA has dispatched radiological inspector No significant radiological hazard is expected, COSTELLO, F., SHITH, O.H. Region 1, Philadelphia, Office of the Director. 80/08/29 ip
- 8009120214 PNO-V-80-066, media increase on rise Board of Supervisors of City & County of San Francisco & other groups have been critical of EPA for delays in release of info on surveys of sea disposal sites off coast of CA.

  800K.H.E. Region 5, San Francisco, Office of the Director.

  80/08/20. 2pp.
- 8009180149 PNO-IV-80-028: on 800903, svc water flow to containment cooling coils failed to meet min flow rate required by Tech Spaces. When compliance w/Tech Space could not be demonstrated unit was shut down Licenses is investigating.

  JOHNSON, M. D. Region 4, Dallas, Office of the Director. 80/09/04, 2pp.
- 8009190418 EN-BO-039.on 800910.notice of violation & notice of proposed imposition of civil penalty will be issued, based upon alleged item of noncompliance re loss of radiographic exposure device.

  BROCKETT.T.M., THOMPSON,D. Office of Inspection & Enforcement, Office of the Director. 80/09/08, ip.
- 8009190600 PNO-IV-80-030 on B00905, furing full power operation steam generator tube lest occurred Lesk was indicated by N-15 detector, offgas monitor t main stack monitor. Unit will be thut down approx two wks.

  JOHNSON, W. D. Region 4, Dellas, Office of the Director. 80/09/05.
- 8009190765 PNO-78-147: on 780818, one of six air compressors experienced measure failure resulting in rapid loss of control air pressure to all units. Caused by large hole in cylinder head. Btats of AL notified Hedia attention anticipated. KLINGER, O., NOLAN, F., SNIEZEN, J. Office of Inspection & Enforcement, Office of the Director. 78/08/18, 1p.
- 8009230655 PNA-80-33: on 800903. Medical Research Foundation, Inc., shipped 4 vials of microspheres tagged w/Yb-90. Customer notified company of apparent tagging problem. Eight patients treated. OA will not reauthorize shipments w/o FDA verification. KERR. O. W., MCORATH, J. R. Office of State Programs, Director. 80/09/18. ip.

- 8009300048 EN-80-041 on 800918 notice of violation & proposed imposition of civil penalties will be issued Action based upon items of noncompliance re shipment of low specific activity radioactive matl BROKKETT.T.W. THOMPSON, D. Office of Inspection & Enforcement, Office of the Director 80/09/14 ip
- 8009300162 PNO-V-80-066 state & local govts in GA have been critical of EPA for delays in release of info re surveys of sea disposal sites on CA coast Inquiries received from media BDOK-H E Region 5. Ban Francisco, Fuel Facility & Materials Safety Branch 80/08/20 2pp
- 8009300166 EN-80-042 on 800919, notice of violation & notice of proposed imposition of civil penalties to be issued to C Immerman, MD Action based on two alleged items of moncompliance re loss of I-131 capsule BROCKETT, T., THOMPSON, D. Office of Inspection & Enforcement, Diffice of the Director, 80/09/17 ip
- 6009300190 PNS-80-003 on 800910, near Roanoke, VA truck carrying shipment of low enriched U was abandoned by driver because of two flat tires. Another driver & mechanic were dispatched to truck.

  JAMES, J W . BUSH, L, L . HOMARD, E, M. Office of Inspection & Enforcement, Office of the Director 80/09/13 ip.
- 8009300600 PNO-I-80-129: on 800914.plant was shutdown when one of three seals failed on three reactor coolant gump Bhutdown expected to last until 800918.

  LAZARUS.N. J. Region 1, Philadelphia, Office of the Director. 80/09/15 1p

#### MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

- 8009080485 Ack receipt of ltr re GA of training programs. Brudy of operator training programs & methods for accrediting training institutions underway RFP will be forwarded if need for GA program is established.

  COLLINS, P. F. Operator Licensing Branch. 80/08/14. 1p.
- 8009100632 Forwards FR notice of Advisiony Committee on Medical Uses Isotopes 800818 public meeting CHILK:S.J. Office of the Secretary of the Commission 80/04/20 in
- --8009100635 Notice of Advisory Committee on Medical Uses of Isotopes 800818 public meeting or experience criteria for physician users & other related Issues HOYLE, J. C. Office of the Secretary of the Commission. 80/06/20.
- 8007110577 Discusses draft IE Bulletin 80-21 re integrity of polymer coating for surfaces inside containment All plant sys which take suction from containment sump during accident mitigation should be included in projected evaluation MICHELSON.C. Director's Office. IEB-80-21. 80/08/29. 2pp.
- 8009150647 Responds to request re funding for development of training programs for nuclear power plant personnel. At present, training is responsibility of industry Study is underway to determine if NRC should become involved.

  GOLLING.P F. Operator Licensing Branch 80/08/26 if
- 8009170178 Responds to 800730 ltr requesting published repts on U mining & milling including repts on exploration & hezerds involved Forwards draft QEIS on U milling & NUREO/GR-0573 H/d encl.
  FISHER, B P Uranium Recovery Licensing Branch 80/08/24 1p.
- --8009170181 Requests repts on U mining & milling, including repts on exploration & hazards & NUREO-0511.
  PASSAKANI.8 Affiliation Unknown 80/07/30 ip
- 8009190197 Recommends endorsement of research program, entitled "Bur Have & Meteorological Measurements Along Coast of FL." SCHROEDER, F. Assistant Director for Generic Projects. REB-80-3 60/08/29 1p
- --8009190205 Forwards research proposal entitled "Burge, Have & Meteorological Heasunements Along Coast of FL " Requests return of signed memo if proposal is responsive to Ofc of Nuclear Reactor Regulation."
  BUDNITT, R. J. Office of Nuclear Regulatory Research, Director RES-80-3 80/06/27. App.
- ---B009190211 Marked-up research proposal entitled "Hydrodynamic & Mateorological Measurements of High Wind Over Shallow Water Along Coast of FL " \* Florida. Univ of, Qainasville. 80/03/31 16pp.

BO09220125 Responds to 800715 ltr requesting info re licensing delays of new nuclear plants FMI accident has delayed licensing activities NRC currently considering licensing three plants Forwards NUREO-0674 M/o encl DENTON.H R Office of Nuclear Reactor Regulation, Director 80/08/15 4pp

--8009220128 Requests info re nuclear plant licensing delays Nuclear power viewed as great banefit to country.

BEATTY, D Affiliation Unknown 80/07/15 ip.

8009290379 Forwards recommendations re OC of sieves used to test concrete & soil const matls Verification sieve conforms to requirements when received. Frequent visual checks by user & annual period checking recommended HAASS, W.P. Quality Assurance Branch. 80/09/03 2pp

8009290498 Submits check list for issuance of facility licenses Includes required findings license conditions & requirements prerequisite to licensing REIS.E J. Rearings Division 80/09/19 9pp

NUREO REPORTS AND RELATED CORRESPONDENCE

8008280370 Forwards comments on proposed Revision 2 to BRP 3.7 6. value/lepact statement & NUREQ-0577. UTLEY.E.E. Carolina Power & Light Co. NO-80-1123. 80/07/30, 12pp.

8009020023 Discusses schedule for Alternate 2A ATMB plant mode proposed in Draft Vol 4 of NUREQ-0460, Proposed schedule unrealistic due to non-ATMB mode Preliminary schedule of 3 5 yrs reached w/Middle Bouth Bycs is more realistic.

SHERHOOD, 0.0 General Electric Co MFN 146-80. 80/08/22 2pp.

8009020161 NUREO/CR-1607
"Prop-Size Estimates for LUCA."
"ESTEL,A . PION. 0 . LAPKIN, D.E. Los Alamos Beientific Laboratory.
"N A-7105 LA-8449-NS. 80/08/31. 3ipp. Available at GPD.

0294 Comments on proposed revision to SRP Section 3.9 6, ervice Testing of Pumps & Valves. Document does not titute viable testing program, in present form, LEG.D.L. Commonwealth Edison Co. 80/07/31. 4pp

O316 Submits review of draft NUREO-0676 re proposed nuclear data . Recommends that specific provisions re determining ential for breaching barriers to radioactivity release & litoring site meteorological data be added EALY, H O South Carolina, State of 80/08/27. 2pp

)9020349 NUREO/CR-1377
"Risk Methodology for Gaologic Disposal of Radwaste:
Transport Model Sensitivity Analysis."
CAPPBELL.J E. IMAN.R.L. Bandia Laboratories REEVES,M INTERA
Environmental Consultants. Inc FIN A-1192. SANDBO-0644, 80/06/30
83pp Available at NTIS.

120355 NUREO/CR-1602
rength & Stiffness of Tensioned Reinforced Concrete
1s Subjected to Membrane Sheer, Two-Way Reinforcing. "
IKARIB.P.C., WHITE.R.N., GEROELY.P. Cornell Univ. FIN B-5688.
7/31 350pp. Available at NTIB.

0358 NUREO/CR-1482
lear Power Plant Simulators.Use in Operator Training & alification. \*\*
8.0 H · BAER, D. K. · FRANCIB, C. C. Dak Ridge National Laboratory.
8-0421-8. ORNL/NUREO/TM-3 80/07/31 144pp. Available at

"361 NUREO/CR-1448
ical Protection of Nuclear Facilities, Guarterly
eas Rept Jan-Mar 1980."
HANLL D. Bandla Laboratories. FIN A-1060. BANDBO-1006
/31. 19pp. Available at NTIS.

373 NUREO-0540 V2 NO5 » List of Documents Hade Publicly Available, " 780, Vol 2, Number 5, fice of Afministration 80/05/31, 352pp. Available at NTIS

179 NUREG/CR-1892
'ssible Analysis of Inlet Plenum Pressure Rise Due to oiling in Fuel Subassemlies During Pump Coastdown

AH, HUMMEL, H. H. Argonne National Laboratory FIN A-2015. B. 80/05/31 2ipp. Available at NTIS. 8009020483 NUREO/CR-1340

"State-of-the-Art Study Concerning Near-Field Earthquake
Oround Motion: "annual rept. Sept 1978-Sept 1979
SHAMPER,H. J. HARPHY, J. R. SENNETT, T. J. Systams, Sciences &
Boftware FIN 8-6491 888-R-80-4217, 80/08/31 148pp. Available

BO09020519 \*Evolution of Wake in Unsteady Flow & Transverse Forces, \* unpublished memo.

BABPKAPA T. Affiliation Unknown 80/08/25 18ss

8009030006 Comments on proposed Revision 2 to SRP 3.96. CURTIS.N.M. Pennsylvania Power & Light Co 45FR36236 011. 80/07/30 2pp

BOO7030012 Comments on proposed Revision 2 to SRP 3.9.A re inservice testing of pumps & valves: revision required due to inconsistency w/requirements of ABME code CROUSE.R P Toledo Edison Co. 45FR36236 00B. BO/07/25. 3pp

BOG9030014 Comments on proposed Revision 2 to BRP 3 9.6: improper forum for enumerating new requirements to be backfitted onto licensed facilities. Mandating generic change to specific facility before risk assessment is performed imappropriate OLBON, R C. Baltimore Oms & Electric Co 45FR36236 013 80/07/28.

8009030032 Forwards notice of availability of NUREO/CR-1580, "Draft Human Engineering Quide to Control Room Evaluation," for publication in FR CHILK, B. J. Office of the Secretary of the Commission. 80/09/15.

--8009030055 Notice of availability of NUREO/CR-1580, "Draft Human Engineering Quide to Control Room Evaluation."

TOND1.D Human Factors Engineering Branch. 80/08/12. 3pp.

8009030663 86-1120838-00

"Evaluation of Instrumentation to Detect Inadequate Core
Cooling," prepared for 177 ceners group
FROTH D Batcock & Wilcox Co. 80/08/15. 18pp

9009030667 Forwards FR notice of issuance & availability of NUREO-0612, "Control of Heavy Loads at Nuclear Power Plants - Resolution of Task A-36."

CHILK, B J Office of the Secretary of the Commission, 80/08/15.

19.

--8009030669 Notice of issuance & availability of NUREO-0612, "Control of Heavy Loads at Nuclear Power Plants - Resolution of Task A-36" EISEMMUT.D O. Division of Licensing. 80/08/12 App.

8009030471 NUREO/CR-1543

009030671 NUMEW/UR-1063
"Eddy-Current Insp for Steam Cenerator Tubing Program,"
annual progress rept for puriod ending 791231.
DODD,C V DEEDS.M., MCCLUMO,R W. Oak Ridge National Leboratory.
FIN 8-0417 DRNL/NUREO/THI-. 80/07/31. 27pp. Available at NTIS

8009040437 NUREO/CR-1487
"Vital Area Analysis Using 8st Equation Transformation Sys."
8TACK, D. N. FRANCIB, K. A. Sandia Laboratories. FIN A-1040.
80/05/31. 25pp. Available at NT18.

8009040487 Notice of availability of draft NUREO/CR-1580, "Human Engineering Quide to Control Room Evaluation." TONDI,D Division of Human Factors Bafety. 80/08/12. 3pp.

8009040461 BECY-80-253
Informs of Ofc of Nuclear Regulatory Research comments on ACRB rapt to Congress - NUREO-0557, "Review & Evaluation of NRC Safety Research Program for FYS1." Annual ACRS review is extremely valuable Specific comments encl.
BUDNITZR. J. Office of Nuclear Regulatory Research, Director.

8009040495 Submits comments re draft NUREO-0578. "Clarification," per 800815 mesting request. Discusses shift personnel education & training. THOMAS,E.L. Institute of Nuclear Power Operations. 80/08/27, 2pg.

8009050361 Forwards draft radiological emergency preparedness plan, addressing criteria in NUMES-0634.W/o encl.
DAVIDOF:D 8. New York, State of. 80/09/02 2pp.

8007050397 Transcript of 800820 workshop re emergency response facility hosted by Region 3 in Chicago, IL. Pp 1-238.

\* Commission 80/08/20. 238pp.

8009050403 Transcript of 800819 workshop re amergency response facility hosted by Region 1 in Valley Forge, PA Pp 1-291 a Commission. 80/08/19. 291pp.

B0090B0392 NUREO/CR-1592

DOMENCY™ NURLEVOK™107≤ "Compressible Analysis of Inlet Plenum Pressure Rise Dus to Saddum Boiling in Fuel Subassemblies During Pump Cometdown OF LIMBR
KALINILAH, HUMMEL.H H. Argonne National Laboratory. FIN A-2015.
AAL-80-48 80/03/31. 22pp Available at NTIB

8004080402 NUREO/CR-1583
"Radon Release & Dispersion from Open Pit U Mine "
K/BIELESKI, M.E. Argonne National Laboratory FIN A-2209.
ANL/EB-97 80/06/30. 74pp Available at NTIS

BOOPOPOOZO NUREO/CR-1484
"Dynamic Analysis to Establish Normal Bhock & Vibration of Radioactive Matl Shipping Packages," quarterly progress rept Oct-Dec 1979, FELDS, R. r. MECH. S. J. Hanford Engineering Development Laboratory FIN 8-2263, HEDL-TME 80-24, 80/08/31, 33pp

BOOTOTO639 Ack receipt of BOO528 itr re NRC rulemaking on emergency planning for nuclear facilities & forwards final rules on easignment planning.

AHEARNES, J. F. Commission. 80/08/14 1p.

--8009090ABB Comments on draft guidelines published as NUREQ--0610, "Draft Emergency Action Level Guidelines for Nuclear Power Plants." NRC should give more cognizance to programs & responsibilities of federal state & local govt agencies. COX.F.T. Texas. State of 79/11/29 5pp.

--- 8009090662 Comments on NUREO-0654 re emergency response plans. Objects to provisions seemingly included for benefit of federal personnel reviewing state & local plans.

COX.F. T. Texas: State of 80/05/13 7pp

9009090799 SECY-79-430

OCTOYOTYY SECY-7Y-430
Informs of Ofc of Nuclear Regulatory Research comments on ACRS rest to Congress - NUREO-0496, "1978 Review & Evaluation of NRC Safety Research Program " ACRS comments & recommendations useful Specific comments encl LEVINES, Office of Nuclear Regulatory Research, Director 3370, 79/07/06, 26pp.

BOO9100036 HRMEO/CR-1185

"COMPARE-Mod 1 Code Addendum"

GIDO,R.O., WILLCUTT,O J.E., LUNSFORD, J.L. Los Alamos Scientific
Laboratory, FIN A-7109. LA-7199-MS ADD1. 80/08/31. 54pp
Available at NTIS. #3 25.

BOO9100043 NUREC/CR-1625

\*Bleas-Nater Hixing % Sye Hydrodynamics Program - Task 4, "
quarterly progress rept Jul-Sept 1979.
COLLIER'S P., DHORAK', A. FLANIOAN, L. J. Battelle Memorial
Institute, Columbus Laboratories. FIN A-4048 BHI-2058 BO/08/31.
125pp. Available at NTIB. \$4.75.

8009:00033 NUMEO/CR-1458 "Radiation Dose Estimates & Hazard Evaluations for Inhaled Airborne Radionuclides," annual progress rept Jul 1978-June 1979. MEMHINMEY, J A. Lovelace Biomed & Environmental Research Institute. FIN A-1031. LF-71, 80/04/30, 95pp. Available at NTS. \$5.25.

#009100158 NUREO-0478

"Effects of Temp. Moisture, Concentration, Pressure & Hass
Transfer on Adsorption of Krypton & Xanon on Activated Carbon. "
UNDERHILL, D. W., MOELLER, D. W. ACRB - Advisory Committee on Reactor Bafaguards. B0/08/31, 1200pp.

B009100403 NUREO/CR-1349

normal manus/UR-1349 "Reactor Safety Research Programs," quarterly rept,Oct-Dec 1979. 1979.
DOTSON, G.W. Battelle Memorial Institute, Pacific Northwest
Laboratory. FIN 8-2041. PNL-3040-4. 80/08/31. 175pp. Available
at NYIB. X5.50.

BO09100407 NURE0-0483

"Rept on Nuclear Industry & Procedures for Safety Analysis
Computer Code Davelopment & Use."
SHERON, B. W. Reactor Systems Branch, ROGITOCZY, Z. P. Equipment
Qualification Branch, 80/08/31, 163pp. Available at NTIS

8009100413 NUREQ/CR-1847

NO9100413 NUREO/CR-1347
"Criticality Elpeniments H/Bubcritical Clusters of 2.35 Ht%
& 4.31 Ht% U-235 Enriched U Dioxide Rode in Water at Water
to Fuel Vol Ratio of 1 6."
BIERMANN 8 R. CLAYTON E D Battelle Memorial Institute, Pacific
Northwest Laboratory. FIN 8-2094 PML-3314 60/07/31 38pp
Aveilable at NTT9. Available at NTI8

B009100944 NUREQ/CR-1347 NOP100944 NUREC/CR-1347
"Thermacouple Signal Sensitivity to Sheath Thickness of
Thermacouple Signal Sensitivity Indirectly Heated Electric
Fuel Pin Simulators"
DABBS: D. DTT.L J Gak Ridge National Laboratory FIN 8-0125
ORNL/NUREC-62 80/08/31 64pp Available at NTIS.

8009100947 NURFO/CR-1404

DOYLOUSY, NAREO/CR-1404
"Transient Analysis of Godlent Flow & Heat Transfer in LMFBR Piping Eys "
MADNI,I.K Broothaven National Leboratory, FIN A-3015 BNL-NMREG-51177, 80/04/30 49p Available at NTIS

8009100950 NUREQ/CR-0803

Risk Assessment of PHR for Class 3-8 Accidents "
RALL, R.E. Brockhaven National Laboratory. FIN A-3057
BML-MUREG-50950 79/10/31 494pp Available at NTIS.

8009100933 NUREO/CR-1521
"HTOR Bafety Studies for Div of Reactor Safety Research."
quarterly progress rept. Jan-Mar 1980
BALL.8 J., CLEVELAND, J.C., CONKLIN, J.C. Dat Ridge National
Laboratory, FIN 8-0422 GRNL/MUREO/TM-3 80/08/31 30pp.
Available at NTS.

8009100754 NUREO/CR-1450
"Multirad Burst Test Program," progress rept for Jul-Dec CHAPHAN, R. H. Oak Ridge National Laboratory FIN 8-018 DRNL/NUREG/TM-3 80/08/31, 138pp Available at NTIS. FIN 8-0120

BOO9110321 NUREO/CR-1402
"Advanced Reactor Bafety Research Div," quarterly progress
rept.Oct-Dec 1979.
ROWIELH.J.C., KATO.W.Y., ROMANO.A.J. Brootheven National Laboratory.
FIN A-3015. BML-MUREQ-51177. B0/04/30 95pp Available at QPO

8009110372 NUREO/CR-0200 VI

204110372 NOMEO/CH-0200 VI \*\*Scale Modular Code Bys for Performing Standardized Computer Analyses for Licensing Evaluation: Scale Bys Criticality Safety Analyses Modules CBASI & CBASE \*\* BUCHOLZ, J A , WESTFALL, R. H. HERMANN, O W. Dak Ridge National Laboratory, FIN 8-0172, ORNL/NUREO/CSD-, 80/08/31, 305pp.

8009110500 NUREO/CR-0761

RV4110300 NUREVICK-0701
"Extended Analysis of Data from 1/5-Ecale Mark I BWR
Pressure Suppression Experiment "
MCCAULEY,E W . HOLMAN, O.B., CARR,E.W. Laurence Livermore Laboratory
FIN A-0188-9 UCRL-92707 S0/07/31. 293pp.

8009110503 NUREO/CR-1516
"Nuclear Reactor Safety," quarterly progress rept
Oct - Dec 1977.
JACKSON, J. F., BTEVENSON, M. Q. Los Alamos Scientific Laboratory
LA-8299-PR. 80/05/31. 154pp Available at NTIS

8009110639 NUREO-0436 NO1 Bi "Plan for Re-evaluation of MRC Policy on Decommissioning of Nuclear Facilities." CALKIMB, Q.D. Office of Standards Development, Director, 80/08/31

9009126333 NUREQ-0540 V2 NO&

Title List of Documents Made Publicly Available, " June 1980, Vol 2, Number 6, \* Division of Technical Information & Document Control. 80/08/31. 455pp. Available at NRC 48.50.

8009120336 NUREO/CR-1609
"Daterministic-Probabilistic Hodel for Containment
Transport." user manual
80HMMRT2.F W. GROME.A. COB, Inc. FIN 8-6693 COB/NR85U060
80/08/31. 166pp Available at NRC 45 50.

8009120337 NUREQ-0679

AVVIROUS/ NAMEG-D679

"Pipe Cracking Experience in LWRs."

"Pipe Cracking Experience in LWRs."

FRAMW. R. Structures & Components Standards Branch HAZELTON, W.S.

FRAMW. R. Office of Inspection &

Enforcement. Office of the Director BO/08/31 Sipp. Available at

NRG. \$2.25.

8009120338 NUREO/CR-1038
"Dynamic.Inelastic Buckling Analysis of Mark I Torus Bupport
Columns "
BENDA, B J Lawrence Livermore Laboratory FJN A-0213 UCRL-52723.
80/08/31 65pp Available at NRC 63 50

8009120339 NUREO/CR-1120 V3
"Beismic Safety Margins Research Program (Phase 1),"
Programs Rept 7, through June 1980, Vol 3
BAILEY:R D , BHITH.P. D , DONO.R.O Lawrence Livermore Laboratory
FIN A-0126 80/06/30 95pp. Available at NRC. \$4 00

8009120628 NUREG-0718 DRFT
"Proposed Licensing Requirements for Pending Applications for CPs & Hfg Licenses." Graft rept for comment # Office of Nuclear Reactor Regulation, Director 80/08/31 Sopp

8009120664 Reaffirms NRC position on incorporating Lessons Learned Short-Term Requirement 2 i 3 b in TMI action plan. Instrumentation is guidelines for indication of inadequate reactor core cooling do not satisfy long-term requirement. ROSS, D F Division of Systems Integration 80/09/09 2pp

8009150245 Provides addl comments on hydrogen control & improvement of containment capability Recommendations in ACRS 791213 btr re reliability assessments & design features for core damage & core melt accidents should be adopted & given priority. PLESET, NS ACRS — Advisory Committee on Reactor Safeguards, 80/09/08 2pp.

8009150249 Discusses 245th ACRS meeting re final version of NUREO-0630, "Cladding Swelling & Rupture for LDCA Analysis." Implementation should be held in abeyance until NRC revises code requirements PLEBBET.M.S ACRS - Advisory Committee on Reactor Safeguards. 80/09/09 2pp

8009150585 NUREO/CR-1608
"Scenario Davelopment & Evaluation Re Risk Assessment of High Level Redwaste Repositories." final rapt, June 1979-June 1980
GCHMARTZ,F W., DONATH,F A. CGS,Inc., FIN 8-6693. CGS/NR85F060
80/08/31 98pp Available at NRC #4 00

009150595 NUREO/CR-1471
"Assessment of LHR Fusl-Failure Propagation Potential"
Literature Burvay "
CRONNENBERO, A. SCOTT, J H Los Alamos Scientific Laboratory
LA-URBO-45-15, 80/08/31, 150pp, Available at NRC \$4.75

8009150397 NUREO/CR-1302
"Study of Pu Oxide Powder Emissions from Simulated Shipping Container Leaks"
"YESSO, J D , MADIA, W. J Battelle Hamorial Institute, Columbus Laboratories SCHMENDIMAN, L. Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2093 PNL-3278 80/08/31, 109pp Available at NRC 84, 23

BOO9150597 NUREO/CR-1634
"Film Entrainment & Drop Deposition for Two-Phase Flow,"
informal rept.
KOE8TEL.A., 0180,R.O., QILBERTS,J.B. Los Alamos Scientific
Laboratory FIN A-7112 LA-8475-HB, 80/08/31. 26pp. Available at
NRC 41.75

8009160198 NUREO/CR-1333
"Flow Topography Instrumentation & Analysis Sys "
CARY.C.N Crears, Inc. FIN A-4070, TN-314, 80/08/31 45pp.
Available at NTIS. \$3 50.

BOO9140202 NUREO/CR-0200 VI
"BCALE Modular Code Bys for Performing Standardized Computer
Analyses for Licensing Evaluation, BCALE Bys Criticality
Safety Analysis Modules CSASI & CSAS2."
BUCHGLZ, J. A. Oak Ridge National Laboratory, FIN 8-0172,
DRNL/NUREO/CSD-. 80/08/31 450pp, Available at NTIS 47.00

3009160446 NUREO/CR-1593
"Performance Testing of Personnel Dosimetry Svcs
Alternatives & Recommendations for Personnel Dosimetry
Testing Program "
PLATO, P. HUDSON, O. Michigan, Univ. of FIN B-1049, 80/08/31,
55pp Available at NTIS \$3.50.

8009160450 NUREO/CR~1045
"Acute Effects of Inhalation Exposure to U Hexafluoride & Patterns of Deposition U Hexafluoride/U02F2 Studies in Experimental Animals. Rept Period-June 1978-Jul 1979."
MORROM-P.E., LEACH.L. J., SMITM:F. A. Rochester Univ. of FIN A-4083, 80/08/31. 114pp. Available at NTIS #4 25.

8009160456 NUREG/CR-1298
"Orouth & Histological Effects to Protothaca Staminea
(Littlemeck Clam) of Long-Term Exposure to Chlorinated Salt
Water."
GIBSON.C I , HILLMAN.R.E , HILKINBON.P. Battella Memorial Institute,
Pacific Northwest Laboratory FIN 8-2098 PNL-3158, 80/08/31
84pp Available at NTIS \$3.75

8009160481 NUREO/CR-0893
"Acute Toxicity & Dioaccumulation of Chloroform to Four Bperies of Freshwater Fish."
ANDERSON, D R . LUSTY, E. B. Battelle Hemorial Institute, Pacific Northwest Laboratory. FIN 8-2098 PNL-3046 80/08/31, 34pp. Available at NTIS \$3.50

8009160493 NUREO/CR-1539
"Hestodology & Preliminary Data Base for Examining Health Risks of Electricity Generation from U & Coal Fuels."
\* Oak Ridge National Laboratory EL-BASSIONI.A Science Applications, Inc FIN B-0424-8 ORNL/808-7615/1. 80/08/31 532pp. Available at NTIS

8009180434 NUREQ/CR-1582 V3
"Seismic Hatard Analysis, Solicitation of Expert Opinion,"
Vol 3.
BERNREUTER, D.L. Laurance Livermore Laboratory \* TERA Corp. FIN
A-0233 80/08/31 167pp Available at NTIS, \$5.50

8009180443 Forwards comments on proposed Revision 2 to BRP 3.9.6, Draft i, "Inservice Testing of Pumps & Valves," App A to BRP 3.9.6 "Leak Testing of Pressure Isolation Valves," Revision 0. Draft 1 & valve/impact statement for proposed App A LOOMIB.J. 8 Bargent & Lundy, Inc. 49FR36236 016, B0/08/14, 2pp.

8009180446 NUREG/CR-1582 V2
"Beismic Haiard Analysis. Methodology for Eastern U8," Vol 2.
BERNREUTER.D L Lawrence Livermore Laboratory # TERA Corp FIN
A-0233. 80/08/31. 138pp. Available at NTIB. \$4.75.

8009190398 NUREO/CR-1492
"Qualification Testing Evaluation Program LNR Safety
Research," quarterly rept. Jul-Sept 1977.
BDNION,L., OLLEN,K T. Sandia Laboratories, FIN A-1051-0
BAND80-1117 80/07/31. 62pp. Available at NTIS

8009190405 NUREO/CR-1358
"Vagetational Cover in Monitoring & Stabilization of Shallow
Land Burial Sites: " annual rept for Oct 1978-Sept 1979.
MALLACE.A., ROWNEY.E.M.: NISHITA: M. California: Univ. of, Los
Angeles FIN 8-3027-9. UCLA 12-1235 79/09/30. 132pp.

8009190672 Comments on proposed Revision 2.Draft 1,to SRP 3 9 6. "Inservice Testing of Pumps & Valves" CAHN.A.L. Bechtel Corp. 45FR36236 004 80/07/24 2pp.

8009190677 Comments on proposed Revision 2 to SRP 3 9.6, "Inservice Pump & Valve Testing " Rephrasing & clarification, as indicated, will be useful in development of pump & valve test programs. App A & value/impact statement should be withdrawn RENBERGER, D. L. Hashington Public Power Supply System 45FR36236 005. 80/07/23. 10pp.

BO09190684 Comments on proposed Revision 2, Draft 1 of BRP 3.9.6, "Inservice Testing of Pumps & Valves " Frequency of leak testing should ref ABME requirements rather than having basis on percentage of design pressure, PATT1.F.J. Burns & Roe Co 45FR36236 014, 80/08/08 2pp.

BOOP190691 Comments on proposed Revision 2 to BRP 3 9.6 re inservice testing of pumps & valves. AddI guidance should be provided to reviewer specifying pumps & valves to be included in inservice testing program.

ODODWIN.C. Portland General Electric Co 45FR36236 015 80/08/14.

8009190743 NUREO/CR-1509
"LWR Safety Research Program," quarterly rept Jan-Mar 1980.
BERMAN, Bandia Laboratories, FIN A-1019, BANDS0-1304/10F,
BO/07/31, 148pp. Available at NTIS,

8009190782 NUREC/CR-1527
"Enhancement of Nuclear Matl Mgt & Safeguards Sys," final rapt,
\*\* Beeing Computer Services, Inc. (subs. of Boeing Co.), FIN B-6902-9, 80/08/31, 200pp, Available at OPD

B009220217 Forwards comments on NRC draft criteria for util mgt & tachnical competence. Title should be changed to recognize distinction of document as being guidelines rether than criteria KEARNEY, J. J. Edison Electric Institute. 80/09/17. 6pp

8009220275 Documents comments made at NRC 800827 meeting w/industry representatives re NVREO-0577 NUREO-0577 does not distinguish between integral & nonintegral supports Integral supports have had more restrictive requirements ANDERBON.T M Hestinghouse Electric Corp NB-TMA-2304 80/09/09. Ep.

8009220277 Comments on NRC Biting Policy Task Force rept.Rationale for selecting min exclusion distance of 12.5 miles for all capable faults not clear Small faults which may be capable according to existing criteria may not be hazardous VEATCH.M.D. Ghannon & Wilson, Inc 80/09/12 ip

BO09240605 NUREO/CR-1113
"Licensability of CANDU-Type Reactors in UB," preliminary assessment of R&D requirements
CAVE.L. California, Univ of, Los Angeles FIN B-3004-9
UCLA-EN9-7953 B0/08/31, 110pp Available at GPD

BOO9240686 NUREO/CR-1677 V1
"Piging Benchmark Problems, Dynamic Analysis Uniform Support Motion Response Spectrum Method." Vol 1.
BEZLER,P., HARTIMAN,M., REIGH,M. Brookhaven National Laboratory FIN A-3225. ENL-NUREO-51267 BO/08/31 412pp Available at NTIE #8,00.

8009260028 MJREG/GR-1631
"Lateral Loads on Vent Pipe in Steam Chugging "
CATTON.I., CHAN.C.K., DHIR.V K California, Univ of, Los Angeles
FIN 8-5878 80/08/31. 158pp.

BOC9240092 NUREC/CR-1579
"Considerations on Nuclear Data Link Implementation in Relation to Technical Support CirrEmergency Operations Pacility & Safety Parameter Display Sys."
STIEFELD, B. VEPPESEN, D. Sandia Laboratories FIN A-1239 SAND BO-1618. BO/07/31 29pp.

80092&0191 Notice of extension of period for comment on draft NUREQ/ CR-1590, "Human Engineering Quide to Control Room Evaluation." TONDI.D Human Factors Engineering Branch 80/08/25. 1p

8009260896 NUREO/CR-1529
"Two-Phase Flow Measurements w/Advanced Instrumented Spool Places."
TURNADE,K C. Dak Ridge National Laboratory FIN 8-0401. ORNL/NUREO-72 80/09/30. 36pp Available at NTIS.

8009260669 NUREO/CR-1561
"Behavior of Hydrogen During Accidents in LURs "
GHERMAN, M. P. BERMAN, H. Sandia Laboratories. BIENIARZ, P. P. Energy Incorporated. FIN A-1051. SANDBO-1495 80/08/31. 310pp
Available at OPO.

B0092b0688 NUREO/CR-1428
"Bolublity Classification of Airborne U Products from LWR-Fuel Plants."
KALKHARF,D R Battalle Memorial Institute, Pacific Northwest Laboratory. FIN 8-21239, PML-3411, 80/08/31, 68pp. Available at QPD, 43,75.

8009290038 NUREO 0020 V4 NO8
"Operating Units Status Rept." data as of 800731
s Uffice of Management and Program Analysis, 80/08/31 200pp.
Available at NTIS. \$12.50.

8009270062 NUREO/CR-1485 VI NO1
"Bafeguards Matl Control & Accounting Program," quarterly
rapt Cct-Dac 1979: Vol 1:NO1.
DUNN, D. Lawrence Liveracre Leboratory FIN A-0115-0.
UCRL-52715-80-1. 80/09/30. 24pp. Available at NRC #1.75.

B009290296 Comments on draft NUREO-0696. "Functional Criteria for Easequency Response Facilities." Document would be improved if repatition of same requirements were minimized & expanded to provide guidence to multiple unit sites. COX.E L. Black & Veetch. 80/09/19. 2pp.

8009300160 NUREO/CR-1282

"Statistical Analysis of Steam Generator Insp Plans & Eddy
Current Tessing "
EASTERLING, R. G. Bandia Laboratories. FIN A-1108. BAND79-2300.
BO/08/31. 101pp. Available at OPO. \$4.25

SCC9300164 NUREC/CR-1657
"Btsam-Nater Mixing & Bys Hydrodynamics Program-Task 4,"
quarterly progress rept for Oct-Dec 1977.
SCCEV.A., FLANIGAN,L.J., COLLIER,R.P. Battells Memorial Institute,
Columbus Laboratories FIN A-4048 BMI-2062. 80/08/31, 119pp.
Available at OPD. \$4,25

8009300303 NUREG-0485
"Environ Assessment for Effective Changes to 10CFR50 & App E to 10CFR80: Emergency Planning Requirements for Nuclear Power Plants."
DTT.M.R 8it & Environ. Stds Br (formerly Environ Prot 8tds Br.) 80/08/31 58pp

8009300300 NURE0-0404 V2 NO3 "Ofc of Nuclear Reactor Regulation Unresolved Safety Issues Bummary Aqua Book," Vol 2 N 3 \* Office of Management and Program Analysis 80/08/15 44pp

B009300357 Forwards comments on NUREQ-0696. "Functional Criteria for Emergency Response Facilities " Quidelines should be developed from evaluation of what is attainable & actually matessary UTLEV.E.E. Carolina Power & Light Co B0/09/26 Bpp

8009300390 Comments on draft NUREO-0696 re functional criteria for emergency response facilities Independent verification requirements introduce unnecessary delays Availability goal should be adjusted DUNN, C. N. Duquesne Light Co. 80/09/26 4pp

8009300398 Comments on draft NUREO/CR-1580 re human engineering guide to control room evaluation Representative data samples must be included in development of human engineering stds SEELEY, Q. T., LEPPKE, D. M. Fluor Power Service. Inc. 80/09/26 App.

8009300436 Comments on draft NUREO/CR-1580, "Human Engineering Guide to Control Room Evaluation," Color conventions re red & green for abnormal & normal, respectively, may be dangerous Alternate method suggested.

SHERIDAN: T.B. Massachusetts Institute of Technology 80/09/23

8009300443 Comments on NUREO/CR-1280, "Power Plant Staffing." Caution unged before acceptance of info due to superficial nature of review & unsubstantiated statements. Naval nuclear propulsion progream has shortcomings TMI requirements not in rept. COUNSIL, N. O. Northeast Utilities HOC-80-G-623 80/09/25, 9pp

8009300447 Comments on NUREC-0676, "Functional Criteria for Emergency Response Facilities" Impossible for util to direct work & plan for new requirements w/o explicit direction Plant should be example from such requirements if derived by NRC BRYAN, J. K. Union Electric Co. ULNRC-391. 80/09/23. 1p.

8009300466 Forwards comments on draft NUREO/CR-1580, "Human Engineering Guide to Control Room Evaluation." Guide not directed at obvious problem. Recommendations include endorsement of ATOO approach & use of B&W ATOO training procedures

ENRIVER, E. L. Affiliation Unknown 80/09/26 Spp

8009300646 Forwards comments on NUREO/CR-0570 re technology, safety & costs of decommissioning ref low level waste burial ground.
Rept is thorough & analysis has been carefully considered HENARD, H. N. Interior, Dept of, Geological Burvey. EGB-ER-80/841 80/09/11. 5pp.

#### ORQ CORRESPONDENCE WITH OTHER ORGANIZATIONS

8009030082 Forwards notice of availability of IAEA draft safety guides re greatredness for emergencies at nuclear gover plants. CHILK, S. J. Office of the Secretary of the Commission. 80/06/18 is.

8009030305 Advises that Revision 1 to IE Bulletin B0-19, "Failures of Mercury-Wetted Harrix Relays in Reactor Protective Sys of Operating Nuclear Power Plants Designed by C-E," was sent to listed licensess on 800815. PAPPAB, H Region 3, Chicago, Office of the Director. 80/08/18, 280

8009080402 Forwards std order for DDE wort, "Geoscience Case Reviews II \* BCHROEDER,F. Division of Systems Safety. FIN A-7118-9. 79/09/18 289.

--B009050412 Btd order for DOE work, "Quantience Case Reviews II," issued to LASL Btatement of work entl.
TRIPLETT.M P. Division of Systems Gafety. FIN A-7118-9.
20-79-192. 79/09/17. Epp

8009090117 Advises that IE Bulletin 80-07, Suppl 1, "BWR Jet Pump Assembly Failure," was sent to listed licensees on 800513, PAPPAB, H Region 9, Chicago, Office of the Director. 80/05/15.

## NONDOCKETED ITEMS

- BO09140092 Advises that IE Info Notice 80-30, "Potential for Unacceptable Interaction Between Control Rod Drive Scram Function & Nonessential Control Air at Gertain GE BHR Facilities." was sent to listed licensees on B00819 PAPPAS.H Region 3, Chicago, Office of the Director 80/08/22
- 9009180062 Advises that IE Circular 80-18, "100FR50 59 Befety Evaluations for Changes to Radwaste Treatment Sys," was sent to listed licenses on 800822 PAPPAS.H Region 3, Chicago, Office of the Director 80/08/26 Rpp.
- 8009180123 Advises that Suppl 3 to IE Bulletin 80-17. "Failure of Control Rods to Insert During Boram at SMR," was sent to listed utils on 800822 PAPPAS, H Region 3. Chicago, Office of the Director 80/08/29 200
- BOO9180393 Recommends approval of draft ANSI/ANS 8td 3.3(NIS 17), "Security for Nuclear Power Plants " Submite comment on grandfather clause re criminal records check in personnel acreeming.

  BCHROEDER, F. Division of Safety Technology 80/09/10 1p
- 8009230106 Advises that IE Info Notice 80-31, "Maloperation of Quild-Brown Boveri 480 Volt Type K-6008 & K-DON 6008 Circuit Breakers," was sent to listed licenses on 800827 PAPPAB.II Region 3, Chicago, Office of the Director 80/08/30 200
- 8009230423 Advises that IE Circuler 80-20; "Changes in Safe-Blab Tank Dimensions," was sent to listed licensees on 800821 PAPPAS; H. Region 3, Chicago, Office of the Director, 80/08/25 480
- 8009290537 Advises that Revision 1 to IE Bulletin 79-26, "Boron Loss from BHR Control Blades," was sent to listed licensees on 800829, PAPPASH Region 3, Chicago, Office of the Director. 80/09/02 19
- 8009240386 Advises that IE Circular 80-19, "Noncompliance H/License Requirements for Medical Licensees," was sent to medical licensees on attached list on 800826, PAPPA9.H Region 3, Chicago, Office of the Director 80/08/30

## R PROPOSED AULE

- 005210647 Comments on proposed rule 100FR50: primary emphasis on plant safety should be maintained & present scope should not be expanded to safety-related sys & components PRATT. C.M. Power Authority of the State of New York. 80/03/27. Tap.
- 8009020544 Forwards notice of final rule 100FR40 re deletion of source mat1 medicinals from general license for small quantities of source mat1 for publication in FR on 800820 CHILK-S. J Office of the Secretary of the Commission 80/08/15, ip
- --8009020546 Notice of finel rule 10CFR40 re deletion of source matl medicinals from general license for small quantities of source stati.

  DIRCKS.M.J. Office of the Executive Director for Operations 80/08/07. 4pp.
  - 9030006 Comments on proposed Revision 2 to SRP 3.96 URITE, N W Pennsylvania Power & Light Co PLE 214. 80/07/30. Pp.
  - 9030638 Forwards request to restore CA Energy Commission & CA Dept & Conservation to syc list for NRC waste confidence ulsmaking.

    "RANIMITE California, State of 80/08/12 1p.
  - O9030549 Motion to request 30-day extension of time for filing cross-statements of position, due to NRC failure to serve position statements upon GA Energy Commission & CA Dept of Conservation Certificate of Svc encl.
    VARANINI, E.E., OREM, P. California, State of 80/08/12 Bpp
  - 109030647 Provides substitution for LC Lampher for receiving matls on behalf of CA Energy Commission & CA Dept of Conservation, VARANINI, E E California, State of. 80/08/27. 1p

- 8009030576 Comments on proposed rule 10CFR34 re permanent records of radiation exposure to radiographers Supports proposed amend. BROWN, W F Reliance Testing Laboratories, Inc. 43FR39656 006 80/07/25 ip
- BOO904011B Comments on proposed rule 10CFR34 re pocket dosimeter readings & amending regulation to provide that records need be retained for only 2 yrs Supports amend. HOY.C E Intermountain Testing Co. 80/07/28 1p.
- 8009050123 Addl response to FOIA request for records pertaining to proposed fire protection rule.
  FELTON, J M Division of Rules and Records 80/09/05, 1p
- --8009050126 Forwards Sandia Labs 790919 & 0904 memos re fire protection in nuclear plants & SECY-79-478 updating status of NRC actions in response to UCB petitions.

  HANAUER, S. H. TMI-2 Unresolved Safety Issues 79/11/08. Sap.
- 8009050429 Cross-statement specifying that industry failed to establish factual basis for confidence that nuclear waste will be safely disposed of by any given date. Tethnical gaps, deficiencies & uncertainties have prevented resolution.

  ARRAMS, R., CORMIN, J. W., SIALIK, E. I. New York, State of 80/09/02 700s
- 8009050494 Response in opposition to CA Energy Commission & CA Dept of Conservation request for extension to file cross-statements of position & suggestions he haw areas. Urges application of extension to all parties if granted W/Certificate of Svc AXELRAD.M Edison Electric Institute. AXELRAD.M. Lowenstein.Newman,Reis.Axelrad & Toll, 80/09/03 7pp.
- BOO9080036 Forwards notice of "Emergency Planning," 10CFR50 & 10CFR70, final rule & "Emergency Planning, Negative Declaration; Finding of no Bignificant Impact for Effective Rule Changes, "10CFR50, final negative declaration CHILK, B J Office of the Bacretary of the Commission. 80/09/12 16.
- --B009080053 "Emergency Planning: Negative Declaration: Finding of No Bignificant Impact for Effective Rule Changes, " 10CFR50 finel negative declaration: finding no need to prepare EIS. Rule would not significantly impact human environ. HINDGUE.R.B. Office of Standards Development, Director, 80/08/64
- 8009090517 Comments on proposed rules 10CFR 50 & 51 re storage & disposel of nuclear waste. Arguments by participants in proceeding for licensing moretorium are misplaced.

  # Atomic Industrial Forum, 80/09/05. 12pp.
- > 8009090639 Ack receipt of 800528 ltr re NRC rulemeting on emergency planning for nuclear facilities & forwards final rules on swargency planning AMEARNE, J. F. Commission. 80/08/14 ip.
  - --B009090651 Comments on proposed rules 10CFR50 & 70 re emergancy planning detailed evaluation planning unnecessary. Fifteen-minute warning requirement should be rejected in fewor of PBAR criteria.

    COX.F T. Texas. State of. 80/05/28 7pp.
- 8009090826 Comments on proposed rule 10GFR60'rs technical criteria for regulating geologic disposal of high level radwastes. Fails to recognize distinction between important siting raquirements & conditions.

  AXELRAD.M Lowerstein, Newman, Reis, Axelrad & Toll. 45FR31393 028.
  80/07/31. 3ipp.
- 8009100444 Gross-statement re proposed rulemaking on radmasts storage & disposal Urges treatment of site of each new nuclear masts generating unit as site for indefinite storage of maste. MUCHNICKI,E D., BROWN,M.J. Chio, State of. 80/09/08. Zpp.
- 8009100446 Cross-statement re proposed rulemaking on redwaste storge & disposal Urges conservative decision w/option of permanent disposal site prior to generation. Away from reactor storage should be avoided.

  MACARTOR, J D Delaware, State of. 80/09/05, 5pp

- BOOT100370 Gross-statement of DDE re proposed rulemaking on storage & a disposal of nuclear waste Disposal site decision should be made on hasis of economics & logistics of operation within framework of applicable regulations. H/Certificate of Svc. COLEMAN.L. R., DISTEFANO, J., BROWN, O.F. Energy, Dept of, DOE/NE-007-81. 80/09/03. 250pp Available at NTIS \$17.00
- BOO9110012 Gross-statement re proposed rulemaking on radwaste storage & disposel. Onvt plan for establishing geologic repositories is effective for developing safe disposal sys MCMEDIESE, R. M. ZUMBRUN, R. A. HHITE, E. B. American Nuclear Bociety, BO/09/05. 23pp
- 8009110026 Cross-statement of position by CA Dept of Conservation Affirms 800707 position Concurs w/several participant positions that comprehensive site studies must be conducted prior to locating geologic repository OREW.F.C. California. State of 80/09/05 44pp
- 8009110796 Order dismissing as most CA Energy Commission & CA Dept of Conservation 800828 motion for 30-day extension to file cross-statements Movents filed timely position on due date. NILLER, M. E. Atomic Safety and Licensing Board Panel. 80/09/09 ip.
- 8009120358 Cross-statement of Environ Coalition on Nuclear Power re proceedings on proposed rulemaking on radwaste disposal & spent fuel storage Radwaste is production problem Production should cease due to lack of space disposal JOHERRUD, J H Environmental Coalition on Nuclear Power. 44PR61372 017. 80/09/10 Spp.
- --BO09120374 Request for unserved documents listed in Environ Coalition on Nuclear Power cross-statement is proposed rulemaking on radwaste disposal & spent fuel storage.

  JOHNSRUD. J. H. Environmental Coalition on Nuclear Power 80/09/10.
- 8009150182 Forwards Nawport News Shipbuilding & Dry Dock Co comments on proposed rule 10CFR19 re permitting NRC & licenses to invite third party to participate in NRC insps Proposed rules are vague & responsibility for employee participation unclear TRIBLE.P. House of Rep., Merchant Marins & Fisheries 45FR19564 057. 80/07/22. 1p.
- 8009150185 Comments on proposed rule 10CFR60 by including so much datail. NRC is inviting endless lawsuits by organizations that will stop at nothing to delay waste isolation as long as gossible.

  KRALMSKOPF, K. B. Btanford Univ 45FR31393 101. 80/06/30 lp.
- BOO9160046 Joint cross-statement re proposed rulemaking on radwaste storage & disposal Industry approach re performance criteria of seologic waste depositories is unworkable & violates dafense-in-depth concept. Legal stds misstated.

  WEISS, E. R. Natural Resources Defense Council. MEISS, E. R., COCHMAN, T. New England Coalition on Nuclear Pollution. 80/09/10. 9048.
- 8009160161 Cross-statement re proposed rulemaking on radwaste storage & disposal Buitable sites are unrenamble natural resources. Fotal number of geological repositories w/expenses & availability must be determined through investigation. LEWIS, M. I. Affiliation Unknown. 80/09/11. Spp.
- BOOPI60281 Cross-statement re proposed rulemaking on radwaste storage & fisposeal Supports & adopts encl comments of DO Bridenbaugh of MM Technical Associates. Radwaste cannot be safely stored onsite after expiration of licenses MURRAY M. J. FARNER, T. C., VAN VRANKEN, J. Illinois, State of, 89/09/03 16pp.
- --B0091602B4 Review & comments on 800707 statement prepared for Util Nuclear Maste Mgt Group & EEI re "Capability for Bafe Interim Storage of Spent Fuel." BRIDENBAUGH D. HMB Tachnical Associates. 80/08/28 20pp.
- 80091&0443 Transcript of 800904 discussion of SECY-80-399 rw proposed interim amends to 100FR80 re hydrogen control & certain degraded core considerations in Washington DC Pp 1-86. Viewgraphs encl. s Commission. 80/09/04. 95pp.
- 8009180522 Cross-statement re rulemaking proceeding on radwaste storage & disposal Discusses cost of maintaining monitoring station. Certificate of Byc encl. COCHETET.W.A. Affiliation Unknown. 80/09/05 Spp.

- 8009190103 Comments on proposed rule iGCFR60 re regulating geologic disposal of high level redwastes Considerations adequately identify relevant issues involved in disposal of high level waste. Exposure limits are inappropriate HEUBNER, A T Connecticut, State of, 45FR31393 027 80/07/14 ip
- 8009190529 Response in opposition to Environ Coalition on Nuclear Power B00910 motion to suspend further proceedings Certificate of Bvc encl COLEMAN, L. R., DISTEFAND, J., BROWN, D. F. Energy, Dept. of 80/09/15 Onn
- BOOP190614 Add1 response to FGIA request for nine categories of documents re AEC amend to 10CFR50 57(c) proposed on 701028 & adopted on 710514 Forwards documents listed in app FELTON, J H Division of Rules and Records BO
- --8009190634 Forwards 100FR50, "Authorization of Low Power Operation "
  Requests publication,
  MGCOOL:N B. Atomic Energy Commission 71/05/10. 1p.
- --8007190638 "Authorization of Low Power Operation," 100FR50 effective rule Proposed amends define extent of preoperational activities which could be conducted grior to issuance of OL & provide for authorization of low power testing.
  HOBBS, F. T. Atomic Energy Commission 71/03/03 Bpp.
- --B009190642 Discusses proposed rule 10CFRB0 re authorization of low power operation Commission should adopt rule in effective form Adoption of proposed amend re fuel loading under CP is not recommended Draft FR notice and PRICE, H. L. Atomic Energy Commission 71/04/21 11pp
- ~8009190647 Forwards draft FR notice re proposed rule iOCFR80, "Licensing of Production & Utilization Facilities" & public announcement Proposed rule provides for operation during pending OL processings. FR notice only snc1 PRICE, A L. Atomic Energy Commission. 71/04/13 4pp
- ---BO09190453 Bummary of 710115 Regulatory Info Meeting 445 List of attendees included Proposed amends to 100FR50 & 2 re effective date of initial decision authorizing issuance of OL approved MCCOOL,N B. Atomic Energy Commission, 71/01/15 2pp
- --8009190689 Informs that Commission approved amends to 10GFR50 & 2 re effective date of initial decision authorizing issuance of CL at 710115 Info Meeting 445, W/o attached FR notice. PRICE: H L Atomic Energy Commission 71/01/15 ip.
- ~~8009190668 Forwards comments on proposed rules 10CFR2 & 50 reeffective date of initial decision authorizing issuance of
  DL Bone features of proposed rules unless clarified could
  introduce further uncertainty into ileansing process,
  QLEASON.O. L. Atomic Industrial Forum. 10CFR2, 70/12/31 23pp
- --8009190676 Comments on proposed rules 100FR2 & 50 re effective date of initial decision authorizing issuance of DL.
  Preoperational radiological monitoring programs should be completed prior to core loading & low power testing.

  # Interior, Dept. of, Fish & Wildlife Bervice. 100FR2, 70/12/18
- 8009190629 FOIA request for mine categories of documents re AEC amend to 100FR30 57(c) proposed on 701028 % adopted on 710514 BROWN,H.H. Hill Christopher & Phillips 80/08/07 2pp.
- 8009190667 Comments on proposed rule 10CFR90 re environ qualification fire protection: "DOR Outdelines" should be viewed as preliminary & used by NRC as guideline.nut as rule.in evaluating equipment qualification HHITE.L.D. Rochester Gas & Electric Corp 45FR34082 053 80/08/05
- 8009190707 Comments on proposed rule 100FR34 re retaining pocket dosimeter records, Concurs w/proposal. Retention period should be reduced to 1 yr instead of 2 yrs HENDRIX.G.M. Navy, Dept. of, Navel Facilities Engineering Command 45FR39856 005 80/07/28 ig
- 800923064A Response urging that Environ Coalition on Nuclear Power motion filed as part of cross-statement be held in abeyance until B01006 Similar motions re future conduct are due on 801006 per 800327 ander Certificate of Svc encl. BAUBER.M.A. . . . obsolete code. . . 80/09/17 7pp
- 8009240012 Responds to FOIA request for nine categories of documents re AEC amend to 100FR50 57(c) proposed on 701028 & adopted on 710514 Forwards documents listed in App A responding to 1tems 1-5, Bearch is continuing for add1 records FELTON, J. H. Division of Rules and Records 80/08/21 2pp

- --8009240018 Forwards draft notice of proposed rules 10CFR2 & 10CFR50 Proposed amends authorize nuclear fuel loading in reactor core w/o attainment of critical reaction & authorize Director of Regulation to issue license PRICE,H L Atomic Energy Commission 70/10/22 12pp.
- --8009240021 Forwards FR notice to AEC proposed rules 10GFR2 & 10GFR50, "Rules of Practice" & "Licensing of Production & Utilization Facilities GLs " Requests publication., HCCGGL,N B Atomic Energy Commission 70/10/22 1p
- --8009240024 Notice of AEC proposed rules 10CFR2 & 10CFR50, "Rules of Fractice" & "Licensing of Production & Utilization Facilities OLs." respectively Atomic Energy Commission 70/10/20 Spp
- Atomic Energy Commission 10CFR2 71/01/14. Spp.
- --8009240063 Comments on proposed rules 10CFR2 & 30.on behalf of Bave New England Commission should undertake thorough & comprehensive review of entire licensing scheme contained in proposed rule.w/full public hearing

  KESSLER, Q. Affiliation Unknown. 10CFR2. 70/12/28 11pp
- --B009R40070 Comments on proposed rules 100FR2 & 50 re effective date of initial decisions authorizing issuance of OLs Change in procedures undercuts congressional review procedures for objections to issuance of GL Draft FR notice encl. BUTLER: H A Environmental Defense Fund. 100FR2, 70/12/28
- -- BOOT240086 "Effective Date of Initial Decisions Authorizing Issuance of OLs," IOCFR2 & 50 effective rule. Amend provides for immediate effectiveness of initial decisions authorizing issuance of OLs HOBBS.FT Atom Atomic Energy Commission, 71/01/15 App.
- --8009240092 Forwards HL Price 71042; memo & info for Commission consideration at info meeting. Includes draft notice of rulemaking, draft ltr to EJ Bauser & draft public announcement Atomic Energy Commission SECY-R 221 71/04/21 1p
- --8009240108 Discusses proposed rule 10CFR50 re authorization of low power operation Recommends that Commission adopt rule in effective form. Draft notice of rulewaking, itr to EU Bauser & draft public announcement encl
  PRICE, H L Atomic Energy Commission. 71/04/21. iSpp.
- --8009240113 Informs that Commission approved SECY-R 221 re proposed rule 100FR50 concerning authorization of low power operation MCCOOL, H B Atomic Energy Commission 71/04/29
- 8009240562 Comments on proposed rulemaking, "Qualifications of Reactor Operators" Provisions should be made for phasing in administration of NRC simulator exams in same manner as requelification exams
  DENTON.H R Office of Nuclear Reactor Regulation, Director, DOCAD TO THE CONTRACT OF THE PROPOSE TO THE PR 80/08/25
- B009240563 Forwards corrected erratum sheet to be incorporated in position statement. Correction provides further degree of conservation in supporting containment & isolation objectives proposed by DEE BROWN, D.F. Energy, Dept. of B0/09/19. 2pg.
- 8009300303 NUREQ-0685 JOYAGO2GO NUMER-COMD
  TENVION Assessment for Effective Changes to 10CFR90 & App E
  to 10CFR80,Emergency Planning Requirements for Nuclear Power Plants " 017,W R Sit & Environ Stds. Br (formerly Environ, Prot Stds. Br }, 80/08/31 58pp,

#### PRM PETITION FOR RULEHAKING

- 8009050337 Advises that 800603 request for exemption of industrial radiographers from certain code requirements is under consideration as patition for rulemaking 71-8 No ltrs of comment have been received in response to enci FR notice.

  HENRY-J J Transportation & Product Standards Branch. 80/08/13
- 8009120492 Forwards quarterly rept on petitions for rulemaking as of 800630 for transmittal to PDR FELTON: J M Division of Rules and Records, 80/08/18 24pp

- 8009160204 Comments on petition for rulemaking 71-8 re requirement that user have all documents referred to in certificate. Acceptance would relieve industry from chore which has no benefit toward improved safety. re improved sarety. Technical Operatums, Inc. 45FR39519 002. 80/08/11 2<sub>88</sub>
- 8009160206 Comments on petition for rulemaking 71-8 from Foster Wheeler Energy Corp Supports proposed exemption of persons under 100FR34 from provisions of 100FR71 12(b), (i) & (j), THOMAS.E. Air Transport Association 45FR39817 003 80/08/11.
- 8009160209 Comments on petition for rulemaking 71-8 re requiring documentation referred to in license certificate or other approval in order to deliver licensed matl, Certificate of compliance is adequate documentation to have on file.

  BROWN WF Reliance Testing Laboratories, Inc. 45FR39319 001 80/07/30 ip
- 8009190661 Comments on petition for rulemaking 2-10 rs increased publi involvement in licensing process request should be denied HAFFMAN, D.P. Consumers Power Co. 45FR26071 013 80/08/05 2pp

#### PROJECTS - PREDOCKET LICENSING PROJ

- 8009130140 Notification of contract execution Mod 5 to "Economic Consulting Byes in Connection W/Stanislaus Nuclear Unit "Contractor. P Outmann OLAGOLA, A F Technical Assistance Contracts Branch FIN B-6521. NRC-03-79-113
- ~-B009180143 Mod 5, extending period of performance & increasing ceiling amount, to "Economic Consulting Sycs in Connection M/ Btanislaus Nuclear Unit." GUTMANN.P. Outman, Peter OLAGOLA, A.F. Technical Assistance Contracts Branch FIN 8-6521. NRC-03-79-113 80/06/30 1p.

#### PT9 10CFR, PART 9 -

- 7903230216 Confirms actions undertaken on 790131 re use of licensed byproduct math by individuals not authorized as users. Corrective actions will half use of math secure licensed matt on hand & resums use only by approval KEFFLER, J. O Region 3, Chicago, Office of the Director. 79/02/01
- 7704120080 Discusses IE insp of License 12-18044-01 on 770131-0202 & forwards notice of violation.
  KEPPLER, J O Region 3, Chicago, Office of the Director. 77/04/03.
- --7904120082 Notice of violation from insp on 790131-0202 Noncompliant noted, procured seven bulk shipments of Xe-133 marked "Not for Human Use:" no licensed supervision of licensed matl & no program to measure radioactive matl in air # NRC Regional Offices. 79/04/05 Spp
- 7904170409 Schedules 790323 meeting to discuss noncompliance itams noted in imag of Licenses 48-17464-01MD & 12-18044-01MD. KEPPLER, J Q Region 3, Chicago, Office of the Director 79/03/3 79/03/19.
- 7904170412 Behedules 790323 meeting to discuss noncompliance items noted in insp of License 48-17466-01MD.
  KEPPLER, J. & Region 3. Chicago, Office of the Director, 79/03/19.
- 7906010084 Ack receipt of 790306 ltr informing NRC of steps taken to correct violations noted in IE insp of License 08-18308-01MD on 790208 MCCLINTOCK,R O. Region 1, Philadelphia, Office of the Director. 79/03/23 ip
- --7906010086 Responds to NRC 790223 ltr re violation noted in IE insp License 08-18308-01MD on 780208 Corrective actions:no further transfers of Xe-133 to individuals lacking necessary license info & chart willcensing info posted, IRWIN.R F. Pharmatopes, Inc 79/03/06 2pp
- -7904010088 Discusses IE insp 30-14924-01 of License 08-18308-01 on 790208 & forwards notice of violation MCGLINTOCK.R O. Region i. Philadelphia. Office of the Director-79/02/23 2pp

- --7906010091 Notice of violation from insp on 790208 Noncompliance noted shipped Xe-133 to hosp w/o verifying that hosp license authorized Xe-133.

  \* Region 1. Philadelphia. Office of the Director 79/09/09 to
  - Region 1. Philadelphia. Office of the Director 79/02/23. 1p
- 79062790524 Ack receipt of 790425 ltr informing NRC of steps taken to correct violations noted in IE insp of License 12-18044-01 en 790405 en , 70900 KEPPLER, J & Region 3, Chicago, Office of the Director 79/05/18
- ---7906290556 Responds to NRC 790405 ltr re violations noted in IE insp of Licanse 12-18044-01 on 790405 Corrective actions will not buy Xe-133 w/o label "for human use." bioassay procedure changed & hired addl personne! ZIMMER,A M Nuclear Pharmacy, Inc. 79/04/25 7pp
- 7910020407 Grants extension to 791022 for submission of response to 790817 notice of violation served on Nuclear Pharmacy Inc. STELLO.V Office of Inspection & Enforcement, Office of the Director 79/09/07 2pp.
- 77:1090069 Discusses IE inep of License 12-17910-01MD on 790926 & 1010 & farwards natice of violation. DAVIE.A B. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 12-17910-01MD 79/10/25 ip.
- --7911090077 Notice of violation from insp on 790926 & 1010 Noncompliance noted: failure to make surveys re radiation exposure to personnel extremities: failure to made monthly thyroid readings of person using I-101 & failure to make lab survey a Region 3. Chicago: Office of the Director 12-17910-01MB. 79/10/25 ip
- 7912040149 Ack receipt of 791105 ltr informing NRG of steps taken to correct violation noted in IE insp of License 12-17190-01MD en 791025.

  DAVIG.A.B. Region 3. Chicago, Fuel Facility & Materials Safety Branch. 79/11/21.
- --7912040136 Responds to NRC 791025 itr re violations noted in IE insp of License 12-17190-01MD on 791025. Corrective actions. evaluations on personnel ring badge readings for 781225-791024 & 0625-0725 sent to R.B Landauer, JR & Co for records COMER.F. M Pharmaco Nuclear, Inc. 79/11/05 4pp
- 7412180310 Discusses IE insp of License 37-18461-01 MD on 790828-29. No noncompliance noted. Major areas inspected review of circumstances surrounding receipt of package containing HCCLINTOCK, R O. Region 1. Philadelphia. Office of the Director 79/10/05 ip
- 79[2]900[4 Ack receipt of 7909]7 Itr informing NRC of steps taken to correct violation noted of License 37-1846]-0]MD on 7906[8 GREEN, B. H. Region I, Philadelphia, Office of the Director 79/10/03. 19
- --7912190023 Responds to NRC 790910 ltr re-violation noted in IE insp of License 37-18461-01MD on 790618. Corrective actions: restricted area workers will be instructed auditor will survey radiation heards & syringe shields will be used. DESSEL 8 Nuclear Pharmacy, Inc. 79/09/17. App.
- --7912190047 Responds to NRC 790821 ltr re violation noted in IE insp of License 37-18461-01MD on 790618. Corrective actions, sent copy of guidelines for radwaste packaging & pick up to customers & institued training program for trainsporters.

  DESSEL. 8 Nuclear Pharmacy, Inc. 00618 79/09/10, 34pp
- --7912190054 Ack receipt of 790807 ltr informing NRC of steps taken correct violation noted in IE insp of License 37-18461-01MD on 790618 Requests add1 info re mpt control sys. to be received within 7 days of ltr.
  BHITH.O H Region 4. Dallas. Office of the Director. 79/09/10 taken to
- --7912190067 Responds to NRC 790723 itr re violations noted in IE insp of License 37-18461-01MD on 790618. Corrective actions: surveys of radioactive matis discharged in effluent air from fume hood will be done routinely DESSEL.S. Nuclear Pharmacy, Inc. 79/08/07 3pp
- --79[2]90073 Forwards notice of violation from IE insp of License 37-18461-03MD on 790618. QRIER.B.H. Region i. Philadelphia. Office of the Director. 79/07/23 2pp

- -7912190080 Notice of violation from insp on 790618 \* Region 1, Philadelphia, Office of the Director 79/06/23 3pp
- 8001020069 Ack receipt of 791120 ltr informing NRC of steps taken to correct violations noted in IE inep of License 08-18308-0IMD on 790913 MCCLINTOCK,R & Region 1: Philadelphia, Office of the Director 79/12/10
- --8001020073 Responds to NRC 791114 1tr re violations noted in IE insp of License 08-18308-01MD on 790913 Corrective actions dose calibrator will be adjusted or repaired when activity measurements during linearity tests differ by more than 5% IRMIN.R F Pharmatopse. Inc 79/11/20 ip
- ---8001020078 Ack receipt of 791017 ltr informing NRC of steps taken to correct violations noted in IE insp of License 08-18308-0IMD on 790913 Requests add1 info re dose calibrator adjustment & wips tests MCCLINTCCK,R C Region 1, Philadelphia, Office of the Director
- --8001020083 Responds to NRC 790922 ltr re violations noted in IE insp of License 08-18308-01MD on 790913 Corrective actions suringe shields will be used at all times & linearity tests will be repeated upon indication of more than 10%.

  IRWIN.R F Pharmatopes, inc 79/10/17 3pp
- --8001020105 Discusses IE insp of License 08-18308-01MD on 790713 & forwards notice of violation HCCLINTOCK,R C. Region 1. Philadelphia. Office of the Director 79/09/27. 2pp
- ---8001020108 Notice of violation from insp on 790913. Noncompliance noted, failure to use lead syringe shields, failure to record constancy checks on 790820-21 & failure to perform wipe test on incoming packages
  \* Region i, Philadelphia, Office of the Director 79/09/27 2pp
- 8001290275 Ack receipt of 800107 ltr informing NRC of steps taken to correct violations notes in IE insp of License 24-16617-01MD. DAVID-A B. Region S. Chicago, Fuel Facility & Materials Safaty Branch. 80/01/18 is
- --8001290281 Responds to NRC 800102 ltr re violations noted in IE insp of License 24-16617-01MD Corrective actions have requested NRC to emend to license from three months to yearly calibr for radiation monitors. Pharmaco Nuclear, Inc. 80/01/07 ip
- BOO2180275 Confirms meeting to be held between NRC & Nuclear Pharmacy.
  Inc on BOO122 in King of Prussia,PA to discuss results of
  NRC 770802-03 insp & noted noncompliance.
  ORIES,B,H Region 1. Philadelphia, Office of the Director
  SO/01/09 1p.
- 8002150283 Discusses error in 800109 ltr Purpose of meeting is to discuss results of 800103 insp Meeting date is 800122 at Region 1 ofc SMITH.0 H Region 1, Philadelphia. Fuel Facility & Materials Bafety Branch. 80/01/15 ip
- 8002190229 Clarifies Nuclear Pharmacy. Inc comments made during 800121 meeting re NRC notice of violation. Forwards summary of facts available to NRC prior to issuance of notice Urges dismissal or remission of civil penalties.

  VAKERIGS: T V D'Connor & Hannan 80/02/05 7pp
- 8003050215 Ack receipt of 791221 ltr informing NRC of steps tal correct violations noted in IE insp of License 37-18461-01MD on 79109 Itam A corrective & preventive actions will be discussed at 300122 NRC masting. GRIER.8 H Region I, Philadelphia, Office of the Director 80/01/21 ip.
- -B003050219 Responds to NRC 791211 itr re violations noted in IE insp of License 37-18461-01MD on 791109 Corrective actions steps have been taken to lower employee radiation exposure Syringe shield will be used whenever possible.

  DEBBEL.8 Nuclear Phermacy, Inc. 79/12/21. 4pp
- Region 1, Philadelphia, Office of the Director ORIER, B. H Red 79/12/11, 2pp.

- --8003050226 Notice of violation from insp on 791109 Noncompliance noted emplayee eversposure, failure to report overesposures; failure to conduct required surveys + Region 1, Philadelphia, Office of the Director 79/12/11 3pp
- --8003050232 Submits revised quarterly figures re extremity exposures Company has instituted adequate measures to ensure significantly lower exposure levels DESSEL.8 Nuclear Pharmacy, Inc. 79/11/12 2pp
- 8003190517 Ack receipt of 800128 itr informing NRC of steps taken to correct violations noted in IE insp of License 45-18378-01 MD on 791206 STOHR J.P Region 2. Atlanta. Fuel Facility & Materials Safety Branch 80/02/06 1p
- ~-8003190525 Responds to NRC 800118 ltr re violations noted in IE insp of License 45-18378-01MD on 791206. Corrective actions linearity test of both dose calibrators will be performed first Monday of calendar quarter PDTTER:M F Pharmatopes. Inc 80/01/28 1p
- --8003170527 Discusses IE insp of License 45-18378-01MD on 791206 & forwards notice of violation STOHR.J.P Region 2. Atlants, Fuel Facility & Materials Safety Branch 80/01/18 2pp.
- ---B003190537 Notice of violation from insp on 791216 Noncompliance noted. linearity tests not conducted on fose calibrators between Apr & Nov 1979. Records of radiation surveys performed on bags of syringer at disposal not recorded \* Region 2. Atlanta. Office of the Director B0/01/18 ip
- 8003240038 Forwards on behalf of Nuclear Pharmacy, Inc. cashiar check re-civil penalty imposed per 800219 notice of violation to Elfreth Allay Apothecary in Philadelphia.PA Will not challenge penalty Situation will be corrected per encl MCDONALD.N E. Sutin. Theyer & Browne 80/03/10 5pp
- 9003250232 Forwards reconstructed 1978 film badge summary rept Results of summary repts from AB Landauer Co & Bearle Diagnostic will be forwarded within next month Advises of move to new licensed facility

  #UBER.S A Nuclear Pharmacy, Inc. 80/02/19 3pg
  - )5070552 Ack receipt of 800220 ltr re plans & progress in upgrading radiation protection program per IE Insp Rept 30-15125/79-01.
    SMITH. 6 H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 80/02/28 ip
- ---8005090553 Informs of change in 790807 proposed corrective actions re [E Insp Rept 30-15125/79-01. Instead of installing portal monitor in threshold area between ofts & lab.plans to install permanent contamination survey station BTEPHENS.C M. Nuclear Pharmacy. Inc. CMS-280-8 80/02/20 2pp.
- 9005200654 Ack receipt of full civil pensity payment imposed in NRC 800219 ltr & receipt of licenses 800310 ltr re corrective actions Info on agt controls & audit program expected by actions into on age controls & audit program expected by 800512
  STELLO, V. Office of Inspection & Enforcement, Office of the Director, 80/04/07 ip
  - 05300691 Forwards IE Insp Rept 30-14386/80-02 on 800403 of activities under License 12-18044-01 No noncompliance noted NAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safety Iranch 80/04/21. 2pp
  - 1005300695 IE Insp Rept 30-14396/80-02 on 800403 No noncompliance noted Hajor areas inspected: Secontaminated radiopharmaceutical facility.

    ADAM.M. J. PAPERIELLO, C. J. Region 3. Chicago, Office of the Director. 80/04/15. 3pp
  - 005300697 Submits rapt re results of closeout radiation survey. HUBER.S A Nuclear Pharmacy, Inc., 80/03/07. 7pp.
  - 412088: Forwards IE Insp Rept 30-1362280-01 on 800416 of activities inder License 12-17910-01 MD No noncompliance noted NAVIB:A B. Region G. Chicago, Fuel Facility & Materials Safety Branch 80/03/07, 2pg
- \*8006120884 IE Insp Rept 30-13622/80-01 on 800416. No nuncompliance noted Hajor areas inspected matle, facilities & equipment, receipt & transfer of matl, surveys & redicactive effluents & waste disposal.

  DBERGO,C. T. Region 3, Chicago, Office of the Director PAPERIELLD,C. J. Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/05/06, 12pp.

- PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE
- 8009120699 Revised Part 21 rept re defective pipe hangers Revised list of hangers shipped to Job site encl BECKBYED. H F Bergen-Patterson Pipe Support Corp 75000-32-0669 80/08/14.
- 8009180255 Part 21 rept re pump failure in containment gas monitoring sys. Caused by deadheading pump w/inclusion of check valve & bypass line for pressure Rept should be considered part of original 800403 rept MERCER: N Comsip.Inc , Delphi Systems Div 80/08/22 1p.

#### QA999 QUALITY ABSURANCE INSPECTIONS

- 8009050280 Informs NRC that deficiency re welding of attachments to safety-related piping occurred in North Anna Units 1 & 2 only Corrective action has been completed. No safety hazard exists Further review of item is not warranted.

  JACOBS.8 B Stone & Webster, Inc. 10CFR 050 55E 80/08/27 2pp
- 8009080465 Forwards QA Program Insp Rept 99900061/80-01 on 800605-06. No noncompliance noted PDTAPOVS, U. Region 4: Dallas, Vendor Inspection Branch 60/07/09.
- --8009080467 GA Program Insp Rept 99900061/80-01 on 800605-06.No NYVOUNDE OF TROOTER INSPIRED TYPYOUND INDICATE OF SUBJECT OF THE STATE OF THE STATE
- 0009100208 Ack receipt of 800723 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99700347/80~01 Region 4. Dalles, Vendor Inspection Branch. 80/08/22.
- ---8009100219 Responds to NRC 800626 ltr re deviation noted in GA Program Insp Rept 99900347/80-01 Corrective actions GA menual revised & will be released approx 800815 RRMHULM B. Gulf & Western Industries, Inc. 80/07/23.
- --8009100223 Forwards GA Program Insp Rept 99900347/80-01 on 800602-04 k notice of deviation POTAFOVS, U Region 4. Dellas, Vendor Inspection Branch. 80/06/24.
- --8009100227 Notice of deviation from insp on 800602-04 \* Region 4, Dallas, Office of the Director. 80/06 80/06/20 2pp.
- --B009100231 GA Program Insp Rept 99900347/B0-01 on B00602-04.
  Noncompliance noted calibr activities not performed in accordance W/procedures required by GA Manual.
  MHITESELL, DE L., BUTTGN.D.E. Region 4, Dallas, Vendor Inspection Branch. B0/06/20. App
- 8009110613 Forwards GA Program Insp Rept 99900357/80-01 on 800602. No noncompliance noted, POTAPOVS,U Region 4, Dallas, Vendor Inspection Branch, 80/06/30
- --B009i10618 GA Program Insp Rept 99900357/80-01 on B00602. No noncompliance noted Major areas inspected implementation of code requirements including applicable codes & side & review of vendor activities HHITESELL, D. E., KELLEY, H. D. Region 4, Dallas, Vendor Inspection Branch B0/06/27 Bpp
- 8009120334 Forwards GA Program Insp Rept 99900522/80-02 on 800616-20. No noncompliance noted POTAPOVS.U. Region 4. Dallas. Vendor Inspection Branch 80/07/09.
- ---8009120335 QA Program Insp Rept 99900522/80-02 on 800616-20 No noncompliance noted Major areas inspected: seismic analysis of as-built safety-related piping sys.iaplementation of 100FR50 in areas of design change document control. BRICKLEY.R.H. AGEE.J.R. HALE, C.J. Region 4, Dallas, Office of the Director 80/07/02, 10pp.
- 8007120654 Ferwards GA Program Insp Rept 97900328/80-01 on 800619-19 No noncompliance noted POTAPOVB,U. Region 4. Dallas: Vendor Inspection Branch. 80/07/10

- --9009120637 GA Program Insp Rept 97900328/80-01 on 800618-i9 No noncompliance noted Major areas inspected activities re IE Bulletin 79-14. HALE.C.J. BRICKLEY.R H., YIN.I T Region 4. Dallas, Vendor Inspection Branch IE8-79-14 80/07/02 8pp
- 8009:50017 Forwards GA Program Insp Rept 99900064/80-01 on 800624-27. No mancastitance noted
  POTAPOVS, U Region 4. Delles. Vendor Inspection Branch 80/07/11
- --B009130021 GA Program Insp Rept 99900064/B0-01 on 800624-27 No noncompliance noted. Major areas inspected, implementation of 100FR50. App B. including control of nonconformances, actions & audits MHITEBELL, D E . BROWN, R L Region 4. Delias, Vendor Inspection Branch. B0/07/09 App
- 8009150171 Forwards GA Program Insp Rept 99900726/80-01 on 800624-27. No noncompliance noted POTAPOVS.U Region 4. Dallas, Vendor Inspection Branch 80/07/15.
- --B009150173 GA Program Insp Rept 99900726/80-01 on 800624-27 No noncompliance noted Major areas inspected GA program vendor activities, welding control re purchase, issuance & storage & possible welder certification deficiency OLLER.R.E., POTAPOVB.U Region 4, Dailas, Vendor Inspection Branch. 80/07/10. 12pp.
- 8009150195 Ack receipt of 800808 & 0520 itre informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900109/80-01. POTAPOVS.U. Region 4: Dallas: Vendor Inspection Branch BO/OB/R2.
- --8009150199 Responds to NRC 800602 ltr re deviation noted in GA Program Insp Rept 99700109/80-01. Corrective action: corrent temporary attachments procedures revised to include all aspects of utilization & emphasize mat
- ---BO09150200 Ack receipt of 800520 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900109/B0-01 Requests addl info.
  P0TAPGVB.U Region 4. Dallas. Vendor Inspection Branch 80/06/CR.
- -9009130204 Responds to NRC 800417 ltr re deviation noted in GA Program Insp Rept 99900109/80-01 Corrective actions welder surveillance repts reviewed & equipment corrected to produce electrical requirements established in welding procedures.

  MUELLER: A J Pittsburgh-Des Moines Steel Co 80/05/20 7pp
- --8009150207 Forwards GA Program Insp Rept 99900109/80-01 on 800324-28 A notice of deviation.

  POTAPOVB.U. Region 4, Dallas, Vendor Inspection Branch 80/04/17.
- --B009150210 Notice of deviation from insp on 800324-28.
  \* Region 4. Dallas, Vendor Inspection Branch. 80/04/16 ip.
- --8009150217 OA Program Insp Rept 99900109/80-01 on 800324-28
  Noncompliance noted; installation & removal of temporary
  attachments not documented on fabrication check list. Welding
  procedure electrical characteristics not maintained
  WHITESELL, D. E. , BUTTON J W Region 4, Dallas, Vandor Inspection
  Branch. 80/04/16, 14pp.
- 8009180221 Ack receipt of 800520,0804 & 0626 ltrs informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99700525/80-01. POTAPDV6.U. Region 4. Dallas. Vendor Inspection Branch. 80/08/18.
- ---8009150223 Responds to NRC 800716 ltr re deviation noted in GA Program Insp Rept 99900525/80-01. Corrective actions, cover sheets, interim drawings & lists of specs imprinted w/nuclear safety-related as applicable BARKER:N R. 011bert/Commonwealth Cos. 80/08/04 2pp.
- --- 8009150224 Ack receipt of 800520 & 0626 ltrs informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900525/80-01. Requests addl info re deviation Items B. 2 & POTAPOVS, U. Region 4. Dallas, Vendor Inspection Branch. 80/07/16.

- ~~8009190226 Responds to NRC 800603 ltr re deviations noted in QA Progra Insp Rept 9990525/80-01 Corrective actions all but seven items identified in Internal Audit IA-80-1 resolved Requests extension re Deviation Items 8 2 & 8.3 BARKER.N R 0ilbert/Commonwealth Cos 80/06/26 2pp
- ---8009150227 Ack receipt of 800520 ltr informing NRC of steps taken to correct deviations noted in QA Program Insp Rept 99900525/80-01. Requests add1 info re Deviations B 2.8.3.C 1 POTAPOVS.U Region 4: Dallas, Vendor Inspection Branch 80/06/03
- --8009180228 Responds to NRC 800421 ltr re deviations noted in GA Program Insp Rept 99900525/80-01. Coreective actions procedures to be prepared to record annual mpt review & changes made in prepared to February may be a february for the february f
- -8009150229 Forwards OA Program Insp Rept 99700525/80-01 on 800324-28 & notice of deviation. POTAPOVS.U Region 4. Dellas, Vendor Inspection Branch 80/04/21
- ---8009150231 Notice of deviation from insp an 800324-28 \* Region 4. Dallas, Office of the Director 80/04.
- --8009150234 GA Program Insp Rept 99900525/80-01 on 800324-28
  Noncompliance noted no procedures for conducting annual mgt
  reviews of GA programs Certain design activities & audits
  not performed in accordance w/approved procedures.
  HALE, C.J., JOHNSON, J. H., FOX, D. F., Region 4, Dallas, Vendor
  Inspection Branch 80/04/18. 30pp
- 8009170155 Forwards GA Program Insp Rept 99900389/80-01 on 800708-09 No noncompliance noted. POTAPDVB.U Region 4, Dallas, Vendor Inspection Branch 80/07/21.
- --8009170189 QA Program Insp Rept 99900389/80-01 on 800708-09, No noncompliance noted Major areas inspected evaluation of supplier performance & followup of corrective action taken re GA Program Insp Rept 99900389/79-01.

  WHITESELL, D. E., BROWN, R. L. Region 4, Dailes, Vendor Inspection Branch. 80/07/17 App
- 8009170156 Forwards GA Program Insp Rept 99900014/80-01 en 800630-0703 No nencompliance notes. PDTAPGVS,U Region 4. Dallas, Vendor Inspection Branch 800/07/21.
- --B00917015B GA Program Insp Rept 99900014/B0-01 on B00630-0703 No noncompliance noted Major areas inspected equipment calibr, nondestructive examination & audits.
  BARKEG. I. ROBERDS. M. W. Region 4. Dallas. Vendor Inspection Branch. B0/07/18. Sep.
- 8009180056 Ack receipt of 800821 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 79790321/30-01 Region 4, Dallas, Vendor Inspection Branch. 80/08/28. POTAPOVS, U
- --8009180064 Responds to NRC 800729 ltr re deviation noted in GA Progra Inst Rept 99900321/80-01 Corrective actions: serial number log to be used to control serial number identification on all tools. BROWN, M E., PEET, W. J. Ametek, Inc. 80/08/21. 3pp.
- --8009180070 Forwards GA Program Insp Rept 99900321/80-01 on 800707-10 & notice of deviation.
  PDTAPOVS,U Region 4: Dailas: Vendor Inspection Branch 80/07/29
- --8009180077 Notice of deviation from insp on 800707-10. \* Region 4. Dallas, Office of the Director 80/07.
- --8009180085 GA Program Insp Rept 99900321/80-01 on 800707-10
  Noncompliance noted insp tool one month overdue for
  calibr & serial number log not maintained
  HUNTER: V H., WHITEBELL: D E. Region 4, Dallas, Vendor Inspection
  Branch. 80/07/25 Spp.
- 8007180072 Ack receipt of 800805 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 97900081/80-01. POTAPOVS, U Region 4. Dallas, Vendor Inspection Branch

- --BDG9180104 Forwards GA Program Insp Rept 999000B1/80-01 on 800610-12 & notice of deviation. PDTAPDVB, U. Region 4: Delles, Vendor Inspection Branch 80/04/25 200.
- -8009180109 Notice of deviation from insp on 800610-12 \* Region 4. Dallas, Vendor Inspection Branch. 80/06/23 ip.
- -8009180119 GA Program Insp Rept 99900081/80-01 on 800610-12.

  Noncompliance noted, matl not traceable to starting matl per Guality Procedure 8 Matl not labeled w/cleaning date re GC 8td KN-868146

  MCNEILL, W M , WHITESELL, D.E. Region 4, Dallas, Vendor Inspection Branch 80/06/23, 6pp.
- 009180169 Ack receipt of 800806 itr informing NRC of steps taken to correct deviation noted in 8A Program Insp Repts 99900400/79-04 & 99900400/80-01 POTAPOVE, U Region 4, Dallas, Vendor Inspection Branch. 80/09/02 in
- -8009180177 Responds to NRC lit re deviations noted in GA Insp Repts 99900400/79-04 & 99900400/80-01 Corrective actions.NPCD calculation procedure revised to define common knowledge design inputs GUILBERT, D.E. Bebook & Wilcox Co. 80/08/06. 2pp
- -BOOY:BOIGS Responds to NRC ltr re deviations noted in QA Insp Repts 79700400/79-04 & 79900400/80-01 Corrective actions. swaluation of calculation pactages shows common knowledge theory to be technically sound QUILBERT, D. E. Bebcock & Wilcox Co. 80/06/24, 10pp.
- 009:80484 Ack receipt of 8006:3 & 08:3 ltrs informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99:00245/80-01. POTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 80/08/26
- -8009180490 Responds to NRC 800509 itr re deviation noted in GA Program Imap Rept 97900245/80-01 Corrective actions revised Section 3 Class I valve drawings to have flange backfacing machined using 3/14-inch radius tool bits.

  LITTLEFIELD, J J.E.Lonergan Co 80/08/13, 1p
- 8009180495 Responds to NRC 800509 ltr re deviation noted in GA Program Imap Rept 97900245/80-01 Disputes NRC findings of deviation re backfacing machining details Drawlings under review.

  General note requirements to be incorpopated.

  LITTLEFIELD. J J E Lonergan Co 80/06/13 2pp.
- 8009180500 Forwards GA Program Insp Rept 99700245/80-01 on 800421-22 & notice of deviation POTAPOVE, U. Region 4. Dallas, Vendor Inspection Branch 80/05/09.
- 9009180302 Natice of deviation from insp on 800421-22 # Region 4, Dallas, Office of the Director 80/05/08 ip
- 800918050B GA Program Insp Rept 99900245/80-01 on 800421-22
  Noncompliance noted:removal of radius of Bonnet 0022010172
  by backfacing operation contrary to code requirements &
  drawing dimensions.
  KELLYU D , WHITESELL.D.E Region 4. Dallas, Vendor Inspection
  Branch. 80/05/08. 9pp.
- 09180527 Forwards QA Program Insp Rept 9990059/80-01 on 800404-05 No noncompliance noted \*\*\* Orange Office Office
- 1009180536 GA Program Insp Rept 9990059/80-01 on 800604-05 No noncompliance noted Major areas inspected corrective action to severic considerations repotential const deficiency involving Turkey Point Unit 4, including assessment of cause BUTTON. J W. WHITEBELL.D E. Region 4, Dallas, Vendor Inspection Branch 80/07/01 6pp.
- 9:30562 Forwards GA Program Insp Rept 99700344/80-01 on 800609-12 to moncompliance noted OTAPOVG.U Region 4. palles. Vendor Inspection Branch 80/07/03 en

- --8009180366 GA Program Insp Rept 99900344/80-01 on 800609-12.No noncompliance noted. Major areas inspected audit control, records, welding, nondestructive testing & design document control HUNTER.V H , WHITEBELL.D E. Region 4, Dailas, Vandor Inspection Branch 80/07/01 3pp.
- BO09190014 Ack receipt of 800703 & 0804 ltrs informing NRC of Steps taken to correct deviation noted in GA Program Insp Rept 99900259/80-01.
  PDTAPDVB.U Region 4. Dellas, Vendor Inspection Branch 80/08/20 ip
- --8009190017 Responds to NRC 800716 ltr re deviation noted in QA Program
  Insp Rept 99900259/80-01 Corrective actions base metal
  repair & Incomel cladding completed by temper bead welding
  technique
  HHITE.C.E. ALMEDA.D.C. C-E Power Systems 80/08/04 2pp
- --B009190020 Ack receipt of 800703 ltr informing MRC of steps taken to correct deviation noted in GA Program Insp Rept 99900259/80-01 Add1 info requested POTAPOVS.U Region 4. Dellas, Vendor Inspection Branch, 80/07/16 lb.
- ---B009190024 Responds to NRC B00606 ltr re deviation noted in QA Program
  Insp Rept 99900259/B0-01. Corrective actions documentation
  for production welding stressed in training program &
  voltage meter on power source replaced.
  WHITE: C E , ALMEDA, D. C C-E Power Bystems. B0/07/03. 3pp.
- --B009170027 Forwards GA Program Insp Rept 99900259/80-01 on 800519-23 thatics of deviation PUTAPOVS.U. Region 4. Dellas. Vendor Inspection Branch. 80/04/06.
- ---8009190029 Natice of deviation from insp on 800519-23.
  \* Region 4. Dallas, Office of the Director 80/06/05. 3pp.
- --8009190031 QA Program Insp Rept 99900289/80-01 on 800519-23.

  Noncompliance noted; use of nunspecified detail welding procedure & performance of production welding using amperage & voltage values above allowed ranges.

  POTAPDV8.U., ELLERSHAW, L. E., BARNEG, I. Region 4, Dallas, Vendor Inspection Branch 80/06/05, 10pp.
- 8009250307 Ack receipt of 800730 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900346/80-01 POTAPOVS: U Region 4, Dallas, Vendor Inspection Branch 80/08/21.
- ---B009250313 Responds to NRC B00830 ltr re deviation noted in GA Prograd Insp Rept 99900346/80-01. Corrective actions: PGRs changed to reflect correct F number applicable at time of qualification, FRANCOIS.E. I., HUCK, M. J. Velan Valve Co. 80/07/30. 3pp.
- --8009250325 Forwards GA Program Insp Rept 99700346/80-01 on 800603-05 to notice of deviation POTAPOVS, U. Region 4. Dallas, Vendor Inspection Branch. 80/06/30.
- --8009250326 Notice of deviation from insp on 800603-05. # Region 4, Dallas, Vendor Inspection Branch. 80/06/27. 1p.
- ---B009250327 GA Program Insp Rept 99900346/80-01 on B00403-05 Noncompliance noted, test coupen not welded within MP8 specified amperage range. WHITEEELL.D E , KELLEY.H.D. Region 4. Dallas. Vendor Inspection Branch. B0/06/27 13pp
- 8009290310 Ack receipt of 800724 & 0821 ltrs informing NRC of steps taken to correct deviations noted in QA Program Insp Rept 99700049/80-01 PDTAPOVS, U. Region 4, Dallas, Vendor Inspection Branch. 80/09/03.
- ---8009270312 Responds to NRC 800625 ltr re deviations noted in GA Program Insp Rept 97900049780-01. Corrective actions; corrected procedures for visual insps & calculations include backseat loading on cover TONEATTI, V.W. Atwood & Morrill Co., Inc. (subs. of Foster Wheeler Corp.). 80/08/21 8pp
- --8009290314 "Performing Visual Insp of Matls & Items " LYONS:M D Atwood & Morrill Co., Inc. (subs. of Foster Wheeler Corp.), GC-210-4. 80/05/12. 2pp.

- --B009290315 Forwards JH Cowley ltr inadvertently omitted from response to GA Program Insp Rept 99900049/80-11 re Class 2 Mye Stop Chect Valve w/hydraulic operator TOMEATTI,V.H. Atwood & Morrill Co., Inc. (subs. of Foster Wheeler Corp.) B0/07/31 2pp
- ---B009290316 "Design Stress Rept for 16-inch -- 1500# Class 2 Wye Stop Check Valve w/Hydraulic Operator " a Atwood & Morrill Co , Inc (subs of Foster Wheeler Corp ). 79/01/09. 3pp
- ----9009290318 Responds to NRC 800625 ltr re deviation noted in GA Program Insp Rept 9990049/80-01 Corrective actions surface defects caused by arc strikes are being eliminated & area around temporary attachments marked so that area can be identified TOMEATTI, V. W. Atwood & Morrill Co , Inc (subs of Foster Wheeler Corp.) 80/07/24 2pp.
- --B009290320 Forwards GA Program Insp Rept 99900049/80-01 on 800505-06 & notice of deviation.
  POTAPDVB.U. Region 4. Dallas, Vendor Inspection Branch B0/06/25 app.
- --B009290322 Notice of deviation from insp on 800505-06.
  \* Region 4. Dallas, Office of the Director 80/06/19. 2pp
- --8009290323 GA Program Insp Rept 99900049/80-01 on 800805-06.

  Nancempliance noted:design & stress rept did not include celculations force imposed by operator in closed position & procedures did not provide for removal of surface defects.

  WHITESELL, D. E., KELLEY, H. D. Region 4, Dallas. Office of the Director 80/06/19. 14pp

#### REQULATORY QUIDES

- 7909040729 Gomments on proposed Reg Ouide 1 XXX:considers static calibration for manual scanning is more repeatable, scanning at increased (2X or 6dB) sensitivity level enhances resolution Guestions determination of near/far degradation. MOGRE,R.L. Affiliation Unknown. 79/07/19 2p.
- 9009020529 Forwards notice of issuance & availability of draft Reg Ouide S. (OH 710-4), "Health Physics Survey in U Mills," for publication in FR. CHIEK, S. J. Office of the Secretary of the Commission, 80/08/15, in
- --B009020331 Notice of issuance & availability of draft Reg Guide 8 (QH 710-4). "Mealth Physics Survey in U Hills " OOLLER, K R. Division of Siting, Health & Bafeguards Standards B0/08/11 2pp
- 8009030051 Forwards notice of issuance & availability of Reg Ouide 8.25. "Calibr & Error Limits of Air Bampling Instruments for Total Vol of Air Bampled." for publication in FR GMTLK.8 J Office of the Becretary of the Commission 80/08/15.
- --80090300&7 Notice of issuance & availability of Reg Quide 8 25, "Calibr & Error Limits of Air Sampling Instruments for Total Vol of Air Sampled " HINOUE, R. B. Office of Standards Development, Director, 80/08/12
- 8009070147 Comments by Instituto de Investigaciones Electricas on Reg Quids 1.57. "Design Limits & Loading Combinations for Metal Primary Reactor Containments Sys Components." Regulatory position portion seems incomplete LINARES.F. Affiliation Unknown FCL/01/80 80/07/03 ip.
- BO091006R8 Advises of inability to endorse Reg Quide 1.97.Revision R in present form Suggests that scope of guide be reduced or contents clarified. PLESET.H S AGRS Advisory Committee on Reactor Safeguards Bo/08/13. 3pp.
- 8009100672 Forwards corrected pages & supplemental info submitted as enc1 to 800410 ltr re proposed reg guide, "Lightning Protection for Nuclear Power Plants."

  JOHNSON, I. 8 Affiliation Unknown. 80/04/18 16pp
- 8009120533 Comments on proposed Revision 1 to Reg Guide 8 12, "Criticality Accident Alarm Bys " Exampting new fuel storage areas from criticality monitoring will improve revision since these areas fit into size constraints.

  BULLIVAN.T. J Consumers Power Co. 9552. 80/07/25 ip.

- 8009120540 Comments on proposed Revision 1 to Reg Ouide 8 12, "Criticality Accident Alarm Bys." Page 2.second line "handled, used or stored" does not explicitly include transports even though transportation is addressed BDSWELL, J N C I du Pont de Nemoure & Co , Inc 80/07/23 1p
- 8009150167 Comments on proposed Revision 4 to Reg Quide 8 8 "Info Relevant to Ensuring That Occupational Radiation Exposures Hill be ALARA " Rule ludicrous as NRC is requesting more stringent requirements for industry th
- 8009150174 Comments on proposed Revision 1 to Reg Guide 10 6; if requirements for details are eliminated reg guide would be more useful aid to obtain license & would not require amends whenever supplier relocates &/or model number is changed CADENA, D. O. Southwest Research Institute 80/08/08 ip
- 8009150229 Comments on proposed Reg Quide OH 902-4, "Instruction re Risk From Occupational Exposure " Hell done summary of radiation risk on fairly sophisticated level. Matl unlikely to be understood by some radiation workers

  DVERBERGER.C Q Hichigan, Univ of. 80/07/29 2gp
- 8009150230 Comments on proposed Reg Guide DH 902-4, "Instruction re Risk From Occupational Rediation Exposure " Guide conclusion that spreading out dose may reduce risk is contrary to "Low Dose & Leukenta Rept "
  TUMA.A T Popular Bluff Hosp Popular Bluff.MG 80/07/24 2pp
- 8009150243 Comments on proposed Rag Quide DH 902~4. "Instructions re Risk From Occupational Radiation Exposure." Info must be presented in manner which can be understood & easily comprehended by worker.

  HICKS.H M Utility Horkers Union of America 80/07/25, App
- B009150309 Comments on proposed Reg Guide OH 902-4, "Instruction re Rist From Occupational Radiation Exposure " Analogy between smoking & radiation exposure is inappropriate because smoking risk is much greater than radiation risk. CURTIS.N W Pennsylvania Power & Light Co ER 100450 80/08/12
- 8009150320 Comments on proposed Reg Guide OH 902-4, "Instruction Re Risk From Occupational Redistion Exposure." Bias renders instruction meaningless & may invite cerelessness LEWIG.M.I. Affiliation Unknown 80/07/23. 19
- 8009160366 Addresses requirements of Reg Guide 1,92 pertaining to closely spaced modes & Lists supporting refs.Vendor will recommend SAR amend for plants under NRC review GANG-N.9 General Electric Co MrN-137-BD, 8D/09/08
- 8007190279 Responds to FOIA request for 15 documents listed in bibliography of NUREO-0625, "Rept of Siting Policy Task Force." Documents 6-8 & 13 are available in PDR Forwards remaining documents. FELTON.J M. Division of Rules and Records 80/09/04, 1p
- ---8009170587 BECY--79-362
  Informs Commission of proposed changes to meteorological model used in assessing potential accident consequences for nuclear plants. For determination of site acceptability & adequacy of engineered safety features MINGOUE, R B Dffice of Standards Development, Director 79/06/04
- ---8009190612 Draft Reg Quide 88 724-4, "Atmospheric Dispersion Models for Potential Accident Consequence Assessments at Nuclear Power Plants "

  \*\* Office of Standards Development, Director 79/06/04 29pp.
- ---8009190624 Draft value/impact assessment of proposed Reg Guide SS 724-4, "Atmospheric Dispersion Models for Potential Accident Gonsequence Assessments at Nuclear Power Plants." Reg guide should be developed Documentation and Physics of Standards Development. Director 79/06/04. 34pp
- B009190703 Comments on proposed Reg Quide OH 902-4 re occupational radiation exposure because employers have conflict of interestricourses of instruction should be established which would be administered by agencies other than employer COLLINS.F. Oil.Chemical & Atomic Horkers Intl. 80/09/14 3pp
- 8009190717 Comments on proposed Reg Guide OH 902-4 suggests some specific rewording.
  LOYARS.A Colorado State Univ 80/08/14 ip
- 8009190726 Requests proposed Reg Ouide DH 941-4. "Info re Ensuring That Occupational Radiation Exposures at U Mills Will be ALARA" OHLBSON, K Affiliation Unknown 80/08/19. ip.

- 1009170702 Communts on proposed Reg Quide OH 710-4 favors publication wind major changes.
  BURTBAVAGE, E M Affiliation Unknown 80/08/19 ip.
- EB RESEARCH AND TECHNICAL ASSISTANCE REPORTS
- 009030010 E09030010
  "Issa Input for LDFT RELAPS Calculations"
  KEE.E J. BHALLY, P. J., WINTERS, L. E0&0 Idaho, Inc. FIN A-6048,
  EE0-LDFT-5199, E0/07/31 23pp
- 009050200 Bubmits bi-monthly status ltr re LNR pressure vessel desimatry program for Apr & May 1980. Document clearance request, publications release & charts of ABTM stds for surveillance of nuclear reactor pressure vessels encl PREBTON: C C. Ifanford Engineering Development Laboratory 80092754 800/07/18 9pp.
- 09000399 "LDFT Lead Rod Test Results Evaluation," internal technical rept
  DRIBMELL.W E , TOLMAN, E.L. EG&G Idaho, Inc. USNRC-P394 80/07/30
  73pp.
- 109030405 "PRF-LOCA Test Series. Test LOC-6. Thermal Fuel Behavior Propram. Experiment Predictions."
  LUFEBRE. N T. WATERMAN. M. E. YACKLE. T. R. EQ&Q Idaho, Inc. FIN A-6041. EQQ-TFUP-3193 90/07/31. ip
- 09050407 "Multired Burst Test Program Preliminary Results of 8-5 (0)8) Bundle Test," quick look rept CMPMAN.R.H., CROMLEY.J.L., HAYNES.R.F., Oak Ridge National Laboratory. FIN 8-0120. DRNL/MR8T-5. 80/07/14. 48pp.
- 09090132 "Physical Protection of Nuclear Facilities," monthly progress rept for Jul 1980. HAPKAN, L. D. Bandie Leboratories, FIN A-1060 80/08/19, 7pp
- )9090770 "Bafeguards for Proliferation Resistant Fuels," progress

  'apt for Jul 1980.
  APMELL, J. J. Brookhaven National Laboratory FIN A-3221. 80/08/20

  Opp
- 19100412 "Power-Cooling-Mismatch Test Series Test PCM-7," quick look ept ept PARKE, D. T. . LEFEBRE, N. T . MCCARDELL, R. K. EG&G Idaho, Inc. FIN 1-6041. EGO-TFSP-5218. GO/08/31. SSpp.
- 9100808 "Advanced Instrumentation for Reflood Studies Program," ereign trip rept. ADB.B.C.: ZABRIBKIE,W.L. Dak Ridge National Laboratory. FIN -0410. DANL/FTR-888. 80/08/11. 9pp.
- 9100820 "LDCA Test Harias, Test LOC-6. Thermal Fuels Behavior regram," axperiment operating spec.
  AKKE, T. R. , WATERMAN, M. E. EORG Ideho, Inc. FIN A-6041
  W-TFRP-5171, 80/07/31, 62pp.
- 7100530 "Cladding Creep (CCSTRN & CCSTRS) Fuel Behavior Hodel (velopment, " interim rept. | ORMAN D L. EGG Idaho, Inc. FIN A-6050 EEG-CDAP-5216 (707/31. 4709.
- '110416 "Bafeguards for Proliferation Resistant Fuel Cycles,"
  formal monthly progress rept for June 1980
  DMELLI J Brookhaven National Laboratory FIN A-3221 80/08/11
- 110421 "Acoustic Emission/Flaw Relationships for Inservice iltering of Nuclear Fressure Vessels," informal monthly igness rapt for Jul 1780 Insert Memorial Institute, Pacific TOW, F. I., KURTZ: R. J. Battelle Memorial Institute, Pacific Tow, F. I., KURTZ: R. J. Battelle Memorial Emistitute, Pacific Telescope State Constant FIN B-2088. 80/08/20 Spp.
- 10483 "Decontamination as Precursor to Decommissioning," Informal thly progress rept for Jul 1980.

  10483 "Decontamination as Precursor to Decommissioning," Informal this progress rept for Jul 1980.

  10483 "Decontamination as Precursor to Decommissioning," Informal this progress rept July Part B-2303 80/08/14, Rep 97887 FIR B-2303 80/08/14, Rep
- 10490 "Bafeguards Analysis for Byproduct Matte & Small Guantities NM," monthly progress rept for Jul 1980.

  TER.R.O. MANDOLPH.M. L. RYAN, MT. Oak Ridge National STER.R.O. MANDOLPH.M. L. RYAN, MT. Oak Ridge National STER.R.O. MANDOLPH.M. L. RYAN, MT. Oak Ridge National STER.R.O. MANDOLPH.M. CRNL/MASRD-90. 80/08/18 App.

- BOO9110574 "Advanced Instrumentation for Reflood Studies," foreign trip rept LLOYD, D. B. DINKINS, M.A. Dek Ridge National Laboratory FIN 8-0413. ORNL/FTR-892. 80/08/08 5pp
- BO09110634 "Safeguards Analysis for Byproduct Matls & Small Quantities of Skh." topical rept summary of docket file survey RANDOLPH.M.L. Dak Ridge National Laboratory FIN B-610B, ORNL/HASRD-89 80/08/05, 25pp
- 8009110876 "Evaluation of Docket Files of Terminated Licenses," monthly progress rept for Jul 1980 HOLOMAY,C.F. DICKENSON,H W. Dak Ridge National Laboratory. FOM A-7085-7 ORNL/HASRD-88 80/07/31 21pp
- SOC9:10885 "Program for Standardized Analysis of Fuel Shipping Containers." quarterly rept for Apr-June 1980 HHITEBIDES, Ø.E., WESTFALL, R.M. Oak Ridge National Laboratory FIN B-0172 GRML/CSD/INF/80 80/07/29. 19pp
- 8009120567 "Div of Reactor Safety Research-ORNL Programs," monthly rapt for Jul 1980 HYNATT, F. R. Oak Ridge National Laboratory, 80/08/10 30pg.
- BOD9120571 "Definition of Parameters for Major Accidents at Haste Bolidification & Spent Fuel Storage Facilities," sonthly progress rept for Jul 1980 FEDERICK, E. J. Dak Ridge National Laboratory FIN 8-0425. 80/08/15 3pp
- 8009120572 "Investigation of Ventilation Component Response to Large Pressure Pulses," monthly progress rept for June 1980 QRECREY. M. S. Los Alemos Scientific Laboratory. FIN A-7028 WX-8-3775 80/08/08 2pp.
- 8009120581 "Steam Water Instrumentation Development Program & Modeling." Foreign trip rept. THOMAS.D. & Dak Ridge National Laboratory FIN 8-0427. ORNL/FTR-897 80/08/13 9pp.
- 8009120590 "Integrated Geophysical & Geological Study of Tectonic Framework of 38th Parallel Lineament in Vicinity of Intersection W/Extension of New Madrid Pault Ione," annual progress rept fy80.

  BRAILE, L. W. Purdue Univ, KELLER, C. R. Texas, Unvi. of, El Paso. LIDIAK, E. C. Pittsburgh, Univ. of, FIN 8-5971. NRC-04-74-323 80/08/31. 142pp.
- 8009120866 "Loft Monthly Progress Rept." for June 1780. KAUFRANIN C. E080 Idaho, Inc. LD-HR-007. 80/07/31. 10759.
- 8009120733 "Forecasting Electricity Damand by State & by Util Svc Area." monthly progress rept for June 1980. CHERN.W.S. Dak Ridge National Laboratory FDM 8-0190-8. ORNL/ED/EAB-80. 80/07/15. 5pp.
- 8009:503:: "Advanced Instrumentation for Reflood Studies (AIRS)." monthly highlights rept for June 1980. HYNATT.F.R Dak Ridge National Laboratory, 80/07/10. 30pp.
- 8009150849 Forwards agenda for 801027-31 eighth water reactor safety research info meeting at NBB in Gaithersburg MD. BUDNITZ:R J Dffice of Nuclear Regulatory Research, Director 80/07/28. 2069.
- 8009160492 "Invastigation of Accident-Induced Flow & Matl Transport in Nuclear Facilities." monthly progress rept for Jul 1980 MARTIN:R A.: GREGORY.W S. Los Alamos Scientific Laboratory. FIN A-7029. WX-8-3786. 80/08/14. 3pp.
- 8009140498 "Matl Control & Accounting Effectiveness Evaluation Davelopment," monthly progress rept for May 1980. POGGIO, A Lawrence Livermore Laboratory FIN A-0115. 80-80-08-02. 80/08/07. 11pp
- 8009190401 "Evaluation of Alternative Packages for Solidified & Unsolidified (Dewatered) Low Level Ion-Exchange Remins & Filter Sludge Measters," informal rept MANAKTALA.H.K., NICOLOSI,S.L. Brookhaven National Laboratory FIN A-3158, BNL-NUREO-28199 80/08/31 163pp.
- 8009190768 "Containment Analysis Development," informal rept.
  DDYLER J., MINOS.W.J., RAMSTHALER, JA EOGO Idaho, Inc. FIN
  A~6042 EOG-CDAP-5166, 80/05/31 157pp
- 8009240283 "Environ Assessments of Fuel Cycle Facilities," monthly progress rept for Jul. 1980.
  INTEL.H E. Dak Ridge National Laboratory. FIN 8-0279
  ORNL/ED/EIS-134 80/07/31 689

8009240291 "Application of Internal Priction Nondestructive Evaluation Tachnique for Datecting Incipient Cracking of Bypass Lines & Pipas in BMR Piping Bys." progress rapt for 800623-0815, Repts 7 & 8 Dandalean Associates, Inc NRC-04-78-242 80/08/15 7pp

8009240069 "Comparison of Computed Density Profiles from Transient Flow Callbr Facility, Using Three or Six Beam Measurements " MEACHUM, T. R. HAMBACH, J. L., HANSON, D. J. EQ&Q Idaho, Inc USNRC-P394 80/08/14 3ipp

8009260075 "LOFT LTBF Thermocouple Thermal Analysis to Datermine Transient Temp Response " HOMELL, B. K. EQ&Q Idaho, Inc. RE-A-80-055 80/06/23 17pp.

9009260099 "LOCA Test Series TC-3, Experiment Operating Spec "
YACKLEITR , WATERMAN H E. E0k9 Idaho, Inc FIN A-6041 E00-TFSP-5221 80/08/31, 54pp

BOO9260542 "Analysis of Semiscale Mod-1 LOCE 8-04-6 Using TRAC-Pia Computer Program," proliminary assessment rept DEMMIE, P. N EG&O Idaho, Inc FIN A-6047 EEG-CAAP-5181, 80/06/30,

8009260350 "Assessment of Radiation Doses Resulting from Releases of Rn-222 & Ra-226 from U Mining & Milling Activities "Monthly progress rept Mar 1980 TRAVIS, C.C., MCDOMELL-BOYER, WATSON, A.P., Dak Ridge National Labratory. FIN 8-0281 ORNL/HASRD-76 80/04/22. Spp.

8009260538 "Measured Effects of Fuel Rod Internal Cas Pressure & Xenon Concentration in Operating Fuel Rods & Comparison W/Basic Theory & FRAP Calculations," preliminary rept MILLER, R. H. A PPELMANS, A D EGGO Idaho, Inc. FIN A-6041, EGG-TFRP-5222 80/08/31 93pp.

#### REVIEW ORP NRG RESEARCH REVIEW GROUPS

BO09180362 Notifies of 800903 seminar in Bethesde.MD re matls aging. FEIT.R Division of Reactor Safety Research. 80/09/03 2pp.

#### PER PHARTNO

BOO9100490 Comments on RM 50-5.public should be advised of advantages & disseventages of implementing Pu recycle, NRC should not have terminated efforts on GEBMO fuels.

DECHER, U. Affiliation Unknown. BO/09/03. 1p

8009160224 Requests 9E8MO re fuel be completed info is needed for fuelra decisions re reprocessing of spent nuclear fuel, VILLEMY, G. R. Affiliation Unknown. 45FR53933 003. 80/09/08, ip

BOO9160420 Comments on rulemaking 50-5 GEBMD proceedings should be respend to provide early procedural framework for subsequent licensing.
RICHARDS, R. B. General Electric Co 48FR53933 004, 80/09/08. 2pp.

8009170366 Comments on rulemaking 50-5 re mixed oxide fuel DESMO & other recycle-related licensing proceedings should continue Positive affirmative action to approve licenses recommended. KIRK-H.F. Hilliam F Kirk. 80/08/28 4pp.

8009220231 Comments on rulemaking 50-5 GESMO proceedings should not be respended Apposes any action which would be contrary to non-proliferation policy, MCLAUGHLIN.M.T. Affiliation Unknown. 80/09/12. 1p.

8009220233 Comments on rulemaking 50-5:068MO proceedings should be reopened. Recycling of nuclear fuel is greater proliferation risk. Proceedings can clear way for sensible nuclear policy LAMBREMONT. E. N. Affiliation Unknown 80/09/16. ip.

9009220237 Comments on rulemaking 50-5: GESMO proceedings should be resumed & completed Reprocessing & recycle of LMR fuel should be considered.

TEXMLFANIDIB.N. Affiliation Unknown 80/09/15. ip.

8009220240 Comments on rulemaking 50-5.0ESMO proceedings should be resumed immediately due to INFCE results & domestic public asinians. BARRY, D. Affiliation Unknown. 80/09/14 1p.

8009220245 Comments on rulemaking 50-5 supports resumption of QEBMO proceedings. NRC should evaluate nuclear fuel recycling on technical/environ basis.

QEISEMBRIJP. Affiliation Unknown 80/09/16 1p

SECY POSITION PAPERS BEFORE THE COMMISSION

8009030252 SECY-80-342 Notifies of proposed contract renewal to SRI Intl for continued research in lider technology No conflict of interest would result from award. Findings & determination

DONDOHUE.D.J Office of Administration 80/07/23 6pp.

--8009030255 Findings & determination statement proposing research by SRI Intl on "Analysis of Atmospheric Diffusion Through Application of Lidar Technology "
HORTON, K. V Research Contracts Branch HALMAN, E.L. Division of Contracts 80/06/19 3pp

9009040459 BECY-80-349 Submits semiannual rept of SD program cost & schedule Last of Core i 3D ECCS reflood & refill tests in JAERI Cylindrical Core Yest Facility completed in May 1980. Facility shut down until Jan 1981. Supporting matl encl BUDNITZ.R. J Office of Nuclear Regulatory Research, Director 80/07/25 Spp.

9009040461 BECY-80-253

Informs of Ofc of Nuclear Regulatory Research comments on ACRB rept to Congress - NUREO-0657, "Review & Evaluation of NRC Barety Research Propries for FV91." Annual ACRB review is extremely valuable Specific comments enci.

BUDNITZ.R J Office of Nuclear Regulatory Research, Director. 80/05/19 50p

8009050123 Add1 response to FOIA request for records pertaining to proposed fire protection rule FELTON, J M Division of Rules and Records. BO/08/05 ip.

---B009050126 Forwards Sandia Labs 790919 & 0904 memos re fire prote in nuclear plants & SECY-79-478 updating status of NRC actions in response to UCS patitions HANAUER, S. H TMI-2 Unresolved Safety Issues 79/11/08 Spp.

--8009050131 SECY-79-478

Informs Commission of present status of NRC actions in response to UCS petition for emergency & remedial action & petition for reconsideration Seven items have been completed. DENTON, H R. D 79/08/08, 4pp Office of Nuclear Reactor Regulation, Director.

8009230141 BECY-75-338

DVX:0141 BECY-75-33H
Recommends that Commission approve correspondence w/
concerned parties to obtain clarification of comments on
750308 FR notice re provisional view on Pu recycle
CHAPMAN K R Office of Nuclear Material Safety & Bafeguards
75/07/03 5pp.

--B009230145 Responds to SECY-75-338 re comments received during Puracycle proceedings. Recommendation should be accepted w/caution. Request for clarification will delay comment procedures. STRAUSS,P.L. Office of the General Counsel, 75/07/09, 2pp

--8009230274 BECY-75-638
Forwards draft FR notice me scape & procedures for generic
Pu recycle environ statement & interim licensing actions.
BHAPAR,H K Office of the Executive Legal Director. 75/11/10

8009090083 BECY-80-273 Waskly info rapt for wk ending 800613 REHM.T A Office of the Executive Director for Operations. 80/06/18 40pp

9009090799 BECY-79-430

DIPODYNY BECY-79-430
Informs of Dfc of Nuclear Regulatory Research comments on ACRB rept to Congress - NUREO-0476, "1978 Review & Evaluation of NRC Safety Research Program " ACRB comments & recommendations useful Specific comments encl LEVINE.8. Office of Nuclear Regulatory Research, Director. 3370-79/07/06. 26pp

8007150410 Forwards responses to 800927 questions re info provided by NRC on 800901 concerning differences in role of NRC & Executive Branch in processing expart requests. Supporting documentation encl
AHEARNE, J. F. Commission 80/08/22 13pp

- 8009180269 Transcript of 800904 public meeting in Hashington. DC re discussion & vote on enforcement policy Pp 1-91 • Commission 80/09/04 93pp
- --8009180277 SECY-80-139A

  Recommends adoption of proposed policy of enforcement action as interinguidance Draft FR notice encl

  STELLO, Unities of Inspection & Enforcement. Office of the Director 80/08/27 50pp
- --8009180284 Summary of Commission 800319 meeting in Washington.DC re SECY-80-139 dealing w/NRC enforcement program Revised policy discussed but no final conclusions reached CHILK.S J Office of the Secretary of the Commission 80/03/28 in
- --8009180291 Comments on SECY-80-139 re enforcement policy NRC divs must submit alternatives to Executive Director of Operations AHEARNE.J F Commission 80/03/24. 4pp
- --8009180298 Comments on proposed enforcement policy Policy paper is good first step but of little use if licensee commitments & NRC stds are not in enforceable form BRADFORD.PA Commission 80/04/09. 18pp
- 8009190299 Responds to FOIA request for 13 documents listed in bibliography of NUREG-0625. "Rept of Siting Policy Task Force." Documents 6-8 & 13 are available in PDR Forwards resaining documents FELTON.J M Division of Rules and Records 80/09/04 ip
- --8009190320 SECY-75-518
  Responds to Commission direction to develop alternative plans for revision of code re power reactor siting regulations. Forwards diagram of scheduling network makeup of study panel % study & task scope of work MINDOUE.R B Office of Standards Development, Director. 75/09/12.
- 8009190358 Forwards SECV-75-286 concerning reactor siting policy Issue is large & complicated NRC will prepare oral briefing to outline principal areas of concern & potential solutions. 00SSICKL V Office of the Executive Director for Operations 76/05/25 ip
- --8009190366 SECY-76-286
  Forwards "Staff Review of Site Evaluation Policy & Practice" Recommends that Commission hold further discussions w/Directors of NRC ofcs to develop basis for decisions concerning future site evaluation policy.
  MINDOUE.R B Office of Standards Development, Director 76/05/25.
- ---8009190370 "Staff Review of Site Evaluation Policy & Practice." \* Commission 78/05/25 55pp
- --8009190377 Provides recommendations from review of siting policies for licensing nuclear facilities Recommends that criteria be developed for other portions of fuel cycle, Related documentation ancl KERR.W AGRS Advisory Committee on Reactor Safeguards 75/12/10 35p
- -8009190383 Informs that Commission has reviewed SECY-75-818 re reactor siting Program described re development of policy paper is not fully consistent w/intent of Commission directive Lists Commission requests re program ANDERS,N A Office of the Executive Director for Operations 78/10/30 3pp.
- 30091903B6 Discusses review of 760301 memo re reactor site evaluation & practice Paper needs significant improvement in defining further actions & providing basis for Commission decision on those actions

  HUBERMAN.B. Office of Policy Evaluations 76/03/19 1p
- ~8009190390 Discusses review of reactor site evaluation policy & practice Review is well written & makes persuasive statement for thorough revision of existing site evaluation policy. Proposed actions re-siting policy issues end:
  STRAUSS.P.L. Office of the General Counsel 76/04/01 13pp.
- --B009190394 SECY-76-286A
  Requests Commission approval of development plan for nuclear facility siting policy & practice revision Recommends that Commission approve proposed plan & direct staff to proceed w/programs Related documentation encl
  MINOGUE, R. B. Office of Standards Development, Director 76/12/14.
  2400

- --B009190397 Forwards comments on development plan for nuclear facility siting policy & practice Requests that comments be reviewed, modified, commented on & summarized REHM.T A Office of the Executive Director for Operations, 76/11/23 1p.
- --8009190400 Discusses development plan for nuclear facility siting policy & practice revision. Principal concern is whether NEPA considerations will receive adequate attention STRAUSS.P.L. Office of the General Counsel 76/11/23 2pp
- --8009190464 Comments on 761103 draft of "Development Plan for Nuclear Facility Siting Policy & Practice Revision " Draft is not adequate response to Commission 760830 guidance Ofc of 8tds Development response enc! HUBERHAN.B Office of Policy Evaluations 76/11/11 13pp
- ---B009190470 Provides Commission comments on BECY-76-286 re reactor site evaluation policy study Rept provides valuable partial background for site evaluation policy formulation, Lists benefits of cohesive.seplicit siting policy.

  CHILK.S. J Office of the Secretary of the Commission 76/08/31 3pp
- ---BOO7190480 Responds to 760831 request for comments on Commission review of BECY-76-286, "Staff Review of Reactor Site Evaluation Policy & Practice," Ofc of Stds Development will produce program plan, re reformulation of siting policy MINGOUE, R B. Office of Standards Development, Director, 76/09/24, 2pp
- ---9009190484 Recommends public release of BECY-76-286 & BECY-76-286A on siting policy & practice Requests review & concurrence in placement of documents in PDR.

  MINUGUE, R B Office of Standards Development, Director. 77/03/02, 200.
- --B009190498 Responds to 770302 request to review SECY-76-286 & SECY-76-286A & concurs w/recommendation to place documents in PDR Release of documents should be coordinated w/Ofc of of General Counsel BHAPAR.H K Office of the Executive Legal Director 77/03/18.
- ---8009190514 BECY-77-288
  Forwards proposed general policy statement on nuclear reactor site evaluations Recommends that Commission provide guidence on proposed policy statement & directive redevelopment of replacement regulation.

  MINOGUE, R.B. Office of Btandards Development, Director. 77/06/07 9700
- --8009170520 BECY-77-288
  Comments on general policy statement re nuclear reactor site evaluations Paper is inadequate & does not set forth range of options open to Commission. Possible legal problems exist w/general policy statement approach, as proposed KELLY.J. L. Diffice of the General Coursel. 77/06/02 3pp.
- --B007190526 Forwards comments on 770527 draft of "General Policy Statement on Nuclear Reactor Site Evaluation Policy." General approach is inadequate for Commission decision regeneral reactor site evaluation policy TERRELL.N Office of Policy Evaluations. 77/06/02 11pp.
- --8009190532 BECY-77-433

  Bubmits policy statement on alternative site evaluations under NEPA for nuclear generating stations. Recommends that Commission require review & approval of applicant site selection process prior to acceptance of CP application. MINOGUE. R. B. Office of Standards Davelopment, Director. 77/08/16
- --8009190539 Comments on draft of "Policy Statement on Alternative Site Evaluation Under NEPA for Nuclear Stations " Paper is suitable for Commission review Value of paper could be enhanced by encl comments.

  PEDERSEN, K Office of Policy Evaluations 77/07/18 App
- ~-8009190546 Comments on proposed policy statement on evaluation of alternate sites. Policy statement does not clearly identify how Commission will act to enforce stds. Related documentation encl KELLEY.J.L. Office of the General Counsel 77/07/25 Bpp.
- --8009190550 BECY-78-371
  Reviews BECY-77-288, "General Policy Statement on Nuclear Power Reactor Site Evaluations "Recommends approval of general statement of current policy on nuclear power site evaluations for publication in FR & draft ltr.
  MINGOUERS Office of Standards Dayslopment, Director 78/07/03, 300p.

- ---G009190557 Lists Commission requests for further action to be taken on 8ECY-77-288 concerning siting policy & practice Four siting policy issue papers should be forwarded to Commission as proposed in schedula CHILK.8 J. Office of the Secretary of the Commission 77/06/30 200
- --- P609190568 Comments on general policy statement on current nuclear reactor sits evaluation Lists items which should be considered before statement is adopted & published Ofc of Btds Development responses encl
  BHAPAR, M. K. Office of the Executive Legal Director 78/05/08
  Bbs

- 8009240569 BECY-80-393
  Forwards Executive Branch response on pending Transnuclear,
  Inc application for license to export highly enriched U to
  Jagan.
  BHEA, J. R. Office of International Programs, Director. 80/08/22
- BD09238276 Transcript of 800904 Affirmation Bession 80-39 to discuss fees for withdrawl of applications for CPs & OLs in Washington. DC. Pp 1-2. Draft proposed rules encl. Cameission 80/09/04 20pp
- --BO07250280 BECY-80-364
  Recommends recovery of licensing review fees for applications denied, withdrawn, suspended or postponed Draft FR notice encl.
  DOMOGRAE, D. J. Office of Administration, 80/08/04 11pp
- BOOP270021 Transcript of BOOP16 public meeting in Washington, DC rediscussion & vote on Commission program to review DL applications, AM session, Pp 1-62
  AMEARME, J. A. Commission. BO/09/16, 65pp.
- -- 9007270032 SECY-B0-414
  Requests approval of conceptual draft plan re systematic safety evaluation of all currently operating nuclear power reactors. Widnaft 90-day status rept. considerations re identification of regulations & draft public announcement DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 80/09/07
- 8009290405 SEGY-80-408
  Informs Commission of Executive Branch response on pending export application XBNM-1666 for Kartini Research Reactor. Copies of original application & itrs of assurance encl SHEA, J. R. Office of International Programs, Director 80/09/04. 20as.

### STATE PROQ STATE PROGRAMS

- 8009020316 Submits review of draft NUREO-0696 re proposed nuclear data link. Recommends that specific provisions re determining potential for breaching barriers to radioactivity release & monitoring site meteorological data be added BHEMLY.N O South Carolina, State of. 80/08/27. 2pp.
- 8009020500 Recommends that grants or contract program be developed to provide funding for mandates to permit states to exercise responsibilities originally bestowed on AEC. Meeting of Agraement States & NRC would be appropriate AXELROD.D. New York, State of. 80/08/ii. 1p.
- 8009030178 Expresses appreciation re Southern States Energy Board concern about future role of Ofc of State Programs Views expressed in itr will be carefully considered in any reorganization affecting Ofc of State Programs. DIRCKS.N.J. Office of the Executive Director for Operations BO/08/04. 19

- --8009030184 Expresses concern on behalf of Southern States Energy Board re transferring of Agreement States Program to any licensing div. Oft of State Programs is most responsive & responsible organization in federal establishment
  NEMETH.K J Southern States Energy Board 80/07/25 ip
- BO07050191 Confirms discussion following review of administrative & technical aspects of radiation control program No comments on areas examined.

  KERR,O N Office of State Programs, Director 80/08/12 ip
- 8009050361 Forwards draft radiological emergency preparedness plan, addressing criteria in NUREQ-0534 W/o encl DAVIDOFF.D.B New York, State of 80/09/02 2pp
- 8007080399 "Rept to President:State Radiological Emergency Planning & Preparedness in Support of Commercial Nuclear Power Plants "MAGY.J W. Federal Emergency Hanagement Agency. 80/06/30 350pp
- BOO9080459 Confirms discussions w/K Schneider re review & evaluation results for regulation of agreement matis. Submits recommendations for review completion planned for end of yr Comments on recommendations requested KERR, Q. W Office of State Programs, Director BO/OB/Ob 2pp
- ---B0090B0462 Confirms 800719 discussions w/K Schneider re review & evaluation results for radiation control program No recommendations on adequacy will be made at this time Comments on encl technical recommendations requested KERR. O W Office of State Programs, Director 80/07/30 5pp
- 8009100094 Forwards State of GA transportation surveillance program third quanterly (third yr) progress rept JANINEK.M Office of State Programs, Director. NRC-06-78-362 80/08/19 2p.
- ---8009100097 Forwards State of CA transportation surveillance program third quarterly (third ur) progress rept.

  INGRAM.W.D. Georgia, State of NRC-06-78-362. 80/08/14 49pp
- 8009150457 Ack receipt of 800811 ltr re results of NRC Jul 1980 review of radiation control program for agreement matis. Review will be completed by accompanying field inspectors during wk of 800908 Suggests meeting date for late 8ept 1980 KERR.O. W Office of State Programs. Director 80/08/26 2pp.
- 8009190863 Submits semiannual rept of activities performed through 800630 per UMTRCA grant to State of CA FESS.K.S. California. State of NRC-06-80-308. 80/08/27. 2pp
- 8009190874 Submits semiannual rept of activities in response to NRC B00612 request Reportable areas include preparation of lagislation, regulations & development of administrative procedures HAZLE, A J Colorado, State of NRC-04-80-311 80/07/28, 2pp
- ---BO09190877 Forwards semiannual financial status rept Jan-June 1980 & request for reimbursement per UHTRCA grant to State of CO SHANSON.M V , HAZLE.A. Golorado, State of NRC-06-80-311, 80/08/01 3pp
- 8009190881 Submits technical performance rept re NRC-04-80-310 per second quarter requirements. VADEN. J. Nevada, State of NRC-04-80-310. 80/04/30 ip.
- 8009190891 Submits semiannual rept of activities & forwards status rept through 800630 for UMTRCA grant to State of NM WOLFF.T. A New Mexico, State of, NRC-06-80-076. 80/08/05. 4pp.
- BO09190894 Forwards program technical performance rept.800206-0630.per UNTRGA grant to State of TX BAILEVE.D Texas. State of. NRC-06-80-307 80/08/20 5pp
- 8009230655 PNA-80-33 on 800903, Medical Research Foundation, Inc. shipped 4 vials of microspheres tagged w/Yb-90 Gustamer notified company of apparent tagging problem Eight patients treated OA will not reauthorize shipments w/o FDA varification. MERR.O.W. MCGRATH, J.R. Office of State Programs, Director 80/09/18. 1p.
- B009240260 Forwards status rept of activities & financial rept through B00630 STRONG TR Washington, State of NRC-06-80-306 B0/07/31. Spp

8009260204 Discusses NRC review & evaluation of CO radiation control program Program for regulation of agreement matls adequate to protect public health & safety Requests comments on recommendations on technical aspects of program KERR.O W Office of State Programs. Director 80/09/08 2pp

### TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE

- 8009020023 Discusses schedule for Alternate 2A ATHS plant mods proposed in Draft Vol 4 of NUREQ-0460 Proposed schedule unrealistic due to non-ATHS mods Preliminary schedule of 3 5 yrs reached w/Hiddle Bouth Bycs is more realistic SHERHOOD, 0 Q General Electric Co MFN 146-80 80/08/22 2pp
- B0090200B1 Forwards TVA-TR75-1A.Revision 4. "GA Program Description for Design. Const & Operation of TVA Nuclear Power Plants." in response to NRC 800818 ltr.
  MILLS.L M Tennessee Valley Authority. B0/08/26 1p
- --8009020103 TVA-TR75-1A R4
  "GA Program Description for Design Const & Operation of TVA
  Nuclear Power Plants," Revision 4
  \* Tennessee Valley Authority 80/08/31, 20pp.
- B009020128 Forwards second request for add1 info re MCAP-9500, "Ref Core Rept 17 x 17 Optimized Fuel Assembly " Requests submittal schedule to develop NRC review schedule. MILLER, J. R Standardization & Special Projects Branch 80/08/08 4pp
- 8009020237 Advises that SEP Owners Group has contracted w/URS/Blune to develop & implement program to seismically qualify cable trays at SEP plants. Anchorage will be addressed as part of program will require approx 18 months. SCHAFFSTALL, R. KMC, Inc. 80/08/28 2pp
- 8009020364 Supercedes 800807 ltr to NRC re organizational change notification requirements. Info provided re recent organization changes made within nuclear power generation & angineering divs TAYLORJ H Babcock & Wilcox Co. 80/08/27 3pp.
- S009030359 Forwards draft Revision 2 to "Corporate Operations Manual, Part IV - Functional Manuals, Section I - Nuclear GA Manual," RAUSCH, W.P. Burns & Roe Co. 80/08/29, 1p
- --8009030364 B&ROE-CDM4-1-NP R2
  Draft Revision 2 to "Corporate Operations Henual, Part IV -Functional Manuals Section I -- Nuclear GA Manual "
  # Burns & Roe Co 80/08/29. 73pp.
- 8009030557 Forwards Revision 2 to GE regt, NEDO-11209-04A. "Nuclear Energy Business Group BWR GA Program Description." Revisions deal w/organizational changes per OE 800806 ltr & alternate position change per Reg Guide 1 123. BREED.A. General Electric Co 80/08/26. 9pp
- 8009030663 86-1120838-00
  "Evaluation of Instrumentation to Detect Inadequate Core Cooling," prepared for 177 owners group.
  FROTH,D Babcock & Hilcox Co 80/08/15 18pp
- 8009040409 Notifies of organizational restructuring within Water Reactor Div. New Strategic Operations Div encompasses steam generator sys.matls engineering, plant margin improvement activities & man/machine interface product line.

  ANDERSOND T.M. Westinghouse Electric Corp. PAS-PTM-80-555 80/08/27 5pp.
- 8009050325 Forwards NEDD-24757, "Caorso Safety Relief Valve Bischarge Tests Phase II Test Rept: "nonproprietary version. NEDE-24757-P. submitted on 800703.
  BUCCHOLZ,R H Omeral Electric Co. MFN-145-80 80/08/25 ip.
- --8007030328 NEDD-24757
  "Caorso Safety Relief Valve Discharge Tests Phase II Tests
  Phase II Test Rept."
  # General Electric Co. 80NEDO56, 80/07/31 100mo.
- 8007050363 Forward: "Operator Training Bycs Instructor Requalification Program"

  JANECEK, D. L., DIETZ, C. R. General Electric Co. CRD 80056 80/07/31 is.
- --8009050365 "Operator Training Bycs Instructor Requalification Program " \* General Electric Co 80/07/31. App

- G009100150 Summary of G00627 meeting w/Westinghouse in Bathesda,MD re WCAP-9500, "Ref Core Rept 17:17 Optimized Fuel Assembly," MUNDY,J A. Gore Performance Branch B0/08/13 4pp.
- BOOT100233 Forwards "Responses to NRC Questions on Topical Rept BAM-80133P, Revision 1, Hark C Fuel Assembly LDCA & Seismic Analysis, May 1979. "Responses withheld (ref 10CFR2 790) TAYLOR: J H Babcock & Wilcox Co. B0/09/05
- BOO7100532 Forwards CE-1-A.Revision 14 re QA program NAVOHTON,W F Commonwealth Edison Co BO/09/05 ip
- --BOO9100548 CE-1-A R14
  GA program, Revision 14
  # Commonwealth Edison Co BO/09/09. 69pp
- 8007i10335 Responds to FDIA request that specific listed documents be placed in PDR D0 Eisenhut 760302 memo to K Goller will be placed in PDR PELTON.J. H Division of Rules and Records 80/07/04 ip.
- --8009110351 Topical rept evaluation of NEDE-21156, "Suppl Info for Plant Mod to Eliminate Significant In-Core Vibration " Mods are acceptable " Office of Nuclear Reactor Regulation, Director. 76/02/28 3509
- BO09110436 Forwards "Generic Reload Fuel Application," Amend 8 for review & approval Changes incorporated include 12 new fuel bundle surichment designs & C-lattice fuel bundles. Proprietary info withheld (ref 10CFR2, 790) ENGEL.R E General Electric Co. MFN-147-80 80/08/26 2pp.
- --8009110443 Forwards Amend 8 to, "Generic Reload Fuel Application" containing nuclear characteristics tables for 12 new fuel bundle designs. Amend 8 & affidavit withheld (ref 10CFR2 770).

  ENOEL.R E General Electric Co 80/09/22 1p.
- BOO9120205 Submits review & analysis of BAFSTOR holding periods.Cost differences between 30 & 60-yr storage periods would not justify cost of performing analysis.
  SMITH.R.I. Battelle Mamorial Institute, Pacific Northwest Laboratory BO/06/18 5pp.
- 8009120270 Confirms 800904 telcon re use of B&H TAFY code for fuel & ECCB analysis Transition will begin from TAFY to TACOZ for fuel & ECCB analysis. Current & revised LOCA limits provided. Resnablysis will be performed after NRC approval of TACOZ. TAYLOR, J. H. Babcock & Wilcox Co 80/09/05. 2pp
- 9009120360 Forwards operational QA program description. Revision 4, Draft 2. RENBERGER, D. L. ELE-908-80-268, 80/09/02. 2pp.
- --9009120363 WPP88-GA-004 R4
  GA program, Revision 4, Draft 2.
  \* Washington Public Power Supply System 80/09/02. 57pp.
- 9009120595 "Analysis Summary in Support of Early Reactor Coolant Pump Trip." \* Bebcock & Wilcox Co. 80/08/28, Sipp.
- BO09120664 Reaffirms NRC position on incorporating Lessons Learned Short-Term Requirement 2 1.3 b in TMI action plan. Instrumentation & guidelines for indication of inadequate reactor core cooling do not satisfy long-term requirement. ROSS:D.F Division of Systems Integration. 80/09/09. 2pp.
- BOO9160192 Forwards NEDE-24011-P-A, App D App D withheld (ref 10CFR2 790), ENGEL, R. E. General Electric Co MFN-156-80, 80/09/08, 1p.
- 8009160366 Addresses requirements of Reg Guide 1.92 pertaining to closely spaced modes & lists supporting refs. Vandor will recomment BAR amend for plants under NRC review. GANG. H. O General Electric Co MFN-157-80. B0/09/08, dpp
- 8009160424 Forwards add1 info on NEDO-24259; "Generic Info for Barrier Fuel Demonstration Bundle Licensing," in response to NRC 80082B request: Requests NRC approval by 800930 so that hardware mfg can begin Oct 1980. ENGEL.R E. General Electric Co. MFN-156-80 80/09/11 33pp.

```
---8009160436 GEAP-25163-2
"Demonstration of Fuel Resistant to Pellst-Cladding Interaction Phase 2 - Second Semiannual Rept.Jul-Dec 1979" & Affiliation Unknown ARMIHO, J B., ROSENBAUM, S. Osmeral Electric Go. UC-78 80/03/31 87pp. Available at NTIS
```

9009190341 Forwards corrected NECAN solution to NRC benchmark problem four Encl A discusses differences in two solutions. Encl B provides summary results & addi solution is given in Encl C Encl B & C hard copies in Central Files only ANDERBON, T. M. Hestinghouse Electric Corp NS-TMA-2300. 80/09/03

8009190157 Notifies of review of util 800215 & 0715 submittals ra organizational changes within water reactor divs & product assurance dept. Encl changes are acceptable & should be incorporated into next revision of WCAP-8370 HAASS, W. P. Quality Assurance Branch 80/08/14 8pp

9009190449 Forwards WCAP-9764 & WCAP-9765, proprietary & nonproprietary version of, "Documentation of Westinghouse Core Uncovery Tests & Small Breat Evaluation Model Core Mixture Level Hodel." Proprietary version withheld (ref 10CFR2.790) JRGENSEN, R W. American Electric Power Co., Inc. 09-40. 80/09/15.1189.

ANDERSON, T M He 80/07/31 29pp. Hestinghouse Electric Corp , Nuclear Energy Systems.

BO07190457 Forwards proprietary & nonproprietary versions of responses to NRC request for add1 info on Addendum 1 to WCAP-8720 Proprietary version withheld (ref 10CFR2 770).
ANDERBON, T.M. Westinghouse Electric Corp., PWR Systems Div. NS-THA-2303. 80/09/09 28pp

8009190378 Notification of 800911 meeting w/C-E & Omahe Public Power in Satheeda, MD to discuss guidelines for plant emergancy procedures. SHERON, B.

Reactor Systems Branch. 80/09/05. 3pp.

8009220139 Forwards proprietary & nonproprietary version of, "Dow Bys for Solidification of Low Level Radwasts from Nuclear Power Plants," revising 780331 rept to include Amends 1 through G. CMEN.J.B. Dow Chemical Co 80/09718. 1p

BOOP220275 Documents comments made at NRC BOOB27 weeting w/industry processoriatives to NUREO-0377, NUREO-0577 does not distinguish between integral & nonintegral supports. Integral supports have had more restrictive requirements. ANDERSON. T. M. Westinghouse Electric Corp., NB-TMA-2304 GO/09/09.

8009220395 BML-NUREO-28060 "Sensitivity of Risk Parameters to Human Errors for PHR." SAMANTA.P., HALL,R.E., Broothaven National Laboratory, KERR.H Hichigan, Univ. of 80/09/11, 12pp.

8009230308 Forwards add1 data to NEDO-24708, prepared by GE on behalf of BMR owners group, Republication of NEDO-24708 anticipated incorporating prepublication mat1 submitted since original publication.
BUCHROLZ,R.H. General Electric Operating Plant Coners Group.
HFN-162-80. 90/09/16. 135pp.

BO09230308 Forwards add1 data to NEDO-24708, prepared by GE on behalf of BMR tweets group Republication of NEDO-24708 anticipated incorporating prepublication mat1 submitted since original publication. BUCHHOLZ, R. H. General Electric Co RHB-074-80. 80/09/16. 135pp.

BOC9230430 Forwards nonproprietary varsion of NEDD-24798, "Mark II Containment Program, Caorso Extended Discharge Test Rept, " on behalf of Mark II owners group as part of Task 8-5 BUCHMOLZ.R H General Electric Operating Plant Gwmers Group, MFN-158-80, 80/07/12, ip.

## --8009230431 NEDO-24798

DV430431 NBDU-24798 Kunpropristary version of "Mark II Containment Program, Cabrao Discharge Test Rept." HOLAN, J. HINTZ, B., MUZZY, R. J. Ganeral Electric Co. GONED282, 90/08/31 35p.

8007230472 Forwards nonproprietary version of NEDO-24811, "4T Condensation Oscillation (4TCO) Test Program Final Test Rept." on behalf of Mark II owners group as part of Task A-17. BUCHROLZ, R H General Electric Operating Plant Owners Group. HFN 153-80 80/09/03, ip.

--8009230475 NEDO-24811 NONECONA NEDD-24811 Konproprietary version of "4T Condensation Oscillation (4TCO) Test Program Final Test Rept " BYRD.P K., FITISIMHONS, G., ROCERS, A E. General Electric Co. SONEDDS7 BD/07/31 100pp

8009230591 Advises of new owners group urganized to address generic angineering, licensing & operational issues & completion of projects begun under owners group on post-TMI efforts KP Baskin of Southern CA Edison was elected chairman LIEBLER. O E C-E Operating Plants Owners Oroup 80/09/04 ig.

8009230672 Forwards revised pages to QA program CE-1-A NAUGHTON, H. F. Commonwealth Edison Co. 80/09/18. 1

--8009230684 CE-1-A R14 Revised Pages 1-31,1-41 & 1-24 to GA program CE-1-A,Revision 14 # Commonwealth Edison Co 80/09/09 3pp

8009230685 Forwards responses to MRC 790725 questions on MCAP-9292 re fracture toughness of ABME matt Review & consideration of rept & enct info in conjunction w/safety analyses rept refs requested ANDERSON, T. H . Westinghouse Electric Corp. NS-TMA-2312 80/09/18

8009240520 Forwards CEMPD-254-NP-A & CEMPD-254-P-A. nonproprietary & proprietary versions of "Post-LOCA Long-Term Cooling Evaluation Model" Affidavit re proprietary nature of CEMPD-254-P-A encl
8CHERER, A. E. C-E Power Systems. LD-80-043 80/08/04. 5pp

--8009240527 CENPD-254-NP-A "Post-LOCA Long-Term Cooling Evaluation Model," nonproprietary version \* C-E Power Systems. 80/06/30, 200pp.

8009250462 Ack receipt of B00324 k 0801 ltrs urging Commission to require inerting of Mark I & Mark III containments Commission will consider views in reaching Secision CHILK.S. J. Office of the Secretary of the Commission 80/08/25.

--B009250467 Requests containment inerting at all Mark I & Mark II containments w/o delay JORDAN, M. S., MEISS, E. R. Sheldon, Harmon & Weiss 80/08/01, 2pp.

---B009250471 Requests approval of NRC staff recommendation to require immediate inerting of Mark I & Mark II containments.
JURDAN-W B : WEIBBLE R. Bheldon, Harmon & Weiss. B0/03/24. App

8009250477 Forwards nonproprietary Exxon Nuclear Co topical repts: XN-NF-79-55(NP); XN-NF-79-71(NP), Revision ii XN-NF-80-19(NP), Vol ii XN-NF-80-19(NP), Vol 2A: XN-NF-80-19(NP), Vol 2B. Nonproprietary version of three addl repts to follow. OHSLEY, O. F. Exxon Nuclear Go. Inc. (subs. of Exxon Corp.) GFD: 136:80 80/09/19 ip.

--B009260482 XN-NF-79-89(NP)

"Methodology for Calculation of Pressure Drop in EWR Fuel
Assemblies," nonproprietary version.
ADAMS.F.T. PATTEN.T M. Exxon Nuclear Co.. Inc. (subs. of Exxon
Corp.) 80/08/13. 59pp

--8009240407 XN-NF-79-71(NP) RI NOVAMONDY IN-HW-/Y-/I(HY) KI
"Exxon Nuclear Plant Transient Hodel for Jet Pump BWRs,"
Revision i.nonproprietary version
KELLEY/R H. Exxon Nuclear Co : Inc (subs of Exxon Corp ).
80/08/14. 39pp.

--8009260493 XN-NF-80-19(NP) Vi
"Exxon Nuclear Methodology for BMRs:Neutronics Methods for Design & Analysis." Vol 1, nongropristary Version # Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 80/08/07 217pp.

---8009260498 XN-NE-80-19(NP) V2A
"RELAX:RELAP4 Based Computer Code for Calculating Blowdown
Phenomena," Vol 2A, monpropriatory version.
KKLESAR, D C Exxon Nuclear Co , Inc (subs. of Exxon Corp.).
80/07/31. 71sp.

--G009260504 XN-NF-80-19(NP) V28
"FLEX.Computer Code for Jet Pump BLR Refil) & Reflood
Analysis: "Vol 28:morproprietary version.
BUORNARD.T.A. 7 ZIMMERMAN.L.R. Exxon Nuclear Co., Inc. (subs. of
Exxon Corp.). B0/07/31, 98pp

- 8009300038 Notification of 800919 meating w/BHR owners group representative.6E & NRC in Bethesda.MD to discuss proposed criteria for plant-specific mods reseam discharge vol HANNON.J & Operating Reactors Branch 2 80/09/12 2pp
- 8009300394 Requests reply to 800221 & 0625 ltrs re status of technical review of topical rept on Fox-Howlett rebar couplars DEUBERT, J R Fox Industries 80/09/23 ip
- 8009300477 Forwards modified App 8 of NEDD-10329, "LOCA & ECCS Models for OE BURs." re technical description of computer code SAFE. to suppl 800625 ltr
  CAMERON.C A General Electric Co MFN-164-80 80/09/23 ip
- --8009300483 NEDO-10329 Modified App B of "LOCA & ECCE Models for CE BWRS " \* General Electric Co 80/09/23 48pp

## WABTE HOT NUCLEAR WASTE MANAGEMENT

- 8009090748 Forwards "Environ Assessment of Dawn Mining Co Below-Orada Tailings Mgt Plan.Ford.WA." conforming to contents of Dapt of Social & Health Svcs 800326 ltr re schedule & scope SCARANO.R A Uranium Recovery Licensing Branch. 80/08/29. 1p
- --8009090769 "Environ Assessment of Dawn Mining Co Proposed Below-Grade Tailings Hgt Plan.Ford.WA" \* Uranium Recovery Licensing Branch. 80/08/31 100pp
- 8009100135 Summary of 800814 meeting w/BNHL in Silver Spring.MD re requirements for remedial action program for Edgemont.SD EADIE.G Q. Uranium Recovery Licensing Branch 80/08/19 2pp.
- BOO9100478 Forwards proposed agendas for 800902 & 03 meetings in Edgemont & Rapid City.8D re Edgemont cleanup action program SCARANO,R A Uranium Recovery Licensing Branch B0/08/21 1p
- 8009100491 Forwards proposed agendas for 800902 & 03 meetings in Edgement & Rapid City,8D re Edgement cleanup action program SCARANG.R A Uranium Recovery Licensing Branch 80708/21 3pp
- 8009100940 Summary of 800815 meeting w/Cyprus Mines Corp in Silver Spring.MD re tailings agt alternatives. TRAGER,E A Uranium Recovery Licensing Branch 80/08/22 App
- 8009110550 Ack receipt of 800811 submittal of discussion paper & research proposal or U mill tailings sits at Edgemont, 8D Research proposal unnecessary due to recent congressional action Supplemental appropriations & rescission bill encl HILLER, H J Uranium Recovery Licensing Branch. 80/08/27. 3pp
- 8009i10847 Forwards invoice re star tabulation & rept. "Beasonal Hind Distribution by Pasquill Stability Classes (6) (Star Program )" " Commerce. Dept. of. National Oceanographic & Atmospheric Adminstration 17107 80/08/13
- BOO9150535 Responds to 800401 request for review of autline re U mill tailings remedial action. Outline meets Council on Environ Guality requirements Agrees w/EIB MILLER. H J. Uranium Recovery Licensing Branch 80/08/28 3pp
- 8009160475 Forwards plan developed for offsite remedial action program at Edgemont.8D Orab working level measurements are compatible w/HUD/8D radiation survey protocol Requests concurrence by 800902

  MARTIN.J B. Division of Waste Management 80/08/19 2pp
- --B009160479 Bubmits remedial action program for Edgemont, BD. Program consists of grab working level measurements; gamma radiation measurements; long-term radon progeny sampling, soil sampling, engineering assessment & remedial action/verification EADIE, G. Uranium Recovery Licensing Branch FIN 8-2217 B0/08/12 itpp
- 8007160486 Forwards application for matls license Vols 1 & 2 filed w/CO Dept of Health.Radiation & Hazardous Waste Control Div on 800715.
  VINYCH.V. Dravo Corp. 17322. 80/07/28. 416pp
- 8007i60543 Forwards examiner rept & proposal for decision re application by Anaconda Copper Cu for U surface mining operation permit. BLEVINS: G N Texas, State of 17043, 80/07/17 19pp.

- 8009170250 Submits priority list of structures scheduled for remedial action & residences requiring further radiological assessments.

  EADIE, G G , SCARANO, R. A. Uranium Recovery Licensing Branch FIN B-2217. B0/08/14, 2pp
- 8009180321 Forwards Geophysical Logs WH-78-2,M-78-2,M-78-3 & M-78-4, W/O encls
  WILLERT.R L Figner Urayan, Inc 17259. 80/08/21. ib.
- 8009180494 Forwards rept of tailings mgt evaluation of Gulf Mineral Resources Co Taylor U mill project Completes NRC assistance as agreed in 800303 meeting SCARANOR. A Uranium Recovery Licensing Branch 80/05/16. 40pp.
- BOO9190762 Forwards info on 26 properties in area of processing site under DOE consideration for determination as remedial action properties Identification & evaluation of approx 100 addi properties ongoing H/o encl MOTT, W E Energy, Dept of. 17120, 80/06/12, 1p
- BO09220046 Forwards info developed on 30 properties in vicinity of Salt Lake City site Properties may be designated for remedial action due to contamination w/residual radioactive mat1 derived from site Requests comment.

  MOTT, W E Energy, Dept of 17076 80/07/24. 1p
- 8009220116 Forwards decision upholding 790427 affirmation of Forest 8vc approval of operating plan of Homestake Mining Go Pitch project PETERBON,R M Agriculture,Dept of, Forest Bervice 17106 807/89/15 7nn.
- 800926085 Bummarizes purpose & function of diversion structures associated w/tailings disposal Diversion ditch will be constructed along north side of tailings isolation area to pravent runoff from entering trenches during exception LANGE, 8 L Pioneer Nuclear, Inc 17209. 80/08/14 2pp.
- 8007270499 "Tailings Disposal Facility, Dawn Mining Co. Addl Info for DSH8." Aug 1980.

  # Dawn Mining Co. 17295 80/08/31. 17pp.
- --8009290501 "Addl Info for DSH8," Sept 1980 \* Dawn Mining Co. 17295 80/09/30. 25pp.
- 8009300232 Responds to request for info concerning characteristics of U sill tailings & transportation to pit from mill at Rhode Ranch Includes description of transportation to pit & radiometrics in tailings. Related data encl DAVIS.OR Anaconda Co., Anaconda Copper Co. Div 17225. 80/08/20. 2pp.

#### XPORTLIC EXPORT AND IMPORT LICENSES

- 8009020120 Provides add1 info re 800730 ltr requesting visus on proposed amends to Edlow Intl export license, Federal Inst for Reactor Research Switzerland is proposed storage facility for U hezafluovide mstl.
  PETERSON.H R. Assistant Director for Export/Import & International Safeguards 80/08/22. ip.
- 8007020127 Forwards license application & proposed license for export of depleted U to Canada per Commission 800728 decision re delegations of authority in export-related areas M/o ancl. PETERSON.H.R. Assistant Director for Export/Import & International Safeguards. 80/08/22 ip
- 8007020162 Forwards Exxon Nuclear Co Inc 800729 add1 and use info on export license application M/o enci DEVINE, J.B. Assistant Director for Export/Import & International Bafeguards. 80/08/13 1p.
- 8007020464 License for GE to export 4.000 kg U-235, contained in 140.000 kg U dioxide to Taiwan. PETERBON'M R. Assistant Director for Export/Import & International Safeguards. BOW 79201. 80/08/26. 2pp.
- 8009020471 Amend 2 to License for Transnuclear, Inc. extending expiration date from 801201 to 811201.
  PETERBON.M.R. Assistant Director for Export/Import & International Safeguards MISC-241 78-073, 80/08/25, ip
- 8009020478 Amend 3 to license for Hestinghouse, extending expiration date from 800930 to 821231.
  PETERSON.H R. Assistant Director for Export/Import & International Safeguards. PC-AEC-19. 80/08/25 1p.

- B009020480 Forwards application by Transnuclear. Inc for license to export 11.03 kg U to France.
  MATSON.V. Transnuclear, Inc 80/08/20 ip
- --B007020486 Application by Transnuclear, Inc for license to export
  11 03 kg U, enriched to max 2 2286% U-235 to France
  MAT60N, V Transnuclear, Inc. 80-173/01 TNP-3 80/08/20 1pp.
- 8009020492 Forwards application by Westinghouse for license to apport 312,000 kg U to Taiwan
  HESS,R J. Hestinghouse Electric Corp. ICS-0718 80/08/14 ip
- --B009020499 Application by Mastinghouse for license to export 312,000 kg U. containing 12,480 kg U-235, to Taiwan HESS.R.J. Mestinghouse Electric Corp ICS-0718 80/08/14 2pp.
- 8009030697 Application by Honeywell Defense Sys Div for license to export rod ends &/or scrap piece parts to Canada

  # Honeywell, Inc. 80/07/29 ip
- --8009030698 Supports application for license to export rod ends &/or scrap piece parts to Cahada BARRY.C.B Honeywell, Inc. 80/07/29 2pp
- 8009050442 Forwards Cabot Corp application for license to export afrecunium tubing to Canada, TUPPER.K F Cabot Corp 80/08/08 1p
- --8009050446 Application by Cabot Corp for license to export zirconium Orade 2 seamless tubing to Canada.
  TUPPER,K Cabot Corp 1-9817(19-28012 80/08/08. 1p
- 8009050449 Requests Executive Branch position re GA Co application for license to export replacement parts & components to West Germany.

  DEVINE, J. B. Assistant Director for Export/Import & International Bafeguards 80/08/19. 1p
- B009050466 License for Canada Dept of Supply & Svcs to export 0 0002 microgram Pu-239 to Canada DEVINE: J B Assistant Director for Export/Import & International Bafeguards 23233-0-0314. 80/08/27 2pp
- 8007050467 Submits application to amend export & import licenses, asterming expiration dates.

  HATBON. V. Transnuclear. Inc 80/08/18 1p
- BOOPOSOSIS Requests Executive Branch position re Edlow Intl Co application for license to export BNM to Taiwan DEVINE.J.B Assistant Director for Export/Import & International Bateguards. BO/OB/15. ip.
- 8009090279 Executive Branch position re Reactor Experiments, Inc application for license to export 0.033 mg PU-239.0.098 mg U-235 to 1007 mg Np-237 to Saudi Arabia License should be granted. NOSENZO.L.V State.Dapt.of. Bureau of Oceans & Internat1 Environ & Scientific Affairs 80/09/14 2pp
- BOOGOS47 Executive Branch position re Transnuclear, Inc application for license to export 10,083 kgs U-235, contained in 22 142 igs U, to Japan, License should be granted. Ltr of assurance encl.
  NOBENZO, L. V. State, Dept. of, Bureau of Oceans & Internati. Environ & Scientific Affairs 80/08/13 5pp.
- BOOYOYO&& Application by CERAC, Inc for license to export 20 kg thorium metal powder to The Netherlands.
  COLTON:E Cerac, Inc. 80/09/08. ip.
- BOOGOPO202 Forwards application by Sandvik Special Metals Corp for license to export zirconium tubes to Japan DUSONSKY.E. George S. Bush & Co. 80/08/12. 1p.
- --BOOGO7020B Application by Sandvik Special Metals Corp for license to apport 2R-4 caterpillar thimble tubes to Japan.

   Sandvik Special Metals Corp. 0392. 80/08/12. 1p.
- 8009070213 Forwards application by Sandvik Special Metals Corp for license to export zirconium tubes to Japan pusinksky.E George S. Bush & Co 80/08/12. 1p.
- ---BOO9090215 Application by Sandvik Special Metals Corp for license to export zirconium tubes to Japan.

  Bandvik Special Metals Corp 0391 80/08/11 2pp.

- 8009090614 Forwards application for licenses to export 395 71 g U. contained in U oxide fuel rod to West Germany OLSEN, R N National Nuclear Corp. 80/07/31 1p
- --8007090619 Application by Natl Nuclear Corp for license to export 395 71 g U.contained in U oxide fuel rod, to West Germany End use statement encl \*\* National Nuclear Corp 80/07/02 3pp
- ---8009090630 License for Natl Nuclear Corp to export 7,95 g U-235, contained in 395 71 g U-to Weat Oermany QUHIN.M A Assistant Director for Export/Import & International Bafaguards 76/09/24 5pp
- 8009090659 Application by Edlow Intl Co for license to export 5 tons deplated U tatrafluoride for penetrators for non-nuclear and use to United Kingdom. MARMON D. H. Edlow International Co. 80/08/29. ip.
- 8007090663 Application by Marubeni America Corp for license to export 50 kg spacer piece parts \* Harubeni America Corp. (subs. of Marubeni Corp.). INGY-1968 800/08/23 10
- 8009100032 Submits application to amend license to export addl 2 kg U dioxide in powder form to Taiwan.
  WILSON B. B. General Electric Co. BDM-80096 80/08/11 ip.
- 800910004B Bubmits application to emend export license changing consignee address & proposed expiration date.
  RODI, J. P. Hestinghouse Electric Corp. TFG/NRC-5162 80/08/13
- 8009100096 Forwards application for license to export four sources, totalling 904 micrograms Cf-252, to Taiwan HEBB:R J. Westinghouse Electric Corp ICS-0721 80/09/14. ip.
- --8009100101 Application by Hestinghouse for license to export four sources, totalling 904 micrograms CF-252, to Taiwan, HESS,R J Westinghouse Electric Corp ICS-0721 80/08/14 2pp
- --8009100131 Application by Westinghouse for license to export 240 mg Np-237, contained in 12 radiation surveillance capsules, to Taiwan.
  HEBS.R.J. Westinghouse Electric Carp. ICS-0722. 80/08/14. 2pp
- 8009100155 Executive Branch position re OA Co application for license to export low enriched U to Indonesia for use in Kartini Research Reactor, License should be granted Ltr of assurance required NOBENZO, L. V. Btate, Dept. of. Bureau of Oceans & Internatl, Environ & Scientific Affairs 80/08/28 19pp
- 8009100198 Requests Executive Branch position re Westinghouse application for license to export radiation capsules containing Np-237 & primary neutron sources containing Cf-252 to Taiwan.

  PETERBON M.R. Assistant Director for Export/Import & International Bafeguards. 80/08/25. 1p.
- 8009100493 Application by Westinghouse for license to export one compensated ionization chamber to France.
  POCHAL.W.F. Westinghouse Electric Corp. 26-20293-5 80/08/08, ip
- 800P110028 Response in apposition to Friends of Koraan People Aug 1780 motion to amend petition to intervene & request for hearing Interest may be represented by Ctr for Development Policy, if intervention allowed, Certificate of Svc encl COWAN.B Z , KENRICK.J.R. Wastinghouse Electric Corp. COWAN.B Z Eckert, Seamans, Cherin & Mellott. 80/07/14, 4pp
- 8009110254 License for Edlaw Intl Co to export 347 kg U-235 for fuel fabrication to Japan DEVINE, J.B. Assistant Director for Export/Import & International Safeguards. SUM 13 80/09/02 2pp.
- 8009110260 License for Westinghouse to export 8,845 kg U-235, contained in 928,822 kg U-to Taiwan.
  DEVINE, J. B Assistant Director for Export/Import & International Bafeguards ICS-7823. 80/08/29. 2pp.

- 8009110264 Submits application to amend export license, changing consignee address & proposed license expiration date RODI, J.P. Westinghouse Electric Corp. TFO/NRC-5162 80/08/13 ip.
- 8009110270 Submits application to amend export license to increase quantity of goods from 10 to 20 pieces of Model RB-C4-0201-23: EECKHOUT. A Reuter-Stokes, Inc. 80/08/15 1p
- 8009110279 Submits application to emend export license, reflecting changes in form of licensee name & address deleting five intermediate consignees & changing address of remaining intermediate consignee.

  HILSON.B D General Electric Co BDW 80099 80/09/13. 2pp.
- 8009110403 Submits application to amend Licenses ISNM-79010, XSNM-1559, XSNM-1483 & XT-8429, artending expiration dates to 810901. 811201.810901 & 811201.Pespectively HATSON, V Transnuclear, Inc 80/08/18 ip
- 8007110406 Requests that raview of application for license to export utilization facility to Taiwan be expedited for issuance prior to Mar 1981 HESS.R J. Westinghouse Electric Corp. ICS-0724 80/08/14 1p
- 8009110492 Forwards application for license to export 25,000 lb depleted U solid metal to Canada BCHAEFFER, M. R. R. R. R. Co. . RKI Titanium 80/08/25. ip.
- --8009110587 Application by RMI Co for license to export 25,000 16 U solid metal to Canada SCHAEFFER. M.R. RMI Co , RMI Titanium 80/08/25. 299
  - 7110494 Requests cancellation of License XBNM-1597 ICKHOUT, A Rauter-Stokes, Inc. 80/08/28 ip
  - 9110497 Forwards application for license to export 7 508 kg V to lest Cermany.

    4ATBON V. Transnuclear, Inc. 80-180/01 80/08/25 ip.
- -8009110502 Application by Transnuclear Inc for license to export 7.808 kg U.in form of U hexafluoride to Germany Transnuclear Inc NUK-339 80-180, 80/08/25 2pp
- 8009110559 Certifies that matl in Westinghouse 800612 application to export 3 7 kg U-235 to Italy will be subj to 600725 Addl Agreement for Cooperation & that ultimate consignee is authorized to receive & possess matl.

  MARCHALJ European Communities, Commission of. 80/09/28. 1p
  - 79110564 Certifies that meth in Natl Nuclear Corp 800702 application a export 395,71 g U to Hest Germany will be subj to 600723 dl Agreement for Cooperation & that ultimate consignes is thorized to receive & possess math
  - 110580 Certifies that math in Westinghouse 800612 application to port 6,000 g U to Belgium will be subj to 600725 Addinament for Cooperation & that ultimate consignee is thorized to receive & possess math.

    RCHAL.J European Communities, Commission of, 80/08/27, ip
  - 110585 Forwards Executive Branch response on pending export cense application requiring Commission review. Ofc should itiate final review of case to facilitate early response forthcoming action paper.

    EAr.J.R Office of International Programs, Director. 80/08/21.
  - liOS91 Requests Executive Branch position re Westinghouse plication for amend to License XR-0083, extending piration date to 201231, W/o encl TERSON, M R. Assistant Director for Export/Import & International leguards 80/08/R7, 1p.
  - 7110592 Forwards application for license to export 1 kg deuterium o Mexico DELSTEIN/8 Aldrich Chemical Co., Inc. (subs. of Sigma-Aldrich orp.). 80/08/25 ip.
  - .00911059A Application by Aldrich Chamical Co.Inc for license to export 1 kg deuterium.contained in 5 kg deuterium oxide, to Mesico EDELBTEIN, B. Aldrich Chamical Co., Inc. (subs of BigmanAldrich Corp ). 16/80. 80/08/21. 1p.

- 8009110593 Advises that Commission has accepted recommendation to amend QA Co license to export addinuclear components, including control rod elements, fission & ion chambers & electronic amplifiers to Taiwan HOYLE, JC Office of the Secretary of the Commission 880-390 80/09703 ip
- 8009110600 Application by Matheson Qas Froducts for license to export 500 liters deuterium to Australia WOQD,L D Matheson Qas Products 101-96919 80/09/21. 1p
- 8009110602 Application by Mitsubishi Intl Corp for license to export 500mCi encapsulated cement wire of Cf-252 to Japan KUGE, T. Mitsubishi International Corp. (subs. of Mitsubishi Corp.) 64-7376-79. 80/08/22 1p.
- 8009110606 Forwards Westinghouse 800914 ltr re license to export two power reactors to Taiwan If license not issued by Mar 1981. bid will be disqualified W/o encl PETERSON,M R. Assistant Director for Export/Import & International Safeguards 80/08/27 1p
- 8007110607 Amend I to license for Hoke Inc increasing value of exported items & extending expiration date to 830630 PETERSON.H R. Assistant Director for Export/Import & International Badeguards. 1126-81. 80/08/27. ip.
- 8009110629 Submits application to amend license to export addl quantities of U & U-235 MATSON,V Transnuclear, Inc. 80/08/15, ip
- 8009110632 Forwards application to export 60.500 ft xirconium seamless tubing to Ganada.
  TUPPERIK.F. Cabot Corp. 80/08/08 ip.
- --8009110635 Application by Cabot Corp for license to export zirconium Orade 2 seamless tubing to Canada TUPPER.K Cabot Corp. 1-9816,9818.529 80/08/08, 1p
- 8009110689 Forwards RMI Co 800829 ltr confirming Iraq as ultimate destination re export license application XU-8505. W/o encl. DEVINE, J.B. Assistant Director for Export/Import & International Bafeguards 80/07/03. lp
- --8009110214 Supple 800825 export license application for shipment of 347 kg U-235 to Canada. SCHARFFER M. R. RMI Co., RMI Titanium 80/08/29, ip
- 8007i10695 Forwards UNC Recovery Sys 800818 ltr re discontinuance of highly enriched U operations. Ltr requests info re plans for matl being stored for NVKEM.

  MATSON; V. Transnuclear, Inc. NVK-273 80/08/25. Spp
- B007110700 Requests quantity of matls on 790124 export license application & 790213 amend be changed to 10 364 kg U containing 9 670 kg U-235.
  MATBON.V. Transnuclear, Inc. NUK-264. 80/08/25. ip.
- 8009110723 License for Hestinghouse to export 3 70 kg U as U oxide for fabrication of BHR fuel to Italy.
  DEVINE. J B Assistant Director for Export/Import & International Gafeguards ICS-0417. 80/09/03. 2pp.
- BOO9110741 Amend 1 to OA Co export License XCDM-0300, increasing value of items to be exported & authorizing export of add1 components
  DEVINE, J B Assistant Director for Export/Import & International Safeguards IEL-1106, B0/09/03 ipp.
- 8009110743 Bubmits application to amend license to export to include 1,144 kg U as U-308,containing 5 kg U-235.
  MATSUM,U. Transpuclear, Inc. 79-211/01. 80/09/02, ip
- 8009110795 Requests Executive Branch position re QE application for license to export addl 2 0 kg U.enriched to 11 W/o max.for use in Taiwan. PETERBON.N R. Assistant Director for Export/Import & International Bafaguards. 80/08/27. 1p
- 8009110830 Submits application to amend license to export increasing value limitation from \$100,000 to \$250,000.

  HILBON, BD General Electric Co., Nuclear Energy Products Div. BDM-80100 80/08/21. jp.
- 8007120036 Notifies of Edlow Inti Co 800819 request for withdrawal of export license application XBNM-1585.
  DEVINE.J B Assistant Director for Export/Import & International Safeguards. 80/08/29. ip.

- 8009120062 Ltr of assurance re Kansai Electric Power Co. Inc application for license to export 347 kg of U-235, contained in 13,090 tg U to Japan HIYASAYASHI, M Japan 80/08/14 ip
- 8009120574 Submits application to amend license to export Zircaloy-4 fusl channels to ENEL BWR power station located at Cacrso, Italy, WOZNIAK, D. R. Carpenter Technology Corp. 80/08/26 3pp
- 80091274-03 Bubmits application to amend license, increasing export value limitation & sitending expiration date BRUBH.P.N Hoke, Inc. 80/08/20 1p
- 8009120607 Ltr of assurance re export license application XBNM-1700 WULLER, R.E., HOFMAN, R. Switzerland BO/08/11 in
- 5009120624 Forwards application to export 1 kg deutarium.in 5 kg dautarium oxide, to Chile EDELSTEIN:B Aldrich Chemical Co., Inc (subs. of Sigma-Aldrich Corp.). BO/08/26 1p
- --BOO9120627 Application by Aldrich Chamical Co. Inc for license to export it g deuterium in 5 kg deuterium avide to be used in lab quantities for RtD in deuterium nuclear magnetic resonance work to Chile.

  EOELBIETH. 8 Aldrich Chemical Co., Inc (subs of Sigma-Aldrich Corp.) 17/80. 80/08/25 ip.
- 8009130029 Forwards Executive Branch response on pending export license application XSNM-1542. Commission action paper will be forwarded Requests initiation of final review to facilitate early response. M/o encl SHEA.J R Office of International Programs, Director. 80/08/26. is.
- 6009150072 Informs that NRC has not completed licensing action on expert license application to expert low enriched U to Taiwan Favorable Executive Branch reviews received 790616 Final Commission action expected shortly SHEALUR Assistant Director for Export/Import & International Bafeguards. 80/08/14. 10
- B009150410 Forwards responses to 800527 questions re info provided by NRC on 800501 concerning differences in role of NRC & Executive Branch in processing export requests Supporting documentation and AREARNE, J.F. Commission. 80/08/22, 13pp.
- --B009150418 BECY-78-216A
  Forwards documents re proposed license for Transnuclear, Inc
  to export high-enriched U to Sweden.
  BMEA, J. R. Office of International Programs, Director. 78/05/11
  Jap.
- -B009150422 Submits conclusions re proposed license for Transnuclear, Inc to export high-enriched U to Sweden License issuance would be consistent w/Nuclear Nonproliferation Act. MOORE, R. N Office of International Programs, Director, 78/05/10. 5ps.
- --B009150423 Provides comments on proposed license for Transmuclear, Inc to export high-enriched U to Sweden Supporting documentation encl. TARNOFF, P. State, Dept. of. 78/03/03 Spo
- -- 8009150428 Forwards revised analysis of Transnuclear, Inc application to export high-enriched U to Sweden NOSENZO, L V. Btate, Dept of Bureau of Oceans & Internat! Environ & Scientific Affairs 78/05/08, 17pp
- --BO09180433 Application by Transnuclear, Inc. to export 21.053 kg U hasafluoride, enriched to max 93 90X U-235, to Sweden. End use statement enci.
  MATSON, V. Transnuclear, Inc. 77/01/25, 2pp
- --800915043B Forwards application for license to export 19.442 kg U-235, contained in 21 053 kg U as U hexafluoride enriched to 93.5%, to Bweden, H/o encl Proposed license encl. HATBON, V. . Transnuclear, Inc. 77/01/25, 4pp
- --BOO9180442 Submits conclusions re Ediow Intl Co application to export SAM to Sweden No mati changed circumstances re application from those existing at time of issuance of XSNM-1074 & XSNM-1248, License may be issued.

  MOORE, N. Office of International Programs, Director, 79/09/06.

- --8009130446 Advises of no matl changed circumstances re application from those existing at time of issuance of XBNM-1532 License may be issued. MODRE,R N Office of International Programs, Director 90/02/28
- 8009160191 Amend to license for GE.increasing value of items to be exported to \$250,000.
  PETERBON.M.R. Assistant Director for Export/Import & International Bafeguards. BDM-102-78:8010 80/08/27 1p
- 8009160193 License for Westinghouse to export one unit proportional counter to Belgium.

  DEVING. J B. Assistant Director for Export/Import & International Safaguards. ZE-20351 80/08/27 1p
- 8009160194 License for Honeyweil to export 555,800 kg depleted Unin rod ands or screp pieces/to Canada DEVINE. J B Assistant Director for Export/Import & International Safaguards 80/08/27 2pp
- 8009160233 License for Reuter-Stokes, Inc to export one unit Hodel R8-Ci -2514-115 compensated ionization chamber & two R8-C2-2510-104 uncompensated ionization chambers to Sweden PETER80N, M R. Assistant Director for Export/Import & International Bafeguards. V-8627. 80/09/02 ip
- BO09160236 Forwards application for license for minor nuclear export Ltr of assurance required. M/o encl DEVINE. J. B Assistant Director for Export/Import & International Safeguards BO/08/27 ip
- 8009160274 Amend 1 to Bendvik Special Metals Corp export license, extending expiration data from 800901 to 801130. PETERBON, M.R. Assistant Director for Export/Import & International Safeguards 9314 80/09/22 [p.
- 8009160278 Response in opposition to Ctr for Development Policy 800620 petition to intervene & request for hearing Environ impacts in Taiwan are beyond Commission authority Effects on global commons already decided Mappe
- 9009160287 Application by Westinghouse for license to export two incore neutron detactors. Model MC-23465, each containing 0 025 g U, contained in 0 026 g enriched U-235, to Bwitzerland POCHAL, N F. Westinghouse Electric Corp. ZE-10327. 80/08/20 ip.
- B009150459 Submits application to amond license to export increasing amount to be exported to 5,000 ib depleted U to China, Albania & Romania as shielding in packaging, License currently limits U exports to 250 kg
  HKNNRO,J J Tach/Ops (Technical Operations, Inc.) 80/08/18 2pp
- 8009170195 Notifies of review of SECY-80-383 re Westinghouse application for license to export components to Korea. Commission accepts recommendation to export specially designed nuclear equipment to Korea HOYLE, J.C. Office of the Becretary of the Commission 880-383 80/09/05 ip.
- BOO9180296 Executive Branch position re QA Co application for license to export low enriched U fuel to Indonesia Recommends issuance of license Supporting documentation encl NOBENZO, L.V. State, Dept. of, Sureau of Oceans & Internati Environ & Brientific Affairs, BO/09/03 27pp.
- 8007180420 Requests Executive Branch position re Washinghouse application for license to export initial cores. spares & three reloads each for Taiwan Units 7 & 8, PETERSON.M.R. Assistant Director for Export/Import & International Bafeguards. 80/08/27 ip
- 8009190126 Forwards notice of receipt of application by Honeywell Defense Sys to export 585,800 kg of depleted U to Canada. LAFLEUR, J D. Office of International Programs. Director 80/08/12, 19.
- ---8007190128 Notice of receipt of application by Honeywell Defense Sys to export 535,800 kg of depleted U to Canada LAFLEUR. J D Office of International Programs, Director. 80/08/12, 2pp
- 8009190245 Hithdraws application for License X8NN-1585 on behalf of BLM. Requests advisement of receipt of request for cancellation of License ISNN-79015.
  EDLOW. J Ediow International Co 80/08/19 ip

- 8009190258 Ltr of assurance re Transmuclear application for license to export 11,054 tg U.erriched to 4 3% U-235 to France MARCHAL.J European Communities, Commission of 80/08/28 1p
- 800919057: Lir of assurance re license to export 8NM to Japan Japan Nuclear Fuel Co.Lif has been appointed authorized person. MIYABAYASHI,M Japan 80/08/25 ip
- 8009190687 Amend to license for QE & QE Technical Svcs Co. Inc. changing licenses name & address, deleting consigness, changing intermediate consignes address & deleting other export

DEVINE, J B Assistant Director for Export/Import & International Safeguards BDM-79001 80/08/27 ip

8009190746 Requests Executive Branch position re RMI Co. Extrusion Plant application for licanse to export 11,340 Kg depleted U solid metal to Canada DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/09/02 ip

- 8009190752 Requests Executive Branch position re Transnuclear application for license to export SNM to West Carmany DEVINE, J B Assistant Director for Export/Import & International Safeguards 80/08/29 ip
- 8009190785 Advises that License X8NM-1681 may be issued since no math circumstances associated w/application have changed since issuance of License X8NM-1674.

  NORE.R. N Assistant Director for Export/Import & International Safeguards, 80/08/29 ip
- 8009230119 Advises that License XSNM-1678 may be issued No mat1 changes occurred since issuence of XSNM-1895 MODRE:R N Assistant Director for Export/Import & International Safeguards 80/08/29 ip
- 8009230417 License for Reactor Experiments. Inc to export 0 190 mg U-235 to Japan DEVINE.J. B Assistant Director for Export/Import & International Safeguards JAP 80255 80/08/29 2pp
- 8009230420 License for Westinghouse to export one unit compensated ionization chamber. Model M.C.29444, to France DEVINE, J. B Assistant Director for Export/Import & International Safeguards ZE-20203-5, 80/09/02, ip
- 8009230425 License for Cabot Corp to export 140,040 ft zirconium Grade 2 seamless tubing to Canada. DEVINE,J.B. Assistant Director for Export/Import & International Bateguards 1-9817(19-28012, 80/09/02 ip
- 8009230427 License for Sandvik Special Metals Corp to export 525 pieces xirconlum metal tubes to Japan. DEVINE.J B Assistant Director for Export/Import & International Safeguards 0392 80/09/02 ip.
- 8009230428 License for Cabot Corp to export 60,500 ft xirconium Grade 2 DEVINE, J. B Assistant Director for Export/Import & International Bafeguards. 1-9816,9818,529. 80/09/02 1p.
- 009230429 Amend 1 to license for Transnuclear, Inc to import 39,500 kg enriched U from France, extending expiration date from 800901 to 310901.
  DEVINE, J B. Assistant Director for Export/Import & International Safeguards 80/08/28, ip.

- 1009230754 Advises of Reuter-Stokes withdrawal of License Application WYSSO/JS NAVISES OF NEWS NAVIS 80/09/08 1p. Safequards
- 009230781 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl. DEVINE, J B Assistant Director for Export/Import & International Safeguards. 80/08/29. ip.
- 1009230783 Application by Mestinghouse for license to export three ML-23448 incore radiation detectors to Japan.
  PDCHAL: M.F. Hestinghouse Electric Corp. ZE-60191 80/08/26 5pp
- B009230797 Application by Edlow Intl Co for license to export 5 g U-010 & 5 g U-015 to Japan
  HARMON, D W Edlow International Co SIB 8(8-97-90) 80/08/27 ip

- 8009230800 Amend i to Transnuclear, Inc export license, extending appiration date from 801201 to 811201.
  DEVINE, J.B. Assistant Director for Export/Import & International Safeguards TNP-297 77-241/ 80/08/28 1p.
- 8009230601 Amend 2 to Transmuclear, Inc export license, extending NOVAMONDO E ROBBE & EU TRAISINGERAFTE DE REPORTE LICENSEI EXTENSION DE PROPOSITO DE SENDRE LE PROPOSITO DE SENDRE LE PROPOSITO DE L'ARGONNE DE L'ARG
- 9009230803 License for Sandvik Special Metals Corp to export 3,315 pisces irronium metal tubes to Japan.
  DEVINE.J S. Assistant Director for Export/Import & International Safeguards. 0391 80/09/02 1p
- 0009240569 RECY-80-393 Forwards Executive Branch response on pending Transmuclea. Inc application for license to export highly enriched U to SHEA.J R Office of International Programs, Director 60/08/22
- 8009250009 Hamorandum & order denying Ctr for Development Policy & Friends of Korean Paople petition to intervene Application for export of two reactors to Bouth Korea meets Atomic Energy Act criteria JF Ahearne & JM Handrie opinion encl GHILK.S.J Office of the Secretary of the Commission. CLI-80-34 BO/09/22. 14pp.
- 8009250333 Forwards Transnuclear, Inc 800815 amend application to increase quantity of matl authorized for export.W/o enci PETERSON.H.R. Assistant Director for Export/Import & International Safeguards 80/08/22. 1p.
- 8009200068 Confirms 800908 telcon re NRC review of license to export fauterium axide to West Germany & urges action to effect shipment under convenient weather conditions WERNER, H. George Uhe Co., Inc. 80/09/08 ip.
- 8007260175 Ltr of assurance re Hestinghouse application to export 5.746 g U to Bweden ALLOARDH O Sweden 80/09/04 ip.
- 8009260218 Forwards application for license to export 1,840 kg U. containing 0,016 kg U-235, to France MATSON, V. Transnuclear, Inc 80-184/01, 80/09/03 ip
- --8009260224 Application by Transnuclear, Inc for license to export 1,840 kg U, containing 0,016 kg U-235, to France.
  MATSON, V Transnuclear, Inc 80-184/01 80/09/03 ip
- 8009270061 Requests Executive Branch position re United Nuclear Corp application for license to export 7.926 kg U to West Germany & other European customers DEVINC.J.B. Assistant Director for Export/Import & International Bafeguards. 80/09/12 1p
- 8009290130 Executive Branch position re QA Co application for license to export electronic control console including instrumentation & power level control components to Belgium. License should be issued.

  NOSENTO.L. V State. Dept of. Bureau of Oceans & Internat! Environ & Biginatific Affairs. 80/09/09 2pp.
- 8009290136 Executive Branch position re Transnuclear, Inc application for license to export 2 799Kg U~235 to West Germany.License should be issued, MOSENYO,L. V. State, Dept of, Bureau of Oceans & Internatl, Environ & Scientific Affairs, 80/09/03, 4pp.
- 8009290147 Requests Executive Branch position re Edlow Intl Co application for license to export 117,319 Kg U to West Ourmany. DEVINE.U.B. Assistant Director for Export/Import & International Safeguards. 80/09/11. 1p
- BO09290149 License for Mestinghouse to export three units in-core radiation detectors. Hodel WL-23448, to Japan. DEVINE, J. B. Assistant Director for Export/Import & International Bafeguards. ZE-60191, B0/09/12 1p.
- BO07270151 License for Aldrich Chemical Co to export 1.0 kg deuterium, contained in 5.0 kg deuterium oxiderto Mexico DEVINE. J. B. Assistant Director for Export/Import & International Bafaguerds. 16/80. B0/09/12. ip.
- 8009270133 Forwards application for export license for minor nuclear export. Ltr of assurance required. M/o encl. DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. 80/09/11 1p

- 8009290137 End use statement for export of depleted U to Great Britain. HARMON.D W Edlow International Co 80/09/08 ip
- BO09290259 Application by Mitsubishi Corp for license to export 500 mCi sncapsulated cermet wire to Japan KU9E, T Mitsubishi International Corp (subs of Mitsubishi Corp ). 04-7462-80 BO/09/03 ip
- 8009290395 License for Matheson Qas Products to export 90g deuterium to Australia. DEVINE.J B Assistant Director for Export/Import & International Safeguards. 101-96919 80/09/11. 1p
- 8009290405 BECY-80-408 Informs Commission of Executive Branch response on pending export application XBNM-1666 for Kartini Research Reactor Copies of original application & ltrs of assurance encl BMEAIJ.R. Office of International Programs, Director 80/09/04
- 8009290476 License for CERAC, Inc to export 20,0 kg thorium metal powder to Mest Germany.
  PETERSON, M R Assistant Director for Export/Import & International Safaguards. 80/09/17. 2pp
- 8009290485 Application by Sigma Chemical Co for license to export equivalent of 10 kg deuterium oxide to Brazil SPERN.M.C. Sigma Chemical Co. (subs of Sigma-Aldrich Corp.) D-53. 80/09/12. 1p
- 8007270488 Application by Sigma Chemical Co for license to export squivalent of 10 kg deuterium to Singapore.

  BTERN.M.P. Sigma Chemical Co. (subs of Sigma-Aldrich Corp ). D-52 BO/07/12. ip.
- 8007270581 Application by Bigma Chemical Co for license to export equivalent of 10 kg deuterium oxide to India.

  STERN, M. C. Bigma Chemical Co. (subs of Bigma-Aldrich Corp.). D-51 B0/09/12. 1p.
- BO07300024 Application by Bigma Chemical Co for license to export squivalent 10 kg deuterium oxide to New Zealand BTERN. M. C. Bigma Chemical Co (subs. of Bigma-Aldrich Corp ). D-50 80/09/12. [p.
- 8009300028 License for Wastinghouse to export 146 kg U-235, contained in 5.746 kg U, to Sweden. PETERSON, M.R. Assistant Director for Export/Import & International Safayards. ICS-0272. 80/09/17. 2pp.
- 8009300032 License for DOE to import 245 kg U.enriched to 2.95% U-235, from Cânada. DEVINC.J.B. Assistant Director for Export/Import & International Bafaguards. 80/09/17. ip
- 8009300039 Requests Executive Branch position re Monsento Research Corpapplication for amend to license to export Cf-252 & Cm-242 & 244 to New Zealand.

  DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. 80/09/17 ip
- 8009300062 Forwards application to amend license to export Pu-238 sealed radiation sources, adding New Zealand to list of countries.

  TAYLOR, R. R. Monsanto Co. 80/09/08, 2pp
- BOO9300071 Requests Executive Branch position re Edlow Intl Co application for license to export 5,000 kg depleted UF4 to Great Britain. DEVINE.J.B. Assistant Director for Export/Import & International Bafeguards. BO/09/16. 1p.
- 8009300074 Executive Branch position re B&W application to export 430 kg depleted U to Japan License shhould be issued Ltr of assurance encl.
  NOSENZO, L. V. Btate, Dept. of. 80/09/08 3pp.
- 8009300078 Application by Transnuclear. Inc for license to import 1510 tg U from West Germany. MATBON V. Transnuclear: Inc. 80-178/02. 80/09/05. 2pp.
- 8009300079 Forwards application by Transnuclear, Inc for license to apport 4.371 kg U to Austria Related end use statement & reactor checklists encl.

  MATSON, V Transnuclear, Inc 80/09/08 ip.

- --8009300084 Application by Transnuclear, Inc for license to export 4 371 kg enriched U to Austria MATSON, V. Transnuclear, Inc NUX-345 80-188 80/09/08 3pp
- S009300088 Application by GA Co for license to export components & replacement parts to Italy MOMRY, M.R. General Atomic Co (subs of Gulf Dil Corp.) IEL-2012 80/09/08 3pp
- 8009300650 Executive Branch position re Coordination Council for North American Affairs application for license to export 4,000 kg of heavy water to Taiwan License should be granted Ltr of assurance encl. NOSENZO.L V. Btate, Dept of 80/09/05 3pp
- 8009300652 License for B&W to export reactor vessel O ring gastets, gasket retaining clips & clip screws, all specially designed for use in nuclear reactor, to Bouth Korea DEVINE, J B Assistant Director for Export/Import & International Safeguards 788-98052-51 60/09/03 ip
- 8009300655 Requests Executive Branch position re Transnuclear, Inc request for amend to license to export add1 1,144 kg of normal U oxide.es U oxide.to Hest Germany DEVINE, J.B Assistant Director for Export/Import & International Safeguards 80/09/08 1p.
- 8009300657 Amend 1 to license for Reuter-Btokes, Inc to export 10 add1 radiation detectors, Models RS-C6-0201-231, to South Korea DEVINE, J. B. Assistant Director for Export/Import & International Safeguards. OE-8025, V-3636. 80/09/09 1p
- 8009300660 Executive Branch position re George Uhe Co. Inc application for license to export 2,250 lbs of heavy water for use in nuclear resonance spectroscopy to West Germany License should be granted.

  NOSENZO,L V State, Dept of. 80/09/05, 2pp
- 8009300662 License for Dapt of Navy to export 5.076 kg depleted Uras component of 74,000 rounds of amountition to Bingapore DEVINE, J B Assistant Director for Export/Import & International Safeguards SER 63/779123 80/09708 10
- B009300664 Executive Branch position re Dept of Navy application for license to export 5,076 kg depleted U to Bingapore, Proposed export may be made w/o being subj to terms of Agreement for Cooperation, License should be granted NOSENZO, L V Btate, Dept of. B0/09/03, 2pp
- B009300666 License for Mitsui & Co to export 0 325 g U-235, contained in 30 g U-to Japan DEVINE, J.B Assistant Director for Export/Import & International Bafeguards. B0/09/08. 2pp.
- 8009300668 Application by Edlow Intl Co for license to export 117,319 kg U.contained in 138,348 kg U-308, to West Germany.
  HARMON, D. W. Edlow International Co NUEX-1 80/09/02 1pp
- 8009300670 Application by Matheson Gas Products for license to export 500 liters deuterium in Size 3 cylinder to Vanezuela JAROD, L. Matheson Gas Products. 101-94099-A. 80/08/28 1pp

			l

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUT JECT CATEGORY
ASEL, J 8	6009150399	71-9113	AKER, R. E	8007020401*	50~275 B	ARNOLD, R. C.	8009300014	50-320 @
ABEL, J. B.	8009110737*	50-254 G	AKER, R. E.	80090204574	50-275 6	ASH, R. F.	8009080350	50~317 F
ABEL, J. B.	8007110545	50-237 Q	AKI,K	8009120514*	50~204 P	ASH, R. F.	8009160453	50-317 P
ABEL, J. B.	8009160681	50-237 G	AKIN, R. C.	8009190378*	50-204 P	ASHENDEN, M. C.	8009030281#	50-390 @
ABEL: J. 8	8007120453	50-10 F	ALBERT, O	8004550504*	50~289 H	ASHELL, D. L.	8009170369	50-392 9
ASERCRONSIE, H	8009170277*	50-259 R	ALDEN, N H	04E0809008	50-277 R	ASHELL, D. L.	9009190158 9009190153	50-382 0 50-382 0
ASERCROHBIE, H	8009170274	50-259 R	ALDEN, H. H	8009160296*	50-277 R 50-186 S	ABNELL, D. L	8007170183	50-382 B
ASRAHS, R.	6009050429	PR	ALPER D H	8007040417* 8007050331*	50-186 S 50-278 S	ABHELL, D. L. ABHELL, D. L.	8009300092	50-362 Q
ACKERMAN, N. C. ACKERMAN, N. C.	8009100288 8009170134	40-8102 40-8745	ALLEN, M. D ALLGARDH, O	B009240195	XPORTLIC	ABHELL, D. L.	8009300212	50-382 0
ACOSTA, A. P.	8009110850	40-9584	ALLISON, D. P	8009290143	50-10 P	ABHELL, D L.	8009190491	50-362 H
ACOSTA, A P	8007030470	40-8584	ALLISON, D. P.	8007260022	50-10 P	ABHELL, D. L.	8009290394	50-382 B
ADAM: H J.	8005300495*	PT9	ALLRED, D. L.	8009040242	70-2709	ATKINSON, E. V.	8009020323*	50-320 H
ADAM, L. E.	8009220190*	50-289 H	ALMEDA, D C.	B009190024#	QA999	ATTERIDOE, D. Q.	8009020219	50-445 A
ADAMS, D.P.	8009190779	40-4492	ALMEDA, D. C.	8009190017#	QA999	AUSTIN M A.	8007110244	70-135
ADARS, F. T.	8009260482*	TOPREP	ALTERMAN, I. B.	8009190639*	50-133 P	AUSTIN, M A	8009230138	70-364
ADAMS, A	8009030427*	50-255 G	ALTHOUSE, V	B009030480*	50-289 H	AUSTIN M. A	8009090876	70~135
ADLER Y A	8009240535	50-289 Q	ALUKON IB: J	8009050484	50-293 G 70-2909	AUSTIN, M. A. AUSTIN, M. A.	8007180183 8007180196#	70-135 70-135
ADLER T A	8007240538*	50-289 <b>Q</b>	AMOB, H R	8009150411 8009190383*	70-2709 F01A	AUSTIN, M. Á	6009150480	70-135
ADLER: T. A.	8009240538*	50-289 <b>Q</b>	ANDERS, W.A.					
ADLER, T. A	9009300629	50-287 <b>0</b>	ANDERBON, J. O.	B009090656*	50~275 <u>T</u>	AUSTIN: M A.	8009150019	71-6400
ADLER: T. A.	8009300632*	50-289 0	ANDERBON, T. K	8009080294	50-34B P	A .H .HITEUA	8009150553 8009290026#	71~5442 50~327 T
ADLER, T.A.	6009300629	50-289 G	ANDERBON, T. H	B009190453*	TOPREP 50-445 A	AUSTIN, J. H AUTIO, H. A	6007270028	50-29 B
AGEE, J. R.	8009120335*	GA999	ANDERSON, W. E.	8009020219 8009040409	50-445 A TOPREP	AXELRAD, M	6007070826	PR
AQUILERA, N. F.	8009100409*	CONTRACT	ANDERSON: T. M.					
AHEARNE, J. F.	8009180291*	10CFR	ANDERSON, C.	8009110742	50-322 A 50-243 R	AXELROD, D. AXELRAD, M.	9007020500 8007050434	State Prop PR
AHEARNE J F	8007080573	COMMISSION	ANDERBON, T. V	8009300197* 8009160481	50-243 R NUREO	AXELRAD, M	6007050434	PR
AHEARNE, J. F.	8007070330	50-339 P 50-339 P	ANDERSON, D. R. ANDERSON, C. R.	8007070362*	50-244 P	AXELRAD, M	8007140148	50-376 0
AHEARNEIJF AHEARNEIJF.	800707 <b>03</b> 46 800707 <b>033</b> 8	50-337 F	ANDERSON, F.	8007270171*	50~170 F	AXELRAD, H	8009160151+	80-376 9
AHEARNE, J. F	8009020368	COMMISSION	ANDERSON, T M	8009180341	TOPREP	AXELRAD, M	8009160148	50-376 0
AHEARNE, J F	8007070639	COMMISSION	ANDERSON, T. M.	8009220275	NUREQ	AXELRAD, M.	8009160151*	50-376
AHEARNE, J. F	8007110408	COMMISSION	ANDERSON, T. M.	8009190457	TOPREP	AXELRAD, H.	8009300462	50-376
AHEARNE, J. F	8009140644	COMMISSION	ANDERGON, T. H	8009190374*	50-206 P	AYER, J. E.	8009100232	70-1257
AHEARNE, J. F.	8009100073	50-352 U	ANDERSON, T M	0009230685	TOPREP	BACHMANN, R Q.	B007110015	70~130 <del>8</del>
AHEARNE, J. F	8009100078*	50-352 U	ANDOONINI, 0 G	B00909004B#	50-293 9 50-293 8	BACHMANN, R. Q BACHMANN, R. Q.	8009170126 8009170160	70~2909 50~54 9
AHEARNE, J. P	8009100086	COMMISSION	ANDOONINI. Q. C.	8009190076* 8009020110	50-293 Q	BACHHANN, R. Q.	6009300018	70-1308
AHEARNE, J. F	B00910009B	COMMISSION	ANDOONINI.O.C.	8009080546	50-293 0	BACHHANN, R. G.	6009300049	70-1308
AHEARNE, J. F. AHEARNE, J. F.	8009100102* 8009100111	COMMISSION COMMISSION	ANDOONINI. O. C	8007070660	50-293 @	BACKUS, R. A	8009020034	50~443 9
AHEARNE, J. F	8009100114*	COMMISSION	ANDOONINI. C. C.	8009120036	50-293 @	BAER, T. S.	8009260168	71-6058
AREARNE, J. F.	8009100114*	COMMISSION	ANDOONINI, O C	8009160516	50-293 Q	BAER, D. K.	8009020358	NUREO
AREARNE J. F.	8009100122#	COMMISSION	ANDOGNINI, Q. C.	8009160519	90-293 G	BAGAGLIO, M.	8009230219*	80-275 Q
AMEARNE, J. F	8009100124*	COMMISSION	ANDOGNINI. Q. C.	8009190940	50-293 G	BAILEY, R. D.	8009120339	NUREO 50-220 G
AHEARNE, J. F	8009100128*	COMMISSION	ANDOGNINI. G C	8009090034	50-293 G	BAILEY, R J	8009160242*	90-850 M
AHEARNE, J. F.	8009120477	COMMISSION	ANDREWS, C. L	9007070384	50-290 J	BAILEY, E. D.	8009190894 8009100242*	State Prop 50-344 R
AMEARNE, J. F.	8007120480#	COMMISSION	ANDRUS, N. J. ANO, N. P	8009100654 8009240241#	40~4492 50-369 G	Bair, Q. O. Baisden, L.	8007040468	CONTRACT
AHEARNE, J. F	6009120493*	COMMISSION	ANG: H. P.	8007270271#	50-348 G	BAISDEN, L	8007110001	CONTRACT
AHEARNE, J. F	8007120484* 8007120485*	COMMISSION	ANG: W. P.	8007170307#	50-395 G	BAISDEN, L.	8009100034	CONTRACT
ALGEARNE, J. F							8009240073	CONTRACT
AHEARNE, J. F	8009120489*	COMMISSION	ANTHONY: B	8009120494* 8009260558	COMMISSION RES	Baisden, L. Baisden, L.	8007100002	CONTRACT
AMEARNE J. F.	8009150410	COMMISSION	APPELHANS, A D. AREHART, T.	8009290331	50-320 H	BAIBDEN, L.	8009110346	CONTRACT
AHEARNE, J. F	8009300250	COMMISSION 50-327 T	ARMIHO, J S.	8009160436#	TOPREP	BAIBOEN, L.	8009120068	CONTRACT
AMEARNE, J. F. AMEARNE, J. F	8009290023* 8009290021	50-327 T	ARNOLD, R. C.	8009020037	50-320 P	BAISDEN, L.	8009290139	CONTRACT
AMERINE U. F	BUUTATUUEL	## DE( )						

AUTHOR	ACCESSION NUMBER	SUBJ	ECT CORY	AUTHOR	ACCESSION NUMBER	CATEOC		AUTHOR	ACCEBBION NUMBER	SUBJE CATEO	
BAKER, K. R. BAKER, K. R. BAKER, K. R. BAKER, C. E. BALL, B. J.	80092604204 80091001404 80092904364 8009300409 8009100953	50-25	5 G 5 G 81	Bayne; J. P Bayne; J. P Bayne; J. P Bayne; J. P. Bayne; J. P	8009220379 8009040420 8009050273 8009120362 8009130254	50-284 50-286 50-286 50-333 50-286	д Р Р	BISHOP,C J BISHOP,C J BISHOP,C J BISHOTT,P H BISHETT,P H	8009260469 8009290043 8009260445 8009160186* 8009150358*	50~275 50~387 50~409 70~135 70~135	000
BALLARD, R.L. BALLENTINE, J.M. BALLENTINE, J.M. BALLINGER, P.L. BALOUGH, R.C.	9009150064* 9009170262* 9009170261 9009160264* 9009160332	50-32 50-32	7 R 7 R 8 R	BAYNE, J. P BAYNE, J. P BAYNE, J. P. BAYNE, J. P. BAYNE, J. P.	8009170325 8009180384 8009230451 8009260442 8009260446	50-286 50-286 50-247 50-286 50-333	6 6 6	BITNER,J L BIXLER,Q BIXLER,E BJORKLUND,P,P BJORNARD,T A	9007020017# 9007020314# 9007220346 9007020174 9007260504#	50~337 50~320 50~320 50~320 TOPREP	ሉ ዘ ያ ዝ
Balter, J Bandazza, J. B Bandorth, C. B. Barl, R. A Barker, N. R	8009050370 80092305914 80092200374 80082106184 80091502284	50-32	9 P 9 H 7 P	BEACH, A B BEACH, A B BEACH, A. B, BEARD, E P BEATTY, D,	8009150357* 8009250398* 8009150362* 8009110267 8009220128*	50-458 50-458 50-459 70-820 MIBG	G G	BLACK,R L. BLACK,R L BLAKE,J J BLAKE,E.L. BLAKE,E.L.	8009110014 8009300012 8009240374* 8009110020 8009300011	50~466 50~466 50~324 50~289 50~289	00000
Barker, N.R. Barker, J.L. Barker, N.R Barker, D.Q Barker, J.L.	8009150226# 8009100148# 8009150223# 8009180473 8009260404#	GA999 50-10 GA999 50-498 50-10	B 9	Beghhoefer, C. Bechhoefer, C Bechhoefer, C. Bechhoefer, C Beck, O.P.	8009220413 8009250012 8009250001 8009300030 8009150456	50-358 50-409 50-409 50-498 50-356	0 0 0 R	BLEVINS, C N. BLOND, R. M. BLOSSOM, J. N BLUMBERG, N. BLUMBERG, N. J.	8009160543 8009120626 8009030462 8009100399* 80091103( )*	WASTE M 50-247 40-8452 50-334 50-333	ខ្
Barley.r. Barneg.i. Barneg.i. Barr.d.w Barrack.t.	8007250414# 8007170031# 8007170158# 8007300286# 8007170046	50-289 GA777 GA777 40-279 50-250	7	Beckman, D. A. Becksted, W F Beeole, C. W Beers, F. C Beers, F. C.	8009110050* 8009120699 8009110361 8009160301* 8009160259*	50-334 PT21 FOIA 50-271 50-309	Q R R	BLUME, J A BLUME, M B. BOBLINGER, L, H. BODTKE, P. J. BOODEN, O	8009020100* 8009090339 8009090537* 8009120462* 8009260041	50~206 50~348 50~458 50~255 40~1162	P H F R
BARRETT, P. A BARRY, L. M. BARRY, C. B. BARRY, D. BARTH, C. A	8007110661* 8007030455* 8007030678* 8007220240 8007020445	50-356 F01A XPORTU RM 50-356	.IC	BEERS.F.C. Belible,Q A Belible,Q.A Bell.D.A. Benda,B.J.	8007160303* 8007030441* 8007120071* 8007250456* 8007120338	50-29 50-290 50-348 50-341 NUREO	R G G A	Booden, Q Booden, Q Booden, Q Bohn, R. J Bohn, R. J	8009180419 8009150550 8009300141 8009020005 8009020051	40~1162 40~1162 40~1162 50~367 50~367	
BARTH, C. A. BARTH, C. A BARTH, C. BARTH, C. A BARTH, C. A	8009110023 8009160176 8009300039 8009260251 8009300007	50-282 50-488 50-282 50-488 50-237	9 9	BENDER, B. BENDER, B. B. BENEDICT, D. E. BENNETT, T. J. BENNETT, B. L.	8009290398* 8009290401* 8009020431 8009020483 8009300197*	50-382 50-382 50-30 NUREG 50-243	8 W R	BOHM, R. J. BOHM, R. J. BOHM, R. J. BOHM, R. J. BOHM, R. J	8009090429 80090904489 8009150474 8009250297 8009300446	50-367 50-367 50-367 50-367 50-367	A A A R R
Bartlett, J. Baskin, K. P. Baskin, K. P. Baskin, K. P. Baskin, K. P.	9009180268 9009160626 9008270278 9009020063 9009020082	50-220 50-361 50-361 50-206 50-206	G F P	BENNETT, R. C. BERGER, D BERGGUIST, R G. BERKLEY, J. BERMAN, M.	8009150168 8009020050 8009260018 8009170332 8009190743	50-324 50-266 50-440 50-352 NUREO	8 U 8 F	BOHN, R. J. BOLON, A E BONZON, L. L. BOODY, F. P. BOOK, H E	8007300417 8007240641 8007170378 8007170614* 8007080566*	50-367 50-201 NUREQ 70-258 50-298	A O
Baskin, K. P. Baskin, K. P. Baskin, K. P. Baskin, K. P Baskin, K. P	8009020006 8009300017 8009030387 8009080343 8009090463	50~361 50~361 50~206 50~206 50~206	Q F P	BERMAN, M. BERNERO, R. M. BERNREUTER, D. L. BERNREUTER, D. L. BERNRETEN, D. L.	8009260669 8009120626 8009180434 8009180446 8009100429	NUREO 50-247 NUREO NUREO 50-282	P O	800K, H. E. 800K, H. E. 800K, H. E. 800K, H. E. 800K, H. E	8007080569# 800702054 8007020261# 8007240407 8007240533#	50-298 70-734 70-734 50-147 50-147	0 0 0
Baskin, K. P Baskin, K. P Baskin, K. P. Baskin, K. P Baskin, K. P	8007170361 8007070352 8007050382 8007160230 8007160230	50-206 50-206 50-206 50-361 50-206	P	Bernstein, D.L. Berry, O.T. Beshear, G.L. Bettenhausen, L. Bevill, T.	8007100427 8007120376 8007100575 8007100861* 8007120474*	50-282 50-264 50-358 50-277 COMMISSI	G G	800K, H, E 800K, H, E 800K, H, E, 800K, H, E 800K, H, E	8007020237* 8007020235 8007270131* 8007200324* 8007300318*	70-984 70-984 50-254 50-344 50-344	000
Baskin, K. P. Baskin, K. P. Baskin, K. P. Baskin, K. P. Baskin, K. P.	8009080322 8009180421 8009190402 8009170336 8009290348	50-206 50-361 50-206 50-206 50-206	<u>የ</u> የ የ	BEYER, J M BEZLER, P. BIALIK, E. I. BIALIK, E. I. BIALIK, E. I	8007050498# 8007240686 8007050427 8007300525 8007300525	50-320 NUREG PR 50-201 50-564	H H	BOOK, H. E. BOOK, H. E. BOOKB, P. A BOOKB, P. A BORDAN, A. J.	8009120214 8009300162 8009300312 8009180381 8009090537*	1&E 1&E 50-344 50-320 50-458	о Н Е
Baskin, K. P. Baskin, K. P. Bassin, K. P. Bassin, N. Bateman, N. H.	8009300377 8009300362 8009300448 80090805664 8009190223*	50-206 50-206 50-298 50-298 50-354	P P G G	BIALIK,E.I BICKHIT,L. BIELAWSKI,A BIELAWSKI,A P BIELAWSKI,A,P.	8007300525 8007080261+ 8007080256 8007070233 8007070233	70~1432 FOIA FOIA 50~559 50~599	0 0	BORDENICK, B. M BORDENICK, B. M. BORDENICK, B. M. BORDENICK, B. M. BORDENICK, B. M.	8009020411 8009040248 8009040261 8009170231 8009250003	50-322 50-322 50-448 50-322 50-322	0000
BATEKAN, W. H BAUER, E. G. BAUM, E. A BAUM, E. A	8009150190# 8009180316# 8009030184 8009120451# 8009090274	50-354 50-277 50-280 50-133 50-280	9 F R F	Bieniarz, P. P. Bierman, S. R Bigiarelli, M. J Birkel, R. A Birkel, R. A.	8009260669 8009100413 8009020383* 8009030069 8009300043	NUREQ NUREQ 50-245 50-349 50-389	8 A A	BORDENICK, B. M BORDENICK, B. M BORES, R. J. BORES, R. J. BORES, R. J.	8009250020 8009300001 8009190056# 8009150124# 8009150137#	50-498 50-322 50-352 50-219 50-271	0000
BAUMIE, A. BAUMACK, W BAUBER, M. A. BAXLEY, B. X. BAXLEY, B. X.	8007160429 80091003999 8009230644 8009020469# 8009150283#	50-338 50-334 PR 50-321 50-321	P Q 8 8	Birkel, R. A. Birkel, R. A Birkel, R. Biscoff, C. A. Biscoff, C. A	8009300644 8009300667 8009290175 8009030714 8009030714	50-249 50-389 50-347 50-528 50-528	A F Q O	BOROMANN, E.A. BOROMANN, E.A. BOROMANN, E.A. BOROMANN, E.A. BOROMANN, E.A.	8007300126* 800725027* 8007270460* 8007030588 8007170422	FOIA 50-358 50-358 50-358 50-358	0 0 F
BAXTER, T. A.	8009090784 8009090788* 8009090784 8009090788* 8009090570	50-312 50-312 50-312 50-312 50-483	0000	BISHOP, T W BISHOP, T W. BISHOP, C, J. BISHOP, C, J. BISHOP, C, J.	8009150378# 8009040482# 8009030112 8009050432 8009050437	50-397 50-275 50-367	9	Boromann, e. A. Boromann, e. A Bosnak, r. J. Bossenmaier, W. Boswell, J., M	8009170429 8009260137 8009180506 8009260472 8009120540	50-358 50-358 50-312 50-312 RECOD	0 9 8
BAXTER, T. A. BAYNARD, P. Y. BAYNARD, P. P. BAYNARD, P. Y. BAYNARD, P. Y.	9009300570 9009190786 9009030206# 9009030230 8009090442	50-483 50-302 50-302 50-302 50-302	0 0 R F P	BISHOP, C. J. BISHOP, C. J. BISHOP, C. J. BISHOP, C. J. BISHOP, C. J.	8007080518 8007070375 8007120403 8007160438 8007160525	50-263 50-219 50-263 50-155	00000	BOSWORTH, O. R BOWKNIGHT, J. A. BOWKNIGHT, J. A BOWKNIGHT, J. A. BOWKNIGHT, J. A.	9009300289 9009160033 9009160041* 8009160033 8009160041*	FOIA 50-389 50-389 50-389 50-389	н н н
BAYNARD, P. Y. BAYNARD, P. Y. BAYNARD, P. Y. BAYNARD, P. Y. 'AYNARD, P. Y.	900707078 9007300143 9007170288 9007180285 9007220361	50-302 50-302 50-302 50-302 50-302	P Q P F R	BISHOP, C. J. BISHOP, C. J. BISHOP, C. J. BISHOP, C. J. BISHOP, C. J	8009170116 8009180537 8009190189 8009190419 8009280032	50-488 50-488 50-344 50-367	0000	Bouknight, J. A Bouknight, J. A. Bouknight, J. A. Bouknight, J. A. Bournia, A.	9009170232* 9009170235* 9009300476 9009300476 9009110420	50-445 50-445 50-450 50-250 50-273	H H H

AUTHOR	ACCESSION NUMBER	GUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY
BOURNIA, A BOURNIA, A. BOURNIA, A. BOWERS, C. E. BOWERS, C. E.	8009150016 8009110715 8009180540 8009180527 8009110221	50-438 A 50-373 A 50-373 A 70-820 70-820	BROWN, W F BROWN, O D BROWN, W F BROWN, O BROWN, O	8009030674 8009100205* 8009160209 8009180093*	PR 40-6457 PRM 40-8594 40-1162	BUDNITZ,R J BUDNITZ,R J BUDNITZ,R J BULLINOTON,R L BURCHETTE,W H	8009190205* 8009040459 8009150543 8009120662* 8009170361	MISC SECY RES CONTRACT 50-445 G
BOMERBIC E	8007110235	70-820	BROWN, W. K	8009050214*	71-9508	BURCHETTE, W H BURCHETTE, W H BURDETTE, T E BURGEN, R. E BURGER, A C	8009170232*	50-445 M
BOMERBIC. E	8007170005*	70-820	BROWNLEE, V L	8009150304*	50-438 G		6009170364*	50-445 M
BOMERBIC. E	8007110252*	70-820	BROWNLEE, V L	8009020337*	50-327 G		8009110427*	50-413 G
BOMERBIC. E.	8007110230	70-820	BROWN, H H	8009190629	FOIA		8009290059*	Foia
BOMYERIJ. E	8007270085*	FOIA	BROWN, G. D	8009180027	40-2259		8009150355*	50-320 H
BDYD, A. B. BDYD, D. C. BDYD, D. C. BDYER, V. G BDYER, V. G.	8007150044* 8007050214* 8007300224* 8007300367 8007270380*	50-271 U 50-255 G 50-255 G 50-277 P 50-352 B	Brown, G. D Brown, G Brown, G Brown, G Brown, G D	8007180087 8007180193 8007180033* 8007180081* 8007180072	40-9594 40-1162 40-2259 40-9452 40-8452	BURGEES, B L BURGER, F J BURKE, D. J BURKE, D. J BURKHARDT, W	8009260271* 8009160301* 8009240713* 8009020220* 8009100232	50-282 9 50-271 R 50-280 9 50-280 9 70-1257
BRADHURY, V. A	8009110382	50-275 H	BROWN, O. D.	8007240729*	40-299	BURMASTER, M	8009230004*	50-409 Q
BRADFORD, P. A.	8009180298*	10CFR	BROWN, O. D.	8007240721	40-299	BURNETT, R, F	8009120170	70-33
BRADFORD, W. H.	8009110202*	50-348 G	BROWNEHELL, R. P	8007170317*	50-320 P	BURNETT, R F	8009150524	70-364
BRADFORD, P. A.	8009270021	50-327 T	BROWN, O. D.	8007080472	40-3453	BURNE, B Q	8009030134	50-409 Q
BRADLEY, B.	8009020191*	50-219 H	BROWN, M. E.	8007180064*	GA999	BURNE, B Q	8009110017	50-255 Q
RRADCEY, J.P.	8007030440*	50-295 P	BROWN, J. F	8009160488*	CDNTRACT	Burrell, A	8007260646*	50-201
BRADCEY, E. J.	8007150478	50-277 F	BROWN, B. C.	8009020235	50-404 Q	Burrib, L	8007300540	
BRADCEY, E. J	8007180304	50-277 P	BROWN, B. C.	8009020399	50-404 Q	Burstein, S	8007020477	
BRADCEY, E. J	8007180316*	50-277 P	BROWN, B. C.	8009020416	50-404 Q	Burstein, S	8007030542	
BRADCEY, E. J.	8007270378	50-352 B	BROWN, B. C.	8009230087	50-404 G	Burstein, S	8007160442	
PRADSHAW, J.L.	8007070343#	50-337 U	BROWN, P	8009120444	50-206 H	BURSTEIN, B	8009300305	50-246 Q
Brady, R.W.	8007230777#	CONTRACT	BROWN, B.	8009160276*	50-254 R	BURSTEIN, B	8009250249	50-266 P
Braile, L.W	8007120570	RES	BROWN, C. F.	8009100590	PR	BURSTEIN, B	8009290177	50-266 F
Bramlett, L.S.	8007090568#	50-313 S	BROWN, R. H	8009110019	50-275 Q	BURSTEIN, B	8009290341	50-266 P
Bramlett, E.S	8007230700#	50-313 R	BROWN, R. H	8009110019	50-275 Q	BURTSAVAGE, E M	8009190732	REGOD
DRAMETT, E. B. DRAND, W. E.	8009230715#	90-913 B	BROWN, W J	8009100444	PR	BURWEELL S. B	8009100004	50-445 A
	8009020468#	50-995 M	BROWN, H. H	8009150404	50-275 G	BUSCH, R. W.	8009180528	50-522 G
	8009150312#	50-995 M	BROWN, H H	8009150404	50-275 G	BUSH, L. L	8009300190	1&E
	8009160337	90-995 G	BROWN, H H.	8009220405	50-275 G	BUTLER, W. A	8009240070#	FOIA
	8009150307	50-995 M	BROWN, O F	8009190529	PR	BYENGTON, J. H	8009230499	50-412 I
BRAULKE, O R	8009260396#	50-287 T	BROWN, H H	8009230616	50-275 Q	BYRD:P K	8009230475*	TOPREP
BRAY, T. C.	8009020356#	50-297 R	BROWN, H H	8009230616	50-275 Q	CADENA:D O	8009150174	REGOD
BRAITLL, O J	8009260396#	50-289 T	BROWN, D F.	8009240563	PR	CADWELL:J	8009110416	RES
BREED, A.	8009030557	TOPREP	BRUGGER, R M	8009040406	50-186 B	CADWELL:J.J	8009090770	RES
BRENNAN, J. E	8009170345	50-309 F	BRUGGER, R M	8009040418	50-186 8	CAHN:A L.	8009190672	NUREG
BRICKLEY, R. H	8009120335#	GA797	BRUQGER,R.H	8009190594	71-5088	CAIN.C L	8009100199*	40-6657
BRICKLEY, R. H	8009120657#	GA797	BRUGGER,R.H	8009230586	50-186 P	CAIN.C L	8009080487*	40-3453
BRICKLY, R. H.	8009290101#	50-346 G	BRUNNER,E J	8009100392*	50-334 Q	CALDWELL.R A	8009170176*	50-313 0
BRIDENBAUCH, D.	8009160284#	PR	BRUNNER,E J	8009110301*	50-333 Q	CALDWELL.R A	8009170183*	50-382 G
BRIEMHURBY, L. J.	8009030728#	50-202 G	BRUNNER,E J	8009190078*	50-273 Q	CALDWELL.H A	8009110387	50-327 H
BRIGOS, L.	8007110663	50-272 8	BRUNNER, E J.	8007070244*	50-287 Q	CALHOUN, J R	8009030367	50-327 8
BRIGHT, R. M.	8007100733	50-302 0	BRUNNER, E J.	8007120175	50-247 Q		8009030317	50-327 8
BRINKLER, J. E.	8007260642*	50-309 8	BRUNNER, E. J.	8007150082	50-245 Q		8009030488	50-259 8
BRINKLER, J E	8007260503*	50-309 8	BRUNNER, E J	8007150137*	50-271 Q		8009030597	50-296 8
BRISCOE, Q. A	8007230202*	50-289 H	BRUNNER, E J	8007160227*	50-277 Q		8009090547	50-327 8
BROCKETT, T. W	8008210619	1&E	BRUNNER, E J	8009100847	50-247 @	CALHOUN, J R,	8007080354	50-327 8
BROCKETT, T. W.	8009040591	50-333 8	BRUNNER, E. J	8009180001	50-334 @	CALHOUN, J R	8007080360	50-327 8
BROCKETT, T. W.	8009020510	50-286 8	BRUNNER, E J	8009100874	50-293 @	CALHOUN, J, R	8007080373	50-327 8
BROCKETT, T. W.	8009190418	1&E	BRUNNER, E J	8009150159	50-322 @	CALHOUN, J R	8007070467	50-240 8
BROCKETT, T. W.	8009190565	50-255 8	BRUNNER, E J	8009150180	50-277 @	CALHOUN, J R	8007030558	50-259 8
BROCKETT, T. W.	8009300048	I&E	BRUNNER, E J.	8009110663	50-272 S	CALHOUN, J R	8007080382	50-327 8
BROCKETT, T.	8009300144	I&E	BRUNNER, E J	8009100837	50-277 G	CALHOUN, J R	8007070327	50-327 8
BROEHL, D. J.	8009020039	50-344 P	BRUNNER, E. J	8009110047	50-334 G	CALHOUN, J R	8007070531	50-327 8
BROEHL, D. J.	8009100449	50-344 B	BRUNNER, E J	8009110509	50-217 G	CALHOUN, J R	8007070314	50-296 8
BROHBERG, B.	8009230354	Contract	BRUNNER, E J	8009090237	50-287 G	CALHOUN, J R	8007070445	50-260 8
BROMBERG, B. BROMBERG, B. BROMBERG, B. BROMBERG, B. BROMB, E. H	8009230364 8009120010 8009120023 8009260232 8009130115*	CONTRACT CONTRACT CONTRACT CONTRACT 50-302 Q	BRUNNER, E. J BRUNNER, E. J BRUNNER, E. J BRUNNER, E. J BRUNNER, E. J	8007100384 8009150430 8009190073 8009020501 8009190575	50-334	CALHOUN, J. R.	9007070557 8007120411 8007120412 8007140325 8007140375	50-259 B 50-327 B 50-327 B 50-327 S 50-327 S
BROOKS, R. BROOKS IELD, N S. BROUGHTON, T. O. BROUGHTON, T. O. BROUGHTON, T. O.	8009190046	50-250 9	BRUNNER, J E.	8009190420	50-329 0	CALHOUN, J. R	8007070332	50-296 8
	8009110288*	50-320 H	BRUNNER, E. J	8009300600	50-309 8	GALHOUN, J. R	8007070470	50-260 8
	8009260322*	50-289 T	BRUSH, P N.	8009120605	XPORTLIC	CALHOUN, J. R	8007160416	50-296 8
	8009260411*	50-287 T	BRYANT, W H	8009120413*	50-220 V	CALHOUN, J. R	8007160421	50-327 8
	8009260439*	50-287 T	BRYANT, W H	8009120417*	50-220 V	CALHOUN, J. R	8007160432	50-260 8
BROWN, F. R. BROWN, H. BROWN, K. H. BROWN I NO, M BROWNR YOO, D. L.	8007180237* 8007170286* 8007260417* 8007270156* 8007080335*	50-546 0 50-320 H 70-1167 FOIA 50-133 R	BRYAN, J. K. BRYANT, J. C BRYAN, J. K. BRYAN, J. K. BRYAN, J. K.	8009100080* 8009180457* 8009090546 8009230451 8009230462	50-400 Q 50-483 B 50-483 B 50-483 K	CALHOUN, J. R CALHOUN, J. R. CALHOUN, J. R. CALHOUN, J. R. CALHOUN, J. R.	8009160454 8009160390 8009160406 8009160463 8009190471	50-260 S 50-327 B 50-327 S 50-327 S 50-327 S
BROWN, Q. D.	8007080552*	50-278 G	BRYAN, J.K.	8009300447	NUREO	CALHOUN, J. R	8009190440	50-260 8
BROWN, Q. D.	8007080557	50-278 G	BRYAN, B.E.	8009260260	30-255 &	CALHOUN, J. R	8009190465	50-259 8
BROWN, Q. D.	8007100179*	40-6657	BUCCHOLZ, R. H.	8009050325	Toprep	CALHOUN, J. R	8009190467	50-259 8
BROWN, R. L.	8007150021*	GA777	BUCHHOLZ, R. H.	8009230472	Toprep	CALHOUN, J. R	8009190540	50-327 8
BROWNR I QQ, D. L.	8007080336*	50-133 R	BUCHHOLZ, R. H.	8009230430	Toprep	CALHOUN, J. R.	8009230706	50-259 B
BROWN, R. A.	9007040068*	27-39	BUCHHOLZ, R. H	8009230308	TOPREP	CALHOUN, J R	9009230716	50-259 8
BROWN, Q. D.	80007080487*	40-3453	BUCHHOLZ, R. H.	8009230308	TOPREP	CALHOUN, J R	8009230597	50-327 8
BROWN, Q. D.	80007080475*	40-3453	BUCHOLZ, J. A	8009110372	NUREO	CALHOUN, J, R	8009230674	50-296 8
BROWN, R. L.	8000170159*	9A999	BUCHOLZ, J. A	8009160202	NUREO	CALHOUN, J, R	8009230669	50-296 8
BROWN, EE, V. L.	8000110427*	50-413 g	BUDNITZ, R. J	8009040461	BECY	CALHOUN, J P.	8009230730	50-327 8

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCE8SION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESE I ON NUMBER	SUBJECT CATEGORY
CALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R	8009270345 8009300562 8009300567* 8009300451 8009300514	50-259 B 50-259 B 50-259 B 50-327 B 50-259 B	CARTHRIGHT. H R	8007030617* 8007030627 8007030632* 8007030642 8007030647*	50-337 8 50-338 8 50-338 8 50-338 8 50-338 8	CHANANIA,F D GHANANIA,F D GHANANIA,F D GHANANIA,F D GHANANIA,F D	8009030721 8009040289 8009170232* 8009170239* 8009170364*	50-445 K 50-445 K 50-445 K 50-445 K
CALHOUN.JR	8009300544	50-294 8	CARTHRIGHT, W.R.	8009030653	50-338 8	CHANANIA,F D	8009170229	50~445 K
CALHOUN.JR	8009300548	50-260 8	CARTHRIGHT, W.R.	8009030658*	50-338 8	GHANANIA,F D	8009160160*	50~445 H
CALKING.OD	8009110639	NUREO	CARTHRIGHT, W.R.	8009030612	50-338 8	GHANDLER,L J	8009090774	50~361 Q
CALLAN.LJ	8009180481*	50-313 G	CARTHRIGHT, W.R.	8009030623*	50-338 8	CHANDLER,L J	8009100448	50~361 H
CAHERON.CA	8009300477	TOPREP	CARTHRIGHT, W.R.	8009050335*	50-338 R	CHAPLIN,8 D	8009020387*	50~320 B
CAMPBELL, M CAMPBELL, J E CAMPBELL, D O CAMPBELL, D O CANADY, K S	8007270064* 8007020347 8007020080* 8007030334* 800703087*	FOIA NUREG 50-320 P 50-320 P 50-369 G	CARTWRIGHT, W R	8007070477 8007070512* 8007070538 8007070541 8007070584*	50-338 8 50-338 8 50-339 8 50-338 8 50-339 8	CHAPLIN, B. D CHAPLIN, B D CHAPLIN, B D CHAPLIN, B D CHAPLIN, B D	8007030361# 8007120406# 8009180426# 8009120452# 8009180408#	50-320 B 50-320 B 50-320 B 50-320 B 50-320 B
CANNON, J M CANNON, J M CANTER, H L CANTER, H L CANTRELL, F B	8009090331 8009090331 8009170244# 8009120490# 8009030040#	27-39 27-39 50-312 P 50-312 G 50-390 G	CARTHRIGHT, H. R CARTHRIGHT, H. R CARTHRIGHT, H. R CARTHRIGHT, H. R CARTHRIGHT, H. R	8009090586* 8009180412 8009180417* 8009220239 8009220241	50-338 8 50-339 8 50-339 8 50-339 8	CHAPMAN, K. R. CHAPMAN, K. R. CHAPMAN, K. R. CHAPMAN, K. R. CHAPMAN, K. R.	8009230141* 8009230170* 8009230195* 8009230272* 8009230283*	FOIA FOIA FOIA FOIA
CANTRELL, F S	8007070257*	50-553 G	CARTWRIGHT, W R	B007220243	50-338 8	CHAPMAN, R. H	8009050409	RES
CANTRELL, F S	8007110177*	50-516 G	CARTWRIGHT, W R	B007220251	50-338 8	CHAPMAN, L., D	8009020361	NUREO
CANTRELL, F S	8007250114*	50-566 G	CARTWRIGHT, W R	B007220306*	50-338 8	CHAPMAN, L. D,	8009090132	RES
CAPAWANA, S	8007270447	FDIA	CARTWRIGHT, W R.	B007220319*	50-339 8	CHAPMAN, R. H	8009100954	NUREO
CAPHTON, D L	8007170081*	50-293 G	CARTWRIGHT, W R.	B007220324*	50-339 8	CHARNOFF, O	8009300570	50-480 O
CAPHTON, D. L.	8009150184*	50-277	CARTWRIGHT, H R	8007220355	50-339 B	Charnoff, o	8009300570	50~483 0
CAPHTON, D. L.	8009100861*		CARTWRIGHT, H R	8007220360*	50-339 B	Chase, J. W	8009300081*	50~259 0
CAPHTON, D. L.	8009110518*		CARTWRIGHT, H R	8007220367	50-338 B	Chase, o	8009150167	REQQD
CAPPUCCI, A. J.	8009150018*		CARTWRIGHT, H R	8007220373*	50-338 B	Chaudhary, s K.	8009090232*	50~352 0
CARDONA, T. M.	8009180944		CARTWRIGHT, H R	8007230589	50-339 B	Chaudhary, s	8009100899*	50~207 0
CAREY, J. J	8009090412*	50-334 P	CARTHRIGHT, H R	8009230600*	50-337 8	CHAUDHARY, 8 K	8009050533#	50-478 0
CARLEON, R. T	8009190100*	50-443 Q	CARTHRIGHT, H R	8009230554	50-337 8	CHECK, P S	8009050029	50-250 P
CARLEON, R. T	8009190277*	50-387 Q	CARTHRIGHT, H R	8009230577*	50-339 8	CHECK, P S	8009050032	60-275 P
CARLEON, R. T	8009190254*	50-387 Q	CARTHRIGHT, H R	8009230605	50-338 8	CHECK, P S	8009050033	50-27 P
CARLEON, R. T	8009090229*	50-352 Q	CARTHRIGHT, H R	8009230615*	50-338 8	CHECK, P, S	8009050343	50-267 P
CARLSON, R T	8009090058*	50-293 Q	CARTHRIGHT, N R	6009230622	50-338 8	CHECK, P 8.	8007050026	50-338 8
CARLSON, R T	8009190214*	50-354 Q	CARTHRIGHT, N, R,	8009230636*	50-338 8	CHERBA, R B.	8007030627*	50-255 9
CARLSON, R T	8009100025*	50-352 Q	CARY, C, N	6009160198	NUREO	CHERN, W B	8007120733	RES
CARLSON, R T	8009050482	50-410 Q	CASE, E Q	6009030501*	50-266 P	CHESTER, R D	8007110478	RES
CARLSON, R T	8009250299	50-387 Q	CASE, E, Q	8009040299	50-266 P	CHIANGI, N J	8007100465	50-400 8
CARLEON, R T	8009190231	50-387 Q	Casey. B. B.	6007170083	50-361	CHIANGI, N. J	8007080254	50-400 B
CARLEON, J D	8009020240*	50-397 Q	Cabey. S. B.	8007170083		CHILDB, N. V.	8007030414*	50-333 B
CARLEON, R T	8009150092	50-410 Q	Cashiell. R. J.	8007040397		CHILDB, N. V	8007030423*	50-333 B
CARLEON, R T	8009100881	50-352 Q	Catchpole. G. J.	8007050362		CHILDB, N. V.	8007020357*	50-333 B
CARLEON, R. T	8009100889	50-387 Q	Catchpole. G. J.	8007150552		CHILDB, N. V	8007020403*	50-333 B
CARLEON, R. T. CARLEON, R. T. CARLEON, R. T. CARLEON, R. T. CARLEON, R. T.	8009100895 8009240259 8009100865 8009150187 8009090041	50-287 Q 50-317 G 50-412 G 50-354 G 50-273 G	CATCHPOLE, Q J CATCHPOLE, Q J CATCHPOLE, Q J CATCHPOLE, Q J, CATCHPOLE, O J,	8007300202 8007030476 8007030455 8007030385 8007140383	40-8745 40-8745 40-8673 40-8745 40-8745	CHILDS, W V CHILDS, W V CHILDS, W V CHILDS, W V	8007020422* 8007070361* 8007120415* 8007120365* 80071607449*	50-333 8 50-333 8 50-333 8 50-333 8
CARLBON, R. T	9009090450	50-387 8	CATCHPOLE, O J	8009160462	40-8745	CHILDS, W V.	8007160476*	50-333 B
CARLBON, R. T	9009110401	50-387 9	CATCHPOLE, O J	8009160386	40-8745	CHILES, L.	8007020375*	COMMIBBION
CARLBON, R. T	8009120120	50-322 8	CATCHPOLE, O J	8009160330	40-8745	CHILK, B. J	8007170326*	FOIA
CARLBON, R. T	8009120128	50-387 8	CATCHPOLE, O J	8009160331*	40-8745	CHILK, B. J,	8007230156*	FOIA
CARLBON, R. T	8009120711	50-387 8	CATCHPOLE, O, J,	8009160333*	40-8745	CHILK, B. J	8007230157*	FOIA
CARLSON, R Y CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T	8009190247 8009120704 8009090222 8009100022 8009150193	50-387 G 50-387 B 50-352 G 50-352 G 50-492 B	CATCHPOLE, Q, J CATCHPOLE, Q J CATCHPOLE, Q J CATCHPOLE, Q J CATCHPOLE, Q J	8009160334* 8009160346* 8009160345* 8009160350*	40-8745 40-8745 40-8745 40-8745 40-8745	CHILK, S J CHILK, S J, CHILK, B, J, CHILK, B, J, CHILK, B J	8009230164* 8009190470* 8009190557* 8009180284* 8009030150*	FOIA FOIA FOIA 100FR 50-40Y Q
CARLSON, R. T.	8007170203	50-354 Q	CATCHPOLE, Q J,	8009160354*	40-8745	CHILK, S. J	8007030077*	LOCFR
CARLSON, R. T.	8007170244	50-387 Q	CATCHPOLE, Q J,	8009160357*	40-8745	CHILK, S. J	8007030074	LOCFR
CARLSON, R. T.	8007170087	50-443 Q	CATCHPOLE, Q J,	8009160357*	40-8745	CHILK, S. J.	8007030082	DRO
CARLSON, R. T.	8007070837	50-410 S	CATCHPOLE, Q J	8009190389	40-8745	CHILK, S. J.	8007030093	LOCFR
CARLSON, R. T.	8007070844	50-410 S	CATCHPOLE, Q, J,	8009190392	40-8745	CHILK, S. J.	8007100632	MIBC
CARLSON, R T	8009150037	50-354 8	CATCHPOLE, Q. J. CATCHPOLE, Q. J. CATTON, I. CATTON, I. CAVANAUGH, W	8009220332	40-8745	Chilk, S. J.	9009190241	ACRS
CARLSON, R, T,	8009220325	50-423 8		8009300457	40-8745	Chilk, S. J	8009150449	ACRS
CARPENTER, M	8009020178*	50-320 H		8009230113	ACRB	Chilk, S. J.	8009160509	ACRS
CARPENTER, K	8009150164*	40-8743		8009240028	NUREQ	Chilk, S. J.	8009100917	ACRS
CARPENTER, T O	8009230771*	CONTRACT		8009170241	50-313 V	Chilk, S. J.	8009080046*	PR
CARR. J. C	8009300136#	FDIA	CAVANAUGH, H	8009150287	50-368 P	CHILK, B. J.	8007080036	PR
CARR. E. H	8009110500	NUREO	CAVANAUGH, H	8009090482	50-313 P	CHILK, B. J.	8007020527	REOOD
CAHROLL. D	8009180370	50-287 I	CAVANAUGH, H	8009180424	50-368 P	CHILK, B. J.	8007020544	PR
CARTER, R. S.	8009100504	50-184 F	CAVANAUGH, H	8009260453	50-368 P	CHILK, B. J.	8007030052	NUAEO
CARTHRIGHT, H. R	8009030555	50-338 8	CAVANAUGH, H	8009300242	50-368 P	CHILK, B. J.	8007030061	REOOD
CARTHRIGHT, H. R.	8007030561*	50-338 8	CAVE,L	8007240603	NUREO	CHILK, B. J.	8007030667	NUREO
CARTHRIGHT, H. R	8007030567	50-339 8	CAYOT,R F.	8007080333*	50-199 R	CHILK, B. J	8007240564*	50-327 P
CARTHRIGHT, H. R	8007030571*	50-339 8	CAYOT,R F	8007080334*	50-199 R	CHILK, B. J.	8007030648	ACRE
CARTHRIGHT, H. R.	8007030576	50-339 8	CERNE,A C	8007170104*	50-449 G	CHILK, B. J.	8007250462	TOPREP
CARTHRIGHT, H. R.	8007030586*	50-339 9	CHADMELL,H,M	8007070508*	50-915 B	CHILK, B. J.	8007020417	50-309 Q
CARTWRIGHT, W. R.	8007030593	50-339 8	CHADHELL, H. M	8009110348#	50-315 8	CHILK, 8. J	8009040263	50~344 Q
CARTWRIGHT, W. R.	8007030606	50-338 8	CHADHELL, H. M	8009150328#	50-315 8	CHILK, 8. J	8009040355	50~369 Q
CARTWRIGHT, W. R.	8007030608*	50-339 8	CHAFFEE, A. E.	8009120478#	50-324 G	CHILK, 8. J	8009090406	50~458 Q
'ARTWRIGHT, W. R.	8007030614*	50-339 8	CHAN, C. K	8009260028	NUREG	CHILK, 8. J,	8009160347*	50~369 Q
ARTWRIGHT, W. R.	8007030615	50-339 8	CHANANIA, F. D	8009020459	50-375 M	CHILK, 8. J,	8009120244	50~344 Q

AUTHOR	ACCEBBION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESS I ON NUMBER	SUBJECT CATEOURY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CHIEKIB J CHILKIB J CHELKIB J CHELKIB J CHILKIB J	B009120394 B009120398 B009160142 B009160522 B009180546	50-3 Q 50-443 Q 50-599 Q 50-409 Q 50-389 Q	CLAYTON, F L CLAYTON, E, D CLAYTON, F L CLAYTON, F L CLAYTON, F L	8009110258 8009100413 8009050052 8009020291 8009190583*	50-348 Q NUREO 50-348 Q 50-348 Q 50-348 Q	COHN. D D COHN. D H COLE. R F COLEMAN. R COLEMAN. R	8009030149 8009030152* 8009300439 8009100405 8009250258	50-367 0 50-367 0 50-376 0 CONTRACT CONTRACT
CHILK: 8, J CHILK: B J CHILK: B J, CHILK: B J, CHILK: 8, J	8007220427 8007250007 8007250010 8007250028 8007250037	50-327	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8007020301 8007100324 8007020030 8007020045 8007100363	50-364 G 50-364 F 50-364 A 50-364 A 50-364 B	COLEMAN, L R COLEY, J L COLLING, B J COLLING, E D	8009100590 8009190529 8009240313* 8009150137* 8009020080*	PR PR 50-413 Q 50-271 Q 50-320 P
CHILK: 8 J CHILK: 8 J CHILK: 9 J CHILK: 8 J CHILK: 8 J.	8009250042 8009250045 8009250053 8009260467 8009260639	50-498 0 50-498 0 70-143 50-546 0 50-556 0	CLAYTON,F L CLAYTON,F L CLAYTON,F L CLAYTON,F L CLAYTON,F L	8009020038 8009020062 8009100237 8009030427 8009030491	50-364 A 50-348 B 50-364 Q 50-348 B 50-348 R	COLLING, E D COLLING, J T COLLING, J T COLLING, R E	8009030534* 8009090603 8009110678 8009020135 8009300282*	50-320 P 50-320 P 50-320 P 50-320 R 50-267 G
CHILK, B. J. CHILK, B. J. CHILK, B. J. CHILK, B. J.	B009260639 B009260463 B009300019 B009300037 B009300320	50-856 0 50-387 0 27-39 50-443 0 50-3 0	CLAYTON, F L GLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8009030492 8009080387 8009110687 8009040246 8009040386	50-344 A 50-348 P 50-348 Q 50-344 A 50-364 A	COLLING.F COLLING.PF COLLING.JT COLLING.JT COLLING.JT	8009190703 8009080485 8009090796 8009120677 8009100375	RECOD M18C 50-287 R 50-320 P 90-320 R
CHILK, B. J. CHILBON, V. T. CHILTON, A. B CRIN, H. Y. CHONO, L. K	8009300560 8009170281* 8009150456 8009110328 8009170059	50-375 M 50-250 R 50-356 R 50-320 P FOIA	CLAYTON, F.L. CLAYTON, F.L. CLAYTON, F.L. CLAYTON, F.L. CLAYTON, F.L.	8007080273 8007070566 8007070585 8007120425 8007100318	50-364 A 50-348 P 50-348 F 50-348 P 50-348 V	COLLINS, J T COLLINS, P F COLLINS, P F. COLLINS, J T COLLIER, R P	8009150539 8009190745 8009150447 8009150532 8009100043	50-320 R 50-282 P H18C 50-320 R NUREO
CHOULEB, N. C CHOULEB, N. C CHON, E. T. CHRISTIANBON, F. CHRISTENBURY, E	8007160616* 8007270118* 8007270118* 8007100161* 8007110603	50-305 G 50-255 G 50-255 G 50-331 G 50-452 O	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8009150484 8009160320 8009160415 8009160358 8009160268	50-364 A 50-348 B 50-364 A 50-348 P 50-348 R	COLLIER, R P COLLINS, P F COLLINS, J T COLLIER, L B COLLINS, J, T	8007300164 8007110317 8007180204 8007240557* 8007230126	NUREO 50-144 V 50-285 R 50-375 Q 50-320 H
CHRISTOFFER, O. CHRISTENSEN, J. H. CHURCH, F. CHURCHILL, R. L. CHURCHILL, R. L.	8009030133* 8009260417* 8009110413* 8009150078 8009110702	50-275 G 50-289 T COMMISSION 70-33 70-33	CLAYTON: F L CLAYTON: F L CLAYTON: F L CLAYTON: F L CLAYTON: F L	8009160307 8009170353 8009150259 8009150260* 8009170214	50-346 8 50-364 A 50-348 K 50-348 K 50-364 A	COLLINS, J T COLLINS, M COLOMPO, R W COLOMBO, R W	8009250440 8009290491 8009180441 8009150272* 8009160297*	50-320 P 50-320 R 50-274 S 50-312 S 50-312 R
CIESTKIEHICZ, 8 CIESTKIEHICZ, B CIMSUEMANI, D K CIPOLLA, A J CLARDY, L.	8007020388# 8007230720# 8007040404 8007300241 8007100161#	50-237 8 50-10 R 50-3 H 40-3392 50-331 Q	GLAYTON, F L GLAYTON, F L GLAYTON, F, L GLAYTON, F L GLAYTON, F L	8009230465 8009230566 8009230448 8009230722 8009230710	50-364 A 50-364 R 50-364 A 50-348 B 50-348 B	COLOMBO, R W COLTON, E COMBS, C COMER, F M COMER, F M	8009260476# 8009090665 8009180191# 7912040196# 8009160029	50-312 & XPORTLIC CONTRACT PT9 Bocket 30
CLARK, A T CLARK, R A CLARK, R. A CLARK, R. A CLARK, R A	8009120543 8009110610 8009170264 8009170267* 8009020336	70-1308 50-338 P 50-309 P 50-309 P 50-317 P	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8007270327 8007300381 8007300534 8007300435 8007270371	50-364 A 50-348 P 50-348 Q 50-348 H 50-364 A	COMPTON,R M CONKLIN,J C CONKON,T E CONKON,T E	8009180162* 8009100953 8009100149* 8009120539* 8009120141*	50-280 G NUREO 50-389 G 50-250 G 50-414 G
CLARK, R. A CLARK, R. A CLARK, R. A CLARK, R. A CLARK, R. A.	8009120107 8009150415 8009180213 8009030048 8009150350	50-285 F 50-317 P 50-336 P 50-336 P 50-317 P	CLAYTON, F. L. CLAYTON, F. L. CLAYTON, F. L. CLAYTON, F. L. CLAYTON, F. L.	8009300458 8009300572 8009300463 8009300523 8009300424	50-344 V 50-348 S 50-344 V 50-348 B 50-348 P	CONLON, T E CONLON, T E CONLON, T E CONLON, T E CONLON, T E	8009150370* 8009110427* 8009240274* 8009103307* 8009020337*	50-321 0 50-413 0 50-370 0 50-364 0 50-327 0
CLARK, A T CLARK, L CLARK, R. A CLARK, R. A CLARK, L	8007080409 8007030565 8007170082 8007170088* 8007080178	50-201 U 50-20 R 50-282 P 50-282 P 50-20 F	GLAYTON, F L CLEMENS, P GLEVELAND, C J GLGVELAND, C J GLGVELAND, C J	0009300511 9009270060 9009120579 9009120639 9009260110	50-348 8 FDIA 50-263 P 50-315 P 50-263 P	CONLON, T E CONLON, T E CONLON, T, E CONNER, T B CONNER, T B	8009050176* 8009100258* 8009250343* 8009050272 8009050272	70-1151 50-400 Q 50-413 Q 50-358 Q 50-358 Q
CLARK.R A CLARK.R A CLARK.R.A CLARK.R.A	8007170011 8007170175 8007170179* 8007170185* 8007170295	50-318 P 50-205 P 50-205 P 50-205 P 50-202 O	CLEVELAND, C J CLEVELAND, J C CLOUD, R L CODB, A B COCHRAN, T B	8009240548 8009100953 8009020094 8009100003 8009050179	<b>₩ CONTRACT</b>	CONNER, F B CONNER, F B CONNER, T B CONNER, T B	8009190451# 8009230027 8009230027 8009300016 8009300016	50-286 R 50-395 O 50-358 O 50-358 O
CLARKIR A CLARKIR A CLARKIR A. CLARKIR A. CLARKIR A	8009190297 8009190308 8009190322 8009190336 8009190352	50-335 0 50-344 0 50-336 0 50-285 0 50-266 0	COCHRAN, R. Q. COCHRAN, T. COCHRAN, T. B. COCKRELL, R. Q. COCKRELL, R. Q.	8007030548 8007140044 8007300004 8007020352 8007020354	90-59 R PR 50-367 9 50-297 R ★ 50-297 R	CONNOR, L CONSTABLE, O L CONVEY, H H CONVEY, H F CONVEY, H F	8009110339 8009170172* 8009180385 8009160291 8009240207	FOIA 50-382 G 50-349 H 50-271 R 50-271 P
CLARK, R. A.	8009240520 8009240535 8009240402 8009240415 8009120575	50-317	COGOIN, C.L. COGOIN, C.L. COGOIN, C.L. COGOIN, C.L. COGOIN, C.L.	8007030461 8007030447 8007020367 8007020414 80070704438	* 50-366 8 * 50-366 8 * 50-321 8	COOK, L. GOOK, J. H GOOK, J. H GOOK, J. H GOOK, J. H	8009160647* 8008080297 8009180240* 8008190605 8009230110	COMMISSION 50-327 F 50-327 G 50-327 S 50-327 G
CLARK, R. A CLARK, R. A CLARK, R. A. CLARK, R. L. CLARK, R. L.	8009260032 8009260197 8009290421 8009290467 8009200077	50-344 P 50-309 P 50-282 P 50-285 P 50-317 P	COOOIN, C L COOIN, C L COHEN, H. B COHEN, B. COHEN, I	8007150278 8007150274 8007020333 8007150147 8007150358	# 50-321 B # 50-320 H # CONTRACT	COOK, J H COOK, J H COOK, J H COOK, J H	8009040295 8009290475* 8009090397 8009090298* 8009230275	50-329 A 50-275 R 50-329 S
CLARK, R. A CLARK, R. A, CLARK, B CLARK, R. A, CLARK, R. A.	8007300080* 8007300085* 8007220287* 8007280120*	50-317 P 50-317 P 50-275 B 50-368 P 50-368 P	COHEN, E. COHEN, P COHN, D B COHN, D D COHN, D, B	8009120183 8009030350 8009090635 8009090635 8009090627	90-206 H # 50-367 Q # 50-367 Q	COOK' A M COOK' A M COOK' A M COOK' A M	8009170259 8009290368 8009220238 8009230550 8009190218	50-329 A 50-329 A 50-329 A 50-329 A 50-329 K
CLARKIPA A CLANDEN, D H CLAY, R V. CLAY, E. L.	8009250137* 8009260394* 8009180560* 8009170284* 8009100795*	50-368 P 50-289 T 50-320 H 50-320 H	COHN. D. B COHN. D. B. COHN. D. B. COHN. D. B COHN. D. H	8009090633 8009090633 800909063 800903014 8009030153	7* 50-367 0 3* 50-367 0 7 50-367 0	COOKE, W D	9009250268 8009250284 9009290360 9009200507 8009230643	50-329 8 50-329 8 50-329 8 50-329 A 50-157 P

AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	BUBJECT Category
COONEY, M J COOPEY, M J COOPEY, M J COOPEY, M J	8007020261* 8007020239* 8007040576 8007160561 8007250274	70-734 70-984 70-734 70-734 50-171 F	COWHEY, J COX, E L COX, F T COX, F T	8009170263* 8009270276 8009070455* 8009070462* 80090704651*	50-289 H NUREO COMMISSION COMMISSION	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8009110512 8009110575 8009110581* 8009110594* 8009020456	50-409 P 50-255 P 50-255 P 50-255 P 50-10 P
COUNEY, M J COUNEY, M J COUNEY, M J	8009030635 8009120330 8009120369 8009160439 8009160441	50-277 8 50-278 8 50-278 8 50-278 8 50-278 8	CRACRAFT,T M CRAIO,L L CRANE,P A CRANE,P.A CRANE,P.A	8009150178* 8009040099* 8009050082 8009110756 8009050321	CONTRACT 40-2061 50-133 G 71-9096 50-133 V	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8007040088 8007050497 8009120279 8009120281 8009180040	50-155 P 50-29 P 50-237 P 50-237 P 50-237 P
COONEY, M J COONEY, M J COONEY, M J COONEY, M J	8009260621 8009160294 8009180439 8009190482 8009260616	50-278	CRANE, P A CRANE, P A CRANE, P A CRANE, P A CRANE, P A	8009020263 8009030649 8009090514 8009090544 8009080333	50-275 A 50-275 O 50-275 K 50-275 A 50-133 R	CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D	8009180312 8009180428 8009240593 8009240596 8009240586	50-237 P 50-10 P 50-219 P 50-245 P 50-29 P
COOPER, J COPELAND, R L COPELAND, J G COPELAND, J G COPELAND, R L	8007110831* 8007020014 8007040271 8007040271 8007020002	40-4826 50-537 A 50-466 G 50-466 G 50-537 B	CRANE, P A CREWS, J L	8007120349 8007230551 8007180486 8007250268 8007100151#	50-133 8 50-133 R 50-275 A 50-275 A 50-320 P	CRUTCHFIELD, D GRUTCHFIELD, D CRUTCHFIELD, D GRUTCHFIELD, D CRUTCHFIELD, D	8009230757 8009190655 8009300247 8009300253 8009300265	50-244 F 50-244 F 50-244 Q 50-206 Q 50-217 Q
COPELAND, R L COPELAND, J O COPELAND, J O COPELAND, J O	8009090549 8009090575 8009180475 8009180475 8009160201	50-537 B 50-537 B 50-466 G 50-466 Q 50-466 Q	CREWS, J L CREWS, J L CREWS, J L CREWS, J L	8007120474* 8007020233 8007020244 8007120470* 8007120475	50-326 Q 50-397 Q 50-344 Q 50-326 Q 50-361 Q	CRUTCHFIELD, D CULP, R. H CULP, R. H CULP, R. H CULP, R. H	8009300651 8009160201 8009160201 8009240565 8009230691	50-29 0 50-466 0 50-466 0 50-466 0 50-466 0
COPELAND, J O COPELAND, J O COPELAND, J, O COPELAND, J O COPELAND, J O	8009160201 8009160157 8009160157 8009300469 8009300469	50-466	CREWS, J L CREWS, J L CREWS, J L CRNICH, J	8009230212 8009120487 8009170243 8009120459 8009290396*	50-275	CULVER, M W CUNNINGHAM, G E, CUNNINGHAM, G E CUNNINGHAM, G E CUNNINGHAM, G, E	8009220365# 8009190751 8009150001 8009110225 8009180509	50-302 8 70-754 71-3980 70-754 70-1007
CORBETT, J S CORCORAN, T CORDANI, R A CORDANI, R A CORDERO, Z C	8009220172 8009020217* 8009030001 8009110767 8009150402*	71-9080 COMMISSION 70-27 70-27 50-546 <b>Q</b>	CROCKER, H W CROCKER, H W CROCKER, H W CRONENBERG, A CROSBY, P J	#007230150* 8007250334* 8007110274 8007150576 8007300528*	70-1417 70-820 70-820 NUREO 50-219 8	Cunningham, o e Cunningham, r e Cunningham, a l Cunningham, r e Cunningham, o e	009100227 #00917008 #100917008 1840017008 7220087008	70-754 70-1100 50-370 0 70-1151 71-6400
CORE.M R CORREA.J H CORNEA.M A CORWIN.J W CORYELL.G P	8007070536* 8007260400* 8007260460 8007050427 8007080238*	50-285 S 50-287 T 50-311 J PR 50-332 Q	CROBBMAN, W A CROBBMAN, W A CROBBMAN, W A CROBBMAN, W A CROBBMAN, W A	8009150066* 8009150071* 8009150077* 8009150080* 8009150083*	50-445 Q 50-445 Q 50-445 Q 50-445 Q 50-445 Q	CUNNINGHAM, O E CUNNIGNHAM, O E CUNNINGHAM, O E CUNNINGHAM, O E. CUNNINGHAM, O E	8009240703 8009260051 8009260106 8009260391 8009260581	71-5926 71-5990 71-5971 71-9044 71-9049
CORYELL, O P COSTALUPES, Y COSTELLO, F M COSTELLO, F COTTLE, H	8009150605* 8009230021* 8009270041* 8009100372 8009040330*	70-1113 50-142	CROSSMAN, W A CROSSMAN, W A CROSSMAN, W A CROSSMAN, W A CROSSMAN, W A	8009150087* 8009150093* 8009150105* 8009170385* 8009170387*	50-445 Q 50-445 Q 50-445 Q 50-498 Q 50-462 Q	, D. L. MAHRNINNUD D. L. MAHRNINNUD D. L. MAHRNINNUD D. L. MAHRNINNUD M. L. MAHRNUD	8009040278 8009040278 8009180496 8009180571 8009020083*	50-289 0 50-289 0 50-289 0 50-289 0 50-204 8
COUNBIL.W 0 COUNBIL.W 0 COUNBIL.W.0 COUNBIL.W 0 COUNBIL.W.0	8009120197 8009120247 8009220330* 8009230749 8009110482	50-245 G 50-213 G 50-423 8 50-245 G 50-336 G	Croeeman, H A Croesman, H A Croesman, H A Croesman, H A Croesman, H A	8007070648* 8007150367* 8007150348* 8007250378* 8007250405*	50-482 G 50-445 G 50-482 G 50-458 G 50-498 G	CURRAN, J M CURRAN, J, M CURTIE, N, W CURTIE, J R CURTIE, N W	8007070265 8007260513* 8007070654* 8007240533* 8007110414*	50-206 R 50-206 B 50-387 B 50-147 Q 50-367 B
CONNSIL' N O CONNSIL' N O CONNSIL' N O CONNSIL' N O	8007110474 8007100113 8007090017 8007100107 8007020231	50-213 Q 50-423 Q 50-245 Q 50-336 Q 50-213 P	CROSSMAN, W A CROSSMAN, W A CROSSMAN, W A CROSS, J L. CROSS, J L.	8009300102* 8009190340* 8009300096* 8009030631 8009050257	50-498 9 50-382 0 50-382 0 50-296 P 50-327 P	CURTIS, N W CURTIS, N. W CURTIS, N W CURTIS, N W CURTIS, N W	8007030006 8007120142 8007170756 8007070616 8007180307	NUREO 50-387 Q 50-387 Q 50-387 Q REOOD
COUNSIL, W O COUNSIL, W O COUNSIL, W O COUNSIL, W O	8009020286 8009050195 8009030641 8009030532 8009150247	50-245 P 50-336 P 50-213 P 50-213 P 50-336 P	CROSS, J. L CROSS, J. L CROSS, J. L. CROSS, J. L CROSS, J. L	8009090347 8009090555 8009080259 8009090370 8009090522	50-259 P 50-259 P 50-327 P 50-327 P 50-438 A	CURTIE, N W CURTIE, N, W CURTIE, N W CURTIE, N W CURTIE, N W	8007070036 8007120660* 8007080364 8007070472 8007150470	50-387 Q 50-387 A 50-387 A 50-387 B
COUNSIL,W 0 COUNSIL,W 0 COUNSIL,W 0 COUNSIL,W 0	8009030378 8009030378 8009050103 8009110245 8009190434	50-213 P 50-213 P 50-336 P 50-245 P 50-245 P	CROSS.J.L. CROSS.J.L. CROSS.J.L. CROSS.J.L.	8007070543 8007120245 8007120261 8007120387 8007250480	50-259 I 50-276 P 50-327 V 50-327 P 50-327 Q	W M, RITHUD B N, RITHUD B N N, RITHUD M N, N, IND B N, N, IND B N, N, IND	8009160310 8009170290 8009220423 8009110787 8009110016	50-387 A 90-387 A 50-349 G 50-387 Q 50-387 Q
COUNSIL. W. O COUNSIL. W. O COUNSIL. W. O COUNSIL. W. O	8007120257 8009090636 8009300297 8009180445 8009240571	50-213 P 50-245 P 50-245 P 50-336 P 50-245 P	CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R, P	8009030012 8009150067 8009220176 8009110504 8009260097	NUREO 50-346 Q 50-346 Q 50-346 Q 50-346 Q	CUTCHIN, J. M CUTGHIN, J. M CYR, K. D. CYR, K. D D'AHORE, M	8009180131 8009170346 8009030134 8009230255 8009110135×	50-289 T 50-289 T 50-409 Q 50-266 Q 70-1131
COUNSIL, W O COUNSIL, W O COUNSIL, W O COUNSIL, W O	8007170427 8007180387 8007230621 8007180357 8007270351	50~245 P 50~213 P 50~213 P 50~213 P 50~213 P	CROUSE.R P CROUSE.R P CROUSE.R P CROWSE.R P CROW.W T.	8009120430 8009100172 8009220297 8009220301* 8009170084	50-346 F 50-346 P 50-346 P 50-346 P 70-33	DABES,R D DAIL,L,C DAIL,L,C DAIL,L,C DAIL,L,C DAIL,L,C	8009100944 8009020211 8009020139 8009120574 8009120212	NUREO 50~488 Q 50~488 Q 50~488 Q 50~488 Q
COUNSIL, W O COUNSIL, W O COUNSIL, W O COUNSIL, W O	8009290351 8009300239 8009300179 8009300239 8009300403	50-213 P 50-245 P 50-336 P 50-245 P 50-423 A	CROW, M. T CROW, W. T. CROW, W. T. CROW, W. T. CROW, W. T.	8009250478* 8009140132 8009170001 8009240339* 8009150183*	70-1257 40-2061 70-820 70-33 70-258	DAILY,L DALE,L.F. DALE,L F DALE,L.F. DALE,L F	8009020317* 8009230642* 8009020218 8009020292 8009230092	50-320 H 50-416 B 50-416 Q 50-416 Q
COUNSIL, W. O COUNSIL, W. O COWAN, B Z COWAN, B Z COWOILL, C J	8009300291 8009300443 8009110028 8009110028 8009160229#	50-334 P NUREO XPORTLIC XPORTLIC 50-277 G	CROW, W T. CROWE, A CROWLEY, J. L CROWLEY, B. R CROWLEY, B. R	8009250470* 8009120334 8009050409 8009050421* 8009300041*	70-1151 NUREO RES 50-364 G 50-416 G	DALE, L. F. DALE, L. F. DALE, L. F. DALE, L. F. DALLINGER, J. F	8009110681 8009050352 8009150489 8009300437 8009170136	50-416 Q 50-416 A 50-416 H 50-416 A 71-6717

AUTHOR	ACCESSION NUMBER	SUBJECT CATEOURY	AUTHOR	ACCEBBION Number	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT
DALOUGH, R.C. DALTON, J. N. DALTROFF, B. L. DALTROFF, B. L. DALTROFF, B. L.	8007040287 8007070333* 86 <i>0722</i> 0374 8007080533 8007150502	50-445 M 50-339 P 50-277 G 50-277 G 50-277 G	DE SANTIS, N DEALE, V 8 DEARDORFF, P E DECHER, U DEEDS, W	8004110323 8009240125* 8009020111* 8009100490 8009030671	Docket 30 50-263 0 50-237 P 50-5 H NUREO	DEVINE, J. B DEVINE, J. B DEVINE, J. B DEVINE, J. B	8009110260 8009120056 8009190752 8009230417 8009230781	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
DALTROFF: 8, L DALTROFF: 8 L DALTROFF: 8 L DALTROFF: 8 L DANCE: H. C	8009100121 8009090015 8009100090 8009110251 8009030281*	50-277 Q 50-278 Q 50-277 Q 50-277 Q 50-390 Q	DEL GEORGE, L O DELAPORTE, C T DELGEORGE, L O DELGEORGE, L O, DELGEORGE, L O	8009160585 8009030314* 8009120446 8009240555 8009180406	50-373 A 50-387 A 50-454 F 50-10 P 50-373 A	DEVINE, J. B DEVINE, J. B DEVINE, J. B DEVINE, J. B DEVINE, J. B	9009230801 9009110254 9009190746 8009230420 8009230425	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
DANCE, H. C. DANCE, H. C. DANCE, H. C DANIELBON, L. J DANIELBON, D. H	8009300081* 8009220341* 8009020225* 8009170376* 8009100126*	50-259 Q 50-321 Q 50-259 Q 40-299 50-440 Q	DELGEORGE:L O DELGEORGE:L O DELGNO,8 D DELVIN,J H DELVIN,J	8009290399 8009260511 8009300517* 8009160242* 8009160246*	50-373 8 50-373 A 50-315 8 50-220 9 50-334 9	DEVINE. J B DEVINE. J B DEVINE. J B DEVINE. J B DEVINE. J B	8009230427 8009230428 8009230803 8009110689 8009110723	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
DAMIELBOM, D. H DAMIELBOM, D. H DAMIELBOM, L. J. DAMIELBOM, D. H. DAMIELBOM, T. T.	8009150203* 8009110627* 8009020200* 8009150508* 8009160514*	50-327	DEHMIE, P. N. DENECOUR, C. DENTON, H. R. DENTON, H. R. DENTON, H. R.	8009260542 8009120439 8009050131* 8009180448 8009030285	8ES 50-361 H FOIA 50-3 H 50-387 A	DEVINE, J. B DEVINE, J. B DEVINE, J. B DEVINE, J. B	8007110741 8007300652 8007330754 8007300655 8007300662	XFORTLIC XFORTLIC XFORTLIC XFORTLIC XFORTLIC
DANIELBON, D. H. DANIELBON, D. H DANIELBON, D. H DANIELBON, D. H DANIELBON, D. H	8007180021* 8007260286* 8007270101* 8007270114* 8007160247*	50-275 0 50-461 0 50-346 0 50-546 0 50-327 0	DENTON, H R DENTON, H R DENTON, H R. DENTON, H R. DENTON, H R	8009300246 8009150070 8009150413 8009080331 8009090599	50-320 H 50-269 P 50-320 H 50-320 H COMMISSION	B C'ANIÀDA B C'ANIÀDA B C'ANIÀDA B C'ANIÀDA B C'ANIÀDA	8009300666 8009300697 8009290147 8009290153 8009290385	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
DANIELBON, D. H. DANMHEYER, T. R. DANTILER, H. U. DARHITZEL, R. W. DARHITZEL, R. W.	8009180054* 8009160278 8009290142* 8009030639 8009040255	50-373 G XPORTLIC CONTRACT 50-70 P 50-70 P	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8007070783 8007020108 8007160503 8007150084 8007150087*	50-320 P 50-445 H 50-224 P 50-250 G 50-250 O	DEVINE, J F DEVINE, J B DEVINE, J B DEVINE, J B DEVINE, J B	8009160363* 8009270061 8009270149 8009270151 8009300071	50-275 S XFORTLIC XFORTLIC XFORTLIC XPORTLIC
DARMITZEL, R. W DARMITZEL, R. W DAVIDBON, D. R. DAVIDBON, D. R DAVIDBON, D. R.	8009180474 8009250245 8009100112* 8009160636 8009020067	50-70 P 50-70 P 50-440 Q 50-440 G 50-440 S	DENTON, H R DENTON, H, R DENTON, H, R DENTON, H R DENTON, H R	8009220125 8009120736 8009180548 8009110332 8009160657*	H150 50-320 H 50-320 H 50-327 P 50-339 P	DEALIN* 7 M DEALIN* 7 M DEALIN	8009300032 8009300059 8009100652* 8009250363* 8009160625*	XPORTLIC XPORTLIC 70-371 50-201 @ 50-277 G
DAVIDBON, D. R. DAVIDDEF, D. B. DAVIDBON, D. R. DAVIDBON, D. R. DAVIEB, D. L.	8009120297 8009030341 8009190133 8009190431 8009180329*	50-440 8 State Prog 50-440 K 50-440 A CONTRACT	DENTON, H. R DENTON, H. R DENTON, H. R DENTON, H. R DENTON, H. R	8007150104 8007150107* 8007070621 8007100145 8007150314	50-311 P 50-311 P 50-367 Q 50-320 P 50-352 H	DEVLIN, J DEWEY, L S DEXTER, W D DEYOUNG, R C	8009300633 8009160033 8009160041# 8009150212# 8009170417#	50-272 8 50-389 M 50-389 M 40-8745 50-458 0
DAVIS.D. DAVIB.J.S DAVIS.A B DAVIS.J. DAVIS.A.B	8009100471 8009290092* 7911090069 8009290087* 7912040149	40-6502 FOIA PT9 FOIA PT9	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8007240562 8007030142* 8007170407 8007240106 8007240560	PR 50-409	DHIR.V K DIAZ.N J DICKERSON.M W DICKERSON.M W	8009240028 8009140389 8009150075* 8009100055*	NUREG 50~83 P 50~445 O 50~445 O 50~267 O
DAV(8.A.B. DAV(8.A.B. DAV(8.A.B. DAV(8.A.B. DAV(8.A.B.	8009290046* 8001290275 8009290116* 8009290102* 8008300691	FOIA PT9 FOIA FOIA PT9	DENTON H R	8007180226 8007180232* 8007180242* 8007110347 8007070436		DICKENSON.H W DICKEON.M W BICKBON.H O DIECKAMP.H DIECKAMP.H	8009110876 8009300282+ 8009230312 8009160361+ 8009170265	RES 50-267 0 50-255 R 50-320 P 50-320 P
DAVIS.A B. DAVIS.J.H DAVIS.P.B DAVIS.A B. DAVIS.A.B.	8004120881 8009240644* 8009050480 8009150121* 8009030323	PT9 70-143 70-143 40-2061 50-305 G	DENTON, H R DENTON, H R. DENTON, H. R. DENTON, H R. DENTON, H R.	8009290057* 8009290220 8009290235 8009290032* 8009190569	50~443 H 50~320 P	DIETCH, R DIETCH, R DIETCH, R DIETZ, C R DIOOS, R M	8009030634 8009030637* 8009190338 8009050363 8009050194	50-206 P 50-206 P 50-361 K TDPREP 50-443 A
DAVIS, A. B DAVIS, A. B. DAVIS, A. B DAVIS, D. DAVIS, A. B.	8007100085 8007130166 8007120306 8007130177* 8007020227	50-87 G 70-36 50-155 G QAF79 50-315 G	DENTON, H. R DENTON, H. R DENTON, H. R. DENTON, H. R DENTON, H. R	8009290081 8009290384 80092900304 80092900304 8009300159	COMMIGSION 50~289 H 50~327 P 50~327 T 50~289 H	Dicog, R M Dicog, R M Dicog, R M Dicog, R. M Dicog, R M	8009180525 8009150031 8009090645 8009220384 8009190670	50-334 P 50-219 P 50-346 P 50-277 P 50-245 P
DAVIB.R.J DAVIB.A.B. DAVIB.A.B. DAVIB.A.B. DAVIB.A.B.	9009190313 8009290090 9009290123 8009290017 8009300232	FOIA 70-1308 50-254 g 50-246 g Waste Mot	Derrick, B Derrick, B Desantis, N Desantis, N Desantis, N.	8007020217* 8007070570 8007270127* 8007270122* 8003240087	50-320 U FOIA	Diggs, R M Diggs, R M Dignan, T G Dignan, T G Dill, J	8009100617# 8009160433# 8009250049 8009250049 8009030438#	50-334 P 50-338 P 50-471 G 50-471 P
DAVIS,A B DAVIS,A B DAVIS,A.B. BAVIS,L.D	8009190118 8009260659 8009260628 8009160339 8009030549#	40-2061 50-346 G 50-315 G 50-361 Q	DESSEL, S. DESSEL, S DESSEL, S DESSEL, S DESSEL, S	7912190067* 7912190047* 7912190023* 8003050232* 8003050219*	• P19 • P19 • P19	DINKINS, MA DIPIAZZA, RP DIPIAZZA, RP DIRCKS, WJ DIRCKS, WJ	8009110574 8009100187 8009250257 8009080468 8009020127	RES 70-1143 50-22 G 50-201 G 50-483 H
DAVIS, A. B. DAVIS, A. B. DAVIS, E. M. DAVIS, L. D. DAVIS, J. F.	8007300606 8007120455* 8007160341 8007170337	70~1377 50~317 B 50~361 0 50~362 P 50~275 0	DEUBERT, J R DEVINCENTIS, J DEVINE, J B DEVINE, J B	8009300374 8009190094 8009110478 8009020162 8009050513	50-443 G XPORTLIC	DIRCKS.W J DIRCKS.W J DIRCKS.W J DIRCKS.W J	8009030178 8009020151 8009020166 8009020187 80090205464	
DAVIB, S. M DAVIB, S. M DAVIB, L. D DAVIB, S. M. DAVIS, S. M	8007230546# 8007230546# 8007230633 8007230675# 8007300450#	50~317 8 50~361 H 50~317 8	DEVINE, J. B.	8007050447 8007030553 8007050466 8007160173 8007160174	XPORTLIC 50-443 8 XPORTLIC XPORTLIC	DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J	9009110241 9009020320 9009020118 9009020328 9009020476	50-397 U 50-320 H 50-320 H 50-320 H 50-320 U
DAMBON, D. M DAMBON, R. DAMBON, R. DAMBON, D. M DAMBON, D. M. DE POIX, V. P.	8009110488 8009050459 800909093 8009030585 8009300585 8009120125	70-1308 71-9033 70-1308	DEVINE, J. B. DEVINE, J. B. DEVINCENTIS, J. DEVINE, J. B. DEVINE, J. B. DEVINE, J. B.	8009160236 8009190687 8009090419 8009230429 8009230800	XPORTLIC XPORTLIC 50-443 B XPORTLIC	DIRCKS.W J DIRCKS.W J DIRCKS.W J DIRCKS.W J DIRCKS.W J	8009020482 8009020487 8009020496 8009100082 8009110268	50-320 U 50-320 U 50-320 U 50-387 D 50-320 H

AUTHOR	ACCEBSION NUMBER	SUBJEC CATEO		AUTHOR	ACCEBSION NUMBER	SUBJECT CATEODRY	AUTUON	ACCESSION	SUBJECT
BIRCKS, H J DIRCKS, H J DIRCKS, H J DIRCKS, H J DIRCKS, H J	8007180101 8007110501 8007110514 8007110474 8007110486	018CL09 50-320 50-275 50-320 50-320	BURE H U H	DUNN, C, N DUNN, C, N DUNN, C N DUNN, D DURR, J P	8007230253 8007300357 8007300370 8007270052 8007100873*	50-334 P 50-334 P NUREO NUREO	AUTHOR EISENHUT, D O	NUMBER 	CATEGORY 30-247 P 50-264 A 50-284 Q 50-250 Q 50-272 Q
DIRCKS, H J DIRCKS, H J DIRCKS, H J DIRCKS, H J	8009110290 8009110314 8009110212 8009110218 8009120301	50-320 50-320 50-320 50-3 50-327	Н Н Н Н	DUTTON, D. DUTTON, D DUTTON, D DUTTON, D, DUTTON, D.	8007040635 8007040637 8007030487 8007040458 8007220133	50-424	EIBENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G	8009190302* 8009190304* 8009190310* 8009190311* 8009190324*	50-335 0 50-262 0 50-313 0 50-344 0 50-312 0
DIRCKS, H J DIRCKS, H J DISE, D P DISE, D P DISE, D P	8009220255 8009240540 8009120408 8009180344 8009260403	50-275 50-466 50-220 50-220 50-220	U H V P	DUTTON, B DUTTON, B DUTTON, B DWORAK, J A DYM, H	8009240389 8009190493 8009300110 8009100043 8009160033	50-424 0 50-424 8 50-424 0 NUREQ 50-389 M	EISENHUT, D O EISENHUT, D O EISENHUT, D O EISENHUT, D O EISENHUT, D O	8009190328* 8009190343* 8009190357* 8009190369* 8009190380*	50-336 0 50-285 0 50-266 0 50-277 0 50-302 0
DISTEFANO.J DISTEFANO.J DIXON.G DOAN.P F DODD.C V	8009100590 8009190529 8009050424 8009050289 8009030471	50-298 NUREO	H 8	DYM, H, DYM, H DYM, H DYM, H, DYM, H	8009160041* 8009170162 8009170162 8009300476 8009300476	50-387 M 50-387 M 50-389 M 50-250 M 50-250 M	EIBENHUT, D G EIBENHUT, D G EIBENHUT, D G EIBENHUT, D G EIBENHUT, D G	8009190581* 8009190754 8009280011* 8009880014* 8009820017*	50-346 Q 50-461 A 50-247 Q 50-220 Q 50-249 Q
DODDS.R T DODDS.R T DODDS.R T DODDS.R T DODDS.R T	8009110429# 8009120472# 8009120631# 8009120296# 8009120309#	50-397 50-460 50-528 50-460	G G G	EADIE, O. O EADIE, O. O EADIE, O. O EADIE, O. O EADS, B. O	8009160479* 8009170250 8009100135 8009190767 8009100508	WASTE MGT WASTE MGT WASTE MGT 40-834B RES	EIBENHUT, D O EIBENHUT, D O EIBENHUT, D O EIBENHUT, D O EIBENHUT, D O	8009220019* 8009220091* 8009220096* 8009220101* 8009220107*	50-259 9 50-295 9 50-334 9 50-243 9 50-333 9
DDDDS,R T DDDDS,R T DODDS,R T DOGCETT,S A	8009120500* 8009040482* 8009190170* 8009300054* 8009140527		@ @ @ @	EAST.D J EASTERLING.R Q EBERLEIN,F EBNETER.B D EBNETER.S D	8007020508 8007300140 8007020185 8007070232* 8007070044*	40-9745 NUREQ FOIA 50-352 Q 50-293 Q	EISENHUT.D O EISENHUT.D.O EISENHUT.D.O EISENHUT.D.O EISENHUT.D.O	8009220112* 8009220117* 800922012* 8009230117* 8009230129*	50-331 9 50-271 9 50-324 9 50-348 9 50-267 9
DOLAN, Y R DONAT, T J DONATH, F A DONAT, T DONG, R Q	8007070216* 8007050550* 8007150585 8007240481 8007120337	50-289 50-349 NUREO 50-349 NUREO	H G S	EBNETER, 8. D EBNETER, 9. EBNETER, 9 D ECKERT, J P ECKERT, R M	8009250302* 8009100899* 8009240265* 8009090885 8009110323	50-387 0 50-289 0 50-317 0 70-27 50-272 V	EISENHUT, D, O EISENHUT, D O EISENHUT, D O EISENHUT, D O EISENHUT, D, O	8007230130# 8007230132# 8007230134# 8007240603# 8007260532#	50-241 9 50-280 9 50-305 9 50-321 9 50-317 9
DONGCHUE, D J DONGCHUE, D J DOTEON, C W DOUGHERTY, D J. DOUGHERTY, D J.	8007030252 8007250280* 8007100403 8007170070* 8007120083*	SECY 10CFR NUREO FOIA CONTRACT		ECKHARDT, J H ECKHARDT, J H ECKHARDT, J H ECGNOMOS, N ECGNOMOS, N	8007020267# 8007120500# 8007170178# 8007160552# 8007120477#	50-361 G 50-528 G 50-528 G 50-269 G 50-250 G	EISENHUT, D. Q EISENHUT, D. Q EISENHUT, D. Q EISENHUT, D. Q EISENHUT, D. Q	8009240540* 8009240597* 8009260601* 8009260607* 8009240413*	50-348 0 50-289 0 50-298 0 50-309 0 50-315 0
DOUGHERTY, D J. DOUGHERTY, D J. DOUGHERTY, D J. DOUGHERTY, D J DOUGHERTY, D J	8009150149* 8009140815* 8009240680* 8009300595* 8009300286*	CONTRACT CONTRACT CONTRACT CONTRACT 40-299		EDELBTEIN, B EDELBTEIN, B EDELBTEIN, B EDELBTEIN, B EDLOH, J.	8009110596* 8009110592 8009120627* 8009120624 8009190245	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	EISENHUT, D O EISENHUT, D O EISENHUT, D O EISENHUT, D O EISENHUT, D O	9009240624* 9009240667* 8009290251* 8009300258* 8009300258*	50-338 0 50-269 0 50-244 0 50-206 0 50-219 0
DOUGHERTY, J B DOUGHERTY, J B DOUGHERTY, J B DOYLE, R J DOYLE, B C	8009230013 8009230013 8009230013 8009190748 8009110338*	50-280 50-280 50-280 RES CONTRACT	ф Ф Ф	EECKHOUT, A EECKHOUT, A EENIGENBURO, J EICH, E EICHHORN, W H	8009110270 8009110494 8009030194* 8009230571* 8009040281	XPORTLIC XPORTLIC 50-320 H 50-247 R 50-367 0	EISENHUT, D O EIBENHUT, D O EIBENHUT, D O EIBENHUT, D O EITENHUT, D O	8009300653* 8009240137 800929054 8009300584 8009300588*	50-27 0 50-309 H 50-275 H 50-293 0 50-293 0
DRAPER, E L DRAPER, E L DRAPER, E L DRAPER, E L DRAPER, E L	80090505224 8009290326# 8009250412 8009090409 8009090532	50-458	0 0 A F	EICHHORN, W H EICHHORN, W. H EICHHORN, W H EICHHORN, W H EICHHORN, W H	8007040281 8007080507 8007080511 8007080507 8007080511	50-367 0 50-367 0 50-367 0 50-367 0 50-367 0	EIBENHUT, D Q, EIBENHUT, D Q EIBENHUT, D Q EIBENHUT, D Q	8009170293* 8009300591 8009300598* 8009300603 8009300614*	50-289 P 50-271 Q 50-271 Q 50-249 Q 50-249 Q
DRAPER, E L DRAWBRIDGE, B L DRAZ, Z DRAZ, Z DRAZ, Z	8007300086 8007110334# 8007230237# 8007230242# 8007230245#	50-320 50-320	Q 5 Н Н Н	EIGHHORN, W H EICHHORN, W H, EICHHORN, W H EIGHHORN, W. H EIGHHORN, W. H	8009110808 8009110808 8009190039 8009230035 8009190039	50-367 0 50-367 0 50-367 0 50-367 0 50-367 0	EISENHUT, D Q EL-ABHRY, M T EL-BABBIONI, A ELDER, K ELIN, J, D	8007300617* 8007030377 8007160473 8007110763 8007120472*	50-249 0 50-327 R NUREO 70-2784 50-397 0
DRAZ, Z DREYER, E P DRISKELL, W E DROMERICK, A W DROMERICK, A W	8009230247* 8009170301* 8009050399 8009190658 8009300056	50-244 RES 50-339	H P P F	EICHHORN,W H EICHHORN,W H EICHHORN,W H EICHHORN,W H EISENHUT,D O	8009230035 8009300025 8009300576 8009300576 8009310347#	50-367 0 50-367 0 50-367 0 50-367 0 FOIA	ELIN, J O ELLERBHAW, L E ELLIOTT, A E ELLIB, J, ELLIB, J	8007020267* 8009190031* 8009090379 8009090579	50~361 0 0A999 50~123 P 50~445 0
DUBIEL, R W DUBONSKY, E DUBONSKY, E, DUCKWORTH, J P DUCKWORTH, J P	8009260439* 8009090202 8009090213 8009150132* 8009120601	XPORTLIC XPORTLIC 50-201	T R	EIBENHUT, D 0 EIBENHUT, D 0 EIBENHUT, D 0 EIBENHUT, D 0 EIBENHUT, D 0.	8006300604 8008060358 8009240158* 8009110554 8009020157	50-10 P 50-320 P 50-313 8 50-10 P 50-245 P	ELLIB, J. EMORY, K EMPBON, F. M ENGELKEN, R H ENGELKEN, R, H	8007110044* 8007180462* 8007180408 8007150078* 8007150107*	50-445 0 50-3 H 70-1308 50-201 U
DUCKHORTH, J. P DUCKHORTH, J. P DUCKHORTH, J. P DUNNER, G. H DUMMER, G. H	8009120604* 8009170378 8009110648 8009230359* 8009300264*	50-201   50-201   50-201   CONTRACT CONTRACT	₹	EISENHUT, D 0 EISENHUT, D 0 EISENHUT, D 0 EISENHUT, D 0	8009110616 8009110619 8009020297 8009080080 8009230052	50-344 F 50-264 F 50-3 P 50-3 P	ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R, H, ENGELKEN, R H	8007130107* 8007170183* 8007070052 8007150378* 8007150378*	50-201 Ú 50-528 q 50-397 q 50-397 q 50-397 q
DUNAVONT, D H. DUNAVONT, D H DUNN, C. N DUNN, C. N, DUNN, C. N	8009110299* 8009110304* 8009100389* 8009080309 8009070374	50-293 0 50-293 0 50-334 0 50-334 0	) ! !	EIGENHUT, D. Q EIGENHUT, D. Q EIGENHUT, D. Q EIGENHUT, D. Q.	8007030667* 8007020311 8007020318 8007020322 8007020327	NURE9 50-245 P 50-257 P 50-313 P 50-317 P	ENGELKEN, R H	8009260297 8009260298 8009260299 8009260300	50-508 8 50-206 0 50-312 0 50-133 0 50-344 0
DUNN, C. N. DUNN, B. D. DUNN, C. N. DUNN, C. N. DUNN, C. N	8009070405 8009190444* 8009160374 8009180188 8009190446	50-334 P 50-280 R 50-334 G 50-334 R 50-334 R		EISENHUT, D 0 EISENHUT, D 0 EISENHUT, D 0 EISENHUT, D 0 EISENHUT, D 0	8009160656 8009090863 8009090040 8009190589 8009190134	50-339 P 50-339 P 50-329 H 50-334 P 50-247 P	ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H, ENGELKEN, R. H ENGELKEN, R. H	8009030262 8009030267 8009030318 8009030327 8009030327	50-397 q 50-328 F 50-397 F 50-312 F 50-344 F 50-133 F

POHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ENGELMEN, R. H ENGELMEN, R. H ENGELMEN, R. H ENGELMEN, R. H ENGELMEN, R. H	8009020528	90-206 F 50-928 E 50-928 Q 50-279 Q 50-361 Q	FABRIKANT,R FABRIKANT,R FAHNER,T C FAHNER,T C FAHNER,T C	B009170239* B009160160* B009020048 B009020084 B009040208*	50-445 H 50-445 H 50-367 Q 50-367 Q 50-237 Q	FELTON.J K FELTON.J M FELTON.J K FELTON.J K FELTON.J M	8009190236 9009190242* 8009190614 8009110286 8009110335	50-369 A 50-369 A FOIA FOIA
ENGELMEN, R. H ENGELMEN, R. H ENGELMEN, R. H ENGELMEN, R. H ENGELMEN, R. H	8007030283 8007030287 8007030288 8007030270 8007030272	90-204	FAHNER, T C FAHNER, T C FAHNER, T C FAHNER, T C FAHNER, T C	8009040218* 8009110783 8009150281 8009150400 8009160247	50~237 G 50~367 G FR 50~367 G 50~367 G	FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8009190299 8009110354 8009110359 8009110527 8009110538	50-219
engelhen R. H Engelhen R. H Engelhen R. H Engelhen R. H Engelhen R. H	8009040472 8009290302 8009290305 8009290307 8009290404	50-397 Q 50-397 Q 50-133 Q 50-528 Q 50-344 Q	FAHNER,T C FAHRNER,H J FAHRNER,H J FAIRTILE,M B FALK,K M	8009220177 8009040455 8009160417 8009160505 8009030498	50-367	FELTON, J M	8009110546 8009110567 8009290025 8009260187 8009150302	FOIA FOIA 50-265 H FOIA
ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H	8009290407 8009290457 8009190169* 8009150379* 8009230363	50-312 Q 50-206 Q 50-528 Q 50-397 Q 70-734	FALK, K M FANKHAUSER, D FARNELL, A S FARNELL, A S FARNELL, A S	8009080348 8009030693 8009030718 8009030718 8009160397	50-266 0 50-358 0 50-329 0 50-327 0 50-329 0	FELTON, J. M FELTON, J. M FELTON, J. M FELTON, J. M	8009240141 8009240606 8009300109 8009250484 8009250448	FOIA 50-302 P FOIA FOIA FOIA
ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H ENGEL, R. E.	8007230367 8007230370 8007230371 8007230375 8007110443*	70-1287 70-754 70-28 70-984 TOPREP	FARNELL,A 8 FARNELL,A 8 FARON,R 8 FARRAR,A 0 FABIG,F	8009300023 8009300023 8009040413 8009110296* 8009300163*	50-329 G 50-329 G 50-244 P CONTRACT 50-289 H	FELTON.J K FELTON.J K FELTON.J K FELTON.J M FELTON.J M	8007300620 8009270414 8009270443 8009300284 8009300330	FOIA FOIA FOIA FOIA 50-128 R
engelken ir. H Engelken ir. H. Engelken ir. H Engelken ir. H Engelken ir. H.	8009120029 8009120030 8009150374 8009140178 8009140181	50-133	FAULKENBERRY, B FAULKENBERRY, B FAULKENBERRY, B FAULKENBERRY, B FAY, C U	B009120478* B009170244* B009120479* B009120490* B009110557	50-326	FELTY, D E FERGUSON, J H FERGUSON, J H FERGUSON, J H	8007030350 8007020437 8007030426 8007070344 8007020134	50-280 P 50-338 P 50-338 P 50-280 P
engelken, R. H. Engelken, R. H. Engelken, R. H. Engelken, R. H Engelken, R. H	8007160183 8007160184 8007160185 8007160187 8007170157	50-344	FAY,C W Fay,C W Fay,G W. Fay,G W Fay,G W	8007070537 8007180158 8007180304* 8007260215 8007160302	50-266 R 50-266 G 50-266 R 50-266 F 50-266 R	Fernos, o Fernos, o Fernos, o Fernos, o	8009040233 8009110010 8009110055 8009260670	50-376 0 50-376 0 50-376 0 50-376 0 50-376 0
enoelken. R H Enoelken. R. H Enoelken. R H Enoelken. R. H. Enoelken. R H	8009230327 8009230332 8009230334 8009230337 8009230339	70-984 70-1257 70-734 50-275 F 50-344 F	FAY, C. W FAY, C. W FAY, C. W FEDERICK, E. J FEE, W. F	8009230660 8009230666 8009300461 8009120571 8009120197	50-266 P 50-266 P 50-266 P REB 50-245 G	FERNOS.O FERNOS.O FERS.K H FIDELL.E R FIELDER.J	8009260681* 8009260684* 8009190863 8009150371 8009030374	50-376 Q State Prog FOIA 50-327 J
enoelken, r. h. Enoelken, r. h Enoelken, r. h Enoel, r. e. Enoelken, r. h	8007230342 8007230344 8007240587 8007110436 8007260307	90-206 F 90-312 F 70-25 TOPREP 70-2708	FEE.WF. FEE.WF FEE.WF FEE.WF FEE.WF	8009230749 8009020231 8009020286 8009030532 8009180247	50-245 G 50-213 P 50-245 P 50-213 P 50-336 P	FIELDS, SR FINFROCK, IR FINFROCK, IR FINFROCK, IR FINFROCK, IR	8009090181* 8009120179 8009230104 8009090031	50-219 G 50-219 G 50-219 G 50-219 G
enoelken, r. H. Engelken, r. H Engelken, r. H Engelken, r. H Engelken, r. H.	8007260311 8007120456 8007120458 8007120460 8007120463	70-1470 50-528	FEE.WF. FEE.WF FEE.WF FEE.WF.	8009110245 8009190434 8009120237 8009090636 8009230621	50-245 P 50-245 P 50-213 P 50-245 P 50-213 P	FINFROCK, I R FINFROCK, I R FINFROCK, I R FINFROCK, I R	8009020379 8009020392 8009030340 8009020360 8009190421	50-217 S 50-217 S 50-217 B 50-217 P
ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H. ENGEL, R. E.	8009120468 8009120468 8009180130 8009180134 8009020412*	50-312 0 50-397 0 50-133 0 50-397 0 50-296 P	FEHRINGER, J M FEIERABEND, C D FEID, D FEIL, R. FEIT, R	8009180309 8009260271* 8009300314 8009150097* 8009150562	50-201 G	FINFROCK, I R FINFROCK, I R FINFROCK, I R FINFROCK, I R	8009220283 8009260440 8009300404 8009290365 8009300522	50-219 P 50-219 B 50-219 B 50-219 P
ENCELMENTR H ENCELTR E ENCELTR. E. ENCLETL. B EPSTEINTE.	8009170238 8009160192 8009160424 8009170273* 8009180112*		FELTON, J K FELTON, J M FELTON, J M FELTON, J M FELTON, J M.	8009050123 8009080251 8009080258 8009050383 8009050367	FOIA FOIA FOIA 50-395 P 50-320 P	FINFROCK, I R FINFROCK, I R FINFROCK, I R FINKEL, A E	8009300364 8009300261 8009300270 8009240265 8009100118	50-440 Q
EPSTEIN, E O ERB, C. H ERB, C. M ERB, C. M	8007030554 80071802803 80071505023 80072504153 80072701733	50-346 G	FELTON, J. K FELTON, J. M FELTON, J. K FELTON, J. K FELTON, J. M	8007050488 8007050445 8007020175 8007020182 8007050473	70-1308 FOIA FOIA	FIORELLI.0 FIORELLI.0 FIORELLI.0 FIORELLI.0	8009110307 8009150194 8009250346 8009110620	50-461 G 50-282 G
ERB. C M ERB. W. B. ERNST. M. L. ERTEL. A E. EGMRIDGE, H. E.	8007270215 8007180144 8007080346 8007250422 8007030326	50-320 H 50-247 P 50-289 U * 70-34	FELTON, J. M FELTON, J. H FELTON, J. M FELTON, J. M FELTON, J. M	8007070337 8007050166 8007050177 8007050065 8007050471	70-143 7 70-143 5 50-466 Q	FIDRELLI.0 FIDRELLI.0 FIDRELLI.0 FIDRELLI.0	8009150178 8009150504 8009170217 8009180244	50-546 Q 50-346 Q 50-456 Q 50-373 Q
E8810, T. H.	8009120509 8009290018 8009260665 8009040473	* 50-155 Q * 50-266 Q * 50-346 Q 70-1257	FELTON, J M FELTON, J, M FELTON, J M FELTON, J M FELTON, J M	8009120492 8009020493 8009020813 8009240013 800908043	5 FOIA 1 50-302 H 2 50-263 0	FIORELLI,0 FIORELLI,0 FIORELLI,0 FIORELLI,0 FIORELLI,0	8009020190 800918022 800918022 800915059	3 50-461 8 1+ 50-546 Q 9 50-546 B 4 50-546 Q
ESTEY.H P. ESTEY.H P. ESTRADA.H. ETSEY.H.P. EURY.L.H	8009110278 8009140523 8009240417 8009110271	70-1257 + 50-287 T - 70-1257 50-261 G	FELTON, J M FELTON, J M FELTON, J, M FELTON, J, M FELTON, J M	800708044 800711005 800715000 800712058 800715036	6 50-397 A 2 FOIA 2 50-320 P	FIGRELLI,0 FIGRELLI,0 FIGRELLI,0 FIGRELLI,0 FIGRELLI,0	900918001 900918003 900918023 800902016 800902033	3 50-461 Q 1 50-329 Q 5 50-329 A 1 50-483 S
EVANG, A K.  EVANG, T. P.  EVANG, A.  EVERBT, E. J.  FABRIKANT, R  FABRIKANT, R	8009240284 8009120030 8009190384 80090200355 800904028 80090170236	9# CONTRACT 9# 50-285 G 2# 50-295 B 9 50-445 M	FELTON, J M	800912059 800916035 800917004 800917005 800917006	12 50-364 6 19 FOIA 17 FOIA	FIGRELLIG FIGRELLIG FIGRELLIG FIGRELLIG FIGRELLIG	800903045 800903045 800924045 800929046	7 50-329 S 19 50-373 S 19 50-461 Q

AUTHOR	ACCESSION NUMBER	6UBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOURY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
FIGRELLIG FIGRELLIG FIGRELLIG FIGRELLIG FIGRELLIG	8009100105 8009110445 8009150491 8009300971* 8009100070	50-440 0 50-454 0 50-544 9 50-367 0 50-483 8	FROST, S R FROST, S R FROST, B R FROST, D FROTH, D FROTH, D	8009070548 8009230440 8009240488 8009030663 8009030663	50-255 Q 50-255 P 50-255 8 TOPREP 50-312 P	GEISZEWSKI, P GELSTON, A H GELSTON, A H GEORGIOU, B S	8009220245 8009120443* 8009140378* 8009160468* 8009110019	8M 50-327 B 50-327 B 50-327 B 50-275 0
FIGRELLI,O	8007270077	50-346 Q	FROTH.D J	8009100176*	50-346 P	OECROIDU, B S OECROIDU, B S OECROIDU, B S OERBER, D A OERGELY, P	8009110019	50-275 0
FIGRELLI,O	8007270104	50-546 Q	FROTH.D J	8009290373*	50-329 A		8009220406	50-275 0
FIGRELLI,O	8007270110	50-546 Q	FUHRER.E C	8009260443*	50-289 T		8009230616	50-275 0
FIGRELLI,O	8007270188	50-454 Q	FULLER.J K	8009030540	50-267 P		8009020111*	50-275 P
FIGRELLI,O	8007270525	50-440 Q	FULLER.J K	8009240194	50-267 O		8009020355	NUREO
FIORELLI,O FIORELLI,O FIORELLI,Q FIORELLI,O FIORELLI,O	8009300365 8009100620 8009160248 8009100664 8009100826	50-347	FURBUSH: M H FURR: B J FURR: B J FURR: B J FURR: B J	8009030489 8009020198 8009030307 8009020199 8009230059	50-275	GERSTNER, W C GERSTNER, W C GETTY, B G. GEYER, J C GIBBONS, T D	8009100830* 8009100833* 8009120419* 8009240125* 8009240276*	50-461 Q 50-461 Q 50-133 B 50-263 Q 50-370 Q
FIORELLI.O	8009250205	50-441 G	FURR, B. J	8009230080	50-324 Q	01880NS, T D	8009100307*	50-364 0
FIORELLI.O	8009250230	50-440 G	FURR, B. J	8009230085	50-324 Q	01880N, A F	8009240646*	70-143
FIORELLI.O	8009250474	50-461 S	FURR, B. J	8009240348	50-261 Q	01880N, A F	8009020477*	50-348 0
FIORELLI.O	8009250483	50-546 S	FURR, B. J	8009120228	50-261 Q	01880N, A F	8009240195*	50-302 0
FIORELLI.O	8009250252	50-461 S	FURR, B. J	8009240370	50-324 Q	01880N, O T	8009040330*	50-327 0
FIGRELLI.O FIGRELLI.O FIGRELLI.O FIGRELLI.O	8009240229 8009250479 8009290071 8009290065 8009290448	50-440 8 50-544 8 50-440 8 50-341 8 50-358 9	FURR: B. J FURR: B. J FURR: B. J FURR: B. J GAGLIARDO, J. E	8007110662 8007120366 8007170186 8007260635 8007050477*	50-324 Q 50-325 S 50-324 P 50-324 S 50-267 Q	CIBSON, A F CIBSON, C I CIBSON, J W CIDO, R C CIDO, R C	8009250200* 8009160456 8009300563* 8009020161 8009100036	50-369 0 NUREQ 50-267 # NUREQ NUREQ
FIORELLI,O	8009270472	50-329	GAGLIARDO, JE	8009100055*	50-267 G	OIDO.R Q	8009150599	NUREQ
FIORELLI,O	8009270197		GAHK, JW	8009030640*	50-267 G	OILBERT.L, D.	8009170387*	50-482 Q
FIORELLI,O	8009270202		GAHK, JW	8009160288*	50-267 R	OILBERT.L D	8009150357*	50-458 Q
FISHER,W L	8009100091*		DAHK, JW	8009260396*	50-267 R	OILBERT.L D	8009100279*	50-445 Q
FISHER,W L	8009150165*		GAHK, JW	8009160299*	50-267 R	OILBERT.L D	8009190340*	50-382 Q
FISHER.W L FIGHER.W L FISHER.W L FISHER.W L FISHER.B P	8007030675* 8007240255* 8007270074* 8007260634* 8007170178	50-263 F 50-282 F 70-1308 50-315 Q MISC	QAHKIJ.W QALLACHER.E J QALLACHER.E J QALLACHER.J W. QALLACHER.E J	8007230607* 8007180073* 8007180061* 8007120165 8007180033*	50-267 8 40-8584 50-461 G 50-277 G 40-2259	OILBERTS, D E	8009150076 8009150218 8009110534 8009110539 8009090019	50-282 G 50-282 G 50-282 G 50-282 G
FITTI,C FITZPATRICK,R FITZBIMMONB,O FLACK,W FLACK,Q	8009220420* 8009170349* 8009230473* 8009110297 8009300375	50-466 0 50-287 T TUPREP 50-293 0 50-424 9	QALLEN,K P. GALLEN,K P GALLO,R M GALLO,J GALLO,J	8007070334 8007070334 8007170241* 8007150344* 8007150344*	50-409	OILBERTS, D E OILBERTS, D E, OILBERTS, D E OILBERTS, D E OILBERTS, D E,	8009110499 8009250411# 8009170405 8009170441 8009180007	50-263 Q 50-263 Q 50-262 Q 50-263 Q 50-263 Q
FLANDERB.W L FLANIGAN,L J FLANIGAN,L J FLANNIGAN,R.D FLAXMAN,C A	8009300430* 8009100043 8009300164 8009030190* 8009190046	50-307 R NUREO NUREO 50-278 S 50-280 O	OALLO, J GALLO, J GALLO, J GANO, H & GANTHNER, R W	8009130339 8009220185 8009220216* 8009160366 8009080438*	50-155 G 50-155 G 50-155 G TOPREP 50-312 P	GILBERTS, D E GILBERT, J D GILNSKY, V GILNSKY, V	8009170413 8009150599 8009050335# 8009230260# 8009230289#	50-263 Q NUREQ 50-338 R FOIA FOIA
FLAXMAN, CA	8009150075*	50~250	QARCIA, M	8007030581	50-275 H	OILINSKY,V	8009270021	50-327 T
FLEENOR, CH	8009150409		GARNER, D J	8007170244*	50-312 P	OILLESPIE,F P	8009170651*	50-259 Q
FLEENOR, CH	8009300271		GARNER, D J.	8007230765	50-312 F	OILLESPIE,F P	8009100914*	70-143
FLEISCHAKER, D	8009160234		GARRETT, E G.	8008120480	50-309 H	OILLESPIE,F P	8009110173*	50-250 G
FLEISCHAKER, D	8009160234		GARRETT, E G	8008120525	50-309 H	OILLESPIE,F P.	8009120133*	70-143
FLEISCHAKER, D FLEISCHAKER, D FLEISCHAKER, D FLYNN, M FLYNN, M FLYNN, M J	8009220262 8009220262 8009240544 8009110022 8009030080	50-275 G 50-275 G 50-275 G CONTRACT CONTRACT	QARRETT, E O QARRETT, E O QARRETT, E O QARRETT, E O QARRITY, J, H	8008120534 6008120549 8008120555 8008120549 6009230455	50-309 H 50-309 H 50-309 H 50-309 H 50-309 R	OILLESPIE,F P OILLESPIE,F P OILLESPIE,F P OILLESPIE,F P	8009110142* 8009110191* 8009190398 8009170152* 8009250439*	70-1181 50-327 Q NUREO 50-302 Q 70-143
FLYNN,M J	8009120659	CONTRACT	QARRETY, J H	\$009300426	50-307 R	OILLEN.D M	8009100133	40-4492
FLYNN,P.G.	8009040289	50-445 M	QARY, R J	8009170420	50-445 G	OILLESPIE.F P	8009100795*	70-27
FLYNN,M J	8009300206	CONTRACT	QARY, R. J	8009150213	70-2932	GILLESPIE.F P	8009250066*	70-1151
FODE6,R L	8009220289*	50-255 8	QARY, R. J	8009150213*	70-2932	OILLETT,W.T	8009160277*	50-315 R
FOLK,J.	8009220200*	50-287 H	QARY, R. J	8009150012	50-445 G	OILLETT,W T	8009160283*	50-316 R
FONO, T.	8009300324*	50-344 0	QARY, R. J	8009290571*	50-445 G	GILLMAN,D W	8009190344*	50-341 M.
FORD, E. J.	8009120071*	50-349 0	QARY, R. J	8009180045	50-445 B	GILLDGLY,J	8009290423	F01A
FOREMAN, H.	8009160530	70-2909	QARY, R. J,	8009180457	50-445 G	GINSBURG,R A	8009290180	50-280 Q
FOSTER, W. E.	8009150100*	50-445 0	QARY, R. J,	8009300055	50-445 G	GIRARD,E H	8009030140*	50-373 Q
FOSTER, J. M.	8009160511	CONTRACT	QARY, R. J	8009090387	50-445 V	GITLEN,P H	8009110484	50-201 Q
FOSTER, J M	8009110375	CONTRACT	GARY, R. J	8009300070	50-445 G	OITLEN,P H	8009120545	50-201 P
FOSTER, L, E	8009260308*	50-314 G	GARY, R. J	8009160362	50-445 A	GIVEL,M 8	8009020517	50-302 H
FOSTER, J E	8009260415*	50-327 G	GARY, R. J	8009300065	50-445 G	GIVEL,M 8	8009240611	50-302 P
FOUCHARD, J J	8009050462*	FDIA	GARY, R. J	8009300074	50-445 G	GLAGDLA,A F	8009150140	CONTRACT
FOUKE, R L	8009260005	50-445 G	GARY, R. J	8009220334	50-445 A	GLAGDLA,A F	8009150143*	CONTRACT
FOX: D. F	8007150234*	GA979	GARY, R. J.	8009230301	50-445 8	QLAGOLA,A.F	6007160471	CONTRACT
Francie, K. A	8007040437	NUREO	GABBER, E. R.	8009110222*	CONTRACT	QLAGOLA,A.F	8007160495*	CONTRACT
Francie, E. 1	8007250313*	GA979	GABBER, E. R.	8009260242*	CONTRACT	QLAGOLA,A.F	6007110377*	CONTRACT
Francie, C. C	8007020358	NUREO	GAULKE, A. E.	8009190422	50-315 R	QLAGOLA,A.F	6007100012*	CONTRACT
Francie, C. P	8007230148*	50-289 H	GAWRYCH, M. A.	8009120295	50-387 0	QLAGOLA,A.F	8007250477*	CONTRACT
Frankil	8007120337	NUREO	GAY.G M	8009090238	50-445 G	OLAOOLA,A F	8007230161*	CONTRACT
Frantzi B. P	8007170037	50-367 0	GAY.G M	8009090238	50-445 G	OLANTZ,C.	8007230222*	50-320 H
Frantzi B. P.	8007230035	50-367 0	GAY.G M	8009150045	50-445 G	OLEABON,G L	8007170668*	FOIA
Frantzi B. P.	8007300576	50-367 0	GAY.G M	8009150045	50-445 G	OLENN,J.E.	8007270087*	FOIA
Freeman, M. D	8007150577*	40-8769	GEHR.A C	8009030689	50-275 G	OLENN,J E	8007270152*	FOIA
FREEMAN, J	8009250486	FOIA	QEHR, A C	8009030689	50-275 Q	GODDARD,R J. GODDARD,R J GOLCHERT,N,W, GOLCHERT,N,W, GOLDBERG,S C. GOLDBERG,S C	8007260310	50-471 Q
FREEMAN, M D	8009150575	40-8768	GEHR, A C	8009030714	50-528 Q		8007300045	50-237 Q
FRIESEMA, H P	8009100463*	50-275 H	GEHR, A. C	8009030714	50-528 Q		8007040104*	40-2061
FRIZZLE, C D	8009230591*	50-309 P	GEHR, A. C	8009030699	50-275 Q		8007110018	50-347 Q
FRONNE, R.	8009020376*	50-346 G	GEHR, A. C	8009030699	50-275 Q		8007120416	50-320 P

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
COLDBERG. S C OCLDBERG. S C OCLDBERG. S C OCLDBERG. S C OCLDBERG. S C	8009170167 8009170282 8009230041 8009250024 8009300005	50-367 0 50-395 0 50-367 0 50-250 0 50-367 0	ORIER, BH GRIER, BH GRIER, BH GRIER, BH GRIER, BH	8007070074 8007070076 8007070101 8007070105 8007070106	50-387 0 50-354 0 50-271 0 50-277 0 50-333 0	GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8009180037 8009180042 8009180044 8009180048 8009180050	50-387
OOLDEN, J. C. OOLLER, K. R. OODDHOPE, A. C. OODDHOPE, A. C. OODDLING, B.	8009030440* 8009020531* 8009120022 8009120409 8009030432	50-295 P RECOD 70-1308 27-39 50-289 H	GRIER, BH GRIER, BH GRIER, BH GRIER, BH GRIER, BH	8007070111 8007070113 8007070168* 8007100034 8007100037	50-245 Q 50-293 Q 50-219 Q 50-217 Q 50-293 Q	GRIER.B H ORIER.B H ORIER.B H ORIER.B H ORIER.B H	8009180051 8009180055 8009180057 8009180339 8009180478	50-485 G 50-271 G 50-27 G 50-3 G 50-334 G
COORLING B COORMAN L. S. COORMAN L. S COORMAN L. S COORMAN L. S	8009230442* 8009030457* 8009160253* 8009230657* 8009230664*	50-287 H 50-407 B 50-409 R 50-409 B 50-409 B	GRIER, BH GRIER, BH GRIER, BH GRIER, BH GRIER, BH	8009140421* 8009150130 8009140225 8009140220 8009090145	50-277 Q 50-271 Q 50-277 Q 50-244 Q 50-219 Q	GRIER.B H GRIER.B H GRIER.B H GRIER.B H GRIER.B H	8009180483 8009180948 8009230162 8009230165 8009230167	50-412
ODORKAN, L. S ODORHIN, C. SOODHIN, H. L. SOODHIN, C. OODBHIN, C.	8009260636* 8009160620 8009110135* 8009150009 8009150039	50-407 8 50-344 9 70-1151 50-344 9 50-344 9	ORIER.B H ORIER.B H ORIER.B H ORIER.B H ORIER.B H	8009120550 8009120709 8009120469 8009120101 8009110257	50-322	ORIER. B H ORIER. B H ORIER. B H ORIER. B H ORIER. B H	8009230169 8009230172 8009230174 8009230175 8009230178	50-213 F 50-334 F 50-219 F 50-289 F 50-309 F
COODMIN. C COODMIN. C COODMIN. C. COODMIN. C	8009190691 8009280337 8009300314* 8009240375 8009030875	NUREO 50-344 G 50-344 G 50-344 G 50-344 R	ORIER, BH ORIER, BH ORIER, BH ORIER, BH ORIER, BH ORIER, BH	8007120585 8007150465 8008280053 8008280054 8007030037	40-672 50-245	ORIER, BH ORIER, BH ORIER, BH ORIER, BH ORIER, BH	8007230180 8007230184 8007230185 8007230188 8007230187	50-220 F 50-286 F 50-333 F 50-171 F
QDODHIN; C QOODHIN; C, QOODHIN; C QOODHIN; C,	8009100509 8009110308 8009180379 8009180385 8009180468	50-344 F 50-344 Q 50~344 B 50-344 P 50-344 P	ORIER, D H ORIER, B. H ORIER, B H ORIER, B. H ORIER, B H	8007030042 8007030044 8007030047 8007030059 8007030060	50-363 0 50-289 0 50-443 0 50-485 0 50-354 0	QRIER.B H GRIER.B H GRIER.B H GRIER.B H	8009230193 8009230196 8009230199 8009230200 8009230211	50-272 F 50-244 F 50-271 F 50-29 F
OCCUPATION C CORPONIC Z CORPONIC A CORPORIC V. CORPORIC V.	8009220343 8009240729* 8009160414 8009190358* 8009150005*	50-344 P 40-299 50-387 Q FOIA FOIA	GRIER, B H GRIER, B. H GRIER, B H GRIER, B H GRIER, B H	8009030063 8009030066 8009030069 8009030070 8009030073	50-29 Q 50-271 Q 50-219 Q 50-334 Q 50-3 Q	ORIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8009230215 8009230220 8009230223 8009230225	50-201 F 70-33 70-371 70-820 70-1143
ORAEGBER, K L ORAEGBER, K L ORAEGBER, K L ORAEGBER, K L ORAEGBER, K L	8007020447 8007030441 8007020375 8007020276 8007020452	50-275 8 50-275 R 50-275 8 50-304 8 50-295 B	ORIER.B H ORIER.B H ORIER.B H ORIER.B H ORIER.B K	8009030075 8009030076 8009030081 8009030083 8009030086	50-412	ORIER, B H ORIER, B H ORIER, B H ORIER, B H ORIER, B. H	8009120166 8009120169 8009120171 8009120174	50-293 0 50-317 0 50-3 9 50-213 0
GRAEBBER, K.L. GRAEBBER, K.L. GRAEBBER, K.L. GRAEBBER, K.L.	8009120299 8009120302 8009120305 8009090294 8009160293	30-295 8 50-295 8 50-295 8 50-295 R 50-304 8	QRIER.B H QRIER.B H ORIER.B H QRIER.B H QRIER.B H	8009030087 8009030089 8009030090 8009030091 8009030094	50-410 G 50-322 G 50-244 G 50-272 G 50-333 G	GRIER.B H GRIER.B H GRIER.B H GRIER.B H GRIER.B H	8009120177 9009120180 8009120184 8009120186	50-363 Q 50-322 Q 50-287 Q 50-307 Q
GRAEBBER, X L GRAEBBER, K L GRAEBBER, K L GRAEBBER, K L GRAEBBER, K L	8009160408 8009220274 8009220349 8009220381 8009230481	50-275 8 50-304 8 50-275 8 50-275 8 50-304 8	QRIER.B.H ORIER.B.H GRIER.B.H GRIER.B.H GRIER.B.H	8007030075 8007030077 8007030107 8007030111 8007030113	50-309 Q 50-220 Q 50-317 Q 50-293 Q 50-213 Q	GRIER.B H GRIER.B H GRIER.B H GRIER.B H GRIER.B H	8007120173 8007120176 8007120200 8007120204	50-410
ORAEBSER, K.L.  ORAHAM, E. T.  ORAMM, P.  ORAMY, M.  ORAVEG, R. H.	B009290317* B009120494 B009130164 B009020015	+ 50-293 8 + COMMISSION	ORIER, BH ORIER, BH ORIER, BH ORIER, BH ORIER, BH	8007100454 8007230405 8007230406 8007230407 8007230412	50-213 P 70-1100 70-1143 70-135 50-201 Q	GRIER, B H	8009120211 8009120213 8009120215 8009120216	50-443
ORAYES R H ORAY, J R ORAY, J R ORAY, J R ORAY, J R.	8007040272 8007070252 8007160137 8007170165	50-142 0 50-344 0 50-287 0 50-287 0	GRIER, B H ORIER, B. H ORIER, B H ORIER, B H ORIER, B H	8009230413 8009230415 8009230414 8009230419 8009230421	70-820 70-33 70-371 70-687 70-398	ORIER.B H ORIER.B H ORIER.B H ORIER.B H ORIER.B H	8009120229 8009120230 8009120233 8009120237 8009120239	50-219 0 50-220 0 50-333 0 50-277 0 50-354 0
ORAY, J. R ORAY, J. R OREMMAN, E OREENMAN, E OREENMAN, E	8009260003 8009260004 8009260006 8009110304 8009090250	* 50-287 G * 50-287 G * 50-333 G * 50-287 G	GRIER, B. H GRIER, B. H GRIER, B. H GRIER, B. H GRIER, B. H	8009120084 8009120087 8009120088 8009120090 8009120095	50-293	GRIER, B H ORIER, B H ORIER, B H ORIER, B H	8009120243 8009230490 8009230493 8009230495	50-244 9 50-293 9 50-219 9 50-220 9
GREENHAN, E GREENHAN, E GREEN, D GREENKORN, R GREGER, L. R.	8009180005 8009020501 8009170277 8009240130 8009240235	90-277 8 * 50-259 R 0* CONTRACT 3* 50-282 F	GRIER, 8 H GRIER, 8 H GRIER, 8 H GRIER, 8 H GRIER, 9 H	8009120097 8009120100 8009120103 8009120103 8009120103	50-277 G 50-352 G	GRIER, B H GRIER, B H GRIER, B H GRIER, B H	9009230499 9009230514 9009230519 9009230775	50-333
GREGORY, W 8. GREGORY, W 8. OREW.P. GREW.P.C.	8009120572 8009160492 8009240125 8009030643 8009110026	2 RE8 5* 50~263 G 3* PR 5 PR	GRIER, B. H ORIER, B H ORIER, B H ORIER, B H ORIER, B H	8007120110 8007120110 800718000 8007180000 8007180000	50-271 0 50-213 0 50-363 0	GRIER.B H GRIER.B H GRIER.B H GRIER.B H GRIER.B H	8009230778 8009230779 8009230780 8009230782	50-3 4 50-213 9 50-334 9 50-217 0
ORIDLEY, C F ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H.	8009030520 800918057 791219007 791219001 800305022	3* 50-327 5 2 50-317 G 3* PT9 4 PT9 4* PT9	ORIER, B. H GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H	800918000 800918001 800918001 800918001	3 50-289 G 5 50-309 G 7 50-245 G	GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8007230770 8007230770 8007230770 8007230773	50-289 Q 50-245 Q 50-220 Q 50-286 Q
ORIER, B H ORIER, B H ORIER, B. H	800215027 800305021 800929014 800909008 800909008	5 PT9 5 PT9 0* FOIA 5 50-322 G 7 50-410 G	GRIER, B. H GRIER, B. H GRIER, B. H GRIER, B. H GRIER, B. H	800418003 800418003 800418005 800418005	3 50-410 Q 5 50-286 Q 8 50-333 Q 0 50-277 Q	GRIER, BH GRIER, BH GRIER, BH GRIER, BH GRIER, BH GRIER, BH	800923079 800923079 800923079 800923079	50-354 G 50-443 G 50-485 G

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESS I ON NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEODRY
GRIER.B M	8009240030	50-309 0	HAASB,W P	8009290379	MISC	HARMON, D W	8009300668	XPDRILIC
GRIER.B M	8009240031	50-412 0	HACKNEY, B D	8009030563*	50-528 8	HARMON, D W	8009290187	XPORILIC
GRIER.B H	8009240032	50-363 0	HAFERA, T	8009080427*	50-254 8	HARRAN, G	8009190459#	30-245 A
GRIER.B H	8009240033	50-410 0	HAFFMAN, D P	8009190661	PRM	HARRIS, J R	8009100149#	50-369 Q
GRIER.B H	8009240035	50-333 0	HAGA, P B	8009100586	50-437 A	HARRIS, J R	8009150370#	50-321 Q
ORIER.B H	8009240043	50-277 Q	HAGAN, T. F	8009110215	CONTRACT	B L'SIBNAH	8009150177#	50-545 Q
ORIER.B H	8009240045	50-272 Q	HAGAN, T F	8009240229	CONTRACT	B L'AIBNAH	8009110769#	50-545 Q
GRIER.B H	8009240048	50-244 Q	HAGAN, T F	8009180167	CONTRACT	B L'AIBNAH	8009180221#	50-545 Q
GRIER.B H	8009240050	50-29 Q	HAGAN, T F	8009300193	CONTRACT	B L'SIBNAH	8009250343#	50-410 Q
ORIER.B H	8009240215	50-77 Q	HAGEY, H	8009110412	CONTRACT	B L'SIBNAH	8009020285#	50-336 S
ORIER, B H ORIER, B H ORIER, B H ORIER, B H ORIER, B H	6009240218 8009240221 8009240225 8009240227 8009240231	50-208	HAGEY, H HAGEY, H HAGEY, H HAGEY, H	8007030208 8007020475 8007160485 8007110409 8009230768	CONTRACT 70-2919 CONTRACT CONTRACT CONTRACT	HARRIB.J F HARRIB.D R HARRIBON.P HARRIBON.P. HARRIB.J B	8009120448 8009300207 8009150266# 8009160467# 8009190531#	50-361 H 71-374 50-220 8 50-220 8 60-336 8
GRIER, B H	8009240234	50~225 Q	HAGEY, H	8009230774	CONTRACT	HARRIS, J S. HARRIS, J S HARRIS, J, S HARRIS, J, S HARRIS, J, S	8007170537*	50-334 8
GRIER, B H	8009240238	50~57 Q	HAGEY, H	8009120004	CONTRACT		8007170543*	50-334 8
GRIER, B H	8009240242	50~223 Q	HAGEY, H	8009240034	CONTRACT		8007160461*	50-334 8
GRIER, B H	8009240247	50~166 Q	HAGRMAN, D	8009100530	REB		8007160464*	50-334 8
ORIER, B H	8009240250	50~134 Q	HAIRSTON, C A	8009100010	CONTRACT		8007160467*	50-334 8
GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8009240252 8009240268 8009240271 8009240275 8009240277	50-22 0 50-54 0 50-193 0 50-170 0 50-47 0	HAIRSTON,C HAIRSTON,C A HAIRSTON,C A HAIRSTON,C A HAIRSTON,H G	8009250493 8009230157 8009190051 8009190057* 8009020048*	CONTRACT CONTRACT CONTRACT CONTRACT 50-348 B	HARRISON:P HARRIS:J E HARRISON:P HARRIS:V A HART:J.L.	8009180278# 8009260654# 8009300495# 8009300442 8009100435	50-220 8 50-334 8 50-220 8 50-445 6 50-445 9
GRIER.B H GRIER.B H GRIER.B H GRIER.B H ORIER.B H	8009240278 8009240281 8009240285 8009240303 8009240304	50-184 G 50-184 G 50-317 G 50-293 G	HAIRSTON, W O HAIRSTON, C HAIRSTON, C HAIRSTON, C HAIRSTON, W O	8007030427* 8007260676 8007160270* 8007300573 8007160323*	50-34B 8 CONTRACT 50-34B R CONTRACT 50-34B 8	HART, J. L HART, J HART, J. HARTMAN, D HARTMETT, R A	8007240005 8007240008 8007300338 8007160546 8007270376#	50-445 0 50-445 0 50-382 6 40-8745 50-382 8
ORIER B H ORIER B H ORIER B H ORIER B H ORIER B H	8009240308 8009240309 8009240311 8009240315 8009240316	50-213	MAIRSTON, C MAIRSTON, W. C. MAIRSTON, W. C. MAIRSTON, W. C. MAIRSTON, W. C.	8007300281 8007140308* 8007230729* 8007230737* 8007300577*	40-299 50-348	HARTZMAN, M HARVEY, J, L HARWOOD, T P HABBROOK, R E HAWKINB, F, C	8009240686 8009150390 8009090343# 8009120012# 8009110769#	NUREQ 71-9044 50-339 U CONTRACT 50-546 Q
GRIER. B. H	8009240319	50-245 Q	HAIRSTON, W O	8009300527*	50-348 8	HAWKINS, F. C	8009270107*	50-546 Q
GRIER. B. H	8009240323	50-410 Q	HAIRSTON, W G	8009300515*	50-348 8	HAWLEY, B. C.	8009030530*	50-27 R
GRIER. B H	8009240324	50-333 Q	HALE, C J	8009150234*	GA999	HAWTHORNE, S	8009070238	50-445 9
GRIER. B H	8009240325	50-277 Q	HALE, C J	8009120335*	GA979	HAWTHORNE, S	8009070238	50-445 9
GRIER. B H	8009240328	50-387 Q	HALE, C, J	8009120457*	GA999	HAYES, D. W.	80090110324*	50-454 B
GRIER, B. H	8009240330	50-354 Q	HALL,RE	8009150093*	50-445 Q	MAYES, D. W	8009170221#	50-456 0
GRIER, B H	8009240332	50-443 Q	HALL,RE	8009100950	NUREO	HAYES, D. W	8009110769#	50-546 0
GRIER, B H	8009240335	50-485 Q	HALL,RE	8009090569	30-293 F	HAYES, D. W	8009290107#	50-546 0
GRIER, B H	8009240337	50-271 Q	HALL,RE	8009090364	50-171 F	HAYNES, R. C	8009020267#	50-361 0
GRIER, B H	8009240338	50-29 Q	HALL,RE	8009050533*	50-498 Q	HAYNES, R. F	8009050409	REG
ORIER, B H	8007240342	50-412 Q	HALL,R E	8009170387*	50-482 @	HAYNES, J. Q	800924050B	50-206 G
ORIER, B, H	8007240345	50-217 G	HALL,R E	8009100279*	50-445 @	Hazelriqq, 8	8009020455*	50-275 8
ORIER, B H	8007240346	50-220 G	HALL,R E	8009250398*	50-458 @	Hazelton, W B,	8009120337	NUREO
ORIER, B H	8007240349	50-286 Q	HALL,R E	8009250405*	50-498 @	Hazle, A J	8009190874	Btate Frod
ORIER, B H	8007240353	50-352 Q	HALL,R E	8009190340*	50-392 @	Hazle, A	8009190877*	State Frod
GRIER, 8 H	8007240355	50-272 Q	HALL,R E	8007300102*	50-498 0	HEARN.P.C	8009170351*	50-269 T
GRIER, 8 H	8007240361	50-244 Q	HALL,R E.	8007150362*	50-458 0	HEGNER.J D	8009110050*	50-334 0
GRIER, 8 H	8007240362	50-307 Q	HALL,R E	8007020032	50-293 E	HEIDER.L H	8009230100	50-271 0
GRIMES, 8 K	8007160570	50-289 Q	HALL,R E	8007020053	50-171 E	HEIDER.L H	8009020021	50-29 P
GRIMES, 8 K	8007070782	50-544 F	HALL,R E.	8007070362	50-171 F	HEIDER.L H	8009080375	50-271 P
ORIMES, B X OROCE, R H OROCE, R H OROMOL, M B OROSSHAN, X	8009120592	50-349 F	HALL.R E	8007070564	50-285 F	HEIDER,L H	8007120401	50-271 P
	8009090468	50-309 R	HALL.R E.	8007070424	50-171 F	HEIDER,L H	8007180451	50-271 P
	8009100425	50-309 P	HALL.R E	8007220375	TOPREP	HEIDEL,C.M.	8007240507*	50-241 A
	8009100219*	GA999	HALLER,N	8007230232*	FOIA	HEINAMOY,V A	8007030503*	50-202 B
	8009020505	FOIA	HALLER,N M	8007240134*	50-313 8	HEINZ,J	8007150448*	COMMISSION
Ordsman, H	8007020402	50-347 0	HALLIOAN,T J	8009180394	50-387 0	HEISHMAN.R F.	8007270020*	50-046 0
Ordsman, H	8007070420	50-347 0	HALMAN,E L	8009030255*	SECY	HEISHMAN.R F	8007260418	50-409 0
Ordsman, H	8007170175	50-155 0	HAMILTON,W P	8009240421*	50-289 T	HEISHMAN.R F	8007050208	50-255 0
Ordsman, H	8007230030	50-155 0	HANAUER,B,H	8009250453*	FOIA	HEISHMAN.R F	8007100132	50-255 0
Ordsman, H	8007300033	50-155 0	HANAUER,B H	8009050126*	FOIA	HEISHMAN.R F	8007100143	50-10 0
GROSSMAN, H OROSSMAN, H OROTENHUIS, M OROTENHUIS, M OROTENHUIS, M	8007300036* 8007300331 8007170607* 8007120047 8007170708	50-155 Q 50-367 Q 50-334 P 50-250 P 50-250 P	HANGOCK, J. A HANGOCK, J. A HANGOCK, J. A HANGOCK, J. A	8009020197 8009240184* 8009030200 8009030475 8009030497	50-302 B 50-302 Q 50-302 R 50-302 B 50-302 S	HEISHMAN,R F. HEISHMAN,R F. HEISHMAN,R F HEISHMAN,R F HEISHMAN,R F	8007020117 8007100154 8007150022 8007160610 8007020183	50-358 A 50-331 Q 50-373 Q 50-305 Q 50-316 P
GUAGUIL.L GUHIN.M A GUHIN.M A GUILBERT.D E GUILBERT.D E,	8009120395 8009090434* 8009090430* 8009180185* 8009180177*	50~322 A XPORTLIC XPORTLIC GA999 GA999	HANCOCK, JA HANCOCK, JA HANCOCK, JA HANCOCK, JA	8007030600 8007050265 8007110337 8007150280 8007300027	50-302 S 50-302 S 50-302 S 50-302 S 50-464 Q	HEIBHMAN,R F HEIBHMAN,R F HEIBHMAN,R F HEISHMAN,R F HEIBHMAN,R F	8009160509 8009260304 8009290109 8009300236 8009260263	50-350 q 50-314 q 50-255 q 50-346 q 50-282 q
GULBRANSEN, & A GULDEMOND, W G GURUNATHAN, S GURUNATHAN, S, GUSTAVE, R P	8009040412 8009290015* 8009120324* 8009120331* 8009240065	50-320 P 50-266 G 50-275 S 50-275 S CONTRACT	HANGOCK, D HANGOCK, J. A HANNON, J. N HANGEN, L. E HANGEN, L. E	8009300027 8009290290 8009300038 8009260184 8009260105	50-466 0 50-302 8 TOPREP 71-9022 71-6581	HEISHMAN, R.F. HEISHMAN, R.F HEISHMAN, R.F HEISHMAN, R.F HEISHMAN, R.F	8007250345 8007260375 8007270425 8007030115 8007300217	50-315 Q 50-295 Q 50-255 Q
Custave, R. P	8009120013	CONTRACT	HANSON, D. J	8009260069	RES	HEISHMAN, R. F.	8007110727	50-255 0
Qutmann, P.	8009150143*	CONTRACT	HARDIN, A. K	8009240284*	50-324 Q	HEISHMAN, R. F.	8007250338	50-275 0
Qutme in, E. E	8009190123*	40-2061	HARDI, A. R	8009300041*	50-416 Q	HEISHMAN, R. F.	8007270440	50-315 0
Haase, W. P	8008210180	50-261 P	HARMON, D. W	8009230799	XPORTLIC	HEISTAND, Q. S.	8007020041	50-409 0
Haase, W. P	8009190157	TOPREP	HARMON, D. W	8009090659	XPORTLIC	HEISTAND, Q. S.	8007020041	50-409 0

AUTHOR	ACCESSION NUMBER	SUBJECT Category	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
EISTAND, O 8 ELVLY, B J ELLER, J, K ELVLER, J K ELVLCK, C	8009300008 8009170011* 8009050216* 8009300824* 8009230016	50-409 0 50-289 H 50-255 0 50-255 Q 50-142 Q	A L. GNIH A L. GNIH A L. GNIH A L. GNIH A L. GNIH	8008280495* 8008280488 8009030133* 8009030126 8009110732	50-254 G 50-254 G 50-255 G 50-295 G 50-275 G	HOVEY, O K HOVEY, O K HOVEY, O K	8009020075 8009020241 8009030372 8009030529 8009030349	50-320 P 50-320 G 50-320 P 50-320 P 50-320 S
ENDRIE.J M ENDRIE.J H ENDRIE.J, M ENDRIE.J, M ENDRIE.J K	8009150032* 8009150035* 8009150039* 8009150047* 8009150054*	COMMISSION COMMISSION SO-271 U COMMISSION COMMISSION	HIND, J A HINES, E HINES, E HINES, E	8009150462 8009250419 8009180016 8009180029 8009090417	50-305	HBAEA'G K HDAEA'G K HDAEA'G K HDAEA'G K	8007030473 8009160384 8007090502 8007090556 6009160382	50-320 P 50-320 P 50-320 H 50-320 H 50-320 P
ENDRIE, J. H ENDRIE, J. H ENDRIE, J. K HENDRIE, J. H HENDRIE, J. H	8009150030* 8009150054* 8009150061* 8009150074* 8009150090*	COMMISSION COMMISSION COMMISSION COMMISSION	MINEB, E MIRSCH, D. MIRSCH, D MJELMFELT, D C MJELMFELT, D C	8009250446 8009040203 8009240466 8009260662 8009260662	50-341 0 50-142 0 50-142 0 50-348 M 50-348 M	HOVEY, O K HOVEY, O K HOVEY, O K	8009140395 8009170334 8009180415 8009120402 8009120450	50-320 P 50-320 G 50-320 S 50-320 S 50-320 S
HENDRIE, J. H HENDRIE, J. H HENDRIE, J. H HENDRIE, J. K	8009150026* 8009190707 8009110417 8009090601 8009020202	COMMISSION COMMISSION COMMISSION	HOBBB: F T HORBB: F T. HOCKER, H M HODDER: M H HODDER: M H	8009240086# 8009190638* 8009090571 8009190046 8009150095*	FOIA FOIA 50-320 H 50-250 G 50-250 G	HOVEY. 0 K HOVEY. 0 K HOVEY. 0 K	8009120454 8009180432 8009150554 8009160381 8009170314	50-320 P 50-320 P 50-320 P 50-320 P 50-320 P
HENDRIE, J. H HENDRIE, J. H HENDRIE, J. H HENDRIE, J. M HENDRIE, J. M	8009020204* 8009020206* 8009020207* 8009020210* 8009020212*	COMMISSION COMMISSION COMMISSION COMMISSION	HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P.	8009110820* 8009030117* 8008130378* 8009110730* 8009020070	50-155 G 50-255 G 40-277 50-255 G 50-155 S	HOVEY, O K HOVEY, O K HOVEY, O K HOVEY, O K	6009170377 8009180404 8009220277 8009190490 8009220129	50-320 P 50-320 S 50-320 P 50-320 R 50-320 P
HENDRIX, O W HENDRIX, O W HENDRIE, J. M HENDRIE, J. M HENDRIE, J. M	8009080442 8009150188 8009150020 8009110525 8009100597	71-4888 71-112 50-201 U COMMISSION 50-443 0	HOFFMAN, D P HOFFMAN, D P HOFFMAN, D, P HOFFMAN, D P HOFFMAN, D P.	8007020262 8009020265 8007030544 8007030583 8007030624	50~255 Q 50~155 S 50~155 R 50~255 S 50~255 Q	HOVEY, O K HOVEY, O K HOVERD, E M HOVERD, E M HOVERD, E, M	8007220276 8007300387 8007150050* 8007150057* 8007150063*	50-320 P 50-320 P 50-445 0 50-445 0 50-445 G
HENDRIE, JH HENRY, JJ HENRY, LO HENRY, LO HENSLEY, KD	8009240459 8009050337 8009040376 8009160338 8009150027	50-389 Q PRM 30-57 P 50-57 I 70-143	HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P.	8009100574 8009180102 8009030430 8009030490 8009040423	50-155 P 50-155 Q 50-255 P 50-155 P 50-155 P	HOWARD, E H HOWARD, E K HOWARD, J E HOWARD, J E HOWARD, E M	8009150068* 8009150113* 8009150270 8009150284 8009300190	50~445 G 50~445 G 50~293 P 50~293 P 1&E
HENSLEY, X D HENSLEY, K D HERBETH, J O HERBETH, J G	8009240858 8009300475 8009030464 8009080240 8009030472	70-143 70-143 50-287 V 50-287 V 50-287 P	HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P	8007080406 8007080418 8007080432 8007100573 8007260125	50-255 8 50-255 8 50-255 8 50-155 P 50-155 0	HOWELL, D B HOWELL, B K HOWELL, B K	8009250351* 8009100241 8009180450 8009260075 8009120536*	50-400 G 50-400 G 50-400 G REB 70-343
Herbein, J 0 Herbein, J 0 Herbein, J 0, Herbein, J 0 Herbein, J 0	8007020008 8007020013 8007030481 8007080369 8007110316	50-287 P 50-287 G 50-287 P 50-287 P 50-287 R	HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, O. P. HOFFMAN, D. P. HOFFMAN, D. P.	8009260146 8009090438 8009090500 8009100321 8009120364	50-155 0 50-155 8 50-327 A 50-155 P 50-255 \$	HOWELL, J C HOWELL, J C HOWETT, Q H HOWEDN, T O HOY, C E	8009110173* 8009170152* 8009230347* 8009180359 8009040115	50~250 G 50~302 G 50~336 R 50~320 P PR
HERBEIN, J O HERDI, A. R. HERDI, A. R. HERDI, A. R. HERDI, A. R.	8009120341 8009240241* 8009240374* 8009240313* 8009120499*	50-287 8 50-367 9 50-324 9 50-413 0 50-250 9	HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P.	8009110428 8009140370 8009190098 8009250276 8009220285	50-255 F 50-255 R 50-155 B 50-155 P 50-255 B	HOYLE, J. C HOYLE, J. C HOYLE, J. C HOYLE, J. C	8007030102 8007030105* 8007120528 8007100635* 8007170266*	10CFR 10CFR 50~327 D MISC ACRS
HEADT. A R HERDT. A R. HERDT. A HERDT. A R. HERDT. A R	8007030140* 8007150377* 8007170607* 8008280126* 8007050421*	50-375	HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P	8007230612 8007300231 8007230436 8007230458 8007270364	50-255 B 50-155 P 50-255 P 50-255 P 50-255 P	HOYLE, J C HOYLE, J C HOYLE, J C HOYLE, J C	8009100920* 8009150440 8009160079 8009160083 8009120104	ACRS ACRS ACRS 50-327 D CONTRACT
HERDY, A.R. HERDT, A.R. HERDT, A.R. HERDT, A.R. HERDT, A.R.	8009240320* 8009240421* 8009110198* 8009180162* 8009240071*	50-413	HOFFMAN, D HOFFMAN, D P. HOFFMAN, D P HOFMAN, D P HOFMAN, R	8007300484 8007300487* 8007300492 8007300497* 8007120607	50-255 E 50-255 E 50-255 E 50-255 E XPORTLIC	HOYLE, J. C HOYLE, J. C HOYLE, J. C HOYLE, J. C HOYLE, J. C.	8009030650* 8009160074 8009110593 8009090400 8009090411	ACRS ACRS XPORTLIC 27-39 50-376 Q
HERDT, A R HEREFORD, J. H HERHANN, R. HERHANN, R.	8007170163* 8007070570* 8007170547* 8007240057* 8007110372	50-328 G 50-327 8 50-327 B 50-206 P NUREO	HOLAN, J HOLDEN, R B HOLDEN, R B. HOLIFIELD, C HOLLAND, F	8009230431* 8009080231 8009300549 8009240117* 8009030816*	TOPREP 50-332 Q 50-201 9 FOIA 50-237 B	HOYLE, J C HOYLE, J C HUBACEK, N O HUBARD, H W	8009090415 8009170195 8009150077* 8009090648* 8009120578	50-364 0 XPORTLIC 50-445 0 50-482 0 50-327 P
HERMANN, R. A. HERMANDEZ, Q. HERMANDEZ, V. A. HERMANDEZ, V. A. HERMANDEZ, V. A. HESS, R. J.	8009120337 8009120307* 8009050248* 8009270306* 8009020492	NUREO 50-440 G 50-302 B 50-302 B XPORTLIC	HOLLINGSHORTH HOLMAN, J. F. HOLMAN, Q. S HOLDDY, D. J HOLDWKA, P.	8009230477 8009120083* 8009110500 8009180497* 8009020515*	50-312 R CONTRACT NUREO 70-33 50-320 H	HUBBARD, R B HUBERHAN, B HUBERHAN, B HUBERHAN, B HUBERHAN, B	8009240546# 8009230176# 8009230190# 8009190386# 8009190464#	50-275 0 FOIA FOIA FOIA FOIA
Hess, R. J Hess, R. J Hess, R. J Hess, R. J Hess, R. J.	8007020477* 8007100074 8007100101* 8007100117* 8007100131*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	HOLOWAY, C F HOOD, D HOOD, D, 8 HOPPER, D M HORIN, W A	8009110876 8009100005 8009300332 8009050335* 8009110048	RES 50-327 A 50-327 A 50-338 R 50-445 Q	HUBER, S A HUBER, S A HUBER, S A HUBER, S A HUBER, J M	8003260087 8003250292 8004110323 8005300697* 8009170262*	Doctet 30 PT9 Docket 30 PT9 50-327 R
HESS, R J HEVENER, A T HEVTER, L J, HICKLE, B J HICKS, H M	8009110404 8009190103 8009100091* 8009230351* 8009150243	XPORTLIC PR 50-97 G 50-285 R REGOD	HORIN: W A HORIN: W A HORIN: W A. HORIN: W A HORIN: W A	8007110048 8007110781 8007110781 8007170141 8007170141	50-445	HUCK.H J HUDBON.D HUETER.L J. HUGHEB.J HUKILL.H D	8009250313* 8009160446 8009260634* 8009270526* 8009160329	0A999 NUREO 50-315 Q 50-440 Q 50-289 P
HIESTAND, O. S HIESTAND, O. S HICOINS, J. C. HILF, C. L. HILLMAN, R. E	8009090336 AEE0609008 *13101519008 *2140209008 4840419008	50-409 0 50-409 0 50-322 0 50-296 P NUREO	HORIN, W. A HORIN, W. A HORHER, C HOVEY, O. K	8009230005 8009230005 8009190046 8009240117* 8009020378	50-445	HUKILL.H D. HUKILL.H D. HUMMEL.H H HUMMEL.H H HUNNIGUTT.D H	8009160367 8009220288 8009020479 8009080392 8009180481*	50-287 P 50-289 R NUREO NUREO 50-313 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBB I ON	GUBJECT CATEGORY
HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M HUNSTAD, A A	8009160557 8009180149 8009190590 8009190600 8009160282*	50-313 8 50-348 8 50-348 8 50-313 8 50-313 8	IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A	8007240545 8009240546 8009240577 8009240601 8009240649	50-259 P 50-271 P 50-271 P 50-271 P 50-259 P 50-298 P	JOHN, D F JOHNSON, T C JOHNSTON, R S JOHNSON, I B JOHNSON, J M	8009300533 8009150412* 8009300185* 8009100672 8009150234*	50-498 K 70-1398 40-0092 ACRE 0A999
HUNSTAD, A A HUNSTAD, A A HUNSTAD, A A HUNTER, V H HUNTER, R S	8007080401* 6007230750* 6007300558* 8007160546* 8007020232*	50-282 5 50-282 S 0A999 50-315 Q	IPPOLITO,T A IRELAND.R N IRELAND.J H IRELAND.J H IRWIN.R F	8009240515 8009070412* 8009180292 8009230443 7904010086*	50-220 F 50-334 P 50-255 J 50-155 J PT9	ЈОНИВОМ, Р Н ЈОНИВОМ, О Н ЈОНИВТОМ, О И ЈОНИВОМ, А Н ЈОНИВОМ, И О	8009020240* 8009140223* 8009020251* 8009030199* 8009180481*	50-097 Q 50-244 Q 50-044 Q 50-369 Q 50-313 Q
HUNTER, V H HUNTER, R S HUNTER, R S HUNTER, R S	8007180085* 8007270444* 8007250373* 8007160175 8007260212	50-315 G	IRWIN.R F IRWIN.R F ISLEY.T ISLEY.T ISLEY.T	8001020083* 8001020073* 8009020061* 8009120356* 8009230680*	PT9 PT9 50-346 8 50-346 8 50-346 8	ЈОНИВОМ, А D ЈОНИВОМ, Ц ЈОНИВОМ, Ј ЈОНИВОМ, Ј М ЈОНИВОМ, И Р	8009120479+ 8009160557 8009090572 8009110356 8009090431	50-341 G 50-313 B 50-367 G FOIA 50-309 G
HUNTER, R S HUNTER, M HUNTER, R HUNTER, R S HUNTER, M	8009170350 8009170188 8009170188 8009240349 8009300542*	50-315 V 50-445 M 50-445 M 50-315 P 50-498 M	ITSCHNER, L C ITSCHNER, M F JABLON, R A JABLON, R A JABLON, R A	8009090024* 8009260414* 8009220223* 8009220223* 8009220222*	90~289 H 50~289 T 50~389 M 50~389 M	ЈОНИВОМ, Ј Е ЈОНИВОМ, А О ЈОНИВОМ, А В ЈОНИВОМ, W D ЈОНИВОМ, W D	8007240233# 8007300197# 8007070487# 8007180149 8007170570	50~267 R 50~243 R 50~295 Q 50~368 B 50~368 B
HUNTER, H HUTTON, P H HUTTON, J C HYDE, K C IMAN, R L	8009300533 8009110421 8009020351 = 8009090519 = 8009020349	50-478 M RES 50-244 5 90-285 8 NUREO	JABLON, R A JABLON, R A JABLON, R A JABLON, R A JABLON, R A	8009220221 8009220222* 8009170142 8009170091 8009170162	50-389 M 50-389 M 50-389 M 50-335 M 50-389 M	JOHNSON, W D JOHNSON, C JOHNSON, C JOHNSOUD, J H JOHNSOUD, J H	8009190600 8009170194* 8009170225* 8009120368 8009120374*	50-313 8 90-466 9 90-466 9 PR PR
Ingram, F Ingram, F Ingram, F Ingram, H D. Ingram, F	8009220033 8009220078 8009230143 8009100097* 8009090022	50-337 H 50-352 H 50-289 H State Prog 50-289 H	JABLON, R A JABLON, R A JACKBON, H M JACKBON, J F JACKBON, T J	8009190091 8009300013 8009100107* 8009100503 8009190056*	50-335 M 50-445 M COMMISSION NUREQ 50-352 Q	OONES, W C JOHNBON, J H JOHNBON J H JOHNBON J H	8009120379* 8009170343 8009260666 8009260238* 8009020106	PR 50-304 P 50-289 9 CUNTRACT 50 285 0
IPPOLITO, T A	8007020144 8007040125 8007040307 8007040532 8007050450	50-331 P 50-263 P 50-324 P 50-271 P 50-293 P	JACKBON, R E JACOBB, A JACOBB, B JACOBB, A JACOBB, A	8009190637 8009150176 8009050280 8009230751 8009300259	50-133 P CONTRACT GAFFF CONTRACT CONTRACT	JONES, D W JONES, D W JONES, J K JONES, C E JONES, R A	8009120133* 8009020358 8009030216* 8009110675* 8009300602	70-143 Nureq Contract 50-454 G 71-6144
IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A	8009170255 8009170389 8009040176 8009150500 8009150503	50-333 P 50-220 P 50-298 P 50-293 P 50-298 P	JAFFE, S JAKEL, E JAMES, J JAMES, J JAMES, J	8009150003 8009240211 8009240408* 8009100977 8009240432	FOIA 71-9116 40-8180 50-112 R 50-112 R	JONES, C E JONES, J A JONES, J A JONES, J, L JONES, J, L	8009290193* 8009020321 8009110027 8009030449* 8009030474*	50~454 0 50-324 0 50-324 0 50-249 8 50-270 8
IPPOLITO, T A	8009180204 8009180252 8009190678 8009190697 8009190758	50-331 P 50-237 P 50-324 P 50-259 P 50-220 P	JAMES, J H JANACEK, R F JANECEK, D L JANECEK, R F	8007300170 8007170411 8007040632 8007050363 8007110562	1&E 50-10 Q 50-237 G TOPREP 50-237 Q	JONES, W C. JONES, D W, JONES, U C JONES, J L	6007030479 6007020440 8007250066* 6007070561 6007120431*	50-205 A 50 329 Q 70-1151 50-265 P 50-270 B
IPFOLITO, T A IPPOLITO, T A IPPOLITO, T A IPPOLITO, T A IPPOLITO, T A	8009190951 8009230237 8009230243 8009150437 8009090776	50~271 P 50~333 P 50~263 P 50~293 F 50~263 P	JANEGEK.R F JANEGEK.R F JANEGEK.R F JANEGEK.R JANEGEK.R F	8009160216 8009090013 8009020105 8009050349 8009120404	50-237 P 50-237 Q 50-237 P 50-237 P 50-10 P	JONES, J. L JONES, W C JONES, W C JONES, J L	9009120436# 8009150444 8009230349 8009160480# 8009180365	50-269 9 50-265 P 50-265 R 50-269 0 50-324 0
IPPOLITO, T A	8009090777 8009110259 8009110285# 8009110290# 8009120121	50-331 P 50-271 P 50-271 P 50-271 P 50-259 F	JANECEK.R F JANECEK.R F JANECEK.R F JANECEK.R F JANECEK.R F	8007080338 8007110374 8007170421 8007070374 8007250504	50-254 P 50-10 P 50-237 Q 50-237 P 50-237 Q	JONEB, R C JONEB, R C JONEB, R C JONEB, R C JONEB, W C	8007260320* 8007260322* 8007260388* 8007260400* 8007230721	50~207 T 50~207 T 50~207 T 50~207 T
IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A	8009090778 8009220013 8009220015 8009220018 8009220098	50-333 P 50-220 Q 50-249 Q 50-259 Q 50-259 Q	JANECEK, R F JANECEK, R F JANECEK, R J JANECEK, R F JANECEK, R F	8009270335 8009220293 8009270334 8009230463 8009250292	50-10 P 50-10 P 50-10 P 50-10 P 50-10 P	JONES, J. L. JONES, J. L. JONES, J. L. JORDAN, W S JORDAN, W S	8009230517# 8009260455# 8009230504# 8009250471# 8009080444	50-270 9 50-297 9 50-270 8 TOPRIP 70-920
IPPOLITO, T A	8009220104 8009220109 8009220115 8009220120 8009260596	50-333	JANINEK, M JANUSKA, A Q JANUSKA, A Q JANUSKA, A Q JANUSKA, A Q	8009100094 8009030326* 8009120509* 8009240255* 8009290018*	State Prog 50-305 G 50-155 G 50-282 F 50-266 G	JORDAN, W S JORDAN, W S JORDAN, H. S JORDAN, W S JORDAN, W S	8009220064 8009170002* 8009250467* 8009110802 8009110802	70 020 70-020 TOPRLP 50 155 Q 50 155 Q
IPPOLITO, T A	8009180531 8009180554 8009190001 8009190047 8009190084	50-293 P 50-333 P 50-331 P 50-324 P 50-263 P	JAPE, F JAPE, F JARDINE, E F JARDINE, E F JAROD, L	8009100816* 8009300640* 8009020525* 8009020522 8009300670	50-269 G 50-269 G 71-385 71-385 XPORTLIC	JORDAN, W 8 JORGENSEN, B L JORGENSEN, B L JOY, J M. JOYNER, J. H	8007110365 8007050216# 8007300224# 8007070268# 8007110281#	50~155 Q 50~255 Q 50~255 Q 50~206 R 70~105
IPPOLITO, T A	6009180526*	50-293 P 50-293 P 50-220 P 50-237 P 50-237 P	JENKINS. G R JENKINS. G R JENKINS. G R JENKINS. R A JENNINOS. P C	8007220184* 8007040330* 8007120271* 8007220278* 8007020091*	50-335 Q 50-327 Q 50-370 Q 50-304 S 50-206 P	JOYNER, J JOYNER, J H JOYNER, J, H JOYNER, J, H JOYNER, J, H	8009110272* 8009180497* 8009160186* 8009120235* 8009120235*	70~131 70~33 70~135 70~371 70~135
IPPOLITO, T A	8009170166 8009240591 8009240641 8009240644	50-237 P 50-293 P 50-220 P 50-293 P 50-298 P	JEPPESEN, D JERMAN, P. C JOHN, D. F. JOHN, D. F. JOHN, D. F.	8009260092 8009290092* 8009170188 8009170188 8009170188	NUREG FOIA 50-445 M 50-445 M 50-445 M	JOYNER, L JULIAN, C A JURGENSEN, R W KAHLE, J B KAHLE, J B	8007260411# 8007040417# 8007170447 8007080238# 8007110150#	50-209 F 50-10A B TOPAEP 50-332 Q 70-1113
IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A	8009250272 8009260324 8009260331+	50-263 F 50-259 F 50-276 P 50-296 P 50-296 P	JOHN, D F JOHN, D F JOHN, D F JOHN, D F JOHN, D F	8009300842* 8009300542* 8009300842* 8009300833 8009300833	50-498 M 50-498 M 50-498 M 50-498 M 50-498 M	KAHLE, J B KAHLE, J B KAHLE, J, B KAHLE, J, B KAL IMULLAH	8009090184# 8009120227# 8009100297# 8009150405#	70-143 70-143 70-1113 70-1113 NUREQ

	ACCEPATON TOURACT	ROHTUA	NUMBER CA	UBJECT ATCOORY	AUTHOR		SUBJECT CATEGGRY
AUTION  KALINGLAN  KALINGANAKISI, N  KALINGANAKISI, N  KALINGANAKISI, N	NOMBLIX   CAT OFFICE	RENNA, W B RENNA, W B RENNA, W B RENNA, W B RENNA, W B	8009120227* 70 8009280435 70 8009100297* 70 8009100290 70 8009120124 70	143  -143  -1113  -1113  -1113	XEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8009120041 5 8009120044 5 8009120046 5 8009120050 5 8009120050 5	0-440 Q 0-409 Q 10-341 Q 10-331 Q 10-441 Q
KALIVIANARIB, N KALIVIANARIB, N KALIVIANARIB, N KALIVIANARIB, N KALIVIANARIB, N	1009/000422	MENNA, U. E. MENNA, H. T. MENNA, H. B. MENNA, H. D. MENNA, H. D.	8009170403 80 8009100790 70 8009110118 80 8009110121 80	0-1113 0-259 @ 0-27 0-327 Q 0-250 Q	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8009120057 8009120060 8009170407 8009170408	60-367 0 60-263 0 50-315 0 50-315 0
KALEVIANANES N KALEHARFID N KAPBERERIG. KAN-B KAREIN	HOO9260AH   HOREO   HOO9200A07*   DO 209   H   HOO9000A07*   DO 265   H   HOO9110765   DO 202   A   H   H   H   H   H   H   H   H   H	KENNA, H D KENNA, H D KENNA, H D KENNA, H D	0009110126 76 0009230204 56 0009250062 76 0009170145 5	0-1151 0-1113 0-321	KEPPLER.J G KEPPLER.J G KEPPLER.J G KEPPLER.J G	8009170415 8009170418 8009170419 8009170426	50-440 Q 50-195 Q 50-327 Q 50-407 Q 50-341 Q
KANTER, M. A. KANTER, M. A. KANTOR, F. KAPLAN, A. L. KAPLAN, A. L.	0009090507# COMPTENTING 0009040927# 50 175 9 0 195 9 0	KCHRA, U. C. KCHNEDY, B. T. KENTER, J. R. KLNRICK, J. R.	1009230281#	10-280 G *OTA \$0-255 R (PORTLIC (PORTLIC	KEPPLER, J G	8009170430 8009170432 8009170433 8009170436	50-331
KAPLANI B N KAPLANI B N KAPLANI A L KAPLANI B N	H009040040   50 244   P   H009110161#   70 1114   H009030414   71 9019   H009030049   70 444   7   H009110801   70 1414   FORESTIN   FORE	мери (п. ) 0 С С ил ичин О С ил ичин О С ил ичин О С ил ичин	7904170409   7904170412   7904120000   7	эт <del>у</del> Рту Рту Рту Р <b>т</b> у	KEPPLER.J Q KEPPLER.J Q KEPPLER.J Q KEPPLER.J Q KEPPLER.J Q	8009170449 8009170440 8009180520 8009180524 8009180551	50-346 0 50-483 0 50-266 0 50-305 0 50-10 0
KAPLANIA L KAPLANID A. KAPDIP B KAPDLEIA H RATDIN Y	0009110021 50 197 H 00091101/1 50 115 P 000910111 MURED 0009110111 MURED 0009110111 50 325 H	KEPPEER, J. G. KEPPEER, J. G. KEPPEER, J. G. KEPPEER, J. G. KEPPEER, J. G.	0007170166 0007270113# 0007270111#	FOIA FOIA FOIA 1 UIA	KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q	8009230280 8009230284 8009230288 8009230300 8009230300	50-315 F 50-10 F 50-155 F 50-409 F
KATTENBACISER, P KAUTHAN, N C KAY, J A KAY, J A KAY, J A	0009120AAA MUU 0009010A31 10 29 F 0009100132 10 29 F 0009100132 10 29 F	0 (1911) 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	H009040917 ED09040531 ED09040536 ED09040940 B00909020	50-237 0 50-350 0 50-440 0 50-155 0 50-409 0	KEPPLER, J G	8007230305 8007230305 8007230307 8007230314 8007230318	50-263 F 50-345 F 50-265 F 50-305 F
RAY, JA KEARHEY, JJ KEATEN, RH KEATEN, RH WEATEN, RH	######################################	######################################	009090029 0090909042 009090043 009090047 009990090	50-341 0 50-331 0 50-461 0 50-367 0 50-263 0	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8009160430 8009180040 8009230057 8009230058	50-255 P 50-373 G 50-305 G 50-346 G
MEATENIA W MERIE J MEERIR MEBBERIR MEHOWID		и при ( R. Ј Q Сентри ( R. Ј Q Сентри ( R. Ј Q Сентри ( R. Ј Q Сентри ( R. Ј Q	11007270017 11007040087 11007020132 110071110211 110070703688	50 346 0 40-2061 50-255 6 50-546 0 50-263 C	KEPPLER, J G	8009230063 8009230066 8009230068 8009230071	50-315
METHIO, A METHIO, A METHEY, J L METHEY, H D METHEY, H D	(100911086) 70 元7年 B (1009110868 1 H3 A (10091190848 1 H3 A (10091106118 0 A 999	REPPERS C REPPERS C REPPERS C REPPERS C REPPERS C REPPERS C	0007040465 0007270011 0007240239 0007030170	50 461	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8009230073 8009230074 8009230079 8009230081 8009230082	50-461 G 50-367 Q 50-358 Q 50-338 Q
RELLEY, W D RELLEY, W D RELLEY, W H RELLER, O R, WELLER, C R.	0009380 137# 0A979 00090804A7# 0A979 00093A04B7# 10941* 00093A04B7# 10941* 00093A04B7# 0	Синтерия В Синтерия В Синтерия В Синтерия В Синтерия В Синтерия	8089010195 8089030194 8089030198 8089030202 8089030204	50-440	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8009230087 8009230087 8009230093 8009230094 8009230478	50-407 0 50-266 0 50-155 0 50-10 0
KELLOOD, P. J KELLOOD, P. J KELLOOD, P. J KELLOOD, P. J	1009240714	керрі (к. J. О С. Б. Івтерія О. С. Б. Іртерія О. С. Б. Іртерія О. С. Б. Іртерія	8007030207 8007030210 8007030213 8007030214 8007030218	50-367 0 50-263 0 50-546 0 50-346 0 50-463 0	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8007230483 8007230484 8007230487 8007230487	90-358 Q
METTA'N METTA'N D METTA'N D METTA'N D	H0051 10 (15.4 30 515 11 H0051 10.501	REPORTER J O REPORTER J O REPORTER J O REPORTER J O REPORTER J O	8009030219 8009030228 8009030228 8009030229 8009030231	50-266	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	9009070591 9009250490 9009250490 9009270224	50-373 5 50-358 5 50-255 P
MELLY, J A	19091701014 90 HIJ 9 1909170171 70 HI 9 190917010 70 HIJ 0 19091707014 70 JB7 0	0 6.41144434 0 6.41144434 0 6.4114434 0 6.4114434	0009180401 0009260410 0009180484 9009180489 0009180489	50-10 P 50-329 0 50-195 0 50-409 0 50-331 0	D L.REJPRENJ G B.REPPLER, J G B.REPPLER, J G B.REPPLER, J G B.REPPLER, J G	9007250471 9007250471 9007240071 9007240071	50-358 d 50-358 d 50-440 d 6 50-155 d
HEMPER, J & KEMPER, J & KEMPER	000410005% 00 105 0	REPRESES & BERNELES &	0009150466 0009150469 0009150473 0009150479	90-263 0 50-440 0 50-350 0 50-341 0 50-461 0	KEPPLER. J G KEPPLER. J G KEPPLER. J G KEPPLER. J G	800924010 800924010 800924010 800924010	3 50-331 0 4 50-461 0 7 50-315 0
KENNA, W B KENNA, W B KENNA, W B KENNA, W D KENNA, W D	HOOATEGE 10* 10 147 9 147 9 140 0 147 9 14	KEPPLER, J. C KEPPLER, J. C KEPPLER, J. C KEPPLER, J. C	8009150403 8009150485 8009150495 8009230376 8009230377	90-367 Q 50-10 G 70-0 70-36	KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	800924011 800924011 80092401 80092401	50-263 0 50-387 0 50-387 0 16 50-346 0
renna a i Renna a i Renna a i Renna a i	10099193714   50 373   0   10099190194   70   1151   1   1   1   1   1   1   1   1	O CHARLESTAN O CHARLESTAN O CHARLESTAN O CHARLESTAN O CHARLESTAN	8004130035 8004330383 8004330383	3 70-152 G 30-152 G 5 70-152 G	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	80092401 80092401 80092401 80092401 80092401	22 50-266 G 24 50-305 G 26 50-327 G
KEMIA, M B KEMIA, M B KEMIA, M B	800V030110 70 143 800V0301104 70 143 800V1402244 70 143	KUPPLERI J O	8004150030 8004150030	, , , , , ,			

AUTHOR	ACCESSION SUBJ NUMBER CATE	ODRY AUTHOR	ACCE89ION NUMBER	SUBJECT CATEOGRY	AUTHOR	ACCESSION NUMBER	BUBJE CATEC	CT XXX
KEPPLER.JO KEPPLER.JO KERR.W KERR.OW KERR.OW	9007260656 50-29; 8009300215 50-45; 8009190377* FDIA 9009080462* State 8009080459 State	5 Q KNOTTS.J B 4 Q KNOTTS.J B KNOTTS.J B Prog KNOTTS.J B Prog KNOTTS.J B	9099170369* 9009170359 8009170369* 8009300009 8009300009	50-445 K 50-445 M 50-445 M 50-395 O 50-395 M	LAWTON, M D LAWTON, R R LAZARUS, W J LAZO, R M LAZO, R M	8007300520 8007230571 8007300600 8007080514 8007110807	40-608	14 P B
KERR. O H KERR. B H KERR. O H KERR. H	8009050191 State 8009150457 State 8009110378 27-10 8009240204 State 8009220395 TOPREP 8009230455 I&E	Prog XNOTTS, J B KNOUPF, O Prog KO, H KOCH, L J	8009300009 8009300009 8009180391 8009080299* 8009250208*	50-398 Q 50-395 Q 50-320 P 50-348 P 50-441 Q	LAZO,R M LAZO,R M LAZO,R M LEACH,L J LEAGIEWBKI,J S	8009180542 8009230625 8009250034 8009160450 80092305361	50-466 50-282 50-329 NUREO 50-317	0
KERRIGAN, J KERRIGAN, J KERRIGAN, J KERRIGAN, J	8009020335 50-528 8009120551 50-528 8009110725 50-311 8009180306 50-272	P KOCH, L J P KOCH, L J KOCH, L J	8009220130 8009080193 8009080202 8009090254 8009080347	50-461 A 50-461 A 50-461 C 50-461 K 50-461 H	LEAR. O LEBO. C. D LEBOETTER. L LEE. B	8009020173 8009120665 8009180159 8009120075* 8009260465	90-029 CONTRAC CONTRAC CONTRAC 50-237	CT CT CT
Kerrigan, J Kerrigan, J D Kerrigan, J D Kessler, O Ketchen, E G Ketchen, E G	800912050B 50-528 8009180534 50-528 8009160595 50-528 8009240063* FOIA 800910103 50-369	A KOCHER, C R A KOESTER, G L KOESTER, G L H KOESTER, G L	8007270337 8007170063 8007150381* 8007150014 8007270218	50-461 8 50-361 0 50-482 Q 50-482 G 50-482 8	LEE,E W K LEE.E W K LEE.E W K LEE.O R LEE.O R	8009100126# 80091502036# 8009170189# 8009170189# 8009100841#	50-440 50-327 50-461 50-267 50-267	
KETCHEN, E O KETCHEN, E O KETCHEN, E G KETNER, M H KETNER, M H	80090241 50-369 8009120252 50-369 8009160343 50-369 8009160340 50-275 8009020273 50-289	O KOESTER, O L O KOESTEL, A O KOESTEL, A O KOFFLER, H KOHLER, J E	8007300612* 8007020161 8007150579 8007100651* 8007270436*	50-482 Q NUREQ NUREQ 70-312 50-295 Q	LEE, V. W LEE, V W LEFEBRE, N T LEFEBRE, N T LEHR, J. C	8009090464* 8009090464* 8009050405 8009100412 8009300340*	50-275 50-275 REB REB 50-282	T T
KETZLACH, N KETZLACH, N KEY, H J KIEFER, N KIMBALL, T L	8009170291 50-289 8009090124 70-27 8009240339* 70-33 8009180021* 50-295 8009230746 50-369	O KOLESAR, D.C. KOLTAY, P.S. KOLTAY, P.S. KONKLIN, J.E. KOOI, M.	8009260498* 8009090066* 8009250302* 8009110675* 8009220271*	TOPREP 50-293 Q 50-387 Q 50-454 Q 50-245 B	LEMBKE.B LEMPGES.T E LEMPGES.T E LEMPGES.T.E LEMPGES.T E	8009120565* 8009220158 8009090668 8009120263 8009160508	40~1041 50~220 50~220 50~220	9999
KINYEL, J J KING, L J KING, L J KINNEMAN, J D KINNEMAN, J D	8009300004 50-347 8009300121* CGNTRAC 80090200800 50-320 8009030534* 50-320 8009250293 40-4348	O KOPACZ, J F KORCHYNSKY, H P KORCHYNSKY, M P KOTTAN, J J KOUTS, H J C	8009120399* 8009300473* 8009300478* 8009150124* 8009110321	50-254 8 50-237 8 50-237 8 50-219 0 NUREQ	LEMPGEB, T E.	8009160513 8009090281 800900622 800900264 8009160460	50-220 50-220 50-220 50-220	, 00008
HINNEY, W W DEINNEY, J D DEINNEMAN, J D DEINNEMAN, J D D DEINNEMAN, J D D DEINNEMAN, J D	8009120342* 70-343 8009250334* 70-820 8009150380+ 40-8113 8009230142 70-1417 8009240712 70-2554	KRAUSKOPF,K B KROUT,K O KRUMPOS,P J KUGE,T. KUGE,T	8007150185 8007030375* 8007070388* 8007110602 8007270257	PR 50-320 H 50-282 S XPORTLIC XPORTLIC	LEMPGEB, T E LEMPGEB, T E LEMPGEB, T E LEMPGEB, T E LENNGN, T J,	8009150265 8009150297 8009250331 8009300491 8009150164#	50-220 50-220 50-220 50-220 40-6743	9 R A
KINNEMAN, J D KINNEMAN, J D KINNEMAN, J D KINNEMAN, J D KINNEY, W W	8009120201 40-2940 8009150364 40-8113 8009240044 70-710 8009100847* 70-312 8009100634 70-312	MURTZ,R J Mushner, w L Lacey, w s Lacey, w s Lacey, w s	8007110421 8007110281# 8007030234# 8007120386# 8007140311#	RES 70-135 50-334 S 50-334 S 50-334 S	LEPPKE, D M. LEBH, L LEBSOR, L C LEBSOR, L. C LEBSOR, L. C.	8009300398 8009220211# 8009050326 8009050326 80090503252	NUREO 50-289 50-298 50-298 50-298	11 6
KINTNER, L KINTNER, L KINTNER, L KINTNER, L KINTNER, L	8009110294 70-820 8009220043 50-341 8009110541 50-364 8009230767 50-364 8009300051 50-364	LACEY, W S A LACEY, W S A LACEY, W S A LACEY, W S	8009160451# 8009160472# 8009160411#	50-334 8 50-334 8 50-334 8 50-334 8 50-334 8	LESBOR, L. C. LESBOR, L. C. LESBOR, L. C. LESBOR, L. C. LESBOY, R. P.	8009050187 8009050184 8009050199 8009140262 8009250002	50-298 50-298 50-298 50-298	8 8 8 8 R
KIPER,K L KIPER,K L KIRK,H F KIRK,H F KIRK,O B.	8009240333 50-410 8009240668 70-371 8009170366 50-201	A LACEY, W S A LACEY, W S A LACEY, W S LAFLEUR, J D LAFLEUR, J D	8009240461* 8009290257* 8009190126	50-334 8 50-334 8 50-334 8 KPORTLIC KPORTLIC	LESSY, R P LEVINE, B LEVINE, H R LEVIN, H. A. LEVINE, B H	8009290034 8009090799 8009020112# 8009110746	50~10	0 H P
KIRK, O B KIRK, O B KIRK, O B KIRK, O B KIRK, O B	90070703B3* 50-327 8009120440* 50-327 8009160412* 50-327 8009230594* 50-327	S LAGATTA, D P S LAGIEMSKI, H B LAGIEMSKI, J B S LAGIEMSKI, J B LAGIEMSKI, J B	8009030522* 8009120378* 8009230527*	CONTRACT 50-317 8 50-317 8 50-318 8 50-317 8	LEWALD.O H. LEWALD.O H LEWIS.R C LEWIS.R C LEWIS.R C	8009030601 8009250049 8009250049 8009030270# 8009100811#	50~249	F 0 0 0
KIRKLAND, M W KIRKLAND, M W KIRKLAND, M W KISIELESKI, W E KISIELESKI, W E	8009030454 70-2784 8009120089 70-754 8009110279 70-754 8009080402 NUREO	S LAHTI, O P LAMBREMONT, E N LAKKIN, D E LANCASTER, K F LANCASTER, K F	8009020161 N 8009030482* 5	0-275 P WREQ 0-302 B 0-302 B	LEWIS, R C. LEWIS, R C LEWIS, R C LEWIS, M I LEWIS, R C	8007030264# 8007160637# 8007240706# 8007120143 8007150320	50-395 50-200	Q Q Q Q
KISTER, H B KISTER, H B KISTER, H B KITTRELL, J O KITTS, R J	8009100853# 50-247 0 8009150161# 50-322 0 8009160223# 50-244 0 8009170052 FQIA		8007170071 5 8007100654 4 8007260412* 5	0-335 M 0-335 M 0-4492 0-289 T ABTE MOT	LEWIS, R. C. LEWIS, R. C. LEWIS, R. C. LEWIS, R. C. LEWIS, R. C.	8009220265	50-259 50-261 50-302	9
KLEIMIO, R KLEINSORGE, W P KLEINSORGE, W P KLEINFELDER, J KLEIN, 8	8009030438# 50-327 P 8009300633 50-272 8 8009240313* 50-413 0 8009240421* 50-518 0 8009230161* CONTRACT	LANPHER, L. C	8009110019 56 8009150404 56 8009150404 56 8009220406 56	0-275	LEWIS, R C LEWIS, R C. LEWIS, R. C LEWIS, R C	8009220337# 8009030188# 8009050547# 8009110102		9 9 9
KLIMBERO, S. B KLINGER, C KNAPP, P J KNAPP, P J KNAUSMAN, E	8009110395 50-361 H 8009040250 50-54 0 8009190765 50-259 8 80091000044* 50-219 0 8009240205* 50-244 0	LARDCCA1	8009230414 50 8009110492* 50 8009120549* 50 8009250057 50	1-275 G 1-201 G 1-201 P 1-367 G	LEWIS, R. C LEWIS, R. C. LEWIS, R. C. LEWIS, R. C. LEWIS, R. C.	8009030257 8009020209 8009120045 8009300061	50-290 0 50-290 0 50-248 0 50-261 0	
NAMP, R C KNOP, R C KNOP, R C KNOP, R C	8009220207* 50-289 H 8009250332* 50-461 Q 8009110664* 50-358 Q 6009180064* 50-461 Q 8009180240* 50-329 Q	LAUTZENHEISER LAUTZENHEISER LAVERTY, J. H LAVERTY, J. H LAWRENCE, L. I	8009110299# 50 8009110304# 50 8009180469 50 8009230747 50	-293 G -293 G -142 Q -142 Q -298 8	LEWIS, W L LEWIS, M. I. LEWIS, R. C. LEWIS, R. C. LEWIS, R. C.	8009030157 8009100801 8009050425 8009140631 8009240652	70-261 0 70-275 0 70-269 0 70-289 0 70-291 0 70-280 0	

hohtua	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOURY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
LEWIS.H I LEWIS.R C LEWIS.R C LI.C Y LIBRIZZI.F P	8007140161 8009300060 8009300616 8009300616 8009150034 8009030585	PR 50-259 G 50-269 G 50-317 P 50-311 S	LUKZ:F J LUKZ:F J LUKZ:F J LUNDVALL:A E LUNDVALL:A E	8009100041* 8009190738* 8009180217* 8009020034 8009020020	CONTRACT CONTRACT CONTRACT SO-317 R 90-317 P	MADEDA,T J MADIA,H J MADNI,I K MADSEN,G L MADSEN,G L	8007030133* 8009150597 8009100947 8009150055* 8009150060*	50-295 G NUREO NUREO 50-445 G 50-445 G
LIBREZZI, F.P.	8009030413	50-311 8	LUNDVALL, A.E	8007040301	50-317 P	MADSEN, Q L	8009150066*	50-445 0
LIBREZZI, F.P.	8009090447	50-311 6	LUNDVALL, A.E	8009150250	50-317 P	MADSEN, O L	8009150071*	50-445 0
LIBREZZE, F.P.	8009090542	50-311 8	LUNDVALL, A.E	8009230634	50-317 P	MADSEN, O L	8009150075*	50-445 0
LIBREZZE, F.P.	8009090554	50-311 8	LUNDVALL, A.E	8009300383	50-317 F	MADSEN, O L	8009150116*	50-445 0
LIBREZZI, F.P.	8009090593	50-272 8	LUNSFORD, J.L	8009100036	NUREO	MADSEN, O L	8009150120*	50-445 0
1187(221, FP 1197(221, FP 1197(221, FP 1197(221, F, P 1197(221, FP	8007050290 8007070578 8007070437 8007070587 8007120357	50-272 R 50-272 8 50-311 6 50-272 8 50-272 8	LYONS, M D LYONS, M D LYONS, M D LYONS, M D	8009160481 8009150425 8009150453 8009030121 8009290314*	NUREO 50-416 A 50-416 A 50-397 A GA999	MADBEN, O L MADBEN, O L MADBEN, O L MADBEN, O L MADBEN, O L	8007050465 8009100033 8009170168 8009180470 8009040039	50-267
LIBREZZIAF P.	8009120375	50-272 B	MACARTHUR, T.C.	8009110208*	27-39	MADSEN.O L	0009100842	50-298 0
Librezziaf p	8009120424	50-272 S	MACARTOR, J.D.	8009100446	PR	MADSEN.O L	8009300274	50-267 0
Librezziaf p	8009150264	50-311 B	MACDONALD, C.E.	8009020114	71-5450	MADSEN.O L	8009100836	50-267 0
Librezziaf p	8009160401	50-272 P	MACDONALD, C.E.	8009020116	71-9108	MADSEN.O L	8009160557	50-313 6
Librezziaf p	8009160393	50-311 V	MACDONALD, C.E.	8009020119	71-9108	MADSEN.O L	8009170185	50-267 0
L15A1221, F P	8009230368	50-272 V	MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDOUGALL, E A MACDONALD, C, E	8009020121	71-9094	Madren, o L	8007180147	50-348 8
L15A1221, F P	8009160478	50-311 E		8009020125	71-9027	Madren, o L	8007170570	50-348 8
L15A1221, F P	8009230678	50-311 E		8009110570	71-5957	Magre, u	8007170600	50-313 8
L15A1221, F P	8009250260	50-272 P		8009250247*	90-327 P	Magre, u	8007030078*	10CFR
L15A1221, F P	8009300513	50-311 P		8009080454	71-9039	Makepeace, J M	8007120381*	50-247 8
LIBRIZZI, F P	8009300503	50-272 P	MACDONALD, C E	8007080457*	71-9039	HAKEPEACE, J M	8009160369#	50-247 8
LIBRIZZI, F P	8009300512	50-272 P		8007110595	71-109	MALMROS, M H	8009020251#	50-344 9
LICHTENBERGER	8009150028	70-1100		8007110597*	71-109	HALONEY, G P	8009110310	50-315 R
LICHTENBERGER	8009110706	70-1100		8007150405	71-394	MALONEY, G P	8009260094	50-315 9
LIDIAK, E O	8009120590	RES		8007150407	71-370	HALSCH, M O	8009290452	50-344 9
LIEBLER, O. E	8007230581	TOPREP	MACDONALD, C E	8009230754	71-9001	MALTEBE, M J	8009020252	50-286 F
LINARES, F	8007070147	REGOD		8009230741*	71-9001	MANAKTALA, M K	8009190401	RES
LINDER, F	8007030237	50-407 P		8009090624	71-9096	MANCINI, A J	8009150555	40-8745
LINDER, F	8007070008	50-409 G		8009090426*	71-9096	MANDEL, M	8009120611	70-258
LINDER, F	8007070010	50-409 Q		8009180153	71-6400	MANGUBI, J	8009180512	70-2478
Linder, F	8007030494	50-409 S	MACDONALD, C. E	6009230753	71-35	MANOURI, J	8007110240	70-2478
Linder, F	8007260157	50-409 Q	MACDONALD, C E	6009230758	71-382	MANN, H M	8007170682*	FOIA
Linder, F,	8007070529	50-409 P	MACDONALD, C E	8009230766	71-9136	MANRY, M.	8007050271	50-321 V
Linder, F,	8007160250	50-409 R	MACDONALD, C E	8009230765	71-17	MANRY, M	8007030451	50-366 S
Linder, F,	8007220145	50-409 P	MACDONALD, C E	6009230767*	71-17	MANRY, M	8007020367	50-366 S
LINDER, F LINDER, F. LINDER, F. LINEHAN, J. J LINEHAN, J. J	8007230648 8007240343 8007260630 8007020173 8007050370	50-407 8 50-409 P 50-409 8 40-4492 40-299	MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C, E MACDONALD, C E	8009190692 8009230752 8009240127 8009240132* 8009110750	71~244 71~138 71~4986 71~4986 71~9009	HANRY, M HANRY, M MANRY, M MANRY, M MANRY, M	8009020400 8009020436 8009020439 8009030442 8009020461	50-344 8 50-321 8 50-344 8 50-346 8
LIMENBERGER, O	8009190229	50-466 0	MACDONALD, C E	8009110759*	71-7007	MANRY, M	8009020362	50-344 8
LIMENBERGER, O.	8009250058	50-466 0	MACDONALD, C E,	8009150542	71-18	MANRY, M	8009020404	50-321 8
LIMENBERGER, O. A	80092500456	50-466 0	MACDONALD, C E	8009190544	71-6357	HANRY, M	8009020419	50-346 8
LIMVILLE, J C	8009150161*	50-322 0	MACDONALD, C E	8009190548	71-9039	MANRY, M	8009030415	50-321 R
LITFIN, K	8009050359	50-206 H	MACDONALD, C E	8009190552	71-6458	MANRY, M	8009090469	50-321 8
FILLE: H FILLE: H FIL	8009180495* 8009100161* 8009260271* 8009180490* 8009150420	0A977 50-331 0 50-282 0 0A979 50-206 P	MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E.	9009190555 9009190541 9009250496 9009250498* 9009250500	71-9108 71-9081 71-108 71-108 71-192	MANRY, M MANRY, M MANRY, M. HANRY, M. MANRY, M	8007070428 8007070443 8007070484 8007150275 8007150281	50-366 S 50-321 B 50-366 S 50-321 S
LETTLE, H LETTLE, L H LETTLE, L, H LLOYD, D B LO, A	8009240052 8009110803 8009110813 8009110574 7910110018	50-206 P 50-510 Q 50-237 Q RES 50-10 P	MACDONALD, C E	8007250502* 8007260521 8007270237 8007300122 8007300125*	71-192 71-5740 71-198 71-5980 71-5980	MANRY, M MANRY, M MANRY, M. MANRY, M MANRY, M	8009150291 8009150331 8009150382 8009150384 8009180199	50-321 6 50-366 8 50-321 8 50-321 8
LOCEFF.F	8009170296#	50-244 P	MAGDONALD, C. E	8009300127	71-9037	Manry, M	8009180498	50-386 R
LOCEFF.F	8009170301#	50-244 P	MAGDONALD, C E	8009300130*	71-9037	Manry, M	8009160285	50-386 S
LOCEFF.F	8009170314#	50-244 P	MAGDONALD, C E	8009300135	71-9034	Manry, H	8009230316	50-386 S
LOCHSTET.W.A.	8009180522	PR	MAGDONALD, C E.	8009300137*	71-9034	Manry, M	8009290278	50-386 S
LOCHSTET.W.A.	8009160190	50-320 0	MAGHON, R D.	8009030611	50-293 8	Manry, M	8009300497	50-321 S
LOEFFLER, T.	009170266	50-466 U	MACHON, R. D	8009090422	50-293 S	MANRY, M	8009300519	50-366 B
LOEWIR, J D	8009150468*	50-438 A	MACHON, R. D.	8009070430	50-293 S	MANSER, W C	8009100906*	70-143
LOEVIR A	8009040470*	CONTRACT	MACHON, R. D	8009090369	50-293 S	MANSER, W C	8009240631*	70-143
LONG, F J	8009240273	50-324 Q	MACHON, R. D	8009160452	50-293 S	MANSER, W C	8009120126*	70-143
LONG, F, J	8009240284*	50-324 Q	MACHON, R. D	8009160267	50-293 R	MANSER, W C	8009120147	70-143
LONG, F J	8009150300	50-438	MACHON, R. D.	8009160404	50-293 8	MANSER, W C	8009090445	70-143
LONG, F J	8009150304*		MACHON, R. D.	8009160447	50-293 8	MANSER, W C	8009110392	70-143
LOCK, J.	8009150445*		MACHON, R. D.	8009290284	50-293 8	MARCHAL, J.	8009110258	XPORTLIC
LOCKIS, J B	8009180443		MACHON, R. D.	8009230732	50-293 8	MARCHAL, J.	8009110380	XPORTLIC
LOCKIS, R W	8009080335*		MACHON, R. D.	8009240462	50-293 8	MARCHAL, J.	8009110559	XPORTLIC
LORENZ, R. W	6009080336*	50-133 R	MACHON, R. D	8009240467	50-293 8	MARCHAL, J	8009110564	XPORTLIC
LOYAAS, A	3009190717	REGOD	MACHON, R. D	8009260470	50-293 8	Haribi, A V	8009170329	50-293 F
LOYENDALE, P. G	8009290131*	50-254 G	MACHON, R. D	8009260481	50-293 8	Marker, J L	8009110542	FOIA
LOYENDALE, P. G	8009030695*	50-263 F	MACHON, R. D	8009260480	50-293 8	Harrack, D	8009090451	50-466 Q
LOWENBERO, H	6009230291*	FOIA	MACHON, R. D	8009300500	50-293 R	Harrack, D	8009180418	50-466 C
LOWENBERG. H LOWENBERG. H LUBENAU. L O LUCO, J E. LUCO, E	8009230183* 8009230297* 8009110578 8009150424* 8009090779	FOIA 27-10	MACHON.R.D MACHON.R.D. MACY.J.H MADDEN.H MADDEN.J.J.	8007270283 8007300531 8007080377 8007100652 8007020277		MARRAGK.D HARRIOTT,D HARGH,R.J MARSHALL,H H HARSGLAIS,L D	B009260007 800920217* 8009240284* 8009050423 8009110467	50-466 C CDM1BSIGN 50-324 G 50-329 O 50-271 G

ROHTUA	ACCESSION NUMBER	EUBJECT CATEGORY	AUTHOR	ACCEBSION NUMBER	BUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MARSGLAIS, L D	8009260458	50-271 P	MATTHENSE R	8009240495	50-305 8	MCCLINTOCK, R O	8004240527	Docket 30
MARTIN, W O	8009100646*	70-371	MATTIA: J G.	8009100030+	50-352 0	MCCLUNG, R N	8009030471	NUREO
MARTIN, J B	8009020111*	50-237 P	MATTIMOE: J J	8009030189	50-312 0	MCCOLL, A. C	8009100435	50-445 g
MARTIN, R D	8009100816*	50-269 Q	MATTIA: J C	8009100884*	50-352 0	MCCOLL, A. C	8009260005	50-445 g
MARTIN, T T	8009100038*	50-293 Q	MATTIA: M J	8009110025*	CONTRACT	MCCOLL, A	8009260008	50-445 g
MARTIN W C MARTIN W C MARTIN W C MARTIN W C MARTIN W C	8009250359* 8009110274* 8009110269* 8009180491* 8009160179	50-201	MATTAN, H, J MATTAN H J MATTAN L LJONITYAN L LJONITYAN J LJONITYAN	8009110222* 8009260242* 8009160628 8009050240 8009050339	CONTRACT CONTRACT 50-312 G 50-312 P 50-312 R	MCCONNELL, J W MCCOOL, W B MCCOOL, W B MCCOOL, W B	8009140588 8009190701# 8009240047# 8009240024# 8009240021#	50-395 F FOIA FOIA FOIA
MARTIN, H O MARTIN, T T MARTIN, T J MARTIN, L C MARTIN, H G	8009120150 8009100877* 8009190210* 8009120070 8009160240	70-371 90-293 G 50-354 G Contract 50-220 G	MATTIA: M MATTIA: M MATTIA: M MATTIA: M MATTIA: M J	8009030085* 8009100409* 8009120662* 8009180150* 8009190190*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MCCOOL, W. B MCCOOL, W. B MCCOOL, W. B MCCOOL, W. B MCCOOL, W. B	8009190653# 8009240075# 8009240092# 8009240113# 8009190634#	FOIA FOIA FOIA FOIA
MARTIN, W O MARTIN, W O MARTIN, L E MARTIN, R D MARTIN, R D	8009160244 8009150347 8009150348* 8009110202* 8009050550*	50-334 0 70-135 50-482 0 50-348 0 50-369 0	MATTIA, M J MATTIMDE, J. J MATTIA, M J MATTIMOE, J J	8009250263* 8009150267 8009300121* 8009300097* 8009130540	CONTRACT 50-312 B CONTRACT CONTRACT 50-312 P	MCCORMACK, M, MCCORKLE, O W MCCORKLE, O W MCCORKLE, O W MCCORKLE, O, W	8007020217* 8007120644 8007070877 8007070880 8007150047	COMMISSION 70~734 50~219 } 50~206 f 50~268 f
MARTIN.R D	800730640*	50-267 @	MATTIA, M J	8009180165*	CONTRACT	MCCORKLE, O W	8009120129	70-2322
MARTIN.T J	8007110472	50-354 @	MATTIA, M J,	8009180329*	CONTRACT	MCCORKLE, O W	8009120132	40-2940
MARTIN.L E	8007100279*	50-445 @	MATTIA, M J	8009300198*	CONTRACT	MCCORKLE, O. M	8009120136	70-2478
MARTIN.J B	8007120144*	27-48	MATTIKOE, J J	8009160388	50-312 P	MCCORKLE, O. M	8009120139	70-687
MARTIN.H G	8007110262	70-135	MATTIA, M J	8009180191*	CONTRACT	MCCORKLE, O W	8009120149	70-754
MARTIN.W G MARTIN.W G MARTIN.T J MARTIN.T J MARTIN.W G	8009180487 8009250354 8009150043* 8009120218 8009100642	70-33 50-201	MATTIA:M J MAURA:F MAURIN:L V MAURIN:L V MAXNELL:J C.	9009300209# 8009150025# 9009300100 8009230437 8009230111	CONTRACT 50-373	MCCORKLE.O W MCCORKLE.O W. MCCORKLE.O W MCCORKLE.O W. MCCORKLE.O W	8009120691 8009230731 8009120157 8009150392 8009120152	70-8 50-247 F 70-27 70-2623 70-2786
MARTIN, W G	8009140419	50-277 Q	MAXMELL, O F	8009180459*	50-400 Q	HCCORKLE, O W. HCCORKLE, O W HCCORKLE, O W HCCORKACK, H HCCORKLE, O W	8009150403	70-13\$
MARTIN, R A	8009140492	RES	MAYER, P.	8009220081*	50-352 H		8009120161	70-25
MARTIN, B E,	8009030427*	50-235 Q	MAYER, L O	8008200282	50-282 F		8009120043	70-800
MARYIN, W Q,	8009110243	70-135	MAYER, L O	8009030381	50-283 F		8009120494*	COMMISSIDE
MARTIN, J B	8009140475	Waste Mot	MAYER, L O	8008260337	50-283 F		8009120155	70-820
MARTIN, T J	8007070557	50-354 9	MAYER, L O	8007030524	50-263 F	MCCORKLE, & W	8009260527	50-349 F
MARTINEZ, F R	8007110378	50-204 H	MAYER, L O	8007020055	50-263 F	MCCORKLE, & W,	8009110448	70-344
MARTIN, T J	8007160650	50-354 8	MAYER, L O	8007020072	50-282 F	MCCORKLE, & W	8009150206	50-391 F
MARTIN, D K	8007100575	50-358 0	MAYER, L O	8007020007	50-263 F	MCCORKLE, & W,	8009120096	70-143
MARTIN, T T	8007170575	50-271 8	MAYER, L O	8007030380	50-263 8	MCCORMACK, M	8009260452*	50-201 \$
MARTIN, W	8009300633	50-272	MAYER, L O	800 90 90 297	50-282 R	MCDAVITT, D. F	8009020255	70-33
MARTIN, R.	8009300334		MAYER, L O	800 90 90 375	50-263 P	MCDEOWN, L, M	8009250363*	50-201 0
MARTIN, M	8009230637		MAYER, L O	800 90 80 348	50-263 R	MCDONALD, M E	8009240038	PT9
MARTIN, T. T	8009300600		MAYER, L, O.	800 90 80 375	50-306 8	MCDONALD, R, J,	8009250497*	CONTRAC?
MARTORE, J. A	8009110543		MAYER, L O	800 91 00 500	50-202 Q	MCDOWELL-BOYER	8009260550	RES
MARTORE, J A MARTORE, J A MASON, E A MASON, E A MASON, E A	8009230235 8009180002 8009230187* 8009230201* 8009230234*	50-416 A 50-416 F FOIA FOIA FOIA	MAYER.L O MAYER.L O MAYER.L O MAYER.L O MAYER.L O	8009090282 8009090356 8009140279 8009170341 8009190475	50-263 R 50-282 8 50-282 R 50-282 P 50-263 F	McDuffie, M A McDuffie, M A, McDuffie, M A, McDuffie, M A McDuffie, M, A	8009020203 8009230067 8009120593 8009300581 8009260497	50-400 9 50-400 9 50-400 9 50-400 9
MAGBIE.W A MAGBIE.W A MAGBIE.W A MABTER.W MATHEWB.E R	8007170276# 8009170301# 8009170314# 8009030258 8009150464#	50-244 P 50-244 P 50-244 P 40-8745 50-305 G	MAYER, L. O MAYER, L. O MAYER, L. O MAYER, L. O, MAYER, L. O.	8007170481 8007170484 8007230632 8007230738 8007230620	50-282 P 50-263 P 50-263 8 50-282 8	McGarry, J M McGarry, J M McGarry, J M McGarry, J. M McGarry, J M.	8007050086 8007050086 8007260010 800726026	50-349 0 50-369 0 50-369 0 50-369 0
Mathews, e. r	8007030504	50-305 R	MAYER, L O.	8009230743	50-282 8	MCGARRY, J. H.	8009240273	50-364 0
Mathews, e. r	8009070355 ,	50-305 P	MAYER, L O	8009230244	50-282 P	MCGARRY, J. H.	8009240246	50-364 0
Mathews, e. r	8009260061	50-305 G	MAYER, L O	8009240826	50-263 8	MCGARRY, J. H.	8009240273	50-364 0
Mathews, e. r	8009260081	50-305 G	MAYER, L O	8009300581	50-282 8	MCGARRY, J. H	8009290028	50-489 0
Mathews, e. r	8009260273	50-305 R	MCBREARTY, R A	8009190259#	50-387 0	MCGARRY, J. H	8009290028	50-488 0
MATHEWS, E R	8009110378	50-305 P	HCBREARTY,R A.	8007050484*	50-410 G	McGauchy, R W	8009190104*	50-443 0
MATHENY, D	8009290370#	50-346 S	MCBREARTY,R	8007100877*	50-289 G	McGauchy, R. W	8009100030*	50-352 0
MATHEWS, E R	8009290173	50-305 F	MCCABE,E.C	8007160227*	50-277 G	McGauchy, R W	8009190223*	50-354 6
MATHEWS, E R	8009300425	50-305 R	MCCABE,E.C	8007110050*	50-334 G	McGauchy, J. P	8009100344	50-416 8
MATHIS, C J	8009030607#	50-293 S	MCCALLIBTER,P	8007020177*	50-329 A	McGauchy, J. P	8006270284	50-416 8
MATHIB, C J MATHIB, C J MATHIB, C. J MATBON, V MATSON, V	8009090433* 8009220250 8009260485* 8009150433* 8009150438*	NOI8810MCD WOI881MCD WOI881MCD	MCGARTEN, J B MCCARDELL, R K MCCARREL, B, F MCCAULEY, E W MCCLAIN, C, M	8009190171* 8009100412 8009110011 8009110500 8009230544*	50-254 Q RES 50-344 G NUREG 50-217 R	MCGAUGHY, J P MCGAUGHY, J. P. MCGAUGHY, J P. MCGAUGHY, J. P. MCGAUGHY, R W	8009100335 8009100436 8009100558 8009100519 8009190241*	50-416 8 50-416 8 50-416 8 50-416 8 50-387 0
MATSON, E.	8009290079#	FOIA	MCCLINTOCK, R. O.	8009270048*	FOIA	HCGAUGHY, R H	8009100884*	50-352 0
MATSON, V	8009110629	XPORTLIC	MCCLINTOCK, R. O.	7704010088*	PTP	HCGAUGHY, R. H.	8009100893*	50-387 0
MATSON, V.	8009050469	XPORTLIC	MCCLINTOCK, R. O.	7704010084	PTP	HCGAUGHY, R H,	8009150097*	50-410 0
MATSON, V	80090110403	XPORTLIC	MCCLINTOCK, R. O.	8009270079*	FOIA	HCGAUGHY, J. P	8009100592	50-416 8
MATSON, V	8009020480	XPORTLIC	MCCLINTOCK, R. O.	8009270044*	FOIA	HCGAUGHY, J. P	8009040489	50-416 B
MATSON, V	8007020484#	XPORTLIC	HCCLINTOCK, R. O.	8001020105*	PT9	McGaugh, J. L.	8009120471*	50-326 0
MATSON, V	8007110497	XPORTLIC	MCCLINTOCK, R. O.	7912180310	PT9	McGaughy, R. W	8009150190*	50-354 0
MATSON, V.	8007110495	XPORTLIC	MCCLINTOCK, R. O.	8009290092*	FOIA	McGaughy, R. W	8009100870*	50-412 5
MATSON, V	8007110700	XPORTLIC	MCCLINTOCK, R. O.	8001020078*	PT9	McGaughy, J. P	8009240331*	50-416 0
MATSON, V.	8007110743	XPORTLIC	MCCLINTOCK, R. O.	8009120222*	40-2940	McGaughy, J. P	8009100303	50-416 8
Matson, V.	8007260218	XPORTLIC	MCCLINTOCK: R. O	8007240055*	70-710	HCGAUGHY, J. P	8007100347	50-416 6
Matson, V	8007260224*	XPORTLIC	MCCLINTOCK: R. O.	8007270041*	FOIA	HCGAUGH, J. L	8007120466*	50-326 0
Matson, V	8007300078	XPORTLIC	MCCLINTOCK: R. O.	8001020067	PT9	HCGAUGHY, J. P	8007020064	50-416 8
Matson, V	8007300077	XPORTLIC	MCCLINTOCK: R. O.	8007270152*	FOIA	HCGAUGHY, J. P.	8007020413	50-416 A
Matson, V	8007300084*	XPORTLIC	MCCLINTOCK: R. O.	8007160217	70-375	HCGAUGHY, J. P	8007080247	50-416 B

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
NCOAUGHY, J. P NCOAUGHY, J. P. NCOAUGHY, J. P NCOAUGHY, J. P NCOAUGHY, J. P	8009080328 8009080374 8009300029* 8009100486 8009150301	50-416 G 50-416 S 50-416 G 50-416 S 50-416 S	METLAY, D MEURINNEY, J A MEYER, K A. MICHELSON, C MICHELSON, C	8007050492 8007100053 8007300113 8007150077* 8007170753	FOIA NUREO FOIA 50-249 P 50-259 S	HILLS, L M HILLS, L M HILLS, L M HILLS, L M HILLS, L M	8007100284 8008130476 8008150212 8007040401 8007040430	50-328 S 50-390 B 50-390 S 50-390 S 50-390 B
MCGAUGHY, J. P. MCGAUGHY, J. P. MCGAUGHY, J. P. MCGAUGHY, J. P. MCGAUGHY, J. P.	8009160591 8009250417 8009260473 8009160387 8009230586	50-416 S 50-416 S 50-416 S 50-416 S 50-416 S	MICHEL, C. J. MICHELBON, C MICHEL, C. J. MICHEL, C. J MIDURA, H. J	8007070504 8007110577 8007110371 8007120421 8007070315	70-143 MISC 70-143 70-143 50-311 R	MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8009100526 8009150591 8008190458 8008190463 8009100576	50-518 S 71-9074 50-390 S 50-328 S 50-328 S
HCGAUCHY, J.P. HCGAUCHY, J.P HCGAUCHY, J.P HCGAUCHY, J.P HCGAUCHY, J.P	8009230471 8009230627 8009230595 8009240438 8009240480	50-416 8 50-416 8 50-416 8 50-416 8 50-416 8	MIDURA, H J MIDURA, H J. MIDURA, H J MILES, E MILHISER, R J	8009160351 8009160298 8009180249 8009120028 8009270396*	50-311 P 50-272 R 50-311 R CONTRACT 50-382 8	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8009220038 8009190410* 8009020104 8009020133 8009240400*	40-1341 50-259 Q 50-327 Q 50-259 Q 50-566 Q
MCGAUGHY, J P MCGINNIB, J. MCGINNIB, J A MCGINNEB, J. MCGOEY, R. J.	8007230456 8007270077* 8007270087* 8007270152* 8007260443*	50-414 A FOIA FOIA FOIA 50-287 T	MILHIBER.R.J MILLER.R.N MILLER.D R MILLER.W H MILLER.M E	800930033B 8009150139# 8009110827 8009120539# 8009050451	50-382 8 50-201 U 40-4826 50-250 @ 70-1308	MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8007030406 8007300067* 8007110181* 8007240387* 8007020046	50-259 P 50-259 Q 50-327 Q 50-518 Q 50-390 S
MCORATH, E.T. MCORATH, J.R MCOREGOR, L. MCOUIRE, J. MCOUIRE, P. J.	8009300188 8009230655 8009150025* 8009300218 8009090389	70-2705 1&E 50-373	MILLER, W.D. MILLER, W.D. MILLER, W.D. MILLER, W.D MILLER, W.D	8007110835* 8007030475* 8007050377 8007070835 8007070836	40-4826 50-263 F 71-5942 70-25 70-27	MILLS, L M MILLS L M MILLS L M MILLS, L M	8007020056 8007040484 8007100472 8007240357 8007020281	50-390 S 50-553 A 50-553 A 50-518 Q 50-327 S
MCQUIRE, P. J. MCQUIRE, P. J. MCQUIRE, P. J. MCQUIRE, D. R. MCQUIRE, D. R.	8009020382 8009030477 8009030596 8009030603 8009230210*	50-293	MILLER, J.R MILLER, J.R MILLER, J.R MILLER, W.O MILLER, W.O MILLER, W.H	8007020128 8007080474 8007080478* 8007110560 8007050176*	TOPREP 50-146 P 50-166 P 50-311 P 70-1151	MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8007020069 8007020081 8007020094 8007030560 8007030574	50-296 P TOPREP 50-390 K 50-327 K 50-390 K
HCQUIRE, D.R. HCQURREN, H.J. HCQURREN, H.J. HCQURREN, H.J. HCQURREN, H.J.	8009250360* 8009040276 8009050083 8009110021 8009230038	50-280 Q 50-528 Q 50-528 H 50-376 Q 70-1729	MILLER, W. D. MILLER, W. O. MILLER, W. O. MILLER, H. J MILLER, W. O	8007020184 8009030677 8009080483 8009190781 8009030248	50-277 P 50-346 P 50-313 P 40-8692 50-313 P	HILLS:F H HILLS:F H HILLS:F H	8007250075 8007020404 8007070524 8007070427 8007070530	50-259 Q 50-276 P 50-438 Q 50-518 S 50-518 S
McOurren, H. J McOurren, H. J. McOurren, H. J McK I Been, J. C. McK I Been, J. C.	8009230049 8009250007 8009250022 8009030212 8009040406	50-376 G 50-376 G 50-376 G 50-186 R 50-186 B	MILLER, W. O MILLER, H. J. MILLER, W. O MILLER, W. O. MILLER, W. O	8009110696 8009160020 8009090881 8009220394 8009220388	50-309 P 40-8743 50-338 P 50-409 P 50-286 P	MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8007030436 8007030508 8007030536 8007030548 8007070414	50-327 P 50-260 P 50-327 F 50-391 F 50-327 R
MCK 188EN, J.C. MCK 188EN, J.C. MCLAUGHLIN, J.P MCLAUGHLIN, H.T. MCLAUGHLIN, W.T	8007040418 800723058& 8007240051* 8007030577* 8007220231	50-186 8 50-186 P 70-710 50-293 B RM	MILLER, H. J. MILLER, J. R. MILLER, M. E. MILLER, H. J. MILLER, H. J.	8009100473 8009160434 80090200#4 800914	40-8768 50-131 F	Hirrä'r H Hirre'r W	8007070434 8007070440	50-518 S 50-518 S
MCLAUGHLIN,M T MCLAUGHLIN,M T, MCLAUGHLIN,M T MCLENNAN,J.D, MCLDUGHLIN,M T	8009160402* 8009230739* 8009290313* 8009190248 8009090401*	50-293 8 50-293 8 50-293 8 50-440 K 50-293 8	MILLER, J. R. MILLER, J. R MILLER, H. J. MILLER, J. R MILLER, M. I	80091 80091 80091 80091 80090				
MCLOUGHLIN,M T MCLOUGHLIN,M.T MCLOUGHLIN,M.T. MGLOUGHLIN,M,T. MCLOUGHLIN,M T	8009090376* 8009160483* 8009160410* 8009160435* 8009170381	50-273	MILLER, M. I. MILLER, L. K MILLER, J. R. MILLER, R. W. MILLER, W. O.	80090 80092 80092 80091				
HCLOUGHLINM T HCLOUGHLINM T HCLOUGHLINM T HCLOUGHLINM T HCLOUGHLINM T.	8009240463* 8009240468* 8009260475* 8009260484* 8009300535*	50-293 8 50-293 8 50-293 8 50-293 6 50-293 8	MILLER, W. D. MILLER, M. E. MILLER, M. E. MILLER, W. O MILLER, W. O	80091 80091 80092 80092				
MCMTLLENIN H MCMTLLENIN.H MCMETLLI H M MCMRJLTYI A MCPHERSONIH	8009100261 8009180460 8009180119* 8009120505 8009150178*	50-445 M 50-445 M GA999 50-206 P GONTRACT	MILLER, M. E. MILLER, M. E. MILLER, L. K. MILLER, L. K. MILLER, L. K.	80091 80091 80091 80091 80092				
HCVEIN, J HEACHUM, T R HEANS, D S HECHON, S J. HECHON, S. D.	8007240067* 8007260067 8007180528 8007070020 8007160376	CONTRACT RES 50-522 9 NUREQ 50-293 8	MILLER, W. O. MILLER, J. R. MILLER, J. R. MILLER, J. R. MILLER, J. R.	80091 80093 80093 80095 80092				
HEDROW, L. A K. MEDROW, L. A K MEDROW, L. A. K MEEK, W. E. MENARD, H W.	8009180143 8009190188 8009180320 8009260417* 8009300646	CONTRACT CONTRACT CONTRACT 50-287 T NUREO	MILLER, M. I. MILLE, L. M.	90093 19008 19008 19008				
HENCZER, W B HENEFEE, M B. HERCER, W. HERRIWEATHER, N HERRIWEATHER, N	8009170070* 8009170365* 8009180255 8009240276* 8009100307*	FDIA 50-320 H PT21 50-370 Q 50-364 Q	MILLS, L. M MILLS, L. M. MILLS, L. M MILLS, L. M. MILLS, L. M.	80090 80091 80090 80090 80090				
MERRITT, C. J. MERSON, S. D. MERSON, S. D. MESCHER, M. C. MESSINGER, M	8007050354 8007270246 8007270248* 8007180366 8007050174*	50-327	MILLS: L. M MILLS: L. M MILLS: L. M. MILLS: L. M. MILLS: L. M.	80070 80071 80070 80070 80071				

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORI
HILLS, L H HILLS, L H HILLS, L H	8009240425 8009300195 8009220210 8009230611 8009190488	50-518 8 50-327 0 50-259 P 50-390 8 50-259 P	MODENOS, L MOELLER, D W MOMBOISSE, R M MOMBOISSE, R M MONROE, J D	8007020337 8007100158 8007110012 8007110012 8007240357	NUREO PR PR	MORTON, K V MORTON, K V MORTON, K V MORTON, K V MORTON, K V	8009180217 8009240028 8009240238 8009240130 8009240038	* CONTRACT * CONTRACT * CONTRACT
MILLE,L M MILLE,L M MILLE,L M MILLE,L M	8009230333 8009230549 8009240372 8009250254 8009250273	50-327 F 50-327 P 50-518 S 50-438 S 50-390 S	MGNTGDHERY, D M MOODY, D E MOODY, D E MOODY, D E MOODY, D E	8007160497* 8007080526 8007080541 8007120275 8007080522	50-280 Q 50-27 Q 50-307 Q 50-307 Q 50-27 Q	MORTON, K. V. MORTON, K. V. MORTON, K. V. MOSCHNER, R. A.	8009290142 8009300597 8009260247 8009300264 8009190751	CONTRACT
MILLS.T MILLS.L M MILLS.L M MILLS.L M MILLS.L M	800725000B 8007230560 8007230610 8007250240 8007270324	50-445 Q 50-390 B 50-390 B 50-438 S 50-390 B	HOODY, D E HOODY, D E	8007080528 8007120207 8007020050 8007160257 8007160287	50-307 G 50-309 G 50-266 U 50-309 R 50-29 R	MOBB.L B MOTT,W E MOTT,W R MONRY,W R MROCZKA,E J	8909020174 8009190742 8009220044 8009300088 8009020377	FOIA HABTE MOT HABTE MOT XPDRTLIC 50-245
MILLS.L M MILLS.L M MILLS.L M MILLS.L M	8009290327 8009290332 8009290344 8009290346 8009290355	50-390 S 50-328 S 50-390 S 50-438 S 50-553 B	MOON, CH. MOON, CH MOONEY, O MOORE, RN MOORE, RL	9007020058 8009110327 8009170423 8009150422* 7909040723	50-466 G 50-454 A 40-8692 COMMISSION RECOD	MROCZKA, E J MROCZKA, E J MROCZKA, E J MROCZKA, E J MROCZKA, E J	8009020284 8009190456 8009190460 8009160457 8009260649	50-336 E 50-245 A 50-336 E 50-336 E
MILLS.L H MILLS,L H MILLS,L H MILLS,L H MILLS,L H MILLS,L H	8009290375 8009290333 8009270350 8009300226 8009300400	50-518 S 50-327 P 50-328 S 50-327 P 50-259 P	MODRE, N MODRE, R N MODRE, G H MODRE, G H MODRE, R N	8009150442* 8009150446* 8009030390 8009030395* 8009190755	COMMISSION COMMISSION 50-334 R 50-334 R XPORTLIC	MROCZKA, E J MUCHNICKI, E D MUELLER, A J MUELLER, R J MULLER, R E	8009230345 8009100444 8009180204# 8009300539# 8009120607	50-336 R PR GA799 50-265 G XPORILIC
MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8009300411 8009300429 8009300480 8009290262 8009300147	50-438 8 50-294 P 50-438 B 50-327 P 50-259 P	HOORE, R N MOORE, J, E MOORE, O W MOORE, D E MOORE, V A	8009230119 8009040262 8009100609 8009250360* 8009180170	XPORTLIC 50-155 0 50-334 P 50-280 0 50-311 E	MULLHOLLAND, J L L. GRAUM L L. GRAUM MUNED, J J GRAUM MULLHOLLAND, J	8009110410* 8009100150 8009160204 8009020513 8009160459	CONTRACT TOPREP PRH 71-9039 XPORTLIC
MILLS, L M MILLS, L M MILLS, L M	8009300348 8009300353 8009300427 8009300445 8009300395	50-438 S 50-259 P 50-438 S 50-518 8 50-328 8	MOORE, J HORAN, D M MORIARTY, J M HORISI, A V MORISI, A V	8007260414* 8007040361 8007040425 8007070261 8007160346	50-289 T 50-289 0 50-352 B 50-293 R 50-293 P	MUNTB.M.L MUNTZINO.L M MUNTZINO.L M MURPIN,H B MURPHY.G E	8009240490 8009150052* 8009150065* 8009120502 8009240228*	50-246 U F-29-00 90-29-00 90-26-00 90-26-00
MINECK, D L	8009300465 8009030466 8009170315 8009170324 8009170348	50-328 8 50-331 8 50-331 8 50-331 8 50-331 8	Morisi, a v Morris, p a Morrison, h p Morris, m d Morrow, d	8007230453 8007070348* 8007020462* 8007260405* 8007020470	50-293 P FOIA 50-395 M 70-2560 40-8502	MURPHY, C E MURPHY, C E MURPHY, C E MURPHY, C E	8009160337* 8009240363* 8009100130 8009240302* 8009120526*	50-269 q 50-324 q 50-369 q 50-413 q 50-250 q
MINECK, D L MINECK, D L MINECK, D L MINGS, N J MINGOUE, R B	8009170355 8009170363 8009190499 8009300493 8009190768	50-331 8 50-331 8 50-331 R 50-331 8 REB	MORROW, P. E MORBE, A. X MORBE, A. X MORBE, A. X MORBE, A. X	8009160450 8009230001 8009230002* 8009260672 8009260677*	NUREO 50-409 0 50-409 0 50-409 0 50-409 0	MURPHY, C. E MURPHY, C. E MURPHY, C. E MURPHY, C. E MURPHY, C. E	8009120498# 8009140535# 8009030032 8009030138 8009150372#	50-250 0 50-269 0 50-390 0 50-395 0 50-370 0
MINOQUE, R B	8009190320* 8009190364* 8009190480* 8009190494* 8009190484*	FOIA FOIA FOIA FOIA	MORTENSEN, W MORTON, K V MORTON, K V MORTON, K V MORTON, K V	8009240480 8009230359* 8009100071 8009100077* 8009030255*	70-2786 CONTRACT CONTRACT CONTRACT SECY	MURPHY, C. E MURPHY, C. E MURPHY, C. E MURPHY, C. E MURPHY, C. E	8009090253 8009120135 8009120425* 8009150332 8009190588*	50-553 0 50-416 0 50-418 0 50-321 0 50-346 0
MINOQUE, R B	8009190532# 8009190550# 8009190587#	FOIA FOIA FOIA FOIA FOIA	MORTON, K V MORTON, K V MORTON, K V MORTON, K V MORTON, K V	8007040470# 8007240077# 8007110002# 8007110003# 8007110004#	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MURPHY, C E MURPHY, C E MURPHY, C, E MURPHY, C E MURPHY, C E	8008280106 8009050415 80092402464 8009240267#	50-400 @ 50-364 g 50-370 q 50-413 g 50-510 @
MINOGUE, R B MINTZ, S MIRAGLIA, F MIRAGLIA, F MITCHELL, D B	8009030067# 8009230431# 8009300220 8009300295	PR REGOD TOPREP 50-458 A 50-275 H	MORTON, K. V. MORTON, K. V. MORTON, K. V. MORTON, K. V. MORTON, K., V	8009120017 8009120019# 8009110005# 8009100035 8009100041#	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MURPHY, C E MURPHY, C. E. MURPHY, C. E MURPHY, C. E MURPHY, C E	8009240398# 8009110107 8009100300# 8009250109	50-516 Q 50-375 Q 50-364 Q 50-566 Q
MITCHELL, D O MITCHELL, D O MITTL, R. L MITTL, R. L MITTL, R. L	8009120342* 8009220291* 8008280311 8009040352	CONTRACT 50-289 8 50-289 R 50-311 F 50-311 P	MORTON, K. V MORTON, K. V MORTON, K. V MORTON, K. V MORTON, K. V		CONTRACT CONTRACT CONTRACT 70-2313 CONTRACT	MURPHY, C E MURPHY, C E MURPHY, C E MURPHY, C E MURPHY, C E	8007240066 8007300031* 8007170161 8007050173 8007240274*	50-280 0 50-335 0 50-414 9 50-320 9 70-1151
MITTLER L. MITTLER L. MITTLER L. MITTLER L	8009090332 8009090312 8009190213 5	0-311 G 0-311 P 0-311 P 0-311 F 0-311 F	MORTON, K V MORTON, K V. MORTON, K, V MORTON, K V MORTON, K V	8009110254* 8009100003* 8009110350*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MURPHY, C E MURPHY, C E, MURPHY, C E, MURPHY, C E, MURPHY, C E	8007100250# 8007180454# 8007180366 8007110824 8007120486	50-410 g 50-400 g 50-400 g 50-370 g 50-321 g
MITTL,R L MITTL,R L MITTL,R L MITTL,R L MITTL,R L	8009190396 5 8009190479 5 8009190515 5 8009190527 5	0-311 P 0-311 Q 0-311 P 0-311 P 0-311 P	MORTON, K. V HORTON, K. V HORTON, K. V. HORTON, K. V MORTON, K. V	8009110331 8009110338* 8009110410*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MURPHY, C E MURPHY, C E MURPHY, C E MURPHY, C E MURPHY, J, R	8007120515 8007250341* 8007240201 8007240256	50-250 0 50-250 0 50-413 0 50-369 0 50-370 0
MITTLAR L MITTLAR L MITTLAR L MITTLAR, L MITTLAR, L	8009190466 50 8009180455 50 8009180458 50 8009190836 50	)-311 P )-311 P  -311 Q  -311 P  -311 P	MORTON, K, V MORTON, K, V, MORTON, K, V MORTON, K, V, MORTON, K, V,	8009120012* (8009230755* (8009230771* (8009120033* (8009120033* (8009120033*)	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MURPHY, W P. MURPHY, W P. MURPHY, C. E. MURPHY, C. E. MURPHY, G. E.	8007050318 8007050322* 8007240282 8007240292	NUREQ 50-271 8 50-271 8 80-413 0 50-413 0
MITTLIR L HITTLIR L HIYABAYASHI,H HIYABAYASHI,H	8009220280 50 8009290361 50	-311 P -311 P -272 P DRTLIC DRTLIC	MORTON, K. V. HORTON, K. V. MORTON, K. V MORTON, K. V NORTON, K. V	8009230777* C 8009230777* C	ONTRACT ONTRACT ONTRACT GNTRACT ONTRACT	MURPHY, C E MURPHY, P. M MURPHY, C E MURPHY, G E, MURPHY, M J	8009240583 8009090446 8009190576 8009240329	50-518 0 50-586 9 50-255 9 50-248 9 50-224 9 50-211 8

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR	ACCESSION NUMBER	8UBJECT CATEGORY
PRRPHY, H J PRRPHY, H J PRRPHY, K J PURPHY, C E PURPHY, H J	8009120372* 8009120392* 8009120428* 8009160533 8009130267*	50-272 8 50-272 8 50-272 8 50-272 8 50-267 0 50-311 8	NEWMAN, R J NEWMAN, R J NEWMAN, J R NEWMAN, J R NEWMAN, J R	8009090558* 8009090595* 8009180475 8009180475 8009180475	50-311 50-272 50-446 50-466 50-466	8 9 0 0	NORDERHAUG.L R NORDERHAUG.L R NORDLINGER.M S NORDLINGER.M S NORDLINGER.M S	8009170209 8009180289 8009020071 80090907779 8009090632	70-734 70-754 50-275 0 50-275 T 50-275 F
MURPHY, C E MURPHY, H J MURPHY, C. E MURPHY, J MURRAY, T, D	8007250347 8007140482* 8007300026 8007170256* 8007080317	50-400 G 50-311 8 50-416 G 50-440 K 50-346 R	NEHMAN, J R NEHMAN, J R NEHMAN, J R NEHMAN, J R NEHMAN, J R.	8009170149 8009170169 8009170171* 8009300027 8009300027	50-582 50-582 50-582 50-466 50-466	0 0 0 0	NORELIUS, C E NORELIUS, C E NORTON, B NORTON, B NORTON, B	8009190171# 8009240415# 8009220213 8009030489 8009030489	50-254 Q 50-329 Q 50-323 Q 50-275 Q
NURRAY, T. D. MURRAY, M. J. MURRAY, M. J. MURRAY, T. D. MURRAY, M. J.	8009020333 8009020048 8009020084 8009020057 8009160281	50-346 S 50-367 0 50-367 0 50-346 B PR	NEWMAN, J.R. NEWMAN, J.R. NG, C NG, C NICHOLS, D.L	8009300469 8009300469 8009170296* 8009170314* 8009040269*	50-466 50-466 50-244 50-244 50-155	0 0 P P 0	NORTON, B NORTON, B NOSENZO, L V NOSENZO, L V NOSENZO, L V	8009030599 8009030649 8009150428* 8009080547 8009080279	50-275 0 50-275 0 COMMISSION XPORTLIC XPORTLIC
HURRAY, T D. HURRAY, T D HURRAY, J P. HURRAY, J P. HURRAY, J P.	8009190276 8009160391 8009290002 8009290004* 8009290005*	50-346 R 50-346 8 50-266 U 50-266 U 50-266 U	NICHGLSON, N A NICHGLS, T C NICHGLS, T C NICHGLS, T C NICHGLS, T C.	8007170121* 8007160634* 8007100427 8007180511 8007020031	40-2061 50-395 50-395 50-395 50-395	a 8 0 0	NOSENZO, L V NOSENZO, L V NOSENZO, L V NOSENZO, L V, NOSENZO, L V	8009100155 8009300664 8009180296 8009290136 8009300650	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
HURRAY, T D MURRAY, H J MURRAY, T D MURRAY, T, D MURRAY, T D	8007120351 8007220177 8007230682 8007230686* 8007230670	50-346 8 50-367 0 50-346 8 50-346 8 50-346 8	NICHOLS: T C NICHOLS: T C. NICHOLS: T C. NICHOLS: T C NICHOLS: T. C	8007020065 8007250072 8007030460 8007030493 8007110719	50-395 50-395 50-395 50-395 50-395	M Q Q A Q	NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V NOVAK, T. M NOVAK, T. M	8007300660 8007300074 8007270130 8007110563 8007070774	XPORTLIC XPORTLIC XPORTLIC 50-320 P 50-286 P
MURRAY, K J HURRAY, T D HURRAY, J. P MURRAY, T D MUSTAIN, H J	8007220173 8007230671 8007230447 8007270363 8007240727*	50-367	NICHOLS, T C NICHOLS, T C NICHOLS, T C, NICHOLS, T C, NICHOLS, T C	8007030621 8007080337 8007180129 8007100320 8007110211	50~375 50~375 50~375 50~375 50~375	8 9 4 A	NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M	8009110853 8009030201 8009040076 8009040085 8009040114	50-334 P 50-289 I 50-285 F 50-269 P 50-293 P
MUZZY.R J MYERB.J A MYNATT.F R. MYNATT.F R MAIDU.K R	8007230431* 8007070380 8007150311 8007120967 8007110324*	TOPREP 50-320 H RES RES 50-454 Q	NICHOLS, T C NICHOLS, T C, NICHOLS, T C NICHOLS, T C NICHOLS, T, C	8009120347 8009300590 8009150314 8009170294 8009230282	50-395 50-395 50-395 50-395 50-395	A Q K A F	NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T, M	8007020330 8007030344 8007100178 8007170774 8007150427	50-312 F 50-312 P 50-295 P 50-3 P 50-250 P
NAIDU, K.R. NAIDU, K.R. NAPUDA, G. NAPUDA, G. NARBUT, P.P.	8009170221* 8009110675* 8009090250* 8009180005* 8009120500*	50-456 Q 50-484 Q 50-287 Q 50-334 Q 50-528 Q	NICHOLS: T C NICHOLS: T C. NICHOLS: T C NICHOLS: T C NICHOLS: T. C	8007230276 8007240552 8007240337 8007300168 8007260516	50-375 50-375 50-375 50-375 50-375	A A A	NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M	900922006/ 8009180549 8009240093 8009300578 8009260529	50-309 H 50-321 P 50-309 H 50-271 P 50-338 P
NARBUT, F, P. NARROW, L. NAUGHTON, W. F NAUGHTON, W. F NAUGHTON, W. F	8007300054* 8007100870* 8007250344* 8007020107 8007030437	50-312 Q 50-412 Q 50-295 Q 50-10 Q 50-295 P	NICOLOSI, B L NIEHAUS, P W NIERODE, C F. NIMITZ, R. L NIMITZ, R. L	8009190401 8009150042 8009250640* 8009090189* 8009100044*	RES 50-358 50-243 50-217 50-217	8 8 0	NOVAK, T M NOVARRO, J P NOVARRO, J P NOVARRO, J P. NOVARRO, J P	8009170256* 8009120254 8009030433 8009020425 8009030437	50-287 0 50-322 0 50-322 0 50-322 A 50-322 A
NAUGHTON, IF F NAUGHTON, IF F NAUGHTON, IF F NAUGHTON, IF F NAUGHTON, IF F	8007080355 8007110300 8007100532 8007170448 8007170403	50-295 P 50-295 P TOPREP 50-295 P 50-295 P	NISHITA.H NIX.R T NIX.R T NIX.R T NIX.R T	8009190405 8009020374# 8009020405# 8009020444# 8009020446#	Nureo 50-366 50-366 50-321 50-321	\$ 8 6 8	NOVARRO.J P NOHICKI,S J NOHICKI,S J NOHICKI,S J NUGENT,E L	8007230570 8007020448 8007100008 8007120547 8007240045	50-322 A 50-206 Q 50-206 P 50-206 P 40-2259
NAUCHTON, H F NAUCHTON, H F NAUCHTON, H F, NAUCHTON, H F, NAUCHTON, H F	8007300287 8007230672 8007260213 8007300267 8007300485	50-10 V TOPREP 50-295 P 50-275 P 50-454 A	NIX.R T NIX.R T, NIX.R T, NIX.R T NIX.R.T	8007020433* 8007070480* 8007070475* 8007150335* 8007150385*	90-366 90-321 50-366 50-366 50-321	5 6 6 6	NUGENT, E L NUGENT, E L NUGENT, E L NUGENT, E L NUMMERY, W J	8009030510 8009110402 8009140349 8009190393 8009110411	40-2259 40-2259 40-2259 40-2259 50-266 H
NAVARRO, J. P. MEALE, J. B MEEL, J. N ME LOHBORB, J. D ME LOHBORB, J. D	8007120123* 8007160305* 8007120156* 8007100645* 8007150248*	50-322 \$ 50-304 \$ 27-48 50-247 P 50-334 P	NIX,R T NIX,R.T NIX,R T NIX,R T, NIX,R T	8009150386* 8009160306* 8009290281* 8009300502* 8009300526*	50-321 50-366 50-366 50-321 50-366	8 8 8 8	NYCOARD, G R O'BRIEN, J P O'HANLON, J P O'NEILC, B	8009230001 8009120490* 8009050330 800902045B* 800929006B*	50-409 0 50-312 0 50-313 V 50-368 8 FOIA
NEIGHBORB, J. D NEIGHBORB, J. D NEIGHBORB, J. D, NEISLER, J NEIBLER, J. H.	8007180122* 8007180552* 8007240077* 8007250352* 8007180280*	50-261 P 50-280 P 50-315 P 50-461 G 50-373 G	NIXON, H A NOELL, P N NOELL, P, N NOELL, P, N NOELL, P N	8007180440 8007020148* 8007020463* 8007020467* 8007020470*	40-2061 50-331 50-10 50-10 50-10	<b>ዞ</b> ዎ ዎ P	O'NEILL, B O'NEIL, R. A O'NEIL, R. A O'NEIL, R. A O'NEIL, R. A	8009270079# 8009040196 8009040196 8009300496# 8009300035	FOIA 30-445 M 50-445 M 50-445 M
NETBLER, J H. NELBON, P R. NELBON, P R. NELBON, P. R NELBON, C C.	8009290465* 8009150118* 8009150121* 8009150138* 8009050489	50-373 Q 50-201 U 50-201 U 50-201 U 50-70 P	NOELL.P N NOELL.P N NOELL.P N NOELL.P N. NOELL.P N	8007020473* 8007020474* 8007040103* 8007040127* 8007040315*	50-10 50-10 50-155 50-243 50-324	P P P P	O'NEIL, RA O'NEIL, RA O'NEIL, R.A O'NEILL, JH O'REILLY, J.P	8009300488 8009300496* 8009300035 8009300410 8009150094*	50-445 M 50-445 M 50-445 M 50-266 0 50-201 U
NELSON: P. R NELSON: P. R NEHETH: K. J NEUFER: A. G NEUFER: A. G	8007020012 8007300207 8007030184* 8007230360* 8007270321*	50-225 F 71-396 State Prog 50-338 R 50-338 R	NOELL, P N NOELL, P N NOELL, P N NOELL, P, N NOELL, P, N	8007040544# 8007030436# 8007030501# 8007150426# 8007170260#	50-271 50-293 50-29 50-317 50-333	P P P P	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009090055 8009090057 8009090069 8009090073 8009090075	50-324
NEUMANN, M R NEUMANN, M R NEUMANN, M R. NEUMANN, M R. NEUBCHAEFER, E	8008110042 8007240153 8007240024 8007170237 8007030409*	40-8721 40-8380 40-8380 40-8380 50-302 8	NOELL, P. N. NOELL, P. N NOLAN, F. NOON, F NOON, F	8009170402# 8009180217# 8009190765 8009170295 8009170298	50-220 50-336 50-259 50-244 50-244	P B P P	O'REILLY, J.P O'REILLY, J.P O'REILLY, J.P O'REILLY, J.P O'REILLY, J.P	8009100910* 8009050431* 8009100040 8009100042 8009100044	70-143 50-280 50-348 50-241 50-302
NEUSCHAEFERIE NEWFANIR.J. NEWHANIR.J. NEWHANIR.J. NEWHANIR.J.	8007110342* 8007030571* 8007030520* 8007070455* 8007070550*	50-302 8 50-311 8 50-311 8 50-311 8 50-311 8	NOON, F NORDERHAUG, L. R NORDERHAUG, L. R NORDERHAUG, L. R NORDERHAUG, L. R,	8009170312 8009170212 8009050188 8009150510 8009150545	50-244 70-734 70-25 50-312 70-1739	e G	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009100049 8009100051 8009100054 8009100058 8009100063	50-250 50-327 50-280 50-289 50-328

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACC
O'REILLY, J P	6007100065 6007020303 8007020222 6007100702 6007030123	50-404 @ 50-327 @ 50-259 @ 70-143 50-348 @	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009290276 8009290277 8009290282 8009290287 8009290293	50-348	PAGE.P L PAGE.P L PAGE.P L PAGE.P L PAGE.P L	8009 8009 8009 8009 8009
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009030125 8009030128 8009030129 8009030130 8009030137	50-302 0 50-416 0 50-395 0 50-395 0 50-488 0	O'REILLY, J P O'ROURKE, S A OBERG, C T OBERG, C R OBERG, C R	8009290297 8009050453 8006120884= 8009090648* 8009150348=	50-269 G 71-9853 PT9 50-482 G 50-482 G	PACE.P L PACE.P L PACE.P L PACANO.F G PAGE.R O	8004 8004 8004; 8004; 8004
D'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009030141 8009030146 8009030154 8009030158 8009030163	50-280 0 50-259 0 50-321 0 50-250 0 50-261 0	OBERO, C R OEBTMANN, M J OHLSSON, K OLLER, R E OLSEN, R N.	8009150362* 8009260665* 8009190726 8009150173* 8009090614	50-450 0 50-346 0 REGOD GA979 XPORTLIC	PAGE.R Q PAGE.R G PAGE.R G PAGE.R G PAGE.R G	80091 80091 80091 80091
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007030175 8007030181 8007160036 8007160037 8007160040	50-269 G 50-437 G 50-416 G 50-321 G 50-324 G	OLSEN, A F OLSEN, A F OLSEN, F M OLSHAN, L. N OLBON, R C	8007110667 8007030443 8007260014 8007230230 8007030014	70-824 50-99 P 50-409 Q 50-284 P NUREO	PAGLAIRO.J, PAOLINO.R PAPAY,L T PAPAY.L T PAPERIELLO.C J.	80092 80090 80090 80093
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007160049 8007230388 8007230371 8007230376 8007230377	50-259 G 70-824 70-27 70-1097 70-1151	OLSON, N J OLSON, J F OLSON, J, F, OPREA, G W OPREA, G W	8009020219 8009030726 8009300039 8009030170# 8009180479	50-445 A 50-282 0 50-282 0 50-498 0 50-498 8	PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C J. PAPERIELLO, C, J PAPPAB, H	800 72 800 72 800 53 800 61 800 70
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009230398 8009230400 8009230404 8009050422 8009120066	70-1201 50-332 G 70-143 50-280 G 50-518 Q	OPREA, O W OPREA, O, W OPREA, O, W OPREA, O, W OPREA, O W	8009190147 8009180467 8009180461 8009020288 8009020290	50-498 8 50-498 0 50-498 6 50-498 8	Pappas, H Pappas, H Pappas, H Pappas, H. Pappas, H	80090 80091 80092 80091
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009120072 8009120077 8009120080 8009120082 8009160108	50-324 Q 50-321 Q ' 50-416 Q 50-259 Q 50-437 Q	OPREA, Q W OPREA, Q. W OPREA, Q W OPREA, Q W OPREA, Q W	8007300545 8007300555 8007040377 8007050364 8007110384	50-498 @ 50-498 @ 50-498 8 50-498 @ 50-498 B	Pappas, H Pappas, H Pappas, H Pappas, H Paris, O H	80091 80092 80092 80092 80091
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J, P O'REILLY, J P	8007160110 8007160113 8007160115 8007160118 8007160120	50-348	OPREA.G W OPREA.G W OPREA.G W OPREA.G W	8009080201 8009110367 8009300536 8009230603 8009230617	50-498 A 50-498 B 50-498 Q 50-498 8 50-498 B	PARKER,W O PARKER,W O PARKER,W O PARKER,W O PARKER,W O	80072 80071 80071 80072 80072
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009160124 8009160133 8009160137 8009160143 8009160147	50-261 Q 50-488 Q 50-269 Q 50-250 Q 50-321 Q	OPREA.O W OPREA.O W OPREA.O, W OPREA.O W. OPREA.O W	8009150559 8009230658 8009240439 8009230402 8009230161	50-498 K 50-498 S 50-498 S 50-498 B 50-498 B	PARKER, W. O PARKER, W. O PARKER, W. O PARKER, W. O PARKER, W. O	800924 800924 800914 800911
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009160153 8009160172 8009230249 8009230252 8009230256	50-259 0 50-280 0 50-348 F 50-261 F 50-269 F	OPREA, O. W ORDERS, W ORLOSKY, P ORMONDE, S ORNICH, J	8009300453 8009300640* 8009160340* 8009120594 8009300338	50-498 8 50-269 0 50-57 I FOIA 50-382 8	PARKER, W D PARKER, W D PARKER, W D PARKER, W D PARKER, W D	800711 800705 800705 800717 800724
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009230258 8009230261 8009230265 8009230267 8009230273	50-302 F 50-250 F 50-321 F 50-259 F 50-280 F	ORTENBERO, L. I OBANN, E. W OBANN, E. H OBANN, E. H OBANN, E. H.	8009080299* 8009030703 8009030710 8009030703 8009030710	50-348 P 50-367 0 50-367 0 50-367 0 50-367 0	PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	800924 800914 800914 800917 800924
D'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009230277 8009230323 8009230325 8009260274 8009260277	70-824 70-27 70-143 70-1349 70-2872	OBANN, E W OBANN, E W OBANN, E W OBANN, E W	8009230008 8009230382 8009230393 8009230393	50-367 Q 50-367 Q 50-367 Q 50-367 Q 50-367 Q	PARKER, W. O PARKER, W. O PARKER, W. O PARKER, W. O PARKER, W. O	\$07000 \$07000 \$07000 \$057000 \$07000
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009260314 8009260316 8009260317 8009120248 8009120251	70-2621 70-2520 70-1397 50-437 G 50-348 G	OSANN, E. W OSANN, E. W. OSANN, E. W OSTRANDER, F. W OTT, L. J	8009230393 8009240011 8009240011 8009300544 8009100944	50-367 9 50-367 9 50-367 0 50-344 9 NUREO	PARKER, W O PARKER, W O, PARKER, W O, PARKER, W O, PARKER, W O	800702 800711 800712 800725 800704
O'REILLY, J P O'REILLY, J P O'REILLY, J P, O'REILLY, J P,	8009120258 8009120245 8009120284 8009120290	50-302 0 50-416 0 50-375 0 50-395 0 50-261 0	OTT, R F OTT, W R. OTTINGER, R. L OTTOSON, H L OTTOSON, H L.	8007300575* 8007300303 8007110471* 8007070811 8007170207	CONTRACT NUREO 50-320 U 50-206 Q 50-206 Q	PARKER, W O	800708 12: 12:0708 12:0708 12:0708
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009120300 8009120308 8009120311 8009120314 8009120340	50-488 G 50-250 G 50-321 G 50-260 G 50-259 G	0TT0SON; H L. 0TT0SON; H L 0TT0SON; H L 0TT0SON; H L 0TT0SON; H L	8009150011 8009140430 8009140521 8009020078 8009030533	50-206 Q 50-206 Q 50-206 Q 50-206 S 50-206 R	PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	800909( 800910( 800912( 800914( 800912(
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009120343 8009230521 8009230525 8009230526 8009240375	50-267 Q 50-259 Q 50-321 Q 50-324 Q 50-259 Q	OUZTS, J E OVERBERGER, C, O ' OVERLID, T, W OVERLID, T, W OVERLID, T, W	8009150375* 8009150225 8009030401* 8009230641* 8009230630*	50-324 G REGOD 50-263 S 50-263 S 50-263 S	PARKER, W O PARKER, W O PARKER, W, O PARKER, W O PARKER, W O	80071 1 C 80071 5 C 80071 5 C 80071 5 C 80072 5 C
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009260397 8009260517 8009290269 8009290271 8009290274	50-395 Q 50-280 Q 50-437 Q 50-414 Q 50-302 Q	OWEN.J B OWSLEY.G F OWSLEY.G F OWZARSKI,P C DIKER,D	8009220139 8009040490 8009260477 8009110419 8009220242*	TOPREP 50-335 P TOPREP RES 50-329 A	PARKER, W O PARKER, W O, PARKER, W. O PARKER, W. D PARKER, W O	8009160 8009360 8009360 8009160

AUTHDR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PARKER, W O	8009190462 8009180322 8009190399 8009190506 8009230724	50-269 R 50-369 A 50-369 A 50-369 A 50-269 P	PENDERGRAFT, R PEODLES. D L PEOPLES. D L PEOPLES. D L PEOPLES. D L	9007230748* 8007180261 8007110217 8007020274 8007170230	50-368 B 70-2609 70-2609 NUREO 50-237 G	PLESSET, M S PLESSET, M S PLESSET, M S POCHAL, W F POCHAL, W F	8007150238 8007150245 8007150247 8007150247 8007160287	50-327 G ACRS ACRS XPORTLIC XPORTLIC
PARKER, H O	8009240409	50-369 A	PERANICH, M W	8009150055*	50-445 Q	POCHAL, W F	8007230783	XPORTLIC
PARKER, H O	8009230496	50-270 S	PERDIKARIS, P C	8009020355	NUREQ	POCALIES, J K	8009100406	50-341 G
PARKER, H O	8009230509	50-270 S	PERKINS, T J	8009120413*	50-220 V	POCALIES, J K	8009100406	50-361 G
PARKER, H O	8009240448	50-369 V	PERKINS, T J	8009120417*	50-220 V	POGOIO, A	8009160498	RES
PARKER, H O	8009240489	50-369 A	PERKINS, M A	8009050243	50-320 S	POIRIER, L J	8009080352*	50-317 F
PARXER.W O	8009290371	50-367 A	PERKING, J	8009300010	50-289 G	POIRIER, M R	8009090453	50-498 M
PARXER.W O	8009260450	50-287 B	PERLMAN, J	8009120514*	50-206 P		8009150417	50-445 M
PARXER.W O	8009290303	50-369 A	PERLMAN, J	8009120037*	CONTRACT		8009150417	50-445 M
PARXER.W O	8009300428	50-269 J	PERLMAN, J	8009120115*	CONTRACT		8009160275	50-445 M
PARXER.W O	8009300434	50-369 A	PERLMAN, J	8009150414*	CONTRACT		8009160275	50-445 M
PARKER, W. O	B007300486	50-269 P	PERLMAN, J	8009150424*	50-206 P	POIRIER, M R	8007160182	50-445 M
PARKINSON, T F	B007300457	50-124 P	PERLMAN, J	8009240057*	50-206 P	POIRIER, M R	8007160192	50-445 M
PARSONS, E M	B007110411	50-266 H	PERLMAN, J	8009300276*	CONTRACT	POIRIER, M R	8007260318	50-445 M
PARTLOM, J, O	B007230168	70-1143	PERNY, C D	8009250439*	70-143	POIRIER, M R	8007260318	50-445 M
PARTLOM, J, O	B007030046	70-1120	PERRIGO, L D	8009110483	RES	POLANSKI, X	8007160426*	50-295 S
PARTLOW, J O PARTLOH, J O PARTLOH, J O PARTLOH, J O PARTLOH, J G	8007080487 8007150340 8007170242 8007160235 8007150387	70~687 70~1143 70~1113 70~754 70~1257	PERROTTI,D J PERRY,J C PERRY,J C PETERBON,K PETERSON,R M	8009220184* 8009100467* 8009260510* 8009160583 8009220116	50-335	POLK.P J POLLACK, B POLLARD, R D POLLARD, R D POLLARD, R D	8009190770 8009120435 8009230011 8009300420* 8009300422*	50-220 P 50-361 H 50-289 T 50-289 G 50-289 G
PARTLOH, J O	8009150395	70-143	PETERSON, M R	8009020120	XPORTLIC	POLLEIT, R	8009120442	50-361 H
PARTLOH, J O	8009290266	70-1201	PETERSON, M R	8009020129	XPORTLIC	POND, Ø D	8009260478	50-213 P
PARTLOH, J O	8009290374	70-143	PETERSON, M R	8009160274	XPORTLIC	POOLE, D.	8009030206*	50-302 R
PASSAHANI, B,	8009170181*	MISC	PETERSON, M R	8009250333	XPORTLIC	PORTER, B H	8009300399	50-287 R
PASTERNAK, R J	8009110298*	50-333 G	PETERSON, M R	8009020471	XPORTLIC	PORTER, H L	8009260010	50-369 0
PASTERNAK.R J	8009190936	50-333 Q	PETERSON, H R	8009020478	XPORTLIC	PORTER, W L PORTER, W L PORTER, W L POTAPOVB, U POTAPOVB, U	8007240246	50-369 G
PASTERNAK.R J	8009020115	50-333 Q	PETERSON, H R	8009100198	XPORTLIC		8007240273	50-369 G
PASTERNAK.R J	8009090014	50-333 Q	PETERSON, H R	8009020464	XPORTLIC		8007270028	50-488 G
PASTERNAK.R.J.	8009100117	90-333 Q	PETERSON, H R	8009110591	XPORTLIC		8007150207*	GA999
PASTERNAK.R.J.	8009100268	50-333 R	PETERSON, M R	8009110606	XPORTLIC		8007150227*	GA999
Pasternak, R J Pasternak, R J Pasternak, R J Pasternak, R J Pasternak, R J	8007030405 8007030418 8007020354 8007020374 8007020407	50~333	PETERBON, H R PETERBON, H R PETERBON, M R PETERBON, H R PETERBON, H R	8007110609 8007110755 8007160171 8007180420 8007140233	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8007180300* 8007150200* 8009150227* 8009190027*	0A999 0A999 0A999 0A999 0A999
PASTERNAK, R J	8007070357	50-333 8	PETERBON, J M	8009220342	50-320 P	POTAPOVB. U	8009180104*	04777
PASTERNAK, R J	8007070303	50-333 R	PETERBON, M R	8009290476	XPORTLIC	POTAPOVB. U	8009290320*	04779
PASTERNAK, R J	8007120410	50-333 8	PETERBON, M R	8009300028	XPORTLIC	POTAPOVB. U	8009100223*	04779
PASTERNAK, R J	8007120357	50-333 8	PETRICK, N A	8009170442	50-482 8	POTAPOVB. U	8009110613	04779
PASTERNAK, R J	8007160445	50-333 8	PETRICK, N A	8009150196*	50-482 8	POTAPOVB. U	8009250325*	04779
PASTERNAK,R J	8007160458	50-333 8	PETRICK, N A PETRICK, N A PETRICK, N A PETROEL, C D PETROEKY, J A	8009170416	50-482 G	POTAPOVB, U	8007180562	QA999
PASTERNAK,R. J	8007170487	50-333 8		8009030541	50-482 A	POTAPOVB, U	8007180527	QA999
PASTORE, J G	8007240014*	FOIA		8009190441	50-482 K	POTAPOVB, U	8007080465	QA999
PATE,R J,	8007120477*	50-341 0		8009100861*	50-277 G	POTAPOVB, U	8007120334	QA999
PATOK, H D	8007020429	50-327 0		8009020472*	50-289 H	POTAPOVB, U	8007120654	QA999
PATON, U D	8009250004	50-327 0	PFAFF, 9 J	8009100069	40~6659	POTAPOVB, U	8009150173*	04999
PATON, U D	8009240009	50-387 0	PFAFF, 9 J	8009100212*	40~6659	POTAPOVB, U	8009150017	04999
PATON, U D	8009290039	50-327 0	PFAFF, 8 J	8008080187	40~6659	POTAPOVB, U	8009150171	04999
PATTEN, T U	8009240482*	TOPREP	PFAFF, 8 J.	8009100222*	40~6659	POTAPOVB, U	8009150224*	04999
PATTERSON, E S	8009260394*	50-287 T	PFEFFERKORN, W	8009030696	50~488	POTAPOVB, U	8009190020*	04999
PATTIF.J	8007170684	NUREO	PFEFFERKORN,W	8009250015	50-48B	POTAPOVS, U	8009170155	GA999
PATTONIL W	8007120007*	CONTRACT	PHILLIPS,H B	8009170385*		POTAPOVS, U	8009170156	GA999
PAULIP A.	8007270037*	FOIA	PHILLIPS,H P	8009260665*		POTAPOVS, U	8009180070#	GA999
PAULSONIN A	8007020340	50-155 P	PHILPOYT,F T	8009180409*		POTAPOVS, U	8009150221	GA999
PAULSONIN A	8007050500	50-155 P	PICKLE,J J	8009110322*		POTAPOVS, U	8009250307	GA999
PAULBON, W A PAULBON, W A PAULBON, W, A PAULBON, W A PAULBON, K	8007050504*	50-155 P	PICKLE, J J.	8009110319*	50-320 H	POTAPOVS, U	8009100208	0A999
	8007050507*	50-155 P	PICKLE, J J	8009240485	50-466 U	POTAPOVS, U	8009150195	0A999
	8007150042	50-155 P	PIERCE, R. L	8009100061*	CONTRACT	POTAPOVS, U	8009180092	0A999
	8007150046	50-217 P	PIERSON, G W	8009170234	40-4492	POTAPOVS, U	8009180484	0A999
	8007120188	50-341 H	PIERSON, G W	8009110266	40-4492	POTAPOVS, U	8009180056	0A999
PAMLICKI, 8, 8	8007160572	90-395 E	PIODIT, D R	8009110399*	50-361 0	POTAPOVS, U	8009190014	0A999
PECK, C, C,	8007150165*	40-3392	PIODIT, D R	8009110399*	50-361 0	POTAPOVS, U	8009180169	0A999
PECK, C, C,	8007270074*	70-1308	PIODIT, D, R	8009110399*	50-361 0	POTAPOVS, U	8009290310	0A999
PEDERSEN, K	8007170539*	FOIA	PIODIT, D, R	8009110396	50-361 0	POTTER, M F	8003190525*	PT9
PEST, W, J	8007180064*	GA999	PIODIT, D R	8009190083	50-361 0	POTTER, J P	8009040068*	27-39
PELLID M. PELLID M. PELLID M. PELLID M. PELLID M.	8007120224 8007120232 8007120232 8007120232	50-289 0 50-289 0 50-289 0 50-289 0 50-289 0	PIGOTT.D R PILANT.J M PILANT.J M PILANT.J M PILANT.J M	8009190083 8009100031 8009020102 8009020098 8009020101	50-361 0 50-278 0 50-278 0 50-278 0 50-278 0	POTTER, J.P. PRATT, C. M. PRESTON, C. C. PREVENSLIK, T, V. PRICE, H. L.	8007110208* 8005210647 8009050200 8009020017* 8009240054*	27-39 PR RES 50-537 FOIA
PENCE, W B	8009030522*	50-317 8	PILANT, J, M	8009100844*	50-278 Q	PRICE, H L.	8009190695*	FOIA
PENCE, W B	8009230536*	50-317 8	PILANT, J, M	8009190478	50-278 P	PRICE, H L	8009240041*	FOIA
PENCE, W B	8009230546*	50-317 8	PILANT, J, M	8009030551	50-278 F	PRICE, H L	8009240026*	FOIA
PENCE, W B	8009230592*	50-317 8	PILANT, J, M,	8009260282	50-278 R	PRICE, H L	8009240018*	FOIA
PENCE, W. B	8009300470*	50-317 8	PILANT, J, M	8009170287	50-278 P	PRICE, H L	8009240059*	FOIA
PENDERORAFT, R. PENDERORAFT, R. PENDERORAFT, R. PENDERORAFT, R. PENDERORAFT, R	8007030546* 8007030417* 8009150271* 8009150275* 8009230410*	50-368 8 50-368 8 50-368 8 50-368 8	PISH.M D PLATO.P PLAYTON.S J PLEGSET.M.S PLEGSET.M.S	8009080352* 8009160446 8008080193* 8009190766 8009100628	50-317 F NUREG 40-6659 50-327 O REGGD	PRICE, H L PRICE, A L PRICE, H L PRICE, H L PRICE, J E	8007170657* BC07170647* BC07170642* BC07240108* SC07300561	FOIA FOIA FOIA FOIA 50-201

AUTHOR	ACCESSION NUMBER	EUBJE CATE		AUTHOR	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR	ACCESSION NUMBER	SUBJEC	
A L'ATIBA, D A L'ATIBA, D A L'ATIBA, D A L'ATIBA, D B L'ATIBA, D	8009100045 8009020303 8009020222 8009100902 8009030123	50-404 50-327 50-255 70-145 50-346	7 û 7 û 9	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007270274 8007270277 8007270282 8007270287 8007270273	50-349 50-250 50-321 50-261 50-489	0 0 0 0 0	PACE,P L PACE,P L PACE,P L PACE,P L PACE,P L	8009020372* 8009120315* 8009120316* 8009120385* 8009120318*	50-335 50-251 50-335 50-250 50-335	8
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007030128 8007030128 8007030127 8007030130 8007030137	50-302 50-416 50-395 50-395 50-486	Q Q	O'REILLY, J P G'ROURKE, S A OBERG, C T OBERG, C R OBERG, C R	8009290297 8009050433 8006120884* 8009090648* 8009150348*	50-269 71-7853 PT9 50~482 50-482	a a	PACE, P L PACE, P L PACE, P L PAGAND, F G PAGE, R G	8009150290# 8009300494# 8009300485# 8009100378 8009170079	50-335 50-250 50-335 50-10 70-1151	8 8 F
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007030141 8007030146 8007030154 8007030158 8007030163	50-280 50-259 50-321 50-250 50-261	G G	OBERG.C.R OESTMANN.M J OHLBSON.K OLLER.R E OLSEN.R N	8007150362* 8007260665* 8007170726 8007150173* 8007070614	50-458 50-344 Reogd Gayyy Kportli	0 0	PAGE.R G PAGE.R G PAGE.R G PAGE.R G PAGE.R G	8007240334 80071501B1 8007250472 8007250476* 8007250464	70-33 70-258 70-1257 70-1257 70-1151	,
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007030175 8007030181 8007160036 8007160037 8007160040	50-269 50-437 50-416 50-321 50-324	G.	OLSEN, A F OLSEN, A F OLSEN, F M OLSHAN, L N OLSON, R C	8009110667 8009030443 8009260014 8009230230 8009030014	70-824 50-99 50-409 50-286 NUREO	P O P	PAGLAIRO, J PADLINO.R PAPAY,L T PAPAY,L T PAPERIELLO.C J	8009290031* 8009090250* 8009090470 8009300431 8009290079*	FOIA 50-289 50-361 50-361 FOIA	9 8
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009160045 8009230388 8009230391 8009230396 8009230397	50-259 70-824 70-27 70-109 70-115		OLSON, N J, OLSON, J F, OLSON, J F OPREA, O W OPREA, O W	8009020219 8009030726 8009300039 8009030170* 8009180479	50-445 50-282 50-282 50-498 50-498	A Q Q B	PAPERIELLO,C J PAPERIELLO.C J PAPERIELLO.C J PAPERIELLO.C J PAPPAS,H	8009290037* 8009290059* 8005300695* 8006120884* 8009090117	FOIA FOIA PT9 PT9 ORO	
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009230398 8009230400 8009230404 8009050422 8009120066	70-120 50-332 70-143 50-280 50-518	1 G G G	OPREA. O W OPREA. O W OPREA. O W OPREA. O W OPREA. O W	8009190147 8009180467 8009180461 8009020288 8009020290	50-498 50-498 50-498 50-498 50-498	8 9 6 8	Pappas. H Pappas. H Pappas. H Pappas. H Pappas. H	8009030305 8009160052 8009230423 8009180062 8009120117	ORO ORO ORO ORO 50~10	a
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009120072 8009120077 8009120080 8009120082 8009160108	50-324 50-321 50-416 50-259 50-437	œ , œ ,	CPREA, Q W CPREA, O W OPREA, O W OPREA, O W OPREA, O W	8009300545 8009300555 8009040377 8009050364 8009110384	50-498 50-498 50-498 50-498 50-498	0 0 8 0 8	PAPPAS, H PAPPAS, H PAPPAS, H PAPPAS, H PARIS, D H	8009180123 8009230104 8009240384 8009230537 8009170175	0R0 0R0 0R0 0R0 50-155	٠
O.WEITTA'N b O.WEITTA'N b O.WEITTA'N b O.WEITTA'N b	8009160110 8009160113 8009160115 8009160118 8009160120	50-348 50-302 50-416 50-395 50-395	a a a a	OPREA, O W OPREA, O W OPREA, Q. W OPREA, O W OPREA, O W	8007080201 8007110367 8007300536 8007230603 8007230617	50-498 50-498 50-498 50-498 50-498	A 8 9 8	PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8009240220* 8009100807* 8009160541* 8009240212* 8009110275	50-389 50-289 50-269 50-369 70-2623	0 0 0
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P,	8009160124 8009160133 8009160137 8009160143 8009160147	50-241 50-489 50-249 50-250 50-321	9 9 9 9	OPREA, O. W OPREA, O. W OPREA, O. W OPREA, O. W OPREA, O. W,	8009150559 8009230658 8009240439 8009230402 8009330161	50-478 50-478 50-478 50-478 50-478	K 8 8 8	PARKER, W. D PARKER, W. D PARKER, W. D PARKER, W. D PARKER, W. D	8009240298* 8009240204* 8009040640 8009160540* 8009150369*	50-413 50-359 50-269 50-269 50-370	0 0 0
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J. P O'REILLY, J P.	8009160153 8009160172 8009230249 8009230252 8009230258	50-259 50-260 50-348 50-261 50-269	0 0 F F F	OPREA, O M ORDERS, W ORLOSKY, P M ORHONDE, S ORNICH, J.	8009300453 8009300640* 8009160340* 8009120594 8009300338	50-498 50-269 50-57 FOIA 50-382	8 6 8	PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8009110423 8009030183 8009050545 8009170371 8009240290*	50-413 50-369 50-369 50-413 50-413	90000
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009230258 8009230261 8009230265 8009230267 8009230273	50-302 50-250 50-321 50-289 50-280	+ + + + +	ORTENBERG,L I OSANN,E W OBANN,E W OSANN,E W OBANN,E H	B009080299* B009030703 B009030710 B009030703 B009030710	50-348 50-367 50-367 50-367 50-367	6 6 6	PARKER, W. O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8009240297* 8009140642 8009140633 8009170233 8009240262*	50-413 50-413 50-369 50-269 50-370	9 9 9 9
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009230277 8009230323 8009230325 8009260274 8009260277	70-824 70-27 70-143 70-1349 70-2892		OSANN, E W OBANN, E W OBANN, E W OSANN, E W	8009230382 8009230382 8009230382 8009230393	50-367 50-367 50-367 50-367 50-367	0 0 0	PARKER, W O. PARKER, W O PARKER, W. O. PARKER, W O. PARKER, W O	8007020029 8007020044 8007030507 8007300626* 8007020025	50-369 50-269 50-287 50-269 50-269	F R P O P
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009260314 8007260316 8009260317 8009120248 8009120251	70-2621 70-2520 70-1397 50-437 50-348	Q Q	OBANN, E. W. OBANN, E. W. OBANN, E. W. OSTRANDER, F. U. OTT, L. J	8009230393 8009240011 8009240011 8009300344 8009100944	50-367 50-367 50-367 50-344 NUREQ	0000	PARKER, W O PARKER, W O PARKER, W O PARKER, W O, PARKER, W O	8007020371 8007110658 8007120262 8007250171 8007040383	50-370 50-369	A G G S
O'REILLY, J P O'REILLY, J P O'REILLY, J, P O'REILLY, J, P	8009120258 8009120260 8009120265 8009120286 8009120290	50-302 50-414 50-395 50-395 50-261	G G G G	OTT,R F OTT,W R. OTTINGER,R L. OTTOBON,H L. OTTOBON,# L.	8009300595* 8009300303 8009110491* 8009090811 8009170207	CONTRACT NUREO 50-320 50-206 50-208	U G G	PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8007080312 8007120587 8007120578 8007030445 8007030468	50-413 50-369 50-269	6 9 8 8
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8009120300 8009120308 8009120311 8009120314 8009120340	50-498 50-250 50-321 50-280 50-259	0 0 0	OTTOSON, H L OTTOSON, H L OTTOSON, H L OTTOSON, H L OTTOSON, H L	8009150011 8009160630 8009160521 8009020078 8009030533	50-204 50-204 50-204 50-206 50-206	0 0 0 5 R	PARKER, U O PARKER, U O PARKER, U O PARKER, U O PARKER, U O	8009090577 8009100489 8009120418 8009160261 8009120414	50-269 50-270 50-369	R P S A
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007120343 8007230521 8007230525 8007230526 8007240375	50-249 50-259 50-321 50-324 50-259	G G G G	OUZTS, J E OVERBERGER, C G.\ OVERLID, T W OVERLID, T W OVERLID, T W	8007150375* 8007150225 8007030401* 8007230641* 8007230630*	50-324 RE09D 90-263 50-263 50-263	0 8 8 8	PARKER, W. O PARKER, W. O PARKER, W. O PARKER, W. O PARKER, W. O	8009110345 8009150383 8009150439 8009150548 8009250339	50-369 50-369	A A Q
O'REILLY, J. P O'REILLY, J. P O'REILLY, J. P O'REILLY, J. P O'REILLY, J. P	8009260397 8009260517 8009290269 8009290271 8009290274	50-395 50-280 50-437 50-416 50-302	G G G G	OWEN, J B OWBLEY, O F. OWBLEY, O F OWZARBKI. P C OZKER, D	8007220139 8007040490 8007260477 8007110419 8007220242*	TOPREP REB	P A	PARKER, W O PARKER, W O PARKER, W O PARKER, W D PARKER, W D	8009180395	50-287	5 0 5 A

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR	
FARKER, W O. FARKER, W O FARKER, W O FARKER, W O PARKER, W O	8009190462 8009180322 8009190399 8009190506 8009230724	50-267 R 50-369 A 50-369 A 50-369 A 50-369 P	PENDERGRAFT, R PEOPLES, D L PEOPLES, D L PEOPLES, D L PEOPLES, D L	8009230748* 8009180261 8009110217 8009020294 8009170230	50-368 8 70-2609 70-2609 NUREQ 50-237 G	PLESSET, M S PLESSET, M S PLESSET, M S POCHAL, W F POCHAL, W F	8009150238 8009150245 8009150249 8009100493 8009160287	50-327 ACRS ACRS XPORTLIC XPORTLIC	Đ
Parker, w o Parker, w o Parker, w o Papker, w o Papker, w o	8009240409 8009230496 8009230509 8009240448 8009240489	50-369 A 50-270 S 50-270 S 50-369 V 50-369 A	PERANICH.M W PERDIKARIB.P C PERKINB.T J PERKINB.T J PERKINB.M A	8009150055+ 8009020355 8009120413* 8009120417* 8009050243	50-445 G NUREG 50-220 V 50-220 V 50-320 S	POCHAL,W F POGALIES,J X POGALIES,J K POGGIO,A POIRIER,L J	8007230783 8007100406 8007100406 8007160478 8007080352*	XPORTLIC 50-361 50-361 RES 50-317	0 0 F
PARKER, H O PARKER, H O PARKER, H O PARKER, H, O PARKER, H O	8009290371 8009260450 8009290303 8009300428 8009300434	50-369 A 50-287 8 50-369 A 50-269 J 50-369 A	Perkins, J Perlman, J Perlman, J Perlman, J Perlman, J	B009300010 B009120514* B009120037* B009120115* B009150414*	50-289 0 50-206 P CONTRACT CONTRACT	POIRIER, M R POIRIER, M R POIRIER, M R POIRIER, M R POIRIER, M R	8007070453 8007150417 8007150417 8007140275 8007140275	50~445 50~445	M M M M
PAPKER, U O PARKTISSON, T F PARSONS, E M PARTLOW, J. O PARTLOW, J. O	8009300486 8009300459 8009110411 8009230169 8009030046	50-269 P 50-124 P 50-266 H 70-1143 70-1120	PERLMAN, J PERLMAN, J PERLMAN, J PERNY, C D PERRIGO, L D	8009180424* 8009240057* 8009300276* 8009230439* 8009110483	50-206 P 50-206 P CONTRACT 70-143 RES	POIRIER, M R POIRIER, M R POIRIER, M R POIRIER, M R POLANSKI, X	8009160182 8009160182 8009260318 8009260318 8009160426*	50-449 50-445	M M H S
O LINGLITAN O LINGLITAN O LINGLITAN O LINGLITAN O LINGLITAN	8009080489 8009130360 8009170242 8009160235 8009150389	70-687 70-1143 70-1113 70-754 70-1257	PERROTTI, D J PERRY, J C PERRY, J C PETERSON, K PETERSON, R M	9009220184* 8009100467* 8009260510* 8009160583 8009220116	50-335 Q 50-344 6 50-344 S 50-227 P WABTE MOT	POLK,P J POLLACK,S POLLARD,R D POLLARD,R D POLLARD,R D	8009190770 8009120435 8009230011 8009300420* 8009300422*	50-361 50-289 50-289	P H T O
ARTLOW, J 0 ARTLOW, J 0 ARTLOW, J 0 ASSAMANI, B ASTERNAK, R J	8009150395 8009290266 8009290374 8009170181* 8009110278*	70-143 70-1201 70-143 MIBC 50-333 Q	PETERBON, M R. PETERBON, M R PETERBON, M R PETERBON, M R PETERBON, M R	8009020120 8009020129 8009160274 8009250333 8009020471	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	POLLEIT, R POND, O D POOLE, D PORTER, S W PORTER, W L	8009120442 8009260478 8009030206* 8009300399 8009260010	50-213 50-302 50-289	H P R R
ASTERNAK, R. J. ASTERNAK, R. J. ASTERNAK, R. J. ASTERNAK, R. J. ASTERNAK, R. J.	8009190936 8009020115 8009090014 8009100117 8009100268	50-333 G 50-333 G 50-333 G 50-333 G 50-333 R	PETERSON, M R	8009020478 8009100198 8009020464 8009110591 8009110606	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PORTER, W L. PORTER, W L. PORTER, W L. POTAPOVS, U POTAPOVS, U	8009240246 8009240273 8009270028 8009150207# 8009150229#	50~349	9
ASTERNAK, R. J. ASTERNAK, R. J. ASTERNAK, R. J. ASTERNAK, R. J. ASTERNAK, R. J.	8009030405 8009030418 8009020354 8009020394 8009020409	50-333 8 50-333 8 50-333 8 50-333 8 50-333 8	PETERSON, M R	8009110609 8009110755 8009160191 8009180420 8009160233	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8009180500* 8009150200* 8009150227* 8009190031* 8009190027*	QA999 QA999 QA999 QA999 QA999	
ASTERMAK, R J ASTERMAK, R J ASTERMAK, R J ASTERMAK, R J ASTERMAK, R J	8009090359 8009090303 8009120410 8009120359 8009160445	50-333 8 50-333 R 50-333 8 50-333 8 50-333 8	PETERSON, J M PETERSON, M R PETERSON, M R PETRICK, N A PETRICK, N A	8009220342 8009270476 8009300028 8009170442 8009150194*	50-320 P XPORTLIC XPORTLIC 50~482 8 50-482 8	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8009180104* 8009290320* 8009100223* 8009110613 8009250325=	QA999 QA999 QA999 QA999 QA999	
MSTERNAK, R. J MSTERNAK, R. J MSTORE, J. O MTE, R. J MTON, H. D	8009160458 8009190489 8009240014* 8009120479* 8009020429	50-333 8 50-333 6 FOIA 50-361 0 50-327 0	PETRICK,N A PETRICK,N A PETRICK,N A PETRONE,C D PETROSKY,J A	8009170416 8009030541 8009190441 8009100861* 8009020472*	50-482 Q 50-482 A 50-482 K 50-277 Q 50-289 H	POTAPOVS. U POTAPOVS. U POTAPOVS. U POTAPOVS. U POTAPOVS. U	8007180562 8007180527 8007080465 8007120334 8007120654	GA999 GA999 GA999 GA999 GA999	
ITON: W D ITON: W D ITON: M D ITTEN: T W ITTERSON: E, 8	8009250004 8009260009 8009290039 8009260482* 8009260394*	50-329 0 50-389 0 50-329 0 TOPREP 50-289 T	PFAFF,8 PFAFF,8 J. PFAFF,8 J PFAFF,8 J PFEFFERKORN,U	8009100059 8009100212* 8008080187 8009100222* 8009030696	40-6659 40-6659 40-6659 40-6659 50-488 0	POTAPOVS. U POTAPOVS. U POTAPOVS. U POTAPOVS. U POTAPOVS. U	8009150173# 8009150017 8009150171 8009150224# 8009190020#	QA797 QA797 QA797 QA797 QA797	
TTL.F J TTON,L W UL.P.A. ULSON,H A ULSON,H A	8007170684 8007120007# 8007270037# 8007020340 8007050500	NUREG CONTRACT FOIA 50-155 P 50-155 P	PFEFFERKORN, W PHILLIPB.H B PHILLIPB.M P PHILPOTT, F T PICKLE, J J	8009250015 8009170385* 8009260665* 8009180409* 8009110322*	50-488 Q 50-498 Q 50-346 Q 50-287 8 50-320 H	POTAPOVS. U POTAPOVS. U POTAPOVS. U POTAPOVS. U POTAPOVS. U	8009170155 8009170156 8009180070* 8009150221 8009250307	GA999 GA999 GA999 GA999 GA999	
(LEON, WA (LEON, WA (LEON, WA (LEON, W.A (LEON, K	8007050504* 8007050507* 8007150042 8007150046 8007120188	50-195 P 50-195 P 50-195 P 50-219 P 50-361 H	PICKLE, J J. PICKLE, J J PIERCE, R L PIERBON, 0 W PIERBON, 0 W	8009110319* 8009240485 8009100061* 8009170234 8009110266	50-320 H 50-465 U CONTRACT 40-4492 40-4492	POTAPOVB. U POTAPOVB. U POTAPOVB. U POTAPOVB. U POTAPOVB. U	8009100208 8009150195 8009180092 8009180484 8009180056	98999 98999 98999 98999	
MLICKI.B.S CK.C.C. CK.C.C. CERSEN.K ET.H J.	8909160592 8009150165# 8009290094# 8009190539# 8009180064#	50-395 E 40-3392 70-1308 FOIA GA999	PIGOTT, D R	8009110399* 8009110399* 8009110399* 8009110396 8009190083	50-361 Q 50-361 Q 50-361 Q 50-361 Q 50-361 Q	POTAPOVB, U POTAPOVB, U POTAPOVB, U POTTER, M F POTTER, J P	8009190014 8009180169 8009290310 8003190325* 8009040048*	0A999 0A999 0A999 PT9 27-39	
LC, D. H. LC, D. H. LC, D. H LL, D. H LL, D. H.	8009120226 8009120232 8009120226 8009120232 8009230639	50-287 0 50-287 0 50-287 0 50-289 0 50-289 0	PIGOTT, D R. PILANT, J M PILANT, J M. PILANT, J. M PILANT, J M	8009190083 8009100031 8009020102 8009020098 8009020101	50-361 0 50-298 G 50-298 G 50-298 G 50-298 G	POTTER, J P PRATT, C H PRESTON, C C PREVENSLIK, T V PRICE, H L	8009110208# 8005210647 8009050200 8009020017# 8009240054#	27-39 PR RES 50-537 FOIA	٨
KE, W B KE, W B KE, W B. KE, W. B KE, W B	8009030522* 8009230536* 8009230546* 8009230592* 8009300470*	50-317 8 50-317 8 50-317 8 50-317 8 50-317 8	PILANT, J.M PILANT, J.M PILANT, J.M PILANT, J.M PILANT, J.M	8007100844* 8009190478 8009030551 8009260282 8009170287	50-298 Q 50-298 P 50-298 F 50-298 R 50-298 P	PRICE: H L PRICE: H L PRICE: H L PRICE: H L PRICE: R L	8009190695* 8009240041* 8009240026* 8009240018* 8009240059*	FOIA FOIA FOIA FOIA	
DERORAFT, R DERORAFT, R DERORAFT, R DERORAFT, R DERORAFT, R.	8007030546* 8007030417* 8007150271* 8007150275* 8007230410*	50-348 8 50-349 8 50-348 8 50-348 8 50-348 R	PISH.M.D PLATO.P PLAYTON.S J PLESSET.M.S PLESSET.M B	8007080352* 8007160446 8008080173* 8007170766 8007100628	50-317 F HUREQ 40-6659 50-327 Q REGOD	PRICE, H L PRICE, A L PRICE, H L PRICE, H L PRICE, J E	8009190659* 8009190647* 8009190642* 8009240108* 8009300561	FOIA FOIA FOIA FOIA 50-201	o

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
PRIME,W J	8009100077*	CDNTRACT	REID, R W	8009230763	50-321 P	REYNOLDB, N S	8009110048	50-445
PRIME,W J	8009120019*	CDNTRACT	REID, R W	8009150033	50-277 P		8009110781	50-445
PRIMIZ,T A	8009230704*	50-304 8	REID, R W	8009050275	50-289 P		8009110781	50-445
PRITCHARD,W C	8009120626	50-247 P	REID, R W	8009050236	50-312 F		8009170141	50-445
PUCKETT,J M	8009240195*	50-302 G	REID, R W	8009300046	50-346 P		8009170141	50-445
PULIDO,M	8007110430	50-206 H	REID,R.W	8007300052*	50-346 P	REYNOLDB, N S	8007230005	50-445
PULLINS,C	8007030553*	50-528 S	REID,R W	8007300057*	50-346 P	REYNOLDB, N S	8007230005	50-445
PUNT,N A	8007070380	50-320 H	REID,R W	8007170304	50-313 Q	RHOADB, O O	8007170241*	50-387
PURCELL,J	8007030434	50-367 R	REID,R W	8007170316	50-312 Q	RHODE, O K	8007070848*	50-410
PUSCHEL,M A	8007170065	FOIA	REID,R W	8007170362	50-277 Q	RHODE, O K	8007230078	50-410
GOTOK'D GOTOFEA'1 M GOTOFEA'1 M GOTOK'D K	8009150115* 8009300063* 8009090198 8009150158 8009300569*	50-302 0 50-241 9 40-8743 40-8743 50-219 8	REID.R W REID.R W REID.R W REID.R W	8009190375 8009190572 8009240597 8009260592 8009260664	50-302 Q 50-344 Q 50-321 Q 50-289 Q 50-269 Q	RHODE, O K RHODE, O K RIBICOFF, A RICCITELLI, J RICE, T	8009020248 8009150551 8009100093* 8009240121* 8008130378*	50-410 A 50-410 A COMMISSION 50-320 H 40-299
RABUCK, B	8009150336*	50-289 H	REID.R W	8009120645	50-289 P	RICHARDSON, T F	8009160420	50-201 Q
RADER, R M	8009230027	50-395 Q	REID.R W	8009120648*	50-289 P	RICHARDSON, T F	8009240038*	CONTRACT
RAFFELSON, C N	8009020552	40-8745	REID.R W	8009120653*	50-289 P	RICKARD, C L	8009120697	50-275 E
RAGER, M	8009030471*	50-331 S	REID.R W	8009190582	50-302 P	RIDGWAY, K R	8009260420*	50-407 Q
RAGER, M	8009170320*	50-331 S	REID.R W	8009180176	50-312 P	RIDGWAY, D A	8009030118	50-320 Q
RAGER, M RAGER, M RAGER, M RAGER, M S RAGER, M S	8009170328* 8009170352* 8009170360* 8009170367* 8009300501*	50-331 S 50-331 S 50-331 S 50-331 S 50-331 S	REID,R W REID,R W REID,R W REID,R W	8009190143 8009290242 8009260346 8009260353* 8009260364*	50~346 P 50~287 P 50~346 P 50~346 P 50~346 P	RIDOWAY, D. A RIETHLE, W E RIETHLE, W E RIGOS, M W RIGOS, M W	8007030118 8007240541 8007300550 8007110277 8007110277*	50~320 Q 50~320 P 50~287 R 50~293 Q 50~293 Q
RAMEY, J T	8009190688*	FOIA	REID, R W	8009190154	50-249 P	RIGGS,M W	8007110304*	50-293 Q
RAMSTHALER, J A	8009190748	RES	REID, R W	8009250421	50-321 P	RIGGS,R	8007240145*	50-313 B
RANDOLPH, M L	8009110634	RES	REID, R. W	8009250425	50-313 P	RITTER,D	8007110418*	COMMISSION
RANDOLPH, M C	8009110498	RES	REID, R W	8009250427	50-302 P	RIZZO,P G	8007030547*	50-318 B
RANDOLPH, J K	8009230694*	50-311 S	REID, R W	8009250430	50-277 P	RIZZO,P G	8007120378*	50-317 B
RASKIN.D.B.	8009040271	50-466 0	REID.R W	8009250434	50-269 P	RIZZO,P O	8009120455*	50-317 B
RASKIN.D.B	8009040271	50-466 0	REID.R W	8009250491	50-344 P	RIZZO,P Q	8009230695*	50-317 B
RASKIN.D.B	8009260207	50-466 0	REID.R W	8009260200	50-209 H	ROBERTS,K	8009100036*	50-273 Q
RASKIN.D.B	8009260210*	50-466 0	REID.R W	8009260538	50-312 P	ROBERTS,K P	8009100877*	50-273 Q
RASKIN.D.B	8009260210*	50-466 0	REID.R W	8009260559	50-289 P	ROBERDS,H H	8009170158*	QA777
RATHKOPF.C L	8009100074*	50-289 H	REID.R W	8009290077	50-289 F	ROBERTS, H R ROBERTSON, J D ROBERTS, D ROBERTS, D ROBINSON, C R	8009170127	40-8481
RATHKOPF.C L	8009150241*	50-320 H	REID.R W	8009300230	50-277 F		8009030085*	CONTRACT
RATHKOPF.C L	8009300306≈	50-275 H	REID.R W	8009290155	50-289 P		8009300237	40-8481
RAUSCH.W P	8009030359	TOPREP	REID.R W	8009300145	50-313 P		8009100666	40-8481
RAUSCH.W J	8009180466	50-10 Q	REID.R W	8009300146*	50-313 P		8009230147*	70-1417
RAUSCH, T J	8009190007	50-373 Q	REID,R W	8009300155*	50-313 P	ROCKHOLD, H C	8009180309	50-336 P
RAUSCH, T J	8009250468	50-373 Q	REIDHAAR,D L	8009230014	50-142 0	RODI, J P	8009100048	XPORTLIC
RAUSCH, T J	8009260109	50-10 Q	REINHART.M	8009170269*	50-320 H	RODI, J P,	8009110264	XPORTLIC
RAUSCH, T J	8009300200	50-10 Q	REIS.H F	8009020073	50-250 ¢	RODRIGUEZ, R J	8009160295	50-312 R
RAYMOND, W	8009100877#	50-293 Q	REIS.E J	8009020420	40-1162	ROEDER, J R	8009050209*	71-7508
RAYMOND, W J REAVES, T. E REBELOWSKI, T. REBELOWSKI, T	8009190575 8009030504 8009190473* 8009120210* 8009100853*	50-271 8 50-416 H 50-269 R 50-247 Q 50-247 Q	REIS.E J REITLER, E K REIZEN. M 8 REKITO, W A REKITO, W A	8009270498 8009170108 8009110350* 8009190081* 8009150184*	MISC 70-1151 CONTRACT 50-293 G 50-277 G	ROEGIERS, J C ROGERS, L ROGERS, R F ROGERS, A E ROGERS, W H	8009190248 8009020304* 8009220341* 8009230475* 8009090460*	50-440 K 50-287 H 50-381 G TOPREP 50-321 B
RECORD, D	8009080391*	50-327 8	REKITO,W A	8009110518*	50-217 Q	ROISMAN, A Z	8007070363*	50-247 0
REDER, M	8009050333	50-358 F	REMICK,F J	8009110813	50-237 Q	ROISMAN, A Z	8007070342*	50-247 0
REED, C	8009260658*	50-275 0	REMLEY,M E	8009120620	70-25	ROISMAN, A Z.	8007070363*	50-247 0
REED, J O	8009120268	50-483 H	REMLEY,M E	8009150396	71-5088	ROMAND, A J	8007110321	NUREO
REEVES, M	8009020349	NUREO	RENBERGER,D L	8009030342*	50-508 B	ROMAN, T W	8007120413*	50-220 V
REEVES, E	8009100007	50-295 P	RENBERGER, D L	8009100179	50-508 G	ROMAN, T W	8007120417*	50-220 V
REGAN, H	8009090155	50-320 P	RENBERGER, D L	8009190677	NUREG	ROMANO, F R	8007020171*	50-320 M
REHM, T A	8009190397*	FOIA	RENBERGER, D L	8009110422*	50-460 G	ROMAN, T W	8007160213	50-220 R
REHM, T A	800909083	COMMISSION	RENBERGER, D L	8009020043	50-397 K	ROMAN, T W	8007150297*	50-220 R
REHM, T, A	8009090632	COMMISSION	RENBERGER, D L	8009160622	50-460 G	ROMINE, D	8007080380*	50-327 B
REHM.T A	8009110753	COMMISSION	RENBERGER, D. L.	8009170393	50-460 G	ROMINE	8007070588*	50-327 8
REHM.T A	8009150521	COMMISSION	RENBERGER, D. L.	8009030521	50-397 A	ROMINE, D	8007160380*	50-327 8
REHM.T A	8009300158	COMMISSION	RENBERGER, D. L.	8009090023	50-397 G	ROMOSTAD, F	8007180569*	50-320 H
REIGHHOLD.W P	8009160023	70-2599	RENBERGER, D. L.	8009090680	50-397 K	ROOD, H	8007100021	50-361 T
REIGH.M	8009240686	NUREO	RENBERGER, D. L.	8009170388	50-397 G	ROOD, H	8007100417	50-206 P
REID, R W. REID, R W. REID, R. W REID, R. W	8009240617* 8009110642 8009220205 8009090212 8009110637	50-302 P 50-289 H 50-289 H 50-289 H 50-289 H	RENBERGER, D. L RENBERGER, D. L RENBERGER, D. L RENBERGER, D. L RENBERGER, D. L	8009120368 8009080321 8009090494 8009120360 8009120312	50-397 Q 50-397 A 50-397 A TOPREP 50-397 %	ROOD, H ROOD, H ROOD, H ROOD, H ROOD, H	8009140227 8009140252 8009240622 8009110347 8009120273	50-361 A 50-361 A 50-361 A 50-361 A 50-361 A
	8004350505 8004350505 8004350501 8004350168	50-289 H 50-289 H 50-289 H 50-289 H 50-289 H	RENBERGER, D L	8009230352 8009240465 8009230696 8009240464 8009300352	50~397 A 50~397 8 50~397 A 50~397 A 50~397 S	ROOD, H ROONEY, M A ROONEY, M A ROONEY, M A ROONEY, M A	8009190913 8009100325 8009070461 8009160394 8009300580	50-361 A 70-1308 70-1308 70-1308 70-1308
		50-289 8 50-277 P 50-277 F 50-278 P 50-278 P	RENBERGER, D.L. RENBERGER, D.L. RENBERGER, D.L. RENNELS, A.E. RENNELS, A.E.	8009300415 8009300346 8009300379 8009050358 8009260021	50-397 8 50-460 0 50-397 8 40-2061 40-2061	ROOT, L D ROOT, L D ROOT, L D ROOT, L D ROOT, L, D	8009020170 8009170061 8009090026 8009020289 8009040424	50-331 0 50-331 0 50-331 0 50-331 P 50-331 0
		50-278 P 30-249 P 10-249 P 10-249 P 0-277 P	REVELEY, W T REVESTL A REYNOLDBIL E REYNOLDBIN S	8009170194 8009170194 8009300243* 8009260059 8009110048	50-516	ROOT, L D ROOT, L D ROOT, L D ROOT, L D ROOT, L D	8009170427 8009170333	50-331 0 50-331 0 50-331 0 50-331 P 50-331 P

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ROOT, L D ROOT, L D ROSE, D O. ROSENBERG, A B ROSENBAUM, B	8009230286 8009180389 8009220220 8009150083* 8009160436*	50-331 P 50-331 F 50-275 F 50-445 G TOPREP	SARSTEN, O E SATTERFIELD, D SAUER, R. C SAUNDERS, O A SAUNDERS, B L	8009160645 8009120494* 8009240694* 8009030455 8009290180	50-443 S COMMISSION 50-281 Q 40-8693 50-250 G	SCHHENCER, A SCHHENCER, A SCHWENCER, A SCHWENDIHAN, L SCHWENCER, A	8009110707 8009150527 8009090612 8009150597 8009220042	50-275 A 50-327 P 50-275 F NUREO 50-275 H
ROSENBERG: R ROSENBAUM: D. M ROSENTHAL: A B ROSENTHAL: W P ROSS: D A	8009220321* 8009190775* 8009300407 8009190376* 8009090235	50-267 Q 10CFR 50-348 Q 50-206 P 50-219 Q	EAXION, H SCALETTI, D C SCARANO, R A SCARANO, R A SCARANO, R A	8009170157* 8009250451 8009180494 8009180034 8009170099	50-466 Q 50-361 A WASTE MOT 40-8681 40-2259	BCHWENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A	8007080417 8007180248 8007270383 8007250150 8007250466	50-327 E 50-275 H 50-461 H 50-361 A 50-528 H
ROSS, D. H ROSS, D. A. ROSS, D. A ROSS, D. A ROSS, D. A	8009050205 8009090354 8009090351 8009090365* 8009090381*	71-950B 50-219 8 50-219 8 50-219 8 50-219 8	SCARANO, R A SCARANO, R A SCARANO, R A SCARANO, R A SCARANO, R A	8009160651 8009170250 8009020498 8009180336 8009100478	40-8692 Waste Hot 40-299 40-8452 Waste Hot	SCHWENCER, A SCHWENCER, A SCHWOERER, F SCINTO, J F SCOTT, D J	8009260254 8009300329 8009300397 8009190630* 8009030509	50-327 E 50-327 D 50-482 A 50-219 0 50-237 S
ROSS, D. A ROSS, D. A ROSS, D. A. ROSS, D. ROSS, D. F.	8007070353 8007070368 8007070373* 8007250068 8007120664	50-219 8 50-219 R 50-219 B DIBCLOBURE TOPREP	SCARANO, R A SCARANO, R A SCARANO, R A SCARANO, R A SCARANO, R A	8009100491 8009100936 8009170373 8009090768 8009150117	HASTE MOT 40-8084 40-299 Waste Mot 40-8743	SCOTT, D J SCOTT, D J SCOTT, J H SCOTT, J J	80070203B1 8007030454 8007240027 8007150576 8007180460*	50-237 S 50-10 R 40-8698 NUREG 50-369 H
R099: D A. 8088: D, A 8088: D A R088: D A R088: M J	8007160471 8007160474* 8007230488* 8007230481 8007260388*	50-217 8 50-217 8 50-217 8 50-217 8 50-287 T	SCARAND, R A SCARAND, R A SCHAEFFER, M R SCHAEFFER, M °R SCHAEFFER, M R	8009150123* 8009150530 8009110492 8009110587* 8009110214*	40-8743 40-8502 XPGRTLIC XPORTLIC XPORTLIC	SCOTT.D J SCOTT.D J SCOTT.D J SCOTT.D J	8009170223 8009230713 8009230676 80092306468 8009300472	50-466 0 50-10 R 50-237 5 50-237 8 50-237 8
ROSS.M.J ROSS.D.A ROSS.D.A ROSSI.C.E ROSZICZY.Z.P	8009260394* 8009230361 8009260447* 8009080299* 8009100407	50-289 T 50-219 R 50-219 S 50-348 P NUREO	SCHAFFETALL.R SCHAPKER.J F, SCHAPKER.J SCHAPKER.J F SCHAUDEL.S L	8009020257 8009110324* 8009170221* 8009270114* 8009180359	TOPREP 50-454 G 50-456 G 50-546 G 50-320 P	BEABORO, O T SEABORO, O T SEAL, H M SEELEY, G T BEGEV, A	90092400B2* 8009240016* 800915031B* 800930039B 8009300164	FOIA FOIA 50-352 H NUREG NUREG
ROTH A J. ROTH A J ROTHFLEISCH J ROTHFLEISCH J E ROTHFLEISCH J	8009220222# 8009300013 8009020190 8009020518 8009190781	50~389 M 50~445 M 40~8745 40~8745 40~8692	SCHEER, J L SCHEER, J L SCHERER, A E SCHERER, A E SCHERER, A E	8007050264* 8007050255* 8007240520 8007110325 8007240360	50-278	SEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W C	8009150122* 8009150125* 8009150129* 8009150133* 8009150136*	50-445 G 50-445 G 50-445 G 50-445 G 50-445 G
ROTHFLEISCH, J ROTHBCHILD, M V. ROTHBCHILD, M V ROTHBCHILD, M V ROTHBCHILD, M. V.	8009150209 8009020432 8009080033 8009080039 8009110794	40-8745 50-445 0 70-1308 50-445 0 50-445 0	SCHMIDT, Q R SCHMIDT, A D. SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D	8009030863* 9609020365 8009120312 8009120313 8009120350	50-528	SEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W C	8009100047 8009180095 8009050525 8009170380 8009170384	50-482 Q 50-445 Q 50-498 Q 50-498 Q 50-482 Q
ROTHBCHILD, M V ROUSE, L C ROUSE, L C ROUSE, L C ROUSE, L C	8009230044 8009180447# 8009100235# 8009100741 8009170078	70-1308 40-2061 70-1257 70-784 70-1308	BCHMIDT, A.D. BCHMIDT, A.D. BCHMIDT, A.D. BCHMIDT, A.D. BCHMIDT, A.D.	8009120307 8009150288 8009170279 8009300490 8009300482	50-335 8 50-335 8 50-250 R 50-250 8 50-335 8	SEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W C	8009090544 8009150337 8009150340 8009150342 8009100269	50-482 0 50-445 0 50-458 0 50-482 0 50-445 0
ROUBE, L. C ROUBE, L. C ROWE, C. A ROWNEY, E. M AUBIN, M. P.	8009170083 8009170084 8009100647* 8009190405 8009140322*	70-1308 70-1308 70-312 NUREO 50-142 P	SCHNEIDER, F, W BCHNEIDER, F W BCHNEIDER, F W BCHNELL, D F SCHRAEDER, A L	8009080530 8009090230 8009020237 8009020093 8009080352*	50-272	SEIDLE.W C BEIDLE.W C BEIDLE.W C SEIDLE.W C	8007270227 8007250402 8007250370 8007170333 8007030157	50-445 Q 50-478 Q 50-458 Q 50-382 Q 50-498 Q
RUHLMAN, W. A RUITER, O H RULEY, E RUSSELL, L. B RUSSELL, L. B.	8009050441* 8009090277* 8009150416* 8009190665 8009030520	50-280 0 50-305 R 50-320 H 50-317 S 50-317 B	SCHROEDER, F SCHROEDER, F SCHROEDER, F SCHVESSLER, W SCHULTZ, W H	8009050402* 8009190197 8009180353 8009160527 8009290031*	M180 ORO 50-466 0	SEIDLE. H C SEIDLE. W C SEIDLE. W C SEIDLE. W C	8009300089 8009050517 8009300098 8009150338 8009150334	50-382 Q 50-458 Q 50-478 Q 50-458 Q 50-462 Q
AUSSELL, L B AUSSELL, L B RUSSELL, L B RUSSELL, L B RUSSELL, L B	8007030543 8009120354 8009120447 8009120344 8009160315	50-310 5 50-317 8 50-317 8 50-317 8 50-317 8	SCHULTZ, W B SCHULZE, R T SCHULTZ, W B. SCHULZ, R D SCHULTZ, D F	8007070635* 8007020156* 8007070633* 8007100140* 8007150373*	50-320 H 50-367 G 50-255 G	SEIDLE. H C SEIDLE. H C SEKULER. S N SEKULER. S N	8007270325 8007300408 8007020048 8007020084 8007040200	50-482 Q 50-367 Q 50-367 Q 50-237 Q
RUSSELL.L.B RUSSELL.L.B RUSSELL.L.B RUSSELL.L.B RUSSELL.L.B.	8009250311 8009230531 8009230542 8009230583 8009230520	50-317 8 50-317 8 50-317 9 50-317 8 50-318 8	SCHULZ, R D. BCHULTZ, O BCHULTZ, W B SCHULTZ, W B. BCHULTZ, W. B	8007270436 8007030552 8007030147 8007030152 8007030147	50-367 0 50-367 0	SEKULER, S N SEKULER, S N SEKULER, S N SEKULER, S N	8007040208* 8007040218* 8007110783 8007150400 8007160403	50-237 0 50-367 0 50-367 0 70-1308
RUSSELL.L.B RUSSELL.L.B RUSSELL.L.B RUSSELL.L.B. RUTHERFORD.J F	8009230688 8009300441 8009300454 8009300464 8009110291	50-317 8 50-317 B 50-318 B 50-317 B FOIA	SCHULTZIN B BCHUMACHERIJ SCHUYLERIJ O SCHWARTZIF N BCHWARTZIF N	8009030152 8009050342 80090520 800912033& 8009150585	50-275 H * 50-275 K NUREO	SEKULER.S N BELLS,D E SENECHSHYN,J S BENECHAL.M E SERABIN.J A	8009220177 8009150069* 8009090116 8009030726 8009240205*	COMMISSION 50-334 Q 50-282 ( 50-244 ( 40-8463
RYAN, M T BABOL, A. R BABOL, A. R BADAUSKAB, G. J SADDOCK, H G	8007110478 8007170230* 8007170271* 8007240411* 8007220326	RE8 50-387 G 50-387 G 50-289 T 50-244 Q	BCHWEIKER, R. 9 9CHWEIKER, R. 9 8CHWEIBINZ, E. R 9CHWEIBINZ, E. 9CHWENGER, A.	8009020168 8009120317 8009180221 8009150602 8009090195	# 50-327 H # 50-546 G # 50-546 G	SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8007260363 8007260387 8007260370 8007260392 8007300180	70-1167 40-8180 70-2560 40-8092
BALTIMAN, J BALTIMAN, J BAHANTA, P BAMPLEB, M. D SAMPLEB, M. D	8007020131 8007170415 8007170357 8007170357 8007170357	50-387 M 50-322 M TOPREP 50-445 M 50-445 M	SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A.	8009150494 8009120690 8009180168 8009110255 8009150114	50-341 A 50-354 A 50-358 A	SEYFRIT.K V BEYFRIT.K V BEYFRIT.K V BEYFRIT.K V	8009040511 8009090039 8009090046 8009100677* 8009100674	50-458 G 50-298 G 40-6659
SANDERS, F D SANE, A D. SANTINI, J SARPKAYA, T. BARBOUR, B	8009170424 8009020017* 8009020217* 8009020519 8009150277*	50-269 J 50-537 A COMMISSION NUREO 50-346 R	Schwencer, A Schwencer, A Schwencer, A Schwencer, A Schwencer, A	8009170200 8009100497 8009170174 8009260056 8009260065	7 50-275 H 4 50-344 A 3 50-341 M	SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8007180115 8007180115 800702034 8007180117 8007180145	50-278 G 50-458 G 50-278 G 50-213 G

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V	8009180147 8009020538 8009020539 8009180105 8009180108	50-285	SHEA, JR SHEA, JR SHEA, JR SHEA, KH SHEA, KH	8009110586 8009240569 8009150029 8009040281 8009040281	XPORTLIC SECY XPORTLIC 50-347 0 50-347 0	GHULL.C D GHUM.E Y GHUMWAY.N D GIEDER.J D GIEDER.J D	8009170139 8009240525 8009110520* 8009090412* 8009230401	40-8681 70-1113 50-275 U 50-334 P 50-334 P
SEYFRIT. K V SEYFRIT. K V SEYFRIT. K V SEYFRIT. K V	8009180138 8009180140 8009180152 8009180154 8009180157	50-313	SHEA, J J SHEA, K H SHEA, K H SHEA, K H SHEA, K H	8009030096 8009080509 8009080511 8009080509 8009080511	50-409	SIEBER, J D SIEBER, J D SIEBER, J D SIEGEL, S GIEGEL, S	8009230711 8009230454 8009230593 8009240219 8009240690	90-334 P 30-334 P 50-334 P ACRB ACRB
SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V	8007180160 8007260283 8007260286 8007260271 8007260274	50-313 Q 50-285 Q 50-267 Q 50-278 Q 50-313 Q	SHEA.JR SHEA.KH SHEA.KH SHEA.KH SHEA.KH	8009270405 8009070791 8009110808 8009110808 8009150463	SECY 50-347 Q 50-367 Q 50-367 Q 50-367 Q	SILDERO, JE SILBERO, JE SILVER, H SILVER, H	8009100429 8009100429 8009300039 8009090602 8009050458	50-282 0 50-282 0 50-282 0 50-287 I 71-7116
SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V	8009020130 8009020134 8009020137 8009020140 8009020143	50-313 F 50-458 F 50-556 F 50-482 F 50-445 F	SHEA, K H SHEA, K H SHEA, K H SHEA, K H SHEA, K H	8009190039 8009230035 8009190039 8009230035 8009180259	50-367	SIMMONS.Q SIMMONS.Q SIMONETTI.Q SINGER.L N SINGER.L N	8009190224 8009190234 8009180005* 8009040227 8009090249	50~440 K 50~440 K 50~334 G 50~287 Q 50~287 Q
SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8009020147 8009020149 8009020153 8009020155 8009030263	50-498 F 50-267 F 50-267 F 50-298 F 50-482 G	SHEA,K H SHEALY,H G SHEALY,H G SHEALY,H G	8009300574 8009300574 8009100072* 8009100076* 8009020316	50-367	BINGER, L N BINGER, L N BIGUR, B R BKGLDB, J L	8009110779 8009110788 8009110791 8009120438 8009140640#	50-320 Q 0-289 Q 0-289 Q 0-361 H 0-395 Q
SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V	8007030245 8007030246 8007030268 8007030271 8007230116	50-445 Q 50-382 Q 50-498 Q 50-458 Q 50-298 Q	SHEDLOSKY, J T SHELDON, K P SHELDON, K P SHELDEN, K P	8009150088* 8009110802 8009110802 8009300004 8009180334	50-245 G 50-155 G 50-155 G 50-367 G 71-82	SKOLDS.J L BLOTT.N SMITH.O H SMITH.O H SMITH.O H	8009300073* 8007070534 7712170054* 8002150283 8005070552	50~261 0 50~275 H PT9 PT9 PT9
SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V	8009240735 8009250458 8009260526 8009160032 8009160035	50-313 Q 50-267 G 50-265 Q 50-458 Q 50-278 Q	SHERIDON'S L SHERBONDA'S N SHEITEA'M N SHEITEA'M N	8009300654 8009150233 8009020091* 8009260435 8009110531	40-8027 70-925 50-206 P 70-143 FOIA	SMITH,R I SMITH,R D SMITH,Q C SMITH,P D SMITH,R D	8009120205 8009100076* 8009160625* 8009120339 8009100067	TOPREP 27-47 50-277 G NUREG 27-47
SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8007100217* 8007120025 8007120026 8007170370 8007170372	40-4639 50-458 Q 50-298 Q 50-313 Q 50-458 Q	SHERIDAN, T B SHERIDAN, T B SHERMAN, F L SHERMAN, M P SHERON, B W	8007260417* 8007300436 8007120668 8007260667 8007100407	50-289 T NUREO 70-33 NUREO NUREO	SMITH, 0 H SMITH, 0 H SMITH, 0 H SMITH, 0 H SMITH, P A	8007250334 8007150117 8007170047* 8007240176* 8007150146	70-820 50-217 0 50-352 0 50-244 0 CONTRACT
SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8009170394 8009170396 8009170397 8009170399 8009170401	50-498 Q 50-482 Q 50-382 Q 50-298 Q 50-285 Q	SHERDN, B SHERWOOD, O O SHERWOOD, G O SHIELDS, S W SHIELDS, S W	8009190578 8009020023 8009030505 8009020253* 8009180533	TOPREP NUREO 50-333 P 50-546 8 50-546 A	EMITH, Q C EMITH, D R, EMITH, J D EMITH, Q EMITH, Q H	8007160246* 8007050214* 8007270015* 8007300322* 8007120525	50-334 0 71-7508 50-266 0 90-259 H 70-343
SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8009170403 8009170406 8009100362 8009120420 8009120422	50-247 Q 50-445 Q 70-1401 50-313 Q 50-458 Q	SHIELDS, S W SHIELDS, S W SHIELDS, S W SHIELDS, S W	8007030480 8007250482* 8007270208* 8007180521 8007300074	50-546 8 50-546 8 50-546 Q 50-546 A 50-546 0	HITH, OH BMITH, OH BMITH, TC BMITH, TC BMITH, TC	8007170044 8007240186 8007150346* 8007150557 8007230755*	50-352 Q 50-244 Q 50-289 H 40-8672 CONTRACT
SEYFRIT.K V SEYFRIT,K V SEYFRIT,K V SEYFRIT,K V	8009120423 8009120424 8009120427 8009120429 8009120432	90-498	SHIELDS, S W SHIELDS, S W SHIELDS, S W SHIELDS, S W	8007030500 8007040427 8007250447 8007180344 8007070574	50-546 A 50-546 B 50-546 G 50-546 G 50-546 H	W I, HTIMB H O, HTIMB J N, HTIMB H O, HTIMB	8009020059 8009110294 8009080356* 8009090478 8009100372	50-361 0 70-820 50-327 8 50-271 P
SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SHACKELFORD, B	8009120433 8009120434 8009180127 8009300505 8009020107	50-247 @ 80-445 @ 50-298 @ 50-298 @ 70-1738	SHIELDS, S W SHIELDS, S W SHIELDS, S W SHIELDS, S W	8009100469 8009160400 8009160419 8009290511 8009240561	50-546 8 50-546 9 50-546 9 50-546 A 50-546 8	BMITH, F A SMITH, I W SMITH, R D SMITH, R D, SMITH, R L	8009140450 8009050420 8009220179 8009230055 8009090535	NUREQ 50-287 0 27-39 27-39 50-271 R
SHAFER, W D SHALLY, P. J SHALLER, D V SHALLER, D V	8007260308* 8007070501 8007070501 8007150323	50-314	SHIVELDS, S W SHIVELY, C N SHIVELY, C N SHIVELY, C N	8009300452 8009260407* 8009020458* 8009030425* 8009090385*	50-546 H 50-287 T 50-348 S 50-348 S 50-348 S	BMITH, I W BMITH, I W BMITH, I W BMITH, I W BMITH, I W	8009110799 8009140534 8009170137 8009170182 8009170198	50-289 0 50-289 0 50-289 0 50-289 0
SHALLER. D V SHALLER. D V SHALLER. D V SHALLER. D V	8009140273 8009140280 8009190517 8009190503 8009300510	50-315 R 50-316 R 50-316 S 90-315 S 50-315 S	SHIVELY, C N SHIVELY, C N SHIVELY, C N	8007150276* 8007150261* 8007230712* 8007240504* 8007300544*	50-348 B 50-348 B 50-348 B 50-348 B 50-348 B	BMITH, B J BMITH, I W BMITH, I W BMITH, I, W BMITH, I W	8009240557* 8009180557 8009220408 8009220411 8009230024	50-395 Q 50-269 Q 50-269 Q 50-269 Q
EHANAHAN, W P SHANAHAN, W P SHANNON, P C SHAPAR, H K SHAPAR, H K	8009120037* 8009110276* 8009090343* 8009230229* 8009230234*	CONTRACT FOIA 50-339 U FOIA FOIA	SHOEMAKER, C L SHOLLY, S C SHOLLY, S C SHOLLY, S C SHOLLY, S C	8009300438 8009020052 8009050427 8009030421 8009160169	50-317 J 50-289 9 50-289 0 50-289 P 50-289 0	SMITH.C V SMITH.I W SMITH.I W SMITH.I W SMITH.R L	8009300184 8009240531 8009240532* 8009260653 8009260221	50-243 F 50-289 Q 50-289 Q 50-389 M 50-271 P
SHAPAR, H K SHAPAR, H K SHAPAR, H K SHAPAR, H K SHAPAR, H K	8009230266* 8009230268* 8009230274* 8009190498* 8009190568*	FOIA FOIA FOIA FOIA	SHOLLY, S C SHOLLY, S C SHON, F J SHOPENN, N M SHOPENN, N M	8009160030 8009300617 8009170175 8009180203* 8009180081*	50~289	Smith, i W Smith, Q Emith, Q, Smith, I, W Smith, I W	8009240445 8009300325* 8009300327* 800930003 8009300004	50-287 Q 50-257 H 50-257 H 50-287 Q 50-287 Q
SHAPAR, H K SHAPAR, H K SHATTERLY, L H SHEA, J R SHEA, J R	8007110450 8007110013 8007170121* 8007150418* 8007150072	50-289 ¢ 50-389 M 40-2061 COMMISSION XPORTLIC	SHORB, E M SHORB, E M SHORB, E M SHORB, E M SHRIVER, E L	8009100165 8009110556 8009110569 8009230259 8009200466	50-347 Q 50-347 Q 50-347 Q 50-347 Q NUREQ	SMITH, I, W SMITH, I W. SMOKER, C S SMOKER, C S SNAIDER, R P	8007300015 8007300318 8007240501* 8007240508* 8007300214	50-289 0 50-289 0 50-305 8 50-305 8 0EN TEC 18

AUTHOR	ACCEBSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGORY
ENIEZEK, J ENYDER, B J ENYDER, B J ENYDER, B J	8007170745 8007110389 8007020152 8007070572 8007150240	50-259 8 50-344 H 50-320 P 50-320 P 50-320 H	SPECIALE, J R SPECTOR, L S SPENCER, O S SPENCER, O S SPENCER, O S	8009230527* 8009230238* 8009150378* 8009110424* 8009120467	50-318 8 FOIA 50-397 Q 50-460 Q 90-397 Q	STELLO, V STEPHENS, C M STEPTOE, P P STEPTOE, P P STERNBERG, D M	8007300316 8005070553* 8007070471 8007220217* 8007020240*	50-259 H PT9 50-295 0 50-155 0 50-397 G
ENYDER, B J SNYDER, B J SNYDER, B J SNYDER, B J	8007240107 8007020172 8007020315 8007020465 8007030368	50-320 H 50-320 H 50-320 H 50-287 H 50-320 H	BPENCER.O 8 BPENCER.O 8 BPENCER.W C BPENCER.O 8 BPENCER.O 8	8009020258 8009120616* 800905056 8009120292 8009120304	50-361 Q 50-460 Q 50-281 Q 50-528 Q 50-460 Q	STERNBERG, D H STERNDERG, D H STERN, A STERN, H C STERN, H P	8007020251* 8007230217* 8007240147 8007270485 8007270488	50-344 Q 50-275 Q FOIA XPORTLIC XPORTLIC
D G SAYDER. B. J BAYDER. B. J BAYDER. B. J BAYDER. B. J	8007030478 8007030481 8007050375 8007070404* 8007100042	50-289 H 50-289 H 50-320 H 50-320 P 50-289 H	SPENCER, O B SPENCER, J B BPENCER, O B SPENCER, O S SPENCER, W C	8009120496 8009180375 8009110415 8009190169* 8009240180	50-528 G 50-461 A 50-460 G 50-529 G 50-280 G	STERN, W C STERN, W C STEVENSON, M Q STEVENSON, M Q STEVENS, S C	8009290581 8009300024 8009300169 8009110503 8009090525	XPORTLIC XPORTLIC 50-3 P NUREO 50-285 8
U G. PSEYNB B. PSEYNB J. PSEYNB J. B. PSEYNB J. B. PSEYNB J. B. PSEYNB	8009170170 8009170266 8009170272 8009240100 8009190619	50-320 H 50-320 H 50-320 H 50-320 F	BPENCER, O B SPENCER, O B SPENCER, O B SPESSARD, L SPESSARD, R L	8009300047 8009120609 8009120173 8009190171* 8009100148*	50-312 @ 50-460 @ 50-808 A 50-254 @ 50-10 @	STEVENS, S C STEVENS, B C STEVENSON, R L STEVENS, S C STEWART, R C	8007030486* 8007070505 8007250470* 8007300532 8007150066*	50-285 R 50-285 8 70-1131 50-285 8 50-445 0
E RABOYNB L RESTREE L RESTREE L RESTREE L RESTREE L RESTREE L	8007050386 8007020273 8007020277 8007020310 8007030367	50-320 H 50-289 H 50-287 H 50-320 H 50-320 H	SPESSARD, R L SPETH, O SPETH, O SPIEGEL, V SPIEGEL, O	8007260404* 8007240550* 8007070778* 8007270263 8007020282	50-10 G 50-275 G 50-367 G 71-5740 50-445 M	STEWART, R C STEWART, R C STEWART, R C STEWART, R C STEWART, R C	8009150071* 8009150075* 8009150077* 8009150080* 8009150083*	50-445 G 50-445 G 50-445 G 50-445 G 50-445 G
GNYDER, B J GNYDER, B J GNYDER, B J GNYDER, B J GNYDER, B J	8007050474 8007070611 * 8007100068 8007170285 8007170362	50-320 H 50-320 P 50-287 H 50-320 H 50-320 H	SPIEGEL, G SPIEGEL, G SPIEGEL, G SPIEGEL, G SPIECE, P	80070202B2 8007150417 8007150417 8007300013 8007080453	50-445 M 50-445 M 50-445 M 50-445 M 40-8697	SYEWART, R C BIEWART, W P BIEWART, R C BIIEFELD, B BIILWELL, T C	8007150087* 8007240628* 8007300076* 8007260072 8007020148*	50-445 0 50-302 P 50-382 G NUREG 50-331 P
ENYDER, B J BNYDER, B J BNYDER, B J BNYDER, B J, BNYDER, B J,	8009230760 8009020487 8009020488 8009020502 8009050366	50-320 H 50-320 H 50-287 H 50-320 H 50-287 H	SPRENCEL, J F SPRINGER, D SPRINGER, D SPRINGER, D STACK, D W	8009190713* 8009030297 8009030300* 8009050303*	CONTRACT 50-488 G 50-488 G 50-488 G NUREO	STILWELL, T C STILWELL, T C STILWELL, T C STILWELL, T C	8007020463* 8007020467* 8007020470* 8007020473* 8007020474*	50-10 P 50-10 P 50-10 P 50-10 P 50-10 P
ENYDER.B.J ENYDER.B.J ENYDER.B.J ENYDER.B.J ENYDER.B.J.	8009220049 8009230233 8009030187 8009150324 8009180330	50-289 H 50-320 H 50-320 H 50-289 H 50-289 H	BTAGGERS.H O BTAHL.D M STAHL.D.M STAHL.D.M STAHL.D.M	8009100108* 8009110369 8009170369* 8009170235* 8009170239*	COMMISSION 50-445 Q 50-445 M 50-445 M 50-445 M	BTILWELL, T C STILWELL, T C STILWELL, T C STILWELL, T C	8007040103* 8007040315* 8007040544* 8007050456* 8007050501*	50-155 P 50-324 P 50-271 P 50-273 P 50-27 P
BNYDER, B J. BNYDER, B J BNYDER, B J BNYDER, B. J. BNYDER, B J	0009150343 8009150441 8009150452 8009160101 8009170287	90-289 H 90-320 H 50-320 H 50-289 H 50-289 H	STAHL, D STAHL, D M STAHL, D M STAHL, D STAHMER, F	8009170369* 8009170177 8009170177 8009160160* 8009120320*	90-445 M 50-445 M 50-445 M 50-445 M 50-295 8	STILWELL, T C STILWELL, T C STILWELL, T C STILWELL, T C	8009150426* 8009170260* 8009170402* 8009180219* 8009040129*	50-317 P 50-333 P 50-220 P 50-336 P 50-263 P
U 8,790YAB U 8,790YAB U 8,790YAB U 8,790YAB U,890YAB	8009170271 8009230194 8009230216 8009100206 8009180321	50-289 H 50-289 H 50-320 H 50-320 H 50-289 H	STAMIRIS.B STARK.R M STARKEY.R B STARKEY.R B. STARK.R.M	8007260001 8007150478 8007030457 8007030463* 8007170773	50-327 0 50-387 A 50-241 B 50-241 S 50-482 A	STODDART,P O STOHR,J P STOHR,J P STOHR,J P STOHR,J P	8009170358* 8003190529* 8003190517 8009220182 8009240637*	50~289 T PT9 PT9 50~335 Q 70~143
NYDER, B J SNYDER, B J, SNYDER, B J SNYDER, B J SNYDER, B J	8009150351 8007190750 8009170004 8009170283 8009150546	50-320 H 50-320 H 50-287 H 50-320 H 80-320 H	STARK, R. M. STARK, R. M. STARK, R. M. STARKEY, R. D. STARKEY, R. D.	8009230770 8009120651 8009180464 8009150286 8009150287*	50-483 A 50-387 A 50-387 A 50-261 S 50-261 S	STOHR, J P STOHR, J P STOHR, J P STOHR, J P. STOHR, J P.	8007160487* 8007160470* 8007020466 8007040317 8007240189*	50-280 Q 50-280 Q 50-340 Q 50-327 Q 50-302 Q
U BINBOYNB U BINBOYNB J. BINBOYNB U BINBOYNB U BINBOYNB	8009150547 080045008 080045008 E900457008 104005908	50-320 H 50-320 P 50-320 P 50-320 P 50-320 H	STARKEY, R B, SYARK, R M STARKEY, R B STARKEY, R, B STARKEY, R, B	0007160295 0007300667 0007170467 0007170477* 0007250301	50-261 R 50-387 F 50-261 B 50-261 B 50-261 B	STOHR, J P STOHR, J P STOHR, J P STOHR, J P	8009040055 8009110099 8009250196* 8009160473 8009240176	27-39 27-39 50-349 0 50-280 0 50-302 0
BNYDER, B J. BNYDER, B, J. BNYDER, B, J. BNYDER, B, J.	8009300610 8009300636 8009300638 8009290148 8009020066	50-320 H 50-320 H 50-320 H 50-320 H 50-466 0	STARKEY.R B STABZESKY.F M STAUDER.B J STAUDER.W STEFFES.C	8007250304* 8007150081* 8007230372* 8007240028* 8007020376*	90-261 8 80-293 U CONTRACT CONTRACT 90-254 8	STOHR, J.P STOHR, J.P STOTCK, A.F STOTZ, J.C STRAUSS, P.L	8009240318 8009240624 8009260495* 8009160397* 8009230145*	50~416 Q 70~143 40~8663 50~346 B FOIA
BOHINKI, 8 M BOMTRIL, J R, BODNO, A. L BODNO, A. L BOUDER, J L	8009040297 8009080438* 8009250478* 8009150183* 800909082	50-446 Q 50-312 P 70-1257 70-258 50-483 A	BTEFFEB.C BTEINER.G R BTEINDLER.H J BTELLO.V BTELLO.V.	8007080417* 8007030377 8007160530 7910020407 8009290163*	90-265 S 90-327 R 70-2909 PT9 FOIA	STRAUSS.P L STRAUSS.P L STRAUSS.P. L STREETER, J, STREETER, J F	8009230224* 8009170390* 8009170400* 8009150025* 8009290118*	FOIA FOIA FOIA 50-373 G 50-255 G
BOUDER, J. L BOUDER, J. L BOUDER, J. L BOUDER, J. L BOUDER, J. L	8009050424 8009110528 8009100922 8009100924 8009120091	50-266 H 50-289 0 50-335 F 50-327 F 50-484 F	STELLO, V STELLO, V STELLO, V	8005230654 8007080266 8009170410 8009170414* 8009170417*	PTP 50-333 Q 50-458 Q 50-458 Q 50-458 Q	STREETER, J F STROHL, J STROHE, T R STROUBE, W B SULLIVAN, R C	8009260404* 8009020050 8009240260 8009170130 8009300081*	50-10 ( 50-244 t State Pro; 40-8745 50-259 (
BOUDER, J L BOUDER, J L BOUDER, J L BOUDER, J L BOUDER, J L	8007120074 8007240347 8007100730 8007260016 8007260017	50-454 F 50-361 F 50-282 F 50-282 F 50-263 F	STELLO, V STELLO, V STELLO, V STELLO, V	8007070638 8007100066 8007150303 8007180277# 8007100657	50-324	BULLIVAN, T J BUMMERS, R J BUTTON, J W BUTTON, D E	8007120533 8009160186* 8007290076* 8007150217* 8007100231*	RECOD 70-135 FOIA GA999 GA999
BDUDER, J. L. BOHDON, T. L. BPAETH, M. E. BPANNAUS, W. BPARKE, D. T.	8009260043 8009090267# 8009240312 8009030726 8009100412	50-280 F 50-293 R 70-1113 50-282 G RF8	STELLO, V STELLO, V STELLO, V STELLO, V	8007300042 8007270160 8007250047 8007300345 8007260288	50-324 0 50-255 0 50-317 0 50-317 0 50-490 T	H L, NOTTUB H R, MAHA SHANBY, O T SHANBY, O, T	8007180536* 8007110177* 8007080480* 8007110737 8007170143	0A999 50~51B { 40~3453 40~3453 40~3453

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJEC CATEOC	
SHANGER. H J SHANSON, E R SHANSON, M V SHANSON, D T SHART, F E	8009020483 8009100140# 8009190877# 8009170122 8009020221		TEDESCO,R L TEDESCO,R L	800 9030672 800 9030685 800 9030272 800 909070789 800 9020491	50-483 A 50-482 A 50-478 A 50-375 A 50-445 A	THOMAS, D O THOMAS, R. D THOMAS, E L THOMAS, E B THOMAS, E B	8007120581 8007160561 8007040485 8007180340 8007240502	RES 70-734 NUREO 90-220 50-341	P A
SWART.F E SWART.F E SWART.L L SWEARINGEN.J D SWEENEY.A A	8007260227 8007260233* 8007230628 8007160327* 8007030683*	50-267 Q 50-327 S	TEDESCO, R L TEDESCO, R L	8009040506 8009040509* 8009120113 8009040434 8009040464	50-267 P 50-267 P 50-458 A 50-369 A 50-319 P	THOMPSON, D THOMPSON, D THOMPSON, D THOMPSON, D THOMPSON, D	8008210619 8009040591 8009020510 8009190418 8009190565	1&E 50-333 50-284 1&E 50-255	8
SWEENEY, L E SWEENEY, L E SWEENEY, L E SWEENEY, L E	8009020428 8009020421 8009020087 8009080332 8009030431	50-287 I 50-287 Q 50-287 T 50-287 G 50-287 T	TEDESCO,R L TEDESCO,R L TEDESCO,R L TEDESCO,R L TEDESCO,R L	8009040467 8009120116 8009090128 8009090842 8009090851	50-390 A 50-369 A 50-364 A 50-389 A 50-389 A	THOMPSON, D. THOMPSON, D. THOMPSON, T THORNBURG, H D THORNTON, P	8009300048 8009300166 8009230692* 8009110061* 8009220218*	1&E 1&E 50-346 50-397 50-155	B A Q
SMEENEY, L E SMEENEY, L E SMEENEY, L E	8007030372 8007030582 8007150252 8007110374 8007110405	50-269 T 50-289 T 50-289 T 50-269 Q 50-269 T	TEDESCO, R L TEDESCO, R L TEDESCO, R L TEDESCO, R L TEDESCO, R L	8007070877 8007150427 8007150480 8007180489 8007070875	50-369 A 50-267 P 50-267 G 50-369 A 50-395 A	THURLOH, E W TIEPEL, E W, TIERNAN, J. A, TIERNEY, F P TILLMAN, A,	8009230584 8009150023 8009160504 8009180422 8009190451#	50-309 40-8502 50-317 50-282 50-259	P 01 8 02
SWEENSY, L E SWEENSY, L E SWEENSY, L E	8009160371 8009250270 8009170292 8009290357 8009230445	50-269 C 50-289 T 50-287 P 50-289 I 50-289 T	TEDESCO, R L TEDESCO, R L TEDESCO, R L TEDESCO, R L TEDESCO, R L	8009120108 8009120112 8009120501 8009120619 8009120623	50-311 P 50-311 P 50-311 P 50-438 A 50-369 A	TILLMAN, A TIMKO, D R, TING, W. H TOBIN, H. J TOBIN, H. J	8009110173* 8009180194* 8009100202 8009190651* 8009110191*	50-250 50-334 50-201 50-259 50-327	0 R P Q Q
SHEENEY.L E SHEENEY.L E SYLVIA.B R SYLVIA.B R	8009260175 8009230449 8009230434 8009020242 8009240701*	50-289 0 50-289 0 50-269 0 50-280 0 50-280 0	TEDESCO, R L TÉDESCO, R L TEDESCO, R L TEDESCO, R L TEDESCO, R L	8009150565 8009190131 8009110523 8009110529 8009120099	50-275 F 50-311 P 50-423 A 50-438 A 50-460 A	TOBIN, H. J TOBIN, H. J TODD, Q. A TODD, Q. A. TODD, Q. A	8007250437* 8007230210* 8007100714* 8007110142* 8007100775*	70-143 50-321 70-143 70-1151 70-27	Q
SYLVIA, B R SYLVIA, B R SYLVIA, B R SYLVIA, B R	8009120702 8009230097 8009240661* 8009120031 8009050329	50-338 8 50-338 0 50-281 0 50-280 0 50-338 R	TEDESCO,R L TEDESCO,R L TEDESCO,R L TEDESCO,R L TEDESCO,R L	8007120102 8007120197 8007160649 8007170404 8007170776	50-508 A 50-329 A 50-369 A 50-445 A 50-395 A	TOLLIBON, A C	8007240356* 8007240340* 8007020380 8007020371* 8007100433	50-324 50-324 50-324 50-324 50-324	0 9 8 8
SYLVIA, B R SYLVIA, B R SYLVIA, B R SYLVIA, B R	8009080394 8009090528 8009240399 8009110431 8009150257	50-337 P 50-280 Q 50-280 Q 50-338 P 50-338 Q	TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L	8009090035 8009090037 8009090103 8009110250 8009150333	50-410 A 50-491 A 50-397 A 50-10 P 50-369 A	TOLLISON, A C TOLLISON, A C TOLLISON, A C TOLLISON, A C TOLLISON, A C	8009120371# 8009180570 8009160260 8009230624 8009230635#	50-325 50-324 50-324 50-325 50-325	8 8 8
SYLVIA, B R SYLVIA, B R SYLVIA, B R SYLVIA, B R	8009140324 8009180251 8009190437 8009290319 8009300116	50-281 J 50-280 P 50-280 R 50-338 R 50-280 Q	TEDESCO.R L TEDESCO.R L TEDESCO.R L YEDESCO.R L TEDESCO.R L	8009170192 8009190099 8009220030 8009120119 8009180172	50-142 Q 50-416 A 50-311 P 50-395 F 50-327 Q	TOLLIBON, A C. TOLLIBON, A C. TOLLIBON, A C. TOLLIBON, A C TOLLIBON, A C	8009230719 8009230725 8009230727* 8009230735* 8009230736	50-324 50-325 50-324 50-325 50-325	8 8 8
SYLVIA.BR SYLVIA.BR RSYLVIA.BR SYLVIA.BR SYLVIA.BR	8009170321 8009190525 8009230287 8009230356 8009230292	50-281 P 50-280 P 50-338 P 50-338 R 50-338 P	TEDESCO: R L.	8009180569 8009240087 8009250243 8009150538 8009150541	50-375 A 50-367 V 50-327 P 50-528 A 50-375 A	TOLLIBON, A C TOLLIBON, A C TOLLIBON, A. C. TOLLIBON, A C TOLLIBON, A C	8007230740* 8007230459 8007230470 8007230483* 8007230707	50-325 50-325 50-325 50-325 50-325	6 6 8 8
SYLVIA, B R SYLVIA, B R SYLVIA, B R SYLVIA, B R	8007230320 8007230343 8007230627 8007260182 8007260278	50-338 F 50-280 F 50-338 C 50-338 F 50-280 P	TEDESCO, R L TEDESCO, R L TEDESCO, R L TEDESCO, R L TEDESCO, R L	8009170227 8009180330 8009240548 8009090440 8009100484	50-329 Q 50-361 A 50-382 A 50-339 P 50-387 A	TOLLISON, A C TOLLISON, A C TOLLISON, A, C, TOLLISON, A, C TOLLISON, A C.	6009230717* 8009230718 8009230745* 8009250265 8009260638*	50-325 50-325 50-325 50-324 50-324	6 6 8 8
SYLVIA.B R SYLVIA.B R SYLVIA.B R TAGGART.D W TAIT.L	8009290349 8009300255 8009300249 8009220242* 8009100515	50-338 P 50-338 Q 50-338 P 50-329 A 50-367 Q	Tedesco. R L Tedesco. R L Tedesco. R L Tedesco. R L Tedesco. R L	8009150191 8009150540 8009240531 8009180515 8009240510	50-27 P 50-410 A 50-416 A 50-373 A 50-375 Q	TOLLIBON, A, C TOLLIBON, A C TOLLIBON, A C. TOLLIBON, A C TOLLIBON, A, C	8009290286 8009290288 8009290309* 8009290311* 8009300489	50-325 50-324 50-324 50-325 50-325	6 8 8
TALWANI,P TAMBLING T N TAMBLING,T N TAPIA,J I TAPIA,J I	8007050418* 8007270020* 8007140414* 8007150087* 8007050533*	50-395 A 50-346 Q 50-305 Q 50-445 Q 50-498 Q	Tedesco, r l Tedesco, r l Tedesco, r l Tedesco, r l Tedesco, r l	8007240551 8007250146 8007250267 8007260671 8007270047	50-364 A 50-358 Q 50-358 E 50-358 A 50-275 F	TOLLIBON, A C	8009300509* 8009300474 8009300479* 8009300559 8009300568*	50-325 50-324 50-325 50-325 50-325	8 8
TAPTA, J I TARNOFF, P TAUBER, H, TAYLOR, J H TAYLOR, R G TAYLOR, R G	8007250405* 8007150423* 8007030602 8007240634* 8007150073*	50-498 Q COMMISSION 50-341 A 50-302 P 50-445 Q	TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L TEDESCO.R L	8007270001 8007250141 8007250071 8007270086 8007300227	50-369 A 50-400 A 50-346 A 50-358 A 50-311 P	TOLMAN, E L TOMLINGON, D P TOMLINGON, D P. TONDI, D. TONDI, D	8009050399 8009150357* 8009300102* 8009040457 8009030055*	RE8 50-458 50-498 NUREO NUREO	q q
TAYLOR, R O TAYLOR, R O TAYLOR, J H TAYLOR, J H	8009150100* 8009150105* 8009150367* 8009020364 8009100233	50-445 G 50-445 O 50-445 G TOPREP	TEDESCO,R L TEDESCO,R L TERRELL,N THATCHER,D F THIES,A C	8007270157 8007300307 8007170526* 8007170354* 8007030605	50-395 A 50-329 A FOIA 50-287 T 50-269 Q	TONDI,D. TONEATTI,V W. TONEATTI,V,W, TONEATTI,V,W, TONGUE,T M.	8009260191 8009290318* 8009290315* 8009290312* 8009100148*	NUREO QA999 QA999 QA999	a
TAYLOR.J H YAYLOR.R R TAYLOR.R R TAYLOR.J H YEDEBCO.R L TEDESCO.R L	8009120270 8009300062 8009300064* 8009230707 8009110604	TOPREP XPORTLIC XPORTLIC 50-287 P 50-327 P	THOM, T. FHOMAS, R D. THOMAS, R D. THOMAS, R D. THOMAS, R D. THOMAS, M	8009170277* 8009080564* 8009020261* 8009020239* 8009030040*	50-259 R 50-298 G 70-734 70-984 50-390 Q	TOOLE, R, J TOOLE, R, J, TORCIVIA, J A TOTH, R D TOTH, A D	8007260431# 8007300506 8007260407# 8007110427# 8007120631#	50-287 50-287 50-289 50-460	T 8 T Q
TEDESCO, R. L. EDESCO, R. L.	8009030332	50-369 A 50-373 A 50-369 A 50-395 A 50-445 A	THOMAS, R. D. THOMAS, R. D. THOMAS, M. THOMAS, E. THOMAS, R. D.	8009290131* 8009110650 8009250114* 8009140204 8009040596	50-254 G 27-48 50-366 G PRM 70-734	TOTH, A. D TOTH, A. D TOURTELLOTTE, J TOY, H. L TRAGER, E. A	8007040482# 8007150379# 8007170254 8007070886 8007100740	50-397 50-397	G G G

AUTHOR	ACCESSION NUMBER	BUBJECT CATEOORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
~ ~ <del>~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ </del>	8007030054# 8007030062# 8007150356#	40-1341 50-334 P 50-336 P 50-317 P 50-317 P	TUPPER, K F TUPPER, K TUPPER, K F TUPPER, K TURPER, K TURCOTTE, R L	8009050446* 8009050446* 8009110632 8009110635*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC 50-131 F	VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	B009160373 B009230653 B009230701	50-528 C 50-528 T 50-528 S 50-528 C 50-528 A	
TRAMMELL, C. M TRAMMELL, C M TRAVIB, C G. TRAVIEZO-DIAZ TRAVIEBO-DIAZ	8007070823 8007270117 8007240850 8007070768* 8007070768*	50-344 P 50-344 P RES 50-312 0 50-312 0	TURK, 8 E TURK, 8 E TURK, 9. E TURNAGE, K C TUTLEMAN, J 9	6009170129* 8009170131* 8009260536	70-2909 70-2909 70-2909 NUREG 50-320 H	VAN BRUNT,E E VAN BRUNT,E E VAN BICKEL,J VAN VRANKEN,J VAN VRANKEN,J	8007300402 8007170504* 8007160281	50-529 S 50-528 K 50-331 R PR 50-367 Q	
TREAT, E. H. TREBY, B. A TREVINO, T TRIBBLE, J. E TRIBBLE, J. E.	8009290389* 8009090245 80090110379* 8009020113 8009190947	50-289 H 50-510 G CONTRACT 50-271 G 50-271 G	TYLER,P E TYLER,P E TYLER,P E TYLER,P E UDY,A C	8007030450 8007170175 8007270357 8007270148 8007240084	50-170 P 50-170 V 50-170 P 50-170 F 50-316 P	VANDELL, T D VANDOORN, P K VANDOORN, P K VARANINI, E E VARANINI, E E	8009020123 8009240320* 8009240071* 8009030638 8009030643*	40-8102 50-413 G 50-335 G PR PR	
TRIBBLE, J. E TRIBLE, P. TRIFUNAC, H D TRIFUNAG, M D TRIFUNAG, M. D	8009100127 8009150182 8009090456* 8009090472* 8009090464*	50-271 Q PR 50-275 T 50-275 T 50-275 T	UDY, A G UHRIO, R, E UHRIO, R E UHRIO, R E, UHRIO, R E	8009240520 8007290624 8009120520# 8009030320 8009120491#	50-315 P 50-335 F 50-250 Q 50-335 Q 50-250 Q	VARANINI.E E VARELA, A A VARQA, B A VARQA, B A VARQA, B. A	8009030647+ 8009190106+ 8009090792 8009050460 8009050464+	PR 50-443 G 50-272 P 50-315 P 50-315 P	,
TRIFUNAC, M D TRIFUNAC, M TRIMBLE, D. C. TRIMBLE, D. C TRIMBLE, D. C	8009150234 8009090532 8009020224 8008280022 8009040049*	50-70	UHRIG,R E UHRIG,R E UHRIG,R E UHRIG,R E UHRIG,R E	8007020192 8009100585 8009110166* 8009020195 8009030300	50-335 Q 50-367 8 50-250 Q 50-250 Q 50-250 Q	VARGA: BA VARGA: BA VARGA: BA VARGA: BA VARGA: BA.	8009050471* 8009120039 8009120048= 8009120065* 8009030167	50-315 P 50-315 P 50-315 P 50-315 F 50-334 F	P
TRIMBLE, D. C. TRIMBLE, D. C. TRIMBLE, D. C TRIMBLE, D. C	8007020042 8007020447 8007030373 8007020001 8007030422	50-313 P 50-368 8 50-313 P 50-313 R 50-368 8	UHRIG,R.E UHRIG,RE UHRIG,RE UHRIG,RE UHRIG,RE	8009020304 8009170374 8009160639 8009160639 8009030633	50-335 Q 50-335 Q 50-250 Q 50-250 Q 50-389 A	VARCA.S A VARCA.B A VARCA.B A VARCA.B A VARCA.B A	8007030174 8007100473 8007100675* 8007050505 8007050510*	50-281 50-281	P P P
TAIMBLE, D.C.  TAIMBLE, D.C.  TAIMBLE, D.C.  TRIMBLE, D.C.  TAIMBLE, D.C.	8007030537 8007120387 8007030622 8007030628* 8007030410	50-348 8 50-313 P 50-348 8 50-348 8	UHRIG,R.E UHRIG,R E. UHRIG,R E UHRIG,R E UHRIG,R E	8009240174 8009030236 8009110693 8009120671 8009190137	50-389 G 50-250 P 50-389 G 50-250 G 50-335 G	Varca, B a Varca, B. A Varca, B a Varca, B a Varca, B a	8009050519* 8009050528 8009050531* 8009050538* 8009090785	50-295 50-295 50-295 50-280	9 9 9 -
TRIMBLE, D. C.	8007030537 8007030550 8007070326 8007070425 8007070378	50-313 J 50-313 J 50-313 F 50-313 R 50-348 S	UHRIG.R.E UHRIG.R.E UHRIG.R.E UHRIG.R.E UHRIG.R.E	8009090290 8009110853 8009240412 8009090257 8009250209	50-250 R 50-250 Q 50-250 Q 50-250 P 50-250 Q	VARGA:8 A VARGA:8 A VARGA:8 A VARGA:8 A VARGA:8 A	8007090862 8007090882 8007070884 8007100176 8007110030	50-272 50-247 50-305 50-348	F F F P P
TRIMBLE, D. C.	8007070562 8007150273 8007160251 8007150258	50-313 8 50-368 8 50-313 R 50-368 8 50-368 8	UHRIO, REUHRIG, REUHR	8009150251 8009150262 8009160200 8009160378 8009180444	50-335 P 50-387 A 50-335 P 50-250 P 50-335 P	VARQA, S. A. VARQA, S. A. VARQA, S. A. VARQA, S. A. VARQA, S. A.	8007110031* 8007110035* 8007170228 8007170737 8007100125	50-348 50-348 50-315 50-280 50-305	PPFP
Trimble, D. C.	8009150248 8009150273 8009160228 8009170322 8009230407	50-368 8 50-313 P 50-313 F 50-368 R 50-313 R	UHRIO, RE UHRIO, RE UHRIO, RE UHRIO, RE UHRIO, RE	8007170204 8007300152 8007300040 8007230304 8007300372	50-250 P 50-335 G 50-389 G 50-335 P 50-335 G	VARGA, B. A VARGA, B. A VARGA, B. A VARGA, B. A VARGA, B. A	8007110579 8007150511 800910071 8009100040 8009100104	50-315 50-272 50-250 50-247 50-316	PPPP
TRIMBLE, D.C. TRIMBLE, D.C. TRIMBLE, D.C. TRIMBLE, D.C. TRIMBLE, D.C.	8009230697 8009230708 8009230709 8009230744 8009240496	50-313 8 50-368 8 50-369 8 50-368 B	UHRIO, R.E. UHRIO, R.E. UHRIO, R.E. ULLRICH, H. T. UNDERHILL, D. H.	8009290343 8009300129 8009300177 8009080342* 8009100158	50-250 P 50-250 P 50-250 P 50-277 R NUREG	VARGA.S A VARGA.S A VARGA.S A VARGA.S A VARGA.S A	8009110512 8009110773 8009150515 8009150519 8009100064	50-315 50-295 50-286 50-247 50-305	P P P
TRIMBLE, D. C TRIMBLE, D. C. TRIMBLE, D. C TRIPLETT, M. P. TRIPP, L. E.	8009300278 8009300538 8009300173 8009050412* 8009190259*	50-368 8 50-313 P FOIA 50-387 0	UNDERNOOD, P. R. UNDERHOOD, P. R. UNDERHILL, D. H. UPRIGHT, C. M. UPRIGHT, C. M.	8009180208* 8009180235* 8009300276* 8009030149*	50-321 R 50-365 R CONTRACT 50-280 G 50-369 G	VARGA, S. Á VARGA, S. Á VARGA, S. Á VARGA, S. Á VARGA, S. Á	8009120511 8009150436 8009120513 8009180518 8009300518	50-305 50-250 50-272 50-272 50-272	F
TRIPP.L.E  TROUP.G.L.  TROUP.G.L.  TROUTHAN, M  TROUBRIDGE.G F	8009160497* 8009250200* 8009250200* 8009190123* 8009260301	50~280 Q 50~367 Q 40~2061 50~287 Q	UPRIGHT, C. M URBAN, J R URBAN, J R URGUHART, O T UTLEY, E E	8009120071* 8009160033 8009160041* 8009260400* 8008280370	50-348 Q 50-387 M 50-389 M 50-289 T NUREO	Varga, 8 A Varga, 8 A Varga, 5, A Varga, 5, A Varga, 5, A	9009090773 8009090761 8009190596* 8009100638*	50-247 50-247	1
TROWSRIDGE, OF TROWSRIDGE, OF, TROWSRIDGE, O.F. TROWSRIDGE, O.F. TROWSRIDGE, O.F.	8009260301 8009030118 8009030118 8009040365 8009040365	50-287 0 50-320 0 50-320 0 50-287 0 50-287 0	UTLEY, E E. UTLEY, E. E UTLEY, E E UTLEY, E E UTLEY, E E	8007070402 8007070448 8007160376 8007170425 8007230438	50-324 F 50-324 P 50-324 P 50-325 P 50-324 P	Varga.s a Varga.s a Varga.s a Varga.s a Varga.s a	8009190151* 8009120042 8009090771 8009120181 8009150219	50-247 50-286 50-286 50-334	
TROUBRIDGE, O. F. THOMBRIDGE, G. F. TROUBRIDGE, G. F. TROUBRIDGE, G. F. TROUBRIDGE, G. F.	8009100431 8009100431 8009170219 8009170302 8009170319	50-289 9	UTLEY, E E, UTLEY, E E UTLEY, E E UTLEY, E E VADEN, J	8009230693 8009250262 8009260509 8009300357 8009190881	50-324	VARCA.S A VARCA.S A VARCA.S A VARCA.S A VARCA.S A	8009150244* 8009180107 8009180113* 8009180538 8009180545	50-241 50-241 50-260 50-280	
TROWERIDOE, O F TROWERIDOE, O F TROWERIDOE, O. F. TROWERIDOE, O. F.	8009170302 8009240313 8009240313 8009240313 8009300020	50-287 T 50-287 T 50-287 T 50-287 T 50-287 Q	VAKERICS: T V. VAKERICS: T V. VALENTE: F A VAN BRUNT: E E VAN BRUNT: E E	8009270176* 8002190229 8009040240 8009030674 8009030499	FOIA PT9 50-139 F 50-520 G 50-528 G	VARGA, S A VARGA, S. A VARGA, S A VARGA, S A VARGA, S A	8009190255 8009190267 8009190283 8009220009 8009220088	50-247 50-295	
TROHERIDOE, O.F. TROHERIDOE, O.F. TROULFANIDIS, N. TUBES, B. TUMALA.T. TUNSTALL, J. E. TUNSTALL, J. E.	8009300020 8009220237 8009160274 8009150230 8009300198 8009300209	50-289 0 RM # 50-254 R REGOD REGOD	VAN BRUNT, E E. VAN BRUNT, E E. VAN BRUNT, E. E. VAN BRUNT, E. E. VAN BRUNT, E. E.	80070205321 8007120234 8007030511 8007030556 8007070523	50-528 Q 50-528 A 50-528 8	Varoa, e a. Varoa, e a Varoa, e a Varoa, e a Varoa, e a	8009220093 8009230113 8009230120 8009230121 8009230124	50-348 50-305 50-280	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
VAROA, S A VAROA, S A VAROA, S A VAROA, S A VAROA, B A VAROA, B A	8009240078 8009240084* 8009260609 8009120191 8009180904	50-315 P 50-318 P 50-315 Q 50-286 P 50-305 P	WARD, P C WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D	8009300573 8009220318 8009030625 8009160290 8009160292	50-262 S 50-267 Q 50-267 S 50-267 R 50-267 R	WERLING, J A	8007160444 8007160470 8007160405 8007170500 8007240450	50-334 8 50-334 8 50-334 8 50-334 8 50-334 8
VAROA, B A	8009180544 8009290439 8009290464 8009290454# 8009290464	90-305 F 90-206 P 90-206 P 50-200 P	WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D	8009160344 8009160364 8009160286 8009160314 8009230598	50-267 P 50-267 P 50-267 R 50-267 P 50-267 S	WERLING, J A WERLING, J A WERNER, W WERNER, R WEBCOTT, H M	8009290251 8009300412 8009260068 8009230623 8009250352*	50-334 8 50-334 8 XPORTLIC 50-445 A 50-461 Q
VARDA, B A	8009270464* 8009270468* 8009230390* 8009230390* 8009230399*	50-280 P 50-280 P 50-275 P 50-275 P 50-275 P	Warembourg. D Warembourg. D Warembourg. D Warembourg. D Warembourg. D	800723060B 8007230723 8007230687 8007240369 8007260378	50-247 8 50-247 R 50-247 P 50-247 R 50-247 R	WESCOTT, H M WEST, J B WESTERMAN, T F WESTERMAN, T F WESTERMAN, T F.	8009180061* 8009230764* 8009050477* 8009100055* 8009170172*	50-461 Q 50-320 H 50-267 Q 50-267 Q 50-382 Q
VAROA S A	8009260161# 8009260181# 8009360099 8009360015	50-334 P 50-334 P 50-334 P 50-295 P 50-250 P	WAREMBOURG, D. WAREMBOURG, D. WARNICK, R F WARNICK, R F WARNICK, R F	9007230597 8007300554 8007150055# 8007150060# 8007160616#	50-267 8 50-267 8 50-445 0 50-445 0 50-305 0	WESTERMAN, T F WESTFALL, R M WESTFALL, R M WETTERHAHN, M J WETTERHAHN, M J	8009300282* 8009110885 8009110372 8009300119* 8009230027	50-267 Q RES NUREQ FOIA 50-395 Q
VAROA.S A VAROA.S A VEATCH, M D VERDERBER, J J VERRELLI.D M	8007260937 8007260541* 8007260545* 8007220277 8007030403	90-284 P 50-284 P 50-286 P NUREQ 50-397 A	WARNICK,R F. WARNICK,R F WARNICK,R F WARREN,S K WATERMAN,M E	8007160514* 8007270015* 8007300243* 8007260001 8007050405	50-35B	WETTERHAHM, M J WETTERHAIM, M J WHARTON, R J WHARTON, R J WHARTON, R J	8009300014 8009300014 8009110399* 8009110399* 8009100404	50-35B 0 50-35B 0 50-361 0 50-361 0 50-361 0
VEVE, H E. VILLALVA, I VILLEMY, Q R VINYCH, V VOEGELI, R J	8007180163 8007270027 8007230767 8007160224 8007160486	50-366 P FOIA 50-255 P 50-201 Q WASTE MOT	WATERMAN, M E WATERMAN, M E WATERG, D. B WATERG, D. B, WATERG, D. M	8007100520 8007240099 8007120437 8007120437 8007160256*	RE8 RE8 50-261 H 50-261 H 50-261 R	WHARTON,R J WHITEGELL,D E WHITEGELL,D E WHITEGELL,D E WHITEGELL,D E	8009100406 8009180217* 8009180508* 8009290323* 8009100231*	50~361 Q GA799 GA799 GA799 GA799
VOIGHT, B VOLLEN, R J VOLLEN, R, J VOLLEN, R J	8007270040 8007170263* 8007030703 8007030710 8007030703	50-313 P 50-440 K 50-367 0 50-367 0	WATSON,A P WATSON,M WATT,C H WAWZYNIECKI,P WEDER,D A	8009240550 8008250025 8009180371 8009300537 8009020344	RE8 50-574 0 50-320 P 40-791 50-312 P	WHITESELL,DE WHITESELL,DE WHITESELL,DE WHITESELL,DE WHITESELL,DE	8007180117* 8007110618* 8007280327* 8007180536* 8007180566*	QA999 QA999 GA999 QA999
VOLLEN, R J VOLLEN, R J VOLLEN, R J VOLLEN, R J	8009030710 8009120392 8009120445* 8009120392 8009120445*	50-367 0 50-367 0 50-367 0 50-367 0 50-367 0	WEEKS,E D WEGENER,D WEGST,W F WEISLER,J,H WEISS.L A	8009120449 8009090287* 8009140321 8009040599 8009230204*	50-133 R 50-243 R 50-142 P 50-373 B FOIA	WHITE,C E WHITEGELL,D E WHITEGELL,D E WHITEGELL,D E WHITEGELL,D E	8009190024# 8009080467# 8009150021# 8009170159# 8009180085#	QA777 QA777 QA777 QA777 QA777
VOLLEN.R J VOLLEN.R J VOLLEN.R J VOLLEN.R J	6007230008 6007230008 6007230382 6007230382	50-367 0 50-367 0 50-367 0 50-367 0 50-367 0	WEISB, L A WEISB, L A WEISB, L A WEISB, E, R WEISB, E R	8009230209# 8009230213# 8009230218# 8009250471# 8009080575#	FOIA FDIA FOIA TOPREP COMMIBSION	WHITESIDES, O E WHITE, R N WHITE, C E WHITE, L. D WHITE, L. D	8009110895 8009020355 8009190017* 8009110485 8009190667	RES Nureo Ga797 50-244 g Pr
VOLLEN, R. J VOLLEN, R. J VOLMER, G. J VORDERBRUEGGEN	8007230393 8007260011 8007260011 8007180079# 8007120296#	90-347 0 50-347 0 50-347 0 0A999 50-528 0	HEIBS, J D HEIBB, E R HEIBB, E R HEIBB, D.	8009260174* 8009110244* 8009110249* 8009250467* 8009260173*	71~40#8 70-754 70-820 TOPREP 71-60#8	WHITE, L D WHITE, L D WHITE, J, W WHITE, L D	8009240192* 8009300063* 8009050274 8009150414* 8009020026	50-244 Q 50-261 Q 50-244 V CONTRACT 50-244 P
VORDERBRUEGOEN VORDERBRUEGOEN VUHBACO, F. J HAGNER, A. O. WAGNER, H J	8009190149# 8009190178# 8009190220* 8009120240* 8009120309*	50-52B	WE189, E. R WE189, E. R WE189, D. WE189, D. WE189, E. R	8007110547 8007120583 8007150474 8007150434 8007250452	FOIA FOIA 40-8584 50-275 P FOIA	WHITE.L D WHITE.L D WHITE.L D WHITE.L D WHITE.L D	8007020086 8007020346 8007030474 8007030545 8007030485	50-244 V 50-244 B 50-244 P 50-244 P 50-244 P
WAGNER, F, T WAGNER, P, C HALBRIDGE, W C WALBRIDGE, W C WALBRIDGE, W C	8007180523 8007030347 8007070812 8007070813* 8007040408	71-6717 50-285 D 50-312 Q 50-312 Q 50-312 P	WE188, E R WE188, E R WE188, E R WE188, E, R WE188, D	8009040258 8009040358 8009040258 8009040358 8009190760	70-149 50-289 G 70-143 50-289 G 70-1193	WHITE, L D WHITE, L D WHITE, L D. WHITE, L D. WHITE, E B	8007040414* 8007180265 8007070513 8007070377 8007110012	50-244 P 50-244 R 50-244 P 50-244 P PR
WALBRIDGE, W.C. WALBRIDGE, W.C. WALKER, R. B. WALL, L. B.	8007240378 8007080433 8009290353 8009260205 8009160545	50-312 0 50-312 P 50-312 P 50-320 H 40-8681	WE188, D WE188, E R WE188, E R WE188, E R WE188, E R	8009240742 8009110802 8009160046 8009160046 8009150041	70-143 50-155	WHITE, L. D WHITE, L. D WHITE, L. D WHITE, L. D,	8009070551 8009160539 8009170303 8009170317 8009170311	50-244 P 50-244 P 50-244 P 50-244 F 50-244 G
HALLACE, A HALLER, F & WALSH, E J WALSH, P, B WALSH, P &	8009190405 8009190272 8009090421 8009260417* 8009260431*	NUREO 50-440 & 50-320 P 50-287 T 50-287 T	WEISB,E R WEISB,E R WEISB,E R WEISB,E R WEISB,E R	8009150041 8009160046 8009300423* 8009300417 8009300423*	50-287 0 PR 50-287 0 50-287 0 50-289 0	MHITE,L D WHITNEY,O O WHITNEY,O O WHITNEY,O O	8009300365 8009030617* 8009020386* 8009030483* 8009090426*	50-244 P 50-293 8 50-293 8 50-293 8 50-293 8
HALBKE, C. WALTERB, D K WALTERB, D X WALTERB, P W WALTERB, P W	8007070347* 8007120141* 8007100258* 8007070350 8007050486*	50~339 P 50~414 G 50~400 G 50~289 H 50~410 G	WEITZBERG, A WENDERLICH, R.L. WENDERLICH, R.L. WENDERLICH, R.L. WENDERLICH, R.L.	8007220226 8007120348* 8007160318* 8007230372* 8007300460*	50-201 0 50-317 B 50-317 B 50-317 B 50-318 8	WHITNEY, O. Q WICHERB, D. L. WICHERB, D. L. WICHERB, D. L. WICHERB, D. L.	8009160271* 8008110036 8008120614 8009170240 8009300191	50-293 R 40-8502 40-8502 40-8502 40-8502
WAMBACID J L WANAT, B. W. WANAT, B W WANO, C H WANO, C H.	8007260067 8007070331 8007070331 8007300192 8007300184	RE6 27-39 27-39 50-243 R 50-243 F	WENSLAWSKI, F. WENSLAWSKI, F. WENSLAWSKI, F. WENSLAWSKI, F. WERGARD, A. J.	8007240533* 8007300324* 8007180137 8007300615 8007030633	50-147 9 50-344 9 50-206 8 50-206 9 50-277 8	WICKHORST,P M WIDNER,W A WIDNER,W A WIDNER,W.A WIDNER,W A	8007160340* 8007110828* 8007030076 8007020287 8007020180	50-57 I 50-321 Q 50-321 Q 50-321 Q 50-321 Q
HARDIJ. J HARDIK D HARDIK D HARDIE C	8009150100* 8009110627* 8009150508* 8009160249* 8009300234	50-445 Q 50-262 Q 50-346 Q 50-327 Q 50-263 R	WERLING, J A WERLING, J, A WERLING, J A WERLING, J A	8007050250 8007120377 8007150373 8007250251 8007260307	50-334 B 50-334 B 50-334 B 50-334 B 50-334 B	WIDNER, W A	8007020373 8007230105 8007110471 8007030484 8007110474	50-321 0 50-321 0 50-321 0 50-321 F 50-321 0

ROHTUA	ACCESSION NUMBER	SUBJECT CATEOORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	CATEGOI
NIDNER, H A NIDNER, W. A NIDNER, W A NIDNER, H A NIDNER, H A	8009150162 8009240367 8009160448 8009300104 8009190423	50-321	MOLF.JF MOLFE.BJ MOLFE.BJ MOLFE.BJ	8009160530 8009110065 8009120407 8009160520 8009190229	70-2909 50-376	YTHIER, P YUHAB, Q YUHAB, Q P YUNDT, C P YUNDT, C P	8009300209* 8009180139 8009300615 8009250463 8009090410	CONTRAC' 50-206 50-206 71-9018 50-344
Hiddff, M P Hiddff, M P. Higgins, J. T Higgins, E Higgins, E	9007020407 9007020407 9007150184* 9007300118 9007300073	50-289 0 50-289 0 50-277 0 CONTRACT CONTRACT	WOLFE.B WOLFE.B J WOLFE.B J WOLFE.B J WOLFE.B J	8009260466 8009220417 8009220415 8009250058 8009260674	50-536 P 50-466 G 50-466 O 50-466 O 50-466 Q	YUNDT.C P YUNDT.C P YUNDT.C P YUNDT.C P YUNDT.C P	8009150471 8009100453* 8009260506 8009100239 8009170309	50-344 50-344 50-344 50-344 50-344
WILBERT: R. L. WILBORN, L. WILBORN, L. WILBORN, L. WILBUR, L., C.	9007180321 8007080487* 8007180203* 8007180081* 8007020018	WABTE MOT 40-3453 40-1162 40-8452 50-134 F	WOLFE, B J WOLFE, B J WOLFF, T A WOLIVER, J	8009300439 8009300326 8009300456 8009190891 8009030693	50-376 0 50-445 M 50-466 Q State Prog 50-358 Q	YUNDT.C P ZABRISKIE,W L ZAHLER.R E ZAHLER.R E ZAHLER.R E	8009300471 8009100508 8009250017 8009250017 8009300022	50-344 RE6 50-289 50-289 50-289
HILKINSON, P. HILLCUTT, Q J E HILLCUTT, Q J, E HILLIAHS, H A HILLIAHS, C C.	8009160456 8009120589* 800910036 8009020124* 8009150177*	NUREQ 50-320 P NUREQ 50-320 H 50-546 G	WOLLETT, 6 WOLLETT, 6 WOLLETT, 8 WOLLETT, 8	8007190702 8007180207 8007240023 8007240123 8007300572	CONTRACT CONTRACT CONTRACT CONTRACT CUNTRACT	ZAHLER, R E Zajac, L D Zajac, L D Zarakas, P Zarakas, P	8009300022 8009150377* 8009170143* 8009090242 8009120187	50-287 50-370 50-328 50-3 50-3
MILLIAMB, C C MILLIB, R. J MILLIAMBON, E L MILLIAMB, C C MILLIAMB, C C	8007180280* 8007300624 8007150304* 8007270465* 8007040577	50-373 Q F01A 50-438 Q 50-373 Q 50-373 B	HOLLETT, 8 WOLTKER, E WONG, T WONG, T WONG, T	8009260243 8009120235* 8008130375 8009160549 8009120390	CONTRACT 70-371 40-299 40-299 40-299	Zarakas, p Zarakas, p Zarakas, p Zarakas, p Zarakas, p	8009030416 8009030559 8009080329 8009030458 8009030610	50-247 50-247 50-247 50-247 50-3
HILLIAHS, R. L HILLIAHS, C. C HILLIAHS, C. C HILLIS, E. HILLIAKS, W. D	8009170144 8009290193* 8009290526* 8009160263* 8009190511*	40-8745 50-454	WOOD, L D WOOD, J C WOOD, E. C WOOD, E. C WOODHEAD, C P.	8009110600 8009040289 8009260637 8009260494 8009020426	XPORTL 1C 50-445 M 50-307 S 50-309 S 50-409 0	Zarakab, p Zarakab, p Zarakab, p Zarakab, p Zarakab, p	8007030382 8007070383 8007070484 8007070423 8007070506	50-3 50-3 50-247 50-3 50-247
WILLIENS, V H HILLSEY, W B HILLSEY, W B. HILLSEY, W B. HILSDN, F R.	9007260439* 9007020245 9007160427 9007230567 9007170501	50-289 T 50-171 R 50-277 R 50-277 R 50-344 J	WOODLEY, SE WOODRUFF, R. L WOODRUFF, R W WOODS, Q R WOODSMALL, W A	8009180327* 8009290073* 8009090553 8009230016 8009290321*	50-289 H FDIA 50-317 P 50-142 G 50-338 R	Zarakas, p Zarakas, p. Zarakas, p Zarakas, p. Zarakas, p.	8007120353 8007160365 8007230432 8007230568 8007240452	50-247 50-247 50-3 50-247 50-3
NILEON, J. N HILBON, J. L. HILBON, B. D. HILBON, B. D. HILBON, B. D.	8009090631 8009100262* 8009100032 8009110273 8009110830	50-322 A 50-280 B XPDRTLIC XPDRTLIC XPDRTLIC	WOOLEVER.E, J WOOLEVER.E J WOZNIAK, D R WRAY, J R WRAY, C	8009090114 8009090248 8009120574 8009020477* 8009050391*	50-334 G 50-412 B XPORTLIC 50-348 G 50-320 H	Zarakab, p Zarakab, p Zarakab, p Zarakab, p Zarakab, p	8009230491 8009250266 8009300384 8009300524 8009300481	50-247 50-3 50-247 50-247 50-247
HILBON, W.E. HILBON, J. L. HILBON, J. L. HILBON, J. L. HILBON, J. L.	8007030528 8007020089 8007020070* 8007030525 8007020344	50-27 R 50-281 B 50-281 B 50-280 B 50-280 B	WRIGHT,R W WRIGHT,F 8. WULLER,O E WULLER,O E WULLER,O E	8009090259# 8009100421 8009090808 8009110631 8009040491	50-553 G 50-471 O 50-461 G 50-461 G 50-461 A	ZECH.O G ZEFF.D W ZEFF.D W ZEFF.D W ZELLNER.R J	8007170416 8007070874 8007180517 8007230457 8007300112	ACRS 70-1201 70-1201 70-1201 40-8724
HILBON J. T. HILBON J N HILBON J L HILBON J L HILBON J L	8007020350* 8007230772 8007080351 8007080366* 8007100252	50-280 8 50-324 P 50-281 8 50-281 8 50-280 8	WULLER, Q E WULLER, Q E WULLER, Q E WULLER, Q E WYATT, J	8007250457 8007020341 8007170513 8007240457 8007170383	50-461 Q 50-461 A 50-461 A 50-461 K 50-446 U	ZGLICZYNSKI, J ZIBULSKY, H ZIBULSKY, H ZIEMIANSKI, E J ZIMMER, A M	8007030572* 8007110272* 8007120235* 80070707267* 7706290356*	50-59 70-135 70-371 50-293 PT9
HILBON, Q, HILBON, J. L. HILBON, J. L. HILBON, J. HILBON, J. L.	8009160425* 8009150274 8009150278* 8009190444* 8009220248	50-327 B 50-280 B 50-280 B 50-280 R 50-281 B	WYDLER, J W WYDLER, J W YACKLE, T R YACKLE, T R YACKLE, T R	8007020217* 8007120474* 8007050403 8007100520 8007260077	COMMISSION COMMISSION RES RES RES	ZIMMERHAN,R P ZIMMERHAN,L R ZIRWAS,K ZITO,N ZITTEL,H E	8007150088* 8007240304* 8007230487* 8007150305 8007240253	50-245 TOPREP 50-237 FOIA RES
HILBON, J. L. HILBON, J. L. HILBON, J. L. HILBON, J. L. HILBON, J. L.	8009220253 8009220258* 8009220240* 8009220263* 8009220309*	50-280 8 50-280 8 50-280 8 50-280 6 50-281 8	YANDELL, L A YERKES, R F YESSO, J D, YIN, I. T YIN, I T.	8007050477* 8009160363* 8009150597 8009120657* 8009290101*	50-267 0 50-275 0 NUREG QA799 50-346 Q	ZOBEL,W ZUDANB,J ZULLA,B S ZULLA,B B ZULLA,B B	8007030438* 8007240177* 8007080537 8007220030 8007080323	50-327 50-313 50-286 50-286 50-286
HILBON, J.L. HILBON, J.L. HILBON, J.N. HILBON, J.L. HILBON, J.L.	8009220398* 8009220402* 8009170400 8009190553 8009190559*	50-281 8 50-281 8 50-324 P 50-280 8 50-280 8	YIN, I T YORK, 8. YOUNG, R YOUNG, T YOUNGBLOOD, B J	8007180054# 8007110411 8007020474# 8007230217# 8007050192	50-373	ZULLA:B 8 ZUMBRUM:R A ZUMBRUM:R A ZWETZIG:G B ZWICK:E J.	8009190442 8009110012 8009110012 8009120478* 8009300333	50-286 PR PR 50-326 FOIA
HILSON, J. L. HILSON, J. N. HILSON, J. L. HILSON, J. L. HILSON, J. L.	8007170544# 8007240071 8007230645 8007230661# 8007230673#	50-280 8 50-322 A 50-280 8 50-280 9 90-280 8	YOUNGBLOOD, B J YOUNGBLOOD, B J YOUNGBLOOD, B J YOUNGBLOOD, B J YOUNGBLOOD, B, J.	8007050176# 8007050204# 8007160659# 8007120558 8007100192	50-339 P 50-339 P 50-339 P 50-373 Q 50-369 A			
HILSON, J. L. HILSON, J. HILSON, J. L HILSON, J. L HILSON, W. E.	8007240467 8007240470* 8007240471* 8007240473* 8007300371	50-281 8 50-281 8 50-281 8 50-281 8 50-27 P	ADANOBEDON B A CONNOBEDON B A CONNOB	8009110187 8009110397 8009110400 8009110859* 8009110854	50-454 F 50-456 F 50-373 F 50-502 A 50-502 A			
HILSON, J. L. HILSON, J. L. HILSON, J. L. HINTERB, L. HINTERB, L. HINTERB, D. 0	8009300498 8009300504* 8009300508* 8009030010 8009190522*	50-281 B 50-281 B 50-281 B RES 50-314 B	YOUNGBLOOD, B J. YOUNGBLOOD, B J. YOUNGBLOOD, B J. YOUNGBLOOD, B, J. YOUNGBLOOD, B, J.	8009240636 8009180896 8009180319 8009290169 8009260012*	50-337 E 50-347 H 50-337 P 50-347 A 50-389 0			
MITHER D. O.	DUVE 1 80200*	50-315 8	YOUNGBLOOD, B J	8009260013*	50-389 0			

50-315 71-2 71-394 50-320 50-237

8009190509\* 8009260074 8009290024 8009040239 8009110813

WIINER, D. Q. HOLF, C. R. HOLF, C. R. HOLF, J. F. HOLF, J. F.

YOUNGBLOOD, B J B GOODBONUOY C G GOODBONUOY D G GONUOY YTHIER, P

8009240013\* 8009300105 8009300108\* 8009290490 8009300198\*

50-389 50-389 50-389 50-339 CONTRACT

OAAP

		•	
•			

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	
ATCOR	8009260074	71-2			8009160308*	50-348	В
	8009290024	71-396			8009160320	50-348	Ĕ
Advanced Energy Systems	8009240690 8009260219	ACRS ACRS			<b>#ESE0017009</b>	50-348	8
Advisory Council on Historic Preservation		40-B6B1			8009160358 8009160415	50-348 50-364	P
Agriculture, Dept of, Forest Service Air Force, Dept of	8009220114 8009040269*	WASTE MO	e Te		8009170214	50-364	A
Air Transport Association	8009160206	PRM	٠		8009170353	50-364	A
Air and Water Pollution Patrol	8009020171*	50-320	н		8009170356* 8009170583*	50-364 50-348	A G
Al Stern Associates	8009240147	FO1A			8009230448	50-364	A
Alabama Power Co	6009020030	50-364 50-364	Ą		8009230465	50-364	A
	8009020038 8009020045	50-364 50-364	A		8009230566	50-34B	R
	8007020062	50-348	S		8009230710	50-348	8
	8009020068*	50-340	9		6009230722 6009230729*	50-348 50-348	8
	8009020291	50-348	œ		0009230737+	50-348	8
	8009020301 8009030427	50-344 50-348	0 8		8009290329	50-364	Α
	8007030427*	50-348	s		8009290391	50-964 50-348	P
	8009030491	50-348	R		9009300381 9009300381	50~348	P
	6009030492	50-364	A	•	8009300424	50-34B	P
	8007030495* 8007040246	50-348 50-364	R		9009300435	50-34B	Н
	8007040251*	50-364	Ä		800930045 <u>8</u> 8009300463	50-364 50-364	V
	8009040386	50-344	Α		8007300483	50-364 50-348	à
	8009040387*	50-364	A		8009300515*	50-34B	8
	8009040389# 8009040390#	50-364 50-364	A		B009300523	50-348	8
	8007040371#	50-364	Ä		8009300527* 8009300534	50-348 50-348	ES G
	B009040393*	50-364	A		9009300572	50-348	8
	8007040375*	50-364 50-348	A		8009300577*	50-348	8
	8009050052 8009080293	50-344	Ä	Alabama, State of	0009150411	70-2909	
	8009080387	50-346	F	Aldrich Chamical Co . Inc. (subs of	8009280238* 8009110592	CONTRAC XPORTLI	
	8009080387	50-348	P	Bigma-Aldrich Corp )			
	8009090544	50-349	P		B009110596*	XPORTLI	Si .
	8009090544	50-348	ħ		8009120624	XPORTLI	C
	8009090585	50-348	F		8009120627#	XPORTLI	C
	8009100237 8009100318	50~364 50~348	Q V	Allied Chemical Corp	8009300241	40-3392	
				Allist Coneral Nuclear Services	8009080231 8009300549	50-332 50-201	G G
	8009100318	50-348 50-364	ķ				
	8009100324 8009100363	50~364 50~364	9	American Electric Power Co., Inc	8009190422	50-315	R
	8007110258	50-348	q	American Institute of Chemical Engineers	8007170447 8007300540	TOPREP 50-201	9
	B0091106B7	50-348	Q	American Muclear Society	1007110012	PR	
	8009120425	50-348	þ	American Society of Mechanical Engineers	8009100409*	CONTRAC	1
	8007150257	50-348	ĸ	Ametak, Inc	8009180064*	GAP99	
	8009150259 8009150260*	50-348 50-348	ĸ	Anaconda Co / Anaconda Copper Co Div	8009300232	WASTE M	
	8009150263*	50-348	ĸ	Anti-Nuclear Group Representing York	8009120224	50-289 50-289	0
					8007120232 8007230437	50-289	Ğ
	8009150263* 8009150484	50~348 50~364	K			EA	
	8007150464	50-348	Ŕ	Aptech Engineering Services	8009220247* 8009020479	50-329 NUREC	A
	8009140270*	50-340	R	Argonne National Laboratory	8007040104#	40-2061	
	8009160307	50~348	8		8009080402	NUREO	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	YAC	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	4Y
Arisona Public Service Co	8007070364 8007070607* 8007300442 8007020532* 8007030511	50-171 COMMISS 50-445 50-528 50-528	F		8007160296* 8009160256* 8009170241 8009170322 8009170322	50-313 50-313 50-313 50-313 50-313	R V F F
	8007030511 8007030511 8007030511 8007030556 8007030556	50-528 50-528 50-528 50-528 50-528	A A A S S		8007180424 8007180427# 8007190474# 8007230407 8007230410#	50-368 50-368 50-382 50-368 50-368	P H R R
	8009030556 8009030674 8009030714 8009050499 8009090392	50-528 50-528 50-528 50-528 50-528	8 0 0 0	n	8009230697 8009230700* 8009230705 8009230708 8009230712*	50-313 50-313 50-368 50-313 50-368	R = 8
	8009090398* 8009090523 8009120234 8009160373 8009160373	50-528 50-528 50-528 50-528 50-528	C A Q T T		8009230715# 8009230744 8009230748# 8009240494 8009240504#	50-313 50-368 50-368 50-368 50-368	80000
	8009140373 8009140379* 8009140379* 8009140379* 8009230453	50-528 50-528 50-528 50-528 50-528	T T T S		8007260453 8007260456* 8007300173 8007300242 8007300278	50-368 50-368 50-313 50-368 50-313	6 6 6
	8009230453 8009230453 8009230701 8009230701 8009230701	50-528 50-528 50-528 50-528 50-528	8 8 C C C	Army, Dept of, Corps of Engineers Army, Dept of, Office of Burgeon General Association of Community Organizations for Reform Now-Texas	8009300538 8009300546* 8009180237* 8009020179* 8009090238	50-348 50-368 50-544 50-327 50-445	8 9 0 4 0
	8009240422 8009300355 8009300402 8009300402 8009300402	50-528 50-529 50-528 50-528 50-528	A \$ % K K	Atlas Minerals  Atomic Industrial Forum	8007150045 8007080480* 8007110739 8009170143 8009090349*	50-445 40-3453 40-3453 40-3453 50-339	0 P
-kansas Power & Light Co	8009300405* 8009300405* 8009300405* 8008280022 8009020001	50-528 50-528 50-528 50-313 50-313	K K G R	Atwood & Morrill Co . Inc (subs of Faster Wheeler Corp )	8007070517 8007170648* 8007270312*	PR FOIA QA999	
	8009020042 8009020224 8009020449 8009020458* 8009030393	50-313 50-313 50-348 50-348 50-313	P G S B P S	Austin, TX Australia	8009290314* 8009290315* 8009290316* 8009290318* 8009040289 8009170239*	GA797 GA797 GA797 GA797 50-445 50-445	HHO
	8009030410 8009030417* 8009030422 8009030425* 8009030537	50-348 50-348 50-348 50-348 50-313	8 8	BDM Corp Babcock & Wilcox Co	8009110291 8009020364 8009030001 8009030004	50-574 FOIA TOPREP 70-27 70-1201	
	8009030537 8009030539 8009030546* 8009030550 8009030550	50-313 50-348 50-368 50-313 50-313	3 8 7 7		8007030446* 8007030817* 8007080438* 8007100176*	50-99 50-99 50-287 50-312 50-344	ь ь ь
	8007030628 8007030628 8007040047 8007050330 8007070326	50-348 50-348 50-313 50-313	8 8 0 V		8009100233 8009110667 8009120270 8009120586* 8009180177*	TOPREP  70-824  TOPREP  FOIA  GA777	
	8007070326 8007070378 8007070385* 8007070425 8007070425	50-313 50-348 50-368 50-313 50-313	F 8 8 8		8007180185* 8007180517 8007230457 8007230707 8007240634*	9A999 70-1201 70-1201 50-287 50-302	ъ Б
	8007070432* 8007070432* 8007070482 8007070491* 8007070562	50-313 50-313 50-313 50-313 50-313	R R P P S		8007260329* 8007260335* 8007260340* 8007260352* 8007260359*	50-289 50-289 50-289 50-289 50-289	T T T T
	8009090568* 8009120387 8009150258 8009150261* 8009150268	50-313 50-313 50-366 50-368 50-368	8 P 8 8	Babcock & Wilcor Co Naval Nuclear Fuel	8007260366* 8007260380* 8007260402* 8007270373* 8007070885	50-269 50-269 50-269 50-329 70-27	T T A
	8009150271* 8009150273 8009150275* 8009150287 8009150292*	50-368 50-368 50-368 50-368 50-368	8 8 8 P P	Div  Babcock & Wilcox Co , Nuclear Material Div	8009110767 8009090876	70-27 70-135	
	8007150272* 8007150273* 8007150274* 8007140228 8009140251	50-368 50-368 50-313 50-313	5 5 7 8		8007110244 8007150017 8007150480 8007150553	70-135 71-6400 70-135 71-5442	
	8009160251	50-313	B		8009180183	70-135	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC' CATEGO	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Babaon College Baber & Sotts	8009180196* 8009230138 8009230139* 8009020176 8009040271	70-135 70-364 70-364 FOIA 50-466	G.	Bear Creek Uranium Co Bechtel Corp	8007150481 8009250588 8009030462 8009030465* 8009020427*	NUREQ NUREQ 40-8452 40-8452 50-416 A
	8009160157 8009160201 8009180475 8009300027 8009300469	50-445 50-466 50-466 50-466 50-466	K G G G	Bechtel National Inc	8007020430* 8007020434* 8007020438* 8007170672 8007030563*	50-416 A 50-416 A 50-416 A NUREO 50-528 S
Baitimore Gas & Electric Co	8007020020 8007020034 8007020034 8007020035* 8007020035*	50-317 50-317 50-317 50-317 50-317	P R R R	Bechtel Power Corp (subs of Bechtel Corp ) Beltway Limousine Service, Inc Bergen-Patterson Pips Support Corp Berle, Butzel, Kass & Cass	8007080324* 8007030085* 8007120477 8007110484 8007120545	50-206 P CONTRACT PT21 50-201 G 50-201 P
	8007030014 8007030520 8007030522* 8007030543 8007030547*	NUREC 50-317 50-317 50-316 50-318	\$ \$ \$ \$	Bertin, Roisman & Kessler Bernard C Doyle Bio-Tec, Inc	8007070342* 8007070363* 800711033B* 8007110274* 8007110302*	50-247 9 50-247 9 CONTRACT FOIA POIA
	8009040301 8009080350 8009120344 8009120348* 8009120354	50-317 50-317 50-317 50-317 50-317	e e e	Biotechnology, Inc Bhact & Veatch Boeing Computer Services, Inc (subs of Boeing Co )	8009120037* 8009290296 8009190782	CONTRACT NUREO NUREO CONTRACT
	8009120378# 8009120447 8009120455# 8009150250 8009160315	50-317 50-317 50-317 50-317 50-317	9 6 9 P 9	Boston College Boston Edison Co	8007020110 8007020382 8007020386* 8007030477	50-273
	8007160318* 8007160453 8007160453 8007160504 8007170465	50-317 50-317 50-317 50-317 50-317	8 P Q S		8007030483* 8007030574 8007030597* 8007030603 8007030607*	50-273 S 50-273 S 50-273 S 50-273 S 50-273 S
	8009230520 8009230527* 8009230531 8009230536* 8009230542	50-318 50-318 50-317 50-317 50-317	5 5 5 5 5		8007030611 8007030617* 8007050484 8007090034	50-273 6 50-273 8 50-273 0 50-273 0 50-273 0
	8009230546* 8009230583 8009230592* 8009230634 8009230640*	50-317 50-317 50-317 50-317 50-317	6 8 9 P		8007070048* 8007070261 8007070267* 8007070367 8007070376*	50-293 R 50-293 R 50-293 S 50-293 S
	8009230488 8009230495* 8009250311 8009250311 8009290246	50-317 50-317 50-317 50-317 50-317	5 5 5 8 R		8007070387 8007070401* 8007070422 8007070426* 8007070430	50-293 8 50-293 8 50-293 8 50-293 8
	8009290246 8009290246* 8009290246* 8009300383 8009300383	50-317 50-317 50-317 50-317 50-317	R R R F F		8007070433* 8007070660 8007120036 8007150081* 8007150270	50-293 S 50-293 Q 50-293 U 50-293 U
	8007300438 8007300438 8007300441 8007300450* 8007300454	50-317 50-317 50-317 50-317 50-318	8 8 J		8009150289* 8009150285* 8009150285* 8009160267 8009160271*	50-293 P 50-293 P 50-293 P 50-293 R 50-293 R
Barr Engineering Co	8009300460* 8009300464 8009300470* 8009110770 8009110774*	50-318 50-317 50-317 40-299 40-299	8 8 8		8009140344 8009140394 8009140402* 8009160404 8009160410*	50-273 P 50-273 S 50-273 B 50-273 B 50-273 S
Battelle Memorial Institute, Columbus	8007300285*	40-299 70-8			8007160447 8007160452	50-293 8 50-293 8
Leboratories	8007100041* 8007100043 8007150597	CONTRACT NUREQ NUREQ	г		8009160455# 8009160483# 8009160516 8009160519 8009170329	50-273 S 50-273 S 50-273 Q 50-273 Q 50-273 F
Battelle Memorial Institute, Pacific Northwest Laboratory	8009180217* 8009190738* 8009240038* 8009300164 8009020219	CONTRACT CONTRACT CONTRACT NUREO 50-445	Г		8009170381 8009190076* 8009190940 8009220250 8009220252*	50-293 8 50-293 0 50-293 0 50-293 V 50-293 V
	8009100403 8009100413 8009110419 8009110421 8009110483	NUREG NUREG RES RES RES			8007230453 8007230732 8007230739* 8007240462 8007240463*	50-293 P 50-293 S 50-293 S 50-293 S 50-293 S
	8007120205 8007180597 8007160456	TOPREP NUREO NUREO			8009240467 8009240468* 8009250049	50-293 S 50-293 S 50-471 0

AUTHOR AFFILIATION	ACCESS I ON NUMBER	SUBJEC	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEO	
	B009260470 B009260475* B009260480 B009260481 B009260484*	50~293 50~293 50~293 50~293 50~293	8 9 9 8	California, Univ of Irvine	8009230016 8009230018* 8009230021* 8009120466* 8009120471*	50-142 50-142 50-142 50-324 50-326	0
	8007240485* 8007270283 8007270284 8007270313* 8007270317*	50-293 50-293 50-293 50-293 50-293	5 5 5 5	California, Univ of, Los Angeles	8009180234 8009140321 8009140322* 8009190405 8009240405	50-70 50-142 50-142 Nureq Nureq	O P P
Brand & Hali	8009300500 8009300505* 8009300531 8009300535* 8009020468*	50-293 50-293 50-293 50-293 50-395	# # \$ \$ M	Carolina Power & Light Co	8009260028 8008280370 8009020198 8009020199 8009020203	NUREG NUREG 50-261 50-324 50-400	9
Brookhaven National Laboratory	8009150307 8009150312* 8009160337 8009210618* 8009020032	50-375 50-375 50-375 50-327 50-273	M G P E		8007020321 8007020321 8007020380 8007020371* 8007030307	50-324 50-324 50-324 50-324 50-261	0 9 8
	8007020053 8007020053 8007020053 8007070342 8007070342	50-171 50-171 50-171 50-171 50-171	E E F F		8007030320 8007030457 8007030463* 8007080254 8007080254	50-335 50-261 50-261 50-400 50-400	9 8 8 8
	8007070362 8007070424 8007070487* 8007070564 8007070567	50-171 50-171 50-295 50-285 50-293	F G F F		8007080254 8007080254 8007070402 8007070402 8007070448	50-400 50-400 50-324 50-324 50-324	\$ F F
	8007070770 8007100747 8007100750 8007110321 8007110416	RES NUREO NUREO NUREO RES			8007090448 8007100241 8007100433 8007100465 8007100465	50-324 50-400 50-324 50-400 50-400	P G B B
Brownsville, TX	8007170401 8007220375 8007240686 8007250247* 8007020282	RES TOPREP NUREO 50-327 50-445	P M		8007100465 8007100465 8007110027 8007110027 8007110027	50-400 50-400 50-324 50-324 50-261	8 0 0
	8009150417 8009160182 8009160275 8009260318 8009300013	50-445 50-445 50-445 50-445 50-445	н н н		8009110356 8009110662 8009120228 8009120366 8009120371*	FOIA 50-324 50-261 50-325 50-325	9 9 9
iruce Norton durns & Roe Co	8007030489 8007030479 8007220213 8007030359 8007030344*	50-275 50-275 50-323 TOPREP TOPREP	G G		8009120437 8009120437 8009120437 8009120437 8009120437	50-261 50-261 50-261 50-261 50-261	н н н
C-E Operating Plants Owners Group	8007030403 8007150435* 8007170317* 8007170684 8007230581	50-397 50-320 50-320 NUREO TOPREP	A P P		8007120437 8007120437 8007120573 8007120573 8007120573	50-261 50-261 50-400 50-400 50-400	H G G
C-E Power Bystems	8009150028 8009190017* 8009190024* 8009240360 8009240520	70-1100 QA999 QA999 50-317 TOPREP	P		8009120593 8009150286 8009150289* 8009160255 8009160258*	50-400 50-261 50-261 50-261 50-261	Q 8 8 8 R R
COS.inc CONOCO.inc (Continential Oil Co )	8007240527* 8007250422* 8007120336 8007150585 8007070178	TOPREP 70-34 NUREQ NUREQ 40-8743			8009140260 8009140260 8009140263* 8009160376 8009170186	50-324 50-324 50-324 50-324 50-324	R R R P
Cabill, Gordon & Reindel	8007050442 8007050446* 8007110632 8007110635* 8007020462*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC 50-395			8009170186 8009170191* 8009170191* 8009170197* 8009180365	50-324 50-324 50-324 50-324 50-324	P P P Q
California Institute of Technology California, State of	8007020071* 8007030581 8007030438 8007030443* 8007030447*	50-206 50-275 PR PR PR	P H		8009180450 8009180450 8009180450 8009180450 8009180570	50-400 50-400 50-400 50-400 50-324	@ @ @ @
	8007110017 8007110024 8007150404 8007170337 8007170863	50-275 PR 50-275 50-312 State Pr	G G P		8009190425 8009190429* 8009190469 8009190477* 8009230059	50-325 50-325 50-261 50-261 50-324	P P S B
	8009220404 8009230614 8009250456* 8009020040 8009020049	50-275 50-275 50-361 50-224 50-224	Q Q A P F		8007230057 8007230080 8007230080 8007230080	50-324 50-400 50-324 50-324 50-324	Q Q Q Q

AVTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	
	8009230085 8009230438	50-324 50-324	 С Р	Citizens Committee for Protection of the	8009110044* 8009090363*	50-445 50-247	G G
	8009230438 8009230439* 8009230439*	50-324 50-324 50-324	P P	Environment Citizens Energy Forum Citizens for Fair Utility Regulation	8009230013 8009100435 8009260005	50-280 50-445 50-445	G G
	8009230459 8009230459 8009230468*	50-324 50-324 50-219	5 6 5	Citizens for the Conservation of Natural	8007260008 8007040225	50-445 50-376	G G
	8009230624 8009230635* 8009230670	50-325 50-325 50-325	8 8	Resources, Inc	8007040233 8007110010 8007110055	50-376 50-376 50-376	0 0
	8007230683* 8007230673 8007230673 8007230707	50-325 50-324 50-324 50-325 50-325	5 0 0 8	Cleveland Electric Illuminating Co	8007180564 8007260670 8007260681* 8007260684* 8007020067	90-376 50-376 50-376 50-376 50-440	0 0 0
	8009230718 8009230719 8009230725 8009230727*	50-325 50-324 50-325 50-324	5 6 6 5		8009100112* 8009120297 8009160636 8009190133	50-440 50-440 50-440 50-440	9 0 K
	8009230735* 8009230736 8009230740* 8009230745* 8009240340*	50-325 50-325 50-325 50-325 50-324	8 8 8 9		8009190133 8009190138* 8009190138* 8009190141 8009190141	50-440 50-440 50-440 50-440	K
	8009240348 8009240356# 8009240370 8009240370 8009250262	50-261 50-324 50-324 50-324 50-261	0 0 0 0 P		8007170144 8007170144 8007170147 8007170147 8007170156	50-440 50-440 50-440 50-440 50-440	KKKK
	8009250265 8009250265 8009250301 8009250304* 8009250351*	50-324 50-324 50-261 50-261 50-400	5 5 9 8		8009190156 8009190162 8009190165 8009190165	50-440 50-440 50-440 50-440 50-440	K K K K K
	8009250351# 8009250351# 8009250351# 8009260497 8009260409	50-400 50-400 50-400 50-400	G G G H H		8009190219 8009190219 8009190224 8009190224 8009190234 8009190234	50-440 50-440 50-440 50-440 50-440	K K K
	8007260638* 8007270286 8007270288 8007270288 8007270307*	50-324 50-325 50-324 50-324	3 8 8 8 8		8007170240 8007170240 8007170244 8007170244 8007170244	50-440 50-440 50-440 50-440 50-440	K K K K
	8009300337 8009300474 8009300479* 8009300489 8009300509*	NUREG 50-324 50-324 50-325	8 8		B00919024B B009190252 B009190252 B009190256* B009190256*	50-440 50-440 50-440 50-440 50-440	K K K
Carpenter Technology Corp Central & South West Corp	8007300357 8007300368* 8007300381 8007120574	50-325 50-325 50-400 XPORTLIC	8 9		8009190263* 8009190263* 8009190270 8009190270 8009190272	50-440 50-440 50-440 50-440 50-440	K K K
Central & Suddin House Corp	8009170235* 8009170235* 8009170235* 8009170349* 8009170349*	50-445 50-445 50-445 50-445	й и и и		8009190272 8009190279 8009190279 8009190285 8009190285	50-440 50-440 50-440 50-440 50-440	K K K
Cerac. Inc Chem-Nuclear Bystems, Inc Chickering & Gregory	8009090665 8009220172 8009260059 8009110396	XPORTLIC 71-9080 71-9097 50-361 50-361			8007170273 8007170273 8007170274 8007170274 8007170303	50-440 50-440 50-440 50-440 50-440	K K K
Christa-Maria Cincinnati Gas & Electric Co	8009110377* 8009110802 8009260650 8009030588	50-361 50-153 50-155 50-358	0 0 0 F		8009190303 8009190305 8009190309 8009190309 8009190309	50-440 50-440 50-440 50-440 80-440	K K K K
	8007030370* 8007050272 8007170422 8007170427 8007250227*	50-358 50-358 50-358 50-358 50-358	0 0 0		8007170307 8007170312 8007170314 8007170314 8007170318	50-440 50-440 50-440 50-440 50-440	K K K K
Citisuns Against Nuclear Dangers	8009270460* 8009300016 8009300126* 8009180394	50-358 50-358 FOIA 50-387	G G		8009190318 8009190321 8009190321 8009190329	50-440 50-440 50-440 50-440 50-440	K K K K
Citizens Association for Bound Energy	8009090579 8009090579 8009110034 8009110034 8009110044*	50-445 50-445 50-445 50-445 50-445	G O O G		8009190329 8009190334 8009190334 8009190337	50-440 50-440 50-440	K K K

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJEC	
	8009190337 8009190342 8009190342 8009190371 8009190371	50-440 50-440 50-440 50-440 50-440	К К К К		8007030507 8007030516# 8007040632 8007050347 8007080338	50-237 50-237 50-237 50-237 50-254	8 0 P P
	8009190404 8009190404 8009190405 8009190406 8009190407	50-440 50-440 50-440 50-440 50-440	К К К К		8007080341* 8007080355 8007080378 8007080407* 8007080412	50-254 50-295 50-265 50-265 50-265	9 9 9 9
	8009190407 8009190408 8009190408 8009190410 8009190410	50~440 50~440 50~440 50~440 50~440	K K K K		8009080417* 8009080422 8009080427* 8009090013 8009090013	50-265 50-254 50-254 50-237 50-237	8 8 0
	8009190411 8009190411 8009190413 8009190413 8009190431	50-440 50-440 50-440 50-440 50-440	Х Х К А		8007070233 8007070274 8007070274 8007070278* 8007070278*	50-559 50-295 50-295 50-295 50-295	0 R R R
Cahn, D B	8009190431 8009190435* 8009190435* 8009030149 8009030152*	50~440 50~440 50~440 50~367 50~367	A A G G		8009090394 8009090394 8009090394 8009090537* 8009100532	50-237 50-237 50-237 50-458 TOPREP	የ የ የ
Colorado State Univ Colorado. State of	8007020200* 8007160488* 8007170717 8007260233* 8007170874	40-4492 CONTRAC REGOD 50-267 State P	T R		8009100848* 8009110217 8009110300 8009110376 8009110376	TOPREP 70-2409 50-295 50-10 50-10	р Р
Colt Industries, Inc , Fairbanks Morse Engine Div Combustion Engineering, Inc	8007170877* 8007040425 8007050308* 8007110325 8007110704	State P 50-352 50-361 50-335 70-1100	го <u>ў</u> 8 А Р		8009110545 8009110545 8009110545 8009110545 8009110545	50-237 50-237 50-237 50-237 50-237	G G G G
Commerce.Dept of, National Bureau of Standards	8009230646# 8009230650# 8009100504	50-317 50-317 50-184	P F		9007110545 9007110545 9007110545 9007110545 9007110545	50-237 50-237 50-237 50-237 50-237	G G G Q
Commerce.Dept of National Oceanographic & Atmospheric Adminstration Committee to Bridge the Gap	8009110847 8009120014* 8009040203	71-5740 WABTE M CONTRAC 50-142	Г G		9009110545 8009110545 8009110562 8009110562 8009110562	50-237 50-237 50-237 50-237 50-237	0 0 0
Commonwealth Edison Co	8007240446 8007020105 8007020105 8007020107 8007020107	50-142 50-237 50-237 50-10 50-10	e P e a	8 6	3007110562 3007110737* 3007120253 3007120277 3007120302	50~237 50~254 50~254 50~295 50~295	Q Q R S
	8007020107 8007020107 8007020107 8007020107	50-10 50-10 50-10 50-10 50-10	0 0 0	\$ E	3009120305 3009120320* 3009120324* 3009120331* 3009120391	50-295 50-295 50-295 50-295 50-254	8 9 6
	8007020274 8007020277* B007020274 8007020381 8007020388*	50-304 50-304 NUREG 50-237 50-237	9 9 9 9	5 8 8	8009120399# 8009120404 8009120446 8009120446	50-254 50-10 50-454 50-454 50-454	9 P F F F
,	8007020370 8007020375 8007020376* 8007020401* 8007020447	50-254 50-275 50-254 50-275 50-275	5 5 5 5	8 8 8	007120444 007120453 007120453 007120453	50-454 50-10 50-10 50-10	F F F
	8007020452 8007020455* 8007020457*	50-295 50-295 50-295 50-295	8 8 9	8 8 8	007160216 007160272 007160272 007160276*	71-9113 50-237 50-254 50-254 50-254	P R R
	8007030437 8007030440* 8007030441 8007030441	50-295 50-295 50-295 50-295	P P R R	8 9 8	007160276* 007160293 009160305* 009160355* 009160374	50-254 50-304 50-304 50-311 50-334	8 8 8
	800703044# 800703044B 800703044B 8007030453#	50-295 50-254 50-254 50-254	R R R R	9 8	009160408 009160426* 009160585 009160681	50-295 50-295 50-373	\$ \$ Q
	8007030454 8007030454 8007030456 8007030467*	50-10 50-10 50-10 50-10	R R R	81 81 81 81	007160681 007160681 007160681 007160681	50-237 50-237 50-237 50-237	G G G
	8007030467# 8007030467#	50-10 50-10	R R		007140681 007140681		Q Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8007160681 8007160681 8007160681 8007160681 8007170230	50-237 50-237 50-237 50-237 50-237	Q Q Q Q		8009260213 8009260465 8009260511 8009260638* 8009290334	50-295 50-237 50-273 50-275 50-10	Р Р О
	8009170230 8009170230 8009170230 8009170411 8009170411	50-237 50-237 50-237 50-10 50-10	0 0 0 0 0		6009290335 6009290399 6009300200 6009300200	50-10 50-373 50-10 50-10 50-10	P 9 0 0
	8009170411 8009170411 8009170411 8009170411 8009170411	50-10 50-10 50-10 50-10 50-10	G G G G		8009300200 8009300200 8009300200 8009300200	50-10 50-10 50-10 50-10 50-10	G G G G
	8009170421 8009170421 8009170421 8009170421 8009180261	50-237 50-237 50-237 50-237 70-2609	0 0 0		8009300200 8009300200 8009300200 8009300200	50-10 50-10 50-10 50-10 50-10	0 0 0 0
	8009180406 8009180466 8009180466 8009180466 8009180466	50-373 50-10 50-10 50-10 50-10	A Q Q Q		8007300267 8009300273* 8009300287 8009300287 8009300287	50-295 50-295 50-10 50-10 50-10	るなない
	8009180466 8009180466 8009180466 8009180466 8009180466	50-10 50-10 50-10 50-10 50-10	Q Q Q Q		9007300287 9007300287 9007300287 9007300287 9007300287	50-10 50-10 50-10 50-10 50-10	****
	8009180466 8009180466 8009180466 8009190007 8009190007	50-10 50-10 50-10 50-373 50-373	0 0 0 0		8009300287 8009300287 8009300287 8009300287 8009300287	50-10 50-10 50-10 50-10 50-10	****
	8009190007 8009190007 8009190007 8009190007 8009190403	50-373 50-373 50-373 50-373 50-275	Q Q Q P		8007300455 8007300468 8007300472 8007300473* 8007300478*	50-454 50-237 50-237 50-237 50-237	A 9 8
	8007170403 8007170448 8007170468 8007220269 8007220271*	50-295 50-295 50-295 50-265 50-265	P P B S	Computer Data Systems. Inc Computer Systems Support Corp Consip.Inc . Delphi Systems Div Congress (Joint & Rotating Committees, etc.)	8007180171* 8007170170* 8007180255 8007240117*	CONTRACT CONTRACT PT21 FOIA	•
	8009220274 8009220278* 8009220281 8009220287* 8009220293	50-304 50-304 50-295 50-295 50-10	8 8 8 8	Connecticut Yankee Atomic Power Co	8007020015 8007020016* 8007020231 8007030378 8007030641 8007030646*	50-213 50-213 50-213 50-213 50-213 50-213	0 0 0 0 0
	8007220347 8007220352* 8007230463 8007230466* 8007230570	50-295 50-295 50-10 50-10 50-322	5 9 P A		80070403B0 8007110474 8007120247 8007120257 8007180175	50-213 50-213 50-213 50-213 50-213	R Q P R
	8009230672 8009230676 8009230681 8009230684* 8009230687+	TOPREP 50-237 50-304 TOPREP 50-237	s s		8009180180* 8009180357 8009180357 8009230821 8009230821	50-213 50-213 50-213 50-213 50-213	8 P P P
	8009230704* 8009230713 8009230720* 8009230720* 8009230720*	50-304 50-10 50-10 50-10 50-10	6 R R R		8009290354* 8009290358* 8009290362* 8009290367*	50-213 50-213 50-213 50-213 50-213	ե 1 1 1 1 1
	8007240555 8007240555 8007240555 8007250272 8007250272	50-10 50-10 50-10 50-10 50-10	а С		8007270372* 8007270372* 8007270377* 8007270377* 8007270381*	50-213 50-213 50-213 50-213	5 5 6 6
	8007250344* 8007250468 8007250468 8007250468 8007250468	50-275 50-373 50-373 50-373 50-373	Q Q Q		8007270381* 8007270384* 8007270384* 8007270387* 8007270387*	50-213 50-213 50-213 50-213 50-213	6 6 6
	8007250468 8007250468 8007250504 8007250504 8007250504	50-373 50-373 50-237 50-237 50-237	a a a a	Connecticut. Btate of Conner, Moore & Corber	8009190103 8009260478 8009050272 8009230027 8009300016	PR 50-213 50-358 50-358 50-358	P 0 0
	8007260107 8007260107 8007260107 8007260107 8007260107	50-10 50-10 50-10 50-10 50-10	a a e o	Canoco Coel Development Ca Cansolideted Edison Co of New York	8009300119* 8009150158 8009030382 8009030382	FOIA 40-8743 50-3 50-3	R R

AUTHOR AFFILI <b>ATIO</b> N	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGOR	
	8007030382 8007030386* 8007030386* 8007030386* 8007030458	50-3 50-3 50-3 50-3 50-247	R R R R		8009120462* 8009120533 8009150344* 8009160370 8009160642	50-255 REGGD 50-155 50-255 50-413	R Q R Q
	8009030559 8009030610 8009030610 8009030616 8009030618*	50-247 50-3 50-3 50-247 50-247	P S P P		8009170045 8009170259 8009170259 8009180102 8009180292	FOIA 50-329 50-329 50-155 50-255	A A D
	8009080329 8009090242 8009090383 8009090383 8009090383	50-247 50-3 50-3 50-3 50-3	Р 9 Р		8009190098 8009190101* 8009190103* 8009190124* 8009190129*	50-155 50-155 50-155 50-155 50-155	8 8 8 8
	8009090423 8009090484 8009090506 8009120167 8009120353	50-3 50-247 50-247 50-3 50-247	G P G S		8009190218 8009190221* 8009190420 8009190661 8009220216*	50-329 50-329 50-329 PRM 50-155	K Q Q
	9007120381* 9007160365 9007160367* 9007230432 9007230432	50-247 50-247 50-247 50-3 50-3	\$ 8 8 R R		8009220217* 8009220218* 8009220238 8009220238 8009220285	50-155 50-155 50-329 50-329 50-255	Q
	8007230432 8007230433* 8007230433* 8007230433* 8007230451	50-3 50-3 50-3 50-3 50-247	R R R P		8007220287* 8007230110 8007230275 8007230436 8007230440	50-255 50-329 50-329 50-255 50-255	8 9 8 P
	8009230568 8009230571# 8009240452 8009240452 8009240452	50-247 50-247 50-3 50-3 50-3	R R R R		8007230443 8007230458 8007230512 8007230550 8007230550	50-155 50-255 50-255 50-329 50-329	J P R A
	8009250266 8009250266 8009300384 8009300481 8009300524	50-3 50-3 50-247 50-247 50-247	P P P S		8007230557* 8007230557* 8007230562* 8007230612 8007230618*	50-329 50-329 50-329 50-255 50-255	A A S S
Consumers Power Go	8009300530* 8008080297 8008190405 8009020070 8009020077*	50-247 50-329 50-329 50-155 50-155	888		8007250268 8007250268 8007250278 8007250277* 8007250284	50-329 50-329 50-155 50-155 50-329	8 8 8 8 8 8
	8007020262 8007020265 8007020271* 8007020343* 8007030117*	50-255 50-155 50-155 50-155 50-255	0 8 8 0		8009250284 8009260002* 8009260125 8009260146 8009260266	50-329 50-329 50-155 50-155 50-369	B Q Q
	8007030430 8007030470 8007030544 8007030547* 8007030583	50-255 50-155 50-155 50-155 50-255	8 8 8		8009260266 8009260273 8009260273 8009260488 8009260492*	50-369 50-369 50-369 50-255 50-255	G G B B
	8007030594* 8007030624 8007030627* 8007030718 8007040275	50-255 50-255 50-255 50-327 50-327	5 G G R		8007260496# 8007270360 8007270360 8007270364 8007270368	50-255 50-329 50-329 50-255 50-329	8 6 7 8
	8009040423 8009040423 8009080406 8009080414* 8009080418	50-155 50-155 50-255 50-255 50-255	P		8009290348 8009290475* 8009300023 8009300023 8009300231	50-327 50-329 50-329 50-329 50-155	A Q Q Q P
	8009080426* 8009080432 8009080437* 8009090397 8009090458	50-255 50-255 50-255 50-329 50-155	8 8 8		8007300484 8007300487* 8007300472 8007300477* 8007300507	50-255 50-255 50-255 50-255 50-329	9 8 8 8
	8009090474# 8009090500 8009090500 8009090511# 8009090511#	50-155 50-329 50-329 50-329 50-329	8 A A A	Contra Costa Industrial X-Ray Co Control Data Corp Cooper Industries, Inc., Cooper - Bessamer Co Div. Cooper Industries, Inc., Cooper En	8009300507 8009090093 8009020185 8009290398*	50-327 71-7033 FOIA 50-382 50-382	A 8
	8009090548 8009100521 8009100573 8009100574 8009110428	50-255 50-155 50-155 50-155 50-255	G Р Р	Services Div  Cornell Univ	8007270401# 8007020355 8007230649 8007230652#	NUREO 50-157 50-157 50-157	P P
	8009110730* 8009110820* 8009120384 8009120388* 8009120457	50-255 50-155 50-255 50-255 50-255	G G S S R	Cotter Corp	8009230659* 8009230668* 8009230668* 8009150557	50-157 50-157 50-157 40-8692	P P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR AFFILIATION	ACCESSI NUMBER		
Coulse Region Energy Coalition	8007230001 8007230002* 8007230004* 8007260672 8007260677*	50-409 50-409 50-409 50-409 50-409	0 0 0		50090200 80090200 80090200 80090200	44 50-269 47* 50-269 47* 50-269	R R R R
Council on Environmental Guality Covington & Hurling Crears, Inc	8009070798* 8009240550* 8009170162 8009300474 8009160198	50~367 50~275 50~389 50~250 NUREQ	о о н н		80070201 80070202 80070203 80070203 80070301	11 50-488 71 50-369 71 50-369	Q Q A A Q
Cosherland County, PA Dide County, F1 Distallmen Associates, Inc Dairyland Power Cooperative	8007070380 8007270180 8007240271 8007020041 8007030237	50~320 50~250 RES 50~407 50~409	ਜ © © P		80070304 80070304 80070304 80070304 80070305	47* 50-269 68 50-270 74* 50-270	9 9 9 8
	8007030243* 8007030454 8007030457* 8007070008 8007070010	50~409 50~409 50~409 50~409 50~409	F 8 8 9 9		80090305 80090306 80090306 80090306 80090403	05 50-269 05 50-269 05 50-269	P Q Q Q 8
	8009090336 8009090529 8009160250 8009160253* 8009220145	50-409 50-409 50-409 50-409 50-409	G P R R		80070403 80070406 80070500 80070500 80070505	40 50-269 86 50-369 87* 50-369	9 0 0
	6009230648 6009230657# 8009230664# 6009240343 6009240350#	50~409 50~409 50~409 50~409 50~409	9 9 9 9		80090803 80090803 80090905 80090905 80090905	12 50-413 77 50-249 77 50-269	8 9 R R
Danes & Hoore	8007260157 8007260630 8007260636* 6007300008 8007020077*	50-409 50-409 50-409 50-409 50-483	G S S C A		80070705 80070705 80070705 80071004 80071004	92* 50-269 92* 50-269 99 50-269	R R P P
Cartamuth College Cata Consultants Inc Cawn Mining Co	8007120403 8007270171* 8007260480* 8007180150* 8007270477	40-B084 50-170 CONTRAC CONTRAC WASTE MO	Ť		80091004 80091008 80091008 80091008 80091102	07* 50-269 07* 50-269 07* 50-269	Р G G
Dibevolse & Liberman	8007270501* 8007050086 8007110048 8007110781 8007170141	WABTE MG 50-369 50-445 50-445 50-445	9T G G G		80071103 80071103 80071104 80071104 80071104	45 50-369 23 50-413 59 50-269	A G G
	8007170141 8007170369* 8007230005 8007260010 8007260266	50-445 50-445 50-445 50-369 50-369	0 M G G		80071106: 80071202 80071202 80071204 80071204	12 50-488 52 50-370 14 50-269	9 9
	8009260266 8009260273 8009260273 8009290028 8009300009	50-369 50-369 50-369 50-488 50-395	0 0 0		80071204: 80071204: 80071205: 80071205: 80071205:	36* 50-249 76 50-489 37 50-413	8 9 9
Defense, Dept. of. Defense Intelligence Agency Defense, Dept of. Defense Nuclear Agency	8009290168 8009030450 8009030452* 8009190195 8009190199*	50-170 50-170 50-170 50-170 50-170	F F V V		80091205 80091205 80091503 80091503 80091504	78 50-349 59* 50-370 33 50-287	0 0 8 A
Del Mar Technical Associates Delaware, Btate of Detroit Edison Go	8009290359 8009160231* 8009100446 8009030602 8009040455	50-170 50-205 PR 50-341 50-341	P P A		80091504: 80091505/ 80091602/ 80091604; 800916048	IB 50-349 51 50-349 77 50-249	A A 8
	8007090417 8007160417 8007180016 8007180027 8007240307#	50-341 50-341 50-341 50-341 50-341	G S G G		80091405 80091405 80091405 800914060 800914060	11* 50-269 11* 50-269 50-369 13 50-369	9 9 4 9
Dot - Search Associates Doggett, S. A.	8009240509* 8009240513* 8009250446 8009110339 8009160527	50-341 50-341 50-341 FOIA 50-466	A A Q		800917023 800917037 800918033 800918033	71 50-413 22 50-369 22 50-369 27 50-369	G G A A
Dougherty, J B Dow Chemical Co Bravo Corp Dubm Power Co	8007230013 8007220137 8007140486 8007020025 8007020027	50-280 Toprep Wabte M9 50-249 50-349	0 P P F		800918035 800918037 800918034 800918044 800919039	76 50-369 75 50-297 79 50-287 79 50-369	A 8 8 A A
	8007020027 8007020033* 8007020033* 8007020044	50-369 50-369 50-369 50-269	F F R		80071703 80071703 80071704 80071704 80071704	79 50-369 24 50-269 24 50-269	******

AUTHOR AFFILIATION	ACCESSION NUMBER	GUBJEC	DRY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEOD	
	8007190462 8009190462 8009190462 8009190473# 8009190473#	50-269 50-269 50-269 50-269 50-269			8009240450 8009240456* 8009240458* 8009240461* 8009250251	50-334 50-334 50-334 50-334 50-334	8 8 8
	8009190473* 8009190506 8009190506 8009230496 8009230504*	50-249 50-349 50-369 50-270 50-270	R A A S S		8007290251 8009290257* 8007300359 8007300390 8007300412	50-334 50-334 50-334 NUREG 50-334	S 8 P S
	8004230507 8004230517* 8004230724 8004240204* 8004240212*	50-270 50-270 50-269 50-369 50-369	S S P G	E I du Pont de Namours & Co , Inc EDS Nuclear, Inc EO&G Idaho, Inc	8009120540 8009090088 8009030010 8009050399 8009050405	RE00D 50-263 RE8 RE8 RE8	Q
	8009240220* 8009240262* 8009240290* 8009240290* 8009240297*	50-369 50-370 50-413 50-413 50-413	G G G G	,	8009100412 8009100520 8009100530 8009120579 8009120639	RE8 839 839 839 849 80-215	P
	8009240297* 8009240298* 8009240409 8009240448 8009240448	50-413 50-413 50-369 50-369 50-369	G G A V		8009120666 8009180309 8009190768 8009240069 8009260075	839 30-334 839 839 839	ρ
	8009240481 8009240489 8009240489 8009250191 8009250339	50-369 50-369 50-369 50-369 80-413	S A A Q Q		8007260084 8007260077 8007260110 8007260520 8007260542	50-314 REB 50-263 50-315 REB	Р Р
	8009240010 8009240010 8009240450 8009240455* 8009290028	50-369 50-369 50-287 50-287 50-488	០ ០ ន ន ០	EC&G. Inc Earth Sciences Associates Eaton Corp Cutler-Hammer Products Div	8009260558 8009260568 8009020366 8009060256* 8009260018	RES 50-315 50-312 50-70 50-440	P P P
	8007270303 8007270371 8007270371 8007300157 8007300428	50-369 50-369 50-369 50-369 50-269	A A G J	Gberline Instrument Gorp Eckert, Beamans, Cherin & Mellott Edison Electric Institute	8009190123* 8009110028 8009050434 8009220219 8009230644	40-2061 XPORTLI PR NUREO PR	
	8009300428 8009300428 8009300434 8009300486 8009300486	50-269 50-269 50-369 50-269 50-269	J A P P	Edlow International Co	9007070657 8009170245 8009230749 8009270187 8009390668	XPORTLI XPORTLI XPORTLI XPORTLI XPORTLI	C C
	8009300486 8009300543 8009300547 8009300626* 8009300426*	50-269 50-334 50-311 50-269 50-269	P 3 0 0	Eichhorn,Eichhorn & Link	8009040281 8009080509 8009080511 8009110808 8009190039	50-367 50-367 50-367 50-367 50-367	0
Buquesne Light Co	8007300626* 8007030370 8007030375* 8007050250 8007050254*	50-269 50-334 50-334 50-334 50-334	Q R R S S	Electric Power Research Institute	8007230035 8007300025 8007300576 8007110256* 8007110433*	50-367 50-367 50-367 CONTRAC 50-338	о О Ф
	8007080307 8007090114 8007070248 8007070374 8007070405	50-334 50-334 50-412 50-334 50-334	G G G P	Elfreth Alley Apothacary Energy Fuels Nuclear, Inc	8006240527 8009100666 8009170127 8009300237 8009300409	Docket : 40-8681 40-8681 40-8681 40-8681	
	8007070412# 8007100389# 8007100407 8007120377 8007120386#	50-334 50-334 50-334 50-334 50-334	P O P S S	Energy Incorporated Energy, Dept of	8007240667 8007300236* 8007050R05 8007050207* 8007050412*	NUREG 50-155 71-9508 71-9508 FOIA	
	8009150393 8009140309 8009140311* 8009140313* 8009140405	50-334 50-334 50-334 50-334 50-334	8 8 8 8 8 8 8	•	8007070547 8007100074* 8007100570 8007150241* 8007170527	50-537 50-289 PR 50-320 PR	В Н
	8009160411* 8009160444 8009160451* 8009160470 8009160472*	50-334 50-334 50-334 50-334 50-334	5 5 6 8		8009190762 8009220046 8009240563 8009300306* 8009300306*	WASTE M WASTE M PR 50-275 50-275	
	8009180188 8009180194* 8009190446 8009190500 8009230263	50-334 50-334 50-334 50-334 50-334	R R R 8 9 P	Energy, Dept of, Clinch River Breeder Reactor Plant Engineering Decision Analysis Company,	8007020002 8007020003* 8007020014 8007070575 8007180477*	50-537 50-537 50-537 50-537 50-70	B A B ያ
	8009230257* 8009230454 8009230593 8009230501 8009230711	50-334 50-334 50-334 50-334 50-334	ь ь ь	Inc. Environmental Coalition on Nuclear Power	8009120348 8009120374* 8009120379*	PR PR PR	

AUTHOR AFFIL LATION	ACCESSION NUMBER	SUBJECT CATEGORY		AVTHOR AFFIL LATION	ACCESSION NUMBER	SUBJECT	
Environmental Defense Fund Environmental Protection Agency	8009260666 8009300010 8009240070* 8009170144 8009190775*		0 0		8009140378 8009140378 8009140378 8009140439 8009170279	50-250 50-250 50-250 50-250 50-250	P P Q R
Eurapeen Communities, Commission of	8009300218 8009110359 8009110364 8009110580 8009190258	40-2061 XPORTLIC XPORTLIC XPORTLIC XPORTLIC			6009170279 6009170279 8009170281* 8009170281* 8009170281*	50-250 50-250 50-250 50-250 50-250	R R R R
Essan Carp Essan Nuclear Ca . Inc (subs of Exxon Carp )	8009240184 8009040473 8009040475* 8009040490	71-9022 70-1257 70-1257 50-335	P		8009170374 8009180444 8009190137 8009190206 8009190206	50-335 50-335 50-335 50-250 50-250	0 P P P
	8009110278 8009110718 8009160523 8009180099* 8009260105 8009260117*	70-1257 70-1257 70-1257 94999 71-6581 71-4581			8009190209* 8009190209* 8009230306 8009240174 8009240412	50-250 50-250 50-335 50-387 50-250	P P Q Q
	6009260477 6009260462* 6009260467* 8009260493* 6009260498*	TOPREP TOPREP TOPREP TOPREP TOPREP			8007250207 8007270343 8007270343 8007300040 8007300127	50-250 50-250 50-250 50-387 50-250	6 6 6
Federal American Partners	8009260504+ 8009100654 8009100657+ 8009110266 8009170234	TOPREP 40-4492 40-4492 40-4492 40-4492			8009300129 8009300152 8009300177 8009300177 8009300372	50-250 50-335 50-250 50-250 50-335	6 6 6
Federal Emergency Management Agency Flatman.C A Flatschater. D 8	8007080397 8007160388 8007150075* 8007160234 8007220262	State Pro 50-395 50-250 50-275	g c o o		8009300476 8009300482 8009300485* 8009300490 8009300494*	50-250 50-335 50-335 50-250 50-250	X 8 8 8 8
Florida Cities	8007240544 8007170162 8007170071 8007170071 8007220222*	50-275 50-389 50-335 50-335	- 	Florida Power Corp	8009020197 8009030200 8009030206* 8009030230 8009030475	50-302 50-302 50-302 50-302 50-302	S R F S
Florids Power & Light Co	8007220223* 8007270624 8007270625* 8007020077*	50-389 50-335 50-335 50-250	<del>1</del> <del>-</del> - -		8009030492* 8009030497 8009030503* 8009030600 8009030609*	50-302 50-302 50-302 50-302 50-302	5 5 8
	8007020175 8007020175 8007020175 8007020304 8007020345	50-250 50-250 50-335 50-335	) ) )		8007050265 8007050268* 8007070278 8007070442 8007100733	50-302 50-302 50-302 50-302 50-302	5 9 P 0
	8007020372* 8007030236 8007030300 8007030300 8007030633	50-250 ( 50-250 ( 50-250 ( 50-287 (	1 2 4		8009110337 8009110342* 8009150280 8009150282* 8009160639	50-302 50-302 50-302 50-302 50-250	6 8 8 0
	8007070257 8007070270 8007070270 8007070306* 8007070311*	50-250   50-250   50-250   50-250	₹ ₹		8009170288 8009170289* 8009180285 8009190786 8009220361	50-302 50-302 50-302 50-302 50-302	P F G R
	8009090311* 8009100585 8009110166* 8009110693 8009110853	50-387 ( 50-250 (			8009220365* 8009240184* 8009240628* 8009290290 8009290306*	50-302 50-302 50-302 50-302 50-302	R G P S S
	8009110853 8009120307 8009120312 8009120313 8009120315*	50-335 ( 50-335 ( 50-251 ( 50-251 (	1 3 3 3	Florida Rural Legal Services, Inc Florida, Univ of, Gainesville Fluor Power Service, Inc	8009300143 8009300624 8009160389 8009190211* 8009300398	50-302 FOIA 50-63 MISC NUREG	Q P
	8009120316* 8009120318* 8009120350 8009120385* 8009120491*	50-335 5 50-250 5 50-250 5 50-250 6		Fox industries Fox. Farr & Cunningham Frankhauser,D D Franklin Institute/Franklin Research Center	8009300394 8009040278 8009030693 8009020148*	TOPREP 50-287 50-358 50-331	G G P
	8009120520# 8009120671 8009120671	50-250 ( 50-250 ( 50-250 ( 50-335 (	) )		8007020463* 8007020467* 8007020470* 8007020473*	50-10 50-10 50-10	Р Р
	8007150251 8007150262 8007150288 8007150270+	50-335 6 50-335 6			8009020474* 8009040103* 8009040129*	50-10 50-155 50-263	P P
	8007160033 8007160041# 8007160200	50-355 F 50-355 F	f 1		B009040315# B009040544# B009050456#	50-324 50-271 50-273	P P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCEBSION NUMBER	BUBJECT CATEODS	ŔY
	8009050501* 8009150426* 8009170240*	50-29 50-317 50-333	P P	General Public Utilities - GPU Service Corp	8009230472 8009090608*	TOPREP 50-269	1
Friends of the Earth	8009170402* 8009180217* 8009100406	50-220 50-336 50-361	P P		8007110328 8007110330* 8007160357	50-320 50-320	P P P
Gary, IN	8007110397* 8007030147 8007030152* 800703027*	50-361 50-367 50-367 50-367	0		8009160361* 8009170265 8009180370 8009240541 8009300550	50-320 50-320 50-289 50-320	P P I P
Gasser Associates	8007070433* 8007070435* 8007110222*	50-367 50-367 CONTRACT CONTRACT		George B. Bush & Co	8009040505 8009300220	50~287 50~289 XPORTLIC	R R C
General Atomic Co (subs of Gulf Dil Co )	8009260242* 8009120697	50-295	S	George Uhe Co . Inc Georgia Power Co	800702013 8007260068 8007020180	XPORTLIC XPORTLIC 50-321	C
Onneral Atomic Co (subs of Gulf Dil Corp )	8009220321* 8009300088	50-267 XPORTLIC	• •		8007020180 8007020287 8007020362	50-321 50-321 50-366	0 0 8
General Dynamics Corp Electric Boat Div General Electric Co	8009170136 8009020023 8009020412*	71-6717 NUREO 50-296	p		8009020367* 8009020369	50-366 50-366	9
	8009030557 8009030578 8009030639 8009040255 8009050325	TOPREP 70-1308 50-70 50-70 TOPREP	P P		9007020374* 9007020373 8007020373 8007020400 9007020404	50-364 50-321 50-321 50-366 50-321	8 9 8 8
	8007050328* 8007050363 8007050365* 8007050454 8007050457	TOPREP TOPREP TOPREP 70-2786 70-1308			8007020405* 8007020414* 8007020419 8007020433* 8007020436	50-366 50-321 50-366 50-366 50-321	9 8 9 8
	8009090874 8009100032 8009100061# 8009110161# 8009110225	70-1201 XPORTLIC CONTRACT 70-1113 70-754			8007020437 8007020444* 8007020446* 8007020461 8007020467*	50-321 50-321 50-321 50-321 50-321	6 6 8 8
	8009110227 8009110273 8009110279 8009110436 8009110443*	70-754 XPORTLIC 70-754 TOPREP TOPREP			8009030418 8009030418 8009030419* 8009030419* 8009030442	50-321 50-321 50-321 50-321 50-364	R R R 8
	8007110488 8007110763 8007120089 8009160192 8009160278	70-1308 70-2786 70-754 TOPREP XPORTLIC			8007030447* 8007030451 8007030461* 8007030484 8007030487	50-366 50-366 50-366 50-321 50-424	8 8 F 9
	8007160366 8007160420 8007160424 8007160436* 8007180474	TOPREP 50-201 TOPREP TOPREP 50-70	G P		8009030489 8009040458 8009040458 8009040635 8009040635	50-424 50-424 50-424 50-424 50-424	8 8 9 0
	8009180509 8009190751 8009230308 8009230431* 8009230475*	70-1007 70-754 TOPREP TOPREP TOPREP			8009040637 8009040637 8009030076 8009030291 8009090428	50-424 50-424 50-321 50-321 50-366	0 0 V 8
	8007240580 8007240703 8007250245 8007250051 8007260106	70-2786 71-5926 50-70 71-5998 71-5971	Р		800909043B* 8009090443 8009090460* 8009090469 8009090480*	50-366 50-321 50-321 50-321 50-321	8 8 8 8
	8009260391 8009260466 8009260581 8009300227 8009300302*	71-9049 71-4400	P P		8007070486 8007070475* 8007100416 8007110671 8007110676	50-366 50-366 50-424 50-321 50-321	8 9 8
	8009300307* 8009300477 8009300483* 8009300585* 8009300586*	50-245 TOPREP TOPREP 70-1308 70-1308	P		8009110474 8009110828# 8009150142 8009150281 8009150283#	50-321 50-321 50-321 50-321 50-321	0 0 8 8
General Electric Co., Nuclear Energy Products Div.	8009030505		P		8009150291 8009150294# 8009150295	50-321 50-321 50-321	9 8 8
	8007030417# 8007030417# 8007030417# 8007070866	71-9019 71-9019 71-9019			8007150278* 8007150331	50-321 50-366	8
	8007170865 8007110830 8007150001 8007150601 8007170111	70-1113 XPORTLIC 71-5980 70-1113 70-1113			8009150335# 8009150382 8009150384 8009150385# 8009150386#	50-366 50-321 50-321 50-321 50-321	8 8 8 8
Coneral Electric Operating Plant Owners Group	800923030B 8009230430	TOPREP			8009160288 8009160306# 8009160448 8009160448	50-366 50-364 50-321 50-321	8 6 F

AUTHOR AFTIR TATTON	ACCEBBION NUMBER	TODUCUB CATEGOR	Υ	AUTHOR AFFILIATION	ACCESSION NUMBER	GUBJECT CATEGORY
	8007180179 8007180208* 8007180478 8007180478	50~321 50~321 50~366 50~366 50~321	R R R R	Hoke, Inc Honeywell, Inc House of Rep	8007120405 8007030497 8007030498* 8007020217* 8007020323*	XPORTLIC XPORTLIC XPORTLIC COMMISSION 50-320 H
	0009190423 0009190428# 0009190432# 0009190432# 0009190493	80-921 80-921 80-921 80-921 80-424	ម ក ក ម		8009080346 8009090570 8009110267 8009110418* 8009110491*	50-287 U 50-320 U 70-820 COMMISSION 50-320 U
	009220133 001022008 001022008 001022008 31E022008	50-424 50-424 50-521 50-321 50-366	0 0 0 0 8		8009110520* 8009170268 8009170383 8009180560* 8009230442*	50-275 U 50-466 U 50-446 U 50-320 H 50-289 H
	8009240367 8009240367 8009240369 8009240369 8009270276	50-321 50-321 50-424 50-424 50-366	8 0 0	House of Rep , Foreign Affairs House of Rep , Interstate & Foreign	8009240485 8009260205 8009260652* 8009110288* 8009100108*	50-466 U 50-320 H 50-201 G 50-320 H COMMISSION
	0007290201# 0007300104 0007300104 0007300110 0007300477	50-366 50-321 50-321 50-424 50-321	6 0 0 8	Commerce House of Rep , Merchant Harine & Fisheries Stouse of Rep , Science & Technology House of Rep , Hays and Heane	8009150182 8009120494* 8009020156*	PR COMMISSION 50-320 H
b	8009300502# 8009300519	50~321 50~3&&	8		8009110319* 8009110322*	50-320 H 50-320 H
Quorgia, State of	0007300524# 0007100077# 0007120075#	50-344 Blate Pr CONTRACT CONTRACT	-	Hoveton Lighting & Power Co	8007020288 8007020288 8007020270 8007020270 8007030170*	50-498 8 50-498 8 50-498 8 50-498 8 50-498 Q
Quotechnical Ingineers Inc Cetty Dil Co , Petrotomics Co Div	H004100555* B004100515* B004100044 B00B0B01B4	40-6659 40-6659 40-6659 40-6659			8007040271 8007040287 8007040377 8007040377	50-466 G 50-445 M 50-478 S 50-478 S
gibbs & Hill: Inc. (subs. of Drave Gorp.	#862220000 #462222000 #462222000 #462222000 #462222000	50 - 445 50 445 50 445 50 445 50 445	A A A		8007050364 8007050364 8007080201 8007080201 8007110367	50-498 9 50-498 A 50-498 A 50-498 B
	8007220386* 8007220386* 8007220386*	50445 50445 50445 50445 50445	^ ^ ^		8007110367 8007110384 8007150254* 8007150557 8007150557	50-498 8 50-498 8 50-466 0 50-498 K 50-498 K
	0009220383# 8009220383# 8009220383# 8009220383#	50-445 50-445 50-445 50-445 50-445	A A A		8007150361* 8007150361* 8007160157 8007160157 8007160157	50-498 K 50-498 K 50-445 M 50-445 M 50-445 M
	8009220387# 8009220387# 8009220392# 8009220392# 8009220393#	50-445 50-445 50-445 50-445 50-445	^ ^ ^		8007140140* 8007140160* 8007140201 8007180461 8007180467	50-445 M 50-445 M 50-466 G 50-498 G 50-498 G
Gilbert/Gommonwealth Gos.	6007220373# 6007150223# 6007150226# 6007150226# 8007140270	50 -445 QA799 QA999 QA999 50-440	K		8007180473 8007180475 8007180479 8007180479 8007190147	50-478 Q 50-466 Q 50-478 S 50-478 B 50-478 S
Greater Southeast Community Hosp Maskington, D.C.	8009230147#	70-1417			9009190147 9009230402	50-498 8 50-498 8
Oulf & Mestern Industries, Inc Oulf States Utilities Co.	0009100219# 0009050522# 0009090409 0009090502	0A799 50-458 50-458 50-458	Q A F		8007230603 8007230603 8007230617 8007230617	50-478 8 50-478 8 50-478 8 50-478 8
Quiman, Peter FRG, Dept. of, US Public Health Service	8009280412 8009290326# 8009300086 8009180143# 8009170130	50-450 50-459 50-459 CONTRACT 40-9745	a o o r		8007230458 8007230458 8007240437 8007250054 8007250054	50-498 9 50-498 9 50-498 9 50-498 K 50-498 K
FMH Associates, Inc Flanford Engineering Development	6009050302*	50-029 RES	F		8009260210# 8009300027	50~466 Q 50~466 Q
Laboratory Hazlaton Laboratories, Inc	8009090020 8009260284*	NUREQ 50-276	R		8007300161 8007300453 8007300467	50~498 B 50~498 B 50~466 Q
Health & Human Bervices, Dept of Hill Christopher & Philises	8009030258 8009110019 8009150404 8009190629	40-8745 50-275 50-275 FOIA 50-275	0		8009300536 8009300545 8009300545 8009300555 8009170194	50-498 G 50-498 G 50-498 G 50-498 G 50-516 G
Hittman Nuclear & Development Corp. (subs Hittman Corp.)	8009230616 8009030478#	80-299	F	Hunton & Williams Mydro-Enginearing	8008080173#	40-6659
Hjalmfult.D.C. Hodder, H. II	8007260462 8007150075*	50-248 50-250	H O	Hydrology Associates, Inc.	8009130378# 8009130378#	46-8502

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	
YTERA Environmental Consultants.Inc RT Corp Linnis Power Co	8007020349 8007240069* 8007020341 8007040491 8007080173	NUREQ CONTRAC 50-461 50-461	A A A	Illinois, Univ of, Urbana∼Champaign	8007240021 8007120411 8007120414* 8007150454 8007150441*	40-2061 70-258 70-258 50-356 50-356	R
	8009080193 8009080197* 8009080202 8009080202 8009080209*	50-461 50-461 50-461 50-461 50-461	A C C	Indiana & Michigan Electric Co	8007230777* 9007020232* 8007110310 8007110310 8007110326	CONTRAC 50-315 50-315 50-315 50-315	T Q R R
,	8007080207* 8007080211* 8007080211* 8007080347 8007070254	50-461 50-461 50-461 50-461 50-461	С С Н К		8007110348* 8007150323 8007150328* 8007140175 8007140273	50-315 50-315 50-315 50-315 50-315	8 8 0 R
	8007070254 8007070258* 8007070258* 8007070262 8007070262	50-461 50-461 50-461 50-461 50-461	K K K K	:	3009140277* 3009140280 3009160283* 3009170350 3009190517	50-315 50-316 50-316 50-315 50-316	R R R V
	8007070266 8007070266 8007070267 8007070267 8007070272	50-461 50-461 50-461 50-461 50-461	***		3007170522* 3007240367 3007260074 3007260074 3007260212	50-316 50-315 50-315 50-315 50-315	9 0 0
	8007070272 8007070276 8007070276 8007070277 8007070277	50-461 50-461 50-461 50-461 50-461	K K K	E Indiana & Michigan Power Co	3009290444* 3009300510 3009300517* 3009090501	50-315 50-315 50-315 50-315 50-315	0 8 8 8
	8007070283 8007070283 8007070286 8007070286 8007070289	50-461 50-461 50-461 50-461 50-461	KKKK	Indiana Univ	009190503 009190509* 009250373* 009050492	50-315 50-315 50-315 FDIA CONTRACT	9 8 9
	8009090289 8009090293 8009090293 8009090296 8009090296	50-461 50-461 50-461 50-461 50-461	х к к к	Interior, Dept of	8009040485 8009260468* 8009030314* 8009170139 8009190676*	NUREQ 50-237 50-387 40-8681 FOIA	P A
	8007070297 8007070297 8007070301 8007070301 8007070304	50-461 50-461 50-461 50-461	К К Ж Ж	Intermountain Testing Co International Business Services, Inc	009160363* 009300646 009040115 009300097* 009120115*	50-275 NUREG PR CONTRACT CONTRACT	
	8007070304 8007070307 8007070307 8007070310 8007070310	50-461 50-461 50-461 50-461 50-461	K K K K	6 8	009020170 009020289 009030466 009030471* 1009040424	50-331 50-331 50-331 50-331 50-331	0 Р В В
	8009090313 8009090313 8009090317 8009090317 8009090321	50-461 50-461 50-461 50-461 50-461	K K K K	8 8	009090026 009120555 009170061 009170315 009170320*	50-331 50-331 50-331 50-331 50-331	G G B
	8007070321 8007070323 8007070323 8007070808 8007100830*	50-461 50-461 50-461 50-461 50-461	а К К	8 8	009170324 009170328* 009170333 009170348 009170352*	50-331 50-331 50-331 50-331 50-331	8 9 9 8
	8009100833* 8009110431 8009180575 8009190513 8009220130	50-461 50-461 50-461 50-461 50-461	Q Q A A A	8 9	009170355 009170360* 009170363 009170367* 009170409	50-331 50-331 50-331 50-331 50-331	8 8 6
linois, State of	8007240457 8007250208# 8007250457 8007270337 8007020048	50-461 50-461 50-461 50-461 50-367	K G G S	8 9	009170427 009180389 009190499 009190504* 009190533	50-931 50-331 50-331 50-331 50-331	G F R P
	6007020084 6007040200 6007040200 6007040208* 6007040208*	50-347 50-237 50-237 50-237 50-237	0 0 0 0	8 8	009190541* 009230286 009300493 009300501* 009120012*	50-331 50-331 50-331 50-331 CONTRACT	P P 8 8
	8007040218# 8007040218# 8007050358 8009110783 8009150400	50-237 50-237 40-2041 50-367 50-367	0 0 0	8 8	00903071B 009080256 009090233 009090446 009090471	50-329 FOIA 50-559 50-255 50-295	0
	8007140247 8007140281 8007140403 8007220173 8007220177	50-367 PR 70-1309 50-367 50-367	G G	8 8 8	009110369 009150339 009150344* 009160397 009170177	50-445 50-155 50-155 50-329 50-445	9 0 0 0 1

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	RY	AUTHOR AFFILIATION	ACCESSION HUMBER	BUBJECT CATEGOS	
Island Closeup News Service	8009170369 # 8009220185 8009260002 # 8009300023 8009020505	50-445 50-155 50-329 50-329 FOIA	Н Ф С		8007170232* 8007170232* 8007170239* 8007170364* 8007170364*	50-445 50-445 50-445 50-445 50-445	
Brack Walton League of America, Porter County Chapter	8009030703	50-367	O·		8009180460 8009180460	50-445 50-445	M
	8007030710 8009120392 8009120445# 8009230008	50-347 50-347 50-347 50-347	0 0 0	KMC. Inc	8009180460 8009300021 8009020257	50-445 50-395 TOPREP	M
J E Lonergan Go.	8009230382 8009230393 8009240011 8009180490*	50-367 50-367 50-367 GA997	0	Kaiser Engineers Kansas Qas & Electric Co	8009190779 8009150014 8009150381# 8009290218 8009300612#	40-4492 50-482 50-482 50-482 50-482	0 0 8 0
J. H. Kleinfelder & Associates	8007180475* 8007230161*	GA999 CONTRACT		Kentucky, State of Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp.)	6009100395 6009040099#	50-358 40-2061	0
Jarsey Central Power & Light Co	8009120062 8009190571 8009020087 8009020360	XPORTLIC XPDRTLIC 50-289 50-219		Kerr-McGee Corp ) Kerr-McGee Corp Kerr-McGee Nuclear Corp	8009150377* 8009150233 8009150575	40-8769 70-925 40-8768	
	8007020377 8007020385* 8007020372 8007020378* 8007020421	50-219 50-219 50-219 50-219 50-289	\$ \$ \$ \$	Laudig, 8 Law Engineering Testing Co Lawrence Livermore Laboratory	8009180334 8009300454 8009280057 8009120137* 8009110500	71-82 40-8027 50-367 27-48 NUREG	G
	8007020428 8007030372 8007030431 8007030582 8007050340	50-287 50-289 50-289 50-289 50-219	8 T T I		8009120338 8009120339 8009160498 8009180434 8009180446	NUREG NUREG RES NUREG NUREG	
	8007080332 8007070031 8007070181* 8007070235 8007070351	50-287 50-219 50-219 50-219 50-219	0 0 0 8	LeBosuf, Lamb, Leiby & MacRas	8009290062 8009040413 8009150371 8009180340 8009240502	NUREQ 50-244 FOIA 50-220 50-341	
	8007070353 8007070354 8007070365* 8007070368 8007070371*	50-219 50-219 50-219 50-219 50-219	6 5 8 R R	Literature Research Corp Long Island Lighting Co	8009120462* 8009020425 8009030433 8009030437 8009120123*	CONTRACT 50-322 50-322 50-322 50-322	۲ <u>د</u>
	8009090373* 8009090381* 8009110394 8009110405 8009120179	50-217 50-217 50-287 50-289 50-217	8 G T Q	Los Alamos Ecientífic Laboratory	8007120254 8007120375 8007170174 8007020161 8007050214*	50-222 50-322 50-516 NUREO 71-9508	G G
	8009150252 8009160371 8009160471 8009160474* 8009160510	50-289 50-289 50-219 50-219 50-219	T G H S Q		8007050453 8007100036 8007110503 8007120572 8007120587#	71-9853 NUREC NUREC RES 50-320	₽
	8007170292 8007170421 8007220283 8007230104 8007230434	50-289 50-219 50-219 50-219 50-289	P P Q Q		8009150596 8009150599 8009160492 8009220220 8009300169	NUREG NUREG REB 50-275 50-3	F
	8007230445 8007230447 8007230481 8007230561 8007230564+	50-269 50-289 50-219 50-219 50-219	T G G R R	Louisiana Power & Light Co	8009170368 8009190153 8009190158 8009190491 8009230437	50-382 50-382 50-382 50-382 50-382	g a a H ♠
	8009250270 8009260175 8009260440 8009260447* 8009290357	\$0-287 50-289 50-219 50-219 50-287	T G S I		8009290394 8009290396* 8009300092 8009300100 8009300212	50-362 50-362 50-362 50-362 50-362	8 0 0 4
	8007270365 8007270367* 8007300261 8007300270 8007300404	50-219 50-219 50-219 50-219 50-219	P P P 8	Louisiana, State of Lovelace Biomed & Environmentel Research Institute	8007300338 8007300342 8007070537* 8007100053	50-362 50-362 50-458 NUREO	8 8
	8009300522	50-219	8	Lowenstein, Newman, Reis, Arelrad & Toll	8009020073	50-250 50-444	۰
	8007300528* 8007300541 8007300564 8007300567*	50-219 50-219 50-219 50-219	S 8 8 8		8007040271 8007040281 8007030434 8007080507 8007080511	50-466 50-367 PR 50-367 50-367	90.00
John A. Blume & Associates, Engineers faubs, URS Corp.)	8009020100* 8009120083*	50-206 CONTRACT	P.		8009090791 8009090795+	50-367 50-367	0
John F Holman & Co , Inc Justice, Dept of	8007140287 8007100261 8007160033	50-445 50-445 50-387	м м м		8009090826 8009110808 8009150253	PR 50-347 30-464	. Q
	8007160041* 8007160160* 8007160160*	50-367 50-445 50-445	м м м		8007150256* 8007150463 B007160033	50-466 50-367 50-367	e H

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8007160041 * 8007160148 8007160151 * 8007160201 8007170167	50-389 50-374 50-376 50-466 50-582	 G G G	Merrimack College Metropolitan Edison Co	8007240051# 8007020008 8007020013 8007020037 8007020075	70-710 50-289 50-289 50-320 50-320	P G P
	8009180259 8009180475 8009190039 8009230035 8009230691	50~367 50~466 50~367 50~367 50~466	0 0 0 0		8009020241 8009020273 8009020378 8009020387* 8009030118	50-320 50-289 50-320 50-320 50-320	0 8 8 9
	8007240565 8007260207 8007260210* 8007300027 8007300437	50~466 50~466 50~466 50~466 50~376	0 0 0 0 0		8007030347 8007030361* 8007030372 8007030464 8007030464	50-320 50-320 50-320 50-289 50-289	880
	8009300462 8009300469 8009300476 8009300476 8009300576	50-376 50-466 50-250 50-250 50-367	G G M M G		8007030469* 8007030472 8009030473 8007030481 8007030487*	50-320 50-289	ት ት ት
Luco, J E MHB Technical Associates Sadison Gas & Electric Co	8009090779 8009150424* 8009160284* 8009240546* 8009090358*	50-275 50-206 PR 50-275 50-305	Т Р С Р		8007030527 8007040365 8007050245* 8007030246* 8007050247*	50-269 50-320 50-320 50-320	P 0 8 8 8
ine Yankes Atomic Power Co	8007080528 8007080541 8007090431 8007070468 8007070477*	50-209 50-209 50-209 50-209 50-209	Q Q Q R R		8007050249* 8007050374* 8007080240 8007080240 8007080369	50-320 50-289 50-289	日マママ
	8009100425 8009120207 8009120275 8009160257 8009160259#	50-309 50-309 50-309 50-309 50-309	P G G R R		8009090302 8009090556 8009100431 8009110020 8009110316	50~320 50~287 50~287	H 0 0 R
	8009170343 8009170347* 8009230455 8009230584 8009230591*	50-309 50-309 50-309 50-309 50-309	P P R P		8009110316 8009110318* 8009110333* 8009110340* 8009110344*	50-287 50-289 50-289	R R R R
	8007260474 8007260503* 8007260637 8007260642* 8007300426	50-309 50-309 50-309 50-309 50-309	8 8 8 8 8		8009120341 8009120342* 8009120402 8009120406* 8009120450	50-289 50-320 50-320	8 8 8
Haine, State of Mapleton Intervenurs Marrack D. Marsh & Holennan Inc. H & M Nuclear Consultants, Inc. Div	8009300430* 8009170345 8009050423 8009180416 8009020278	50-309 50-309 50-329 50-466 50-348	R G G J		8009120452# 8009120454 8009150432 8009150554 8009140329	50-320 50-320 50-320	8 P P P
Harubent America Corp (subs of Haruben: Corp )	8007030374 8007070384 8007260460 8007070863	50-327 50-280 50-311 XPORTLIC	J J J		8009160367 8009160381 8009160382 8009160384 8009160395	50-320 50-320 50-320	<b>የ</b> የ የ የ
Massachusætts Institute of Technology	8007030565 8007030567* 8007080178 8007120514* 8007230359*	50-20 50-20 50-20 50-206 CONTRACT	R F F		8009160596 8009170219 8009170291 8009170302 8009170316	50-287 50-287 50-289	H 0 0 P
Massachusetts, State of Massachusetts, Univ of Matheon Gas Products	8007300244* 8007300434 8007100421 8007100651* 8007110600	NUREO 50-471 70-312 XPORTLIC	o o		8009170334 8009170377 8009180404 8009180408* 8009180415	50-320 50-320 50-320	0 8 8
Mayer, Brown & Platt	8009300670 8009090461 8009100325	70-1308 70-1308			8007180426* 8007170470 8007220127 8007220288 8007220271*	50-320 50-320 50-289	8 P R R
McDermott, Will & Emerg	8007160394 8009300580 8009170188 8009300533	70-1308 70-1308 50-445 50-498	н		8007220276 8007220277 8007240538*	50-320 50-320	b b
McGean Chemical Co., Inc McGinnis, Lochridge & Kilgora	8009300542* 8009300112 8009170188 8009300533	50-478 40-8724 50-445 50-478	н н н		8009250017 8009260301 8009260313	50~287 50~287	ë o T
Medinaelectric Cooperative, Inc.	8009300542# 8009170188 8009300533	50-498 50-445 50-498	 Н Н		8007260313 8007260320* 8007260322* 8007260388*	50-289 50-289 50-289	Ť T T
Memorial Bloam-Kettering Cancer Center New York,NY	8007300542* 8007110025*	50-498 Contract	Н		8009260394# 8009260396#	50-289	T T
Memphis State Univ Mentor,KY	8009230771* 8009050333	CONTRACT 50-358	F		8009260400* 8009260407* 8009260411*	50~287	† T

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE	ORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	
	8009260412* 8009260414* 8009260417* 8009260421* 8009260431*	50-267 50-267 50-267 50-267 50-267	T T T		8007160571 8007160571 8007230072 8007230072 8007230372	50-416 50-416 50-416 50-416 50-416	8 0 0 A
	8009260439* 8009260443* 8009300014 8009300020 8009300022	50-287 50-287 50-320 50-287 50-287	T Q Q		8009230471 8009230471 8009230556 8009230595 8009230595	50-416 50-416 50-416 50-416 50-416	9 8 8 9
Michigan Technological Univ Michigan, State of Michigan, Univ of	8009300389 8009300904 8009120033* 8009110350* 8009150225	50-320 50-289 Contra Contra Regod	ET S		8009230627 8009230627 8009230642* 8009240331* 8009240438	50-416 50-416 50-416 50-416 50-416	5 5 6 6 6
Mid-America Legal Foundation Miller・Balis & O'Neil	8009160446 8009220242* 8009220395 8009090331 8009040196	NUREG 50-329 TOPREP 27-39 50-445	A M		8009240438 8009240480 8009240480 8009250417 8009250417	50-416 50-416 50-416 50-416 50-416	8 8 8
	8007300035 8007300035 8007300035 8007300488 8007300488	50-445 50-445 50-445 50-445 50-445	M M M	Mississippi, State of	8009260473 8009260473 8009300029* 8009300437 8009100003*	50-416 50-416 50-416 50-416 Contract	8 9 4
	8007300488 8007300488 8007300476* 8007300476* 8007300476*	50-445 50-445 50-445 50-445 50-445	M M M	Missouria Univ. of: Columbia	8009030212 8009040406 8009040418 8009040419* 8009190594	50-186 50-186 50-186 50-186 71-5088	R S S
Minerals Exploration Co (subs of Union Oil Co. of California) Minnesota Power & Light Co Minnesota, State of	8007300476* 8007030470 8007040487 8007030726	50-445 40-8584 50-416 50-282	н В С	Missouri, Univ of Rolla Mitsubishi International Corp (subs of Mitsubishi Corp )	8009230584 8009090379 8009090403* 8009110602	50-186 50-123 50-123 XPORTLIC	P P
Mississippi Power & Light Co	8007030728± 8007030728± 8007030728± 8007300037 8006270284	50-282 50-282 50-282 50-282 50-416	0 000	Mobile Gystems Monsento Co	8009290257 8009300121 * 8009300062 8009300064 * 8009020041	XPORTLIC CONTRACT XPORTLIC XPORTLIC 50-409	
	8007020064 8007020064 8007020218 8007020272 8007020413 8007020413	50-416 50-416 50-416 50-416 50-416	8 0 0 A	Mudge, Rose, Guthrie & Alexander Municipal Electric Utility Association, Alabama Murray & Trettel, Inc Myer, Bowman, Stroup & Flack	9007070336 8007050451 8007280662 8007030440* 8007300375 8007160475*	50-409 70-1309	ا ا ا
	8007020418# 8007020418# 8007020423# 8007020423# 8007030504	50-416 50-416 50-416 50-416 50-416	A A A H	Bervices NL Industries, Inc NUS Corp National Aeronautics & Space Admin	8007120220* 8007170332 8007170313 8007020431 8007300165*	40-2940	F
	8007050352 8007050352 8007050356* 8007050356* 8007080247 8007080247	50-416 50-416 50-416 50-416 50-416	A A A 8 8	National Nuclear Corp National Becurity Agency National Wildlife Federation	8007070614 8007070617* 8007180327* 8007170376* 8007300004	XPORTLIC XPORTLIC CONTRACT 40-299 50-367	o o
	8007080328 8007080328 8007080374 8007080374 8007100303	50-416 50-416 50-416 50-416 50-416	9 9		8007040258 8007050177 8007160046 8007300004 8007080445*	70-143 70-143 PR 50-367 71-4888	G
	8009100303 8009100335 8009100347 8009100347	50-416 50-416 50-416 50-416	8 8	Navy.Dept of, Naval Facilities Engineers ng Command	8009020522 8009020525* 8009080442 8009150189	71-385 71-385 71-4666 71-112	
	8009100436 8009100436 8009100486 8009100519	50-416 50-416 50-416 50-416	8	Nebraska Public Power District	8009150189* 8009190707 8009020078	71-112 PR 50-298	g g
	8009100558 8009100558 8009100566 8009100592 8009110681	50-416 50-416 50-416 50-416 50-416	8 8 8	,	8009020101 8009020102 8009030551 8009050187 8009050190*	50-278 50-278 50-278 50-278 50-278	0 F 8 8
	8009110681 8009150301 8009150425 8009150425	50-416 50-416 50-416 50-416	Q S A		6009050199 8009050203* 8009050252 8009050255*	50-298 50-298 50-298 50-298	\$ \$ 6
	8009150453 8009150453 8009150489 8009150489 8009160387	50-416 50-416 50-416 50-416 50-416	A K K B		8009030240 8009050264# 8009050284 8009050289# 8009050324	50-298 50-298 50-298 50-298 50-298	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	
	8007050331# 8007100031 8007100044# 8007140262 8007160264#	50-298 50-298 50-298 50-298 50-298	S G G R R		8007070017 8007070636 8007100109 8007100113 8007110245	50-245 50-245 50-336 50-423 50-245	Q Q Q
Nevada, State of	8009170287 8009190478 8009190483* 8009260282 8009190881	50-298 50-298 50-298 50-290 State P	9 9 8 8		8009120197 8009150247 8009180357 8009180445 8009190427	50-245 50-336 50-213 50-336 50-245	6 6 6
New England Coalition on Nuclear Pollution	8009160046	PR			8009190434 8009190456	50-245 50-245	P R
New Jersey, State of New Mexico, State of	8009020089* 8009030162 8009050498* 8009190891	50-289 50-219 50-320 State P	1 T H Tog		8007170457# 8007170460 8007170531#	50-245 50-336 50-336	R S 8
New York, State Univ of, Buffalo New York, State of	8009040374 8009140338 8009140340* 8009020500 8009040250	50-57 50-57 50-57 State P 50-54	P I I G		8009190537* 8009190543* 8009230749 8009240571 8009300239	50-334 50-336 50-245 50-245 50-245	8 Q P
	8009050361 8009050429 8009100077* 8009110492* 8009120019*	State P PR CONTRAC 50-201 CONTRAC	rog T	Northeast Utilities	8007300245* 8007300291 8007070642* 8007110482 8007160457	50-245 50-336 50-245 50-336 50-336	P P 0 8
	8009120549* 8009300525 8009300525 8009300525 8009300525	50-201 70-1432 50-201 70-1432 50-564	P G		8009160461* 8009160464* 8009160469* 8009220330* 8009230345	50-334 50-336 50-336 50-423 50-334	8 8 8 R
New York, State Univ of. (Albany) Newberry Township THI Steering Committee Newberry Township, York Haven, PA	8009300525 8009020481* 8009180436 8009180571 8009040278	50-564 70-2313 50-289 50-289 50-289	0 0 0		8009230347* 8009260649 8009260654* 8009290351 8009300179	50-336 50-336 50-336 50-213 50-336	R 8 8 P
Niagara Mohawk Power Corp	8007020248 8007070264 8007070281 8007070668 8007070848*	50-410 50-220 50-220 50-220 50-410	4 0 0 0 5		8009300183# 8009300239 8009300297 8009300311# 8009300403	50-336 50-245 50-245 50-245 50-423	P P P A
	8009120263 8009120408 8009120413* 8009120417* 8009150265	50-220 50-220 50-220 50-220	Q V V V B	Northern Indiana Public Service Co	8007300443 8007020005 8007020051 8007030434 8007040281	NUREQ 50-367 50-367 50-367 50-367	R R R Q
	8007150266* 8007150277 8007150279* 8007150551 8007160213	50-220 50-220 50-220 50-410 50-220	S R R A		8007080507 8007080511 8007070427 8007070487 8007070775*	50-367 50-367 50-367 50-367 50-367	0 0 R R
	8009160214* 8009160460 8009160467* 8009160508 8009160513	50-220 50-220 50-220 50-220 50-220	R S G G		8009100165 8009110556 8009110569 8009110808 8009150474	50-367 50-367 50-367 50-367 50-367	0 0 0 R
	8007180248 8007180278* 8007180344* 8007180348* 8007220158	50-220 50-220 50-220 50-220 50-220	8 8 P P Q		8009190039 8009230035 8009230259 8009250297 8009300419	50-367 50-367 50-367 50-367 50-367	Q Q R A
	8009230098 8009250331 8009250332* 8009260403 8009300491	50-410 50-220 50-220 50-220 50-220	0 R R P S	Northern States Power Co	8009300421* 8009300446 8009300876 8008200282 8008200282	50-367 50-367 50-367 50-282 50-282	A R O F F
North Carolina State Univ North Carolina, State of	8009300495* 8009300622 8009020352 8009020356* 8009180523	50-220 50-220 50-297 50-297 71-4717	8 G R R		9008200284* 8008200284* 8008260337 8008260340* 8007020007	50-262 50-263 50-263 50-263 50-263	4444
Northcutt Ely Northeast Nuclear Energy Co. (subs of Northeast Utilities)	8009170341 8009020283 8009020283	50-445 50-245 50-245	O R		8007020055 8007020040* 8007020072 8007020074* 8007030380	50-263 50-263 50-282 50-282	FFF
	8007020284 8007020285*	50-245 50-336 50-336	8 9		8009030381	50-243	9 F
	8007020284 8007020377 8007020383* 8007030378 8007030532	50-245 50-245 50-245 50-213 50-213	P 8 P P		8007030401* 8007030524 8007050348 8007050365*	50-263 50-263 50-263 50-263	8 F R R
	8007050103 8007050105* 8007050175	50-336 50-336 50-336	P P		8007080401* 8007090019 8007090282 8009090287*	50-306 50-282 50-263 50-263	S Q R R

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEOD	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY
	8007070297 8007090297 8007090302* 8007090302* 8007090354	50-282 50-282 50-282 50-282 50-282	R R R R S	Nuclear Packaging, Inc Nuclear Pharmacy, Inc	8009170378 8009170382* 8009050458 7906290556* 7912190023*	50-201 R 50-201 R 71-9116 PT9
	8009090375 8007090388* 8009100429 8009100500 8009100500	50-243 50-282 50-282 50-282 50-282	P S G Q Q		7912190047* 7912190047* 8003050219* 8003050232* 8003250232	PT9 PT9 PT9 PT9 PT9
	8009100505* 8009100505* 8009110499 8009110534 8009110539	50-282 50-263 50-263 50-263 50-282	a a a a a		8003240087 8004110323 8005090553+ 8005300497+ 8009290122+	Doctet 30 Doctet 30 PT9 PT9 FOIA
	8009110539 8009150076 8009150076 8009150218 8009150218	50-282 50-282 50-282 50-282 90-282	Q Q Q Q	Nuclear Technology, Inc. (Nutech) Nucor Corp O'Connor & Hannan	8009290127* 8009290156* 8009020111* 8009260495* 8002190229	FOIA FOIA 50-237 P 40-8663 PT9
	8009140279 8009140282* 8009170341 8009170341 8009170405	50-282 50-282 50-282 50-282 50-282	R R P P G	O'Neil, Backue, Spielman Dak Ridge National Laboratory	8009290027 8009290174* 8009020034 8009020358 8009030534*	POIA FOIA 50-443 O NUREG 50-320 P
	8009170405 8009170413 8009170441 8009180007 8009180422	50-262 50-263 50-263 50-263 50-262	0 0 0 0 5		75000000000000000000000000000000000000	NUREG RES RES NUREG NUREG
	8009190475 8009190481 8009190481 8009190486 8009230620	50-263 50-262 50-262 50-263 50-263	F P P P S		8009100954 8009110498 8009110574 8009110634 8009110876	NUREO RES RES RES
	8009230430* 8009230441* 8009230738 8009230741*	50-263 50-263 50-263 50-282 50-282	8 8 8 9		8009110885 8009120547 8009120571 8009120581 8009120733	RE6 RE8 RE8 RE8 RE6
	8007230743 8007230750* 8007250244 8007250411* 8007260626	50-282 50-282 50-282 50-243 50-263	S S P Q S		8009150311 8009160202 8009160493 8009240253 8009260836	RES NUREG NUREG RES NUREG
	8009240440* 8009300039 8009300234 8009300551 8009300551	50-263 50-282 50-263 50-282 50-282	S G R S S	Offshore Power Systems (subs of Hestinghouse Electric Corp ) Ogle Petroleum, Inc	8009260550 8009100586 8009030385 8009030455 8009030476	RES 50-437 40-8745 40-8493 40-8745
Northwestern Oklahoma State Univ	8009300558* 8009300558* 8009300573 8009300573 8009260414*	50-282 50-282 50-282 50-282 70-1147	8 8 8		8007050362 8007150552 8007160330 8007160331 * 8007160333 *	40-8745 40-8745 40-8745 40-8745 40-8745
Northwestern Univ Nuclear Engineering Co , Inc , (subs. of Teledyne, Inc )	8007260419* 8007100463* 8007110827 8007070331	70-1167 50-275 40-4826 27-39	н		8009160334* 8009160336* 8009160345* 8009160348* 8009160350*	40-8745 40-8745 40-8745 40-8745 40-8745
Nuclear Fuel Services, Inc (subs of Oetty Dil Co )	8009120156* 8009260168 8009090465	27-48 71-6058 70-143 70-143			8009160354* 8009160356* 8009160357* 8009160383 8009160386	40-874 40-87 40-87 40-8 40-8
	8009090507* 8009100906* 8009110391 8009110392 8009110393*	70-143 70-143 70-143 70-143 70-143			5009160462 6009190369 6009190392 6009220332 6009300202	40-E 40-E 40-B, 40-87 40-87
·	8009110652* 8009120126* 8009120126* 8009120147 8009120421	50-201 50-201 70-143 70-143 70-143 50-201	R	Dhio Historical Society Dhio State Univ	8009300457 800919025&* 8009300184 8009300192 8009300197*	40-874., 50-440 50-243 50-243 50-243
	8007120404* 8007120404* 8007130027 8007130137* 8007240538	50-201 70-143 50-201 70-143	R R U	Ohio, State of Oil,Chemical & Atomic Horkers Intl Oklahoma Osteopathic Hosp Tulsa,Ot Oklahoma, Univ of	8009100444 8009190703 8009260405* 8009100577 8009260408*	PR RECOD 70-2560 50-112 R 40-8180
Nuclear Fuel Services, Inc., West Valley Reprocessing Plant	8009240631* 8009300475 8009150132*	70-143 70-143 50-201	U	Omaha Public Power District	8007250432 8007020106 8007030479 8007030486*	50-112 R 50-285 Q 50-285 R 50-265 R

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	DRY	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEODRY
	8007070505 8007070519# 8007070525 8007070536# 8007070531	50-285 50-285 50-285 50-285 50-285	5 5 6 P	Pennsylvania State Univ Pennsylvania, State of Pfefferkorn & Cooley, P A	8009190956 8009030601 8009190263* 8009030432 8009030696	90-387 Q 50-5 F 50-440 K 90-289 H 50-488 0
	8007150444 8007230347 8007230351# 8007230721 8007300532	50-285 50-265 50-265 50-265 50-285	P R R B	Pharmatopes, Inc	8009250015 7912040156* 8001290281* 8005160029 7906010086*	50-488 0 PT9 PT9 Docket 30 PT9
Oregon, State of Osenn, E. W	8009300539* 8009300566 8009030703 8009030710 800923000B	50-285 50-344 50-367 50-367 50-367	5 G G	Philadelphia Electric Co	8001020073* 8001020083* 8003190525* 8009020245 8009020245	PT9 PT9 PT9 50-171 R 50-171 R
Ott Water Engineers,Inc PRC Information Services Corp	8007230382 8007230373 8007260011 8007300575* 8007270423	50-367 50-367 50-367 CONTRAC FOIA	G G Q		8007020245 8007020244* 8007020244* 8007020246* 8007020635	50-171 R 50-171 R 50-171 R 50-171 R 50-277 B
Pacific Ome & Electric Co	8007020107 8007020263 8007020265* 8007020268* 8007020267*	70~1738 50~275 50~275 50~275 50~275	A A A A		8007080340 8007080340 8007080342* 8007080342* 8007080333	50-277 R 50-277 R 50-277 R 50-277 R 50-277 Q
	8009020270# 8009020272# 8009020274# 8009020275# 8009020277#	50-275 50-275 50-275 50-275 50-275	A A A A		8007080533 8007070015 8007070226* 8007100026* 8007100070	50-277
	8007030687 8007030477 8007030477 8007050082 8007050321	50-275 50-275 50-275 50-133 50-133	9 9 9 9		8007100070 8007100121 8007110251 8007110251 8007120145	50-277 q 50-277 q 50-277 q 50-277 q 50-277 q
	8007050324* 8007080333 8007080334* 8007080335* 8007080336*	50-133 50-133 50-133 50-133 50-133	V R R R		8007120330 8007120347 8007150478 8007150502 8007150502	50-278 8 50-278 8 50-277 F 50-277 0 50-277 0
	8007070514 8007070514 8007070520* 8007070526*	50-275 50-275 50-275 50-275 50-275	K K K K		8009140294 8009160294 8009160296* 8009160427 8009160427	50-277 R 50-277 R 50-277 R 50-277 R 50-277 R
	8007070544 8007070544 8007110756 8007120347 8007120417*	50-275 50-275 71-9096 50-133 50-133	A A 8 S		8009160431# 8009160431# 8009160435# 8009160435# 8009160439	50-277 R 50-277 R 50-277 R 50-277 R 50-278 S
	8009120449 8009120451* 8009180486 8009180493* 8009230351	50-133 50-133 50-275 50-275 50-133	R R A A R		8007160441 8007180304 8007180304 8007180316# 8007180316#	50-278 8 50-277 P 50-277 P 50-277 P 50-277 P
'acific Legal Foundation Parameter, Inc Pathfinder Mines Corp	8009250288 8009110012 8009040470* 8009030510 8009110402	50-275 PR CONTRACT 40-2259 40-2259			8009180335* 8009180335* 8009180439 8009180439 8009180442*	50-277 P 50-277 P 50-277 R 50-277 R 50-277 R
	8009110404* 8009110407* 8009160349 8009190393 8009260045	40-2259 40-2259 40-2259 40-2259 40-2259			8007180442* 8007170048* 8007170482 8007220376 8007230367	50-277 R 50-352 Q 50-278 S 50-277 Q 50-277 R
Peth, D M Pennsylvania Power & Light Co	8009120226 8009120232 8009030006 8009080364 8009090036	50-287 50-289 NUREG 50-387 50-387	0 0 A 0		8009230549 8009230576* 8009230576* 8009250274 8009250616	50-277 R 50-277 R 50-277 R 50-277 R 50-171 F 50-278 8
	8007070472 8007070616 8007070654# 8007110414# 8007110414#	50-387 50-387 50-387 50-387 50-387	53 C 53 C 53 C 53 C 53 C 53 C 53 C 53 C		8007240621 8007270378 8007270378 8007270380* 8007270380*	50-278 B 50-352 B 50-352 B 50-352 B 50-352 B
	8007120142 8007120142 8007120660# 8007130307 8007130470	50-387 50-387 50-387 REGOD 50-387	Q Q A		8009290382* 8009290382* 8009300131 8009300347 8009260085	50-352 B 50-352 B 50-278 Q 50-277 P WABTE MOT
	8009140310 8009170290 8009190250* 8009190271* 8009190956	50-387 50-387 50-387 50-387 50-387	A Q Q Q	Fittsburgh, Univ of	8007180321 8007040412 8007120570 80071300276# 8007150177#	WABTE MOT 50-320 P RES CONTRACT GA799

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGOR	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
Plateau Resources, Ltd Popular Bluff Hosp Popular Bluff, MD Porter-Gertz Consultants, Inc	8009150204* 8009260027 8009150230 8009300399 8009300399	0A777 40-8478 REGOD 50-287 50-287	R R		8009190936 8009220030 8009220379 8009230451 8009260442	50-286 50-286 50-286 50-247 50-286	00000
Portland General Electric Co	#007300401* #007300401* #007020037 #007030575 #007030577*	50-289 50-289 50-344 50-344 50-344	ሴ R P R R	President of US & Executive Offices Public Citizen Litigation Group	8009260446 8009150318* 8009090627* 8009090633* 8009090635*	50~333 50~352 50~367 50~367 50~367	P = 000
	8007070410 8007100237	50-344 50-344	s R	Public Interest Law Center of Philadelph	8009300113 8009050370	FOIA 50-320	Р
	8009100242* 8009100449 8009100453*	50-344 50-344 50-344	R 5 8	ia Public Service Co of Colorado	8009020221 8009030540 8009030625	50-267 50-267 50-267	О Р Б
	8007100461* 8007100467* 8007100509 8007110011 8007110308	50-344 50-344 50-344 50-344 50-344	8 8 6 0		8007030640* 8007100841* 8007160286 8007160288* 8007160270	50-267 50-267 50-267 50-267 50-267	8 8 8 8
	8009150009 8009150059 8009150471 8009150475* 8009160385	50-344 50-344 50-344 50-344 50-344	Q Q 9 8 P		8009160292 8009160314 8009160316* 8009160344 8009160364	50-267 50-267 50-267 50-267 50-267	ው ተ ተ ተ
	8007160620 8007170307 8007180377 8007180468 8007170501	80-344 80-344 50-344 50-344 50-344	8 8 9		8009170189* 8009220318 8009230597 8009230598 8009230404*	50-267 50-267 50-267 50-267 50-267	00000
	8009190691 8009220343 8009240375 8009250337 8009250463	NUREO 50-344 50-344 50-344 71-9018	P Q Q		8907230607* 8007230608 8007230614* 8007230687 8007230723	50-267 50-267 50-267 50-267 50-267	2000
Potomac Alliance	8007240504 8007240510* 8007300314* 8007300471 8007230013	50-344 50-344 50-344 50-344 50-280	8 8 0		8007240174 8007260227 8007260233+ 8007260367 8007260372+	50-267 50-267 50-267 50-267 50-267	222
Power Authority of the State of New York	8005210447 8007020118 8007020252 8007020354 8007020357#	PR 50-333 50-266 50-333 50-333	Q F 8		8009260374* 8009260378 8009260386* 8009300556 8009300563*	50-267 50-267 50-267 50-267 50-267	8 8 8 8
	8007020374 8007020403* 8007020409 8007020422* 8007030405	50-333 50-333 50-333 50-333 50-333	8 6 6 5	Public Service Co of Indiana, Inc	8009020253* 8009030460 8009030460 8009030500 8009040427	50-546 50-546 50-546 50-546 50-546	88846
	8007030414# 8007030418 8007030423# 8007040420 8007050273	50-333 50-333 50-333 50-286 50-286	8 8 8 P P		8009040427 8009090574 8009090574 8009090580* 8009100469	50~546 50~546 50~546 50~546 50~546	8 H H H
	8009080323 8009080325* 8009080537 8009090014 8009090303	50-286 50-286 50-286 50-333	R R Q R		8009100449 8009140400 8009140400 8009140419 8009140419	50-546 50-546 50-546 50-546 50-546	99999
	8007070308* 8007070357 8007070361* 8007100117 8007100268	50-333 50-333 50-333 50-333 50-333	R 8 9 0 R		8009180346 8009180521 8009180533 8009240561 8009250447	50-546 50-546 50-546 50-546 50-546	G A B G
	8009100275* 8009110298* 8009120359 8009120362 8009120365*	50-333 50-333 50-333 50-333 50-333	R Q S P S		8009230447 8009230482* 8009230482* 8009290208*	50-546 50-546 50-546 50-546 50-546	0 5 8 0
	8007120376 8007120376 8007120410 8007120415* 8007150254	50-284 50-286 50-333 50-333 50-284	I I S S P	Public Service Co of New Hampshire	8009290511 8009290513* 8009300094 8009300452 8009030553	50-546 50-546 50-546 50-546 50-443	A Q H 6
S E E	8009160445 8009160449* 8009160458 8009160476* 8009170325	50-333 50-333 50-333 50-333 30-284	8 8 8 9 P	Public Bervice Electric & Gas Co. of New		50-449 50-449 50-449 50-311	F
	8007180384 8007170442	50-286 50-286	P R	Jersey	8007020237 8007030563	50~311 50~311	9 9
	8009190451* 8009190489 8009190496*	50-284 50-333 50-333	R 9 8		8007030591# 8007030513	50-31 t 50-31 t	ľ

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
•	8007030620* 8007040352 8007040374* 8007040375* 8007040378*	50-3 1 50-3 1 50-3 1 50-3 1 50-3 1	S P F F		8009220280 8009230368 8009230368 8009230678 8009230694*	50-272 50-272 50-311	PVVSS
	8009040379* 8009040379* 8009040381* 8009040381* 8009040384*	50-311 50-311 50-311 50-311 50-311	F F F F		8009250240 8009290361 8009300503 8009300512 8009300513	50-272 50-272 50-272	P P P
	8007040385* 8007040388* 8007040372* 8007040374* 8007040376*	50-311 50-311 50-311 50-311 50-311	F F F F	Puerto Rico Electric Power Authority Purdue Research Foundation Purdue Univ	8009160148 8009160151* 8009240130* 8009260247* 8009120590		0
	8009040378* 8009040399* 8009040402* 8009040403* 8009040405*	50-311 50-311 50-311 50-311 50-311	ቸ F F F	R & D Associates R J Reynolds Tobacco Co RMI Co , RMI Titanium	8009120578 8009150414* 8009300602 8009110214* 8009110492	50-327 CONTRACT 71-6144 XPORTLIC XPORTLIC	Ρ
	8007040407* 8007040408* 8007040410* 8007040411* 8007050270	50-311 50-311 50-311 50-311 50-272	F F F R	Reliance Testing Laboratories, Inc Rensselaer Polytechnic Inst	8009110587* 8009030474 8009140209 8009020012 8009300207	XPORTLIC PR PRM 50-225 71-376	F
	8007050274* 8007050332 8007080530 8007070230 8007070312	50-272 50-311 50-272 50-272 50-311	R P Q Q P	Reuter-Stokes, Inc Rip Algom, Ltd Robert L. Gloud Associates, Inc	8009300210# 8009110270 8009110496 8009300520 8009020096#	71-394 XFORTL1C XPORTL1C 40-8084 50-204	P
	8007070315 8007070320* 8007070437 8007070441* 8007070447	50-311 50-311 50-311 50-311 50-311	R & S 5 5 5	Rochester Qas & Electric Corp	8007020026 8007020086 8007020346 8007020351* 8007030485	50-244 50-244 50-244	Р У 8 8 8
	8009070455* 8009070542 8009070550* 8009070554 8009090558*	50-311 50-311 50-311 50-311 50-311	ទ ព ព ព ព		8007030474 8007030545 8007040414* 8007040415* 8007050274	50-244 50-244 50-244	P P P P V
	8007070557 8007070578 8007070587 8007070589* 8007070591*	50-354 50-272 50-272 50-272 50-272	ិ ទ ទ ទ		8009050278* 8009090377 8009090382* 8009090513 8009090551	50-244 50-244 50-244	V P P P
	8007070573 8007070595* 8007110323 8007110357 8007110472	50-272 50-272 50-272 50-311 50-354	\$ \$ V Q Q		8009110485 8009160317 8009160539 8009170303 8009170306#	50-244 50-244 50-244	6 6 6 6
	8009120218 8009120357 8009120372* 8009120375 8009120382*	50-354 50-272 50-272 50-272 50-272	ត ត ត ត ត ត		8009170311 8009180245 8009180272* 8009190467 8009220324	50-244 50-244 PR	Q R R Q
	8009120424 8009120428* 8009150043* 8009150264 8009150267*	50-272 50-272 50-354 50-311 50-311	# # # # # # # # # # # # # # # # # # #	Rochester Univ of Rockweil International Corp , Energy Systems Div	8009240192# 8009300365 8009160450 8009120620	50-244 NUREO 70-25	Q P
	8009140298 8009140300* 8009140351 8009140393 8009140401	50-272 50-272 50-311 50-311 50-272	R R P V P	Rocky Mountain Energy Co	8009150396 8008110042 8008110046# 8009080453 8009170237	71-5088 40-8721 40-8721 40-8497 40-8380	
	8009140401 8009140478 8009140482* 8009140450 8009180249	50-272 50-311 50-311 50-354 50-311	P S S S	Ropes & Gray Rutgers:New Jersey, State Univ of, Busch Campus	8007260024 8007260153 8007260157* 8007250047 8007120536*	40-8380 40-8380 40-8380 50-471 70-343	o
	8007180257# 8007180413 8007180455 8007180458 8007180465	50-311 50-311 50-311 50-311	R 연 P P	SRI International Sacramento Municipal Utility District	8007100012* 8007030187 8007040400 8007050240 8007050241*	50-312 50-312 50-312	Q F P
	8009190213 8009190396 8009190466	50-354 50-311 50-311 50-311	ቦ G P		8007050337 8007050344* 8007080433 8007070784 8007070788*	50-312 50-312 50-312 50-312	R P Q
	8009190527 8009190534	50-311 50-311 50-311	թ թ թ		8007070812 8007070813* 8007150247 8007150272*	50-312 50-312	0 5 5

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	₹Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	RY
	8009150540 8009140295 8009140297* 8009140388 8009140392*	50-312 50-312 50-312 50-312 50-312			8009120583 8009150041 8009160046 8009220064 8009250452	FOIA 50-289 PR 70-820 FOIA	Q
	8009160628 8009230677 8009240378 8009260472 8009260476*	50-312 50-312 50-312 50-312 50-312	Q R Q S S	Sierra Club	8009250467* 800925047[* 80093004£7 8009300423* 8009300004	TOPREP TOPREP 50-287 50-287 50-367	G G
San Antonio, TX San Diego Gas & Electric Co	8009290353 8009290354* 8009040289 8008270280* 8009030538*	50-312 50-312 50-445 50-361 50-206	P P M F R	Sigma Chemical Co (subs of Sigma-Aldri ch Corp )  Small Business Administration	8007270485 8007270488 8007270581 8007300024 8007150178*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC CONTRACT	C C C
	8009110399* 8009170169 8009170169 8009170171* 8009170171*	50-361 50-582 50-582 50-582 50-582	0 0 0	Snali & Wilmor	8009300097* 8009300198* 8009300209* 8009030689 8009030699	CONTRACT CONTRACT CONTRACT 50-275 50-275	T T
San Luis Obispo Mothers for Peace Sandia Laboratories	8009190344* 8009190351* 8009160234 8009220262 8009020349	50-361 50-361 50-275 50-275 NUREG	К К С С	South Carolina Electric & Gas Co	8007030714 8007020065 8007030460 8007030493 8007030621	50-528 50-395 50-395 50-395 50-395	0 M Q A S
	6007020341 8007040437 8007070132 8007120502 8007170378	NURED NURED RES 50-3 NURED	Р		8007100320 8007100427 8007110211 8009110719 8009120347	50-395 50-395 50-395 50-395 50-395	A A O A
Bandvik Special Metals Corp	8009190743 8009260092 8009260649 8009300160 8009090208*	NUREG NUREG NUREG NUREG XPORTLIC	С		8009160634* 8009170294 8009180129 8009180511 8009230027	50-395 50-395 50-395 50-395 50-395	0 A G G
Sargent & Lundy, Inc	8007070215* 8007030440* 8007180443 8007170474* 8007300445*	XPORTL 10 50-275 NUREG 50-275 50-454	C P A		6007230282 8007230276 8007240552 8007240557* 6007250072	50-395 50-395 50-395 50-395 50-395	F A Q Q
Schiff, Hardin & Waite Schultz, N B Science Applications, Inc	8009170002* 8009030149 8009030152* 8009110379* 8009120597*	70~820 50~367 50~367 CONTRACT FO1A	G G T		8009260516 8009260518* 8009290337 8009300002 8009300009	50-375 50-375 50-375 50-375 50-375	A A M Q
Seattle Univ	8009140493 8009140515* 8009240312 8009250497* 8009040240	NUREG CONTRACT 70-1119 CONTRACT 50-139	T	South Carolina Public Service Authority South Carolina, Btate of	8007300168 8007300570 8007180364 900730007 8007020316	50-395 50-395 50-395 50-395 NUREQ	A Q M G
Benate	8009020124* 8009020148* 8009020191* 8009020322* 8009120317*	50-320 50-320 50-219 50-320 50-327	H H H H	South Carolina, Univ of South Texas Electric Cooperative	8007100072* 8007100076* 8007270142* 8007050418* 8007170188	27-47 27-47 CONTRACT 50-395 50-445	T A M
Senate. Danking, Housing & Urban Affairs Senate. Energy & Natural Resources Senate. Foreign Relations Committee Senate. Covernmental Affairs	8009240014* 8009150448* 8009100107* 8009110413* 8009020375*	FDIA COMMISSI COMMISSI COMMISSI	TION , TION TION	South Hest Nuclear Co Southern California Edison Co	8009300533 8009300542* 8009150390 8008270278 8008270280*	50-478 50-478 71-9044 50-361 50~361	# # F
Shannon & Wilson, Inc Shaw, Pittman, Potts & Trowbridge	8009100093* 8009220277 8009030118 8009040365 8009090784	COMMISS: NUREC 50-320 50-289 50-312	G G G		8009020006 8009020006 8009020007* 8009020007*	50-361 50-361 50-361 50-361 50-361	A A A A
	8009090788* 8009100429 8009100431 8009170219 8009170302	50-312 50-282 50-289 50-289 50-289	0 0 0		8007020010* 8007020031 8007020063 8007020078 8007020082	50-361 50-375 50-206 50-206 50-206	A Q P S P
	8009250017 8009260301 8009260313 8009300011 8009300020	50-267 50-267 50-269 50-269 50-267	0 T 2		8007020083* 8007030387 8007030533 8007030538* 8007030634	50-206 50-206 50-206 50-206 50-206	8 F R R
Shældon, Harmon & Weiss	8009300022 8009300410 8009300570 8009040258 8009040358	50-209 50-266 50-483 70-143 50-209	0 0 0		8009030637* 8009030644* 8009050286 8009050286 8009050302	50-204 50-204 50-204 50-204 50-361	į
	8007080444 8007080575* 8007110365 8007110547 8007110802	70-820 COHMISS 50-155 FOIA 50-155	BION G G		8007050302 8009080322 8009080337 8009080343	50-361 50-206 50-395 50-206	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE	ORY	AUTHOR AFFILIATION	ACCESSION NUMBER	CATEOURY
~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	8009090265 8009090268* 8009090463 8009090470 8009090470	50-206 50-206 50-206 50-361 50-361	R R P S	State, Dept of	8007150423 8007300074 8007300650 8007300660 8007300664	COMMISSION XPORTLIC XPORTLIC XPORTLIC XPORTLIC
	8009090552 8009090811	50~206 50~206		State.Dept of Bureau of Oceans & Internati Environ & Scientific Affairs	8009080279	OLITHORY
	8009110399* 8009150011 8009150314	50-361 50-206 50-395	а к		6907080547 8007100155 8007150428* 8007180276	XPORTLIC XPORTLIC COMMISSION XPORTLIC
	8007140230 8007140521 8007140424 8007140430	50-206 50-206 50-361 50-206	P Q Q Q	Steerns-Roger, Inc Stone & Webster Engineering Carp Stone & Webster, Inc	8009290136 8009290136 8009300414* 8009090119* 8009050280	XPORTLIC XPORTLIC 40-8681 50-334 0 GA999
	8009170207 8009170334 8009180421 8009180421 8009180427*	50~206 50~206 50~361 50~361	Q F A A	Sutin, Theyer & Browne Sweten Switzerland Systems, Sciences & Boftwere YERA Corp	8003240038 8009240195 8009120407 8009020483 8009020085*	PT9 XPORTL16 XPORTL16 NUREO 50-204 P
	8009180429* 8009180433* 8009190433* 800919083 8009190338	50-361 50-361 50-361 50-361 50-361	A A Q K		8009100745* 8009100746* 8009180165* 8009180434 8009180446	70-754 70-754 CONTRACT NUREO NUREO
	8009190338 8009190344* 8009190344* 8009190351* 8009190351*	50-361 50-361 50-361 50-361 50-361	К К К К	Tech/Ops (Technical Operations, Inc ) Technassociates, Inc Technical Operatums, Inc	8007020513 8007140457 8007300178* 8007300207* 8007160204	71-9039 XPORYLIC CONTRACT CONTRACY
	8007170361 8007170402 8007260508 8007260513* 8007270348	50-206 50-206 50-206 50-206 50-261	P P S P	Technology Development of California, Inc Tethetron, Inc Teledyne (socopes Tennessee Valley Authority		PRM CONTRACT CONTRACT 40-8113 50-990 8 50-990 8
Southern California, Univ of	8009300362 8009300377 8009300431 8009300448	50-206 50-206 50-361 50-206	ያ 8 የ		8008190458 8008190463 8009020046 8009020046 8009020056	50-370 8 50-328 8 50-370 8 50-370 0
Southern States Energy Board	8009090652 #009090656* #009090664* #009090672* #0090301#4*	50-275 50-275 50-275 50-275 State Pr	T T T 'CQg		B007020056 B007020049 B007020074* B007020081	50-390 8 50-296 P 50-296 P Toprep
Southwest Research Inetitute	8009080352* 8009110297 8009110297* 8009110304* 8009150174	50-317 50-293 50-293 50-293 RE00D CONTRACT	F @ @ @		8007020074 8007020077* 8007020077* 8007020077* 8007020103* 8007020104	50-390 K 50-390 K 50-390 K 50-390 K TOPREP 50-327 G
Southwest Terms Electric Cooperative Southwestern Public Service Co Spiegel & McDiarmid	8009040196 8009300035 8009160299# 8009020282	50-445 50-445 50-267 50-445	M M R M		8007020133 8007020184 8007020214 8007020214 8007020214	50-259 0 50-259 0 50-327 0 50-327 0
	8009150417 8009160182 8009160275 8009170162	50-445 50-389	м м м		8007020214 8007020214 8007020214 8007020214	50-327 q 50-327 q 50-327 q 50-327 q 50-327 q
	8009190091 8009220221 8009220222*	50-335 50-389 50-389	н н к к		8007020214 8007020201 8007020406 8007020400* 8007020260*	50-327 0 50-327 8 50-294 P 50-294 P 50-390 0
St Francis Paoria, IL St Louis Unit	8009300188 1 8009120007* ( 8009230372* (	50-445 70-2705 Contract Contract Contract	н	( E	8009030367 8009030373* 8009030397 8009030406	50-327 g 50-327 g 50-327 R 50-259 p
Standardized Nuclear Unit Power Plant System	8009300597* (	0-206   Ontract 0-482		\$ E	909030404 909030404 909030411#	20-324 b 20-324 b
	8009170416 3 8009170442 5	0-482 £ 0-482 £	)	9 8	1007030411* 1007030411* 100703043& 100703043&	50-259 p 50-259 p 50-327 p 50-327 p
	8009190441 5 8009190441 5 8009190441 5 8009190445* 5	0-482 H 0-482 K 0-482 K 0-482 K	( (	8 8	007030438* 007030488 007030474* 007030508 007030514*	50-327 p 50-259 s 50-259 s 50-260 p 50-260 p
Stanford Univ	8009190445# 5	D-482 K D-482 A		8	007030517 007030523* 007030536 007030548	50-327 9 50-327 9 60-327 6 50-391 F

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	₹¥	AUTHOR AFFILIAYION	ACCESSION NUMBER	SUBJECT	
	8007030558 8007030560 8007030566* 8007030574 8007030574	50-259 50-327 50-259 50-390 50-390	5 K K K		8009090555 8009090555 8009090557 8009090560* 8009090560*	50-259 50-259 50-259 50-259 50-259	P \$ p p
	8007030597 8007030604* 8007030631 8007030662 8007030664*	50-296 50-296 50-296 50-327 50-327	8 8 P P P		8009090540* 8009090543* 8009090563* 8009090563* 8009090563*	50-259 50-259 50-259 50-259 50-259	F I I I
	8007030666* 8007040401 8007040401 8007040430	50-327 50-390 50-390 50-390 50-390	ម ទ ទ ទ		8007070563* 8007070563* 8007070563* 8007070563* 8007070563*	50-259 50-259 50-259 50-259 50-259	I I I I
	8007040436 8007040447 8007040484 8007040486 8007040487*	50-390 50-518 50-553 50-328 50-553	S S A S A		8009090563* 8009090563* 8009090563* 8009090563*	50-259 50-259 50-259 50-259 50-259	I I I
	8007030237 8007080257 8007080259 8007080354 8007080356*	50-327 50-327 50-327 50-327 50-327	e e b a a		8007070563* 8007070563* 8007070563* 8007070565* 8007070583*	50-259 50-259 50-259 50-259 50-327	I I S S
	8007080360 8007080367* 8007080373 8007080380* 8007080382	50-327 50-327 50-327 50-327 50-327	5 6 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		8007070588* 8007070570* 8007070802 8007070802 8007070802	50-327 50-327 50-327 50-327 50-327	8 0 0
	8007080371 * 800707031 4 8007070328 * 8007070332 8007070341 *	50-327 50-294 50-294 50-296 50-296	S S S S S S		8007070802 8007070802 8007070802 8007070802 8007070802	50-327 50-327 50-327 50-327 50-327	0 0 0 0
	8009090367 8009090367 8009090367 8009090370 8009090370	50-259 50-259 50-259 50-327 50-327	ት ት ት		8007100236 8007100283 8007100283 8007100284 8007100273	50-328 50-370 50-390 50-328 50-390	8 8 8 8
	8007070414 8007070418* 8007070427 8007070427 8007070427	50-327 50-327 50-518 50-518 50-518	R R 8 8 9		8009100293 8009100401 8009100401 8009100443 8009100443	50-370 50-438 50-438 50-390 50-390	8888
	8007070434 8007070434 8007070434 8007070434 8007070440	50-518 50-518 50-518 50-518 50-518	9 8 8 8 8 8 8 8 8 8 8		8009100459 8009100472 8009100494 8009100494 8009100526	50-328 50-553 50-438 50-328 50-518	8 8 8 8
	8007070440 8007070440 8007070440 8007070445 8007070462#	50-518 50-518 50-518 50-260 50-260	8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8		8009100937 8009100537 8009100537 8009100537 8009100576	50-327 50-327 50-327 50-327 50-328	8 8 8
	8007070467 8007070481* 8007070470 8007070307* 8007070322	50-240 50-260 50-260 50-260 50-438	8 9 5 8 A		8009100574 8009110181# 8009110320 8009110352 8009110352	50-328 50-327 50-328 50-259 50-259	8 8 8
	8007070522 8007070524 8007070527 8007070530 8007070530	50-438 50-438 50-327 50-518 50-519	A 6 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		8007110352 8007110353* 8007110353* 8007110353* 8007120245	50-257 50-257 50-257 50-257 50-276	R R R P
	8007070531 8007070543 8007070543 8007070543 8007070543	50-327 50-259 50-259 50-259 50-259	8 I I I		8009120249* 8009120261 8009120261 8009120293 8009120389	50-296 50-327 50-327 50-439 50-327	8 A A A
	8009090543 8009090543 8009090543 8009090543 8009090543	50-259 50-259 50-259 50-259 50-259	I I I I		8007120411 8007120412 8007120440* 8007120443* 8007120488	50-327 50-327 50-327 50-327 50-390	8 8 8
	8007070543 8007070543 8007070543 8007070543 8007070543	50-259 50-259 50-259 50-259 50-259	E E E		8009120488 8009120679 8009120679 8009120679 8009120679	50-390 50-327 50-327 50-327 50-327	F Q Q Q
	8007070543 8007070543 8007070543 8007070547 8007070555	50-259 50-259 50-259 50-327 50-259	1 1 5 P		8009120679 8009120679 8009120679 8009120679 8009150460	90-927 50-927 50-927 50-927 50-438	0 0 0 A

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJEC	
	8009150468* 8009150537 8009150591 8009160219 8009160219	50-438 50-390 71-9074 50-259 50-259	A S P P		8009190495# 8009190511# 8009190519# 8009190524# 8009190540	50-259 50-327 50-259 50-259 50-327	P 8 8 8
	8009140219 8009140221* 8009140221* 8009140221* 8009140319	50-259 50-259 50-259 50-259 50-390	Р Р Р S		8009190547* 8009190610* 8009190643* 8009190759 8009220038	50-327 50-259 50-259 70-2910 40-1341	
	8009140325 8009140326 8009160327* 8009140328 8009160353	50-327 50-328 50-327 50-328 50-438	\$ 5 5		8009220041* 8009220210 8009220210 8009230333 8009230333	40-1341 50-259 50-259 50-327 50-327	Р Р Р
	8009160353 8009160353 8009160368 8009160372 8009160372	50-438 50-438 50-566 50-327 50-327			8009230468 8009230524 8009230549 8009230549 8009230560	50-390 50-327 50-327 50-327 50-390	9 P P S
	8009160375 8009160377 8009160377 8009160380# 8009160390	50-327 50-438 50-438 50-327 50-327	8888		8009230560 8009230587 8009230594* 8009230610 8009230610	50-390 50-327 50-327 50-390 50-390	8 8 8
	8009160398* 8009160406 8009160412* 8009160416 8009160418	50-327 50-327 50-327 50-294 50-390	5 9 9 0		8009230611 8009230669 8009230674 8009230675* 8009230679*	50-390 50-296 50-296 50-296 50-296	8 8 8
	8009160418 8009160421 8009160422* 8009160423 8009160423	50-370 50-327 50-274 50-370 50-370	0 8 0 0		8007230704 8007230714* 8007230714 8007230728* 8007230730	50-259 50-259 50-259 50-259 50-327	8 8 8
	8007160425* 8007160432 8007160437 8007160440* 8007160454	50-327 50-260 50-438 50-260 50-260	8 8 8 8		9007230734* 8007240261 8007240261 8007240261 8007240357	50-327 50-259 50-259 50-259 50-518	8 0 0
	8009160463 8009160466* 8009160468* 8009160547 8009160643	50-327 50-260 50-327 50-391 50-518	S S 8 A B		8009240383 8009240383 8009240383 8009240387* 8009240392	50-259 50-259 50-259 50-518 50-518	0 0 0
	8007160648 8009160648 8009170206 8009170261 8009170262*	50-438 50-438 50-259 50-327 50-327	8 8 P R R		8009240425 8009240427 8009240427 8009240427 8009240427	50-518 50-518 50-518 50-518 50-518	6 Q Q Q
	8009170274 8009170274 8009170274 8009170277* 8009170297	50-259 50-259 50-259 50-259 50-327	R R R R		8009240427 8009240427 8009240446 8009240446 8009240446	50-518 50-518 50-259 50-259 50-259	0 0 0 0
	8007170297 8007180048 8007180048 8007180048 8007180048	50-327 50-318 50-518 50-518 50-259	P G G G G		6007240454 6007240454 6007240454 6007240454 9007240454	50-328 50-329 50-328 50-328 50-328	Q Q Q Q
	8007180068 8007180068 8007180068 8007180087 8007180087	50-518 50-518 50-518 50-390 50-390	Q Q Q Q		8009240454 8009240400* 9009250078 8009250075 8009250240	50-328 50-566 50-259 50-259 50-438	Q Q Q Q 8
	B009180087 B009180087 B009180087 B009180087 8009180087	50-390	0 0 0 0		8009250256 8009250273 8009250480 8009290262 8009290280*	50-438 50-370 50-327 50-327 50-327	8 9 9 P P
	8007180087 8007180397 8007180400 8007180402 8007180441	50-259 50-259	Q 8 8 8		8009290324 8009290324 8009290927 8009290327 8009290332	50-390 50-390 50-390 50-390 50-328	8 8 8
	8009190440 8009190454* 8009190465 8009190467 8009190471	50~260 50~259 50~259	8 8 8 8		8009290333 8009290344 8009290344 8009290345 9009290346	50-327 50-370 50-390 50-259 50-438	P 8 8 8
	8007170476 8007170476 8007170488 8007170488 8007170495*	50-327 50-259 50-259	<b>Ե</b> Ե		6009290347* 8009290350 8009290355 8009290355 8009290375	50-259 50-326 50-553 50-553 50-518	8 8 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8009290375 8009290375 8009300067* 8009300067*	50-518 50-518 50-259 50-259 50-259	6 0 0		8007220334 8007220334 8007230005 8007230005 8007230301	50-445 A 50-445 A 50-445 G 50-445 G 50-445 B
	8009300147 8009300147 8009300147 8009300156* 8009300156*	50-259 50-259 50-259 50-259 50-259			8009230301 8009290571 = 8009300055 8009300065 8009300065	50-445 S 50-445 Q 50-445 G 50-445 Q 50-445 Q
	8009300154* 8009300195 8009300226 8009300277 8009300280*	80-259 50-327 50-327 40-1341 40-1341		Teras Utilities Services, Inc Teras, State of	8009300070 8009300076 8009300076 8009230623 8009090851*	50-445 G 50-445 G 50-445 G 50-445 A COMMISSION
	8009300348 8009300348 8009300353 8009300353 8009300353	50-438 50-438 50-259 50-259 50-259	S 5 6 9 9 9		8009070655* 8009090662* 8009160332 8009160343 8009190894	COMMISSION COMMISSION 50-478 M WASTE MOT State Prog
	8007300375 8007300400 8007300400 8007300400 8007300400	50-328 50-259 50-259 50-259 50-259	S P P P	Texas, Unvi of, El Paso Texas-Louisiana Electric Cooperative, Inc	8009120590 8009170232* 8009170232* 8009170364* 8009170364*	RES 50-445 M 50-445 M 50-445 M 50-445 H
	8009300411 8009300411 8009300427 8009300427 8009300429	50-439 50-439 50-439 50-438 50-294	\$ \$ \$ \$ \$ \$	The Tribune Chronicle, Warren, CH  Thompson, Nielson, KlaverKamp & James	8009230239* 8009230242* 8009230245* 8009230247* 8009050354	50-320 H 50-320 H 50-320 H 50-320 H 50-329 0
	8007300445 8007300451 8007300467 8007300480 8007300480	50-518 50-327 50-328 50-438 50-438	9 8 9 9 9	Three Mile Island Alert  Three Mile Island Public Interest Resource Center Toledo Edison Co	8009020407 8009300629 8009300632= 8009020421	50-287 0 50-289 0 50-289 0 50-289 P
	8007300516 8007300521* 8007300527 8007300544 8007300548	50-257 50-259 50-259 50-294 50-260	\$ \$ Q \$ \$		8009020061* 8009020333 8009020374* 8009030012 8009080317	50-346 S 50-346 S 50-346 S NUREQ 50-346 R
Teres A&M Univ	8007300553* 8007300554* 8007300562 8007300567* 8007030350	50-294 50-260 50-259 50-259 50-128	\$ \$ \$ R		8007080317* 8007100172 8007110504 8007120351 8007120356*	50-346 R 50-346 P 50-346 Q 50-346 S
Texas Horder Cooperatives Taxas Instruments, Inc	8007030353* 8007030568 8007030572* 8007300476* 8007020255	50-128 50-59 50-89 50-445 70-33	R R R M		8009120430 8009150067 8009150276 8009150277# 8009160391	50-346 F 50-346 Q 50-346 R 50-346 R 50-346 S
	8007020259* 8007030435* 8007110702 8007120668 8007150078	70-33 50-367 70-33 70-33 70-33	R		8009160399* 8009220176 8009220297 8009220301* 8009220313*	50-346 8 50-346 0 50-346 P 50-346 P 50-346 P
Terms Public Interest Research Group	8009160527 8009170149 8009170153* 8009170154* 8009170157*	50-466 50-466 50-466 50-466	0 0 0		8007230471 8007230480* 8007230482 8007230484* 8007230470	50-346 8 50-346 8 50-346 8 50-346 8 50-346 8
Terms Technologial College Terms Utilities Generating Co	8009170223 8009170225* 8009030216* 8009090387 8009110048	50-466 50-466 CONTRACT 50-445	v o	Taranto, Univ of,	8009230492* 8009240097 8009290343 8009290370* 8009190248	50-346 8 50-346 9 50-346 8 50-346 8 50-440 K
	8009110048 8009110781 8009150012 8009150213 8009150215*	50-445 50-445 50-445 70-2932 70-2932	•	Transnuciear: Inc	8009020480 8009020486* 8009050449 8009110240 8009110403	XPORTLIC XPORTLIC XPORTLIC 70-2478 XPORTLIC
	8009140342 8009140342 8009170141 8009170141 8009170232*	50-445 50-445 50-445 50-445	A 0 0 0		8009110497 8009110502+ 8009110429 8009110495 8009110700	XFORTLIC XFORTLIC XFORTLIC XFORTLIC XFORTLIC
	8009170235* 8009170235* 80091702359 8009170359 8009170359	50-445 50-445 50-445 50-445 50-445	M H H H		8009110743 8009150433* 8009150438* 8009180512 8009260218	XFORTLIC COMMISSION COMMISSION 70-2478 XFORTLIC
	8009170369* 8009170369* 8009170420 8009180045 8009180457	50-445 50-445 50-445 50-445 50-445	M M G G		B009240224# B009300078 B009300079 B009300084#	XFORTLIC XPORTLIC XPORTLIC XPORTLIC

AUTHOR AFFILIATION	ACCESSION	SUDJEC CATEOO		AUTHOR AFFILIATION	ACCEBBION NVMBER	SUBJE: CATEG	
U S Court of Appeals 7th Circuit Union 76 Minerals Exploration Co Union Carbide Corp	8009180431 8009110890 8008130375 8009120390 8009160549	50-312 40-8584 40-299 40-299 40-299	G		8007030571* 8007030576 8007030586* 8007030593 8007030604	50-339 50-339 50-339 50-339 50-338	8 8
Union Electric Co	8009020093 8009090546 8009100080* 8009230651 8009230662	50-483 50-483 50-483 50-483 50-483	8 8 8 %		800703040B* 8007030412 8007030414* 8007030415 8007030417*	50-339 50-338 50-339 50-339	9. 8
	8009230662 8009230667 * 8009230667 * 8009300447 8009300570	50-483 50-483 50-483 NUREO 50-483	6 K		9007030423* 8007030627 8007030632* 8007030642 8007030647*	50-338 50-338 50-338 50-338 50-338	8 8 8
Union of Concerned Scientists	8007040358 8007150041 8007230011 8007300420+ 8007300422+	50-289 50-289 50-289 50-289 50-289	0 7 0 0		8007030653 8007030658* 8007050056 8007050327 8007050327	50-338 50-338 50-281 50-338 50-338	S G R R
United Engineers & Constructors, Inc	8007300423* 8007160645	50-287 50-443	9 8		8009050335* 8009050335*	50-338 50-338	R R
(subs of Raytheon Co ) United Nuclear Corp . UNC Recovery Systems Div	8009110221	70~620			8007080351 8007080366* 8007080374	50-281 50-281 50-339	9 8 P
••	8009110230 8009110235	70-820 70-820			8009090274	50-280	F
United Nuclear Corp .Naval Products Div United Technologies Corp , Pratt &	8009110252* 8009170005* 8009180527 8009240668 8009300537	70-920 70-920 70-920 70-371 40-791			8007090344 8007090344 8007090347* 8007090347*	50-338 50-338 50-338 50-338	<b>ե</b> ե
Whitney Aircraft Group Utility Workers Union of America Velan Valve Go	6009150243 8009250313* 8009020113	RECOD GA999 50-271	g		8007070352* 8007070352* 8007070477 8007070512* 8007070528	50-338 50-338 50-338 50-338 50-280	Р В 9
Vermont Yankee Nuclear Power Corp	8009050318 8009050322* 8009080375	50-271 50-271 50-271	9 8 P		8007070528 8007070538 8007070541 8007070584*	50-280 50-339 50-338 50-339	9 9 9
	8007080381* 8007070478 8007070535 8007070540*	50-271 50-271 50-271 50-271	P P R R		8007070586* 8007100252 8007100262* 8007110431	50-338 50-280 50-280 50-338	8 9 8 P
	8009100127 8009110467 8009120401 8009120405* 8009160291	50-271 50-271 50-271 50-271 50-271	В 6 0		8007120031 8007120031 8007120031	50-280 50-280 50-280	a a
	8009160301* 8009180451 8009180452*	50-271 50-271 50-271	R P P		8009120702 8009150257 8009150274 8009150278*	50-338 50-338 50-280 50-280	8 8
	8009190947 8009230100 8009240207 8009240221	50-271 50-271 50-271 50-271	a a P P		80091 60324 80091 60429 80091 70321 80091 70323* 80091 80251	50-281 50-338 50-281 50-281 50-280	ን ቴ ቴ ቴ c
it Admin Hosp Omaha,NE	8009260458 8009260461# 8009260280	50-271 50-271 50-131 FOIA	P P F		8007180251 8007180412 8007180417*	50-280 50-339 50-339	P 6 8
Jirginia Electric & Power Co	8007030184 8007030207* 8009020088	50-280 50-280 50-281	F F		8009190437 8009190437	50-280 50-280	R R
	8007020070# 8007020234 8007020234 8007020242	50-281 50-404 50-404 50-280	9 9 9		8007170444* 8007170525 8007170525 8007170525 8007170553	50-280 50-280 50-280 50-280 50-280	R P P 8
	8007020344 8007020350* 8007020397	50-260 50-260 50-404	8 8 0		8009190553 8009190559* 8009190566* 8009220134	50-280 50-280 50-280 50-280	8 8 8
	8009020399 8009020416 8009020416 8009020437	50-404 50-404 50-404 50-280	0 0 P		8009220134 8009220239 8009220241	50-280 50-339 50-339	8 8
	8007020437 8007020441* 8007020441* 8007030424	50-280 50-280 50-280 50-338	444		8007220243 8007220248 8007220251 8007220253	50-338 50-281 50-338 50-280	8 8 8
	8007030428* 8007030428* 8007030428* 8007030525	50-338 50-338 50-280	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		8009220256* 8009220240* 8009220243* 8009220306*	50-236 50-260 50-260	8 8 8
	8009030535* 8009030555 8009030561* 8009030567	50-280 50-338 50-338 50-339	8 8		8007220307* 8007220315* 8007220317* 8007220324*	50-281 50-339 50-339 50-338	8 8 8 8
			-		6009220355	50-339	\$

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	BUBUECT CATEGORY	,
	B009220360# B009220369 B009220373# B009220398# B009220402#	50-339 50-338 50-338 50-281 50-281	\$ \$ \$ \$ \$		8009160622 8009170388 8009170393 8009170393 8009190677	50-397 50~460	0 0 0
	8009230097 8009230297 8009230292 8009230320 8009230320	50-338 50-338 50-338 50-338 50-338	Q 무 무 F F		8009230352 8009230696 8009240464 8009240465 8009300346	50~397 50~397 50~397	A A S G
	8007230343 8007230356 8007230360# 8007230360# 8007230554	50-280 50-338 50-338 50-338 50-337	F R R R	Nashington State Univ	8009300352 8009300379 8009300415 8009030528 8009030530+	50~397 : 50~397 : 50~27 :	A S R R
	8009230577* 8009230589 8009230600* 8009230605 8009230615*	50-339 50-339 50-339 50-338 50-338	5 5 5 5	Washington, State of Hest Texas Legal Services Western Cultural Resource Hanagement, Inc.,	8009300391 8009240260 8009090238 8009150045 8009150164*	6tate Pro 50-445	C 00 C
	8009230622 8009230629 8009230629 8009230636*	50-338 50-338 50-338 50-338	8 0 6 6	Western Nuclear, Inc. (subs. of Phelps. Bodge Corp.)	B009150550 B0091B0419	40-1162 40-1162	
	8009230441* 8009230473* 8009230473*	20-580 20-580 20-580	8 9 9 0	Westinghouse Electric Corp	8007250041 8007300141 8007020017* 8007020472	40-1162 40-1162 50-537 XPORTLIC	A
	8009240399 8009240399 8009240399 8009240399	50-280 50-280 50-280	0 0 0 0		8007020477* 8007040180* 8007040407 8007080274	XPORTLIC 50-298 TOPREP	p P
	8009240449 8009240470* 8009240471*	50-280 50-281 50-281 50-281 50-281	8 8		8007080277* 8007100048 8007100076 8007100101* 8007100117*	50-049 P XPORTLIC XPORTLIC XPORTLIC XPORTLIC	P
	8009240661* 8009240701* 8009250087 8009250087	50-281 50-260 50-404 50-404	0 0 0		8007100131* 8007100187 8007100193* 8007100493 8007110028	XPORTLIC 70~1143 70~1143 XPORTLIC XPORTLIC	
	8009260278 8009290319 8009290319 8009290321*	50-260 50-338 50-338 50-338	P R R R		8007110025* 8007110256* 8007110264 8007110406	70-1151 CONTRACT XPORTLIC XPORTLIC	
	8009290321* 8009290349 8009300116 8009300116 8009300116	50~338 50~338 50~280 50~280 50~280	R P Q Q Q		8009140287 8009170295 8009170294* 8009170298 8009170301*	50-244 F	P P
	8009300116 8009300249 8009300255 8009300498 8009300504*	50~280 50~338 50~338 50~281 50~281	Q P G B S		8009170314* 8009170314* 8009180341 8009190365*	50-244 F TOPREP 50-206 F	P P P
Virginia Tech Virginia, State of	8007300508* 8007300457 8007030202* 8007070333* 8007070343*	50-281 50-124 50-280 50-337 50-337	9 F F P U		8009190374* 8009190378* 8009220275 8009230685 8009230783		t t
Vinginia, Univ. of Vollen, R. J.	8009250263* 8009030703 8009030710 8009120392	CONTRACT 50-367 50-367 50-367	0	Hestinghouse Electric Carp , Nuclear Energy Systems	8007250257 8007080299* 8007190453*		Q P
	8009120445* 8009230008 8009230382 8009230373	50-367 50-367 50-367 50-367	0 0 0	Wastinghouse Electric Corp , PWR Systems Div. Waston Geophysical Corp	8009190109 8009190457 8009190240 8009190240		K K
Hashington Public Power Supply System	8007250011 8007020043 8007030342* 8007030521 8007080321	50-367 50-397 50-508 50-397 50-397	0 K 9 A A	Wharton & Pogmlies White, M & Consulting Engineer	8007170244 8007170244 8007100404 8007110377* 8007150242	50-440 k 50-440 k 50-361 0	K 0 0
	8007070023 8007070317* 8007070322* 8007070476 8007070680	50-397 50-397 50-397 50-397 50-397	g K K A K	Whiting Corp Widoff, Reager, Belkowit: & Adler	8009150148 8009020407 8009240535 8009240536* 8009240538*		=  { 
	8007100179 8007110422* 8007120360 8007120363* 8007120568 8007160312	50-508 50-460 TOPREP TOPREP 50-397 50-397	a K	William F Kirk Hilliam Powell Co Winthrop, Stimson, Putnam & Roberts Wisconsin Electric Power Co	8007300527 8007170365 8007170365 8007230597 8007020497	50-269 50-201 50-358 50-412 50-266	p
	8009140622	50-460	G		8009030542	50-266 F	*



BO0090090399   S0-266	AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO	)RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOGR	
B009005459		8009090539	50-266	R			50-244	
BOOTO-005455   SO-266   R			50-266	8	Wiscoulding S Sutilibling and account			
Section   Sect							00 -00	•
P					Wisconsin, State of	8007020050	50-266	11
## ## ## ## ## ## ## ## ## ## ## ## ##					#1200#31## 00-10 01			
P								
P		6009140302	50-266	R	Wisconsin, Univ of Madison			
## 18091 1604342   50-266   F		80071603 <b>0</b> 4*	50-266					ă
8009180158   50-266   P   Worster Polytechnic Inst   800920018   50-134   F   8009200648   50-266   P   Worsham, Forsythe & Sampels   8009170399   50-134   F   8009200648   50-266   P   8009200648   8009200249   50-266   P   8009200648   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249   8009200249		8009160442	50-266	P	***************************************			•
S007160158   S0-266   P   Worcester Polytechnic Inst   S00720018   S0-30   P   Worcester Polytechnic Inst   S00720018   S0-30   P   Worcester Polytechnic Inst   S00720018   S0-30   P   S00720018   S0-30   S00720018   S0-30   P   S00720018   S0-	P	9007180159	50-266	G	Woodward-Clude Consultants, Inc	8009190272	50-440	SE.
B009230460   S0-266   P   Worsester Polytechnic Inst   B00920018   S0-134   F   B009170399   S0-243   P   B009170399   S0-243   P   B009170399   S0-243   P   B009180349   S0-264   P   B009180349   S0-264   P   B009180449   S		8009180158	50~266	a		8009240455*	50~3	
B009/230646   S0-2266   F					Worcester Polytechnic Inst	8007020018	50-134	
B009230646   S0-266   P   Hyoming Mineral Corp   B008110034   40-8002   B009250247   S0-266   P   B008110034   40-8002   B009250247   S0-266   P   B0081100314   40-8002   B009250253   S0-266   P   B008120620   40-8002   B008120						8007170359	50-445	ж
8009250247   50-266   P   8008100384   40-8502     8009250248   50-266   P   8008100614   40-8502     8009250249   50-266   P   8008100614   40-8502     8009250215   50-266   F   8008120620   40-8502     8009270177   50-266   F   8008120621   40-8502     8009270177   50-266   F   8008120621   40-8502     8009270177   50-266   F   8008120621   40-8502     8009270178   50-266   P   Wyaming Outdoor Council   800910034   40-8502     8009270141   50-266   P   Wyaming Outdoor Council   8009020508   40-8502     8009270142   50-266   P   Wyaming Outdoor Council   8009020508   40-8502     8009270142   50-266   P   Wyaming Outdoor Council   8009020508   40-8745     8009270143   50-266   P   Wyaming Outdoor Council   8009020508   40-8745     8009270143   50-266   P   Wyaming Outdoor Council   800918055   40-8745     8009270143   50-266   P   Wyaming Outdoor Council   800918055   40-8745     8009270143   50-205   P   800918055   40-8745     8009270143   50-205   P   800918051   50-29   P     8009180315   50-305   P   800918052   50-29   P     8009180315   50-305   P   800918032   50-29   P     8009180315   50-305   P   800918032   50-29   P     8009180315   50-305   P   800918031   50-					Myoming Mineral Corp	8008110036	40-8502	*-
B0092302539   50-266   F   B008120620   40-8502   80092302539   50-266   F   B008120620   40-8502   800923017   50-266   F   B008120620   40-8502   800923017   50-266   F   B00923017   40-8502   8009150023   40-8502   8009150023   40-8502   800923017   40-8502   800923012   40-8502   800923012   40-8502   800923012   40-8502   800923012   40-8502   800923012   40-8502   800923012   40-8502   800923012   40-8502   800923012   40-8502   800923012   40-8502   800923012   40-8502   800923012   40-8502   800923012   40-8502   800923012   40-8502   800923012   40-8502   800923012   40-8502   800923012   40-8502   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8702   40-8								
80091203539   50-266   F   80081206200   40-8502   80081206200   40-8502   80081206200   40-8502   80081206200   40-8502   80081206200   40-8502   80081206200   40-8502   80081206200   40-8502   80081206200   40-8502   80081206200   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   8008120620   40-8502   40-8502		6009250249	50-266			8008110038*	40-8502	
800920053; 50-266 F 80081206240; 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-8502 40-85		8007250253+	50-266	P		6008120614		
8002502535   50-266   F   80081206264   40-8502   80081206264   40-8502   80081206261   40-8502   80081206261   40-8502   80081206261   40-8502   80081206261   40-8502   80081206261   40-8502   80081206261   40-8502   80081206261   40-8502   80081206261   40-8502   80081206261   40-8502   80081206261   40-8502   80081206261   40-8502   80081206261   40-8502   80081206261   40-8502   80081206261   40-8502   80081206261   40-8502   80081206261   40-8502   80081206261   40-8502   8008120626   40-8502   8008120626   40-8502   8008120626   40-8502   8008120626   40-8502   8008120626   40-8502   8008120626   40-8502   8008120626   40-8502   8008120626   40-8502   8008120626   40-8502   8008120626   40-8502   8008120626   40-8502   8008120626   40-8502   8008120626   40-8502   8008120626   40-8502   8008120626   40-8502   8008120626   40-8502   8008120626   40-8502   8008120626   40-8502   8008120626   40-8502   8008120626   40-8502   8008120626   40-8502   8008120626   40-8502   8008120626   40-8502   8008120626   40-8502   8008120626   40-8502   8008120626   40-8502   8008120626   40-8502   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   8008120626   80081						8008120620*		
8009240717   50-264   F   8009290177   50-264   F   8009290177   50-264   F   8009290177   50-264   F   8009290141   50-264   F   8009290341   50-264   F   8009290341   50-264   F   8009290341   50-264   F   8009290341   50-264   F   8009290342   8009100240   40-8502   8009100240   40-8502   8009100240   40-8502   8009290342   50-264   F   8009290342   50-264   F   8009290342   50-264   F   8009290342   50-264   F   8009290344		<b>9007250253</b> ≠	50-266					
\$004270177   \$0-266   F		8009260215	50-266					
B009290341   50-266   P   B009290342   50-266   P   B009203055   B009300461   B009203055   B009300461   B009203055   B009300461   B009203056   B009300461   B0093056   B00930		8009290177	50-266					
8009290341 50-266 P 8009290342# 50-266 P 8009290342# 50-266 P 8009290342# 50-266 P 800920030395 50-266 P 80093030395 50-27 R 80094030395 50-205 R 80094030395 50-205 R 80094030395 50-207 R		B009290177	50-266	F		8008120631#	40~8502	
B007290341   50-266   P   Hyaming Outdoor Council   B00920501   40-8502   B009290342*   50-266   P   Hyaming Outdoor Council   B009020501   40-8502   B009020342*   50-266   P   Hyaming Outdoor Council   B009020490   40-8703   B009020450   50-266   P   Hyaming State of   B009020490   40-8702   B009100288   50-266   P   B009020450   40-8702   B009100288   40-8702   B009100288   40-8702   B009100288   50-305   P   B009003064   50-266   P   B009003064   50-266   P   B009003064   50-305   P   B0090003064   50-305   P   B0090003064   50-305   P   B0090003064   50-305   P   B0090003064   50-29   P   B0090003064   50-305   P   B00900003064   50-29   P   B0090003064   50-29   B0090003064   50-29   B00900003064   50-29   B00900003064   50-29   B00900003064   50-29   B00900003064   50-29   B00900003064   50-29   B00900003064   50-29   B00900000064   50-29   B00900000064   50-29   B0090000064   50-29   B0090000064   50-29   B0090000064   50-29   B00900000064   50-29   B0090000064   50-29   B00900000064   50-29   B0090000064   50-29   B009000064   50-29   B0090000064   50-29   B009000064   50-29   B009		8009290341	50-266	P		8009150023		
B009290341   S0-266   P   Hyoming Outdoor Council   B009020490   40-B502   6009290342*   50-266   P   Hyoming State of   B009020490   40-B502   80093003030   50-266   P   Hyoming State of   B009020490   40-B502   80093003030   50-266   P   Hyoming State of   B009020490   40-B502   8009100289   40-B745   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009100289   8009						8009170240		
S00920942#2   S0-266   P   Wyaming Outdoor Council   S009200508   40-8745   S0-266   P   S009300401   S0-266   P   S00930040   S0-305   S0-305   S00930040   S0-305		8009290341	50-266	Ъ				
B009200342*   B009300305   B00930035   B00930035   B00930035   B00930035   B00930505   B009300505   B0093		8009290342#	50-266	P	Www.ine Outdoor Council			
B009300461   S0-266   P   B00910026552   40-8745   B0091100288   B0091100289   B		B009290342#	50-266	Ъ	.,			
BO07300461   S0-266   P   B007100288   40-8745   B007100288   40-8745   B007100288   40-8745   B007100288   40-8745   B007100355   40-8745   B007100355   40-8745   B00710030512   B007100355   B00710030512   B00710030512   B00710030512   B00710030512   B00710030512   B00710030512   B0071003051   B007100051   B007100051   B007100051   B00710051   B00710051051   B00710051051   B		8009300305	50-2∌6	a	Wyomiπσ, State of	E009020490	40-8502	
Bisconsin Power & Light Co		8009300461	50-266	P				
Bisconsin Power & Light Co						8007100288	40-8102	
Miscensin   Power & Light Co								
## Sconsin Public Service Carp ## 800930906	Wisconsin Power & Light Co	9007090358*	50-305	P				
B009090273   50-305   R	Wisconsin Public Service Carp	8009030504	50-305					
B009090273   S0-305   R     B009170134   40-8745   B009170423   40		8009030512*	50-305			8009160546	40-8745	
8007070277* 800-305 R		8009090273	50-305	R				
809790355 50-305 P 8009030651 50-29 P 8009030651 50-29 P 800910378 50-305 P 800910378 50-305 P 800910378 50-305 P 800910378 50-305 P 800910381* 50-305 P 800910381* 50-305 P 800910381* 50-305 P 800910381* 50-305 P 800910382 50-29 P 800910382 50-29 P 800910382 50-305 P 8009110329 50-27 P 800910342 50-305 P 800910334* 50-305 P 800910345 50-305 P 800910363 50-305 P 8009100363 50-305 P P 8009100363 50-305 P 8009100363 50-305 P 8009100363 50-305 P 8009100363 50-305 P P 800910						8009170423	40-8492	
8007070358					Yantee Atomic Electric Co			Ρ
800970338* 50-305 P 8009110381* 50-305 P 8009110334* 50-27 P						154050908	50-29	
8007110381* 50-305 P 80079080526 50-27 0 80079080526 50-27 0 9 800710381* 50-305 0 800710324* 50-27 P 8007240473 50-305 S 8007110324* 50-27 8 8007240501* 50-305 S 800710324* 50-27 8 8007240508* 50-305 S 800710324* 50-27 R 80072405081 50-305 O 800710334* 50-27 R 80072405081 50-305 O 800710338* 50-27 R 80072405081 50-305 O 8007180381 50-27 R 8007270173 50-305 F 8007180381 50-27 R 8007270173 50-305 F 8007180381 50-27 R 8007270173 50-305 F 8007180381 50-27 R		8009090358*						
800910381* 50-305 P 8009080526 50-29 Q 8009080526 50-29 Q 800910342 50-29 P 80091034* 50-29 P 90091034* 50-29 P 90091004** 50-29 P 90091004** 50-29 P 90091004** 50-29 P 90091						8009080522	50-29	O.
B009150464*   50-305   C   B009100342   50-29   P		8007110381*	50-305	P		8009080526	50-29	
\$007150444						6009100542	50-29	
B007240473   S								
8009240501* 50-305 S 8009240508* 50-305 S 8009260061 50-305 G 8009260081 50-305 G 8009260081 50-305 G 8009260081 50-305 G 8009290173 50-305 F								
8009260061 50-305 Q 8009160303* 50-29 R 6009180351 50-29 R 8009260081 50-305 Q 8009180355* 50-29 R 8009290173 50-305 F 8009180355 50-29 P				s				
8009260061 50-305 Q 8009160303* 50-29 R 6009180351 50-29 R 8009260081 50-305 Q 8009180355* 50-29 R 8009290173 50-305 F 8009180383 50-29 P						8009160289	50-27	R
8009260081 50-305 Q 8007180351 50-29 R 8007270173 50-305 F 8007180358* 50-27 R 8007270173 50-305 F		8009260061	50-309	Q				
8009260081 50-305 0 8009180355* 50-29 R 8009290173 50-305 F 8009180383 50-29 P								
8009290173 50-305 F 8009180383 50-29 P		8009260081	50-305	a				
				F				
		8009300425	50-305					

#### REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents,"

REPORT NUMBER	ACCESSION NUMBER	BUBJECT CATEGORY	OTHER REPORT NUMBER
01-0910-1087 69-1106001-00 77-03 79-4 80-059	8007070088 8007260366* 8007070636* 8007050418* 8008080302*	50-263 0 50-289 T 50-275 T 50-395 A 50-329 F	
80-1120838-00 8007020366 8007030010 8007050200 8007050397	8009100176* 8009020366 8009030010 8009050200 8009050399		648 E00-EA-5204 EEG-LOFT-5199 8052794 UBNRC-P394
8009050405 8009050409 8009090132 80090907770	8007050405 8007050407 8007070132 8007070770	RES RES RES	EGG-TFBP-5193 DRNL/MRBT-5
8009100412 8009100508 8009100520 8009100530 8009110416 8009110419	8009100412 8009100508 8009100520 8009100530 8009110416 8009110419	REB REB RES RES REB REB	EGG-TFGF-5218 ORNL/FTR-868 EGG-TFBP-5171 EEG-CDAP-5216
8009110421 8009110483 8009110498 8009110574 8009110634	8009110421 8009110483 8009110498 8009110574 8009110634	RES RES RES RES	ORNL/HASRD-90 ORNL/FTR-892 ORNL/HASRD-89
9009110876 8009110889 8009120547 8009120571 8009120572	8007110876 8007110885 8007120567 8007120571 8007120572	RES RES RES RES	ORNL/MASRD-88 ORNL/CSD/1NF/80 WX-8-3775
8009120579 8009120581 80091205890 8009120639 8009120646	8009120579 8009120581 8009120590 8009120639 8009120666	REB REB	EGG-EA-5186 GRNL/FTR-897 NRC-04-76-323 EGG-EA-5220 LO-MR-007
B009120733 B009150311 B009150543 B009160492 B009160498	8009120733 8009150311 8009150843 8009160492 8009160498	RES RES RES RES RES	ORNL/ED/EAS-80 WX-8-3784 89-80-08-02
8009180309 8009190401 8009190768 8009240253 8009240291	8009180309 8009190401 8009190768 8009240253 8009240291	50-336 P RES RES RES RES	E00-EA-5214 BNL-NUREG-28199 E00-CDAP-5166 DRNL/ED/EI8-134
BOO9260069 BOO9260075 BOO9260084 BOO9260179 BOO9260110	9009240049 8009240075 8009240084 8009240099 8009240110	RES FES 50-316 P RES 50-263 P	USNRC-P394 RE-A-80-055 E00-EA-5229 E00-TFBP-5221
3007260520 3007260542 3007260530 3007260558 3007260568	8009260520 8009260542 8009260550 8009260558 8009260568	REB REB RES	EGG-EA-5228 EEG-GAAP-5191 GRNL/HASRD-76 EGG-TF8P-5222 EGG-EA-5220

REPORT NUMBER	ACCESSIGN NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
84-1103595-00	B009260340*	50-289 T	ISSUANCES SP
86-1117679-000	B009260380*		ISSUANCES SP
86-1120838-00	8009290373*	50-329 A	
B&RCE-COM4-1-NP R2 B&W-10043	8007030364* 8007260402*	TOPREP 50-289 T	ISSUANCES SP
PWW-10043	6001260402×	30-207	1990Wifee of
BAH-10103A R3	B009260329*	50~289 T	168UANCES BP
BAW-1634	8009030519*	50-267 P	
BNL-NURE0-28090	8009220395	TOPREP	
CE-1-A R14 CE-1-A R14A	8009100548* 8009230684*	TOPREP TOPREP	
OC A H RAMA	DOO'IEDOOG!	10,110	
CE-78-14	8009090472*	50-275 T	
CE-79-02	8007070664*	50-275 T	
CEB-78-14 R1 CEN-135(B)-NP	8009150468* 8009050308*	50-438 A 50-361 A	
CEN-137(8)	8009230646*	50-317 P	
CEN-138(B)	8009230650*	50-317 P	
CENPD-254-NP-A	8009240527*	TOPREP 50-237 P	64 801 0013
COM-0708-03 CRBRPARD-0204	8009020111* 8009020017*	50-237 A	64 801 0013
CURL-2 81	8007230452*	50-157 P	
EA 80-01	B009260468*	50-237 P	
EDAC 117-250 03 FD-CPH-002 R1	8009180477* 8009300236*	50-70 P 50-155 P	
QA-C15847	8009220321#		1900
0EAP-25163-2	8009160436*	TOPREP	UC-78
NEDD-10329 NEDD-20776 RS	8009300483* 8009300586*	TOPREP 70-1308	
NEDO-20776 NS NEDO-24085-1 R1	8009300307*		BONEDZ81
NEDO-24757	8009050329*	TOPREP	BONEDOSA
NEDO-2479B	8009230431*	TOPREP	BONED585
NEDG GADA	8009230475*	TOPREP	00NED057
NEDO-24811 NUREO 0020 V4 NO8	B007230475*	NUREO	ONE DUO?
NUREQ-0011 DRFT 82	6007110343*	50-327 P	
NUREG-0011 DRFT 53	6009110355*	50-327 P	
NUREG-0011 82	8007080423¥	50-327 €	
NUREQ-0011 93	8009260258*	50-327 €	
NUREG-0053 912	8009110505	50-339 E	
NUREG-0134 ADD 2	8009150523	50-338 D	
NUREG-0436 NO1 81	8009110639	NUREO	
NUREG-0540 V2 N05	8009020373	NUREO	
NUREG-0540 V2 NO6	8009120333	NUREO	
NUREG-0606 V2 NO3	8007300308	NUREO	
NUREG-0653	8009100407	NUREO 50-339 P	
NUREQ-0664 R1 APP A NUREQ-0664 R1 APP B	8009140661* 8009140663*	50-339 P	
NOTICE COST III FITE			
NUREQ-0678	8009100158	NUREO	
NUREG-0579 NUREG-0685	8009120337 E00000003	NUREG NUREG	
NUREO-0702	8007020504*	40-299	
NUREQ-0715	8009120626	50-247 P	
W.000 MT40 DDCT	0000100100	NUREO	
NUREG-0718 DRFT NUREG/CR-0200 VI	8009120528 8009160202	NUREO	ORNL/NUREQ/CE
NUREG/CR-0603	8007100750	NUREO	BNL-NUREG-509
NUREO/CR-0761	8009110500	NUREO	UCRL-52707
NUREG/CR-0893	8009160481	NUREO	PNL-3046

### REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
NUREO/CR-1038	8009120339	NUREG	UCRL~52723
NUREQ/CR~1045	8009160450	NUREG	
NUREO/CR-1113	8009240605	NUREG	UCLA-ENG-7953
NUREQ/CR-1120 V3	8009120339	NUREO	
NUREO/CR-1185	6009100036	NUREG	LA-7199-MS ADDI
NUREG/CR-1282	8009300140	NUREG	SAND79-2300
NUREG/CR-1278	8009160456	NUREO	PNL-3158
NUREG/CR-1302	8009150597	NUREO	PNL3278
NUREO/CR-1333	8009160198	NUREO	TN-314
NUREG/CR-1340	8009020483	NUREG	956-R-80-4217
NUREQ/CR-1347	8007100744	NUREO	ORNL/NUREQ-62
NUREQ/CR-1347	8009100403	NUREO	PNL-3040-4
NUREG/CR-1358	8009190405	NUREC	UCLA 12-1235
NUREO/CR-1377	8009020349	NUREG	SAND80-0644
NUREC/CR-1402	8009110321	NUREG	BNL-NUREG-51177
NUREG/CR-1404	8009100947	NUREO	BNL-NURE0-51179
NUREG/CR-1410 VI	8009120502		SAND80-0617/1
NUREO/CR-1411 V2	6009300169		LA-8306-M8
NUREO/CR-1428	8004240488	NUREC	PNL-3411
NUREO/CR-1448	8009020361	NUREO	4001-0BDMAR
NUREG/CR-1450	8009100954	NUREO	ORNL/NUREO/TM-3
NUREG/C#-145B	8009100053	NUREO	LF-71
NUREG/CR-1471	8007150574	NUREO	LA-URBO-45-15
NUREG/CR-1402	8009020358	NUREG	ORNL/NUREG/TM-3
NUREG/CR-1404	8007070020	NUREG	HEDL-THE 80-24
NUREO/CR-1485 VI NO1		NUREO	UCRL-52715-80-1
NUREQ/CR-1487	6009040437	NUREO	
NUREG/CR-1492	8009190398	NUREG	9AND80-1117
NUREG/CR-1509	8009190743	NUREO	SANDBO-1304/10F
NUREG/CR-1514	8009110503	NUREG	LA-8277-PR
NUREG/CR-1521	8009100953	NUREC	ORNL/NUREQ/TM-3
NUREO/CR-1527	8009170782	NUREO	
NUREO/CR-1529	8009260536	NUREO	ORNL/NUREG-72
NUREO/CR-1539	8007160473	NUREO	ORNL/SUB-7615/1
NUREQ/CR-1847	8009100413	NUREO	PNL-3314
NUREG/CR-1561	8009240669	NUREG	SAND80-1495
NUREG/CR-1563	8009030671	NUREO	ORNL/NUREO/THI-
NUREQ/CR-1579	6007260072	NUREG	SAND 80-1618
NURE0/CR-1582 V2	8009180446	NUREO	
NURE0/CR-1582 V3	8007180434	NUREO	
NUREO/CR-1583	8009080402		ANL/EB-97
NUREQ/CR-1592	8009020479		ANL-40-40
NUREQ/CR-1593	6009160446	NUREO	
"UREO/CR-1402	8009020355	NUREO	
JREG/CR-1607	8007020161	NUREO	LA-8449-H8
JREG/CR-160B	B0091505B5	NUREO	CG8/NR85F06D
JREG/CR-1409	8009120336		C95/NR85U040

REPORT NUMBER	ACCESSION NUMBER	BUBJECT GATEGORY	OTHER REPORT NUMBER
NUREG/CR-1625 NUREG/CR-1631	8009100043 8009240028	NUREO NUREO	BH1-2058
NUREO/CR-1634	8009150599	NUREG	LA-8475-MB
NUREG/CR-1657 NUREG/CR-1662 V1	8009300164 8009020493	NUREO 50-320 P	BW1-5095
NUREO/CR-1677 V1 ORNL/TM-7448	6009240686 6009030534*	NUREO 50-320 P	BNL-NUREG-51267
RH-80-4-ED2	8009220041*	40-1341	100FR 040 65
RH-80-5-8F-3	8009110353*	50-259 R	
RH-80-4-501	8009090418*	50~327 R	
EDTAR-80-05-03	8009170314*	50-244 P	
SDTAR-80-05-05	8009170296*	50-244 P	
80-80-08-RATGB	8009170301*	50-244 P	
SE-SP-59(80)	8009190378*	50-206 P	
SE-SP-58(80) ERR SECY-75-338	8009190365*	50-206 P	
SECY-75-518	8009230141*	FOIA	
SECY-75-638	8009230274*	FOIA FOIA	
SEC1-73-436	6007E30#74*	FUIN	
SECY-74-286	#66509190366	FOIA	
SECY-76-286A	8007170394*	FOIA	
8ECY-77-200	8009190514*	FOIA	
SECY-77-433	8009190532*	FOIA	
SECY-78-216A	8009150418*	COMMISSION	
SECY-78-371	8009170550*	FOIA	
SECY-79-362	B0091905B7*	FOIA	
SECY-79-430	8009090799	SECY	3370
SECY-79-478	8009050131*	FOIA	
SECY-80-139A	6009180277*	10CFR	
56CY-80-253	8007040461	SECY	
BECY-80-293	8009090083	COMMISSION	
SECY-80-275A	8009090783	50-320 P	
SECY-80-342	8009030252	SECY	
BECY-80-349	8009040459	SECY	
SECY-80-344	8009250280*	10CFR	
SECY-80-393	8009240569	8ECY	
BECY-80-408	8009290405	SECY	
SECY-80-414	8009290032*	10CFR	
8ECY-A-80-138	8009290452	50-344 Q	
TVA-TR75-1A R4	8007020103*	TOPREP	
WGAP-9765	8009190453*	TOPREP	
WCAP-9768	8007080277#	90-348 P	
WPP88-GA-004 R4	8009120363*	TOPREP	
XN-52-02 R1	8009260117*	71-6581	17119
XN-NF-79-59(NP)	8009260482*	TOPREP	
XN-NF-79-71 (NP) R1	8009260487#	TOPREP	
XN-NF-80-19(NP) V1	8009260493*	TOPREP	
XN-NF-80-17(NP) V2A	8009260498*	TOPREP	
XM-NF-80-17(NP) V2B	8009240504*	TOPREP	
E0A10LE001Y	8009020412#	50-294 P	
Y1003J01A09	B009300302*	50-245 P	

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date Issued, and the category enables locating the title listing of the enclosure.

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

SUBJECT CATEOORY

50-361 50-361 50-213

50-369

50-269 50-263 50-346 50-348

50-296 50-282 50-155 50-250 50-320

50-206 50-207 50-201 50-206

50-206 50-370 50-483 50-206 TOPREP

50-237 50-445 50-320 50-331 50-320

50-320 50-320 50-320

50-329 50-219 40-4492 COMMISSION COMMISSION

COMMISSION

COMMISSION

50-280 Q COMMISSION

Ġ

50-280 50-259

50-315 70-984 50-397

50-344

HHPH

8

ACCEBBIO	N NUMBER				ACCESS 101	NUMBER	
	PRINCIPAL	DATE	BURJECT			PRINCIPAL	DATE
ENCLOSURE	DOCUMENT	IBBUED	CATEODR	,	ENCLOSURE	DOCUMENT	ISSUED
					~		
7904120082	7904120080	79/04/05	PT9		8009020007	8009020006	80/08/22
7906010086	7906010084	79/03/23	PT9		8007020010	8009020005	80/08/22
7908010088	7906010084	79/03/23	PT9		6007020016	8009020015	80/08/22
7906010091	7906010084	79/03/23	PT9		8009020017	8009020014	80/08/22
7906290556	7906290524	79/05/18	PT <del>S</del>		8009020033	8009020029	80/08/25
7911090077	7911090069	79/10/25	PT9		8009020035	8009020034	80/08/20
7912040156	7912040149	79/11/21	PT <del>S</del>		8007020047	8007020044	80/08/25
7912190023	7912190014	79/10/03	PT <b>S</b>		8009020040	8009020055	80/08/25
7912190047	7912190014	79/10/03	PT9		8007020061	8009020057	80/08/26
7912190054	7912190014	79/10/03	PTS		840020008	8003050095	80/08/22
7912190067	7912190014	79/10/03	PT <del>S</del>		8009020074	8009020069	80/08/26
7912190073	7912190014	79/10/03	PTT		8007020074	B009020072	60/0B/25
7912190080	7912190014	79/10/03	PTT		9009020077	8007020070	80/0E/25
8001020073	B001020069	79/12/10	PTS		8007020079	8009020073	80/08/27
8001020078	8001020069	79/12/10	PTS		8007020080	8009020075	80/08/22
8001020083	8001020067	79/12/10	PT <del>9</del>		*******	******	20 (SD (B)
8001020105	8001020087	79/12/10	PTS		8009020083	0009020078	90/08/21
8001020108	8001020069	79/12/10	PT <del>S</del>		8009020085	6002020082	d0/08/21
8001290281	8001020087	80/01/18	PT <del>S</del>		8007020089	8009020087	80/08/26
8003050219	8003050215	80/01/18	PTS		8009020090	8009020088	80/08/25
0003030417	2003030213	60/01/21	r 17		8009020091	8004050085	80/08/21
8003050224	B003050215	80/01/21	PTT		8009020096	8007020082	80/08/21
8003030226	8003050215	80/01/21	PT9		8007020077	8007020074	80/08/24
8003050232	8003050215	80/01/21	PT9		8009020099	8009020093	80/08/25
6003190525	8003190517	80/02/04	PT9		8007020100	8007020082	80/QB/21
B003190529	8003190517	80/02/06	PT9		8004050103	8009020081	80/08/26
8003190537	8003190517	80/02/06	PT9		8007020111	8009020105	80/08/22
8005090553	8005090552	80/02/28	PT9		B009020112	8007020108	80/08/12
8005300695	8005300691	80/04/21	PT9		B009020124	8009020118	80/08/13
8005300697	8005300691	80/04/21	219		B00902014B	8009020144	80/08/08
8004120884	8006120881	80/05/07	PT9		0007020156	9007020151	80/08/06
8007030202	8007030184	80/06/30	50-280	F	8007020169	8009020166	80/09/06
8007030207	8007030184	80/06/30	20~280	F	8007020171	4410207020	80/08/05
8007290625	8007290624	80/07/23	50-335	F	8007020178	8007020172	80/0B/LI
8008080193	8008080187	80/07/30	40-6659	•	8007020178	8007029173	80/08/05
8008080302	8008080297	80/07/31	50-329	F	8007020171	8009020187	80/08/07
B00811003B	8008110036	80/07/14	40-8502		*****	00000000400	00.100.44
		80/07/14	40-8721		8009020200	8009020193	80/08/11
8008110044	8008110042				8009020204	8009020202	80/08/08
8008120420	8008120614 8008120614	80/07/23 80/07/23	40~8502 40~8502		8009020206	8009020202	80/08/08
8008120626			40-8502		8009020207	8009020202	80/08/08
8008120430	8008120614	80/07/23	40-8502		8007020210	8004050505	80/08/08
B008120631	8008120614	80/07/23	40-8502		8007020212	8004050505	80/00/08
8008130378	6008130375	80/08/05	40-279	_	8007020216	8009020209	80/08/08
8008200284	8008200282	80/0B/15	50-282	F	8009020217	8009020202	80/08/08
8008210418	8008210616	80/08/13	50-327	٩	8007020220	8009020209	80/ <b>08</b> /08
B008260340	8008260337	80/08/21	50-263	F	8009020225	8007020222	60/08/08
8008270280	8008270279	80/08/18	50-361	F	8009020232	8009020227	80/08/08
8008280114	8008280104	80/07/25	50-400	Q.	8009020239	8009020235	80/07/16
E008280126	8008280106	80/07/25	50-400	G G	8007020240	6009020233	80/07/16
8008280495	8008280488	80/08/12	50-254	<u> </u>	8009020246	8009020245	80/08/26
8007020003	8007020002	80/08/29	50-537	B	8007020251	8009020244	80/07/22

ACCESSION	NUMBER			ACCESSION				
ENCLOBURE	PRINCIPAL DOCUMENT	DATE 189UED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT CATEOORY	,
8007020253 8007020237 8007020261 8007020265 8007020267	8009020249 8009020255 8009020254 8009020263 8009020258	80/08/07 80/08/25 80/07/11 80/08/27 80/07/10	50-546 70-33 70-734 50-275 50-361	8009020532 8009020546 8009030040 8009030054 8009030055	8007020528 8007020544 8007030032 8007030048 8007030052	80/08/15 80/08/15 80/07/17 80/08/19 80/08/15	PR 50~370	8 0 P
8007020268 8007020267 8007020270 8007020271 8007020272	8009020263 8009020263 8009020266 8009020266	80/09/27 80/09/27 80/08/27 80/08/26 80/08/27	50-275 50-275 50-275 50-155 50-275	8009030058 8009030062 8009030067 8009030079 8009030085	8007030048 8007030048 8007030061 8007030074 8007030080	80/08/19 80/08/19 80/08/15 80/06/17 80/08/19		P
8007020274 8007020275 8007020277 8007020277 8007020285	8009020263 8009020263 8009020263 8009020276 8009020284	80/09/27 80/09/27 80/08/27 80/08/15 80/08/25	50-275 50-275 50-275 50-304 50-336	8009030098 8009030105 8009030117 8009030133 8009030140	8009030093 8009030102 8009030115 8009030124	80/06/18 80/06/17 80/08/19 80/08/18 80/07/17	50-295	G G
8009020304 8009020308 8009020312 8009020314 8009020317	8009020279 8009020305 8009020303 8009020310 8009020315	80/08/14 80/08/11 80/08/06 80/08/14 80/08/11	50-289 50-289 50-327 50-320 50-320	8009030142 8009030147 8009030150 8009030152 8009030170	8007030134 8007030134 8007030134 8007030147 8007030157	80/08/29 80/08/29 80/08/29 80/08/29 80/08/14	50-409 50-409 50-367	00000
8009020323 8009020332 8009020337 8009020338 8009020343	8007020320 8007020328 8007020303 8007020336 8007020340	80/08/12 80/08/13 80/08/06 80/08/15 80/08/06	50-320 50-320 50-327 50-317 50-155	8007030184 8007030188 8007030174 8007030177 8007030206	8009030178 8009030183 8009030187 8009030183 8009030200	80/08/04 80/08/15 80/08/18 80/08/15 80/08/27	50-320 50-369	G H Q R
8009020350 8009020351 8009020354 8009020359 8009020367	8009020344 8009020346 8009020352 8009020354 8009020362	80/08/27 80/08/25 80/08/27 80/08/29 80/08/29	50-280 50-244 50-297 50-333 50-366	8007030216 8007030243 8007030255 8007030260 8007030264	8007030208 8007030237 8007030252 8007030257 8007030257	80/08/13 80/08/06 80/07/23 80/08/04 80/08/04	8ECY 50-390	P Q
8009020372 8009020374 8009020375 8009020376 8009020383	8009020365 8009020369 8009020368 8009020333 8009020377	80/08/25 80/08/26 80/08/13 80/08/22 83/08/22	50-335 50-366 COMMISSIO 50-346 50-245	8009030270 8009030274 8009030281 8009030314 8009030326	8009030257 8009030257 8009030257 8009030265 8009030323	80/08/04 80/08/04 80/08/04 80/06/11 80/07/16	50-390 50-390 30-387	Q Q A Q
8007020385 8007020385 8007020387 8007020388 8007020391	8009020379 8009020382 8009020378 8009020381 8009020380	80/08/25 80/08/27 80/08/20 80/08/18 80/08/26	50-219 50-293 50-320 50-237 50-324	8007030342 8007030353 8007030361 8007030364 8007030373	8009030338 8009030350 8009030349 8009030359 8009030367	80/07/09 80/08/28 80/08/25 80/08/29 80/08/27	50128 50320 TOPREP	8 8 8
8007020398 8007020379 8007020401 8007020403 8007020405	8007020370 8007020372 8007020375 8007020374 8007020400	80/08/06 80/08/26 80/08/14 80/08/29 80/08/26	50~254 50~219 50~295 50~333 50~366	8007030375 8007030386 8007030375 8007030401 8007030411	8007030368 8007030382 8007030370 8007030380 8007030406	80/08/11 80/08/29 80/08/29 80/08/28 80/08/19	50-3 50-334 50-263	H R R S P
6007020408 6007020412 6007020414 6007020416 8007020422	8009020406 8009020406 8009020404 8009020413 8009020409	80/08/27 80/08/27 80/08/29 80/08/29 80/08/29	50-296 50-296 50-321 50-416 50-333	8007030414 8007030417 8007030417 8007030423 8007030425	8007030405 8007030410 8007030415 8007030418 8007030422	80/08/27 80/08/29 80/08/30 80/08/28 80/08/27	50-358 50-321 50-333	8 R B B
8009020423 8009020427 8009020430 8009020433 8009020434	8007020413 8007020413 8007020413 8007020417 8007020413	80/08/27 80/08/27 80/08/27 80/08/27 80/08/27	50-416 50-416 50-416 50-366 50-416	8007030428 8007030427 8007030435 8007030438 8007030440	8007030426 8007030427 8007030434 8007030436 8007030437	60/08/28 60/08/26 60/08/22 80/08/27 60/08/29	50-348 50-367 50-327	P 8 P P
8007020438 8007020441 8007020444 8007020446 8007020455	8009020413 8009020437 8009020439 8009020436 8009020447	80/08/29 80/08/28 80/08/26 80/08/26 80/08/04	50-416 50-280 50-321 50-321 50-275	8009030444 8009030446 8009030447 8009030449 8009030452	8007030441 8007030443 8007030442 8007030445 8007030450	80/08/07 80/08/29 80/08/26 80/08/29 80/09/01	50-99 50-366 50-269	R P 8 8 P
6009020457 8009020458 8009020462 8009020463 8009020467	8009020452 8009020449 8009020459 8009020456 8009020456	80/08/15 80/08/26 80/08/29 80/08/12 80/08/12	50-295 50-368 50-395 50-10 50-10	8009030453 8009030457 8009030461 8009030463 8009030465	8007030449 8007030454 8007030451 8007030457 8007030462	80/08/13 80/08/27 80/08/25 80/08/29 80/08/29	50-409 50-366	R 8 8 8
8009020469 8009020469 8009020470 8009020472 8009020473	8007020459 8007020461 8007020456 8007020465 8007020456	80/08/29 80/08/28 80/08/12 80/08/11 80/08/12	50-395 50-321 50-10 50-289 50-10	8009030467 8009030469 8009030471 8009030474 8009030478	8009030454 8009030464 8009030466 8009030468 8009030472	80/08/20 80/08/29 80/08/29 80/08/29	50-267 50-331 50-270	R V 8 8 P
8007020474 8007020477 8007020481 8007020486 8007020494	8009020454 8009020464 8009020475 8009020480 8009020487	80/08/12 80/07/14 80/08/19 80/08/20 80/08/15	50-10 50-348 70-2313 XPORTLIC 50-320	8009030482 8009030483 8009030484 8009030487 8009030495	8007030475 8007030477 8007030477 8007030481 8007030491	80/08/27 80/08/27 80/08/27 80/08/28 80/08/28	50-293 50-285 50-287	8 R P R
8007020477 8007020504 8007020515 8007020525 8007020531	8009020492 8009020498 8009020502 8009020522 8009020529	80/08/14 80/08/20 80/08/13 80/08/12 80/08/15	XPORTLIC 40-299 50-320 71-385 REGOD	8009030494 8009030501 8009030512 8009030512 8009030513	8007030488 8007030478 8007030497 8007030506 8007030507	80/08/28 80/08/26 80/08/29 80/08/29 80/08/25	50-266 50-302 50-305	8 P 8 R P

ACCESSION	NUMBER				AGCESSIO				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE IBBUED	SUBJECT		ENCLOBURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT CATEGOS	
8009030514 8009030516 8009030519 8009030522 8009030523	8007030508 8007030507 8007030507 8007030520 8007030517	80/08/29 80/08/14 80/08/25 80/08/29 80/08/27	50-240 50-237 50-287 50-317 50-327	P 8 P 8	8007040387 8007040388 8007040387 8007040370 8007040371	8009040384 8009280311 8009040384 8009040386 8009040386	80/09/02 80/08/22 80/09/02 80/09/02 80/09/02	50-364 50-311 50-364 50-364 50-364	A F A A
8007030530 8007030534 8007030535 8007030538 8007030546	8007030528 8009030529 8009030525 8009030533 8009030539	80/08/25 80/08/22 80/08/28 80/08/27 80/08/27	50-27 50-320 50-280 50-206 50-368	R P B R B	8009040392 8009040393 8009040394 8009040395 8009040392	8008280311 8007040386 8008280311 8007040386 8008280311	80/08/22 80/09/02 80/09/02 80/09/22	50-311 50-364 50-311 50-364 50-311	F A F A F
8007030547 8007030547 8007030561 8007030563 8007030566	8007030544 8007030543 8007030555 8007030554 8007030558	80/08/27 80/08/29 80/08/27 80/08/25 80/08/30	50-155 50-318 50-338 50-528 50-259	R 8 8	8009040398 8009040399 80090404040 8009040403 8009040405	8008280311 8008280311 8008280311 8008280311	80/08/55 80/08/55 80/08/55 80/08/55	50-311 50-311 50-311 50-311 50-311	4 4 4 4
8007030569 8007030571 8007030572 8007030579 8007030586	8007030565 8007030567 8007030568 8007030575 8007030576	80/08/27 80/08/27 80/08/27 80/08/28 80/08/27	50-20 50-337 50-59 50-344 50-337	R 8 8 8	8007040407 8007040408 8007040411 8007040411 8007040414	8008280311 8008280311 8008280311 8008280311 8009040413	80/08/22 80/08/22 80/08/22 80/08/23	50-311 50-311 50-311 50-311 50-244	4 4 4
8007030570 8007030571 8007030574 8007030577 8007030604	8007030588 8007030585 8007030583 8007030574 8007030577	80/08/29 80/08/28 80/08/27 80/08/29 80/08/28	50-358 50-311 50-255 50-293 50-294	F 88 88 88	8007040415 8007040417 8007040443 8007040450 8007040470	8007040413 8007040418 8007040434 8007040434 8007040468	80/09/03 80/08/29 80/08/22 80/08/22 80/07/02	50~244 50~186 50~369 50~369 CONTRACT	P S A A
8007030607 8007030609 8007030607 8007030614 8007030617	8007030603 8007030573 8007030600 8007030606 8007030611	80/08/29 80/08/27 80/08/29 80/08/27 80/08/28	50-293 50-339 50-302 50-338 50-293	8888	8007040474 8007040475 8007040482 8007040487 8007040507	8007040472 8007040473 8007040472 8007040484 8007040506	80/08/15 80/04/05 80/08/15 80/08/22 80/08/19	50-397 70-1257 50-397 50-553 50-267	9 A P
8007030418 8007030417 8007030420 8007030423 8007030427	8009030616 8009030615 8009030613 8009030612 8009030624	60/08/20 80/08/27 80/08/28 80/08/29 80/08/27	50-247 50-339 50-311 50-338 50-255	P 8 8	8009040513 8009040544 8009050087 8009050105 8009050126	8007040506 8007040532 8007050086 8007050103 8007050123	80/08/19 80/08/08 80/09/03 80/08/29 80/08/05	50-267 50-271 50-369 50-336 FOIA	P 0 P
8007030428 8007030432 8007030437 8007030440 8007030643	8007030622 8007030629 8007030634 8007030625 8007030638	80/08/28 80/08/27 80/08/27 80/08/27 80/08/12	50-369 50-339 50-206 50-267 PR	8 8 8	8007050131 8007050174 8007050176 8007050184 8007050190	8007050123 8007050168 8007050173 8007050180 8007050187	80/08/05 80/08/14 80/08/12 80/08/07 80/08/20	FOIA 70-143 70-1151 70-143 50-298	s
8007030644 8007030646 8007030647 8007030647 8007030650	8007030634 8007030641 8007030638 8007030642 8007030648	80/08/27 80/08/27 80/08/12 80/08/27 80/08/17	50-206 50-213 PR 50-338 ACRS	P P 8	8007050176 8007050201 8007050203 8007050204 8007050207	8009050192 8009050192 8009050199 8009050192 8009050205	80/08/18 80/08/18 80/08/18 80/08/18	50-339 50-339 50-298 50-339 71-9508	P B P
8007030658 8007030664 8007030666 8007030667 8007030680	8007030653 8007030662 8007030662 8007030667 8007030678	80/08/27 30/09/02 80/09/02 80/08/15 80/08/11	50-338 50-327 50-327 NUREQ 50-289	8 P P	8007050211 8007050214 8007050216 8007050217 8007050217	6009050208 6009050205 6009050208 6009050210 6009050210	80/07/17 80/08/05 80/07/17 80/08/14 80/08/14	50-255 71-9509 50-255 50-278 50-278	Q Q P P
8007030483 8007030671 8007030475 8007030478 8007030728	8007030681 8007030688 8007030688 8007030677 8007030726	80/08/11 80/08/07 80/08/07 80/07/29 80/08/28	50-289 50-263 50-263 XPDRTLIC 50-282	H F Q	8009050221 8009050241 8009050245 8009050246 8009050247	8007050210 8007050240 8007050243 8007050243 8007050243	80/08/14 80/08/11 80/09/02 80/09/02 80/09/02	50-278 50-312 50-320 50-320 50-320	P 8 8
8007040049 8007040048 8007040083 8007040079 8007040103	8009040039 8009040055 8009040079 8009040087 8009040088	80/08/12 80/07/16 80/08/14 80/07/17 80/08/12	50~313 27-39 50-277 40-2061 50~155	Q F P	8009050249 8009050254 8009050255 8009050254 8009050268	8009050243 8009050250 8009050252 8009050260 8009050265	80/09/02 80/08/18 80/08/18 80/08/18	50-320 50-334 50-298 50-298 50-302	8888
8007040104 8007040107 8007040127 8007040180 8007040208	8007040087 8007040087 8007040125 8007040176 8007040200	80/07/17 80/07/17 80/08/08 80/08/11 80/08/27	40-2061 40-2061 50-263 50-298 50-237	P P O	800705027# 8007050281 8007050289 8007050274 8007050300	8009050274 8009050275 8009050284 8009050290 8009050297	80/08/22 80/08/22 80/08/21 80/09/27 80/09/02	50-244 50-289 50-298 50-272 50-488	V P S R Q
8009040218 8009040251 8009040256 8009040269 8009040274	8007040200 8007040246 8007040255 8007040262 8007040262	80/08/27 80/09/02 80/08/27 80/08/29 80/08/29	50-237 50-364 50-70 50-155 50-155	G A P G Q	6007050303 6007050308 6007050322 6007050324 8007050328	8007050297 8007050302 8007050318 8007050321 8007050325	80/09/02 80/09/03 80/09/02 80/08/20 80/08/25	50-488 50-341 50-271 50-133 TOPREP	O A B V
8007040305 8007040315 8007040330 8007040374 8007040375	8007040299 8007040309 8007040317 8008280311 8008280311	80/08/08 80/08/08 80/07/14 80/08/22 80/08/22	50-266 50-324 50-327 50-311 50-311	P 0 F F	8009050331 8009050335 8009050334 8009050335 8009050336	8007050326 8007050327 8007050337 8007050348 8007050352	80/08/12 80/09/02 80/08/15 80/08/29 80/08/29	50-278 50-338 50-312 50-263 50-414	S R R R
8009040378 8009040379 8009040381 8009040384 8009040385	8008280311 8008280311 8008280311 8008280311	80\08\55 80\08\55 80\08\55 80\08\55 80\08\55	50-311 50-311 50-311 50-311 50-311	# # # #	8009050345 8009050374 8009050376 8009050402 8009050412	8009050363 8009050367 8009050386 8009050383 6009050383	80/07/31 80/08/08 80/08/14 80/08/07 80/08/07	TOPREP 50-320 50-320 FOIA FOIA	P H

#### ACCESSION NUMBER

### NAMES NOT THE PROPERTY OF THE

ACCES	SION NUMBER					REGINAL MOT			
ENCLOSUA	PRINCIPA E DOCUMEN		EURJ CATE		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJ	ECT CORY
80090 504 80090 504 80090 504 80090 504 80090 504	18 80070503 17 80070504 21 80070504 26 80070504	83 80/08/0 14 80/08/2 15 80/07/2 24 80/08/1	7 50-39 1 71-90 3 50-36 5 50-26	5 A 19 4 Q 6 H	8009080\$7 800909002 800909003 800909008 800909008	4 8009090022 8 8009090041 9 8009090041 2 8009090041	80/08/2 80/08/0 80/08/0	1 COMMI 0 50-28 1 50-29 1 50-29	MO188 H 7 O E
80090504 80090504 80090504 80090504 80090504	36 80070504; 41 80070504; 46 80070504; 55 800705044	22 80/08/2 22 80/08/2 12 80/08/0 15 80/08/1	2 50-28: 2 50-28: 8 XPORTI 1 FOIA	0 Q 0 Q	800999006 800909016 800909018 800909018	9 8009090116 9 8009090165 1 8009090165 9 8009090165	80/07/26	50-33 50-21 50-21	4 q 9 q 9 q
900905046 900905046 900905046 900905046	52 800705044 54 800705044 57 800705044 70 800705048	80/08/1 80/07/2 80/07/1 80/07/2	1 FOIA 5 50-31: 4 50-267 5 50-31:	5 P 7 G 5 P	18.040009 18.040008 18.040008 18.040008	8007070202 E120707008 B007070212	80/07/26 80/08/12 80/08/12 80/07/15 80/08/05	XPDRTL XPORTL 50-DRS	IC IC
800905047 800905047 800905046 800905050	77 B00905046 86 B00905046 88 B00905049 01 B00905049	55 80/07/14 12 60/07/14 16 80/08/14 17 80/08/14	50-267 50-410 50-320 50-29	Gr Gr	8009090225 8009090225 8009090224 8009090250 8009090258	8009090222 8009090237 8009090237	80/08/05 80/08/05 80/07/31 80/07/31 80/08/29	50-352	2 0
800705050 800705050 800705050 800705051	7 800705050 9 800705050 0 800705050	0 80/08/11 0 60/08/11 5 60/08/01	50-291 50-155 50-155	b b	8009090259 8009090267 8009000277 8009000277 8009090287	8009090241 8009090265	80/07/21 80/09/01 80/09/04 80/09/05 80/09/05	50-553 50-293 50-204 50-305 50-243	R R
800705051 800705052 800705053 800705053 800705053	2 800705051 1 800705052 3 800705052 4 800705052	7 80/09/15 8 80/09/08 5 80/07/16 9 80/09/08	50-458 50-295 50-498 50-295	P Q P Q P	8007070278 8007070302 8007070308 8007070308 8007070311	8007070274 8007070270 8007070270 8007070303 8007070270	80/09/05 80/08/28 80/09/03 80/09/03 80/09/03	50-295 50-282 50-250 50-333 50-250	R R R
800903053 800905054 800905055 800908004 800908005	7 8009050545 0 8009050545 5 8009080038 3 8009080038	80/08/13 80/08/12 80/08/12	50-349 50-349 PR PR	р 0	8009090319 8009090322 8009090322 8009090333	8009090680 8009090315 8009090680 8009090314 8009090330	80/08/08 80/08/29 80/08/08 80/09/04 80/08/08	50-397 50-311 50-397 50-294 50-339	K R K B P
800908019 800908020 800908023 800908023	7 8007080202 8007080202 9 8007080231	80/08/29 80/08/29 80/08/08 80/08/08	50-461 50-461 50-461 50-332 50-332	A C Q Q	8009090341 8009090342 8009090343 8009090347 8009090348	6007070332 6007070337 6007070338 6007070344 8007070337	80/09/05 80/08/12 80/08/11 80/08/28 80/08/12	50-296 50-247 50-339 50-338 FOIA	8 0 0 P
8009080261 8009080270 8009080299 8009080315	9009080286 9009080294 9009080317 9009080323	80/08/05 80/08/18 80/07/25 80/08/21 80/08/29	FOIA 50-333 50-348 50-346 50-286	G P R R	8007070347 8007070382 8007070383 8007070361 8007070363	8007070346 8007070344 8007070355 8007070359 8007070337	80/08/08 80/08/28 80/09/04 80/09/03 80/08/12	50-339 50-338 50-305 50-333 50-247	P P 8 0
8007080326 8007080334 8007080335 80070803341	8009080333 CCC0807008 BCC0807008 BCC0807008	80/09/08 80/09/04 80/09/04 80/09/04 80/09/02	50-204 50 133 50-133 50-133 50-254	P R R R	8007070365 8007070371 8007070373 8007070374 8007070381	8007070351 8007070368 8007070353 8007070367 8007070354	80/08/28 80/09/02 80/09/02 80/09/05 80/08/14	50-219 50-219 50-219 50-293 50-219	9 R 8 8
8009090342 8009080352 8009080354 8009080364 8009080367	8007080340 8007080350 8007080354 8007080351 8007080360	80/08/29 80/09/02 80/08/29 80/09/02 80/08/29	50-277 50-317 50-327 50-261 50-327	R F S S	8007070382 8007070385 8007070385 8007070398 8007090401	8009090377 8009090378 8009090354 8009090392 8009090389	80/09/04 80/09/03 80/09/05 80/09/08 80/08/26	50-244 50-348 50-282 50-528 50-293	P 8 0 0 8
8007080380 8007080381 8007080371 8007080401	8087080373 8007080375 8007080382 8007080375 8007080378	80/08/29 80/08/28 80/09/02 80/09/02 80/08/11	50-327 50-271 50-327 50-306 50-265	8 8 8 8	8007070403 8007070412 8007070418 8007070426 8007070432	8007070397 8007070405 8007070414 8007070422 8007070425	80/09/03 80/09/04 80/08/29 80/09/02 80/08/29	50-123 50-334 50-327 50-293 50-313	ያ የ የ
8009080414 8009080417 8009080423 8009080424 8009080427	8007080405 8007080412 8007080419 8007080418 8007080422	80/09/02 80/08/13 80/09/04 80/09/02 80/08/19	50-255 50-265 50-327 50-255 50-254	8 E 8	8009090433 8009090439 8009090441 8009090455 8009090460	8007070430 8007070428 8007070437 8007070447 8007070443	80/09/02 90/09/04 80/09/04 80/08/28 80/09/04	50-293 50-366 50-311 50-311 50-321	6 9 8 8
8009080437 8009080438 8009080445 8009080457 8009080462	8007080432 8007080433 8007080442 8007080454 8007080457	80/09/02 80/08/28 80/08/15 80/08/19 80/08/06	50-255 50-312 71-4968 71-9039 State Pro	B P	8007070462 8007070474 8007070477 8007070480 8007070481	8007070445 8007070458 8007070468 8007070467 8007070467	80/09/04 60/09/05 80/08/29 80/09/02 80/08/29	50-260 50-155 50-309 50-321 50-260	8 8 8 8
8009080467 8009080475 8009080478 8009080480	8007080465 8007080472 8007080474 8007080479	80/07/09 80/08/20 80/08/11	0A999 40-3453 50-166 40-3453 40-3453	ħ.	8007070487 8007070491 8007070495 8007070307 8007070508	8009090471 8009090482 8009090486 8009090504	80/09/03 80/09/05 80/09/04 80/08/29 80/09/03	50-295 50-313 50-364 70-143	0 P B
			50-278 50-278	0 0 0	8007070507 8009090511 8009090512 8009090519 8009090520	8007070500 8007070477 8007070505	80/09/05 80/09/05 80/09/03 80/09/05 80/09/03	50-329 50-338 50-285	8 8 8 K

### ACCESSION NUMBER PRINCIPAL

i

		NONBER				ACCESSIO	N NUMBER			
	ENCL OSURE	PRINCIPAL DOCUMENT	DATE	SUBJECT CATEODR	Y	ENCLOSURE	PRINCIPAL DOCUMENT	DATE IGSUED	SUBJECT CATEGOR	
	8009090526 8009090536 8009090537 8009090540 8009090545	8007070514 8007070525 8007070532 8007070535 8007070537	80/09/03 80/08/27 80/08/29 80/09/04 80/08/29	50-275 50-285 50-458 50-271 50-266	K S F R	8009100116 8009100119 8009100129 8009100122 8009100122	8009100111 8009100096 8009100118 8009100111	80/08/22 80/08/14 80/07/09 80/08/22 80/08/22	COMMISSI XPORTLIC 50-440 COMMISSI COMMISSI	Q DN
	8009090550 8009090558 8009090560 8009090563 8009090565	8007070542 8007070554 8007070555 8007070543 8007070557	90/08/28 80/08/28 80/09/03 80/09/04 80/09/04	50-311 50-311 50-259 50-259 50-259	8 P I B	8009100126 8009100128 8009100131 8009100134 8009100140	8009100118 8009100111 8009100094 8009100132 8009100132	80/07/09 80/08/22 80/08/14 80/07/21 80/07/21	50-440 COMMISSI XPORTLIC 50-255 50-255	
	8007070568 8007070580 8007070582 8007070583 8007070584	8007070562 8007070574 8007070577 8007070527 8007070538	80/09/03 80/09/02 80/09/03 80/09/02 80/09/05	50-313 50-546 50-269 50-327 50-339	8 H R S	8009100146 8009100148 8009100149 8009100191 8009100156	8009100130 8009100143 8009100130 8009100145 8009100154	80/05/23 80/07/23 80/05/23 80/08/23 80/07/24	50-389 50-10 50-389 50-320 50-331	0 0 P 0
	8007070586 8007070588 8007070587 8007070570 8007070571	8007070541 8007070531 8007070578 8007070547 8007070587	80/09/05 80/09/03 80/09/02 80/08/28 80/09/04	50-338 50-327 50-272 50-327 50-272	8888	8009100161 8009100170 8009100191 8009100193 8009100197	8007100154 8007100172 8007100188 8007100187 8007100188	80/07/24 80/09/08 80/06/18 80/06/12 80/06/18	50-331 50-346 40-6659 70-1143 40-6659	G P
1	8007070375 8007070404 8007070407 8007070408 8007070411	8007070593 8007070592 8007070601 8007070602 8007070592	80/08/28 80/07/30 80/07/30 80/08/26 80/07/30	50-272 50-320 COMMISSI: 50-289 50-320	5 P ON 1 P	8009100205 8009100217 8009100217 8009100219 8009100222	8007100188 8007100188 8007100188 8007100208 8007100188	80/04/18 80/06/18 80/06/19 80/06/18	40-6659 40-6659 40-6659 0A999 40-6659	
1	8009090619 8009090624 8009090627 8009090630 8009090633	8007070614 8007070624 8007070621 8007070614 8007070621	80/07/31 80/08/28 80/08/25 80/07/31 80/08/25	XPORTLIC 71-7096 30-367 XPORTLIC 50-367	0	8007100223 8007100227 8007100231 8007100235 8007100235	8009100208 8009100208 8009100208 8009100232 8009100232	80/08/22 80/08/22 80/08/22 80/08/14 80/08/14	QA999 QA999 QA999 70-1257 70-1257	
1	B007070634 B007070635 B007070642 B007070648 B007070651	8007070614 8007070621 8007070636 8007070644 8007070637	80/07/31 80/08/25 80/09/04 80/07/21 80/08/14	XPORTLIC 50-367 50-245 50-482 COMMISSI	e O N	8009100242 8009100250 8009100258 8009100262 8009100273	8009100239 8009100241 8009100241 8009100252 8009100269	80/07/02 80/08/22 80/08/22 80/07/05 80/07/31	50-344 50-400 50-400 50-280 50-445	R G G S G
1	8007070654 8007070655 8007070656 8007070662 8007070664	8007070430 8007070437 8007070432 8007070637 8007070632	80/08/01 80/08/14 80/09/05 80/08/14 80/09/05	COMM 18810 50-275 COMM 18810	Ť	8007100275 8009100279 8009100300 8009100300 8009100307	8009100268 8009100269 8009100290 8009100237 8009100237	80/08/26 80/07/31 80/08/20 80/08/22 80/08/22	50-333 50-445 70-1113 50-364 50-364	R Q Q
£	9009090672 9009090769 9009090775 9009090786 9009090788	8009090452 800909070768 8009090773 8009090785 8009090784	80/09/05 80/08/29 80/08/27 80/08/08 80/09/05	WASTE MOT 50-286 50-280	T F O	8007100387 8007100372 8007100377 8007100377 8007100407	8009100384 8009100384 8009100384 8009100384 8009100405	60/08/11 60/08/11 60/08/11 60/08/11 60/08/22	50-334 50-334 50-334 50-334 CONTRACT	G G G
E	9007070798 9007070798 9007070813 9007070848 9007100003	8007070771 8007070771 8007070812 8007070844 8007100002	80/09/05 80/09/05 80/07/16 80/08/20 80/08/22	50-367 50-312	9998	8009100453 8009100461 8009100463 8009100467 8009100505	8009100449 8009100449 8009100457 8009100449 8009100500	80/09/05 80/09/05 80/08/27 80/09/05 80/09/03	50-344 50-344 50-275 50-344 50-282	8 H S G
£	8009100012 8009100024 8009100025 8009100026 8009100028	8009100010 8009100021 8009100022 8009100022 8009100022	80/08/08 80/08/21 80/08/05 80/08/05 80/08/05	50-952 50-952	T 0 0	8009100548 8009100617 8009100638 8009100638 8009100641	8009100532 8009100609 8009100632 8009100631 8009100631	80/07/05 80/07/04 80/06/20 80/08/28 80/08/28	TOPREP 50-334 M180 50-247 50-247	P P
6 6	009100030 009100038 009100041 009100044	8009100022 8009100037 8009100035 8009100034 8009100047	80/08/03 80/07/09 80/08/11 80/07/08 80/06/19	50-293 CONTRACT 50-219	G G G	8007100645 8009100646 8009100647 8009100651 8009100652	8009100631 8009100642 8009100634 8009100634 8009100642	80/08/13 80/08/13 80/08/14 80/08/14	50-247 70-371 70-312 70-312 70-371	þ
6	009100055 009100057 009100059 009100061 009100072	8009100033 8009100033 8009100047 8009100054 8009100067	80/07/16 80/07/16 80/06/19 80/08/18 80/06/30	50-267	a a a	8009100453 8009100457 8009100475 8009100477 8009100745	8009100650 8009100654 8009100673 8009100674 8009100741	80/08/28 80/08/28 80/07/31 80/07/07 80/08/18	50-192 40-4492 50-280 50-298 70-754	P Q
89 88	009100074 009100076 009100077 009100078 009100080	8009100068 8009100067 8009100071 8009100073 8009100070	80/08/14 80/06/30 80/05/01 80/08/20 80/08/17	27-47 CONTRACT 50-352	U O	8009100748 8009100795 8009100811 8009100811 8009100813	8007100741 8007100770 8007100801 8007100801 8007100801	80/09/18 80/09/24 80/09/24 80/08/24 80/08/26	70-754 70-27 50-269 50-269 50-269	0 0 0
8 8	009100091 009100093 009100097 009100101 009100102	8009100085 8009100084 8009100094 8009100096 8009100098	80/08/23 80/08/20 80/08/19 80/08/14 80/08/20	50-87 COMMISSIO State Pro XPORTLIC COMMISSIO	9	8009100816 8009100830 8009100833 8009100841 8009100844	8009100824 8009100824 8009100826 8009100836 8009100842	80/08/26 80/08/28 80/08/28 80/08/25 80/08/13	50-269 50-461 50-461 50-267 50-298	0 0 0 0
9	009100107 009100108 009100110 009100112 009100114	8009100098 8009100098 8009100104 8009100105 8009100111	80/08/20 80/08/20 80/08/19 80/08/15 80/08/22		R P O	8007100853 8009100861 8009100870 8009100877 8009100884	8009100847 8009100857 8009100865 8009100874 8009100881	80/07/18 80/07/25 80/07/25 80/07/23 80/07/21	50-247 50-277 50-412 50-273 50-352	0 0 0

					ACCESSION				
ACCESSION	PR INC IPAL	DATE	SUBJECT	,	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUDJECT CATEODRY	
ENCLOSURE	DOCUMENT	159UED  80/07/21	CATEGOR 50-387		8009110379	8009110375 8009110378	80/07/31 80/09/08	CONTRACT 50-305 F	
8007100893 8007100897 8007100706 8007100710	8009100899 8009100895 8009100902 8009100902 8009100902	80/07/21 80/08/14 80/08/14 80/08/14	50-289 70-143 70-143 70-143	G	8009110381 8009110393 8009110399 8009110404	8007110371 8007110374 8007110402	80/09/03 80/09/03 80/08/29	70-143 50-361 0 40-2259	
8007100714 8007100720 8007110002	8009100917 8009110001	80/08/07 80/08/08	ACRS CONTRACT		8009110407 8009110410 8009110413	8009110402 8009110409 8009110408	80/08/29 80/08/25 80/08/15	40-2259 CONTRACT COMMISSION	4
8009110003 8009110004 8009110005	8009110001 8009110001 8009110001	80/08/08 80/08/08	CONTRACT CONTRACT CONTRACT		8009110414 8009110418	8009110401 8009110417	80/08/01 80/07/29	50-387 E COMMISSION	١
8009110025	B009110022	80/07/28 80/08/14	CONTRACT 50-349	P	8009110422 8009110424	8009110415 8009110415 8009110423	80/08/20 80/08/20 80/08/13	50-460 0 50-460 0 50-413 0	1
8007110031 8007110033 8007110035 8007110044	8009110030 8009110030 8009110034	80/08/14 80/08/14 80/09/03	50~348 50~348 50~445	P P Q	8009110425 8009110426 8009110427	8007110423 8007110415 8007110423	80/08/13 80/08/13	50-413 G	3
B009110050	8009110047	80/07/25	50-334 50-397	g A	8009110429 8009110433	8009110415 8009110431	80/08/20 80/09/08	50-460 C	
8007110061 8007110066 8007110135 8007110137	8009110056 8009110056 8009110122 8009110122	80/08/26 80/08/26 80/08/27 80/08/27	50-377 70-1151 70-1151	Ä	8009110443 8009110491 8009110502	8007110496 8007110496 8007110477	80/08/26 80/08/25 80/08/25	TOPREP 50-320 L XPORTLIC	į
8007110137	8009110122	80/08/27	70-1151		8009110516 8009110518	8009110512 8009110509	80/08/19 80/07/30	50-315 F 50-219 G	
8009110150 8009110153 8009110154 8009110161	8009110126 8009110126 8009110126	80/08/27 80/08/27 80/08/27 80/08/27	70-1113 70-1113 70-1113 70-1113		8009110520 8009110533 8009110581	8007110514 8007110527 8007110575	80/08/21 80/09/08 80/07/29	50-275 U FOIA 50-255 F	
6009110166	8009110121	80/08/27 80/08/27	50-250 50-250	a a	8007110583 8007110584	8009110552 8009110579	80/08/18 80/08/18	50-433 P 50-315 P	
8007110167 8007110173 8007110177 8007110181	8009110121 8009110121 8009110111 8009110118	80/08/27 80/07/28 80/08/27	50-250 50-518 50-327	Q Q Q	B009110587 B009110589 B009110594	8009110492 8009110575 8009110575	80/08/25 80/07/29 80/07/29	XPORTLIC 50-255 P 50-255 P	
9009110198	8009110118	80/08/27	50-327	a Q	8009110594 8009110597	8009110592 8009110595	80/08/25 80/08/24	XPORTLIC 71-109	
8009110191 8009110198 8009110202 8009110208	8009110118 8009110107 8009110102 8009110099	80/08/27 80/07/29 80/07/29 80/07/29	50-327 50-395 50-348 27-39	Q Q	8009110418 8009110627 8009110633	8007110613 8007110620 8007110632	00/04/30 00/07/22 00/08/08	GA999 50-282 G XPORTLIC	1
8009110214	8009110689	80/09/03	XPORTLIC		8007110652 8007110656	8009110648 8009110655	90/08/04 90/07/25	50-201 R 50-358 0	
8009110222 8009110244 8009110249 8009110252	8009110215 8009110227 8009110221 8009110221	80/07/28 80/07/15 80/04/26 80/06/24	CONTRACT 70-754 70-820 70-820		8009110661 8009110675 8009110692	8009110655 8009110665 8009110684	80/07/25 80/08/15 80/07/10	50-358 0 50-454 0 50-201 0	•
8009110256	8009110253	80/08/19	CONTRACT		8009110730	8009110727 8009110732	80/08/20	50-255 0 50-254 0	
8007110267 8007110272	8009110263 8009110263 8009110262	80/08/19 80/08/19 80/08/05	70-135 70-135 70-135		8009110737 8009110759 8009110769	8007110752 8007110750 8007110764	80/09/03 80/07/31	71-9009 50-546	
8009110274 8009110276	8009110262	80/08/05	70-135		B009110774	8009110770	80/08/25	40~277	
8009110281 8009110285	8009110262 8009110259	80/08/05 80/08/22	70-135 50-271	9	8009110777 8009110820 8009110828	8009110773 8009110817 8009110824	80/08/20 80/08/26 80/08/25	50-295 F 50-155 0 50-32[ 0	3
8009110287 8009110288 8009110290	8009110259 8009110260 8009110259	80/08/22 80/08/26 80/08/22	50-271 50-320 50-271	<u>የ</u> ዘ የ	8007110831 8007110835	8007110827 8007110827	80/04/25 80/04/25	40-4826 40-4826	
8009110295 8009110298	8009110286 8009110257	80/09/04 80/08/07	FOIA 50~333	q	8009110859 8009120007	8009110856 8009120004	80/09/04 80/09/03	50-502 A	4
8007110279 8007110299 8007110301	8009110297 8009110257	80/08/07 80/08/07	50-293 50-233	ā a	8007120012 8007120014	8009120010 8009120013	80/08/27 80/08/15	CONTRACT	
B009110302	8009110286	80/09/04	FOIA		8009120019	8009120017	80/08/28	CONTRACT	
8007110303 8007110304 8007110306	8009110257 8009110297 8009110257	80/08/07 80/08/07 80/08/07	50-333 50-293 50-333	0 0 0	8009120033 8009120037 8009120048	8007120028 8007120037	80/08/18 80/07/25	CONTRACT CONTRACT 50-315 F	,
8007110313 8007110318	8009110307 8009110316	80/07/10 80/09/05	50-454 50-289	ä R	8009120052 8009120061	8009120045 8009120039	80/08/08 80/07/25	50-348 G 50-315 P	)
8009110319 8009110322	8009110314 8009110314	80/08/26	50-320 50-320	н н	8009120068 8009120071	8007120037 8007120045	80/07/25 80/08/08	50-315 P 50-348 0	
8009110324 8009110330	8009110307 8009110328	80/07/10 80/09/09	50-454 50-320	G P	8007120075 8007120083	8009120049 8009120070	80/09/03 80/07/21	CONTRACT	
8009110333	8009110316	80/09/05	50-289	R	8009120115	8009120104	80/08/18	CONTRACT	
8009110334 8009110338 8009110340	8009110329 8009110331 8009110316	80/09/09 80/08/25 80/09/05	50-29 CONTRACT 50-289	S R	8009120123 8009120126 8009120130	8007120120 8007120124 8007120124	80/08/01 80/08/20 80/08/20	50~322 E 70~143 70~143	j
8009110341 8009110342	8009110332 8009110337	90/09/20 80/09/08	50-327 50-302	P 8	8009120133 8009120137	8007120124 8007120125	80/08/20	70~143 27~48	
8009110343 8009110344	8009110332 8009110316	80/08/20 80/09/05	50-327 50-287	P	8009120141	8009120135	B0/07/21	50~416 0	ì
8009110347 8009110348	8007110335 8007110326	80/09/04 80/09/05	FDIA 50-315	R 5	8007120144 8007120156 8007120210	8009120125 8009120125 8009120195	80/08/20 80/08/20 80/07/08	27-48 27-48 50-247 0	
8009110350	8009110346	80/08/22	CONTRACT	-	8009120220	8009120201	80/07/31	40-2740	•
8007110351 8007110353 8007110355	8009110335 8009110352 8009110349	80/09/04 80/08/29 80/09/03	FOIA 50-259 50-327	R P	8009120222 8009120223	8009120201 8009120201	90/07/31 90/07/31	40~2740 40~2740	
8009110358 8009110360	8009110349 8009110349	80/07/03 80/07/03	50-327 50-327	P P	8009120224 8009120227 8009120235	8009120147 8009120147 8009120150	80/08/18 80/08/18 80/07/11	70-143 70-143 70-371	

ACCESS 1 O				ACCESSION HUNDER	
ENGLOSURE	PRINCIPAL	DATE	GUBJECT	PRINCIPAL DATE	SUBJECT
	DOCUMENT	198UED	CATEGORY	ENCLOSURE DOCUMENT ISSUED	CATEGORY
8009120240	8009120143	80/07/22	50-416 Q	8009120604 8009120601 80/06/05	50-201 R
8009120249	8009120245	80/09/03	50-296 P	8009120614 8009120611 80/06/03	70-258
8009120271	8009120242	80/08/27	50-370 Q	8009120616 8009120609 80/09/02	50-460 0
8009120276	8009120292	80/08/05	50-528 Q	8009120622 8009120609 80/09/02	50-460 0
8009120309	8009120304	80/08/12	50-460 Q	8009120627 8009120624 80/08/26	XPDRTLIC
8007120315	8009120313	80/09/02	50-251 8	8009120431 8009120409 80/09/02	50-440 G
8007120316	8009120312	80/09/02	50-335 8	8009120448 8009120445 80/09/02	50-289 P
8007120317	8009120301	80/09/08	50-327 K	8009120450 8009120445 80/09/02	50-289 P
8007120318	8009120307	80/09/03	50-335 8	8009120453 8009120454 80/09/02	50-289 P
8007120320	8009120305	80/09/02	50-275 8	8009120457 8009120454 80/07/10	GA799
8009120324	8009120302	80/08/29	50-275 8	8009120460 8009120451 80/09/04	50-387 A
8009120331	8009120299	80/08/29	50-275 8	8009120462 8009120459 80/08/27	CONTRACT
8009120335	8009120334	80/07/09	9A777	8009150004 8009150002 80/08/24	FOIA
8009120342	8009120341	80/09/09	50-287 8	8009150005 8009150002 80/08/24	FOIA
8009120348	8009120344	80/09/08	50-317 8	8009150018 8009150014 80/08/25	50-438 A
8009120356	8009120351	80/09/10	50-346 S	8009150021 8009150017 80/07/11	0A999
8009120363	8009120360	80/09/02	TOPREP	8009150024 8009150022 80/07/24	50-373 0
8009120365	8009120359	80/09/09	50-333 6	8009150025 8009150022 80/07/24	50-373 0
8009120371	8009120366	80/09/05	50-325 8	8009150026 8009150020 80/08/18	COMMISSION
8009120372	8009120357	80/09/04	50-272 8	8009150030 8009150020 80/08/18	COMMISSION
8009120374	8007120368	80/09/10	PR	8009150032 8009150020 80/08/18	COMMISSION
8009120378	8007120354	80/09/06	50-317 S	8009150035 8009150020 80/08/18	COMMISSION
8009120379	8007120368	80/09/10	PR	8009150039 8009150020 60/08/18	50-271 U
8009120381	8007120353	80/09/05	50-247 S	8009150043 8009150037 80/08/20	50-354 B
8009120382	8007120375	80/09/04	50-272 S	8009150044 8009150020 80/08/18	50-271 U
8007120385	8009120350	80/09/02	50-250 B	8009150047 B009150020 80/08/18	COMMISSION
8007120384	8009120377	80/09/04	50-334 B	8009150050 B009150045 80/08/29	50-445 0
8007120388	8009120384	80/09/08	50-255 S	8009150051 8009150045 80/08/29	50-445 0
8007120379	8009120381	80/08/25	50-254 S	8009150052 8009150020 80/08/18	COMMISSION
8007120405	8009120401	80/09/03	50-271 P	8009150054 B009150020 80/08/18	COMMISSION
8009120404	8009120402	80/09/08	50-320 8	8009150035 8009150045 80/08/29	50-445 0
8009120413	8009120408	80/09/05	50-220 V	8009150036 8009150020 80/08/18	COMMISSION
8009120415	8009120410	80/09/08	50-333 8	8009150057 8009150045 80/08/29	50-445 0
8009120417	8009120408	80/09/05	50-220 V	8009150040 8009150045 80/08/29	50-445 0
8009120419	8009120349	80/09/08	50-133 8	8009150041 8009150020 80/08/18	COMMISSION
8009120428	8009120424	80/09/04	50-272 S	8009150063 8009150045 80/08/29	50-445 Q
8009120431	8009120418	80/09/04	50-270 S	8009150064 8009150020 80/08/18	COMMISSION
8009120436	8009120414	80/09/05	50-269 S	8009150066 8009150045 80/08/29	50-445 Q
8009120440	8009120412	80/09/04	50-327 S	8009150068 8009150045 80/08/29	50-445 Q
8009120443	8009120411	80/09/04	50-327 B	8009150069 8009150020 80/08/18	COMMISSION
8009120445 8009120451 8009120452 8009120455 8009120462	8009120392 8009120449 8009120450 8009120447 8009120457	80/09/08 80/09/08 80/09/08 80/09/05 80/09/05	50-347 Q 50-133 R 50-320 S 50-317 S 50-255 R	8009150071 8009150049 80/08/29 8009150074 8009150020 80/08/18 8009150075 8009150045 80/08/29 8009150077 8009150045 80/08/29 8009150079 8009150070 80/07/21	50-445 0 50-293 U 50-445 0 50-445 P
8009120466 8009120470 8009120471 8009120472 8009120474	8009120459 8009120459 8009120459 8009120467 8009120459	80/09/04 80/09/04 80/09/04 80/07/07 80/09/04	50-326 Q 50-326 Q 50-327 Q 50-327 Q	8007150080 8007150045 80/08/27 8007150081 8007150020 8D/08/18 8007150083 8007150045 80/08/29 8007150085 8007150020 80/08/18 8007150087 8007150045 80/08/29	50-445 0 50-293 U 50-445 0 30-293 U 50-445 0
8009120476 8009120478 8009120479 8009120480 8009120483	8009120459 8009120459 8009120475 8009120477 8009120477	80/09/04 80/09/04 80/08/12 80/08/22 80/08/22	50-326 Q 50-361 Q COMMISSION COMMISSION	8009150088 8009150082 80/07/14 8009150089 8009150084 80/08/15 8009150090 8009150020 80/08/18 8009150091 8009150045 80/08/29 8009150093 8009150045 80/08/29	50-245 Q 50-250 Q COMMISSION 50-445 Q 50-445 Q
8009120484	8009120477	00/08/22	COMMISSION	8009150094 8009150020 80/08/18	50-201 U
8009120485	8009120477	00/08/22	COMMISSION	8009150095 8009150084 80/08/15	50-250 G
8009120489	8009120477	00/08/22	COMMISSION	8009150096 8009150095 80/08/29	50-445 G
8009120490	8009120487	00/09/14	50-312 G	8009150097 8009150092 80/07/17	50-410 Q
8009120491	8009120486	00/08/25	50-250 G	8009150098 8009150020 80/08/18	50-201 U
8009120494	8009120477	80/08/25	COMMISSION	8007150100 8007150045 80/08/27	50-445 Q
8009120495	8009120486	80/08/25	50-250 Q	8007150102 8007150045 80/08/27	50-445 Q
8009120497	8009120486	80/08/25	50-250 Q	8007150103 8007150045 80/08/27	50-445 Q
8009120499	8009120486	80/08/25	50-250 Q	8007150107 8007150020 80/08/18	50-201 U
8009120500	8009120496	80/08/12	50-588 Q	8007150107 8007150106 80/08/22	50-311 P
8009120509	8009120505	80/08/01	50-155 Q	8009150111 8009150104 80/08/22	50-311 P
8009120514	8009120505	80/04/01	50-206 P	8009150112 8009150020 80/08/18	50-201 U
8009120520	8009120515	80/08/25	50-250 Q	8009150113 8009150045 80/08/29	50-448 Q
8009120526	8009120515	80/08/25	50-250 Q	8009150114 8009150104 80/08/22	50-311 P
8009120531	8009120515	80/08/25	50-250 Q	8009150115 8009150104 80/07/25	50-302 Q
8007120535	8009120515	80/08/25	50-250 Q	8009190114 8009150045 80/08/29	50-445 0
8007120536	8009120525	80/08/14	70-343	8009150118 8009150020 80/08/18	50-201 U
8007120537	8009120515	80/08/25	50-250 Q	8009150120 8009150045 80/08/29	50-445 0
8007120542	8009120525	80/08/14	70-343	8009150121 8009150020 80/08/18	50-201 U
8007120548	8009120525	80/08/14	70-343	8009150122 8009150045 80/08/29	50-445 0
8009120549	8007120545	80/07/10	50-201 P	8009150123 8009150117 80/08/29	40-8743
8009120565	8007120562	80/08/27	40-1341	8009130124 8009150119 80/08/29	50-219 q
8009120586	8007120562	80/08/28	FOIA	8009150125 8009150045 80/08/29	50-445 o
8009120589	8007120562	80/08/28	50-320 P	8009150127 8009150020 80/08/18	50-201 U
8009120597	8007120571	80/09/02	FOIA	8009150129 8009150045 80/08/29	50-445 o

	N NUMBER					ACCESSION	NUMBER		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 168UED	GUBJEC1 CATEQOS		i	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188VED	SUBJECT CATEODRY
8009150132 8009150133 8009150134 8009150137 8009150138	8007150020 8007150045 8007150045 8007150130 8007150020	60/08/18 60/08/29 80/08/29 80/07/18 80/08/18	50-201 50-445 50-445 50-271 50-201	20007	8 6	8009150355 8009150356 8009150357 8009150358 8009150361	8009150351 8009150350 8009150340 8009150347 8009150350	80/08/25 80/08/19 80/07/28 80/07/25 80/08/19	50-320 H 50-317 P 50-458 Q 70-135 50-317 P
8009150139 8009150143 8009150149 8009150161 8009150164	8009150020 8009150140 8009150146 8009150159 8009150158	80/08/18 80/06/30 80/07/21 80/07/24 80/08/14	50-201 CONTRACT CONTRACT 50-322 40-8743		6 8	9009150342 9009150343 9009150347 9009150349 9009150370	8009150338 8009150337 8009150337 8009150366 8009150332	80/08/19 80/07/23 80/07/23 80/08/22 80/07/23	50-458 G 50-445 G 50-445 G 50-370 G 50-321 G
8009150165 8009150173 8009150177 8009150178 8009150193	8009150163 8009150171 8009150172 8009150176 8009150181	80/07/28 80/07/15 80/07/28 80/08/22 80/08/29	40-3392 0A797 50-546 CONTRACT 70-258	. a	8 8 6	9009180372 9009150373 9009150374 9009180375 9009180377	8009150366 8009150364 8009150366 8009150329 8009150366	80/08/22 80/08/11 80/08/22 80/07/24 80/08/22	50-370 Q 40-8113 50-370 Q 50-324 Q 50-370 Q
8009150184 8009150189 8009150190 8009150196 8009150197	8009150180 8009150189 8009150187 8009150193 8009150194	80/07/24 80/09/15 80/07/25 80/09/05 80/07/18	50-277 71-112 50-354 50-482 50-329	0 8 0	E E E	9007150378 9007150377 9007150380 9007150381 9007150385	8009150326 8009150376 8009150364 8009150334 8009150382	80/06/17 80/08/22 80/08/11 80/08/20 80/09/09	50-397 G 50-397 G 40-8113 50-482 G 50-321 8
8009150179 8009150200 8009150203 8009150204 8009150207	8009150195 8009150195 8009150194 8009150195 8009150195	80/08/22 80/08/22 80/08/22 80/08/22	QA999 QA999 50-329 QA999 QA999	Q	8 <b>8</b> 8	8007150386 8007150387 8007150378 8007150406 8007150412	8009150384 8009150364 8009150395 8009150403 8009150408	80/09/09 80/08/11 80/08/22 80/07/24 80/08/06	50-321 8 40-8113 70-143 70-135 70-1308
8009150210 8009150212 8009150215 8009150217 8009150223	8009150195 8009150209 8009150213 8009150195 8009150221	80/08/22 80/08/28 80/07/10 80/08/22 80/08/18	GA999 40-8745 70-2932 GA999 GA999		6 8	3007150414 3007150416 3007150418 3007150422	8007150409 8007150413 8007150410 8007150410 8007150410	80/08/25 80/07/30 80/08/22 80/08/22 80/08/22	CONTRACT 50-320 H COMMISSION COMMISSION COMMISSION
8009150224 8009150226 8009150227 8009150228 8009150229	8004120551 8004120551 8004120551 8004120551	80/08/18 80/08/18 80/08/18 80/08/18 80/08/18	0777 97740 9777 9777 9777		6 8 8	9009150424 9009150426 9009150428 9009150431 9009150433	8009150420 8009150415 8009150410 8009150427 8009150410	80/08/27 80/08/15 80/08/22 80/08/25 80/08/22	50-206 P 50-317 P COMMISSION 50-267 P COMMISSION
8009150231 8009150234 8009150241 8009150244 8009150246	8009150221 8009150221 8009150240 8009150219 8009150219	80/08/18 80/08/19 80/07/91 80/08/29 80/08/29	0A999 0A999 50-320 50-334 50-334	H P P	9 8 8	8009150435 8009150438 8009150442 8009150445	8009150432 8009150410 8009150410 8009150441 8009150410	80/09/08 80/06/22 80/06/22 80/08/22	50-320 P COMMISSION COMMISSION 50-320 H COMMISSION
8007150248 8007150256 8007150260 8007150261 8007150263	6007150217 8007150257 8007150257 8007150258 8007150257	80/08/29 80/09/10 80/09/12 80/09/09 80/09/12	50-334 50-466 50-348 50-368 50-348	Р О К Б Х	9 9 8	1009150448 1009150461 1009150464 9009150468 1009150475	8009150410 8009150456 8009150462 8009150460 8009150471	80/08/22 80/09/05 80/08/21 80/09/09 80/08/28	COMM18810N 90-336 R 50-305 Q 50-438 A 50-344 8
8009150266 8009150267 8009150271 8009150272 8009150275	8009150265 8009150264 8009150268 8009150269 8009150273	80/09/08 80/09/09 80/09/09 80/09/09	50-220 50-311 50-368 50-312 50-368	8 8 8 8 8	9 9	1009150508 1009150561 1009150577 1009150600 1009150602	8009150504 8009150559 8009150575 8009150594 8009150594	80/07/28 80/07/15 80/08/21 80/08/07 80/08/07	50-346 G 50-499 K 40-8768 50-546 G 50-546 Q
8009150277 8009150278 8009150279 8009150282 8009150283	8009150274 8009150274 8009150270 8009150280 8009150281	80/09/09 80/09/08 80/09/01 80/09/11 80/09/09	50-346 50-260 50-293 50-302 50-321	R 8 P 8 8	# 9 8	009150604 009150605 009160041 009160151	8009130601 8009130601 8009160033 8009160148 8009160137	80/08/28 80/08/28 80/09/12 80/09/11 80/09/15	70-1113 70-1113 50-387 M 50-376 O 50-445 M
8007150285 8007150287 8007150270 8007150272 8007150274	8009150284 8009150286 8009150288 8009150287 8009150291	80/09/01 80/09/10 80/09/03 80/08/29 80/09/09	50-293 50-261 50-335 50-368 50-321	F 5 8 8	9 8 8	009160186 009160214 009160221 009160223 009160229	8009160179 8009160213 8009160219 8009160220 8009160225	80/07/08 80/08/29 80/09/09 80/07/26 80/07/21	70-135 50-220 R 50-259 P 50-244 G 50-277 G
8009150294 8009150298 8009150299 8009150304 8009150306	8009150293 8009150295 8009150297 8009150300 8009150303	80/07/08 80/07/05 80/07/08 80/08/05 80/08/22	50-369 50-321 50-220 50-438 50-286	8 8 R Q	6 8 8	009160231 009160241 009160242 009160246 009160249	8009160230 8009160235 8009160240 8009160244 8009160248	80/09/05 80/08/13 80/07/24 80/07/24 80/08/27	50-206 P 70-754 50-220 Q 50-334 G 50-329 Q
8009150308 8009150312 8009150315 8009150318 8009150325	8009150303 8009150307 8009150314 8009150316 8009150321	80/08/22 80/09/11 80/09/12 80/08/25 80/08/25	50-375 50-375 50-352	Ф И К И Н	9 9 8	009160253 009160256 009160258 009160259 009160263	8007160250 8007160251 8007160255 8007160257 8007160260	80/09/08 80/09/08 80/09/10 80/09/11	50-409 R 50-313 R 50-261 R 50-309 R 50-324 R
8009150327 8009150328 8009150335 8009150334 8009150344	8007150324 8007150323 8007150331 8007150330 8007150337	80/08/22 80/09/10 80/09/09 80/08/22 80/09/10	50-315 50-346 50-269	H 8 8 H 0	8 8	009160264 009160270 009160271 009160276 009160277	8009160262 8009160268 8009160267 8009160272 8009160273	80/09/04 80/09/11 80/09/11 80/09/02 80/09/12	50-298 R 50-348 R 50-293 R 50-254 R 50-315 R
8007150345 8007150346 8007150348 8007150352 8007150353	8009150342 8009150343 8009150342 8009150340 8009150340	80/07/28 80/08/22 80/07/28 80/07/28 80/07/28	50-269 50-462 50-458	а н а а	8 8 8	009160282 009160283 009160284 009160288	8007160279 8007160280 8007160281 8007160286 8007160274	80/09/08 80/09/12 80/09/05 80/09/09 80/09/10	50-282 R 50-316 R PR 50-267 R 50-277 R

ACCESSION NUMBER

	ON NUMBER				ACCEBB	ION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	CATEGO		ENCLOSURE		DATE ISSUED	SUBJEC	
8007160297 8007160299 8007160300 8007160301 8007160303	8007160275 8007160272 8007160278 8007160271 8007160287	80/09/08 80/09/10 80/09/08 80/09/11	50-267 50-272 50-271 50-27	R R R R	800916034 800916035 800916053 800916064 800916064	0 8009160933 2 8009160533 4 8009160610	60/09/04 60/09/04 60/09/04 80/07/28 80/07/28	50-249 50-249 50-249 50-269 50-305	G G G
8009140304 8009140305 8009140306 8009140311 8009140313	8009160302 8009160283 8009160307 8009160309 8009160309	80/09/09 80/09/05 80/09/11 80/09/09 80/09/09	50-266 50-304 50-366 50-349 50-334	R 8 8 8	B00914062 800914068: 800914068: 800916063:	8009160619 8009160619 160631	80/09/13 80/08/13 80/09/13 80/09/04 80/09/04	50-277 50-277 50-277 50-375 50-375	0 9 9
8009140314 8009140318 8009140322 8009140323	8009140314 8009160315 8009140321 8009140320 8009140325	80/07/07 80/07/08 80/07/08 80/07/08	50-334 50-267 50-317 50-142 50-348	8 P 8	80091 60638 80091 60645 80091 60645 80091 6065	8009160631 8009160644 8009160656 8009160656	80/07/04 80/07/04 80/08/18 80/08/21 80/08/21	50-375 50-375 COMMISS 50-339 50-339	P
8009160331 8009160333 8009160334 8009160336	8009160330 8009160330 8009160330 8009160330	80/09/05 80/09/05 80/09/05 80/09/05 80/09/11	50-327 40-8745 40-8745 40-8745 40-8745	8	80091 6064 80091 6064 80091 70005 80091 70005 80091 70061	8009160656 8009170001 8009170001 8009170004	80/08/21 80/08/21 80/08/14 80/08/14 80/08/26	50-339 50-339 70-820 70-820 50-289	Р Р
8007160345 8007160347 8007160348 8007160350	8009160330 8009160330 8009160330 8009160330	80/09/05 80/09/12 80/09/05 80/09/05	50-57 40-8745 50-369 40-8745 40-8745	0	9009170054 8009170076 8009170088 8009170089 8009170092	8009170063 8009170082 8009170082 8009170082	80/09/02 80/09/02 80/08/27 80/08/27 80/08/27	FOIA FOIA 50-282 50-282 50-282	P P
8009160354 8009160355 8009160356 8009160357	8009160330 8009160381 9009160330 900916030	80/09/12 80/09/05 80/09/08 80/09/05 80/09/05	50-369 40-8745 50-311 40-8745 40-8745	P	8009170129 8009170131 8009170133 8009170147 E009170152	8009170126 8009170126 8009170145 8009170145	90/09/13 80/09/15 80/09/15 80/09/05 80/09/05	70-2909 70-2909 70-2909 50-302 50-302	Q G
8009140343 8009140349 8009140379 8009140380	8009160359 8009160360 8009160365 8009160373 8009160375	80/09/12 80/09/12 80/09/10 80/09/11 80/09/04	50-320 50-275 50-247 50-528 50-327	8 1 8	8009170153 8009170154 8009170157 8009170158 8009170159	8009170149 8009170149 8009170149 8009170156 8009170155	80/09/09 80/09/09 80/09/09 80/07/21 80/07/21	50-466 50-466 50-466 GATTP GATTP	0
8009160392 8009140398 8009160399 8009160402 8009160410	8007140388 8007140370 8007140371 8007140374 8007140404	80/09/08 80/09/10 80/09/09 80/09/12 80/09/11	50-312 50-327 50-346 50-293 50-293	8 8 8	80091,70163 8009170171 8009170172 80091,70176 80091,70181	8009170161 8009170169 8009170168 8009170173 8009170178	80/08/04 80/09/11 80/07/31 80/08/29 80/08/26	50-328 50-592 50-382 50-313 MISC	Q Q
8009160411 8009160412 8009160422 8009160425 8009160426	8009160405 8009160406 8009160416 8009160421 8009160408	11/90/08 11/90/08 90/90/08 90/90/09		8 8 8 8	80091.70183 80091.70187 80091.70197 80091.70197 80091.70221	8009170180 8009170185 8009170184 8009170186 8009170217	60/08/29 60/09/02 60/09/05 80/09/05 80/07/28	50-382 50-267 50-324 50-324 50-458	9 P P 9
8909140431 8009140435 8009140435 8009140436 8009140440	8009160427 8009160429 8009160427 8009160424 8009160432	00/09/10 00/09/11 00/09/10 00/09/11 00/09/08	50-338 50-277 TOPREP	R P R	8009170225 8009170232 8009170232 8009170239 8009170244	8009170223 8009170229 8009170229 8009170229 8009170229	80/09/12 80/09/1 80/09/14 80/09/14 80/08/28	50-466 50-445 50-445 50-445 50-312	0 Н Н Я
8009160449 8009160481 8009160485 8009160461 8009160464	8009160445 8009160444 8009160447 8009160457 8009160457	80/09/11 80/09/09 80/09/11 80/09/08 80/09/08	50-334 50-293 50-336	6 8 8 8	8009170256 8009170260 8009170262 8009170263 8009170263	8009170254 8009170255 8009170261 8009170257 8009170264	80/09/15 80/09/08 80/09/09 80/08/22 80/08/14	50-287 50-333 50-327 50-287 50-309	C P R H P
B007160466 B007160467 B007160468 B007160467 B007160472	8009160454 8009160460 8009160463 8009160457 8009160470	80/09/08 80/09/05 80/09/11 80/09/08 80/09/10	50-220 50-327 50-336	8 8 8	8009170269 8009170270 8009170273 8009170275 8009170277	8009170264 8009170264 8009170264 8009170272 8009170274	80/08/11 80/08/14 80/08/14 80/08/11 80/09/17	50-320 50-309 50-309 50-320 50-259	H P H R
8009140474 8009140474 8009140479 8009140480 8009140482	8009160471 8009160458 8009160475 8009160477 8009160478	80/09/10 80/09/11 80/09/19 80/09/10 80/09/11			8009170281 8009170284 8009170284 9009170289 8009170293	8009170279 8009170283 8009170285 8009170288 8009170292	80/09/06 80/08/27 80/08/14 80/09/15 80/09/10	50-250 50-320 50-320 50-302 50-289	5 H H
8007160483 8007160487 8007160488 8007160470 8007160475	8009160452 8009160473 8009160485 8009160473 8009160491	80/07/07 80/08/22 80/08/22 80/08/22 80/07/27	50-293 6 50-280 6 CONTRACT 50-280 6 CONTRACT	1	8009170296 8009170301 8009170301 8009170314 8009170317	8009170299 8009170298 8009170303 8009170312 8009170316	80/07/18 80/07/18 80/09/09 80/07/18 80/09/08	50-244 50-244 50-244 50-244 50-320	6 6 6
8009140497 8009140502 8009140504 8009160507 8009160512	8009160473 8009160501 8009160501 8009160501 8009160509	80/08/22 80/08/20 80/08/20 80/08/20 80/07/31	50-280 0 50-247 P 50-247 P 50-267 P 50-358 0	• !	8007170320 8007170323 8007170328 8007170347 8007170347	8009170315 8009170321 8009170324 8009170343 8009170346	80/09/10 80/09/16 80/09/11 10/09/13	50-331 50-291 50-331 50-309 50-289	8 P 8 P T
8009140514 8009140515 8009140535 8009140537 8009140540	8007160507 8007160511 8007160533 8007160533 8007160533	B0/07/31 80/07/21 80/09/04 80/09/04 80/09/04	50-358 G CONTRACT 50-267 G 50-267 G 50-267 G	!	8009170351 8009170352 8009170354 8009170354 8009170358	8009170346 8009170348 8009170346 8009170353 8009170346	80/09/15 80/09/10 80/09/15 80/09/11 80/09/15	50-287 50-331 50-289 50-344 50-289	T S T A T

ACCESSION NUMBER				ACCESSI	ON NUMBER			
PRINCIPAL ENCLOSURE DOCUMENT	DATE 16SUED	SUBJEC CATEGO		ENCLOBURE	PRINCIPAL DOCUMENT	DATE 188VED	SURJEC	
8009170360 8009170364 8009170365 8009170365 8009170367 8009170367 8009170367 8009170369	80/09/12 8 80/08/14 8 80/09/10	50-331 50-445 50-320 50-331 50-445	8 H H	8009180459 8009180445 8009180472 9009180476 8009180477	8009180450 8009180448 8009180470 8009180470 8009180474	80/09/02 80/04/21 80/08/08 80/08/08 80/09/16	50-400 50-3 50-313 50-313 50-70	о Н О О
8009170376 8009170373 8009170382 8009170378 8009170385 8009170386 8009170387 8009170384 8009170402 8009170389	8 80/07/18 80/07/16 80/07/16	40-299 50-201 50-498 50-482 50-220	R 0 0	B009180480 B009180481 B009180490 B0091B0491 B0091B0493	8009180385 8009180470 8009180484 8009180487 8009180486	80/07/11 80/08/08 80/08/05 80/08/05 80/09/16	50-369 50-313 9779 70-33 50-275	H Q A
8009170414 8009170410 8009170417 8009170410 8009180005 8009180001 8009180021 8009180012 8009180023 8009180027	80/08/18 80/07/18 80/08/07	50-458 50-458 50-334 50-275 40-2259	9	8009180495 8009180507 8009180500 8009180502 8009180504	8009180484 8009180487 8009180484 8009180484 8009180501	80/08/26 80/08/05 80/08/26 80/08/26 80/09/08	GA777 70-33 GA777 GA777 50-237	P.
8009180047 8009180040 8009180054 8009180040 8009180061 8009180043 8009180064 8009180056 8009180070 8009180056	80/08/27 80/08/07 80/08/28	50-373 50-373 50-461 9A999 0A999	0 0 0	8009180508 8009180516 8009180526 8009180536 8009180845	8009180484 8009180801 8009180501 8009180529 8009180538	80/08/26 80/09/08 80/09/08 80/07/07 80/08/29	0A999 50-237 50-237 0A999 50-280	P P
8009180074 8009180072 8009180077 8009180054 8009180081 8009180072 8009180085 8009180089	80/08/28 80/08/13 80/08/28	40-8452 GA979 40-8452 GA979 40-8584		8009180352 8009180360 8009180365 8009180366 8009190017	8009180538 8009180548 8009180548 8009180562 8009190014	80/08/29 80/08/19 80/08/19 80/07/03 80/08/28	50-280 50-320 50-320 GA999 GA999	H
8007180099 8007180072 8007180100 8007180075 8007180104 9007180072 8007180107 8007180072 8007180113 8007180107	80/06/23 80/08/26 80/08/25	GA999 50-445 GA999 GA999 50-261	Q P	8009190020 8009190027 8009190027 8009190029 8009190031	8009190014 8009190014 8009190014 8009190014	80/08/28 80/08/28 80/08/28 80/08/28	GA999 GA999 GA999 GA999 GA999	
8007180118 8007180107 8007180119 8007180192 8007180122 8007180107 8007180150 8007180143 8007180162 8007180148	80/08/25 80/08/29	50-261 GA999 50-261 CDNTRACT 50-280	P P G	8009190049 8009190049 8009190053 8009190056 8009190057	8007170044 8007170044 8007170044 8007170044 8007170051	80/08/14 80/08/14 80/08/14 80/08/14 80/08/21	50-352 50-352 50-352 50-352 CONTRACT	0 0 0
8009180145 8009180159 8009180177 8009180149 8009180180 8009180145 8009180185 8009180149 8009180191 8009180147	80/09/04 80/09/02 80/09/10 80/09/02 60/09/08	CONTRACT GA999 50-213 GA999 CONTRACT	R	8007170076 8009170078 8009190079 8009190081 8009190094	8007170073 8007170073 8007170073 8007170073 8007170087	80/08/13 80/08/13 80/08/13 80/08/13 80/08/14	50-293 50-293 50-293 50-293 50-443	0 0 0
8009180194 8009180183 8009180196 8009180183 8009180203 8009180193 8009180208 8009180199 8009180217 8009180207	80/09/15 80/08/05 80/08/08 80/09/10 80/09/03	50-334 70-135 40-1162 80-321 CONTRACT	R R	8009190100 6009190101 8009190100 9009190105 8009190106	8007170087 8007170078 8007170087 8007170078 8007170087	80/09/14 80/09/12 80/08/14 80/09/12 80/08/14	50-443 50-155 50-443 50-155 50-443	0 8 0 8
8009180219 8009180213 8009180221 8009180211 8009180235 8009180498 8009180235 8009180498 8009180237 8009180226	80/08/15 80/08/05 80/09/02 80/09/10 80/09/02	50-336 50-546 50-546 50-366 50-546	F G R G	8007170121 8007170123 8007170124 8007170128 8007170127	8009190118 8009190116 8009190098 8009190126 8009190098	80/08/20 80/08/20 80/09/12 80/09/12 80/09/12	40-2061 40-2061 50-155 XPORTLIC 50-155	<b>S</b>
8009180240 8009180231 8009180242 8009180224 8009180257 8009180245 8009180272 8009180245 8009180277 8009180249	80/08/07 80/09/02 80/09/10 80/08/29 80/09/04	50-329 50-546 50-311 50-244 10CFR	Q C R R	800717013B 8007170140 8007170143 8007170148 8007170151	8009190133 8009190134 8009190134 8009190145 8009190134	80/09/12 80/08/28 80/08/28 80/09/04 80/08/28	50-440 50-247 50-247 50-346 50-247	K P P P
8009180278 8009180248 8009180280 8009180246 8009180284 8009180249 8009180298 8009180249	80/09/10 80/07/28 80/09/04 80/09/04 80/09/04	50-220 50-373 10CFR 10CFR 10CFR	8 0	8009190149 8009190171 8009190179 8009190179	8009190159 8009190166 8009190159 8009190175 8009190175	80/08/22 80/02/14 90/08/22 80/08/28 80/08/28	50-528 50-254 50-528 50-285 50-285	0 0 0 P P
8009180316 8009180304 8009180327 8009180322 8009180329 8009180320 8009180335 8009180304 8009180344 8009180340	80/09/15 80/09/16 80/09/04 80/09/15 80/09/17	50-369 CONTRACT 50-277	P A P	8009190183 8009190185 8009190190 8009190199 8009190205	8009190159 8009190175 8009190198 8009190195 8009190197	80/08/22 80/08/28 80/08/28 80/09/17 80/08/29	50-528 50-285 CONTRACT 50-170 MISC	Q P V
8009180348 8009180340 8009180355 8009180351 8009180408 8009180404 8009180409 8009180404 8009180417 8009180412	80/09/17 80/08/29 80/09/09 80/09/12 80/09/12	50-29 50-320 50-287	P R 8 6	8009190209 8009190210 8009190211 8009190214 8009190214	8009170206 8009170203 8009170197 8009170203 8009170203	80/09/12 80/08/04 80/08/29 80/08/06 80/08/06	50~250 50~354 MISC 50~354 50~354	Р Q Q
8009180426 8009180424 8009180427 8009180424 8009180429 8009180421 8009180442 8009180421 8009180442 8009180439	80/09/05 80/09/11 80/09/10 80/09/10 80/09/12	50-368 50-361 50-361	B A A R	9007170221 8007170223 8007170241 9007170242 8007170250	8009190218 8009190203 8009190231 8009190236 8009190247	80/09/16 80/08/06 80/07/15 80/09/02 90/08/01	50-329 50-354 50-367 50-369 50-367	K Q Q A
8009180447 8009180449 8009180452 8009180452 8009180453 8009180453 8009180450	80/09/03 80/09/03 80/09/12 80/09/03 80/09/02	40~2041	9 3	8009190254 8009190256 8009190257 8009190259 8009190260	8009190247 8009190252 8009190247 8009190247 8009190255	80/08/01 80/09/12 80/08/01 80/08/01 80/08/29	50-387 50-440 50-387 50-387 50-286	g K G G

	IN NUMBER				ACCESSI	ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE	BUBJE CATEG		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC CATEGO	
8009190263 8009190266 8009190271 8009190275 8009190277	8007170252 8007170261 8007170264 8007170267 8007170264	80/08/11 80/08/11 80/08/29	50-440 ACRS 50-387 50-250 50-387	a	8007170368 8007170383 8007170383 8007170583	8009190572 8009190576 8009190577	80/09/04 80/08/29 80/09/03 80/09/05 80/09/04	F01A 50-346 50-249 50-285 F01A	0 0
8009190282 8009190288 8009190289 8009190302 8009190304	8009190264 8009190264 8009190283 8009190297 8009190295	80/09/11 80/08/29 80/09/29	50-387 50-387 50-272 50-335 50-282	0	8007170588 8007170598 8007170598 8007170607 8007170607	8007170576 8007170587 8007170587	80/09/03 80/09/03 80/08/27 80/08/27 80/08/27	50-348 50-348 50-334 50-334 50-334	G G P P
8007170310 8007170311 8007170320 8007170324 8007170324	8007170304 8007170308 8007170277 8007170314 8007170277	80/08/29 80/09/04 80/08/29	50-313 50-344 FDIA 50-312 FDIA	0 G C	8009 1 90609 8009 1 90612 8009 1 90612 8009 1 90617 8009 1 90624	8007170603 8007170277 8007170603	80/09/03 80/08/21 80/09/04 80/08/21 80/09/04	50-348 50-259 FOIA 50-259 FOIA	a a
8007170328 8007170340 8007170343 8007170344 8007170351	8009190322 8009190333 8009190338 8009190338 8009190338	90/09/13 90/09/29 90/09/12	50-336 50-382 50-285 50-361 50-361	0 0 K K	8007 1 70630 6007 1 70638 8007 1 70638 8007 1 70637 8007 1 70642		80/09/04 80/09/02 80/09/02 80/09/12 80/09/02	50-219 FOIA FOIA 50-133 FOIA	O P
8009190357 8009190358 8009190365 8009190366 8009190369	8009190352 8009190299 8009190361 8009190299 8009190362	80/08/27 80/09/04 80/08/27 80/09/04 80/08/27	50-266 FOIA 50-206 FOIA 50-277	o P o	8009170643 8009170646 8009170646 8009170651 8009170653	8009190603 8009190603 8009190614 8009190603 8009190614	80/09/02 80/09/02 80/09/02 80/09/02	50-259 50-259 Foia 50-259 Foia	G G
8009190370 8009190374 8009190377 8009190378 8009190380	8009190299 8009190361 8009190299 8009190361 8009190375	80/09/04 80/08/29 80/09/04 80/08/29 80/08/29	FOIA 50-206 FOIA 50-206 50-302	Р Р 0	90071 90659 80071 90658 80071 90676 80071 90682 80071 90682	8007190614 8009190614 8009190614 8009190614 8009190614	80/09/02 80/09/02 80/09/02 80/09/02	FOIA FOIA FOIA FOIA	
8009190383 8009190386 8009190390 8009190394 8009190397	8007170277 8007170277 8007170277 8007170277 8007170277	80/09/04 80/09/04 80/09/04 80/09/04 80/09/04	FOIA FOIA FOIA FOIA		8009190845 8009190701 8009190713 8009190738 8009190775	8009190614 8009190614 8009190702 8009190727	80/09/02 80/09/02 80/08/29 80/08/29 80/09/03	FOIA FOIA CONTRACT CONTRACT 10CFR	
8007170400 8007170428 8007170427 8007170432 8007170435	8009190299 8009190423 8009190425 8009190423 8009190431	80/09/04 80/09/15 80/09/15 80/09/15 80/09/12	FOIA 50-321 50-325 50-321 50-440	P P P A	8009190817 8009190817 8009220011 8009220014 8009220017	8009190794 8009190974 8009220009 8009220013 8009220015	80/08/15 80/08/27 80/08/29 80/08/29 80/08/29	50-3 State Pr 50-247 50-220 50-249	P 0 0 0
8007170444 8007170445 8007170451 8007170453 8007170454	8007170437 8007170441 8007170442 8007170449 8007170440	80/09/15 80/09/17 80/09/15 80/09/15 80/09/12	50-280 50-482 50-286 TOPREP 50-260	R K R	800722017 800722017 800722014 800722081 800722091	8007220018 8007220033 800722003B 800722007B 800722008B	80/08/29 80/08/13 80/08/13 80/08/13 80/08/29	50-257 50-337 40-1341 50-352 50-275	e H H O
8009190459 8009190464 8009190470 8009190473 8009190474	8009190456 8009190299 8009190299 8009190462 8009190468	80/09/08 80/09/04 80/09/04 80/09/15 80/09/05	50-245 F01A F01A 50-269 50-295	R R P	8009220096 8009220101 8009220107 8009220112 8009220117	8009220093 8009220098 8009220104 8009220109 8009220115	80/08/29 80/08/29 80/08/29 80/08/29 80/08/29	50-334 50-263 50-333 50-331 50-271	0
8007170477 8007170480 8007170483 8007170484 8007170474	8009190469 8009190299 8009190478 8009190299 8009190491	80/09/15 80/09/04 80/08/27 80/09/04 80/09/16	50-241 FDIA 50-298 FDIA 50-382	8 P H	8009220122 8009220128 8009220184 8009220190 8009220200	8009220120 8009220125 8009220182 8009220188 8009220198	80/08/29 80/08/15 80/06/26 80/07/25 80/07/25	50-324 MISC 50-335 50-287 50-289	9 면 명
8007170495 8007170496 8007170498 8007170504 8007170507	8009190488 8009190489 8009190299 8009190499 8009190299	80/09/17 80/09/12 80/09/04 80/09/12 80/09/04	50-257 50-333 F01A 50-331 F01A	P S R	8007220207 8009220207 8009220211 8009220214 8009220217	8007220203 8007220201 8007220202 8007220185 8007220185	80/07/25 80/07/25 80/07/25 80/09/17 80/09/17	50-287 50-287 50-287 50-155 50-155	Н Н О
8007170507 8007170511 8007170514 8007170517 8007170520	8009190503 8009190471 8009190299 8009190467 8009190299	80/07/12 80/07/11 80/07/04 80/07/12 80/07/04	50-315 50-327 FOIA 50-259 FOIA	s s	8007220218 8007220222 8007220223 8007220242 8007220242	8009220185 8009220221 8009220221 8009220238 8009220238	80/09/17 80/09/10 80/09/10 80/09/15	50-155 50-389 50-389 50-329 50-329	0 Н А А
8009190522 8009190524 8009190526 8009190531 8009190532	8009190317 8009190465 8009190299 8009190460 8009190299	80/09/12 80/09/12 80/09/04 80/09/08 80/09/04	50-316 50-259 FOIA 50-336 FOIA	5 8 8	8009220252 8009220258 8009220260 8009220263 8009220271	8009220250 8009220253 8009220253 8009220253 8009220253	80/09/12 80/09/12 80/09/12 80/09/11	50-293 50-280 50-280 50-280 50-265	8 8 8
B009190537 B009190539 B009190541 B009190543 B009190546	8009190460 8009190299 8009190533 8009190460 8009190299	80/09/08 80/09/04 90/09/10 80/09/08 80/09/04	50-336 FGIA 50-331 50-336 FGIA	S P S	8009220278 8009220287 8009220287 8009220291 8009220301	8009220274 8009220281 8009220285 8009220288 8009220297	80/09/11 80/09/12 80/09/16 80/09/15 80/09/14	50-304 50-295 50-255 50-289 50-346	8 8 8 R P
8009190547 8009190550 8009190557 8009190559 8009190546	8009190540 8009190299 8009190299 8009190553 8009190553	80/09/12 80/09/04 80/09/04 80/09/15 80/09/15	50-327 FOIA FOIA 50-280 50-280	8 8 8	8009220304 8009220313 8009220313 8009220315 8009220319	8009220251 8009220248 8009220297 8009220241 8009220239	80/09/16 80/09/12 80/09/16 80/09/16 80/09/16	\$0-338 \$0-281 \$0-345 \$0-339 \$0-339	5 8 9 9

PHINCIPAL   DATE   SHULECT   SHULLCT   SHULECT   SHULLCT   SHULLCT   SHULECT   SHULLCT   SHULLTH   SHULL	ACCESSION NUMBER					ACCESSION NUMBER				
	ENCLOSURE	PRINCIPAL DOCUMENT	ISSUED				DOCUMENT		SUBJEC CATEGO	
0.00000000000000000000000000000000000	8009220321 8009220324 8009220330 8009220337	6009220318 6009220243 6009220325 6009220265	80/07/02 80/09/16 80/09/03 80/07/25	50~338 50~423 50~321	8 9 0	8009230347 8009230351 8009230359 8009230360	8009230345 8009230349 8009230354 8009230356	80/09/08 80/04/01 80/09/17	50-336 50-295 CONTRAC 50-338 CONTRAC	R
BOOFFEEDINGS   BOOF	6009220344 6009220348 6009220352	8009220334 8009220334 8009220349	60/09/12 60/09/12 60/09/11	50-445 50-445 50-295	A	8009230394 8009230399 8009230410	8009230385 8009230385 8009230407	80/09/09 80/09/09 80/09/15	50-275 50-275 50-275 50-369 TOPREP	P P R
BOOY220389   BOOY22034   BOOY971   SO-45	8009220365 8009220368 8009220373	6007220361 6007220334 6007220367	80/09/15 80/09/12 80/09/16	50-302 50-445 50-338	R A B	8007230437 8007230442 8007230466	8009230438 8009230441 8009230463	80/09/16 80/09/18 80/09/18	50-324 50-287	R P H P
S007220402	8009220385 8009220387 8009220392	8009220334 8009220334 8009220334	80/09/12 80/09/12 80/09/12	50-445 50-445 50-445	A A A	8009230504 8009230517 8009230527	8007230474 8007230507 8007230520	80/09/18 80/09/18 80/09/18	50-219 50-270 50-270 50-310 50-317	5 9 9 8
8009230011 8009230012 80/09/18 50-155 0 800923097 800923098 80/09/18 50-267 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8009230117 8	8009220402 8009220420 8009230002	8009220248 8009220417 8009230001	80/09/12 80/09/16 80/09/10	50-281 50-466 50-409	В 0	8009230559 8009230562 8009230564	8009230550 8009230550 8009230541	80/09/15 80/09/15 80/09/16	50-317 50-329 50-329 50-219 50-247	A A R R
8009230132	8009230021 8009230033 8009230117	8009230016 8009230030 8009230115	80/09/09 80/09/18 80/08/29	50-142 50-155 50-348	0	8007230577 8007230591 8007230592	8009230584 8009230584 8009230883	80/09/18 80/09/17 80/09/17	50-277 50-339 50-309 50-317 50-327	R B B B
8009730147 8009730142 8009730142 8009730143 800973043 8009730147 8009730636 8009730636 8009730636 8009730636 8009730636 800973014 8009730142 8009730147 8009730648 8009730648 800973063 800973014 8009730142 8009730147 8009730648 8009730648 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009730649 8009	8009230132 8009230134 8009230139	8007230121 8007230120 8007230138	80/08/29 80/08/29 80/07/02	50-280 50-305 70-364	Q	8007230604 8907230607 8007230614	8009230598 8009230597 8009230408	80/09/15 80/09/19 80/09/15	50-339 50-267 50-267 50-267 50-338	8 8 8
BO09230149   B009050491   B0/08/18   FOIA   B009230642   B009230643   B0/09/15   S0-416   B009230149   B0/08/18   FOIA   B009230649   B0/08/18   B0/08/1	8009230147 8009230148 8009230150	8007230142 8007230143 8007230142	80/07/30 80/08/13 80/07/30	70-1417 50-289 70-1417	Н	8007230630 8007230635 8007230636	8009230620 8009230624 8009230622	80/09/19 80/09/10 80/09/18	50-255 50-243 50-325 50-338 50-317	8 8 8 P
8099230185 8009930491 80708148 FOIA 8009230699 8009230648 80709712 50-409 8009230199 8009930491 80708188 FOIA 8009230649 8009230643 80709717 50-280 8009230199 800930491 80708188 FOIA 8009230647 8009230648 80709717 50-280 8009230202 8009230491 80708188 FOIA 8009230647 8009230648 80709717 50-280 8009230202 8009230194 80708188 FOIA 8009230648 8009230648 80709717 50-280 8009230202 8009230194 80708188 FOIA 8009230648 8009230649 80709718 50-409 8009230202 8009230194 80708188 FOIA 8009230679 8009230649 80709718 50-296 8009230212 8009230649 80708188 FOIA 8009230679 8009230670 80709718 50-296 8009230212 8009230194 80708188 FOIA 8009230679 8009230670 80709718 50-296 8009230212 8009230212 80708188 FOIA 8009230679 8009230670 80709718 50-296 8009230212 80708188 FOIA 8009230679 8009230670 80709718 50-296 8009230222 8009230212 80708188 FOIA 8009230679 8009230670 80709718 50-296 8009230222 8009230212 80708188 FOIA 8009230679 8009230670 80709718 50-296 8009230222 8009230212 80708188 FOIA 8009230670 80709230670 80709718 50-237 8009230222 8009230212 80708188 FOIA 8009230672 80709230212 80708188 FOIA 8009230672 80709230670 80709718 50-237 8009230222 8009230222 8009230212 80708188 FOIA 8009230672 80709230670 80709718 50-346 8009230672 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 8070923027 807092302	8009230159 8009230161 8009230164	8009050491 8009230157 8009050491	80/08/18 80/08/20 80/08/18	FOIA CONTRACT FOIA		8007230642 8007230646 8007230647	8009230427 8009230434 8009230643	80/09/15 80/09/22 80/09/15	50-414 50-317 50-157	8 P P
8009230202 800930491 80/08/18 FOIA 8009230491 80/08/18 FOIA 8009230701 8009230708 80/09/18 50-320 H 8009230701 8009230708 80/09/18 50-320 H 8009230701 8009230708 80/09/16 50-320 H 8009230701 80/09/16 50-320 80/09/16 50-320 80/09/16 50-320 80/09/16 50-320 80/09/16 50-320 80/	8009230183 8009230187 8009230190	8009050491 8009050491 8009050491	80708/18 80/08/18 80/08/18	FOIA FOIA FOIA		8007230657 8007230657 8007230661	8007230648 8007230643 8007230645	80/09/12 80/09/15 80/09/17	50-409 50-157 50-280	P E B 8
BO09230219   B009050491   B0/08/12   50-275   Q   B009230683   B009230672   B0/09/16   S0-225   B009230222   B009230216   B0/08/12   S0-320   H   B009230683   B009230672   B0/09/16   S0-326   B009230682   B0/09/16   B0/09/16   S0-326   B009230682   B0/09/16   B0	8007230202 8007230204 8007230207	8009230194 8009050491 8009050491	80/08/18 80/08/18 80/08/22	50-289 Foia Foia		8009230668 8009230673 8009230675	8009230643 8009230645 8009230669	80/09/15 80/09/17 80/09/19	50-157 50-280 50-296	K P 8 6 8
BO07230232   B007050491   B0708718   B0708	6009230219 6009230222	8009050491 8009230212 8009230216	80/08/18 80/08/12 80/08/22	FD1A 50-275 50-320		8007230483 8007230484 8007230486	8009230670 8009230672 8009230682	80/09/14 80/09/18 80/09/18	50-325 TOPREP 50-346	8
BO09230245   BO09230233   B0708715   50-320   H   B009230714   B009230705   B0709230705   B0709230707   B0709230	8009230232 8009230234 8009230238	8007050491 8007050491 8007050491	80/08/18 80/08/18 80/08/18	FOIA FOIA FOIA	н	8007230474 8007230475 8007230700	8009230478 8009230488 8009230697	80/09/18 80/09/20 80/09/15	50-311 50-317 50-313	8 8 8 8
8009230266 8009080491 80/08148 F0IA 8009230728 8009230716 80/0916 50-289 8009230269 8009230269 8009230269 8009230269 8009230728 8009230729 8009230728 8009230729 8009230729 8009230729 8009230730 8009230729 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009	8009230245 8009230247 8009230251	8009230233 8009230233 8009050491	80/08/15 90/08/15 90/08/18	50-320 50-320 FOIA	Н	8009230714 8009230715 8009230717	8009230706 8009230708 8009230709	80/09/16 80/09/15 80/09/16	50-259 50-313 50-325	6 6 8 8
	8009230266 8009230268 8009230269	8007050491 8007050491 8009230263	80/08/18 80/08/18 80/09/17	FOIA FOIA 50-334	P	8009230 <i>7</i> 28 8009230 <i>7</i> 29 8009230734	8007230716 8007230722 8007230730	80/09/17 80/09/16 80/09/19	50-257 50-349 50-327	8 8 8
8009230283 8009050491 80/08/18 80/08/18 800923074 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 8009230730 80092	8009230283 8009230289 8009230291	8007050491 8007050491 8009050491	80/08/18 80/08/18 90/08/18	FOIA FOIA FOIA		8009230740 8009230741	8009230736 8009230738	80/09/12 80/09/18	50-325 50-282	8 8 8

ACCE8810N	NUMBER			ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATECORY	ENCLOSURE	PRINCIPAL BOCUMENT	DATE ISSUED	SUBJECT CATEGORY	,
8007230748 8007230750 8009230755 8009230751 8009230764	8009230744 8009230751 8009230751 8009230756 8009230760	80/09/14 80/09/19 80/08/27 80/08/27	50~369 50~282 CENTRACT 71~9001 50~320	800924033 800924033 800924035 800924035 800924035	800924031B 8009240334 8009240329 8009240343	80/08/28 80/08/15 80/09/03 80/09/16 80/09/03	50-416 70-33 50-324 50-409	
8009230771 8009230777 8009230787 8009240014 8009240016	8009230768 8009230774 8009230785 8009240012 8009240012	80/08/27 80/08/29 80/08/29 80/08/21 80/08/21	CONTRACT CONTRACT 71-17 FOIA FOIA	8007240365 800724036 800724037 800724038 800724038	8007240327 8007240327 8007240380	80/09/03 80/09/03 80/09/03 80/09/02 80/09/02	50-324 50-324 50-518	Q Q Q Q
B009240018 B009240021 B009240024 B009240026 B009240028	8007240012 8007240012 8007240012 8007240012 8007240023	80/09/21 80/08/21 80/08/21 80/09/21 80/09/03	FOIA FOIA FOIA FOIA CONTRACT	800924040; 800924045; 800924045; 800924045; 800924045;	8009240380 8009240452 8009240450	80/09/02 80/09/02 80/09/15 80/09/17 80/09/17	50-518 50-3 50-334	G G R S S
8007240038 8007240041 8007240047 8007240051 8007240054	8009240034 8009240012 8009240012 8009240044 8009240012	80/09/09 80/08/21 80/08/21 80/08/11 80/08/21	CONTRACT FOIA FOIA 70-710 FOIA	8009240461 800924046 800924046 800924047( 800924047)	8007240462 8007240467 8007240467	80/09/17 80/09/19 80/09/19 80/09/19 80/09/19	50-293 50-293 50-281	5 5 5 5
8009240055 8009240057 8009240059 8009240060 8009240063	8009240044 8009240052 8009240012 8009240044 8009240012	80/09/11 80/09/29 80/09/21 80/08/11 80/08/21	70-710 50-206 I Füia 70-710 Füia	8009240473 8009240501 8009240503 9009240503 8009240503	8009240495 8009240496 8009240502	80/09/19 80/09/19 80/09/17 80/09/22 80/09/19	50-305 50-368 50-341	S S A S
8009240069 8009240070 8009240071 8009240075 8009240079	8009240045 8009240012 8009240066 8009240012 8009240073	80/08/12 80/08/21 80/08/05 80/08/21 80/08/21	CONTRACT FOIA 50-335 ( FOIA CONTRACT	800924050; 800924051; 800924053; 800924053; 800924053;	8009240502 8009240520 8009240531	80/09/22 80/09/22 80/08/04 80/09/22 80/07/11	50-341 Toprep 30-287	A A C G
8009240082 8009240084 8009240086 8009240089 8009240092	8009240012 8009240078 8009240012 8009240078 8009240012	80/08/21 80/08/29 80/08/21 80/08/29 80/08/21	FOIA 50-315 F FOIA 50-315 F FOIA	8009240538 8009240548 8009240548 8009240558 8009240558	8009240544 8009240544 8009240544	80/09/19 80/09/19 80/09/19 80/09/19 80/09/17	50~289 50~275 50~275	0000
8007240077 8007240108 8007240113 8007240117 8007240121	8007240078 8007240012 8007240012 8007240012 8007240107	80/08/29 80/08/21 80/08/21 80/08/21 80/07/31	50-315 F FOIA FOIA FOIA 50-320 F	800924056/ 800924060/ 800924060/ 800924061/ 800924061/	8009240593 8009240597 8009240606	80/08/29 80/09/02 80/08/29 80/09/11 80/09/11	50~566 50~321 50~302	P Q P P
8007240125 8007240130 8007240132 8007240134 8007240145	8009240012 8009240123 8009240127 8009240106 8009240106	80/08/21 80/09/08 80/09/02 80/08/29 80/08/29	50-263 C CONTRACT 71-4986 50-313 8 50-313 8	800724063 800724063 800724063 800724064 800724064	8009240604 8009240624 8009240624	80/09/08 80/09/11 80/09/08 80/09/08 60/09/08	70-143 50-302 70-143 70-143 70-143	P
8007240151 8007240188 8007240177 8007240184 8007240187	8007240141 8007240106 8007240106 8007240176 8007240176	80/09/10 80/08/29 80/08/29 80/08/28 80/08/28	FOIA 50-313 E 50-313 E 50-302 C	800724066 800724066 800724067 800724068 800724070	8009240652 8009240652 8009240652	80/07/08 80/07/08 80/07/08 80/07/08	50-281 50-281 50-281 50-281 50-280	@ @ @
8009240190 8009240192 8009240198 8009240196 8009240200	8007240176 8007240186 8007240174 8007240186 8007240186	80/08/29 80/08/19 80/08/28 80/08/19 80/08/19	50-302 0 50-244 0 50-302 0 50-244 0	800924070 800924071 900924071 800924072 800925006	8009240693 8009240693 8009240721	80/09/08 80/09/08 80/09/08 80/08/16 80/08/29	50-280 50-280 50-280 40-299 70-1151	0 0
8007240205 8007240204 8007240212 8007240220 8007240228	8009240186 8009240201 8009240201 8009240201 8009240201	80/08/19 80/08/29 80/08/29 80/08/29 80/08/29	50-244 ( 50-369 ( 50-369 ( 50-369 ( 50-369 (	800925011 800925013 800925013 800925013	8009250109 8009250126 8009250126	80/09/04 80/08/04 80/09/12 80/09/12 80/09/12	50-546 50-546 50-368 50-368 50-368	0 P P
E009240232 E009240241 E009240246 E009240255 E009240262	8009240201 8009240201 8009240239 8009240239 8009240256	80/08/29 80/08/29 80/08/12 80/08/12 80/08/29	50-369 C 50-369 C 50-282 F 50-282 F 50-370 C	800725019 800725020 800725020 800725022 800725024	9009250191 9 8009250205 9 8009250223	80/08/27 80/08/27 80/08/30 80/08/30 80/09/03	50-369 50-369 50-461 50-358 50-327	0 0 0
BQ07240265 BQ07240266 BQ07240270 BQ07240276 BQ07240284	8009240259 8009240256 8009240256 8009240256 8009240273	80/07/23 80/08/29 80/08/29 80/08/29 80/08/04	50-317 6 50-370 6 50-370 6 50-370 6 50-324 6	800925025 800925026 800925027 800925028 800925030	9 8009250258 9 8009250278 0 8009250276 2 8009250299	80/09/19 80/09/01 80/09/12 80/09/04 80/07/11	50-266 CDNTRACT 50-135 10CFR 50-387	P G
8007240270 8007240274 8007240277 8007240278 8007240302	8009240282 8009240282 8009240292 8009240282 8009240282	80/09/02 80/09/02 80/09/02 80/09/02	50-413 0 50-413 0 50-413 0 50-413 0	800925032 B00925032 B00925032 B00925032	8009250307 5 6009250307 6 6009250307 7 8009250307	90/09/19 10/08/21 10/08/21 10/08/21 10/08/21	50-261 GA999 GA999 GA999 GA999	S .
8007240306 8007240307 8007240313 8007240314 8007249320	8007240282 8007240272 8007240282 8007240272 8007240272	90/09/02 90/09/02 90/09/02 90/09/02 90/09/02	50-413 0 50-413 0 50-413 0 50-413 0	800925033 800925033 800925034 800925034 800925034	8009250334 8009250334 8009250339	80/09/17 80/07/01 80/07/01 80/09/09 80/09/07	50-220 70-820 70-820 50-413 50-413	R G G

# TO PRINCIPAL DOCUMENTS

ACCESSIO	N NUMBER					ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC CATEGO		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC	
8007250344 8007250349 8007250351 8007250352 8007250357	8009250338 8009250346 8009250347 8009250346 8009250356	80/08/20 80/07/18 80/09/09 80/07/18 80/08/05	50-295 50-461 50-400 50-441 50-201	0 0 0 0	8007260412 8007260413 8007260414 8007260414 8007260418	8009260313 8009260410 8009260313 8009260410	80/09/15 80/08/18 80/09/15 80/08/18 79/08/10	50-287 50-329 50-329 50-329 70-1167	T G T
6009250360 6009250363 6009250373 6009250393 6009250395	8009250357 8009250354 8009250365 8009250390 8009250390	80/09/08 80/08/05 80/08/14 80/08/11 80/08/11	50-280 50-201 50-315 50-458 50-458	0 0	8009260417 8009260419 8009260420 8009260421 8009260431	8009260418	80/09/15 79/08/10 80/07/10 80/09/15 80/09/15	50-289 70-1167 50-409 50-289 50-289	T Q T T
8009250398 8009250405 8009250411 8009250422 8009250439	8009250390 8009250402 8009250408 8009250419 8009250431	60/08/11 80/08/08 80/09/09 80/09/09 80/09/05	50~458 50~498 50~263 70~36 70~143	0 0	8007260437 8007260443 8007240447 8007260455 8007260456	8007260440 8007260450	80/09/15 80/09/15 80/09/18 80/09/22 80/09/16	50-269 50-269 50-219 50-267 50-368	T T B B
8007250453 8007250454 8007250467 8007250470 8007250471	8007250448 8007250451 8007250462 8007250464 8007250462	80/09/14 80/09/13 80/08/25 80/09/11 80/08/25	FOIA 50-361 TOPREP 70-1151 TOPREP	A	8009260461 8009260468 8009260475 8009260476 8009260482	8009260458 8009260465 8009260470 8009260472 8009260477	80/09/19 80/09/23 80/09/19 80/09/12 80/09/19	50-271 50-237 50-293 50-312 TOPREP	P 8 8
8009250476 8009250478 8009250482 8009250497 8009250498	6009250472 8009250472 6009250479 8009250493 6009250494	80/09/10 80/09/10 80/09/08 80/09/15 80/09/10	70-1257 70-1257 50-546 CONTRACT 71-108	5 T	8007240484 8007240485 8007240485 8007240492 8007240493	8009260481 8009260480 8009260477 8009260488 8009260477	80/09/19 80/09/22 80/09/19 80/09/23 80/09/19	50-293 50-293 TOPREP 50-255 TOPREP	8 8 8
8009250502 8009260002 8009260004 8009260006 8009260012	609250500 8009240001 8009260003 8009240003 6009240009	80/09/10 80/09/09 80/09/23 80/09/23 80/09/23	71-192 50-329 50-289 50-289 50-389	0	8009260495 8009260496 8009260496 8009260503 8009260504	8009260363 8009260488 8009260477 8009260494 8009260477	79/08/10 80/09/23 80/09/19 80/09/22 80/09/19	40-8663 50-255 TOPREP 50-309 TOPREP	8
8009260013 8009260063 8009260117 8009260159 8009260173	8007260007 8007260058 8007260105 8007260153 8007260168	80/09/23 80/08/27 80/08/15 80/08/12 80/05/30	50-389 50-341 71-6581 40-8380 71-6058	H	8009260510 8009260513 8009260513 8009260532 8009260540	8009240504 8009240508 8009240514 8009240528 8009240535	80/08/27 80/09/16 80/09/24 80/08/27 80/08/29	50-344 50-206 50-395 50-317 50-368	\$ 8 A G G
8009240174 8009240181 8009240184 8009240192 8009240210	8009260168 8009260166 8009260166 8009260166 8009260207	80/09/30 80/09/10 80/09/10 80/09/10 80/09/24	71-6098 50-334 50-334 50-334 50-464	P P Q	8007260541 8007260545 800726057 9007260601 8007260607	8009260537 8009260537 8009260592 8009260596 8009260602	80/09/12 80/09/12 80/08/29 80/08/29 80/08/29	50~286 50~286 50~287 50~298 50~309	P 0 0 0
8007260224 6007260233 8007260238 6007260242 8007260247	8009260218 8009260227 8009260232 8009260229 8009260243	80/09/03 80/08/27 80/09/04 80/07/28 80/09/10	XPORTLIC 50-247 CONTRACT CONTRACT	R	8009260613 8009260624 8009260634 8009260636 8009260638	8007260607 8007260618 8007260628 8007260630 8007260635	80/08/29 80/08/29 80/08/21 80/09/19 80/09/19	50-315 50-338 50-315 50-409 50-324	0 0 8
8009260256 8009260258 8009260271 8009260284 8009260290	8007260247 8007260254 8007260263 8007260282 800726028B	80/08/14 80/09/16 80/08/14 80/09/10 80/09/19	50-461 50-327 50-282 50-298 50-478	QI E QI R T	800926040 8007260642 8007260642 8007280652 8009260654	8007260626 8007260637 8007260641 8007260641 8007260647	80/09/22 80/09/19 80/09/16 80/09/16 80/09/12	50-263 50-309 50-201 50-201 50-336	8 0 0 8
8007240308 8007240322 8007240327 8007240331	8007260304 8007260313 8007260313 8007260313	80/08/07 80/09/15 80/09/15 80/09/15 80/09/09	50-314 50-269 50-289 50-269 50-276	9 1 1 1 1	8007240658 8007260661 8007260665 8007240667 8007280677	8007260656 8007260657 8007260657 8007260664 8007260672	80/09/10 80/08/20 80/08/20 80/08/27 80/09/15	50-295 50-346 50-346 50-269 50-409	G G G
8009240335 8009240336 8009240340 8009240341 8009260352	8007260313 8007260324 8007260313 8007260324 8007260313	80/09/15 80/09/09 80/09/15 80/09/09 90/09/15	50-287 50-294 50-289 50-294 50-289	ፕ የ የ የ	8007260680 8007260681 8007260684 8007279000 8007279000	8009240476 8009240470 8009240470 8009290002 8009290002	80/08/29 80/09/17 80/09/17 80/09/09 80/09/09	CONTRACT 50-376 50-376 50-266 50-266	0000
8007240353 8007240358 8007240357 8007240344 8007240344	8009260346 8009260346 8009260313 8009260346 8009260313	80/09/08 80/09/08 80/09/15 80/09/08 80/09/15	50-346 50-346 50-287 50-346 50-287	P P T P	9009270013 9009270015 9009270016 9009270020 9009270023	9007270011 8007270011 8007270017 8007270019 8007270021	80/08/11 80/08/11 80/08/19 80/07/10 80/07/16	50-266 50-266 50-266 50-346 50-327	0 0 0 0 T
8007260372 8007260374 8007260380 8007260386 8007260386	8009260369 8009260369 8009260313 8009260378 8009260313	80/09/18 80/09/18 80/09/15 80/09/18 80/09/15	50-267 50-267 50-289 50-267 50-289	R T R T	9009290026 8009290030 8009290031 8009290032 8009290037	8004540052 8004540051 8004540052 8004540051	80/07/16 60/09/08 60/07/08 41/70/08	50-327 50-327 FOIA 10CFR FOIA	T T
8007240374 8007260374 8007260377 8007260400 8007260402	8009260313 8009260313 8009260395 8009260313	80/09/15 80/09/15 80/08/18 80/09/15		T a T T	8009290041 8009290046 8009290059 8009290059 8009290059	8007270025 8007270025 8007270025 8007270054 8007270025	80/09/08 80/09/08 80/09/08 80/09/10 80/09/08	FOIA FOIA FOIA 50-275 FOIA	н
8009260404 8009260405 8009260407 8009260408 8009260411	8007260375 8007260372 8007260313 8007260370 8007260313	80/08/19 79/08/10 80/09/15 79/08/10 80/09/15	70-2560 50-289 40-8180	G T T	8009270064 8009270068 8009270073 8009290079 8009290085	8009290025 8009290025 8009290025 8009290025 8009290025	80/60/08 80/60/08 80/60/08 80/60/08	FOIA FOIA FOIA FOIA FOIA	

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION	NUMBER					ACCESSION				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT CATEGOR	Y		ENCLOSURE	PRINCIPAL DOCUMENT	TAC DAUBRI DAUBRI	SUBJECT CATEGOR	Υ
8009290087 8009290092 8009290094 8009290096 8009290099	8007270025 8007270025 8007270070 8007270025 8007270025	80/09/08 80/09/08 80/09/08 80/09/08	FOIA FOIA 70-1308 FOIA FOIA			8009290464 8009290465 8009290468 8009290475 8009290496	8009290461 8009290462 8009290461 8009290472 8009290490	80/09/05 80/08/14 80/09/05 80/09/10 80/09/19	50-280 50-373 50-280 50-329 50-339	р С Р С
8009290101 8009290102 8009290105 8009290107 8009290111	8007270077 8007270025 8007270025 8007270104 8007270025	80/08/19 80/09/08 80/09/08 80/08/19 80/09/08	50-346 FOIA FOIA 50-546 FOIA	a a		8007270501 8007270513 8007270526 8007270571 8007300027	8009290499 8009290511 8009290525 8009290229 8009300026	80/08/31 80/09/12 80/08/19 80/07/31 80/09/11	WASTE HO 50-546 50-440 50-445 50-416	T 4 4 4
8009290113 8009290114 8009290116 8009290118 8009290122	8009270025 8009290110 8009270025 8009290109 8009290025	80/09/08 80/08/19 80/09/08 80/08/11 80/09/08	F01A 50-546 F01A 50-255 F01A	G: Gi		8007300031 8007300034 8007300036 8007300041 8007300052	8009300026 8009300033 8009300026 8009300046	80/09/11 80/09/11 80/09/24 80/09/11 80/08/27	50-416 50-416 50-155 50-416 50-346	0000
8009290124 8009290127 8009290131 8009290140 8009290142	8009290123 8009290025 8009290123 8009290025 8009290139	80/08/18 80/09/08 80/08/18 80/09/08 80/09/09	50-254 FOIA 50-254 FOIA CONTRACT	G G		8009300053 8009300054 8009300057 8009300063 8009300064	8009300046 8009300046 8009300061 8009300062	80/08/27 80/08/27 80/08/27 80/08/14 80/09/08	50-346 50-312 50-346 50-261 XFORTLIC	Р 0 Р 0
8007270152 8007270156 8007270158 8007270142 8007270143	8007270025 8007270025 8007270025 8007270025	80/09/08 80/09/08 80/09/08 41/90/08	FOIA FOIA FOIA 50-255 FOIA	Q		8009300067 8009300072 8009300073 8009300075 8009300080	8009300060 8009300060 8009300069 8009300060 8009300077	80/09/11 80/09/11 80/08/15 80/09/11 80/09/10	50-259 50-259 50-261 50-259 50-317	0 0 0 0 P
8009290144 8009290144 8009290170 8009290171 8009290174	8009270160 8009290025 8009270025 8009270168 8009270025	80/09/14 80/09/08 80/09/08 80/09/26 80/09/08	50-255 FOIA FOIA 50-170 FOIA	G F		8007300081 8007300083 8007300084 8007300085 8007300074	8009300060 8009300077 8009300077 8009300077 8009300089	80/09/11 80/09/10 80/09/08 80/09/10 80/08/14	50-259 50-317 XPORTLIC 50-317 50-382	Q P P Q
8007270173 8007270208 8007270248 8007270257 8007270280	8007270188 8007270202 8007270246 8007270251 8007270262	80/08/17 80/09/15 80/09/15 80/09/19 80/09/24	50-454 50-544 50-317 50-334 50-327	G R E P		8009300097 8009300101 8009300102 8009300108 8009300119	8009300093 8009300099 8009300098 8009300105 8009300109	80/09/03 80/09/11 80/08/18 80/09/18 80/09/11	Contract 50-295 50-498 50-389 Foja	e G A
8009290281 8009290306 8009290311 8009290311	8009290278 8009290290 8009290288 8009290284 8009290310	80/09/18 80/09/24 60/09/19 80/09/19 80/09/03	50-366 50-302 50-324 50-325 GAYYY	8 8 8		8007300121 8007300125 8007300126 8007300130 8007300136	8009300118 8009300122 8009300109 8009300127 8009300109	80/09/02 80/09/17 80/09/11 80/09/17 80/09/11	CONTRACT 71-8980 FDIA 71-9037 FOIA	
B009290313 8009290314 8009290315 8009290316 8009290317	8009270283 8009270310 8009270310 8009270310 8009270284	80/09/24 80/09/03 80/09/03 80/09/18	50-293 GA999 GA999 GA999 50-293	8		8009300137 8009300148 8009300153 8009300155 8009300154	8009300135 8009300145 8009300145 8009300145 8009300147	80/09/17 80/09/16 80/09/16 80/09/16 80/09/24	71-9034 50-313 50-313 50-313 50-259	p P P
8007270318 8007270321 8007270321 8007270322 8007270323	8007270310 8007270310 8007270317 8007270310 8007270310	E0/09/08 E0/09/08 E0/09/08 E0/09/08	99999 99940 966-05 99940 99940	R		8009300163 8009300183 8009300185 8009300197 8009300198	8009300159 8009300179 8009300180 8009300192 8009300193	80/09/15 80/09/18 79/08/10 80/09/08 80/09/09	50-267 50-235 40-8092 50-243 Contract	H P R
8009290326 8009290342 8009290347 8009290354 8009290356	8009290325 8009290341 8009290345 8009290351 8009290353	80/09/10 80/09/22 80/09/22 80/09/14 80/09/22	50-458 50-266 50-259 50-213 50-312	Ф Р В Р		8009300209 8009300210 8009300221 8009300224 8009300235	8007300206 8007300207 8007300217 8007300217 8007300230	80/09/09 80/09/04 80/08/19 80/08/19 80/09/15	CONTRACT 71-394 50-255 50-255 50-277	0 0 F
8009290358 8009290362 8009290367 8009290369 8009290370	8009290351 8009290351 8009290351 8009290365 8009290363	80/09/16 61/90/08 61/90/08 62/90/08	50-213 50-213 50-219 50-219 50-346	8 6 6 6		8009300235 8009300240 8009300243 8009300245 8009300251	8009300231 8009300238 8009300238 8009300239 8009300247	80/09/18 80/08/12 80/09/18 80/09/29	50-155 50-346 50-346 50-245 50-244	P & G & P & O
8007270372 8007270373 8007270377 8007270380 8007270381	8009290351 8009290351 8009290351 8009290378 8009290351	80/09/14 80/09/12 80/09/16 80/09/24 80/09/16	50-213 50-329 50-213 50-352 50-213	₽ ቀ የ ያ		8009300258 8009300244 8009300269 8009300273 8009300276	8009300253 8009300259 8009300265 8009300267 8009300271	80/08/29 80/09/12 80/09/29 80/09/11	50-206 CONTRACT 50-219 50-295 CONTRACT	P
8007270382 8007270384 8007270387 8007270387 8007270387	8009240378 8009290351 8009290351 8009290386 8009290394	80/09/24 80/09/14 80/09/16 80/09/10 80/09/23	50-352 50-213 50-213 50-287 50-382	명 무 문 H 당		8009300279 8009300280 8009300282 8009300286 8009300300	8007300274 8007300277 8007300274 8007300281 8007300276	80/08/18 80/09/03 80/09/18 80/09/09 80/09/17	50-267 40-1341 50-267 40-299 50-297	Q Q P
8009290398 8009290401 8009290428 8009290429	8009290394 8009290394 8009290425 8009290414 8009290425	80/09/23 80/09/23 80/08/18 80/09/18 80/09/18	50-382 50-382 50-275 FOIA 50-295	ន ១ ០		8009300301 8009300302 8009300307 8009300311	8007300294 8007300297 8007300295 8007300297 8007300297	80/09/17 80/09/09 80/09/19 80/09/09 80/09/09	50-297 50-245 50-275 50-245 50-245	P H P P
8007270444 8007270446 8007270451 8007270454 8007270460	8009290440 8009290439 8009290439 8009290439 8009290448	80/09/10 80/09/05 80/09/05 80/09/05	50-315 50-286 50-286 50-286 50-358	0 P P		8009300314 8009300319 8009300319 8009300322 8009300324	8007300312 8007300312 8007300314 8007300314	80/09/12 80/09/12 80/09/12 80/09/19 80/09/12	50-344 50-344 50-344 50-259 50-344	0 0 0 H 0

# CROSS REFERENCE OF ENCLOSURES TO PRINICPAL DOCUMENTS

Modelaio	ii iidiibeli			
		- 4 -		_
	PRINCIPAL	DATE	SUBJEC	
ENCLOSURE	DOCUMENT	ISSUED	CATECD	RY
8009300325	8009300316	80/09/19	50-259	н
8009300327	8009300314	80/09/19	50-259	н
8009300340	8009300334	80/09/12	50~282	P
104005900	9009300399	80/09/19	50-289	R
8009300405	8009300402	80/09/29	50~528	Ë
8009300414	8009300409	80/09/25	40-8681	
8009300420	8009300417	80/09/25	50-289	٥
8009300421	8007300417	80/09/26	50-367	Ä
8009300422	8007300417	80/09/25	50-289	ő
8009300422		80/09/25		
8009300423	8009300417	80/09/25	50-287	O
******				_
9009300430	8009300426	80/09/25	50-309	R
8009300450	8009300441	80/09/22	50-317	9
8009300460	8009300454	B0/09/26	50-318	8
8009300445	8007300455	80/09/24	5D-454	A
6009300470	8009300464	80/09/26	50-317	8
8009300473	8007300468	80/09/19	50-237	5
6009300478	8009300472	80/09/25	50-237	9
8007300479	8007300474	80/09/24	50-324	8
8009300483	8009300477	80/09/23	TOPREP	-
6007300485	8009300482	80/09/15	50-335	8
444.440.44				-
8009300487	8009300484	80/09/25	50-255	8
8009300494	600400440	80/09/12	50-250	ä
8009300495	8007300471	80/09/18	50-220	8
8009300496	8009300486	80/09/24	50-445	
8009300499	8007300486	80/09/24		M
8004300444	8004300445	80/09/59	50-255	S
DAGES AND A				_
8009300501	8009300493	80/09/23	50-331	6
B009300502	8009300497	80/09/23	50-321	8
8009300504	8009300498	60/09/25	50-281	8
8009300505	8009300500	80/09/23	50-273	R
8009300508	8009300498	80/09/25	50~281	8
8009300509	8009300489	80/09/23	50~325	5
8009300515	B009300511	80/09/26	50-346	8
8009300517	8009300510	80/09/24	50-315	s
B00730051B	8009300512	80/09/24	50-272	P
8009300521	8009300516	80/09/26	50~259	s
				~

ACCESSION NUMBER

	PRINCIPAL	DATE	SUBJE	СТ
ENCLOSURE	DOCUMENT	ISSUED	CATEQ	DRY
<b></b>				
8009300526	8009300519	80/09/23	50-346	8
8009300527	8009300517 E2800E9008	80/07/23	50-348	8
8009300528	8009300523	80/07/25	50-219	8
8009300530	8007300522	80/09/23	30-217 30-247	s
6007300535	8007300524	80/09/24	50-293	s
00010000	0001300331	00/07/24	30-473	-
8009300539	8009300532	80/09/17	50-285	6
8009300542	8009300533	80/09/25	50-498	Ä
8009300546	8009300538	80/09/18	50~348	B
8009300553	8009300544	80/09/26	50-296	8
8009300554	B009300548	80/09/26	50-260	g
6009300558	8009300351	80/09/25	50-282	5
8009300563	8009300556	80/09/24	50-267	Š
6007300567	8009300562	80/09/22	50~259	s
8009300568	B009300559	80/09/24	50-325	ŝ
6004300864	0009300564	80/09/25	50-219	ŝ
				_
8009300571	8009300565	80/09/19	50-367	G
8007300577	8009300572	80/09/24	50-348	8
8009300585	8009300580	80/09/24	70-1309	
8007300586	8009300580	80/09/24	70-1308	
89700598	8009300564	80/09/12	50-273	G
8007300575	6009300593	80/07/04	CONTRACT	
8009300597	8009300592	80/09/09	CONTRACT	,
890000098	17200E900B	P11P0108	179-07	٥
8009300611	8007300604	80/09/02	70-1377	
8007300612	8007300608	80/09/15	50~462	G
B009300614	0009300603	80/09/19	50-249	0
91400EP00B	8009300403	80/09/19	50-249	G
8007300626	8009300616	80/09/16	50~269	G
OEADOEPODB	91900E600B	81\P0\0B	50-269	G
8009300631	61600EP00B	80/09/16	50~269	G
20000000100	******			
8009300632	8009300629	80/04/55	50-289	0
8009300640 8009300653	8009300614	60/09/16	50-249	Q.
EGGOORFUUN	B009300651	80/08/29	50~29	0

ACCESSION NUMBER

#### APPENDIX A

#### **DEFINITIONS OF DOCKET 50 CATEGORIES**

#### A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

- 1. Application for construction permit.
- 2. General Information submitted with construction permit application.
- 3. Amendments and changes to items 1 and 2.
- 4. NRC questions, requests for additional information, and applicant responses.
- 5. Correspondence and documents relating to unresolved design and construction issues.
- 6. Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Construction Permit, amendments, and correspondence relating to the construction permit.
- 10. Scheduling of license application submission or review.
- 11. Environmental review information.
- 12. Application for operating license.
- 13. General Information submitted with operating license application.
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 17. Reports of site visits.
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application.

## B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

- 3. Transmittal and acknowledgement letters.
- 4. Certificates of service to the PSAR.

# C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

- 1. Environmental Report (ER) submitted by the utility.
- 2. Amendments and supplements to the ER.
- 3. Transmittal and acknowledgement letters.
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses.
- 6. Federal register notices citing the availability of items 1 and 2.
- 7. Correspondence relating to the review of ER.
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

# D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

- 1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- 2. Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4. Comments from other federal, state and local government agencies.
- 5. Transmittal and acknowledgement letters.
- 6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above.
- 8. Federal register notice citing availability of items 1 and 2.
- 9. Site visits to obtain information for DES or FES.
- 10. Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

### E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

- 1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).
- 2. Supplements to SER.
- 3. Correspondence relating to SER.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- 7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
- 8. Transmittal and acknowledgement letters.

#### F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

- 1. Fire Hazard Protection Plan and surveys.
- 2. Plant evacuation correspondence.
- 3. Safeguards Contingency Plans.
- 4. Review of Health Physics Program,
- 5. Correspondence relating to aforementioned plans.
- 6. Supplements, changes and revisions to plans.

#### G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3. Requests to make appearances at hearings.
- 4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6. Correspondence to and from intervenors.
- 7. Board orders and decisions.
- 8. Petitions for Commission action.
- 9. Legal filings and Commission orders and decisions resulting from item 8.

#### H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license Items that have no substantive technical content or meaning for the status of the license or application are included.

- 1. Change of address notifications.
- Changes in structure of organization.
- 3. Changes in service lists.
- 4. NRC requests to applicant for additional copies of documents.
- 5. Correspondence from the public requesting information about the facility and NRC responses.
- 6. Correspondence on strictly administrative matters.
- 7. Letters of support, concern or opposition to the facility.
- 8. Correspondence regarding the Local Public Document Rooms (LPDRs).
- 9. Professional qualification statements not pertaining to the hearing process.

#### I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

#### J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments.
- 2. Endorsements insurance policies.
- 3. Other correspondence regarding indemnity and insurance matters.

#### K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
- 2. Amendments and changes to the FSAR.
- 3. Federal register notices citing availability of items 1 and 2.
- 4. Transmittal and acknowledgement letters.
- 5. Certificates of service to the FSAR.

#### L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

- 1. Limited Work Authorizations (LWA) and amendments.
- 2. Correspondence pertaining to work performed under LWA's.

#### M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- 1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".
- 2. Correspondence where the primary topic of discussion is antitrust matters.
- 3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

#### N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

# O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- 1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
- Correspondence from ACRS.
- 3. Announcement of ACRS meetings.
- 4. Transmittal and acknowledgement letters.
- ACRS reports.
- 6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
- 7. Minutes at ACRS Subcommittee Meetings.

#### P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

- 1. Operating license, amendments, proposed amendments, changes and related correspondence.
- 2. Technical specifications and changes.

- 3. Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
- 4. Federal register notices citing availability of items 1 and 2.
- 5 Correspondence regarding the Final Safety Analysis Report (FSAR).
- All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
- 8. Information on the Standard Review Plan (STP).
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10 Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11. Owner's group meeting announcements and reports.
- 12. Quality assurance information.
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.

# Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1. Inspection reports.
- IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN's).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

## R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature.

- 1. Monthly, semiannual, or annual operating reports (other than financial).
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- 3. Periodic personnel exposure reports.
- 4. Operational Logbooks:

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets.

5. Correspondence or other documents relating to the above listed items.

#### S. REPORTABLE OCCURRENCES, PNO'S, PNS'S AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

- 1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
- 2. Potential or possible reportable deficiency reports and related correspondence.
- 3. Personnel exposure reports.
- 4. Construction deficiency reports submitted under 10 CFR 50.55e.
- 5. Preliminary Notification of Occurrence (PNO's) and Preliminary Notification of Safeguards Events (PN's).
- 6. Environmental Technical Specifications violation reports and Environmental Event reports.
- 7. Part 21 Reports of defects and noncompliance.
- 8. Correspondence or other documents relating to Items 1-7.

# T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- 2. Testimony and statements submitted to ASLB and ASLAB.
- 3. Commission meeting transcripts.
- 1. NRC staff briefings to the Commission.
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- 6. Transcripts of utility briefs to NRC staff.
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.

- 3. Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
- 8. Information on the Standard Review Plan (STP).
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11. Owner's group meeting announcements and reports.
- 12. Quality assurance information.
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.

# Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1. Inspection reports.
- 2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN's).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

### R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature.

- 1. Monthly, semiannual, or annual operating reports (other than financial).
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- 3. Periodic personnel exposure reports.
- 4. Operational Logbooks:

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets.

5. Correspondence or other documents relating to the above listed items.

## S. REPORTABLE OCCURRENCES, PNO'S, PNS'S AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

- 1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
- 2. Potential or possible reportable deficiency reports and related correspondence.
- 3. Personnel exposure reports.
- 4. Construction deficiency reports submitted under 10 CFR 50.55e.
- 5. Preliminary Notification of Occurrence (PNO's) and Preliminary Notification of Safeguards Events (PN's).
- 6. Environmental Technical Specifications violation reports and Environmental Event reports.
- 7. Part 21 Reports of defects and noncompliance.
- 8. Correspondence or other documents relating to items 1-7.

# T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- Testimony and statements submitted to ASLB and ASLAB.
- Commission meeting transcripts.
- NRC staff briefings to the Commission.
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- Transcripts of utility briefs to NRC staff.
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.

- 3. Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
- 8. Information on the Standard Review Plan (STP).
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11. Owner's group meeting announcements and reports.
- 12. Quality assurance information.
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.

# Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1. Inspection reports.
- 2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN's).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

#### PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE R

This category includes periodic reports of a routine nature.

- Monthly, semiannual, or annual operating reports (other than financial). 1.
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- 3. Periodic personnel exposure reports.
- 4. Operational Logbooks:

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets.

Correspondence or other documents relating to the above listed items. 5.

#### REPORTABLE OCCURRENCES, PNO'S, PNS'S AND RELATED CORRESPONDENCE S.

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

- All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up İ. correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
- Potential or possible reportable deficiency reports and related correspondence. 2.
- 3. Personnel exposure reports.
- Construction deficiency reports submitted under 10 CFR 50.55e. 4.
- Preliminary Notification of Occurrence (PNO's) and Preliminary Notification of Safeguards 5. Events (PN's).
- Environmental Technical Specifications violation reports and Environmental Event reports. 6.
- Part 21 Reports of defects and noncompliance. 7.
- Correspondence or other documents relating to stems 1-7. 8.

# TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS Т.

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board 1. (ASLAB) transcripts.
- Testimony and statements submitted to ASLB and ASLAB. 2.
- Commission meeting transcripts. 3.
- NRC staff briefings to the Commission. 4.
- Statements and written testimony submitted at Commission meeting or hearings. 5.

8. Corrections to above items.

#### U. CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

- 1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
- 2. Preparatory and backup documents for item 1.
- 3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters.

#### V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1. Operator licenses or administrative information bearing on licensing of operators.
- 2. NRC examination results.
- 3. Power plant examination summary sheet.

#### W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

- 1. Application for authority to voluntarily surrender license.
- 2. Application to dismantle the facility and dispose of component parts.
- Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan,
  Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
- 4. Documents relating to disposal of radioactive material and decontamination of the site.
- 5. Other correspondence relating to above items.
- 6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

#### APPENDIX B

#### **DEFINITIONS OF NONDOCKETED CATEGORIES**

#### 10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

- 1. Sunshine Act Federal Register notices.
- 2. Full, written explanation of closed meetings.
- 3. Certification of General Counsel on closed meetings.
- 4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
- 5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
- 6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
- 7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

#### ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

- Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
- 2. ACRS meeting announcements; description of meeting agendas.
- 3. ACRS-generated reports, memoranda and correspondence that are publicly available.
- 4. ACRS consultant reports, comments and related correspondence.
- 5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

### COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.

- 2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners
- 3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

#### CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

- 1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
- 2. Solicitations (RFP or IFB) issued by the NRC.
- 3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
- 4. Contractual documents and contract modifications, if any.

#### DISCLOSURE - Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

#### FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include

- 1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year—numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- 2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FOIA.

#### GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

- 1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
- 2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.

- 3. Meeting notifications and minutes.
- 4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

#### I&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- 1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
- 2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- 3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
- 4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

#### MISC - Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

#### NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

- 1. These reports are normally final work products and are characterized by the following criteria:
  - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
  - b. They present the results of Commission licensing and policy decisions.
  - c. They present the results of technical research conducted for the Commission.
- 2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- 3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

#### ORG - Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development; and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are.

- Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
- 2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air
- 3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

#### PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

- 1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
- 2. Text of the Proposed Rule (PR).
- 3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- 4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

#### PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- 1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.

- 3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
- 4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

#### PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

- A. Application/Construction Stage
  - 1. Application submitted by the utility.
  - 2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
  - 3. Applicant's Quality Assurance Manual.
  - Early site review information.
  - 5. Backup technical documents submitted in support of the application.
  - 6. Early site visits.
- B. Utility PSAR and Amendments
  - 1. PSARs submitted by the utility.
  - 2. Amendments and changes to the PSAR.
  - 3. Transmittal letters.
  - 4. Letters acknowledging receipt of the PSAR.
- G. Adjudicatory Correspondence
  - 1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.
- M. Antitrust Correspondence
  - Submittals and related material pertaining to the antitrust review.

#### Q. Inspection Reports

- 1. Inspection reports of the applicant's quality assurance program.
- Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

#### 2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

# PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited.
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

#### QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

- NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- 2. Notices of deviations.
- Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

#### REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC

staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

- Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

#### RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
  - a. model documentation reports
  - b. code documentation reports
  - c. code verification reports
- 3. Pre-test prediction reports.
- 4. "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examination analyses.
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by contractors.
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

# REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

#### Q. Inspection Reports

- 1. Inspection reports of the applicant's quality assurance program.
- 2. Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

#### Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

## PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- 2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited.
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

#### QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

- NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- 2. Notices of deviations.
- 3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

#### REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

#### RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
  - a. model documentation reports
  - b. code documentation reports
  - c, code verification reports
- 3. Pre-test prediction reports.
- 4. "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examination analyses.
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by contractors.
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- 9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

## REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

- 1. Agendas for quarterly review group meetings.
- Summary manutes of review group meetings representing views expressed, including dissenting views.
- 3. Research plans and predicted results of major experiments; presentations by research contractors.
- 4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion.

#### RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2. Notifications of hearing board meetings.
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding.
- 6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

#### SECY - Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- 1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

#### STATE PROG — State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

State and local governments in planning responses to radiological emergencies; and (3) a wide range of haison and cooperative activities regarding such functions as licensing and siting. It includes:

- 1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
  - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
  - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
- 2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.
- 3. State Legislative Reports.
- 4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

#### TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

- 1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals.
- 4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

#### WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- 2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

- 3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
- 4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

#### XPORTLIC - Export and Import Licenses

Thus category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are.

- 1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3. Commission letters requesting Executive Branch views.
- 4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
- 5. Correspondence from foreign governments, international organizations, and members of the public.
- 6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- 8. Hearing records and decisions.
- 9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

RC FORM 335	US NUCLEAR REGULATORY COMMISSION BIBLIOGRAPHIC DATA SHEET	N	NUREG-0540 Vol 2, No 9		
TITLE AND SUBTI	TLE (Add Volume No., if appropriate)	····			
	st of Documents Made Publicly A	2 (Leave blank)			
	September 1-30, 1980	3 RECIPIENT'S ACCESSION NO			
AUTHOR(S)		5 DATE REPORT COMPLETED			
			October YEAR 1980		
PERFORMING OF	GANIZATION NAME AND MAILING ADDRESS	(Include Zip Code)			
Division of	Technical Information and Docu r Regulatory Commission				
Washington,	D.C. 20555		6 (Leave blank)		
			8 (Leave blank)		
. SPONSORING OF	RGANIZATION NAME AND MAILING ADDRESS	(Include Zip Code)			
Division of	Technical Information and Docu	ment Control	10 PROJECT/TASK/WORK UNIT NO		
	r Regulatory Commission		11 CONTRACT NO		
TYPE OF REPOR	7 Tr	PERIOD	COVERED (Inclusive dates)		
Monthly	•	PENIOD	COVERED thicksive dates;		
	· · · · · · · · · · · · · · · · · · ·				
. SUPPLEMENTAR	Y NOTES		14 (Leave olank)		
info incl plan mate regu merl Cent docu cont	document is a monthly publicate rmation received and generated with the docketed material associated and other uses of radioactive rial received and generated by latory agency. The docketed into y issued through the U.S. Department under the title Power Reactor ment replaces PRDI, which will a ains the following indexes: Persu, and Report Number Index.	by the US NR ciated with e materials NRC pertinen formation in tment of Ene r <i>Docket Inf</i> no longer be	C. This information civilian nuclear power and (2) nondocketed at to its role as a cludes information formation (PRDI). This prepared. This document		
. KEY WORDS AN	D DOCUMENT ANALYSIS	17a DESC	RIPTORS		
to IDENTIFIERS'C					
AVAILABILITY	STATEMENT	19 <b>S</b>	Unclassified 21 NO OF PAGES		
Unlimited		20 S	ECURITY CLASS (This page) 22 PRICE S		

--- - ---